

Free Companion Website






Consists of 974 (912 + 62**) pages covering the Part, Assembly, Drawing, Presentation, Sheet Metal, Weldments, Stress Analysis, and Mold Design modules of Autodesk Inventor.

(** Pages for free download)

Tickoo-CADCIM Series

Best Textbooks at Affordable Prices



Autodesk Inventor 2016

for Designers, 16th Edition

Includes Stress Analysis and Mold Design

Free Resources for Faculty and Students:

- Online technical support by contacting techsupport@cadcim.com
- Additional student projects available for free download
- Part files used in tutorials, exercises*, and illustrations
- Customizable PowerPoint presentations of all chapters*
- Instructor Guide with solutions to all review questions and exercises*
- Additional learning resources at <http://allaboutcadcam.blogspot.com>

(* For faculty only)

Also available as eBook
<http://ebooks.cadcim.com>

Revised & Updated Edition

 **AUTODESK**
Authorized Author

Sham Tickoo
Purdue University Calumet, USA

Autodesk Inventor 2016 for Designers (16th Edition)

CADCIM Technologies 525 St. Andrews Drive
Schererville, IN 46375, USA
(www.cadcim.com)

Contributing Author

Sham Tickoo Professor
*Department of Mechanical Engineering Technology Purdue University Calumet
Hammond, Indiana, USA*

Published by CADCIM Technologies, 525 St Andrews Drive, Schererville, IN 46375 USA. © Copyright 2015 CADCIM Technologies. All rights reserved. No part of this publication may be reproduced or distributed in any form or by any means, or stored in the database or retrieval system without the prior permission of CADCIM Technologies.

ISBN 978-1-942689-02-7

NOTICE TO THE READER

The publisher makes no representation or warranties of any kind, including but not limited to, the warranties of fitness for particular purpose or merchantability, nor are any such representations implied with respect to the material set forth herein, and the publisher takes no responsibility with respect to such material. The publisher shall not be liable for any special, consequential, or exemplary damages resulting, in whole or part, from the reader's use of, or reliance upon this material.

www.cadcim.com

The reader is expressly warned to consider and adopt all safety precautions that might be indicated by the activities herein and to avoid all potential hazards. By following the instructions contained herein, the reader willingly assumes all risks in connection with such instructions.

The publisher makes no representation or warranties of any kind, including but not limited to, the warranties of fitness for particular purpose or merchantability, nor are any such representations implied with respect to the material set forth herein, and the publisher takes no responsibility with respect to such material. The publisher shall not be liable for any special, consequential, or exemplary damages resulting, in whole or part, from the reader's use of, or reliance upon this material.

www.cadcim.com

CADCIM Technologies

DEDICATION

To teachers, who make it possible to disseminate knowledge to enlighten the young and curious minds of our future generations

To students, who are dedicated to learning new technologies and making the world a better place to live in

SPECIAL RECOGNITION

A special thanks to Mr. Denis Cadu and the ADN team of Autodesk Inc. for their valuable support and professional guidance to procure the software for writing this textbook

THANKS

*To the faculty and students of the MET department of Purdue University Calumet for their cooperation
To employees of CADCIM Technologies for their valuable help*

Online Training Program Offered by CADCIM Technologies

CADCIM Technologies provides effective and affordable virtual online training on various software packages including Computer Aided Design, Manufacturing and Engineering (CAD/CAM/CAE), computer programming languages, animation, architecture, and GIS. The training is delivered 'live' via Internet at any time, any place, and at any pace to individuals, students of colleges, universities, and CAD/CAM/CAE training centers. The main features of this program are:

Training for Students and Companies in a Classroom Setting Highly experienced instructors and qualified Engineers at CADCIM Technologies conduct the classes under the guidance of Prof. Sham Tickoo of Purdue University Calumet, USA. This team has authored several textbooks that are rated "one of the best" in their categories and are used in various colleges, universities, and training centers in North America, Europe, and in other parts of the world.

Training for Individuals

CADCIM Technologies with its cost effective and time saving initiative strives to deliver the training in the comfort of your home or work place, thereby relieving you from the hassles of traveling to training centers.

Training Offered on Software Packages

CADCIM provides basic and advanced training on the following software packages:

CAD/CAM/CAE: *CATIA, Creo Parametric, AutoCAD Plant 3D, SOLIDWORKS, Autodesk Inventor, Solid Edge, NX, AutoCAD, AutoCAD LT, Customizing AutoCAD, EdgeCAM, and ANSYS*

Computer Programming: *C++, VB.NET, Oracle, AJAX, and Java*

Animation and Styling: *Autodesk 3ds Max, Autodesk 3ds Max Design, Autodesk Maya, Autodesk Alias, Pixologic ZBrush, CINEMA 4D*

Architecture and GIS: *Autodesk Revit Architecture, AutoCAD Civil 3D, Autodesk Revit Structure, AutoCAD Map 3D, Primavera, STAAD Pro, Autodesk Navisworks*

For more information, please visit the following link:

<http://www.cadcim.com>

Note

If you are a faculty member, you can register by clicking on the following link to access the teaching resources: <http://www.cadcim.com/Registration.aspx>. The student resources are available at <http://www.cadcim.com>. We also provide Live Virtual Online Training on various software packages. For more information, write us at sales@cadcim.com.

Table of Contents

Dedication

Preface

Chapter 1: Introduction

Introduction to Autodesk Inventor 2016

Part Module

Assembly Module

Presentation Module

Drawing Module

Sheet Metal Module

Mold Design Module

Getting Started with Autodesk Inventor

Quick Access Toolbar

Ribbon and Tabs

Sketch Tab

3D Model Tab

Sheet Metal Tab

Assemble Tab

Place Views Tab

Presentation Tab

Tools Tab

View Tab

Navigation Bar

Browser Bar

Units for Dimensions

Important Terms and Their Definitions

Feature-based Modeling

Parametric Modeling

Bidirectional Associativity

Adaptive

Design Doctor

Constraints

Consumed Sketch

Stress Analysis Environment

Select Other Behavior

Hotkeys

Part Module

Assembly Module

Drawing Module

Customizing Hotkeys

Creating the Sketch

Marking Menu

Color Scheme

Self-Evaluation Test

Review Questions

Chapter 2: Drawing Sketches for Solid Models

- The Sketching Environment
- The Initial Screen of Autodesk Inventor
- Starting a New File
- The Open Dialog Box
- Setting a New Project
- Import DWG
- Invoking the Sketching Environment
- Introduction to the Sketching Environment
- Setting Up the Sketching Environment
- Modifying the Document Settings of a Sketch Sketching Entities
- Positioning Entities by Using Dynamic Input Drawing Lines
- Drawing Circles
- Drawing Ellipses
- Drawing Arcs
- Drawing Rectangles
- Drawing Polygons
- Drawing Slots
- Placing Points
- Creating Fillets
- Creating Chamfers
- Drawing Splines
- Deleting Sketched Entities
- Finishing a Sketch
- Understanding the Drawing Display Tools
- Zoom All
- Zoom
- Zoom Window
- Zoom Selected
- Pan
- Orbit
- Constrained Orbit
- Tutorial 1
- Tutorial 2
- Tutorial 3
- Tutorial 4
- Self-Evaluation Test
- Review Questions
- Exercise 1
- Exercise 2
- Exercise 3
- Exercise 4

Chapter 3: Adding Geometric Constraints to a Sketches

Adding Geometric Constraints to a Sketch

Perpendicular Constraint
Parallel Constraint
Tangent Constraint
Coincident Constraint
Concentric Constraint
Collinear Constraint
Horizontal Constraint
Vertical Constraint
Equal Constraint
Fix Constraint
Symmetric Constraint
Smooth Constraint
Viewing the Constraints Applied to a Sketched Entity Controlling Constraints and Applying them Automatically while Sketching Constraints Settings Dialog Box
Scope of Constraint Inference
Deleting Geometric Constraints
Adding Dimensions to Sketches
Linear Dimensioning
Aligned Dimensioning
Angular Dimensioning
Diameter Dimensioning
Radius Dimensioning
Linear Diameter Dimensioning
Setting the Scale of a Sketch
Creating Driven Dimensions
Understanding the Concept of Fully-Constrained Sketches Measuring Sketched Entities
Measuring Distances
Measuring Angles
Measuring Loops
Measuring the Area
Adding Linear Measurements
Clearing Accumulated Dimensions
Evaluating Region Properties
Tutorial 1
Tutorial 2
Tutorial 3
Tutorial 4
Self-Evaluation Test
Review Questions
Exercise 1
Exercise 2
Exercise 3
Exercise 4
Exercise 5
Exercise 6

Chapter 4: Editing, Extruding, and Revolving the Sketches

Editing Sketched Entities
Extending Sketched Entities
Trimming Sketched Entities
Splitting Sketched Entities
Offsetting Sketched Entities
Mirroring Sketched Entities
Moving Sketched Entities
Rotating Sketched Entities
Creating Patterns
Creating Rectangular Patterns
Creating Circular Patterns
Writing Text in the Sketching Environment
Writing Regular Text
Writing Text Aligned to a Geometry
Inserting Images and Documents in Sketches
Editing Sketched Entities by Dragging
Tolerances
Converting the Base Sketch into a Base Feature Extruding the Sketch
Revolving the Sketch
Direct Manipulation of Features by Using the Mini Toolbar Command Options
Manipulators
Rotating the View of a Model in 3D Space
Rotating the View of a Model Using the Orbit Changing the View Using the ViewCube
Navigating the Model
Controlling the Display of Models
Setting the Visual Styles
Setting the Shadow Options
Setting the Camera Type
Creating Freeform Shapes
Tutorial 1
Tutorial 2
Tutorial 3
Tutorial 4
Self-Evaluation Test
Review Questions
Exercise 1
Exercise 2
Exercise 3
Exercise 4
Exercise 5
Exercise 6
Exercise 7

Chapter 5: Other Sketching and Modelling Options

Need for other Sketching Planes
Work Features
Creating Work Planes

Creating Work Axes
Creating Work Points
Other Extrusion Options
Other Revolution Options
The Concept of Sketch Sharing
Tutorial 1
Tutorial 2
Tutorial 3
Self-Evaluation Test
Review Questions
Exercise 1
Exercise 2
Exercise 3
Exercise 4

Chapter 6: Advanced Modeling Tools-I

Advanced Modeling Tools
Creating Holes
Creating Fillets
Creating Chamfers
Mirroring Features and Models
Creating Rectangular Patterns
Creating Circular Patterns
Creating Rib Features
Thickening or Offsetting the Faces of Features Creating the Embossed and Engraved Features Applying Images on a Feature
Assigning Different Colors/Styles to a Model Assigning Different Material to a Model
Modifying the Properties of an Existing Material Tutorial 1
Tutorial 2
Tutorial 3
Tutorial 4
Tutorial 5
Self-Evaluation Test
Review Questions
Exercise 1
Exercise 2
Exercise 3

Chapter 7: Editing Features and Adding Automatic Dimensions to Setches

Concept of Editing Features
Editing Features of a Model
Updating Edited Feature
Editing Features Dynamically by Using 3D Grips Editing the Sketches of Features
Redefining the Sketching Plane of a Sketched Feature Suppressing and Unsuppressing the Features
Editing of a feature using the Direct Tool

Deleting Features
Copying and Pasting Features
Manipulating Features by EOP
Adding Automatic Dimensions to Sketches
Projecting Entities in the Sketching Environment Projecting Edges or Faces
Projecting Cutting Edges
Projecting 2D Sketch on 3D Face
Projecting DWG Geometry
Tutorial 1
Tutorial 2
Tutorial 3
Self-Evaluation Test
Review Questions
Exercise 1
Exercise 2
Exercise 3
Exercise 4
Exercise 5

Chapter 8: Advanced Modeling Tools-II

Advanced Modeling Tools
Creating Sweep Features
Creating Lofted Features
Creating Coil Features
Creating Threads
Creating Shell Features
Applying Drafts
Creating Split Features
Trimming Surfaces
Extending Surfaces
Deleting Faces
Replacing Faces with Surfaces
Creating Planar Boundary Patches
Stitching Surfaces
Working with the Sculpt Tool
Working with the Bend Part Tool
Reordering the Features
Using the Sketch Doctor
Using the Design Doctor
Tutorial 1
Tutorial 2
Tutorial 3
Tutorial 4
Tutorial 5
Self-Evaluation Test
Review Questions
Exercise 1

Exercise 2

Chapter-9: Assembly Modeling-I

Assembly Modeling

Types of Assemblies

Top-down Assemblies

Bottom-up Assemblies

Creating Top-down Assemblies

Creating Components in the Assembly Module

Creating Bottom-Up Assemblies

Placing Components in the Assembly File

Assembling Components by Using the Constrain Tool Assembly Tab

Motion Tab

Transitional Tab

Constraint Set Tab

Specifying the Limits for Constraining

Assembling Parts by Using the Assemble Tool Using ALT+Drag to Apply Assembly Constraints Applying

Joints to the Assembly

Joint Tab

Limits Tab

Showing and Hiding Relationships

Show Relationship

Hide Relationship

Show Sick Relationship

Moving Individual Components

Rotating Individual Components in 3D Space

Tutorial 1

Tutorial 2

Tutorial 3

Self-Evaluation Test

Review Questions

Exercise 1

Chapter 10: Assembly Modelling-II

Editing Assembly Constraints

Editing Components

Editing Components in the Assembly File

Editing Components by Opening their Part Files Creating Subassemblies

Creating a Subassembly Using the Bottom-up Design Approach Creating a Subassembly Using the Top-down Design Approach Checking Degrees of Freedom of a Component

Creating the Pattern of Components in an Assembly Component

Associative Tab

Rectangular Tab

Circular Tab

Replacing a Component from the Assembly File with Another Component Replacing a Single Instance of

the Selected Component Replacing all Instances of the Selected Component Mirroring Subassemblies or Components of an Assembly Copying Subassemblies or Components of an Assembly Deleting Components
Editing the Pattern of Components
Making a Pattern Instance Independent
Deleting Assembly Constraints
Creating Assembly Section Views in the Assembly File Analyzing Assemblies for Interference
Creating Design View Representations
Design View Representation Area
Positional Representation Area
Level of Detail Representation Simulating the Motion of Components of an Assembly by Driving Assembly Constraint Creating Positional Representations
Viewing the Bill of Material of the Current Assembly Working with Assembly Features
Tutorial 1
Tutorial 2
Tutorial 3
Self-Evaluation Test
Review Questions
Exercise 1

Chapter 11: Working with Drawing Views-I

The Drawing Module
Types of Views
Generating Drawing Views
Generating the Base View
Generating Projected Views
Generating Auxiliary Views
Generating Section Views
Generating Detail Views
Generating Broken Views
Generating Break Out Views
Generating Overlay Views
Generating Slice Views
Drafting Drawing Views
Editing Drawing Views
Deleting Drawing Views and Drawing Sheet
Moving Drawing Views
Copying Drawing Views
Rotating Drawing Views
Changing the Orientation of Drawing Views
Assigning Different Hatch Patterns to Components in Assembly Section Views Editing the Default Hatch Style of the Sectioned Objects Excluding Components from Assembly Section Views Tutorial 1
Tutorial 2
Self-Evaluation Test
Review Questions
Exercise 1

Chapter 12: Working with Drawing Views-II

- Modifying Drawing Standards
- Inserting Additional Sheets into Drawing
- Activating a Drawing Sheet
- Displaying Dimensions in Drawing Views
- Retrieving Parametric Dimensions in Drawing Views Adding Reference Dimensions
- Modifying the Model Dimensions
- Editing Drawing Sheets
- Creating Dimension Styles
- Applying Dimension Style
- Modifying a Dimension and its Appearance Using the Shortcut Menu Adding the Parts List Source Area
- BOM Settings and Properties Area
- Table Wrapping Area
- Editing the Parts List
- Column Chooser
- Group Settings
- Filter Settings
- Sort
- Export
- Table Layout
- Renumber Item 12-13
- Save Item Overrides to BOM 12-14
- Member Selection 12-14
- Adding/Removing Custom Parts 12-14
- Shortcut Menu Options
- Setting the Standard for the Parts List
- Adding Balloons to Assembly Drawing Views
- Adding Balloons to Selected Components Adding Automatic Balloons
- Adding Text to a Drawing Sheet
- Adding Multiline Text without a Leader
- Adding Multiline Text with Leader
- Tutorial 1
- Tutorial 2
- Tutorial 3
- Self-Evaluation Test
- Review Questions
- Exercise 1

Chapter 13: Presentation Module

- The Presentation Module
- Creating the Presentation View
- Assembly Area
- Explosion Method Area
- Defining Units for Presentation Files

Tweaking Components in the Presentation View Animating an Assembly
Rotating the Presentation View Precisely
Tutorial 1
Tutorial 2
Self-Evaluation Test
Review Questions
Exercise 1

Chapter 14: Working with Special Design Tools

Adaptive Parts
Defining Parameters
Working with iParts
Types of iPart Factories
Creating iPart Factories
Procedure to Create Standard iPart
Procedure to Create Custom iPart
Inserting an iPart into an Assembly
Changing the iParts in the Assembly File
Creating 3D Sketches
Line
Spline
Bend
Include Geometry
Intersection Curve
Helical Curve
Tutorial 1
Tutorial 2
Tutorial 3
Tutorial 4
Tutorial 5
Self-Evaluation Test
Review Questions
Exercise 1

Chapter 15: Working with Sheet Metal Components

The Sheet Metal Module
Setting Sheet Metal Component Parameters
Setting the Sheet Metal Rule
Setting the Material
Setting the Unfolding Rule
Creating Sheet Metal Components
Folding Sheet Metal Components
Adding Flanges to Sheet Metal Components
Creating Cuts in Sheet Metal Components
Creating Seams at the Corners of Sheet Metal Components Bending the Faces of a Sheet Metal Component

Rounding the Corners of Sheet Metal Components Chamfering the Corners of Sheet Metal Components
Punching 3D Shapes into Sheet Metal Components Creating Hems
Creating Contour Flanges
Creating the Flat Patterns of Sheet Metal Components Adding or Removing Material from the Flat Pattern
Tutorial 1
Tutorial 2
Self-Evaluation Test
Review Questions
Exercise 1

Chapter 16: Introduction to Weldments

Understanding Weldment Assemblies
Main Types of Welds in Autodesk Inventor
Cosmetic Welds
Fillet Welds
Groove Welds
Adding Welds to Assemblies
Assembling the Components of Weldment Assemblies Preparing Assemblies for Weldments
Adding Welds
Creating Fillet Welds
Creating Cosmetic Welds
Creating Groove Welds
Creating Symbols
Generating Report
Tutorial 1
Tutorial 2
Self-Evaluation Test
Review Questions
Exercise 1

Chapter 17: Miscellaneous Tools

Introduction
Copying the Sketches
Scaling the Sketches
Finding the Center of Gravity
Extracting the iFeature
Inserting the iFeature
Creating iMates
Applying iMates in the Assembly Environment Interactively place with iMates
Automatically generate iMates on place
Viewing the iProperties
Creating User-Defined Drawing Sheets
Importing AutoCAD Blocks into Inventor
Tutorial 1
Tutorial 2

Self-Evaluation Test
Review Questions
Exercise 1

Chapter 18: Introduction to Stress Analysis

Introduction to FEA 1
Types of Engineering Analysis
Structural Analysis
Thermal Analysis
Fluid Flow Analysis
Electromagnetic Field Analysis
Coupled Field Analysis
General Procedure to Conduct Finite Element Analysis FEA through Software
Important Terms and Definitions
Strength
Load
Stress
Strain
Elastic Limit
Ultimate Strength
Factor of Safety
Lateral Strain
Poisson's Ratio
Bulk Modulus
Stress Concentration
Bending
Bending Stress
Creep
Degrees of Freedom
Stress Analysis in Autodesk Inventor 2016 1
Creating Simulation
Using the Guide Tool
Applying Stress Analysis Settings
Stress Analysis Browser Bar
Assigning Material
Assign Material
Applying Constraints
Fixed
Pin
Frictionless
Applying Loads
Force
Pressure
Bearing Load
Moment
Gravity
Remote Force

- Body
- Meshing the Component
- Mesh View
- Mesh Settings
- Local Mesh Control
- Convergence Settings
- Solution Phase of Analysis
- Postprocessing the Solutions
- Generating Report
- Animating the Results
- Tutorial 1
- Tutorial 2
- Tutorial 3
- Self-Evaluation Test
- Review Questions
- Exercise 1
- Exercise 2

Chapter 19: Introduction to Plastic Mold Design

- Introduction to Plastic Mold Design
- Invoking the Mold Environment
- Methods of Designing Core and Cavity
- Importing Plastic Part in Mold Environment
- Adding Core and Cavity by using Individual Models Adjusting Orientation and Position of the Part
- Adjusting Orientation of a Part
- Adjusting Position of the Part
- Selecting Material
- Commonly used material
- Specific Material
- Details
- Report
- Creating Core and Cavity for the Part
- Adjusting Orientation
- Specifying Gate Location
- Analyzing Part for Filling
- Specifying Shrinkage Allowance
- Defining Workpiece
- Creating Patching Surface
- Creating Planar Patches
- Creating Runoff Surface
- Generating Core and Cavity
- Creating Pattern of the Mold
- Creating a Rectangular Pattern
- Creating a Circular Pattern
- Creating a Variable Pattern
- Creating Runner of the Mold
- Creating Runner Sketch

Creating Runner
Creating Gates for the Molds
Type
Placement
Copy of all Pockets
Adding Cold Wells
Adding Mold Base to the Assembly
Standard Area
Placement Area
Layout Information Area
Adding Sprue Bushing
Adding Cooling Channel
Generating Drawing Views
Tutorial 1
Self-Evaluation Test
Review Questions
Exercise 1

Index I-1

Preface

Autodesk Inventor 2016

Autodesk Inventor, developed by Autodesk Inc., is one of the world's fastest growing solid modeling software. It is a parametric feature-based solid modeling tool that not only unites the 3D parametric features with 2D tools but also addresses every design-through-manufacturing process. The adaptive technology of this solid modeling tool allows you to handle extremely large assemblies with tremendous ease. Based mainly on the feedback of the users of solid modeling, this tool is known to be remarkably user-friendly and it allows you to be productive from day one.

This solid modeling tool allows you to easily import the AutoCAD, AutoCAD Mechanical, Mechanical Desktop, and other related CAD files with an amazing compatibility. Moreover, the parametric features and assembly parameters are retained when you import the Mechanical Desktop files in Autodesk Inventor.

The drawing views that can be generated using this tool include orthographic view, isometric view, auxiliary view, section view, detailed view, and so on. You can use predefined drawing standard files for generating the drawing views. Moreover, you can retrieve the model dimensions or add reference dimensions to the drawing views whenever you want. The bidirectional associative nature of this software ensures that any modification made in the model is automatically reflected in the drawing views. Similarly,

any modifications made in the dimensions in the drawing views are automatically reflected in the model.

Autodesk Inventor 2016 for Designers textbook is written with the intention of helping the readers effectively use the Autodesk Inventor 2016 solid modeling tool. The mechanical engineering industry examples and tutorials are used in this textbook to ensure that the users can relate the knowledge of this book with the actual mechanical industry designs. The salient features of this textbook are as follows:

- **Tutorial Approach**

The author has adopted the tutorial point-of-view and the learn-by-doing approach throughout the textbook. This approach guides the users through the process of creating the models in the tutorials.

- **Real-World Projects as Tutorials** The author has used about 54 real-world mechanical engineering projects as tutorials in this book. This enables the readers to relate these tutorials to the real-world models in the mechanical engineering industry. In addition, there are about 40 exercises that are also based on the real-world mechanical engineering projects.

- **Coverage of All Autodesk Inventor Modules** All modules of Autodesk Inventor are covered in this book including the Presentation module for animating the assemblies, the Sheet Metal module for creating the sheet metal components, the Weldment module for creating weldments, and Mold design module for creating mold.

- **Tips and Notes**

Additional information on various topics is provided to the users in the form of tips and notes.

- **Heavily Illustrated Text** The text in this book is heavily illustrated with about 1300 line diagrams and screen capture images.

- **Learning Objectives** The first page of every chapter introduces in brief the topics that are covered in that chapter. This helps the users to easily refer to a topic.

- **Command Section**

In every chapter, the description of a tool begins with the command section that gives a brief information of various methods of invoking that tool.

- **Self-Evaluation Test, Review Questions, and Exercises** Every chapter ends with Self-Evaluation Test so that the users can assess their knowledge of the chapter. The answers to the Self-Evaluation Test are given at the end of the chapter. Also, the Review Questions and Exercises are given at the end of each chapter and they can be used by the Instructors as test questions and exercises.

Formatting Conventions Used in the Textbook Please refer to the following list for the formatting conventions used in this textbook.

- Names of tools, buttons, options, panels, tabs, and Ribbon are written in boldface.
- Names of dialog boxes, drop-downs, drop-down lists, list boxes, areas, edit boxes, check boxes, and radio buttons are written in boldface.
- Values entered in edit boxes are written in boldface.
- Names and paths of the files are written in italics.
- The methods of invoking a tool/option from the **Ribbon**, **Quick Access Toolbar**, **Application Menu** are enclosed in a shaded box.

•

Ribbon: Get Started > Launch > New **Quick Access Toolbar:** New **Application Menu:** New

Example: The **Extrude** tool, the **Finish Sketch** button, the **Modify** panel, the **Sketch** tab, and so on.

Example: The **Revolve** dialog box, the **Start 2D Sketch** drop-down of **Sketch** panel in the **Model** tab, the **Placement** drop-down in the **Hole** dialog box, the **Distance** edit box of the **Extrude** dialog box, the **Extended Profile** check box in the **Rib** dialog box, the **Drilled** radio button in the **Hole** dialog box, and so on.

Example: Enter **5** in the **Radius** edit box.

Example: *C:\Inventor2016\c03, c03tut03.prt*, and so on

Naming Conventions Used in the Textbook Tool

If you click on an item in a toolbar or a panel of the **Ribbon** and a command is invoked to create/edit an object or perform some action, then that item is termed as **tool**.

For example:

To Create: Line tool, Dimension tool, Extrude tool **To Edit:** Fillet tool, Draft tool, Trim Surface tool
Action: Zoom All tool, Pan tool, Copy Object tool

If you click on an item in a toolbar or a panel of the **Ribbon** and a dialog box is invoked wherein you can set the properties to create/edit an object, then that item is also termed as **tool**, refer to Figure 1.

For example:

To Create: Create iPart tool, Parameters tool, Create tool **To Edit:** Styles Editor tool, Document Settings tool



Figure 1 Various tools in the **Ribbon**

Button

The item in a dialog box that has a 3d shape like a button is termed as **Button**. For example, **OK** button, **Cancel** button, **Apply** button, and so on.

Dialog Box

The naming conventions used for the components in a dialog box are mentioned in Figure 2.





Figure 2 The components in a dialog box

Drop-down

A drop-down is one in which a set of common tools are grouped together. You can identify a drop-down with a down arrow on it. These drop-downs are given a name based on the tools grouped in them. For example, **Arc** drop-down, **Fillet/Chamfer** drop-down, **Work Axis** drop-down, and so on; refer to Figure 3.






Figure 3 The Arc, Fillet/Chamfer, and Work Axis drop-downs

Drop-down List


A drop-down list is the one in which a set of options are grouped together. You can set various parameters using these options. You can identify a drop-down list with a down arrow on it. For example, **Extents** drop-down list, **Color Override** drop-down list, and so on, refer to Figure 4.



Figure 4 The Extents and Color Override drop-down lists

Options

Options are the items that are available in shortcut menu, Marking Menu, drop-down list, dialog boxes, and so on. For example, choose the **New Sketch** option from the Marking Menu displayed on right-clicking in the drawing area; choose the **Background Image** option from the **Background** drop-down list; choose the **Front** option from the **Orientation** area, refer to Figure 5.



*Figure 5 Options in the shortcut menu, **Background** drop-down list, and the **Style Type** area*

Free Companion Website

It has been our constant endeavor to provide you the best textbooks and services at affordable price. In this endeavor, we have come out with a Free Companion website that will facilitate the process of teaching and learning of Autodesk Inventor 2016. If you purchase this textbook, you will get access to the files on the Companion website.

To access the files, you need to register by visiting the **Resources** section at www.cadcim.com. The following resources are available for the faculty and students in this website:

Faculty Resources

- **Technical Support** You can get online technical support by contacting techsupport@cadcim.com.
- **Instructor Guide** Solutions to all review questions and exercises in the textbook are provided in this link to

help the faculty members test the skills of the students.

- **PowerPoint Presentations** The contents of the book are arranged in PowerPoint slides that can be used by the faculty for their lectures.

- **Part Files**

The part files used in illustration, tutorials, and exercises are available for free download.

Student Resources

- **Technical Support** You can get online technical support by contacting techsupport@cadcim.com.

- **Part Files**

The part files used in illustrations and tutorials are available for free download.

- **Additional Students Projects** Various projects are provided for the students to practice.

Note that you can access the faculty resources only if you are registered as faculty at www.cadcim.com/Registration.aspx

If you face any problem in accessing these files, please contact the publisher at sales@cadcim.com or the author at stickoo@purduecal.edu or tickoo525@gmail.com.

Stay Connected

You can now stay connected with us through Facebook and Twitter to get the latest information about our text books, videos, and teaching/learning resources. To stay informed of such updates, follow us on Facebook (www.facebook.com/cadcim) and Twitter ([@cadcimtech](https://twitter.com/cadcimtech)). You can also subscribe to our YouTube channel (www.youtube.com/cadcimtech) to get the information about our latest video tutorials.

Chapter 1

Introduction

Learning Objectives

- ***Understand how to open a new part file in Autodesk Inventor.***
- ***Understand various terms used in sketching environment.***
- ***Understand the usage of various hotkeys.***
- ***Customize hotkeys.***
- ***Modify the color scheme in Autodesk Inventor.***

INTRODUCTION TO AUTODESK INVENTOR 2016

Welcome to the world of Autodesk Inventor. If you are new to the world of three-dimensional (3D) design, then you have joined hands with thousands of people worldwide who are already working with 3D designs. If you are already using any other solid modeling tool, you will find this solid modeling tool more adaptive to your use. You will find a tremendous reduction in the time taken to complete a design using this solid modeling tool.

Autodesk Inventor is a parametric and feature-based solid modeling tool. It allows you to convert the basic two-dimensional (2D) sketch into a solid model using very simple, but highly effective modeling options. This solid modeling tool does not restrict its capabilities to the 3D solid output, but also extends them to the bidirectional associative drafting. This means that you only need to create the solid model. Its documentation, in the form of the drawing views, is easily done by this software package itself. You just need to specify the required view.

This solid modeling tool can be specially used at places where the concept of “**collaborative engineering**” is brought into use. Collaborative engineering is a concept that allows more than one user to work on the same design at the same time. This solid modeling package allows more than one user to work simultaneously on the same design.

As a product of Autodesk, this software package allows you to directly open the drawings of the other Autodesk software like AutoCAD, Mechanical Desktop, AutoCAD LT, and so on. This interface is not restricted to the Autodesk software only. You can easily import and export the drawings from this software package to any other software package and vice versa.

To reduce the complications of design, this software package provides various design environments. This helps you capture the design intent easily by individually incorporating the intelligence of each of the design environments into the design. The design environments that are available in this solid modeling tool are discussed next.

Part Module

This is a parametric and feature-based solid modeling environment and is used to create solid models. The sketches for the models are also drawn in this environment. All applicable constraints are automatically applied to a sketch while drawing. You do not need to invoke an extra command to apply them. Once the basic sketches are drawn, you can convert them into solid models using simple but highly effective modeling options. One of the major advantages of using Autodesk Inventor is the availability of the Design Doctor. The Design Doctor is used to calculate and describe errors, if any, in the design. You are also provided with remedy for removing errors such that the sketches can be converted into features. The complicated features can be captured from this module and can later be used in other parts. This reduces the time taken to create the designer model. These features can be created using the same principles as those for creating solid models.

Assembly Module

This module helps you create the assemblies by assembling multiple components using assembly constraints. This module supports both the bottom-up approach

as well as the top-down approach of creating assemblies. This means that you can insert external components into the **Assembly** module or create the components in the **Assembly** module itself. You are allowed to assemble the components using the smart assembly constraints and joints. All the assembly constraints and joints can be added using a single dialog box. You can even preview the components before they are actually assembled. This solid modeling tool supports the concept of making a part or a feature in the part adaptive. An adaptive feature or a part is the one that can change its actual dimensions based upon the need of the environment.

Presentation Module

A major drawback of most solid modeling tools is their limitation in displaying the working of an assembly. The most important question asked by the customers in today's world is how to show the working of any assembly. Most of the solid modeling tools do not have an answer to this question. This is because they do not have proper tools to display an assembly in motion. As a result, the designers cannot show the working of the assemblies to their clients or they have to take the help of some other software packages such as 3D Studio MAX, 3D Studio VIZ. However, this software package provides a module called the **Presentation** module using which you can animate the assemblies created in the **Assembly** module and view their working. You can also view any interference during the operation of the assembly. The assemblies can be animated using easy steps.

Drawing Module

This module is used for the documentation of the parts or assemblies in the form of drawing views. You can also create drawing views of the presentation created in the **Presentation** module. All parametric dimensions, added to the components in the **Part** module during the creation of the parts are displayed in the drawing views in this module.

Sheet Metal Module

This module is used to create a sheet metal component. When you invoke a sheet metal file, the Sketching environment is active by default. You can draw the sketch of the base sheet in this module and then proceed to the sheet metal

module to convert it into a sheet metal component.

Mold Design Module

This module is used to create mold design by integrated mold functionality and content libraries using the intelligent tools and catalogs provided in mold design module. In this module, you can quickly generate accurate mold design directly from digital prototypes.

GETTING STARTED WITH AUTODESK INVENTOR

Install Autodesk Inventor on your system; the shortcut icon of Autodesk Inventor Professional 2016 will automatically be created on the desktop. Double-click on this icon to start Autodesk Inventor.

When Autodesk Inventor is started for the first time, the system prepares itself by loading all the required files and then the initial interface of Autodesk Inventor will be displayed, as shown in Figure 1-1.




Figure 1-1 Initial interface of Autodesk Inventor

By using the tools available in the initial interface of Autodesk Inventor, you can view the recent enhancements and information related to Autodesk Inventor 2016, start new file, open an existing file, set a project, and so on. To view the enhancements and related information, choose the **Whats New** tool available in

the **Get Started** tab of the **Ribbon**. You will learn more about the **Ribbon** and respective tabs and tools available in it later in this chapter.

To start a new file, choose the **New** tool from the **Launch** panel of the **Get Started** tab in the **Ribbon**; the **Create New File** dialog box will be displayed, as shown in Figure 1-2. This dialog box is used to start a new file of Autodesk Inventor. Choose the **Metric** tab from the **Create New File** dialog box and then double-click on the **Standard (mm).ipt** template to open the default metric template. As a result, a new part file with the default name, Part1.ipt, will be opened, refer to Figure 1-3 and you can start working in this file. The figure also displays various components of the interface.




Figure 1-2 The Create New File dialog box

Alternatively, to start a new part file, you can choose the **New Part** button from the **New** area in the initial interface of Autodesk Inventor, refer to Figure 1-1.

Note that on choosing this button, the part file will be invoked with the default template.

It is evident from Figure 1-3 that the screen of Autodesk Inventor is quite user-friendly. Apart from the components shown in Figure 1-3, you are also provided with various shortcut menus which are displayed on right-clicking in the drawing area. The type of the menu and its options depend on where or when you are trying to access the menu. For example, when you are inside any command, the options displayed in the shortcut menu will be different from the options displayed when you are not inside any command. The different types of shortcut menus will be discussed when they are used in the textbook.




Figure 1-3 Components of Autodesk Inventor interface

Quick Access Toolbar

This toolbar is common to all the design environments of Autodesk Inventor. However, some of these options will not be available when you start Autodesk Inventor for the first time. You need to add them using the down arrow given on the right of the **Quick Access Toolbar**, as shown in Figure 1-4. Some of the important options in this toolbar are discussed next.




Figure 1-4 The Quick Access Toolbar

Select

Select tools are used to set the selection priority. If you choose the down arrow on the right of the active select tool, a selection drop-down list will be displayed, refer to Figure 1-5. The **Select Bodies** tool is chosen to set the selection priority for bodies. If this tool is chosen, you can select any individual body in the model. If you choose the **Select Features** tool, you can select any feature in the model. The **Select Faces and Edges** tool is chosen to set the priority for faces and edges. The **Select Sketch Features** tool is chosen to set the priority for the sketched entities. The **Select Groups** and **Select Wires** tools will be activated in their respective environments when the different groups and wires become available.




Figure 1-5 Selection drop-down list

Return

This tool is activated in the sketching environment and is used to exit from the sketching environment. Once you have finished drawing a sketch, choose this tool to proceed to the **Part** module. In the **Part** module, you can convert the

sketch into a feature using the required tools.

Note

*If the **Return** tool is not available in the **Quick Access Toolbar**, you need to add it. To do so, choose the down arrow on the right of the **Quick Access Toolbar**; a flyout is displayed. Next, choose the **Return** option from the flyout.*

Update/Local Update

This tool is chosen to update a design after modifying.

Appearance Override

You can use this drop-down list to apply different types of colors or styles to the selected features or component to improve its appearance. It is much easier to identify different components, parts, and assemblies when proper color codes are applied to them.

MATERIAL DROP-DOWN

You can use the options in this drop-down list to apply different types of materials to the selected features or component.

RIBBON AND TABS

You might have noticed that there is no command prompt in Autodesk Inventor. The complete designing process is carried out by invoking the commands from the tabs in the **Ribbon**. The **Ribbon** is a long bar available below the **Quick Access Toolbar**. You can change the appearance of the **Ribbon** as per your need. To do so, right-click on it; a shortcut menu will be displayed. Choose **Ribbon Appearance** from this shortcut menu to invoke a cascading menu. Next, choose the required option from the cascading menu.

Autodesk Inventor provides you with different tabs while working with various design environments. This means that the tabs available in the **Ribbon** while working with the **Part**, **Assembly**, **Drawing**, **Sheet Metal**, and **Presentation** environments will be different.

In addition to the default tools available in a tab, you can also customize the tab by adding more tools. To do so, choose the **Customize** button from the **Options**

panel of the **Tools** tab in the **Ribbon**; the **Customize** dialog box will be displayed. Make sure that the **Ribbon** tab of the dialog box is chosen. Next, select the **All commands** option from the **Choose commands from** drop-down list, if not selected by default; a list of all the commands/tools will be displayed on the left hand side in the dialog box. Next, select the required tool to be added from the list and then from the **Choose tab to add custom panel to** drop-down list, select the required tab to which the selected tool is to be added. Next, choose the **Add** button which is represented as double arrows and then choose the **Apply** button to add the tool. Similarly you can add multiple tools to the required tab of the Ribbon. Once you are done, close the **OK** button to exit the dialog box.

*Tip. In Autodesk Inventor, the messages and prompts are displayed at the **Status Bar** which is available at the lower left corner of the Autodesk Inventor window.*

Sketch Tab

This is one of the most important tabs in the **Ribbon**. All the tools for creating the sketches of the parts are available in this tab. Most of the tools of the tab will be available on invoking the sketching environment. The **Sketch** tab is shown in Figure 1-6.




Figure 1-6 The Sketch tab

Inventor Precise Input Toolbar

Inventor provides you with the **Inventor Precise Input** toolbar to enter precise values for the coordinates of the sketcher entities. This toolbar is also available in the **Drawing** and **Assembly** modules. The **Inventor Precise Input** toolbar is shown in Figure 1-7. Note that this toolbar is not available by default. You will learn more about this toolbar in chapter 2.




Figure 1-7 The Inventor Precise Input toolbar

3D Model Tab

This is the second most important tab provided in the **Part** module. Once the sketch is completed, you need to convert it into a feature using the modeling commands. This tab provides all the modeling tools that can be used to convert a sketch into a feature. The tools in the **3D Model** tab are shown in Figure 1-8.



Figure 1-8 The **3D Model** tab

The **Start 2D Sketch** button in the **Sketch** panel of the **3D Model** tab is used to invoke the sketching environment to draw 2D sketch. As the first feature in most of the designs is a sketched feature, therefore you first need to create the sketch of the feature to be created. Once you have completed a sketch, you can choose either the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab in the **Ribbon** or the **Return** button from the **Quick Access Toolbar**.

Sheet Metal Tab

This tab provides the tools that are used to create sheet metal parts. This toolbar will be available only when you are in the sheet metal environment. You can switch from the **Modeling** environment to the **Sheet Metal** environment by choosing the **Convert to Sheet Metal** tool from the **Convert** panel of the **3D Model** tab in the **Ribbon**. If the **Convert** panel is not available in the **3D Model** tab, you need to customize to add it. You will learn more about customizing later in this book. The tools in the **Sheet Metal** tab are shown in Figure 1-9.




Figure 1-9 The **Sheet Metal** tab

Assemble Tab

This tab will be available only when you open any assembly template (with extension **.iam**) from the **Create New File** dialog box. This tab provides you all

the tools that are required for assembling components. The tools in the **Assemble** tab are shown in Figure 1-10.




Figure 1-10 *The Assemble tab*

Place Views Tab

This tab provides the tools that are used to create different views of the components. This tab will be available only when you are in the **Drafting** environment. The tools in the **Place Views** tab are shown in Figure 1-11.




Figure 1-11 *The Place Views tab*

Presentation Tab

This tab provides the tools that are used to create different presentation views of the components. This tab will be available only when you open any presentation template (with extension *.ipn*) in the **Create New File** dialog box. The tools in the **Presentation** tab are shown in Figure 1-12.



Figure 1-12 *The Presentation tab*

Tools Tab

This tab contains tools that are mainly used for setting the preferences and customizing the Autodesk Inventor interface. This tab is available in almost all the environments. The tools in the **Tools** tab are shown in Figure 1-13.




Figure 1-13 The Tools tab

View Tab

The tools in this tab enable you to control the view, orientation, appearance, and visibility of objects and view windows. This tab is available in almost all the environments. The tools in the **View** tab are shown in Figure 1-14.




Figure 1-14 The View tab

The tools of a particular tab are arranged in different panels in the **Ribbon**. Some of the panels and tools have an arrow on the right, refer to Figure 1-15. These arrows are called down arrows. When you choose these down arrows, some more tools will be displayed in the drop-downs, see Figure 1-15.




Figure 1-15 More tools displayed on choosing the down arrow on the right of a tool in the **Ribbon**

Navigation Bar

The **Navigation Bar** is located on the right of the graphics area and contains tools that are used to navigate the model in order to make the designing process easier and quicker. The navigation tools also help you to control the view and orientation of the components in the drawing window. The **Navigation Bar** is shown in Figure 1-16.




Figure 1-16 The **Navigation Bar**

Browser Bar

The **Browser Bar** is available below the **Ribbon**, on the left in the drawing window. It displays all the operations performed during the designing process in a sequence. All these operations are displayed in the form of a tree view. You can undock the **Browser Bar** by dragging it. The contents of the **Browser Bar**

are different for different environments of Autodesk Inventor. For example, in the **Part** module, it displays various operations that were used in creating the part. Similarly, in the **Assembly** module, it displays all the components along with the constraints that were used to assemble them.

UNITS FOR DIMENSIONS

In Autodesk Inventor, you can set units at any time by using the **Document Settings** dialog box. You can invoke this dialog box by choosing the **Document Settings** tool from the **Options** panel in the **Tools** tab. After invoking this dialog box, choose the **Units** tab in the **dialog** box; various areas related to the units will be displayed. The options in the **Units** area are used to set the units. To set the unit for linear dimension, select the required unit from the **Length** drop-down. Similarly, to set the unit for angular dimension, select the required unit from the **Angle** drop-down. Next, choose the **OK** button to apply the specified settings and close the dialog box. If you want to apply the specified settings without closing the dialog box, choose the **Apply** button. If you choose the **Apply** button, the **OK** button is replaced by **Close**. Now, you can choose the **Close** button to close the dialog box.

IMPORTANT TERMS AND THEIR DEFINITIONS

Before you proceed further in Autodesk Inventor, it is very important for you to understand the following terms widely used in this book.

Feature-based Modeling

A feature is defined as the smallest building block that can be modified individually. In Autodesk Inventor, the solid models are created by integrating a number of building blocks. Therefore, the models in Autodesk Inventor are a combination of a number of individual features. These features understand their fit and function properly. As a result, these can be modified whenever required. Generally, these features automatically adjust their values if there is any change in their surroundings.

Parametric Modeling

The parametric nature of a software package is its ability to use the standard properties or parameters to define the shape and size of a geometry. The main function of this property is to derive the selected geometry to a new size or shape

without considering its original size or shape. For example, a line of 20 mm that was initially drawn at an angle of 45 degrees can be derived to a line of 50 mm and its orientation can be changed to 90°. This property makes the designing process very easy as now you can draw a sketch with some relative dimensions and then can use this solid modeling tool to drive to the required actual values.

Bidirectional Associativity

As mentioned earlier, this solid modeling tool does not restrict its capabilities to the 3D solid output. It is also capable of highly effective assembly modeling, drafting, and presentations. There exists a bidirectional associativity between all these environments of Autodesk Inventor. This link ensures that if any modification is made in the model in any the environments, it is automatically reflected in the other environments as well.

Adaptive

This is a highly effective property that is included in the designing process of this solid modeling tool. In any design, there are a number of components that can be used in various places with a small change in their shape and size. This property makes the part or the feature adapt to its environment. It also ensures that the adaptive part changes its shape and size as soon as it is constrained to other parts. This considerably reduces the time and effort required in creating similar parts in the design.

Design Doctor

The Design Doctor is one of the most important parts of the designing process used in the Autodesk Inventor software. It is a highly effective tool to ensure that the entire design process is error free. The main purpose of the Design Doctor is to make you aware of any problem in the design. The Design Doctor works in the following three steps:

Selecting the Model and Errors in the Model

In this step, the Design Doctor selects the sketch, part, assembly, and so on and determines the errors in it.

Examining Errors

In this step, it examines the errors in the selected design. Each of the errors is individually examined.

Providing Solutions for Errors

This is the last step of the working of the Design Doctor. Once it has individually examined each of the errors, it suggests solutions for them. It provides you with a list of methods that can be utilized to remove the errors from the design.

Constraints

These are the logical operations that are performed on the selected design to make it more accurate or to define its position with respect to some other design. There are four types of constraints in Autodesk Inventor. All these types are explained next.

Geometric Constraints

These logical operations are performed on the basic sketching entities to relate them to the standard properties like collinearity, concentricity, perpendicularity, and so on. Autodesk Inventor automatically applies these geometric constraints to the sketcher entities at the time of their creation. You do not have to use an extra command to apply these constraints on to the sketcher entities. However, you can also manually apply these geometric constraints on to the sketcher entities. There are twelve types of geometric constraints.

Perpendicular Constraint

This constraint is used to make the selected line segment normal to another line segment.

Parallel Constraint

This constraint is used to make the selected line segments parallel.

Coincident Constraint

This constraint is used to make two points or a point and a curve coincident.

Concentric Constraint

This constraint forces two selected curves to share the same center point. The curves that can be made concentric are arcs, circles, or ellipses.

Collinear Constraint

This constraint forces two selected line segments or ellipse axes to be placed in the same line.

Horizontal Constraint

This constraint forces the selected line segment to become horizontal.

Vertical Constraint

This constraint forces the selected line segment to become vertical.

Tangent

This constraint is used to make the selected line segment or curve tangent to another curve.

Equal

This constraint forces the selected line segments to become equal in length. It can also be used to force two curves to become equal in radius.

Smooth

This constraint adds a smooth constraint between a spline and another entity so that at the point of connection, the line is tangent to the spline.

Fix

This constraint fixes the selected point or curve to a particular location with respect to the coordinate system of the current sketch.

Symmetric

This constraint forces the selected sketched entities to become symmetrical about a sketched line segment which may or may not be a center line.

Assembly Constraints

The assembly constraints are the logical operations performed on the components in order to bind them together to create an assembly. These constraints are applied to reduce the degrees of freedom of the components. There are five types of assembly constraints which are discussed next.

Mate

The **Mate** constraint is used to make the selected faces of different components coplanar. The model can be placed facing the same direction or the opposite direction. You can also specify some offset distance between the selected faces.

Angle

The **Angle** constraint is used to place the selected faces of different components at some angle with respect to each other.

Tangent

The **Tangent** constraint is used to make the selected face of a component tangent to the cylindrical, circular, or conical faces of the other component.

Insert

The **Insert** constraint forces two different circular components to share the orientation of the central axis. It also makes the selected faces of the circular components coplanar.

Symmetry

The **Symmetry** constraint is used to make two selected components symmetric to each other about a symmetric plane so that both components remain equidistant from the plane.

Assembly Joints

The assembly joints are the logical operations performed on the components in order to join them together to create an assembly. These joints allow motion between the connected components or in the assembly. There are seven types of assembly joints which are discussed next.

Automatic

The Automatic joint is used to automatically apply best suitable type of joints between the connecting components of the assembly. The type of joint to be applied automatically will depend upon the selected geometry.

Rigid

The Rigid joint removes all the degrees of freedom from the component. As a result, the components after applying rigid joints can not move in any

direction. The Rigid joint is used to fix two parts rigidly. All the DOFs between the selected parts get eliminated and act as a single component when any motion will be applied to any of the direction.

Rotational

The Rotational joint allows the rotational motion of a component along the axis of a cylindrical component.

Slider

The Slider joint allows the movement of a component along a specified path. The component will be joined to translate in one direction only. You can specify only one translation degree of freedom in slider joint. Slider joint are used to simulate the motion in linear direction.

Cylindrical

The Cylindrical joint allows a component to translate along the axis of a cylindrical component as well as rotate about the axis. You can specify one translation degree of freedom and one rotational degree of freedom in the Cylindrical joint.

Planar

The Planar joint is used to connect the planar faces of two components. The components can slide or rotate on the plane with two translation and one rotational degree of freedom.

Ball

The Ball joint is used to create a joint between two components such that both the components remain in touch with each other and at the same time the movable component can freely rotate in any direction. To create a ball joint between two components, you need to specify one point from each component. The joints thus created will generate three undefined rotational DOFs and restrict the other three DOFs at a common point.

Motion Constraints

The motion constraints are the logical operations performed on the components that are assembled using the assembly constraints. There are two types of motion constraints that are discussed next.

Rotation

The **Rotation** constraint is used to rotate one component of the assembly in relation to the other component.

Rotation-Translation

The **Rotation-Translation** constraint is used to rotate the first component with respect to the translation of the second component.

Transitional Constraints

The transitional constraints are also applied on the assembled components and are used to ensure that the selected face of the cylindrical component maintains contact with the selected faces of the other component when you slide the cylindrical component.

UCS to UCS Constraint

This constraint is used to constrain two components together by their UCSs.

Consumed Sketch

A consumed sketch is a sketch that is utilized in creating a feature using tools such as **Extrude**, **Revolve**, **Sweep**, **Loft**, and so on.

STRESS ANALYSIS ENVIRONMENT

In Autodesk Inventor Professional, you are provided with stress analysis environment which is an analysis tool to execute the static and modal stress analysis. You can calculate the displacement and stresses developed in a component with the effect of material and various loading conditions applied on a model. A component fails when the stress applied on it goes beyond a permissible limit. Figure 1-17 shows the Displacement plot of leaf spring designed in Autodesk Inventor and analyzed using the analysis tools.




Figure 1-17 *The resultant model with Displacement Select other behavior*

While working on the complicated models, sometimes you may need to select the entities that are not visible in the current view or are hidden behind other entities. To do so, Autodesk Inventor provides you with the **Select Other** feature automatically displayed when you hover the cursor at a point where more than one entity is available. To select any entity, click on the down arrow; a flyout will be displayed. Select the desired entity from the flyout; the selected entity will be displayed in blue. Figure 1-18 shows the **Select Other** flyout displayed in the modelling environment. You can use this tool in all the modes and environments of Autodesk Inventor.




Figure 1-18 *Selecting the entities from the **Select Other** flyout*

HOTKEYS

As mentioned earlier, there is no command prompt in Autodesk Inventor. However, you can use the keys on the keyboard to invoke some tools. The keys

that can be used to invoke the tools are called hotkeys. Remember that the working of the hotkeys will be different for different environments. The use of hotkeys in different environments is given next.

Part Module

The hotkeys that can be used in the **Part** module and their functions are given next.

Hotkey	Function
E	Invokes the Extrude tool
R	Invokes the Revolve tool
H	Invokes the Hole tool
CTRL+SHIFT+L	Invokes the Loft tool
CTRL+SHIFT+S	Invokes the Sweep tool
F	Invokes the Fillet tool
CTRL+SHIFT+K	Invokes the Chamfer tool
CTRL+SHIFT+M	Invokes the Mirror tool
CTRL+SHIFT+R	Invokes the Rectangular Pattern tool
CTRL+SHIFT+O	Invokes the Circular Pattern tool
F6	Invokes the Home view
]	Invokes the Work Plane tool
/	Invokes the Work Axis tool
.	Invokes the Work Point tool
CTRL+W	Invokes the SteeringWheels

The following hotkeys are used in the Sketching environment:

Hotkey	Function
L	Invokes the Line tool
D	Invokes the Dimension tool

X	Invokes the Trim tool
F7	Invokes the Slice Graphics tool
F8	Displays all constraints
F9	Hides all constraints

Assembly Module

In addition to the hotkeys of the part modeling tool, the following hot keys can also be used in the **Assembly** module:

Hotkey	Function
P	Invokes the Place tool
N	Invokes the Create tool
C	Invokes the Constraint tool
V	Invokes the Move Component tool
G	Invokes the Rotate Component tool

Drawing Module

The hotkeys that can be used in the **Drawing** module are given next.

Hotkey	Function
B	Invokes the Balloon tool
D	Invokes the Dimension tool
O	Invokes the Ordinate Set tool
F	Invokes the Feature Control Frame tool


In addition to these keys, you can also use some other keys for the ease of designing. Note that you will have to hold some of these keys down and use them in combination with the pointing device. These hotkeys are given next.

Hotkey	Function
F1	Invokes the Help command

F2	Invokes the Pan tool
F3	Invokes the Zoom tool
F4	Invokes the Free Orbit tool
F5	Previous view
SHIFT+F5	Next view
ESC	Aborts the current command
SPACEBAR	Invokes the recently used tool
T (In Presentation module)	Invokes the Tweak Components tool

Customizing Hotkeys

You can customize the settings of hotkeys. To do so, choose the **Customize** tool from the **Options** panel of the **Tools** tab in the **Ribbon**; the **Customize** dialog box will be displayed. Next, choose the **Keyboard** tab; a list of all the available commands will be displayed, as shown in Figure 1-19. The options corresponding to the **Keyboard** tab are discussed next.



*Figure 1-19 The **Customize** dialog box displaying various commands in the **Keyboard** tab*

Categories

Select the required category of command from this drop-down list; the commands related to the selected category will be listed in the list box.

Filter

You can further shortlist the displayed commands from this drop-down list. If you select the **All** option, all the commands related to the selected category will be displayed. If you select the **Assigned** option, then the commands to which the hotkeys are assigned will be displayed. Similarly, if you select the **Unassigned** option, then the commands to which the hotkeys are not assigned will be displayed.

List Box

The list box has four columns: **Keys**, **Command Name**, **Type**, and **Category**. The **Key** column displays the hotkeys assigned to the commands. The name of the command, its type, and category will be listed in the **Command Name**, **Type**, and **Category** columns, respectively. To assign hotkeys to a tool, click in the **Keys** column that is associated to the command; an edit box will be displayed. In this edit box, enter the shortcut key that you want to assign. To accept the settings, click on the tick-mark provided at the right side of this edit box. Else, click on the cross-mark provided next to the tick-mark.

Reset All Keys

The **Reset All Keys** button is used to remove all the customized hotkeys and restore the default hotkeys.

Copy to Clipboard

Choose this button to copy the contents of the **Keyboard** tab and paste them to other document.

Import

Choose this button to restore the customized settings from the .xml format. Note that before importing the file, all the Autodesk Inventor files must be closed.

Export


Choose this button to save the customized settings in the .xml format. Make sure that all the Autodesk Inventor files are closed before choosing this button.

Close

Choose this button to close the **Customize** dialog box.

CREATING THE SKETCH

After starting Autodesk Inventor, you can start creating model in the **Part** environment. But before creating the model, you need to create its sketch in the **Sketching** environment. To do so, choose the **Start 2D Sketch** tool from the **Sketch** drop-down in the **Sketch** panel of the **3D Model** tab, see Figure 1-20. On choosing this tool, the Sketching environment is invoked and you can create 2D sketches. If you choose the **Start 3D sketch** tool from the **Sketch** panel, you can create 3D sketches.



*Figure 1-20 Tools in the **Sketch** drop-down*

MARKING MENU

Marking menu is a type of menu that consists of tools and options which are commonly used in Autodesk Inventor software in different environments. Marking menu replaces the conventional right-click context menu. The Marking menu consists of different tools in different environments. For example, in the Sketching environment, the Marking menu consists of commonly used tools such as **Create Line**, **Two Point Rectangle**, **Done [ESC]**, **Trim**, **General Dimensions**, and so on. In the Modeling environment, it consists of tools and options such as **Extrude**, **Fillet**, **Hole**, **New Sketch**, and so on.

You can invoke a tool in Marking menu by using two modes: Marking mode and Menu mode. To invoke the Marking menu using the Menu mode, right-click anywhere in the graphic window; all the menu items surrounding the cursor will be displayed. After invoking the Marking menu, you can choose the desired tool or option from it. To do so, move the cursor toward the desired tool; the tool is highlighted along with a marker ray. Next, choose the highlighted tool to invoke it.

The other mode, Marking mode, is also known as gesture behavior. It helps you to mark a trail and choose the desired tool. To choose a tool in the Marking mode, right-click and drag the cursor immediately in the direction of the desired tool.

Figure 1-21 shows a Marking menu invoked in the Sketching environment and Figure 1-22 shows a Marking menu which is invoked in the Modeling environment.

*Tip. You can modify the tools listed in the Marking Menu. You can also turn the Marking Menu feature on or off using the options in the **User Interface** flyout in the **Windows panel** of the **View** tab in the **Ribbon**.*

COLOR SCHEME

Autodesk Inventor allows you to use various color schemes to set the background color of the screen and for displaying the entities on the screen. Note that this book uses the **Presentation** color scheme with a single color background. To change the color scheme, choose the **Application Options** tool from the **Options** panel of the **Tools** tab in the **Ribbon**; the **Application Options** dialog box will be displayed. Choose the **Colors** tab to display the predefined colors. Next, select the **Presentation** option from the **Color scheme** list box in the **Colors** tab. Select **1 Color** from the drop-down list in the **Background** area, refer to Figure 1-23. Choose **Apply** to apply the color scheme to the Autodesk Inventor environment, and then choose **Close**. Note that all the files you open henceforth will use this color scheme.

Figure 1-21 Marking menu available in the sketching environment



Figure 1-21 Marking menu available in the sketching environment




Figure 1-22 Marking menu available in the modeling environment




Figure 1-23 The *Application Options* dialog box with the required options set in the *Colors* tab

Answer the following questions and then compare them to those given at the end of this chapter:

1. You can invoke the **Line** tool by using the _____ hotkey.
2. Press _____ to invoke the recently used tool.
3. Choose the _____ button from the **Customize** dialog box to restore the customized settings in the .xml format.
4. When you start a new session of Autodesk Inventor Professional 2016, only the **Start a new file** button will be available in the **Quick Launch** area of the **Open** dialog box. (T/F)

5. The **Inventor Precise Input** toolbar is used to specify the precise values for the coordinates of the sketcher entities. (T/F)
6. The tools in the **3D Model** tab enable you to control the view, orientation, appearance, and visibility of objects and view windows. (T/F)

Answer the following questions:

1. You can use the _____ drop-down list to apply different types of colors or styles to the selected feature or component to improve its appearance.
2. You can invoke the **Analyze Interference** tool from the **Assembly** module by pressing the _____ key.
3. The _____ button is used to draw a 2D sketch in the Sketching environment and is chosen by default when you start a new file in the **Part** module.
4. There are twelve types of geometric constraints in Autodesk Inventor. (T/F)
5. Design Doctor works in five steps. (T/F)
6. You can invoke the **Trim** tool by pressing the X key. (T/F)

Answers to Self-Evaluation Test

1. L, 2. SPACEBAR, 3. Import, 4. T, 5. T, 6. F

Chapter 2

Drawing Sketches for Solid Models

Learning Objectives

After completing this chapter, you will be able to:

- Start a new template file to draw sketches.

- **Set up the sketching environment.**
- **Use various drawing display tools.**
- **Understand the sketcher environment in the Part module.**
- **Get acquainted with sketcher entities.**
- **Specify the position of entities by using dynamic input.**
- **Draw sketches by using various sketcher entities.**
- **Delete sketched entities.**

THE SKETCHING ENVIRONMENT

Most of the designs created in Autodesk Inventor consist of sketched and placed features. A sketch is a combination of a number of two-dimensional (2D) entities such as lines, arcs, circles, and so on. The features such as extrude, revolve, and sweep that are created by using 2D sketches are known as sketched features. The features such as fillet, chamfer, thread, and shell that are created without using a sketch are known as placed features. In a design, the base feature or the first feature is always a sketched feature. For example, the sketch shown in Figure 2-1 is used to create the solid model shown in Figure 2-2. In this figure, the fillets and chamfers are the placed features.

Figure 2-1 The basic sketch for the solid model




Figure 2-2 A solid model created using the sketched and placed features

Once you have drawn the basic sketch, refer to Figure 2-1, you need to convert it into a solid model using solid modeling tools.

You can create sketches in Sketching environment. This environment of Autodesk Inventor can be invoked at any time in the **Part** module or in the **Assembly** module. Unlike other solid modeling programs, here you just need to invoke the **Start 2D Sketch** tool and specify the plane to draw sketch; the Sketching environment will be invoked. You can draw a sketch in this environment and then proceed to the part modeling environment for converting the sketch into a solid model. The options in the Sketching environment will be discussed later in this chapter.

Initial Interface of Autodesk Inventor When you start Autodesk Inventor, the initial interface is displayed with the **Get Started** tab chosen by default, as shown in Figure 2-3. The **Launch** panel of this tab contains options

such as **New**, **Open**, **Projects**, and **Open Samples**. These options will be discussed later. By choosing the **Home** option from the **My Home** panel, you can start and open the recent file. The **Team Web** option allows you to attach any required website or HTML file for easy access. You can access the Autodesk help by using the **Help** option and can navigate to the previous page with the help of the **Back** option. By choosing the **What's New** option from the **New Feature** panel of the **Ribbon**, you can view all the enhancements in Autodesk Inventor 2016. You can watch the introductory videos, import files from other CAD Systems, and access resources from the web in the **Videos and Tutorials** panel of the **Get Started** tab of the **Ribbon**.

The initial interface of inventor consists of the **New** and **Recent Documents** areas and various tabs. Using the options in the **New** area, you can start new part, assembly, drawing, and presentation file. On choosing the **Configure Default Template** button from this area, the **Configure Default Template** dialog box will be invoked, as shown in Figure 2-4. You can choose measurement units and drawing standards from this dialog box. The area on the right side of the **New** area consists of the **Projects**, **Shortcuts**, and **File Details** tabs. You can click on the **Projects** tab to set the active project file. Similarly, click on the **Shortcuts** tab to create shortcuts for fast access to project locations, files, and folders. The **File Details** tab is used to view the file information. The **Filter** option in the **Recent Documents** area is used to filter the project and file types according to user's requirements.

Note

*If any of the panels is not available by default in the **Get Started** tab of the **Ribbon**, you need to customize the **Ribbon** to add them.*




Figure 2-3 The initial interface of Autodesk Inventor 2016




Figure 2-4 The Configure Default Template dialog box

Starting a New File

 In Autodesk Inventor, you can start a new file by choosing the **New** tool from the **Launch** panel in the **Get Started** tab of the initial interface. On doing so, the **Create New File** dialog box will be displayed, refer to Figure 2-5. Alternatively, you can start a new file by choosing the **New** tool from the **Quick Access Toolbar** or by choosing the **Start a new file** button from the **Open** dialog box. You will learn more about the **Open** dialog box later in this chapter.

The options in the **Create New File** dialog box are used to select a template file for starting a design. You can select a template of English, Metric, or Mold

Design standard. To start a new metric part file, select the **Metric** option that is available under the **Template** node of the dialog box, as shown in Figure 2-5. The templates that are available on selecting the **Metric** option are discussed next.




Figure 2-5 The Create New File dialog box with the Metric node selected

.ipt Templates

Select any *.ipt* template to start a new part file for creating a solid model or a sheet metal component.

.iam Templates

Select a *.iam* template to start a new assembly file for assembling various parts. Note that if you select the *Weldment.iam* template, the **Weldment** module of Autodesk Inventor will be started.

.ipn Templates Select a *.ipn* template to start a new presentation file for animating the assembly. The **Presentation** module marks the basic difference between the Autodesk Inventor and other design tools. This module allows you to animate the assemblies created in the **Assembly** module. For example, you can create a presentation in the **Presentation** module that shows a Drill Press Vice assembly in motion.

.idw Templates

Select a *.idw* template to start a new drawing file for generating the drawing views. You can use the drawing templates of various standards that are provided in this tab, such as ANSI, ISO, DIN, GB, JIS, GOST, and BSI.

.dwg Templates

Select a *.dwg* template for creating AutoCAD drawing files. You can use the drawing templates of standards such as JIS, ISO, GB, DIN, BSI, and ANSI.

The **Project File** drop-down list in the **Create New File** dialog box displays the active project in which the new file has been started. The **Projects** dialog box can be invoked by choosing the **Projects** button from the **Create New File** dialog box.

The Open Dialog Box

The **Open** dialog box is used to open an existing file. To invoke this dialog box, choose the **Open** tool from the **Launch** panel of the **Get Started** tab. Figure 2-6 shows the **Open** dialog box. The options in the **Open** dialog box are used to open existing files. You can browse and select the file that you want to open from the list displayed in the dialog box. The preview of the selected file is displayed in the preview window located at the lower left portion in this dialog box, as shown in Figure 2-7. By default, you can open any file created in Autodesk Inventor. This is because, the **Files of type** drop-down list displays the **Autodesk Inventor Files (*.iam; .idw; .dwg; .ipt; .ipn, and *.ide)** option, By default. You can also open the files created in other solid modeling programs such as AutoCAD, Pro/ENGINEER and Creo Parametric, Alias, Catia V5, SolidWorks, NX, and so on by selecting the respective options from the **Files of type** drop-down list.




Figure 2-6 The Open dialog box




Figure 2-7 The Open dialog box showing the preview of the selected file

In addition to open an existing file, you can also start new files and setup a project by using the **Open** dialog box. To open an existing file, choose the **Start a new file** button from this dialog box. Note that on starting a new session in Autodesk Inventor, the **Start a new file** button will be active in the **Quick Launch** area of the **Open** dialog box. Choose this button; the **Create New File**

dialog box will be displayed, as shown in Figure 2-8.




Figure 2-8 The Create New File dialog box

By using the **Open** dialog box, you can also invoke the **Project** dialog box to setup a new project. To invoke the **Project** dialog box, choose the **Project** button available on the right of the **Project File** drop down list in the **Open** dialog box. You will learn more about setting a project later in this chapter.

Setting a New Project In Autodesk Inventor, a project defines all the files related to a design project you are working on. You can create new projects or retrieve the previously created projects by choosing the **Projects** tool from the **Launch** panel in the **Get Started** tab of initial interface of Autodesk Inventor. When you choose the **Projects** tool, the **Projects** dialog box will be displayed, as shown in Figure 2-8. All the project folders will be displayed in the upper half of the dialog box and the options regarding the selected project folder will be displayed in the lower half of the dialog box. To add

another project folder to this list, choose the **New** button; the **Inventor project wizard** dialog box will be displayed. The **New Vault Project** radio button is selected by default in this dialog box. Choose the **Next** button from the **Inventor project wizard** dialog box. Specify the name of the project in the **Name** text box and the location in the **Project (Workspace) Folder** text box. You can also choose the **Browse for project location** button to specify the location of the project. Next, choose the **Finish** button. Once you have specified the project folder, it will be added to the upper part of the **Projects** dialog box and its location will be displayed. When you select a project, the options related to it will be shown in the lower part of the dialog box. The **Projects** dialog box with various projects is shown in Figure 2-9. Choose the **Done** button to close the **Projects** dialog box.




Figure 2-9 The Projects dialog box

To view help about topics, press F1; the **Autodesk Inventor Help** window will be displayed. In this window, you will find help topics explaining how to use a particular tool or option of Autodesk Inventor.


Import DWG

In Autodesk Inventor, you can import **AutoCAD** files. To do so, choose **Open > Import DWG** from the **Application Menu**; the **Import** dialog box will be displayed. Browse to the desired folder and import the required AutoCAD file.

INVOKING THE SKETCHING ENVIRONMENT

To invoke the Sketching environment, choose the **Start 2D Sketch** button from the **Sketch** panel in the **3D Model** tab; three different planes namely **XY**, **YZ**, and **XZ** will be displayed in the graphics window, as shown in Figure 2-10. Select the required plane from the graphic window to invoke the Sketching environment.

Figure 2-10 Three different planes displayed in the graphics window



Introduction to the Sketching Environment

The initial interface appearance in the Sketching environment of a *Standard (mm).ipt* file after selecting the **XY** plane as the sketching plane is shown in Figure 2-11. By default, the **Ribbon** is placed at the top of the graphics window, refer to Figure 2-11. You can move this **Ribbon** anywhere in the graphics window. To do so, right-click on the **Ribbon**; a shortcut menu will be displayed. Choose the **Undock Ribbon** option from the shortcut menu; the **Ribbon** will be undocked. Now, you can drag the **Ribbon** anywhere in the graphics window. It is recommended to place (dock) the **Ribbon** at the top of the graphics window so that you can use the space efficiently. To do so, right-click on the **Ribbon** and choose **Docking Position > Top** from the shortcut menu. Alternatively, double-click on the title bar of the **Ribbon** to dock it.




Figure 2-11 Initial interface appearance in the sketching environment

SETTING UP THE SKETCHING ENVIRONMENT

It is very important to first set up the sketching environment. This has to be done before you start drawing a sketch. Setting up the sketching environment includes modifying the grids of a drawing. It is unlikely that the designs that you want to create consist of small dimensions. You will come across a number of designs that are large. Therefore, before starting a drawing, you need to modify the grid settings. These settings will depend on the dimensions of the design. The process of modifying the grid settings of a drawing is discussed next.

Modifying the Document Settings of a Sketch Before sketching, you may need to modify the settings of the Sketching environment as per your requirement. You can change the snapping distance, grid spacing, and various attributes related to line display of the sketching environment. You must have noticed that the drawing window in the sketching environment consists of a number of light and dark lines that are normal to each

other. These normal lines are called Grid lines. The Grid lines help you locate an entity, thereby helping you to draw a sketch correctly or modify an existing sketch precisely.

You can modify the document settings of a sketch. To do so, choose the **Document Settings** tool from the **Options** panel of the **Tools** tab; the **Part1 Document Settings** dialog box will be displayed. In this dialog box, choose the **Sketch** tab to display the options related to the Sketching environment, refer to Figure 2-12. The options under this tab are discussed next.




Figure 2-12 The Part1 Document Settings dialog box with the Sketch tab chosen

Snap Spacing Area

The options under this area are used to specify the snap distances.

X Edit box

This edit box is used to specify the snap spacing in the X direction.

Y Edit box

This edit box is used to specify the snap spacing in the Y direction.

Grid Display Area

The options in this area are used to control the number of major and minor lines. The minor lines are the light lines that are displayed inside the dark gray lines. The dark gray lines are called the major lines.

Snaps per minor

This spinner is used to specify the number of snap points between each minor line.

Major every minor lines

This spinner is used to specify the number of minor lines between two major lines.

Line Weight Display Options Area

The options in the **Line Weight Display Options** area allow you to control the line weight in the sketching environment. The **Display Line Weights** check box is selected by default and displays the sketches with the set line weights. If this check box is cleared, then the differences in the line weights will not be displayed in the sketch. The **Display True Line Weights** radio button, if selected, displays the line weights on screen as they would appear on paper when printed. The **Display Line Weights by Range (millimeter)** radio button, if selected, displays the line weights according to the values entered.

Note

You will have to increase the drawing display area after increasing the grid spacing.

Tip.

*You can also turn off the display of the major and minor grid lines and the axes. To turn off the display of the grid line and the axes, choose the **Application Options** tool from the **Options** panel; the **Application Options** dialog box will be displayed. Next, choose the **Sketch** tab and clear the **Grid lines**, **Minor grid***

lines, and Axes check boxes from the Display area.

SKETCHING ENTITIES GETTING ACQUAINTED WITH THE SKETCHING ENTITIES IS AN IMPORTANT PART OF LEARNING AUTODESK INVENTOR. THE MAJOR PART OF A DESIGN IS CREATED USING THE SKETCH ENTITIES. THEREFORE, THIS SECTION CAN BE CONSIDERED AS ONE OF THE MOST IMPORTANT SECTIONS OF THE BOOK. IN AUTODESK INVENTOR, THE SKETCHED ENTITIES ARE OF TWO TYPES: NORMAL AND CONSTRUCTION. THE NORMAL ENTITIES ARE USED TO CREATE A FEATURE AND BECOME A PART OF IT, BUT THE CONSTRUCTION ENTITIES ARE DRAWN JUST FOR REFERENCE AND SUPPORT, AND CANNOT BECOME A PART OF THE FEATURE. BY DEFAULT, ALL THE DRAWN ENTITIES ARE NORMAL ENTITIES. TO DRAW CONSTRUCTION ENTITIES, CHOOSE THE **CONSTRUCTION** TOOL FROM THE **FORMAT** PANEL OF THE **SKETCH** TAB. ALL THE ENTITIES DRAWN AFTER CHOOSING THE **CONSTRUCTION** TOOL WILL BE THE CONSTRUCTION ENTITIES. DESELECT THIS TOOL BY CHOOSING IT AGAIN TO DRAW NORMAL ENTITIES.

POSITIONING ENTITIES BY USING DYNAMIC INPUT IN AUTODESK INVENTOR, YOU CAN SPECIFY THE POSITION OF SKETCHING ENTITIES BY USING THE DYNAMIC INPUT WHICH CONSISTS OF TWO COMPONENTS: POINTER INPUT AND THE DIMENSION INPUT. THE POINTER INPUT IS DISPLAYED WHEN YOU INVOKE THE SKETCHING TOOLS SUCH AS **LINE**, **RECTANGLE**, **ARC**, AND IT DISPLAYS THE COORDINATES OF THE CURRENT LOCATION OF THE CURSOR. AS YOU MOVE THE CURSOR, THE COORDINATES CHANGE DYNAMICALLY. WHEN YOU SPECIFY THE FIRST POINT, THE POINTER INPUT IS DISPLAYED. THE POINTER INPUT IS DISPLAYED IN THE FORM OF CARTESIAN COORDINATES (X AND Y). IF YOU SPECIFY THE SECOND POINT OR THE SUBSEQUENT POINTS OF ENTITIES, THE DIMENSION INPUT WILL BE DISPLAYED. THE DIMENSION INPUT IS DISPLAYED IN THE FORM OF POLAR COORDINATES (LENGTH AND ANGLE).

To specify the position of sketching entities dynamically, invoke the required sketching tool and then move the cursor in the graphics window; the location of the cursor will be displayed in the cartesian coordinate in the Pointer Input. Press the TAB key and enter the X and Y coordinate values in the Pointer Input to specify the first point; you will be prompted to specify the endpoint or second point of the entity. Alternatively, you can specify the first point of the entity by

clicking in the graphics window. On doing so, the Pointer Input will be modified to the Dimension Input and the polar coordinate input fields will be displayed. To specify the endpoint or second point of the entity, enter the length and angle values in the input fields. To toggle between the length and angle input fields, use the TAB key. If you specify input values by using the Dimension Input and then use the TAB key, lock icons will be displayed on the right of the input fields. The lock icons indicate that the values defined are constrained. Figure 2-13 shows the Pointer Input of a line and Figure 2-14 shows the Dimension Input of the endpoint of a line of length 20 mm at an angle of 45 degrees.




Figure 2-13 Pointer Input of a line




Figure 2-14 Dimension Input of the endpoint of a line of length 20 mm at 45 degrees

If some sketched entities exist in the drawing window and you start creating new entities in the drawing window, an appropriate constraint symbol will be displayed near the cursor. You can control the display of the Pointer Input and Dimension Input by using the **Application Options** dialog box. This dialog box can be invoked by choosing the **Application Options** tool from the **Options** panel of the **Tools** tab. To control the display of Pointer Input and Dimension

Input, choose the **Sketch** tab in the **Application Options** dialog box. Clear the **Enable the Heads-Up Display (HUD)** check box from the **Sketch** tab and choose the **OK** button from this dialog box. As a result, the display of Pointer Input and Dimension Input will be turned off and now you cannot enter the input values of the entities dynamically.

The sketcher entities in Autodesk Inventor are discussed next.

Drawing Lines



Ribbon: Sketch > Create > Line/Spline drop-down > Line **Lines are the basic and one of the most important entities in the sketching environment. As mentioned earlier, you can draw either normal lines or construction lines. A line is defined as the shortest distance between two points. The two points are the start point and the endpoint of the line. Therefore, to draw a line, you need to define these two points. The parametric nature of Autodesk Inventor allows you to draw the initial line of any length or at any angle by just picking the points on the screen. After drawing the line, you can drive it to a new length or angle by using parametric dimensions. You can also create the line of actual length and angle directly by using the Inventor Precise Input toolbar. Both the methods of drawing the lines are discussed next.**

Drawing a Line by Picking Points in the Drawing Window This is a very convenient method to draw lines and is used extensively while sketching. When you invoke the **Line** tool from the **Create** panel, the cursor (which was initially an arrow) is replaced by crosshairs with a yellow circle at the intersection. Alternatively, you can choose the **Create Line** tool from the Marking Menu which is displayed when you right-click anywhere in the graphics window. On doing so, you are prompted to select the start point of the line or drag off the endpoint for the tangent arc. In addition, the coordinates of the current location of the cursor are displayed in the Pointer Input and also at the lower right corner of the Autodesk Inventor window. The point of intersection of the X and Y axes (black lines among grid lines) is the

origin point. If you move the cursor close to the origin, it will snap to the origin automatically. To draw a line, specify a point anywhere in the drawing window; the Pointer Input will display both length and angle values as zero. Move the cursor; a rubber-band line will start from the specified point and the length and angle values will change accordingly in the Pointer Input. One end of this rubber-band line is fixed at the point specified in the drawing window and the other end is attached to the yellow circle in crosshairs. As you move the cursor after specifying the start point of the line, the Pointer Input will display the length and angle of the current location of the line. Click at the required position in the drawing window. Alternatively, enter the required length and angle values in the Pointer Input to specify the endpoint of the line. You can use the TAB key to toggle between the length and angle values in the Pointer Input.

After specifying the endpoint of the line, a line is drawn and a new rubber-band line starts. The start point of the new rubber-band line is the endpoint of the last line and you are again prompted to specify the endpoint of the line. You can continue specifying the endpoints to draw continuous lines.

When you draw entities in Autodesk Inventor, valid constraints are applied automatically to the entities. Therefore, when you draw continuous lines, the horizontal, vertical, perpendicular, and parallel constraints are automatically applied to them. The symbol of the applied constraint is displayed on the line while drawing it. You can exit the **Line** tool by pressing the ESC key. Alternatively, you can exit the **Line** tool by right-clicking anywhere in the graphics window; a Marking Menu will be displayed. Next, choose **OK** from the Marking Menu. Figures 2-15 and 2-16 display the Perpendicular Constraint and Parallel Constraint, respectively being applied to the lines while they are being drawn.




Figure 2-15 Drawing a line using the Perpendicular Constraint




Figure 2-16 Drawing a line using the Parallel Constraint

Note

The default screen appearance in the Sketching environment can be modified for clarity. To do so, choose the **Application Options** tool from the **Options** panel of the **Tools** tab; the **Application Options** dialog box will be displayed. In the dialog box, choose the **Colors** tab and then select the **Presentation** option from the **Color scheme** list box. Next, select **1 Color** from the **Background** drop-down list, and then choose the **Apply** button from the **Application Options** dialog box. The default appearance of the screen is changed in the Sketching environment.

In Inventor, you can close a sketch that has two or more than two lines. To do so, if you have drawn two or more than two continuous lines in the drawing area then on selecting the **Close** option from the Marking menu; a line joining the endpoint of the current line and the start point of the first line will be created and the sketch will be closed. Figure 2-17 shows the **Close** option being chosen from the Marking menu to close the sketch and Figure 2-18 shows the closed sketch created. Note that the **Close** option will not be displayed in the Marking menu once you terminate the creation of continuous lines.




Figure 2-17 Choosing the Close option from the Marking Menu




Figure 2-18 Closed sketch created

Drawing a Line by using the Inventor Precise Input toolbar This is another method of drawing lines in Autodesk Inventor. In this method, you use the **Inventor Precise Input** toolbar to define the coordinates of the start point and the endpoint of lines. To display the **Inventor Precise Input** toolbar for the line, first invoke the **Line** tool. Next, click on the down arrow displayed at bottom of the **Create** panel in the **Sketch** tab; the **Create** panel will expand. Choose the **Precise Input** tool from this panel. As mentioned earlier, the origin of the drawing lies at the intersection of the X and Y axes. The X and Y coordinates of this point are 0, 0. You can take the reference of this point to draw lines. There are two methods to define the coordinates using this toolbar. Both the methods are discussed next.

Specifying Coordinates with respect to the Origin The system that define the coordinates with respect to the origin of the drawing is termed as the absolute coordinate system. By default, the origin lies at the intersection of the X and Y axes. All the points in this system are defined with respect to this origin. To define the points, you can use the following four methods.

Defining the Absolute X and Y Coordinates: In this method, you will define the X and Y coordinates of the new point with respect to the origin. To invoke this method, select the **Indicate a point location by typing X and Y values** option from the drop-down list in the **Inventor Precise Input** toolbar. The exact X and Y coordinates of the point can be entered in the X and Y edit boxes provided in this toolbar.

Defining the Absolute X Coordinate and the Angle from the X Axis: In this method, you will define the absolute X coordinate of a point with respect to the origin and the angle that this line makes with the positive X axis. The angle will be measured in the counterclockwise direction from the positive X axis. To invoke this method, select the **Specify a point using X coordinate and angle from X axis** option from the drop-down list. The X coordinate of the new point and the angle can be defined in the respective edit boxes in the **Inventor Precise Input** toolbar.

Defining the Absolute Y Coordinate and the Angle from the X Axis: In this method, you will define the absolute Y coordinate of a point with respect to the origin and the angle that this line makes with the positive X axis. To invoke this method, select the **Specify a point using Y coordinate and angle from X axis** option from the drop-down list. The Y coordinate of the new point and the angle can be defined in the respective edit boxes in the **Inventor Precise Input** toolbar.

Specifying the Distance from the Origin and the Angle from the X Axis: In this method, you will define the distance of the point from the origin and the angle that this line makes with the X axis. To invoke this method, select the **Specify a point using distance from the origin and angle from X axis** option from the drop-down list. The distance and the angle can be defined in the respective edit boxes.

Specifying Coordinates with respect to the Last Point This system of specifying the coordinates with respect to the previous point is termed as the relative coordinate system. Note that this system of defining the points cannot be used for specifying the first point (the start point of the line). All absolute coordinate methods for specifying a point with respect to the origin can also be used with respect to the last specified point by choosing the **Precise Delta** button along with the respective method. This button will be available only after you specify the start point of the first line. The **Reset To Origin** button moves the triad to the origin of the sketch (0,0,0). The **Precise Redefine** button is used to enter a point relative to the coordinate origin.

Note

1. *While drawing continuous lines, when you move the cursor close to the start point of the first line, the color of yellow circle changes to green and the cursor snaps to the start point. On selecting the point at this stage, the loop will be closed and you will exit the current line chain.*

2. *To draw center lines, first choose the **Centerline** tool from the **Format** panel and then create lines. Alternatively, select the required entities from the drawing window and then choose the **Centerline** tool; the selected entities will become center lines.*

Restarting a Line

To restart a line, right-click in the graphics window and choose **Restart** from the Marking Menu; the start point of the line is cancelled and you are prompted to select the start point of the line.

Drawing Circles

In Autodesk Inventor, you can draw circles by using two methods. You can draw a circle by defining the center and the radius of the circle or by drawing a circle that is tangent to three specified lines. Both these methods of drawing the circle are discussed next.

Drawing a Circle by Specifying the Center Point and Radius Ribbon:
Sketch > Create > Circle drop-down > Circle Center Point This is the default method of drawing circles. In this method, you need to define

the center point and radius of a circle. To draw a circle using this method, choose the **Circle Center Point** tool from the **Create** panel, refer to Figure 2-19; you will be prompted




Figure 2-19 Tools in the **Circle** drop-down

to select the center of the circle. Specify the center point of the circle in the drawing window; you will be prompted to specify a point on the circle. Click at the required location in the drawing window to specify a point on the circumference of the circle. This point will define the radius of the circle. Alternatively, enter the required value in the Pointer Input to specify the diameter of the circle. You can also specify the center and the radius using the **Inventor Precise Input** toolbar. Figure 2-20 shows a circle drawn by using the center and the radius.

Drawing a Circle by Specifying Three Tangent Lines Ribbon: Sketch > Create > Circle drop-down > Circle Tangent

The second method of drawing circles is used to draw it tangent to three selected lines. To draw a circle using this method, choose the **Circle Tangent** tool from the **Draw** panel, refer to Figure 2-19; you will be prompted to select the first, second, and third line, sequentially. As soon as you specify the third line, a circle tangent to all the three specified lines will be drawn, as shown in Figure 2-21.




Figure 2-20 Circle drawn using the center point and radius




Figure 2-21 Circle drawn using three tangent lines

Drawing Ellipses

Ribbon: Sketch > Create > Circle drop-down > Ellipse **To draw an ellipse, choose the Ellipse tool from the Create panel; you will be prompted to specify the center of the ellipse. Select a point to specify the center of the ellipse; you will be prompted to specify the first axis point. Specify a point to define the first axis of the ellipse; you will be prompted to select a point on the ellipse. Select a point on the ellipse; the ellipse will be created. You can also specify these points using the Inventor Precise Input toolbar. However, remember that you cannot use the relative options for defining the points of the ellipse. Therefore, if you use the Inventor Precise Input toolbar for drawing the ellipse, all the values will be specified from the origin. However, you can redefine the origin by choosing the Precise Redefine button and placing it at the point that you want to define at the origin. Figure 2-22 shows an ellipse drawn in the Sketching environment.**




Figure 2-22 An ellipse drawn in the Sketching environment

Drawing Arcs

Autodesk Inventor provides three methods for drawing arcs. These methods are discussed next.

Drawing an Arc by Specifying Three Points Ribbon: Sketch > Create > Arc drop-down > Arc Three Point This is the default method of drawing arcs. To create an arc with three points, choose the **Arc Three Point** tool from the **Create** panel, see Figure 2-23, and then specify three points. The first point is the start point of the arc, the second point is the endpoint of the arc, and the third point is a point on the arc. You can define these points by specifying them in the drawing window or by using the **Inventor Precise Input** toolbar. You can also use the Pointer Input for specifying the second and the third point of the arc. Figure 2-24 shows an arc drawn using this method.




Figure 2-23 Tools in the Arc drop-down

Drawing an Arc Tangent to an Existing Entity Ribbon: Sketch > Create > Arc drop-down > Arc Tangent

This method is used to draw an arc that is tangent to an existing open entity. The open entity can be an arc or a line. To draw an arc using this method, choose the **Arc Tangent** tool from the **Create** panel (see Figure 2-23); you will be prompted to select the start point of the arc. The start point of the arc must be the start point or endpoint of an existing open entity. Once you specify the start point, a rubber-band arc will start from it. Note that this arc is tangent to the selected entity. Now, you will be prompted to specify the endpoint of the arc. Click on the drawing window to specify the endpoint of the arc. Alternatively, enter the radius and the angle values in the Pointer Input to specify the endpoint

of the arc. Here, it is very important to mention that the **Inventor Precise Input** toolbar or the Pointer Input cannot be used to select the start point of this arc. However, you can use this toolbar to specify the endpoint of this arc. Figure 2-25 shows an arc drawn tangent to the line.




Figure 2-24 Drawing the three points arc




Figure 2-25 Drawing the tangent arc

Drawing a Tangent/Normal Arcs by Using the Line Tool You can also draw a tangent or a normal arc when the **Line** tool is activated. At least a line or an arc should be drawn before drawing an arc using this method. To do so, draw a line or an arc and then invoke the Line tool; you are prompted to select the start point of the line. Move the cursor close to the point from where you want to start the tangent or normal arc, the yellow circle in the cursor turns green. Select the point at this stage; the green circle in the cursor turns gray. Press the left mouse button and drag the mouse; four construction lines appear at the start point displaying the normal and tangent directions. If you drag along

the tangent direction, a tangent arc is drawn. But if you drag along the normal direction, an arc normal to the selected entity is drawn.

Drawing an Arc by Specifying the Center, Start, and End points

Ribbon: Sketch > Create > Arc drop-down > Arc Center Point

This method is used to draw an arc by specifying the center point, start point, and endpoint of the arc. To draw an arc using this method, choose the **Arc Center Point** tool from the **Create** panel (see Figure 2-23). On doing so, you will be prompted to specify the center point of the arc. Once you specify the center point of the arc, you will be prompted to specify the start point and then the endpoint of the arc, refer to Figure 2-26. You can also specify the start point and endpoint of the arc by using the Pointer Input. In case of start point, you need to specify the radius and angle of the arc from the center point. Whereas, in case of endpoint, you need to specify the arc length in terms of angle value. You can use the TAB key to toggle between the input values of the Pointer Input. As you define the center point and the start point, the radius of the arc will be defined automatically. So, the third point is just used to define the arc length. An imaginary line is drawn from the cursor to the center of the arc. The point at which the arc intersects the imaginary line will then be taken as the endpoint of the arc, see Figure 2-27. You can also use the **Inventor Precise Input** toolbar to specify these three points of the arc.




Figure 2-26 The arc created by specifying the center, start, and end points





Figure 2-27 The imaginary line created while drawing the center point arc

Drawing Rectangles

In Autodesk Inventor, rectangles can be drawn by using various methods that are discussed next.

Drawing a Rectangle by Specifying Two Opposite Corners Ribbon:
Sketch > Create > Rectangle/Slot drop-down > Rectangle Two Point
This is the default method used to draw a rectangle specifying its two opposite corners. To draw a rectangle by using this method, choose the **Rectangle Two Point** tool from the **Create panel**, see [Figure 2-28](#); you will be prompted to specify the first corner of the rectangle and the Pointer Input will be displayed. Click at the required location to specify the first corner of the rectangle. Once you specify the first corner, you will be prompted to specify the opposite corner of the rectangle and the Pointer Input will be modified. Click to specify the second corner or enter the length and height of the rectangle in the Pointer Input. [Figure 2-29](#) shows a rectangle drawn using the **Rectangle Two Point** tool



*Figure 2-28 Tools in the **Rectangle/Slot** drop-down*

Drawing a Rectangle by Specifying Three Points on a Rectangle Ribbon: Sketch > Create > Rectangle/Slot drop-down > Rectangle Three Point You can draw a rectangle by specifying its three points. In this method, the first two points are used to define the length and angle of one of the sides of the rectangle and the third point is used to define the length of the other side. To create a rectangle by using this method, choose the **Rectangle Three Point** tool from the **Rectangle/Slot** drop-down of the **Create** panel of the **Sketch** tab, see Figure 2-28; you will be prompted to specify the first corner of the rectangle. Once you specify it, you will be prompted to specify the second corner of the rectangle. Both these corners are along the same direction. As a result, you can use these points to define the length of one side of the rectangle. After specifying the second corner, you will be prompted to specify the third corner. This corner is used to define the length of the other side of the rectangle. Note that if you specify the second corner at a certain angle, then the resultant rectangle will also be inclined. You can also specify the first, second, and third points of the rectangle by using the Pointer Input. In case of second point, you need to specify the length and angle of rectangle in the input value fields of the Pointer Input. Whereas, in case of endpoint, you need to specify the height of the rectangle. You can use the TAB key to toggle between the input values of the Pointer Input. You can

also specify the three points for drawing the rectangle using the **Inventor Precise Input** toolbar. Figure 2-30 shows an inclined rectangle drawn by using the **Three Point Rectangle** tool.





Figure 2-29 Drawing a rectangle using two points




*Figure 2-30 An rectangle draw using the **Three-Point Rectangle** tool*


Drawing a Rectangle by Specifying its Two Points Ribbon: Sketch > Create > Rectangle/Slot drop-down > Rectangle Two Point Center
You can also draw a rectangle by specifying its two points. In this method, the first point is used to define the center of the rectangle and the second point is used to define the length and width of the rectangle. To create a rectangle by using this method, choose the **Rectangle Two Point Center** tool from the **Rectangle/Slot** drop-down of the **Create** panel in the **Sketch** tab, refer to Figure 2-28; you will be prompted to specify the center of the rectangle. Click in the

Graphics window to specify it and move the cursor toward left or right; the Pointer Input will be displayed. Enter the length and width of the rectangle in the Pointer Input. Figure 2-31 shows a rectangle drawn using the **Rectangle Two Point Center** tool.

Drawing a Rectangle by Specifying Three Different Points on a Rectangle Ribbon: Sketch > Create > Rectangle/Slot drop-down > Rectangle Three Point Center You can also draw a rectangle by specifying its three points. In this method, the first point is used to define the center of the rectangle, the second point is used to define the length and orientation of the rectangle, and the third point is used to define the width of the rectangle. To create a rectangle by this method, choose the **Rectangle Three Point Center** tool from the **Rectangle/Slot** drop-down in the **Create** panel of the **Sketch** tab, refer to Figure 2-28; you will be prompted to specify the center of the rectangle. Click at the required location to specify the center; Pointer Input will be displayed. Now, move the cursor and click to specify the first corner point and orientation of the rectangle. Again, move the cursor to specify the second corner point of the rectangle. Figure 2-32 shows a rectangle drawn using the **Rectangle Three Point Center** tool.



*Figure 2-31 Drawing a rectangle by using the **Rectangle Two Point Center** tool*



*Figure 2-32 Drawing a rectangle by using the **Rectangle Three Point Center** tool*

Drawing Polygons

Ribbon: Sketch > Create > Rectangle/Slot drop-down > Polygon **The polygons drawn in Autodesk Inventor are regular polygons. A regular polygon is a multi-sided geometric figure in which the length of all sides and the angle between them are same. In Autodesk Inventor, you can draw a polygon with the number of sides ranging from 3 to 120. When you invoke the Polygon tool, the Polygon dialog box will be displayed, as shown in Figure 2-33, and you will be prompted to select the center of the polygon. The options in this dialog box are discussed next.**



Figure 2-33 The Polygon dialog box

Inscribed

This is the first button in the **Polygon** dialog box and is chosen by default. This option is used to draw an inscribed polygon. An inscribed polygon is the one that is drawn inside an imaginary circle such that its vertices touch the circle. Once you have specified the polygon center, you will be prompted to specify a point on the polygon. In case of an inscribed polygon, the point on the polygon specifies one of its vertices, see Figure 2-34.

Circumscribed

This is the second button in the **Polygon** dialog box and is used to draw a circumscribed polygon. A circumscribed polygon is the one that is drawn outside an imaginary circle such that its edges are tangent to the imaginary circle. In case of a circumscribed polygon, the point on the polygon is the midpoint of one of the polygon edges, see Figure 2-35.

Number of Sides This edit box is used to specify the number of sides of the polygon. The default value is 6. You can enter any value ranging from 3 to 120 in this edit box.

Note

The rectangles and polygons are a combination of individual lines. All the lines can be separately selected or deleted. However, when you select one of the lines and drag, the entire rectangle or polygon will be considered as a single entity. As a result, the entire object will be moved or stretched.




Figure 2-34 Drawing a six-sided inscribed polygon




Figure 2-35 Drawing a five-sided circumscribed polygon

Drawing Slots

In Autodesk Inventor, you can draw linear or arched slots by using the Slot tools available in the **Rectangle/Slot** drop-down of the **Create** panel in the **Ribbon**, refer to Figure 2-36. The methods of drawing slots are discussed next.

Drawing a Center to Center Slot

Ribbon: Sketch > Create > Rectangle/Slot drop-down > Slot Center To Center
To create a center to center slot, choose the Slot Center to Center tool from the Rectangle/Slot drop-down; you will be prompted to specify the start center point. Click in the graphics window to specify the start center point, you will be prompted to specify the end center point. Now, you can specify the end point by specifying distance in dynamic prompt or by clicking in the graphics window to specify the point. Specify the end center point; you will be prompted to specify the diameter or width of the slot. Specify the width or diameter in the dynamic prompt; the slot will be created. This type of slot is called the linear slot. Figure 2-37 shows a Center to Center Slot created.




Figure 2-36 The Slot drop-down

Drawing an Overall Slot Ribbon: Sketch > Create > Rectangle/Slot drop-down > Slot Overall To create an Overall Slot, choose the **Slot Overall** tool from the **Rectangle/Slot** drop-down; you will be prompted to specify the start point. Click in the graphics window to

specify the start point; you will be prompted to specify the end point. Now, you can specify the end point by specifying the distance in dynamic prompt or clicking in the graphics window. Specify the end point; you will be prompted to specify the diameter or width of the slot. Specify the width or diameter in the dynamic prompt; the slot will be created. This type of slot is also called the linear slot. Figure 2-38 shows an Overall Slot created.




Figure 2-37 Center to Center Slot




Figure 2-38 Overall slot

Drawing a Center Point Slot Ribbon: Sketch > Create > Rectangle/Slot drop-down > Slot Center Point To create a Center Point Slot, choose the **Slot Center Point** tool from the **Rectangle/Slot** drop-down; you will be prompted to specify the center point of the slot. Click in the graphics window to specify the center point of the slot; you will be prompted to specify the second point. You can specify the distance of the second point either by using the dynamic prompt or clicking in the graphics window. Specify the second point; you will be prompted to specify the diameter or width of the slot. Specify the width or diameter in the dynamic prompt; the slot

will be created. This type of slot is also called a linear slot. Figure 2-39 shows a Center Point Slot created.




Figure 2-39 Center Point Slot created

Drawing a Three Point Arc Slot Ribbon: Sketch > Create > Rectangle/Slot drop-down > Slot Three Point Arc To create a Three Point Arc slot, choose the **Slot Three Point Arc** tool from the **Rectangle/Slot** drop-down; you will be prompted to specify the start point of the center arc. Click in the graphics window to specify the start point of center arc; you will be prompted to specify the end point. Now you can specify the end point either by specifying length in the dynamic prompt or by clicking in the graphics window; you will be prompted to specify the third point of the center arc. Specify the third point; you will be prompted to specify the diameter or width of the slot. Specify the width or diameter in the dynamic prompt; the slot will be created. This type of slot is called the arc slot. Figure 2-40 shows a Three Point Arc slot created.




Figure 2-40 Three Point Arc Slot created

Drawing a Center Point Arc Slot Ribbon: Sketch > Create >

Rectangle/Slot drop-down > Slot Center Point Arc To create a Center Point Arc slot, choose the **Slot Center Point Arc** tool from the **Rectangle/Slot** drop-down; you will be prompted to specify the center of the Center Point Arc. Specify the center; you will be prompted to specify the start point of the arc. Specify the start point by entering angle value in the dynamic prompt; you will be prompted to specify the end point. Specify the end point by entering angle value in the dynamic prompt; you will be prompted to specify the diameter or width of the slot. Specify the width or diameter in the dynamic prompt; the slot will be created. This type of slot is also called the arc slot. Figure 2-41 shows a Center Point Arc slot created.




Figure 2-41 Center Point Arc Slot created

Placing Points


Ribbon: Sketch > Create > Point **In Autodesk Inventor, you can place the sketched points in a sketch by using the Point tool. To place a point, choose the Point tool from the Create panel of the Sketch tab; you will be prompted to select the center point. Specify the center point; a point will be placed. You can specify the location of a point in the sketch by picking a point from the graphics window or by entering the value in the Inventor Precise Input toolbar.**

Creating Fillets

Ribbon: Sketch > Create > Fillet/Chamfer drop-down > Fillet **Filletting is defined as the process of rounding the sharp corners of a sketch. This is done to reduce the stress concentration in the model and for smooth handling. Using the Fillet tool, you can round the corners of the sketch by creating an arc tangent to both the selected entities. The portions of the**

selected entities that comprise the sharp corners are trimmed when the fillet is created. When you invoke this tool from the **Fillet/Chamfer** drop-down, refer to Figure 2-42, the 2D Fillet dialog box will be displayed with the default fillet radius, as shown in Figure 2-43, and you will be prompted to select the lines or the arcs to be filleted. If you have already created some fillets, their radius values will be stored as preset values. You can select these preset values from the list that is displayed when you choose the arrow provided on the right of the edit box.


You can create any number of fillets of similar or dissimilar radii. If the **Equal** button in the **2D Fillet** dialog box is chosen, the dimension of the fillet will be placed only on the first fillet and not on the other fillets created by using the same sequence, see Figure 2-44. On modifying the dimension of the first fillet, all instances of fillet will be modified. To create fillets of independent radii values, deactivate the **Equal** button before creating fillets. The fillets thus created will show individual dimensions, see Figure 2-45. As a result, you can modify the dimension of one fillet without affecting the other. You can fillet two parallel or perpendicular lines, intersecting lines or arcs, non-intersecting lines or arcs, and a line and an arc.




*Figure 2-42 Tools in the **Fillet/Chamfer** drop-down*



Figure 2-43 The 2D Fillet dialog box



*Figure 2-44 Rectangle filleted using the same radius with the **Equal** button chosen*



*Figure 2-45 Rectangle filleted using different radii with the **Equal** button deactivated*

Creating Chamfers Ribbon: Sketch > Create > Fillet/Chamfer drop-down > Chamfer Chamfering is defined as the process of beveling the sharp corners of a sketch. This is the second method of reducing stress concentration. To chamfer sketched entities, choose the **Chamfer** tool from the **Create** panel (see Figure 2-42); the **2D Chamfer** dialog box will be displayed, as shown in Figure 2-46. Also, you will be prompted to select the lines to be chamfered. Select the lines; the chamfer will be created. The options in the **2D Chamfer** dialog box are discussed next.




Figure 2-46 The 2D Chamfer dialog box

Create Dimensions

The **Create Dimensions** button is chosen to show the dimensions of the chamfer on the sketch. When you chamfer two lines, the dimensions of the chamfer are shown in the sketch. If you choose this button again, the chamfer dimensions will not be displayed in the sketch when you create another chamfer.

Equal

The **Equal** button is chosen to create multiple chamfers with the same parameters. This button is enabled only if the **Create Dimensions** button is chosen.

Equal Distance The **Equal Distance** button is chosen to create an equal distance chamfer. The distance of the vertex along the two selected edges is the same. As a result, a 45-degree chamfer is created using this method. The distance value is specified in the **Distance** edit box. If the **Create Dimension** button is chosen, two dimensions of the same value will be shown in the sketch, as shown in Figure 2-47





Figure 2-47 Chamfer with dimension values

Unequal Distances


The **Unequal Distances** button is chosen to create a chamfer with two different distances. The distance values are specified in the **Distance1** and **Distance2** edit boxes. The distance value specified in the **Distance1** edit box is measured along the edge selected first. Similarly, the value in the **Distance2** edit box is measured along the edge selected next. Figure 2-48 shows a chamfer created by using the **Unequal Distances** button.

Distance and Angle

The **Distance and Angle** button is chosen to create a chamfer by specifying a distance and an angle. On choosing this button, the distance needs to be specified in the **Distance** edit box and the angle in the **Angle** edit box. The specified angle is measured from the first edge selected to chamfer, see Figure 2-49.



*Figure 2-48 The chamfer created using the **Unequal Distances** button*



*Figure 2-49 The chamfer created using the **Distance and Angle** button*

Tip.

1. If multiple chamfers are created with same values, the dimension value is displayed only at the first instance. At the remaining chamfers, the dimension will be displayed as fx of the value, which means the function of the original value.

2. You can also select the vertex to create a fillet or chamfer. The two entities forming the selected vertex will be filleted or chamfered using the current parameters.

Drawing Splines

Autodesk Inventor provides various methods for drawing splines. These methods are discussed next.

Drawing a Spline by Using the Spline Interpolation Tool Ribbon:

Sketch > Create > Line/Spline drop-down > Spline Interpolation To

draw a spline, choose the **Spline Interpolation** tool from the

Line/Spline drop-down of the **Create** panel, refer to Figure 2-50; you

will be prompted to specify the first point of the spline. Specify the

first point; you will be prompted to specify the next point of the

spline. This process will continue until you terminate the spline

creation. To end the spline at the current point, double-click in

the drawing window or right-click to display the Marking Menu and

choose **Create**. Note that if you choose **Cancel(ESC)** from

the Marking Menu, the spline will not be drawn. You can also end the

spline creation by pressing the ENTER key. Note that after creating a

spline, the square and diamond points will be displayed on the spline

along with the tangent handles, as shown in Figure 2-51. You can drag

these square and diamond points to modify the shape of the spline. To

exit the command, press the ESC key or choose **Cancel(ESC)** from

the Marking Menu.




Figure 2-50 Tools in the **Line/Spline** drop-down

You can undo the last drawn spline segment while drawing a spline. This can be done by choosing the **Back** option from the Marking Menu which is displayed when you right-click anywhere in the graphics window. You can also draw a spline tangent to an existing entity. To draw the tangent spline, select the point where the spline should be tangent. Next, hold the left mouse button and drag it; a construction line will be drawn, displaying the possible tangent directions for the spline. Drag the mouse in the required direction to draw the tangent spline and release the left mouse button. Figure 2-52 shows a spline drawn tangent to an existing line.

*Tip. Autodesk Inventor allows you to invoke the last used tool by right-clicking anywhere in the drawing window and choosing the **Repeat** option (**name of the last used tool**) from the Marking menu. For example, the **Repeat Line** option will be available in the Marking Menu, if the line tool was the last used tool. Alternatively, you can press the SPACEBAR key to invoke the last used tool.*



Figure 2-51 A spline drawn by specifying different points




Figure 2-52 A spline drawn tangent to a line

Drawing a Spline by Specifying Control Vertices Ribbon: Sketch > Create > Line/Spline drop-down > Spline Control Vertex To draw a spline, choose the **Spline Control Vertex** tool from the **Line/Spline** drop-down in the **Create** panel, see Figure 2-53; you will be prompted to specify the first point of the spline. Specify the start point; you will be prompted to specify the next point of the spline. This process will continue until you terminate the spline creation. To end the spline at the current point, double-click in the drawing window or right-click to display the Marking Menu and choose **Create**. Note that if you choose **Cancel (ESC)** from the Marking Menu, the spline will not be drawn. You can also end the spline creation by pressing the ENTER key. Note that after creating a spline, the control vertices will be displayed on the spline along with the tangent handles, as shown in Figure 2-54. You can drag these

control vertices to modify the shape of the spline. These control vertices act as poles for controlling the shape of the splines. Figure 2-55 shows a spline drawn tangent to a line. To exit the command, press the ESC key on the keyboard or choose **OK** from the Marking menu.




Figure 2-53 Spline Control Vertex tool to be chosen in the Line/Spline dropdown




Figure 2-54 A spline drawn by specifying different control vertices




Figure 2-55 A spline drawn tangent to a line

Creating a Smooth Curve between the Two Existing Curves Ribbon: Sketch > Create > Line/Spline drop-down > Bridge Curve In Autodesk Inventor, you can create a smooth (G2) continuous curve between two existing curves. The existing curves can be arcs, lines, splines, or projected curves. To create a smooth curve, choose the **Bridge Curve** tool from the **Line/Spline** drop-down in the **Create** panel of the **Sketch** tab, refer to Figure 2-53; you will be prompted to select the curves one after the other. Select the two curves; a smooth G2 continuous curve, known as bridge curve, will be created between the selected curves. The profile of the bridge curve depends on the position of the points selected on the existing curves. Figure 2-56 shows two points selected on the two curves and the resulting bridge curve. Figure 2-57 shows two different points selected on the curves shown in Figure 2-56 and the resulting bridge curve.




Figure 2-56 Bridge curve created between two points selected on two curves




Figure 2-57 Bridge curve created between two different points on the curves shown in Figure 2-56

DELETING SKETCHED ENTITIES

To delete a sketched entity, first ensure that no drawing tool is active. If any of them is active, press the ESC key for deactivating. Now, select the entity you want to delete using the left mouse button and then right-click to display the Marking Menu. Choose the **Delete** option from this Marking Menu. You can also press the DELETE key to delete the selected entities. To delete more than one entity, you can use a window or a crossing as discussed next.

Deleting Entities by Using a Window

A window is defined as a box created by pressing and holding the left mouse button and dragging the cursor from left to right in the drawing window. The window has a property that all the entities that lie completely inside the window

will be selected. The box defined by the window consists of continuous lines. All the selected entities will be displayed in cyan color. After selecting the entities, right-click and choose **Delete** from the Marking menu or press the DELETE key to delete all the selected entities.

Deleting Entities by Using a Crossing A crossing is defined as a box created by pressing and holding down the left mouse button and dragging the cursor from right to left in the drawing window. The crossing has a property that all entities that lie completely or partially inside the crossing or the entities that touch the crossing will be selected. The box defined by the crossing consists of dashed lines. Once the entities are selected, right-click and choose **Delete** from the Marking menu.

Tip. You can add or remove an entity from the selection set by pressing the SHIFT or the CTRL key and then selecting the entity by using the left mouse button. If the entity is already in the current selection set, it will be removed from the selection set. If not, it will be added to the set.

FINISHING A SKETCH

After creating the required sketch, you need to save it. But before you save the sketch, you need to finish the sketch and come out of the sketching environment. To do so, choose the **Finish Sketch** tool from the **Exit** panel of the **Sketch** tab; the sketch will be finished and you will switch to the **Home** view. You can also exit the sketching environment by choosing the **Finish 2D Sketch** option from the Marking menu. The **Home** view enables you to view and create the modeling features with ease. After switching to the **Modeling** environment, you can save the document.

UNDERSTANDING THE DRAWING DISPLAY TOOLS

The drawing display tools or navigation tools are an integral part of any design software. These tools are extensively used during the design process. These tools are available in the **Navigation** Bar located on the right in the graphics window and in the **Navigate** panel of the **View** tab. Some of the drawing display tools in Autodesk Inventor are discussed next. The rest of these tools will be discussed in the later chapters.

Zoom All

Ribbon: View > Navigate > Zoom drop-down > Zoom All

Navigation Bar: Zoom flyout > Zoom All **The Zoom All tool is used to increase the drawing display area to display all the sketched entities in the current display.**

Zoom

Ribbon: View > Navigate > Zoom drop-down > Zoom

Navigation Bar: Zoom flyout > Zoom The **Zoom** tool is used to interactively zoom in and out of the drawing view. When you choose this tool, the default cursor is replaced by a zoom cursor. You can zoom in the drawing by pressing the left mouse button and dragging the cursor down. Similarly, you can zoom out the drawing by pressing the left mouse button and then dragging the cursor up. You can exit this tool by choosing another tool or by pressing ESC. You can also choose **Done [Esc]** from the Marking menu, which is displayed on right-clicking. You can also zoom in the drawing by rolling the scroll wheel of the mouse in the downward direction. Similarly, you can zoom out the drawing by rolling the scroll wheel in the upward direction.

*Tip. If you need to increase the drawing display area then zoom out the drawing by using the **Zoom** tool after increasing the grid spacing.*

Zoom Window

Ribbon: View > Navigate > Zoom drop-down > Zoom Window

Navigation Bar: Zoom flyout > Zoom Window **The [Zoom Window](#) tool is used to define an area to be magnified and viewed in the current drawing. The area is defined using two diagonal points of a box (called window) in the drawing window. The area inscribed in the window will be magnified and displayed on the screen.**

Tip.

1. *The size of the dimension text always remains constant even if you magnify the area that includes some dimensions.*

2. *To switch to the previous view, right-click in the drawing window and then choose **Previous View** from the shortcut menu or press the **F5** key. You can restore nine previous views in the current sketching environment by using this option.*

Zoom Selected

Ribbon: View > Navigate > Zoom drop-down > Zoom Selected

Navigation Bar: Zoom flyout > Zoom Selected **When you choose the [Zoom Selected](#) tool, you will be prompted to select an entity to zoom. Select an entity from the drawing area; it will magnified to the maximum extent and will be placed at the center of the drawing window. This tool can also be invoked by pressing the END key.**

Pan

Ribbon: View > Navigate > Pan

Navigation Bar: Pan **The [Pan](#) tool is used to drag the current view in the drawing window. This option is generally used to display the contents of the drawing that are outside the display area without actually changing the magnification of the current drawing. It is similar to holding the drawing and dragging it across the drawing window. You can also invoke the [Pan](#) tool by pressing and holding the middle scroll wheel of the mouse.**

Orbit

Ribbon: View > Navigate > Orbit drop-down > Orbit

Navigation Bar: Orbit flyout > Orbit **The Orbit tool is used to rotate a model freely about any axis. It is useful when you want to rotate a model to any position. It is a transparent tool as it can be invoked inside any other command. You can invoke this tool by choosing the Orbit tool from the Navigate panel in the View tab. On doing so, an arcball will be displayed. This arcball is a circle with four small lines placed such that they divide the arcball into quadrants. The orbit axis is parallel to the screen and if you rotate an object by dragging the mouse pointer outside the arcball, the object will rotate about the orbit axis. Figure 2-58 shows the model to be rotated and Figure 2-59 shows the same model rotated about the vertical axis by using the Orbit tool.**




Figure 2-58 Position 1: Default view of the model




Figure 2-59 Position 2: Model rotated about the vertical axis

Note

While working with the **Orbit Tool** the viewport adjusts for better visibility and understanding.

Constrained Orbit Ribbon: View > Navigate > Orbit drop-down > Constrained Orbit

Navigation Bar: Orbit flyout > Constrained Orbit

The **Constrained Orbit** tool is used to visually maneuver around the 3D objects to obtain different views. This is one of the most important tool used for advanced 3D viewing. Figures 2-60 and 2-61 show the default view of the model, and the view after one complete rotation, respectively. When the **Constrained Orbit** tool is invoked, the cursor changes and looks like a sphere encircled by two arc-shaped arrows. This cursor is known as the Orbit mode cursor. You can click and drag the mouse to rotate the model freely. You can move the Orbit mode cursor horizontally, vertically, and diagonally. In

this case, the axis is normal to the top and bottom faces of the **ViewCube**. This is also a transparent tool as it can be invoked inside any other tool.

Tip. 1. Press and hold the **SHIFT** key and the middle mouse button to temporarily enter the **Constrained Orbit** mode.




Figure 2-60 Position 1: Default view of the model




Figure 2-61 Position 2: Model after a complete rotation

TUTORIALS

Although Autodesk Inventor is parametric in nature yet in this chapter you will use the **Inventor Precise Input** toolbar and the Dynamic Input method to draw objects. This is to ensure that you are comfortable while using various drawing options in Autodesk Inventor. In the later chapters, you will use the parametric feature of Autodesk Inventor to size or draw the entities as per the desired

dimension values.

Note

You can also choose the tools displayed by default in the Status Bar at the bottom of the graphics window.

Tutorial 1

In this tutorial, you will draw the sketch of the model shown in Figure 2-62. The sketch to be drawn is shown in Figure 2-63. Do not dimension it, as the dimensions are given only for reference. **(Expected time: 30 min)**




Figure 2-62 Model for Tutorial 1




Figure 2-63 Sketch of the model

- The following steps are required to complete this tutorial:
- Start a new Autodesk Inventor session and then start a new metric part file.
 - Invoke the **Line** tool and draw the sketch by specifying the coordinates of the points in the Dynamic Input.

c. Save the sketch with the name *Tutorial1* and close the file.

Starting Autodesk Inventor

1. Start Autodesk Inventor by double-clicking on its shortcut icon on the desktop of your computer; a new session of Autodesk Inventor is started.
2. Choose the **New** tool from the **Launch** panel of the **Ribbon**; the **Create New File** dialog box is displayed.
3. Choose **Metric** and then double-click on the **Standard (mm).ipt** icon to start a standard metric template; a new metric standard part file starts.
4. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
5. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
6. Now, select the **YZ** plane as the sketching plane from the graphics window; the Sketching environment is invoked and the **YZ** plane becomes parallel to the screen.

Note 1. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

2. *If by default the Grid lines are not displayed in the sketching environment, choose the **Application Options** button from the **Options** panel of the **Tools** tab; the **Application Options** dialog box will be invoked. Now, select the **Grid lines** check box from the **Display** area of the **Sketch** tab.*

3. *For the purpose of accuracy, Grid lines are kept ON in all the tutorials.*

Drawing the Sketch As mentioned earlier, Autodesk Inventor is parametric in nature. Therefore, you can draw the sketch from any point in the drawing

window. In this tutorial, *Dynamic Input* has been used to enter dimensions while drawing the sketch.

1. Choose the **Line** tool from the **Create** panel in the **Sketch** tab. Alternatively, choose the **Create Line** tool from the Marking Menu that is displayed on right-clicking in the drawing / Graphics window. On doing so, you are prompted to select the first point for the line. Next, choose **Precise Input** from the expanded **Create** panel of the **Sketch** tab; the **Inventor Precise Input** toolbar is displayed. Double-click on the title bar of this toolbar to dock it. If required, you can also leave this toolbar floating on the screen.

Initially, the **Precise Input** button is not enabled. This button is enabled only when you invoke a sketching tool. Since all initial settings are configured, you can now start drawing the sketch.

When you invoke the **Line** tool, the cursor is replaced by a drawing cursor that has a yellow circle at the intersection of crosshairs. When you move the crosshair in the drawing window, this circle snaps to the point that is closer to it. Also, coordinates of the current location of the cursor are displayed at the status bar.

2. To specify the first point, enter **0** in both the **X** and **Y** edit boxes of the **Inventor Precise Input** toolbar and then press ENTER; you are prompted to specify the endpoint of the line.
3. In the **Inventor Precise Input** toolbar, enter **-3** and **3** in the **X** and **Y** edit boxes, respectively. Next, press ENTER to define the endpoint of the line. On doing so, the first line of the sketch is drawn and you are prompted to select the endpoint of the line.

You will notice that the dimensions of the sketch are very small but the drawing display area is large. Therefore, you need to modify the drawing display area by using the drawing display tools. To do so, you can use the **Zoom** tool.

Tip.

You can use the **TAB** key to switch from the **X** edit box to the **Y** edit box and vice versa in the **Inventor Precise Input** toolbar.

4. Choose the **Zoom** tool from the **Navigation Bar**; the drawing cursor is changed to an arrow cursor.
5. Move the cursor to the top of the drawing window, press and hold the left mouse button and then drag the cursor downward till the display is adjusted.
6. Right-click to display the shortcut menu, and then choose **Done** to exit the **Zoom** tool.
7. Again, right-click in the graphics window and then choose **Cancel (ESC)** from the Marking Menu to exit the **Line** tool. Also, close the **Inventor Precise Input** toolbar.
8. Invoke the **Line** tool again. From this step onward, you will use the Dynamic Input to create lines in this tutorial. Select the end point of the first line that was created with the help of the **Inventor Precise Input** toolbar. Move the cursor toward left, and enter **0.5** in the length input field and **180** in the angle input field and then press ENTER. Use the TAB key to toggle between the input fields.
9. Now, you need to create the third line between points 3 and 4, refer to Figure 2-64. To do so, move the cursor downward in the graphics window. Enter **3** in the length input field, press TAB to switch to the angle input field, and enter **90** and then press ENTER; a line is created between the 3 and 4 points.
10. Move the cursor toward left in the graphics window. Enter **2** in the length input field, press TAB to switch to the angle input field, and enter **90** in it, and then press ENTER; a line is created between points 4 and 5, refer to Figure 2-64.
11. Move the cursor downward in the graphics window. Enter **1** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line is created between points 5 and 6, refer to Figure 2-64.




Figure 2-64 Sketch for Tutorial 1

12. Move the cursor toward right in the graphics window. Enter **3** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line is created between points 6 and 7.
13. Move the cursor downward in the graphics window. Enter **0.75** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line is created between points 7 and 8, refer to Figure 2-64.
14. Move the cursor toward right in the graphics window. Enter **0.5** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line is created between points 8 and 9, refer to Figure 2-64.
15. Move the cursor upward in the graphics window. Enter **0.25** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line is created between points 9 and 10, refer to Figure 2-64.
16. Move the cursor toward right in the graphics window. Enter **4** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line is created between points 10 and 11, refer to Figure 2-64.
17. Move the cursor downward in the graphics window. Enter **0.25** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line is created between points 11 and 12, refer to Figure 2-64.
18. Move the cursor toward right in the graphics window. Enter **0.5** in the length input field, press TAB and enter **90** in the angle input field and then press ENTER; a line connecting points 12 and 13 is created, refer to Figure 2-64.

19. Move the cursor upward in the graphics window. Enter **0.75** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line connecting points 13 and 14 is created, refer to Figure 2-64.
20. Move the cursor toward right in the graphics window. Enter **3** in the length input field and **90** in the angle input field and then press ENTER; a line connecting points 14 and 15 is created, refer to Figure 2-64.
21. Move the cursor upward in the graphics window. Enter **1** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line connecting points 15 and 16 is created, refer to Figure 2-64.
22. Move the cursor toward left in the graphics window. Enter **2** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line connecting points 16 and 17 is created, refer to Figure 2-64.
23. Move the cursor upward in the graphics window. Enter **3** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line connecting points 17 and 18 is created, refer to Figure 2-64.
24. Move the cursor toward left in the graphics window. Enter **0.5** in the length input field, press TAB, and enter **90** in the angle input field and then press ENTER; a line connecting points 18 and 19 is created, refer to Figure 2-64.
25. Now, to close the geometry, click on the point 1 that you created with the help of the **Inventor Precise Input** toolbar.
26. Next, right-click in the Graphics window and choose **Cancel (ESC)** from the Marking menu displayed to exit the **Line** tool.

Note

The method of applying additional constraints and using them to fully constrain the sketch will be discussed in Chapter 3.

Saving the Sketch

Remember that you cannot save a sketch in the Sketching environment. This is because the Sketching environment is just a part of the **Part** module in

Autodesk Inventor. This environment is used only for drawing the sketches of features. Therefore, you need to exit the Sketching environment to save the sketch for further use. The sketches in the **Part** module are saved in the *.ipt* format.

1. Right-click in the graphics window and then choose the **Finish 2D Sketch** button from the Marking Menu displayed; the Sketching environment is closed and you switch to the Part modeling environment. Now, choose the **Home** button of the [ViewCube](#); the current orientation of the sketch is changed to Isometric. Also, notice that the **3D Model** tab is activated in place of the **Sketch** tab. The options in the **3D Model** tab are used to create features. The options under this tab will be discussed in later chapters.
2. Choose **Save** from **Quick Access Toolbar**; the **Save As** dialog box is displayed.
3. Create a new folder with the name *Inventor_2016* in the C drive of your computer. In this folder, create another folder with the name *c02*.
4. Enter **Tutorial1** as the file name in the **File name** edit box, refer to Figure 2-65, and then choose the **Save** button from the **Save As** dialog box to save the sketch.




Figure 2-65 The Save As dialog box

5. Choose **Close > Close** from the **Application Menu** to close this file.

Tutorial 2

In this tutorial, you will draw the sketch for the model shown in Figure 2-66. The sketch to be drawn is shown in Figure 2-67. Do not dimension it, as the dimensions are given only for reference. **(Expected time: 30 min)**




Figure 2-66 Model for Tutorial 2




Figure 2-67 Dimensioned sketch for Tutorial 2

The following steps are required to complete this tutorial:

- a. Start a new metric standard part file.
- b. Draw the outer loop by specifying the length and angle lines by using the Dynamic Input method, refer to Figure 2-68.
- c. Draw the inner closed loop by using the Dynamic Input method, refer to Figure 2-69.
- d. Save the sketch with the name *Tutorial2.ipt* and close the file.

Starting a New File

1. Choose the **New** tool from the **Launch** panel of the **Get Started** tab ; the **Create New File** dialog box is displayed. In this dialog box, choose **Metric**, and then double-click on the **Standard (mm).ipt** icon to start a standard metric template.

Drawing the Sketch

As evident from Figure 2-66, the sketch consists of two nested loops: inner loop and outer loop. While extruding a nested loop, the inner loop can be subtracted from the outer loop. In this way, a cavity will be created automatically in the model when you extrude the sketch. This reduces the time and effort required in creating the inner cavity as another feature. Therefore, you can draw both the loops together for this tutorial.

1. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the

sketching plane.

2. Choose the **Home** button of the **ViewCube**; the current orientation of the sketch plane is changed 3. Now, select the **XY** plane as the sketching plane from the graphics window; the Sketching environment is invoked and the **XY** plane becomes parallel to the screen.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose *Set Current View as > Top/Front* from the flyout.

4. Choose the **Line** tool from the **Create** panel. Next, move the cursor and click when the cursor displays **-40** and **-25** in the Pointer Input or press the TAB key and then enter the X and Y coordinate values in the Pointer Input. As you specify the first point, you are prompted to specify the endpoint of the line and the Pointer Input is changed to Dimension Input.
5. Enter **80** in the length input field of the Dimension Input and press the TAB key; the angle input field becomes active. Enter **0** and then press ENTER; the first line is created and the Dimension Input is displayed again.
6. Move the cursor up and then enter **10** in the length input field of the Dimension Input. Next, press the TAB key and enter **90** in the angle input field and then press ENTER; the second line is created and the Dimension Input is displayed again.
7. Move the cursor toward the left and then enter **15** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the third line is created and the Dimension Input is displayed again.
8. Move the cursor up and then enter **30** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the fourth line is created and the Dimension Input is displayed again.
9. Move the cursor toward the right and then enter **15** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press

ENTER; the fifth line is created and the Dimension Input is displayed again.

10. Move the cursor up and then enter **10** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the sixth line is created and the Dimension Input is displayed again.
11. Move the cursor toward the left and then enter **80** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the seventh line is created and the Dimension Input is displayed again.
12. Move the cursor down and then enter **10** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the eighth line is created and the Dimension Input is displayed again.
13. Move the cursor toward the right and then enter **15** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the ninth line is created and the Dimension Input is displayed again.
14. Move the cursor down and then enter **30** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the tenth line is created and the Dimension Input is displayed again.
15. Move the cursor toward the left and then enter **15** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the eleventh line is created and the Dimension Input is displayed again.
16. Move the cursor down and then enter **10** in the length input field. Next, press the TAB key and enter **90** in the angle input field. Next, press ENTER; the twelfth line is created and the Dimension Input is displayed again.
17. Right-click to display the Marking Menu and choose **OK** from it to exit the **Line** tool. The sketch of the outer loop is shown in Figure 2-68. You need to arrange the positions of dimensions in the sketch by dragging them to view the sketch clearly.

Next, you need to draw the inner loop. You can draw the loop by using the **Two Point Rectangle** tool.

18. Choose the **Rectangle Two Point** tool from the **Sketch > Create > Rectangle/Slot** drop-down; you are prompted to specify the first corner of the rectangle.
19. Press the TAB key and then enter **-15** and **-10** in the Pointer Input. Alternatively, move the cursor and click when the cursor displays **-15** and **-10** in the Pointer Input. As you click to specify the first corner, you are prompted to specify the opposite corner of the rectangle and the Pointer Input is changed to Dimension Input.
20. Move the cursor diagonally upward in the right direction and enter **30** and **20** in the horizontal and vertical input fields of the Dimension Input, respectively, and then press ENTER.
21. Next, right-click on the graphics window; a Marking Menu is displayed. Choose **Cancel (ESC)** from the Marking Menu; the sketch is created, as shown in Figure 2-69.




Figure 2-68 Sketch of the outer loop




Figure 2-69 Completed sketch for Tutorial 2

Note

The angular dimensions have not been shown in Figures 2-68 and 2-69 for clarity of sketches. You can control the display of the linear and angular dimensions of the sketch. To do so, choose **Application Options** from the **Options** panel of the **Tools** tab; the **Application Options** dialog box is displayed. In the **Sketch** tab of the **Application Options** dialog box, choose the **Settings** button; the **Constraint Settings** dialog box is displayed. Clear the **Create dimensions from input values** check box in the **Dimensions** area of the **Constraint Settings** dialog box and then choose **OK**. Next, choose the **Apply** and **Close** buttons from the **Application Options** dialog box to turn off applying dimensions automatically during sketching.

Saving the Sketch

Next, you need to save the sketch. As mentioned earlier, you cannot save the sketch in the sketching environment. First, you need to exit the Sketching environment and then save it.

1. Choose the **Finish Sketch** button from the **Exit** panel; the Sketching environment is closed and you will switch to the **Home** view of the part modeling environment.
2. Choose the **Save** tool and save the sketch with the name *Tutorial2* at the location given below: *C:\Inventor_2016\c02*
3. Choose **Close > Close** from the **Application Menu** to close this file.

Tutorial 3

In this tutorial, you will draw the sketch for the model shown in Figure 2-70. The sketch of the model is shown in Figure 2-71. Do not dimension the sketch as the dimensions are given only for reference. **(Expected time: 30 min)**




Figure 2-70 Model for Tutorial 3




Figure 2-71 Sketch for Tutorial 3

The following steps are required to complete this tutorial:

- Start a new metric standard part file.
- Draw the sketch by using the **Arc** and **Line** tools, refer to Figure 2-71.
- Save the sketch with the name *Tutorial3* and close the file.

Starting a New File

1. Choose the **New** tool from the **Launch** panel of the **Get Started** tab to invoke the **Create New File** dialog box.
2. Start a new metric standard part file by double-clicking on **Standard (mm).ipt** in the **Metric**.
3. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
4. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
5. Now, select the **YZ** plane as the sketching plane from the Graphics window; the Sketching environment is invoked and the **YZ** Plane becomes parallel to the screen.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Drawing the Sketch

The upper arc of the sketch can be drawn by specifying its center, start, and endpoint. Therefore, you need to use the **Center Point Arc** tool to draw it.

1. Choose the **Center Point Arc** tool from the **Sketch > Create > Arc** drop-down; you are prompted to specify the center of the arc.
2. Press the TAB key and enter **0** in the X coordinate edit field of the Dynamic Input. Again, press TAB and enter **15** in the Y coordinate edit field. Next, press ENTER to specify the center of the arc; the center of the arc is created and you are prompted to specify the start point of the arc.
3. Enter **12** in the length input field. Next, press TAB and enter **180** in the angle input field of the Dynamic Input and press ENTER.

input field and **90** in the angle input field in the Dynamic Input; a line between points 3 and 4 is created.

9. Move the cursor toward right in the graphics window. Enter **12** in the length input field and **90** in the angle input field of the Dynamic Input; a line is created between points 4 and 5.

Now, you need to draw the lower arc of the sketch. You can use the **Line** tool to draw the arc.

10. Move the cursor close to the endpoint of the last line until the yellow circle snaps to that point. When the yellow circle snaps to the endpoint, it turns gray. Now, press and hold the left mouse button and drag the mouse through a small distance in the upward direction. On doing so, four imaginary lines are displayed, showing the four directions in which you can draw the arc.

11. As you need to draw the arc normal to the line, drag the cursor vertically upward along the vertical imaginary line to a small distance and then drag the cursor close to the right endpoint of the upper arc; the cursor snaps to the endpoint of the arc and turns green.

12. Move the cursor downward, you will notice a point where both the vertical and horizontal imaginary lines intersect each other, see Figure 2-73. This point is the endpoint of the lower arc. The cursor automatically snaps to that point. Do not release the left mouse button until the entire process is completed.

13. When the cursor snaps to the intersection of the imaginary lines, release the mouse button to complete the lower arc.

Note

1. In Figure 2-72, the major and minor grid lines, and the triad have not been displayed for a better display of the sketch and the imaginary lines.

2. While using the temporary tracking option to draw lines, you do not need to press and hold the left mouse button and drag it. You just need to click once to

select the endpoint of the line after you get the intersection point of the imaginary lines, refer to Figure 2-73.




Figure 2-73 Use of the temporary tracking option to draw an arc

Next, you need to draw the remaining lines to complete the sketch.

14. Move the cursor toward right in the graphics window. Enter **12** in the length input field and **0** in the angle input field in the Dynamic Input; a line between points 7 and 8 is created.
15. Move the cursor upward in the graphics window. Enter **30** in the length input field and **90** in the angle input field in the Dynamic Input; a line between points 8 and 9 is created.
16. Move the cursor toward left in the graphics window. Enter **12** in the length input field and **90** in the angle input field in the Dynamic Input; a line between points 9 and 10 is created.
17. Exit the **Line** tool.

The final sketch for Tutorial 3 is shown in Figure 2-74.




Figure 2-74 Final sketch for Tutorial 3

Note

In Figure 2-74, the automatic applied dimensions have not been shown for clarity of sketches.

Saving the Sketch

1. As it is not possible to save the file in the Sketching environment, therefore you need to exit the Sketching environment and then save the file. To do so, right-click anywhere in the graphics window; a Marking Menu will be displayed. Choose the **Finish 2D Sketch** option from the Marking menu; the Sketching environment is closed and you switch to the part modeling environment. Now, choose the **Home** button of **ViewCube**; the current orientation of the sketch is changed to Isometric.
2. Choose the **Save** button from **Quick Access Toolbar** and save this sketch with the name *Tutorial4* at the location given below.

C:\Inventor_2016\c02

3. Choose **Close > Close** from the **Application Menu** to close this file.

Tutorial 4

In this tutorial, you will draw the basic sketch of the revolved solid model shown in Figure 2-75. The sketch for creating this model is shown in Figure 2-76. Do not dimension the sketch as the dimensions are given only for reference. Use Dynamic Input to draw the feature. **(Expected time: 30 min)** The following steps are required to complete this tutorial:

- a. Start a new metric standard part file.
- b. Invoke the **Line** tool and draw the sketch with the help of Dynamic Input.
- c. Save the sketch with the name *Tutorial4* and close the file.
- d. Draw fillets




Figure 2-75 Revolved model for Tutorial 4




Figure 2-76 Sketch for the revolved model

Starting a New File

1. Choose the **New** tool from the **Launch** panel of the **Get Started** tab to invoke

the **Create New File** dialog box.

2. Choose **Metric** to display the standard metric templates. Double-click on **Standard (mm).ipt** to start a new metric part file.
3. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
4. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
5. Now, select the **YZ** plane as the sketching plane from the graphics window; the Sketching environment is invoked and the **YZ** Plane becomes parallel to the screen.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Drawing the Sketch

1. Choose the **Line** tool from the **Create** panel in the **Sketch** tab or from the Marking Menu. On doing so, you are prompted to select the first point of the line to be created. In the Dynamic Input, press TAB and enter **0** in the X coordinate field. Next, press TAB, and enter **0** in the Y coordinate field and press ENTER.
2. Now, you need to draw the line 1. Move the cursor toward left, enter **22** in the length input field, and enter **180** in the angle input field of the Dynamic Input; the line 1 is drawn.
3. Move the cursor upward in the graphics window. Next, enter **4** in the length input field, press TAB, and enter **90** in the angle input field; the line 2 is drawn, as shown in Figure 2-77.




Figure 2-77 Sketch after drawing the lines

4. Move the cursor toward left in the Graphics window. Next, enter **14** in the length input field, press TAB, and enter **90** in the angle input field in the Dynamic Input; line 3 is drawn.
5. Move the cursor upward in the graphics window. Next, enter **6** in the length input field, press TAB, and enter **90** in the angle input field in the Dynamic Input; line 4 is drawn.
6. Move the cursor toward the left in the graphics window. Next, enter **8** in the length input field, press TAB, and enter **90** in the angle input field in the Dynamic Input; line 5 is drawn.
7. Move the cursor upward in the graphics window. Next, enter **6** in the length input field, press TAB, and enter **90** in the angle input field in the Dynamic Input; line 6 is drawn.
8. Move the cursor toward the right in the graphics window. Next, enter **40** in the length input field, press TAB, and enter **90** in the angle input field; line 7 is drawn.
9. Move the cursor upward in the graphics window. Next, enter **9** in the length input field, press TAB, and enter **90** in the angle input field; line 8 is drawn.

10. Move the cursor toward left in the graphics window. Next, enter **16** in the length input field, press TAB, and enter **90** in the angle input field; line 9 is drawn.
11. Move the cursor upward in the graphics window. Next, enter **5** in the length input field, press TAB, and then enter **90** in the angle input field; line 10 is drawn.
12. Move the cursor toward the right in the graphics window. Next, enter **20** in the length input field, press TAB, and enter **90** in the angle input field; line 11 is drawn.
13. Move the cursor downward in the graphics window. Next, enter **30** in the length input field and **90** in the angle input field; line 12 is drawn.
14. The initial sketch is drawn. Exit the **Line** tool by choosing **OK** from the Marking menu.

Drawing Fillets

1. Choose the **Fillet** tool from the **Sketch > Create > Fillet/Chamfer drop-down**; the **2D Fillet** dialog box is displayed. Enter **1.5** in the **Radius** edit box of this dialog box. Do not press ENTER.
2. Select the line 8 and then line 9, refer to Figure 2-76; a fillet is created between these lines and the radius of the fillet is displayed in the sketch.
3. Similarly, select lines 7 and 8 and then lines 4 and 5 to create a fillet between these lines. Next, right-click, and choose **OK** from the Marking Menu to exit the **Fillet** tool after creating all fillets.

As all the lines are filleted with the same radius value, the radius of the fillet is not displayed on other fillets. This completes the sketch. The final sketch for this tutorial after filleting all the sketches is shown in Figure 2-78.




Figure 2-78 Final sketch after filleting

Note

In Figure 2-78, the display of axes and grids have been turned off for a better visibility of the lines of the sketch.

Saving the Sketch

1. Choose the **Finish 2D Sketch** button from the Marking Menu.
2. Choose the **Save** button from **Quick Access Toolbar** and save this sketch with the name *Tutorial4* at the location given below.
C:\Inventor_2016\c02
3. Choose **Close > Close** from the **Application Menu** to close this file.

Answer the following questions and then compare them to those given at the end of this chapter:

1. In Autodesk Inventor, the two types of sketching entities that can be drawn are _____ and _____.
2. In the Sketching environment, the _____ tool is used to place a sketch point or a center point.
3. Filleting is defined as the process of _____ the sharp corners and sharp

edges of models.

4. You can toggle between the length and angle input fields by using the _____ key.
5. You can use the _____ toolbar to precisely enter coordinates of the points in the graphics window.
6. You can also delete the sketched entities by pressing the _____ key.
7. In Autodesk Inventor, rectangles are drawn as the combination of _____ entities.
8. You can undo the last drawn spline segment when you are still inside the spline drawing option by choosing _____ from the Marking Menu displayed.
9. You can exit the **Line** tool by pressing the _____ key or by choosing _____ from the _____ menu.
10. Most of the designs created in Autodesk Inventor are a combination of sketched features and placed features. (T/F)
11. Whenever you start a new file in the **Part** module, the Sketching environment is invoked by default. (T/F)
12. You cannot turn off the display of grid lines. (T/F)
13. You cannot draw an arc while the **Line** tool is active. (T/F)

Answer the following questions:

1. Which of the following tools in the **Tools** tab is used to invoke additional toolbars?
(a) **Application Options** (b) **Customize** (c) **Document Setting** (d) None of these
2. Which of the following drawing display options is used to interactively zoom in and out a drawing?

(a) **Zoom All** (b) **Pan** (c) **Zoom** (d) **Zoom Window**

3. Which of the following keys is used to restore the previous view?

(a) F5 (b) F6

(c) F7 (d) F4

4. Which of the following drawing display options prompts you to select an entity whose magnification has to be increased?

(a) **Zoom** (b) **Pan** (c) **Zoom Selected** (d) None of these

5. In most of the designs, generally the first feature or the base feature is the placed feature. (T/F)

6. You can invoke the options related to sheet metal parts from the *.ipt* file. (T/F)

7. You can change the current project directory and the project files by choosing **Projects** from the **Open** dialog box. (T/F)

8. You can specify the position of entities dynamically by using the Dynamic Input. (T/F)

9. In Autodesk Inventor, you can save a file in the Sketching environment. (T/F)

10. In Autodesk Inventor, you can start a new file by using the **Open** dialog box. (T/F)

Exercise 1

Draw the basic sketch of the model shown in Figure 2-79. The sketch to be drawn is shown in Figure 2-80. Do not dimension it as the dimensions are given only for reference. **(Expected time: 30 min)**




Figure 2-79 Model for Exercise 1




Figure 2-80 Sketch for Exercise 1

Exercise 2

Draw the basic sketch of the model shown in Figure 2-81. The sketch to be drawn is shown in Figure 2-82. Do not dimension it as the dimensions are given only for reference.

(Expected time: 45 min)




Figure 2-81 Model for Exercise 2




Figure 2-82 Sketch for Exercise 2

Exercise 3

Draw the sketch of the model shown in Figure 2-83. The sketch to be drawn is shown in Figure 2-84. Do not dimension it as the dimensions are given only for reference.

(Expected time: 45 min)




Figure 2-83 Model for Exercise 3




Figure 2-84 Sketch for Exercise 3

Exercise 4

Draw the sketch of the model shown in Figure 2-85. The sketch to be drawn is shown in Figure 2-86. Do not dimension it as the dimensions are given only for reference.

(Expected time: 45 min)




Figure 2-85 Model for Exercise 4




Figure 2-86 Sketch for Exercise 4

Answers to Self-Evaluation Test **1.** normal, construction, **2. Point**, **3.** rounding,
4. TAB, **5. Inventor Precise Input**, **6.** DELETE, **7.** individual, **8. Back**, **9.**
ESC, **Cancel (ESC)**, Marking menu, **10.** T, **11.** F, **12.** F, **13.** F

Chapter 3

Adding Constraints and Dimensions to Sketches

Learning Objectives

After completing this chapter, you will be able to:

- ***Add geometric constraints to a sketch.***
- ***Control the constraint inference.***
- ***View and delete constraints from a sketch.***
- ***Dimension a sketch.***
- ***Modify the dimensions of a sketch.***
- ***Measure distances, angles, loops, and areas in a sketch.***

ADDING GEOMETRIC CONSTRAINTS TO A SKETCH CONSTRAINTS ARE APPLIED TO THE SKETCHED ENTITIES TO DEFINE THEIR SIZE AND POSITION WITH RESPECT TO OTHER ELEMENTS. ALSO, THEY ARE USEFUL FOR CAPTURING THE DESIGN INTENT. AS MENTIONED IN CHAPTER 1, THERE ARE TWELVE TYPES OF GEOMETRIC CONSTRAINTS THAT CAN BE APPLIED TO THE SKETCHED ENTITIES. THESE CONSTRAINTS RESTRICT THEIR DEGREES OF FREEDOM AND MAKE THEM STABLE. MOST OF THESE CONSTRAINTS GET AUTOMATICALLY APPLIED

TO THE ENTITIES WHILE DRAWING. HOWEVER, SOMETIMES YOU MAY NEED TO APPLY SOME ADDITIONAL CONSTRAINTS TO THE SKETCHED ENTITIES. THESE CONSTRAINTS ARE DISCUSSED NEXT.

Perpendicular Constraint

Ribbon: Sketch > Constrain > Perpendicular Constraint **The Perpendicular constraint forces the selected entity to become perpendicular to the specified entity. The entities to which the constraints can be applied are lines and ellipse axes. To apply this constraint, choose the Perpendicular Constraint tool from the Constrain panel of the Sketch tab; you will be prompted to select the first line or an ellipse axis. After selecting the first entity, you will be prompted to select the second line or ellipse axis. On selecting the second entity, the selected entities will become perpendicular. Figure 3-1 shows two lines before and after adding this constraint. Similarly, you can also apply the Perpendicular Constraint between two arcs.**

Parallel Constraint

Ribbon: Sketch > Constrain > Parallel Constraint The Parallel constraint forces the selected entity to become parallel to the specified entity. The entities to which this constraint can be applied are lines and ellipse axes. To apply this constraint, choose the Parallel Constraint tool from the Constrain panel of the Sketch tab; you will be prompted to select the first line or an ellipse axis. After you select an entity, you will be prompted to select the second line or an ellipse axis. On selecting the second entity, the two entities will become parallel. Figure 3-2 shows two lines before and after adding this constraint.




Figure 3-1 Lines before and after applying the Perpendicular Constraint




Figure 3-2 Applying the Parallel Constraint

Tangent Constraint

Ribbon: Sketch > Constrain > Tangent The Tangent constraint forces the selected line segment or curve to become tangent to another curve. To apply this constraint, choose the Tangent tool from the Constrain panel of the Sketch tab; you will be prompted to select the first curve. After you select the first curve, you will be prompted to select the second curve. The curves that can be selected are lines, circles, ellipses, or arcs. Figures 3-3 and 3-4 show the Tangent constraint applied between a line and a circle, and between an ellipse and arc, respectively.




Figure 3-3 Applying the Tangent constraint between line and circle




Figure 3-4 Applying the Tangent constraint between ellipse and arc

Coincident Constraint

Ribbon: Sketch > Constrain > Coincident Constraint **The Coincident constraint forces two points or a point and a curve to become coincident. To apply this constraint, choose the Coincident Constraint tool from the Constrain panel of the Sketch tab; you will be prompted to select the first curve or point. After you select the first curve or point, you will be prompted to specify the second curve or point. Note that either the first or the second entity selected should be a point. The points include sketch points, endpoints of a line or an arc, or center points of circles, arcs, or ellipses.**

Concentric Constraint

Ribbon: Sketch > Constrain > Concentric Constraint **The Concentric constraint forces two curves to share the same location of center points. The curves that can be made concentric include arcs, circles, and ellipses. When you invoke this constraint, you will be prompted to select the first arc, circle, or ellipse. After making the first selection, you will be prompted to select the second arc, circle, or ellipse. Select the second entity to be made concentric with the first entity.**

Note

If you apply a constraint that overconstrains a sketch, the **Autodesk Inventor Professional - Create Constraint** message box will be displayed informing that adding this constraint will over-constrain the sketch, refer to Figure 3-5. A sketch is said to be overconstrained if the number of dimensions or constraints in it exceeds the number that can be applied to the sketch.




Figure 3-5 The Autodesk Inventor Professional - Create Constraint message box

Collinear Constraint

Ribbon: Sketch > Constrain > Collinear Constraint **The Collinear constraint forces the selected line segments or ellipse axes to be placed in the same line. When you invoke this constraint, you will be prompted to select the first line or ellipse axis. After making the first selection, you will be prompted to select the second line or ellipse axis. Select the entity to be made collinear with the first entity.**

Tip. To select an ellipse axis, move the cursor close to the ellipse. The minor or the major axis, whichever the cursor is close to, will get highlighted. When the required axis is highlighted, select it using the left mouse button.

Horizontal Constraint

Ribbon: Sketch > Constrain > Horizontal Constraint **The Horizontal Constraint forces the selected line segment, ellipse axis, or two points to become horizontal, irrespective of their original orientation. When you invoke this constraint, you will be prompted to select a line, an ellipse axis, or the first point. If you select a line or an ellipse axis, it will become horizontal. If you select a point, you will be prompted to select the second point. The points, in this case, can also include the center points of arcs, circles, or ellipses.**

Vertical Constraint

Ribbon: Sketch > Constrain > Vertical Constraint **The Vertical constraint is similar to the Horizontal constraint, with the difference that this constraint forces the selected entities to become vertical.**

Tip. You can use the Horizontal or Vertical constraint to line up arcs, circles, or ellipses in the horizontal or vertical direction by selecting their center points.

Equal Constraint Ribbon: Sketch > Constrain > Equal

The Equal constraint can be used for line segments or curves. If you select two line segments, this constraint will force the length of one of the selected line segments to become equal to the length of the other selected line segment. In case of curves, this constraint will force the radius of one of the selected curves to become equal to that of the other selected curve. Note that if the first selection is a line, the second selection also be a line. Similarly, if the first selection is a curve, the second selection also needs to be a curve.

Fix Constraint

Ribbon: Sketch > Constrain > Fix **The Fix constraint is used to fix the orientation or location of the selected curve or point with respect to the coordinate system of the current drawing. If you apply this constraint to a line or an arc, you cannot move them from their current locations. However, you can change their length by selecting one of their endpoints and then dragging it. If you apply this constraint to a circle or an ellipse, you cannot edit either of these entities by dragging. Once you apply this constraint to an entity, its color changes.**

Symmetric Constraint Ribbon: Sketch > Constrain > Symmetric This constraint is used to force two selected sketched entities to become symmetrical about a single sketched line segment. On invoking this constraint, you will be prompted to select the first sketched element. Note that you can select only one entity at a time to apply this constraint. Once you have selected the first sketched entity, you will be prompted to select the second sketched element. Select the second sketched entity; you will be prompted to select the symmetry line. Select the symmetry axis (an axis about which the selected entities need to be symmetric); the second selected entity will become symmetric to the first entity. After you have applied this constraint to one set of entities, you will again be prompted to select the first and second sketched entities. However, this time you will not be prompted to select the line of symmetry. The last line of symmetry will be automatically selected to add this constraint. Similarly, you can apply this constraint to other entities.

If the line of symmetry is different for applying the symmetric constraint to different entities in the sketch, you will have to restart the process of applying this constraint by right-clicking and then choosing the **Restart** option from the Marking Menu. This is because the first symmetry line is used to apply this constraint to all the sets of entities you select. However, if you restart applying this constraint, you will be prompted to select the line of symmetry again.

Smooth Constraint Ribbon: Sketch > Constrain > Smooth (G2) This constraint is used to apply curvature continuity between a spline and an entity connected to it. The entities that can be selected to apply this constraint include a line, arc, or another spline. Note that these entities should be connected to the spline.

Note

In Autodesk Inventor, you can apply the Perpendicular, Tangent, and Smooth (G2) constraints between different type of splines.

VIEWING THE CONSTRAINTS APPLIED TO A SKETCHED ENTITY RIBBON: SKETCH > CONSTRAIN > SHOW CONSTRAINTS YOU CAN VIEW ALL THE CONSTRAINTS THAT ARE APPLIED TO THE ENTITIES OF A SKETCH BY CHOOSING THE **SHOW CONSTRAINTS** TOOL FROM THE **CONSTRAIN** PANEL. WHEN YOU INVOKE THIS TOOL AND MOVE THE CURSOR CLOSE TO A SKETCHED ENTITY, IT WILL BE HIGHLIGHTED AND CONSTRAINTS WILL BE DISPLAYED AFTER A PAUSE. THESE CONSTRAINTS SHOW THE SYMBOLS OF ALL THE CONSTRAINTS THAT ARE APPLIED TO THE ENTITY. FIGURE 3-6 SHOWS THE CONSTRAINTS APPLIED TO THE LINES. YOU CAN MOVE A CONSTRAINT BY SELECTING AND DRAGGING IT. IN THE CASE OF COINCIDENT CONSTRAINT, THE

CONSTRAINT APPLIED ON A POINT IS HIGHLIGHTED IN YELLOW. TO VIEW SYMBOLS, MOVE THE CURSOR OVER THE HIGHLIGHTED YELLOW POINT; THE COLOR OF THE POINT WILL CHANGE, REFER TO FIGURE 3-6.




Figure 3-6 Constraints applied to the sketch entities

If you move the cursor close to a constraint, it will be highlighted and the entities to which the constraint is applied is also highlighted. For example, if you take the cursor close to a perpendicular constraint, the vertical line will also be highlighted along with the horizontal line, suggesting that the two lines are perpendicular to each other.

*Tip. You can display all the constraint, applied to the entities. To do so, choose the **Show All Constraints** button from the status bar, which is available at the bottom of the graphics window; separate symbols will be displayed showing the constraints on all entities. Similarly, to hide all constraints, choose the **Hide All Constraints** button from the status bar.*

CONTROLLING CONSTRAINTS AND APPLYING THEM AUTOMATICALLY WHILE SKETCHING
RIBBON: SKETCH > CONSTRAIN > CONSTRAINT SETTINGS YOU CAN CONTROL AND SELECT THE CONSTRAINTS THAT NEED TO BE APPLIED AUTOMATICALLY AS WELL AS SELECT THE GEOMETRY TO WHICH THEY WILL BE APPLIED. YOU CAN DO SO BY USING THE **CONSTRAINTS SETTING** DIALOG BOX. TO INVOKE THIS DIALOG BOX, CHOOSE THE **CONSTRAINTS SETTINGS** TOOL FROM THE **CONSTRAIN** PANEL OF THE **SKETCH** TAB. THIS DIALOG BOX DISCUSSED NEXT.

Constraints Settings Dialog box While drawing the sketch, by default, all the possible constraints get automatically applied to the sketching entities. However, you can also specify the constraints that need to be applied automatically and the geometry to which they will be applied while sketching. To do so, choose the **Constraint Settings** tool from the **Constrain** panel of the **Sketch** tab; the **Constraint Settings** dialog box will be displayed, as shown in Figure 3-7. The options in this dialog box are discussed next.




Figure 3-7 The Constraint Settings dialog box

General

The **General** tab is selected by default. The options in this tab are discussed next.

Constraints

In this area, three check boxes are available. If you select the **Display constraints on creation** check box, Autodesk Inventor allows you to display the constraints applied during the creation of sketch. If you select the **Show constraints for selected objects** check box, Autodesk Inventor allows you to show the constraints for the selected object. If you select the **Display coincident constraints in sketch** check box, Autodesk Inventor allows you to display the coincident constraints in the sketch.

Dimension

This area is used to apply the Dimensions constraints to the sketch. In this area, two check boxes are available. These check boxes are used to apply dimensions during the creation of sketch.

Overconstrained Dimensions

This area is used to control the over defined dimensions applied to the sketch. In this area, two radio buttons are available. If you select the **Apply driven dimensions** radio button, you will be able to apply the over defined dimension to the sketch. In this case over defined dimension is considered as the reference dimension. If you select the **Warn of overconstrained condition** radio button, you will not be able to apply the over defined dimensions to the sketch. In this case, a warning message will be displayed.

Interface

In the **Interface** tab, two areas are available. The options in this tab are discussed next.

Constraint Interface Priority

This area is used to set up the constraints interface priority. You need to select the appropriate radio button to set up the priority.

Selection for Constraint Inference

In this area, nine check boxes corresponding to nine constraints are available. All check boxes are selected by default. However, if you need to clear all the constraints, choose the **Clear All** button. You can manually select or clear the required constraint by selecting the corresponding check box provided on the right of the constraint symbols. The selected constraints will be applied automatically to the geometry while sketching.

Relax Mode

In this tab, the **Enable Relax Mode** check box is available. If you select this check box, you will be able to remove the constraints from the geometry while dragging the sketch. In this case, you can remove only that constraint whose respective check box is selected in the **Constraints to remove in relax dragging** area.

Scope of Constraint Inference Ribbon: Sketch >

Constrain > Constraint Inference Scope

The Constraint Inference Scope tool is used to set the geometry to which the constraint is applied while drawing. You can invoke this tool from the Constrain panel of the Sketch tab. On invoking this tool, the Constraint Inference Scope dialog box will be displayed. In this dialog box, the Geometry in current command radio button is selected by default. As a result, the constraint is applied to the current geometry. If you select the Select check box, the Select button will be activated automatically. You can use this button to select the geometry to which the constraints will be applied. If you select the All Geometry radio button, the constraint will be applied to all the active sketches.

DELETING GEOMETRIC CONSTRAINTS

Autodesk Inventor allows you to delete the constraints applied to the selected entities. To delete constraints, first you need to invoke the constraint box by using the **Show Constraints** tool. Once the constraints are displayed, exit the **Show Constraints** tool by pressing the ESC key. Next, move the cursor over the constraint that you want to delete; it will be highlighted in red. Click the left mouse button to select the constraint. Next, move the cursor away and right-click, and then choose **Delete** from the Marking menu, see Figure 3-8. The selected constraint will be deleted. Similarly, you can delete all unwanted constraints from the sketch.




Figure 3-8 Choosing the **Delete** option from the Marking Menu

Note

The total number of constraints and dimensions required to fully constraint a sketch is displayed at the lower right corner of the graphics window.

Tip. When you move the cursor close to the constraint, its references will be highlighted in the sketch. For example, if you move the cursor over the Perpendicular constraint, the lines on which this constraint is applied will be highlighted. This allows you to confirm that the constraint selected is correct.


**ADDING DIMENSIONS TO SKETCHES RIBBON:
SKETCH > CONSTRAIN > DIMENSION AFTER
DRAWING A SKETCH AND ADDING
CONSTRAINTS TO IT, DIMENSIONING IS THE
NEXT MOST IMPORTANT STEP IN CREATING A
DESIGN. AS MENTIONED EARLIER, AUTODESK
INVENTOR IS A PARAMETRIC SOLID MODELING
PACKAGE. THE PARAMETRIC PROPERTY
ENSURES THAT IRRESPECTIVE OF ITS ORIGINAL
SIZE, THE SELECTED ENTITY IS DRIVEN BY THE
SPECIFIED DIMENSION VALUE. THEREFORE,
WHENEVER YOU MODIFY OR APPLY DIMENSION
TO AN ENTITY, IT IS FORCED TO CHANGE ITS
SIZE WITH RESPECT TO THE SPECIFIED
DIMENSION VALUE. THE TYPE OF DIMENSION
TO BE APPLIED VARIES ACCORDING TO THE
TYPE OF ENTITY SELECTED. FOR EXAMPLE, IF
YOU SELECT A LINE SEGMENT, LINEAR**

DIMENSIONS WILL BE APPLIED AND IF YOU SELECT A CIRCLE, DIAMETER DIMENSIONS WILL BE APPLIED. NOTE THAT ALL THESE TYPES OF DIMENSIONS CAN BE APPLIED USING THE SAME DIMENSIONING TOOL. TO EDIT THE DIMENSION, DOUBLE-CLICK ON THE DIMENSION; THE **EDIT DIMENSION** EDIT BOX WILL BE DISPLAYED, REFER TO FIGURE 3-9. ENTER THE DESIRED VALUE IN THE EDIT BOX TO MODIFY THE DIMENSIONS. THE SELECTED ENTITY WILL BE DRIVEN TO THE DIMENSION VALUE DEFINED IN THIS EDIT BOX. YOU CAN ENTER A NEW VALUE FOR THE DIMENSION OR CHOOSE THE BUTTON ON THE RIGHT OF THIS EDIT BOX TO ACCEPT THE DEFAULT VALUE.

If you do not want to edit the dimensions after they have been placed, invoke the **Dimension** tool and then right-click to display the Marking Menu, refer to Figure 3-10. Clear the check mark on the left of the **Edit Dimension** option by choosing it again. When you place a dimension now, the **Edit Dimension** edit box will not be displayed. To edit the dimension value in this case, click on it after placing, if the **Dimension** tool is still active. If the tool is not active, double-click on the dimension; the **Edit Dimension** edit box will be displayed. Enter the new dimension value in this edit box. The dimensioning techniques available in Autodesk Inventor are discussed next.



Figure 3-9 The Edit Dimension edit box



*Figure 3-10 Choosing **Edit Dimension** from the Marking Menu*

Linear Dimensioning The linear dimensions are defined as the dimensions that specify the shortest distance between two points. You can apply linear dimensions directly to a line or select two points or entities to apply the linear dimension between them. The points that you can select include the endpoints of lines, splines, or arcs, or the center points of circles, arcs, or ellipses. You can dimension a vertical or a horizontal line by directly selecting it. As soon as you select it, the dimension will be attached to the cursor. You can place the dimension at any desired location. To place the dimension between two points, select the points one by one. After selecting the second point, right-click to display the Marking menu, as shown in Figure 3-11. You can choose the dimension type from this menu as per your requirement.




Figure 3-11 Marking menu displaying various options to dimension two points

If you choose **Horizontal**, the horizontal dimension will be placed between the two selected points. If you choose **Vertical**, the vertical dimension will be placed between the two selected points. If you choose **Aligned**, the aligned dimension will be placed between the two selected points. Figure 3-12 shows the linear dimensioning of lines and Figure 3-13 shows the linear dimensioning of two points.




Figure 3-12 Linear dimensioning of lines




Figure 3-13 Linear dimensioning of two points

You can also apply a horizontal or vertical dimension to an inclined line, see Figure 3-14. To apply these dimensions, select the inclined line and then right-click; a Marking Menu similar to the one shown in Figure 3-11 will be displayed. In this menu, choose **Horizontal** to place the horizontal dimension and **Vertical** to place the vertical dimension.




Figure 3-14 Linear dimensioning of an inclined line

Aligned Dimensioning The aligned dimensions are used to dimension the lines that are not parallel to the X or Y-axis. This type of dimension measures the actual distance

of the aligned lines or the lines drawn at a certain angle. To apply the aligned dimension, select the inclined line and then right-click; a Marking Menu will be displayed, refer to Figure 3-11. Choose the **Aligned** option from the Marking Menu; the aligned dimension of the selected line will be attached to the cursor. Next, click in the graphics window to specify the location of the aligned dimension. You can also apply the aligned dimension between two points. The points include the endpoints of lines, splines, or arcs or the center points of arcs, circles, or ellipses. To apply the aligned dimension between two points, invoke the **Dimension** tool. Next, select the two points and right-click; a Marking Menu will be displayed. Choose the **Aligned** option from the Marking Menu. Figures 3-15 and 3-16 show the aligned dimensions applied to various objects.

*Tip. Alternatively, to apply the aligned dimension, choose the **Dimension** tool from the **Ribbon** and then select the aligned entity to be dimensioned. Next, move the cursor away from the line and then click again on the same line. Now, click on the drawing window to place the aligned dimension.*




Figure 3-15 Aligned dimension of a line




Figure 3-16 Aligned dimension between two points

Angular Dimensioning The angular dimensions are used to dimension angles. You can select two line segments or use three points to apply the angular dimensions. You can also use angular dimensioning to dimension an arc. All these options of angular dimensioning are discussed next.

Angular Dimensioning Using Two Line Segments You can directly select two line segments to apply angular dimensions. To do so, invoke the **Dimension** tool of the **Constrain** panel of **Sketch** tab. You can also invoke **General Dimension** from the Marking Menu and then select a line segment using the left mouse button. Instead of placing the dimension, select the second line segment. Next, place the dimension to measure the angle between the two lines. While placing the dimension, you need to be careful about the point where you place the dimension. This is because depending on the location of the placement of dimension with respect to the lines, the vertically opposite angles will be displayed. Figure 3-17 shows the angular dimension between two lines and Figure 3-18 shows the dimension of the vertically opposite angle between two lines. Also, depending on the location of the dimension, the major or minor angle value will be displayed. Figure 3-19 shows the major angle dimension between two

lines and Figure 3-20 shows the minor angle dimension between the same set of lines.




Figure 3-17 Angular dimensioning between two lines




Figure 3-18 Dimension of the vertically opposite angle between two lines




Figure 3-19 Major angle dimension




Figure 3-20 Minor angle dimension

Angular Dimensioning Using Three Points You can also apply angular dimensions using three points. Remember that the three points should be selected in clockwise or counterclockwise sequence. The points that can be used to apply the angular dimensions include the endpoints of lines or arcs, or the center points of arcs, circles, and ellipses. Figure 3-21 shows angular dimensioning using three points.

Angular Dimensioning of an Arc

You can use angular dimensions to dimension an arc. In case of arcs, the three points are the endpoints and the center point of the arc. Note that the points should be selected in the clockwise or counterclockwise sequence, but the center point should always be the second selection point. Figure 3-22 shows the angular dimensioning of an arc. In Autodesk Inventor, you can also assign angular dimensions to an arc by using the Marking menu. To do so, invoke the **Dimension** tool. Then, select the arc and right-click; a Marking menu will be displayed. Choose **Dimension Type** from the Marking menu; a cascading menu will be displayed. Choose **Arc Length** from the cascading menu before placing the dimension on the graphics window, refer to Figure 3-23. Figure 3-24 shows the angular dimensioning of an arc using the Marking menu.




Figure 3-21 Angular dimensioning using three points




Figure 3-22 Angular dimensioning of an arc




Figure 3-23 Angular dimensioning using the Marking menu




Figure 3-24 Angular dimensioning of an arc using the Marking menu

Diameter Dimensioning

Diameter dimensions are applied to dimension a circle or an to specify its diameter. In Autodesk Inventor, when you select a circle to dimension, the diameter dimension is applied to it by default. If you select an arc to dimension it, the radius dimension will be applied to it. You can also apply the diameter dimension to an arc. To do so, invoke the Dimension tool and then select the arc. Next, right click to display the Marking menu, as shown in Figure 3-25. From the Marking menu, choose Dimension Type; a cascading menu is displayed. Choose Diameter from this menu to apply the diameter dimension. Figure 3-26 shows a circle and an arc with diameter dimensions.




Figure 3-25 Marking menu to apply a diameter dimension to an arc




Figure 3-26 Diameter dimensioning of a circle and an arc

Radius Dimensioning

Radius dimensions are applied to dimension an arc or a circle to specify its radius. As mentioned earlier, by default, circles are assigned diameter dimensions and arcs are assigned radius dimensions. However, you can also apply the radius dimension to a circle. To do so, invoke the **Dimension** tool and then select the circle. Next, right-click to display the Marking menu, as shown in Figure 3-27. From the Marking menu, choose **Dimension Type**; a cascading menu is displayed. Choose **Radius** from this menu to apply the radius dimension. Figure 3-28 shows an arc and a circle with radius dimensions.




Figure 3-27 Marking menu to apply a radius dimension to an arc




Figure 3-28 Radius dimensioning of a circle and an arc

Linear Diameter Dimensioning

Linear diameter dimensioning is used to dimension the sketches of the revolved components. The sketch for a revolved component is drawn using simple sketcher entities. For example, if you draw a rectangle and revolve, it will result in a cylinder. Now, if you dimension the rectangle using the linear dimensions, the same dimensions will be displayed when you generate the drawing views of the cylinder. Also, the same dimensions will be used while manufacturing the component. But these linear dimensions will result in a confusing situation in manufacturing. This is because while manufacturing a revolved component, the dimensions have to be specified as the diameter of the revolved component. The linear dimensions will not be acceptable in manufacturing a revolved component. To resolve this problem, the sketches for the revolved features are dimensioned using the linear diameter dimensions. These dimensions display the distance between the two selected line segments as a diameter, that is, double the original length. For example, if the original dimension between two entities is 10 mm, the linear diameter dimension will display it as 20 mm. This is because when you revolve a rectangle with 10 mm width, the diameter of the resultant cylinder will be 20 mm. In this type of dimension, if you select two lines, the line selected first will act as the axis of revolution for the sketch and the line selected last will result in the outer surface of the revolved feature. It means the line selected last will be the one that will be dimensioned. But, if one of these lines is a centerline drawn by choosing the **Centerline** tool from the **Format** panel, the centerline will be considered as the axis of revolution.

To apply linear diameter dimensions, invoke the **Dimension** tool; you will be prompted to select the first geometry to dimension. Select the first line; you will be prompted to select the second geometry to dimension. Select the second line with reference to which you want to apply the linear diameter dimensions. If the first line selected is a centerline, the linear diameter dimension will be displayed. Alternatively, right-click and then choose **Linear Diameter** from the Marking Menu, see Figure 3-29. You will notice that the distance between the two lines

is displayed as twice the distance. Also, the dimension value is preceded by the \emptyset symbol, indicating that it is a linear diameter dimension. Figures 3-30 and 3-31 show the use of linear diameter dimensioning.




Figure 3-29 Choosing the **Linear Diameter** option




Figure 3-30 Selecting elements for linear diameter dimension




Figure 3-31 The linear diameter dimension

Tip. After invoking the **Dimension** tool, as you move the cursor close to the sketched entities, a small symbol will be displayed close to the cursor. This symbol displays the type of dimension that will be applied. For example, if you select a line, the linear dimensioning or aligned dimensioning symbol will be

displayed. If you move the cursor close to another line after selecting the first, the symbol of angular dimensioning will be displayed. These symbols help you in determining the type of dimensions that will be applied.

In Autodesk Inventor, the ellipses are dimensioned as half of the major and minor axes distances. To dimension an ellipse, invoke the **Dimension** tool and then select the ellipse. Now, if you move the cursor in the vertical direction, the axis of the ellipse along the X-axis will be dimensioned in terms of its half length. Similarly, if you move the cursor in the horizontal direction, the axis of the ellipse along the Y axis will be dimensioned equal to its half-length.

To distinguish whether the dimension applied to an arc or a circle is a radius or a diameter, try to locate the number of arrowheads in the dimension. If there are two arrowheads in the dimension and the dimension line is placed inside the circle or the arc, it is a diameter dimension. The radius dimension has one arrowhead and the dimension line is placed outside the circle or the arc.

SETTING THE SCALE OF A SKETCH

In Autodesk Inventor, if you change the current length of an entity by changing its dimension value, all the other entities of the sketch get modified proportionally or scaled accordingly. Note that this will be applicable only if no other dimension is applied to the sketch. As you apply the second dimension to the sketch, the sketch will not be scaled proportionally, on changing the dimension value. Figure 3-32 shows the sketch without any dimension and Figure 3-33 shows the sketch scaled automatically after applying the first dimension to it.




Figure 3-32 Sketch on the graphics screen




Figure 3-33 Sketch resized after editing the first dimension

CREATING DRIVEN DIMENSIONS

Ribbon: Sketch > Format > Driven Dimension This toggle button is used to switch between the driven dimension and the sketch (driving) dimension. **A dimension is called as a sketch (driving) dimension, if it forces an entity to change its length and orientation. A driven dimension is the one whose value depends on the value of the sketch (driving) dimension. The driven dimensions are enclosed within parenthesis and display the current value of the sketched geometry. This value cannot be modified. If you change the value of the sketch (driving) dimension, the value of the driven dimension will change automatically, as shown in Figures 3-34 and 3-35. All dimensions applied after choosing the Driven Dimension button will be the driven dimensions. To convert sketch (driving) dimensions into driven dimensions, select the required sketch (driving) dimension and choose the Driven Dimension button from the Format panel.**




Figure 3-34 Driving dimension and driven dimension in a sketch




Figure 3-35 Modified driving dimension and dynamically updated driven dimension

UNDERSTANDING THE CONCEPT OF FULLY-CONSTRAINED SKETCHES A FULLY-CONSTRAINED SKETCH IS THE ONE WHOSE ALL THE ENTITIES ARE COMPLETELY CONSTRAINED TO THEIR SURROUNDINGS USING CONSTRAINTS AND DIMENSIONS. IN A FULLY-CONSTRAINED SKETCH, ALL DEGREES OF FREEDOM OF THE SKETCH ARE CONSTRAINED. A FULLY-CONSTRAINED SKETCH CANNOT CHANGE ITS SIZE, LOCATION, OR ORIENTATION UNEXPECTEDLY. WHENEVER YOU DRAW A SKETCHED ENTITY, IT WILL TURN BLACK IN COLOR. HOWEVER, THE ENTITY WILL TURN BLUE IF YOU ADD REQUIRED DIMENSIONS TO A SKETCH TO MAKE IT FULLY CONSTRAINT. THERE IS ONE MORE METHOD TO UNDERSTAND WHETHER THE SKETCHED ENTITIES ARE FULLY-CONSTRAINED OR NOT. IN THIS METHOD, YOU NEED TO RIGHT-CLICK ON THE SKETCHED ENTITY AND CHOOSE THE **DISPLAY DEGREES OF FREEDOM** OPTION FROM THE MARKING MENU DISPLAYED; THE ENTITIES WILL DISPLAY THE AVAILABLE DEGREES OF FREEDOM SUCH AS HORIZONTAL, VERTICAL, ANGULAR, OR ROTATIONAL. ALTERNATIVELY, CLICK ON THE **SHOW ALL DEGREES OF**

FREEDOM TOGGLE BUTTON AVAILABLE AT THE BOTTOM OF THE GRAPHICS WINDOW TO DISPLAY THE DEGREES OF FREEDOM. NOTE THAT WHILE CREATING THE BASE SKETCH IN AUTODESK INVENTOR, YOU NEED TO DIMENSION IT WITH RESPECT TO A FIXED POINT TO FULLY CONSTRAIN IT. TO DO SO, YOU CAN FIX THE SKETCH WITH THE ORIGIN, WHICH IS ALREADY FIXED BY DEFAULT. YOU CAN CONTROL THE VISIBILITY OF THIS ORIGIN. TO HIDE THIS POINT, CHOOSE THE **APPLICATION OPTIONS** BUTTON FROM THE **TOOLS** TAB; THE **APPLICATION OPTIONS** DIALOG BOX WILL BE INVOKED. CHOOSE THE **SKETCH** TAB AND THEN CLEAR THE **AUTOPROJECT PART ORIGIN ON SKETCH CREATE** CHECK BOX. NEXT, CLOSE THE DIALOG BOX.

*Tip. In Autodesk Inventor, when you switch to the Part module, a fully-constrained sketch is displayed by symbol in the **Browser Bar**.*

MEASURING SKETCHED ENTITIES AUTODESK INVENTOR ALLOWS YOU TO MEASURE VARIOUS PARAMETERS OF THE SKETCHED ENTITIES. THE PARAMETERS THAT YOU CAN MEASURE ARE DISTANCES, ANGLES, LOOPS, AND AREA. MEASURING THESE PARAMETERS IS

DISCUSSED NEXT.

Measuring Distances

Ribbon: *Inspect > Measure > Distance* Autodesk Inventor allows you to measure the length of a line segment, radius of an arc, diameter of a circle, minimum distance between two entities, or coordinates of a point. All these distances can be measured by using the Distance tool from the Measure panel. On invoking this tool, the Measure Distance dialog box will be displayed and you will be prompted to select the first item. The name of the Measure Distance dialog box is modified depending upon the type of entities selected to be measured. The methods of measuring distances between various entities are discussed next.

*Tip. To restart measuring the distances, right-click in the graphics window to display a shortcut menu and then choose **Repeat Measure**; you will be prompted to select the first element to be measured. Alternatively, choose the right arrow displayed next to the display box in the **Measure Distance** dialog box and then choose the **Restart** option from the flyout displayed.*


Measuring the Length of a Line Segment When you invoke the **Distance** tool, the **Measure Distance** dialog box will be displayed and you will be prompted to select the first entity. Select a line segment; the **Measure Distance** dialog box will be changed to the **Length** dialog box and the length of the selected line segment will be displayed in this dialogbox, see Figure 3-36.



*Figure 3-36 The **Length** dialog box displaying the length of a line segment*

Measuring the Distance between a Point and a Line Segment To measure the distance between a point and a line segment, invoke the **Distance** tool and then select the point. The **Measure**


Distance dialog box will be modified to the **Position** dialog box, which shows the X, Y, and Z coordinates of the point, and you will be prompted to select the next entity. Select the line; the **Position** dialog box will change to the **Minimum Distance** dialog box. This dialog box will display the minimum distance between the point and the line, and the length of the line, see Figure 3-37.



*Figure 3-37 The **Minimum Distance** dialog box displaying the distance between the lines*

Measuring the Coordinates of a Point


To measure the coordinates of a point with respect to the current coordinate system, invoke the **Distance** tool; you will be prompted to select the first element. Select the point whose coordinates you want to know. The selectable points include the endpoints of lines, arcs, or splines, center point of arcs, circles, or ellipses, or hole centers. If you select a hole center or the center point, the **Measure Distance** dialog box will change into the **Position** dialog box and the X, Y, and Z coordinates of the selected point with respect to the current coordinatesystem will be displayed, see Figure 3-38. However, if you select an endpoint, the coordinates will be specified in the **Measure Distance** dialog box.



*Figure 3-38 The **Position** dialog box displaying the coordinates of a point*

Measuring the Distance between Two Points To measure the distance

between two points, invoke the **Distance** tool and then select the first point; the coordinates of the selected point will be displayed in the **Position** dialog box. You will be prompted to select the second element. Select the second point; the **Position** dialog box will be changed to the **Minimum Distance** dialog box. This dialog box will display the distance between the two points. This dialog box will also display the coordinates of the second point. You will also notice the **Delta X**, **Delta Y**, and **Delta Z** values in this dialog box, see Figure 3-39. These values are the distances between the two selected points along the X, Y, and Z axes.



*Figure 3-39 The **Minimum Distance** dialog box*

Tip. In Autodesk Inventor, you can also measure distance between the midpoint of a linear segment and midpoint of a circular arc.

*Measuring the Radius of an Arc or the Diameter of a Circle You can also measure the radius of an arc or the diameter of a circle by using the **Distance** tool. When you invoke this tool, the **Measure Distance** dialog box will be displayed and you will be prompted to select the first item. If you select an arc or move the cursor over the arc, this dialog box will be momentarily changed to the **Radius** dialog box and will display the radius of the arc, see Figure 3-40. If you select a circle or move the cursor over the circle, this dialog box will momentarily change into the **Diameter** dialog box and will display the diameter of the circle, see Figure 3-41. Note that if you select an arc or a circle, you will not be prompted to select the second element because you cannot calculate any value other than their radius or diameter.*



*Figure 3-40 The **Radius** dialog box displaying the radius of the arc*



*Figure 3-41 The **Diameter** dialog box displaying the diameter of the circle*

Measuring Angles Ribbon: Inspect > Measure > Angle To measure an angle, right-click in the drawing window and choose **Measure > Measure Angle** from the Marking menu; the **Measure Angle** dialog box will be displayed. Alternatively, choose the **Angle** tool from the **Measure** panel. This tool is used to measure the angle between two line segments or among three points. Both these methods for measuring angles are discussed next.

Measuring the Angle between Two Lines To measure the angle between two lines, invoke the **Angle** tool; the **Measure Angle** dialog box will be displayed and you will be prompted to select the first item. Select the first line; you will be prompted to select the second line. Select the second line; the **Measure Angle** dialog box will change momentarily into the **Angle** dialog box and the angle between the selected line segments will be displayed, refer to Figure 3-42.



*Figure 3-42 The **Angle** dialog box displaying the angle between two lines*

Measuring the Angle Using Three Points You can also measure the angle using three points. When you invoke the **Angle** tool, you will be prompted to select the first item. Select the first point; you will be prompted to select the next point. After you select the second point, you will again be prompted to select the next point. Select the third point. Once you have selected the three points, Autodesk Inventor draws reference lines between the first and second points as well as

between the second and third points. The angle between these two reference lines will be measured and displayed in the dialog box, as shown in Figures 3-43 and 3-44.




Figure 3-43 *Selecting three points*




Figure 3-44 *Angle between reference lines*

Tip. Autodesk Inventor allows you to switch from one measuring tool to another. This is done using the options in the flyout that is displayed on choosing the arrow on the right in the dialog box of any measuring tool. When you choose this arrow, the flyout will be displayed with the options for invoking other measuring tools.

Measuring Loops

Ribbon: Inspect > Measure > Loop Autodesk Inventor allows you to measure closed loops. To measure closed loops, right-click in the drawing window and choose Measure > Measure Loop from the Marking menu; the Measure Loop dialog box will be displayed. Alternatively, choose the Loop tool from the Measure panel; you will be prompted to select a face or a loop. Select the loop to be measured; the Measure Loop dialog box will be momentarily changed to the Loop Length dialog box and the measurement will be displayed in it. Figure 3-45 shows the Measure Loop dialog box with the measurement of a loop.

Measuring the Area Ribbon: Inspect > Measure > Area
To measure the area of closed loops, right-click in the drawing window and choose **Measure > Measure Area** from the Marking Menu; the **Measure Area** dialog box will be displayed and you will be prompted to select a face or a loop. Select the closed loop to measure the area; the **Measure Area** dialog box will be momentarily changed to the **Area** dialog box and the area of the loop will be displayed in it. Figure 3-46 shows the **Area** dialog box with the area of a closed loop.




Figure 3-45 The Measure Loop dialog box




Figure 3-46 The Area dialog box

Tip. You can also measure the loop or the area defined by the face of an existing

feature. You will learn more about features in the later chapters.

Adding Linear Measurements

Ribbon: Measure > Distance / Angle You can calculate the total measurement of several linear measurements by adding their values. To do so, invoke the Distance or Angle tool. Next, select the geometry or the distance to be measured; the measurement will be displayed in the Measure Distance dialog box. Next, click the arrow on the right side of the display box; a flyout will be displayed. Choose the Add to Accumulate option from the flyout and choose the same arrow again; the same flyout will be displayed. Choose the Restart option from the flyout. Next, choose another measurement and follow the same procedure until you add all the desired measurements. Then, click on the arrow and choose the Display Accumulate option from the flyout; the sum of the measurements will be displayed in the dialog box.

Clearing Accumulated Dimensions

On choosing the **Clear Accumulate** option, you can clear all the accumulated measurements and reset the sum to zero. This option is located below the **Add to Accumulate** option.

Evaluating Region Properties

Ribbon: Inspect > Measure > Region Properties **This tool is used to evaluate the properties of the closed loop sketch such as area, perimeter, and also display the region properties of the sketch such as Area and Moment of Inertia by taking measurements from the sketch coordinate system. To invoke this tool, right-click in the drawing window and choose Measure > Region Properties from the Marking menu; the Region Properties dialog box will be displayed, as shown in Figure 3-47. Alternatively, invoke the Region Properties tool by choosing the Region Properties tool from the Measure panel. The options in this dialog box are discussed next.**

Selections

When you invoke the **Region Properties** dialog box, this option is chosen by default. Also, you will be prompted to select one or more closed sketch loops. Select one or more closed sketch loops from the drawing window.

Dual Units

You can select the required unit of measurement from this drop-down list to display the results of measurements in the selected unit. You can view the results in two different units.

Calculate

After setting the options in the **Selections** and the **Dual Units** area, choose the **Calculate** button; the results will be displayed in the display box. In case you add or remove a closed loop in the **Selections** area or change the unit in the **Dual Units** drop-down list, the recalculation will occur and the updated results will be displayed in the display box.




Figure 3-47 *The Region Properties dialog box*

TUTORIALS

From this chapter onward, you will use the parametric feature of Autodesk Inventor for drawing and dimensioning the sketches. The following tutorials will explain the method of drawing sketches with some arbitrary dimensions and then driving them to the dimension values required in the model.

Tutorial 1

In this tutorial, you will draw the sketch shown in Figure 3-48. This sketch is the same as the one drawn in Tutorial 2 of Chapter 2. After drawing the sketch, you will add the required constraints and then dimension it. **(Expected time: 30 min)**




Figure 3-48 Dimensioned sketch for Tutorial 1

The following steps are required to complete this tutorial:

- Start a new metric standard part file and invoke the Sketching environment.
- Draw the initial sketch by using the **Line** and **Two point rectangle** tools, refer to Figure 3-49.
- Add the required constraints and dimensions to complete the sketch, refer to Figure 3-51.
- Dimension the sketch by using the origin to fully constrain it, refer to Figure 3-52.
- Save the sketch with the name *Tutorial1* and then close the file.

Starting a New File and Invoking the Sketching Environment Start Autodesk Inventor and then invoke the Sketching environment by selecting the sketching plane.

1. Start Autodesk Inventor by double-clicking on its shortcut icon on the desktop of your computer or by using the **Start** menu.
2. Choose the **New** tool from **Quick Access Toolbar** and start a new metric standard part file by using the **Metric** tab of the **Create New File** dialog box.
3. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
4. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
5. Select the **XZ** plane as the sketching plane from the graphics window; the Sketching environment is invoked and the **XZ** Plane becomes parallel to the screen.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Drawing the Initial Sketch 1. Using the **Line** and **Two point rectangle** tools, draw the required sketch similar to the one shown in Figure 3-48. You do not need to draw the sketch to the exact length. Use the temporary tracking option for drawing the sketch. For your reference, all lines in the sketch are numbered, see Figure 3-49.

Note that in this sketch, the display of the X and Y axes has been turned off.

Adding Constraints to the Sketch

It is evident from Figure 3-49 that some of the lines need to be of the same length. For example, lines 1 and 7, lines 2 and 6, lines 8 and 12, and so on. To make the lines of the same length, you can use two options. In the first option, you can assign dimensions to all these lines. However, this will increase the number of dimensions in the sketch. In the second option, you can apply constraints that will force the lines to maintain an equal length. You can apply the **Equal** constraint to all the lines having the same length. This constraint will relate the length of one of the lines with respect to the other. Now, if you dimension any one of the related lines, all other lines related to it will be forced to acquire the same dimension value. The **Equal** constraint is applied in pairs.




Figure 3-49 Initial sketch drawn using the sketching tools

1. Choose the **Equal** tool from the **Constrain** panel of the **Sketch** tab to invoke the **Equal** constraint.

When you invoke this constraint, you are prompted to select the first line, circle, or arc.

2. Select line 2; the color of this line is changed to blue and you are prompted to select the second line, circle, or arc. Select line 6; the **Equal** constraint is applied to lines 2 and 6. Again, you are prompted to select the first line, circle, or arc. Select line 6 as the first line and then line 8 as the second line.

While applying any of these constraints, if the Autodesk Inventor Create Constraint warning message box is displayed, choose Cancel to exit that box.

3. Similarly, select lines 8 and 12, 1 and 7, 3 and 5, 5 and 9, 9 and 11. The **Equal** constraint is applied to all these pairs of lines. Next, right-click in the drawing window, and then choose **Cancel (ESC)** from the Marking Menu displayed.
4. If needed, apply the **Horizontal** and **Vertical** constraints to the horizontal and vertical lines of the sketch, respectively.

Dimensioning the Sketch

Once all the required constraints have been applied to the sketch, you can dimension it. As mentioned earlier in this chapter, whenever you modify or apply dimension to an entity, it is forced to change its size with respect to the specified dimension value.

Note

On applying the first dimension to the sketch and editing it, the whole scale of the sketch is modified accordingly.

1. Choose the **Dimension** tool from the **Constrain** panel of the **Sketch** tab. Alternatively, right-click anywhere in the graphics window and then choose **General Dimension** from the Marking menu displayed. Next, select line 1, refer to Figure 3-49.

As soon as you move the cursor close to line 1, it turns red and a small symbol is displayed, indicating that a linear dimension will be applied to this line. It is important to modify the value of the dimension after it is placed so that geometries are driven to the values that you require. Therefore, after selecting line 1, right-click to display the Marking menu. In this menu, choose **Edit Dimension**. If it has already been chosen, press ESC once. This ensures that the **Edit box** is displayed whenever you place the dimension. This edit box allows you to modify the dimension value.

2. Place the dimension below line 1; the **Edit Dimension** edit box is displayed. Enter **80** as the length of line 1 in this edit box and then choose the check mark on the right of this edit box.

You will notice that the length of this line is modified to **80** units. Also, the length of line 7 is modified because of the **Equal** constraint.

3. As the **Dimension** tool is still active, you are prompted again to select the geometry to dimension. Select line 2 and place the dimension on the left of this line; the **Edit Dimension** edit box is displayed. Change the length of this line to **10** in this edit box and press ENTER.

You will notice that the length of lines 6, 8, and 12 is also forced to 10 units. This is because the **Equal** constraint has been applied to all these lines.

4. Select line 4 and place it along the previous dimension. Modify the dimension value in the **Edit Dimension** edit box to **30** and press ENTER. Notice that the length of line 10 is also modified.

5. Select line 16 and place the dimension outside the sketch on the right. Modify the dimension value in the **Edit Dimension** edit box to **20** and press ENTER.
6. Select line 15 and place the dimension outside the sketch on the top. Modify the dimension value to **30** in the **Edit Dimension** edit box and press ENTER.
7. Now, to dimension the distance between lines 4 and 14, select them one by one. Place the dimension outside the sketch on the top and then change the dimension value to **10** in the **Edit Dimension** edit box and press ENTER.
8. Similarly, select lines 16 and 10 to dimension the distance between these two lines and place the dimension outside the sketch on the top. Change the dimension value to **10** in the **Edit Dimension** edit box and press ENTER. You will notice that the length of lines 5, 9, 3, and 11 is automatically adjusted because the Equal constraint has been applied to them.
9. To locate the inner rectangle vertically from the outer loop, select lines 1 and 13, and then place the dimension on the right of the sketch. Next, modify the dimension value in the **Edit Dimension** edit box to **15** and press ENTER.

With this step, you have applied all the required constraints and dimensions to the sketch. Now the sketch is ready to be converted into a feature. If you try to add more constraints or dimensions to this sketch, the Autodesk Inventor Professional - Create Linear Dimension error message box will appear, informing that adding this dimension will overconstrain the sketch, see Figure 3-50. If you still want this dimension to be displayed, choose the Accept button from this message box; the dimension will be added as a driven dimension. A driven dimension is placed inside parentheses and is not used during the manufacturing process. This dimension is used only for reference. Note that you cannot edit the value of a driven dimension. The sketch after applying all the dimensions and constraints should look similar to the one shown in Figure 3-51.




Figure 3-50 The *Autodesk Inventor Professional* message box

Even after adding all the dimensions, the color of entities in the sketch is blue.

This is because the sketch is not fully constrained. In order to fully constrain the sketch, you need to constrain it with respect to the origin which is fixed by default.

10. Choose the **Coincident Constraint** tool from the **Constrain** panel of the **Sketch** tab; you are prompted to select the first curve or point.
11. Select the intersection point of lines 1 and 2, which is the lower left vertex of the sketch; you are prompted to select the second curve or point.
12. Select the origin; the entire sketch shifts itself such that the lower left vertex of the sketch is now at the origin.

Note that in spite of its shift, the sketch is not completely visible in the drawing window.

13. Choose the **Zoom All** tool from the **Navigation Bar** > **Zoom** flyout to fit the sketch into the drawing window. You will notice that all the entities in the sketch turn purple, indicating that the sketch is fully constrained. Next, press ESC to exit the **Coincident Constraint** tool.

Figure 3-52 shows the fully constrained sketch for Tutorial 1.




Figure 3-51 Sketch after adding dimensions




Figure 3-52 Fully constrained sketch for Tutorial 1

Saving the Sketch

1. Choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab to exit the Sketching environment. Alternatively, choose **Finish Sketch** from the Marking menu to exit the Sketching environment.
2. Choose the **Save** tool from the **Quick Access Toolbar** or **Application Menu** and save the sketch with the name *Tutorial1* at the location given below:
C:\Inventor_2016/c03
3. Choose **Close > Close** from the **Application Menu** to close the file.

Tutorial 2

In this tutorial, you will draw the sketch shown in Figure 3-53. This sketch is the same as the one drawn in Tutorial 4 of Chapter 2. After drawing it, you will apply the required constraints and dimensions to fully constrain it. **(Expected time: 30 min)**




Figure 3-53 Sketch for Tutorial 2

The following steps are required to complete this tutorial:

- a. Start a new metric standard part file.
- b. Invoke the Sketching environment and draw the initial sketch by using the **Line** tool, refer to Figure 3-54.
- c. Add **Linear Diameter** dimensions to the sketch by using the **Dimension** tool.
- d. Apply **Coincident Constraint** between the origin and the lower left vertex of

the sketch to make it a fully constrained sketch, refer to Figure 3-55.

- e. Add fillets, save the sketch with the name *Tutorial2.ipt*, and then close the file.

Starting a New File and Invoking the Sketching Environment 1.

Choose the **New** tool from the **Quick Access Toolbar** and start a new metric standard part file by using the **Metric** tab of the **Create New File** dialog box.

2. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
4. Select the **YZ** plane as the sketching plane from the graphics window; the Sketching environment is invoked and the **YZ** Plane becomes parallel to the screen. Alternatively, you can select the **YZ** plane from the **Browser Bar**.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Tip. Autodesk Inventor allows you to invoke the drawing display options even when a Sketching environment tool is active. This is done using a combination of hot keys and the left mouse button. For example, if the **Dimension** tool is active, you can use the **Pan** option by holding the F2 key and then pressing the left mouse button and dragging the cursor. Similarly, you can dynamically zoom in and out the sketch by holding the F3 key and then pressing the left mouse button and dragging the cursor.

Drawing the Initial Sketch

1. Draw the initial sketch, as shown in Figure 3-54, using the **Line** tool. The lines in the sketch are numbered for your reference.

Dimensioning and Constraining the Sketch The dimensions shown in Figure 3-53 are linear dimensions. As the sketch is for a revolved feature, you need to add linear diameter dimensions to it. It is recommended that you first apply all the dimensions and then add fillets to the sketch. This is because the size of a sketch generally changes after dimensioning. Before adding dimensions to a revolved section, it is important to determine which line segment of the sketch will act as the axis for revolving the sketch. If you refer to Figure 3-54, you will notice that line 1 acts as the axis to revolve the sketch for the model. Therefore, while applying linear diameter dimensions, line 1 should be selected first.




Figure 3-54 Lines numbered in the sketch

1. Choose the **Dimension** tool from the **Constrain** panel of the **Sketch** tab; you are prompted to select the geometry to be dimensioned. Right-click to display the Marking Menu, and then choose **Edit Dimension** from it, if it has not already been chosen. If it has already been chosen, press the ESC key once to exit the Marking Menu.
2. Select line 1; you are prompted again to select the geometry to be dimensioned. Select line 3 and then right-click; a Marking menu is displayed.

From this menu, choose the **Linear Diameter** option.

You will notice that the linear dimension is twice the actual length, which means that the distance between line 1 and line 3 is 4, but it will be displayed as **8** in the linear diameter dimension. Also, the dimension value is preceded by the \emptyset symbol, indicating that it is a linear diameter dimension.

3. Place the dimension on the left of the sketch; the **Edit Dimension** edit box is displayed.

Figure 3-53 shows the value to be specified as **4** because the linear diameter dimensions are placed twice.

4. Enter **8** in the **Edit Dimension** edit box and press ENTER; the vertical distance between lines 1 and 3 is automatically adjusted to the value entered.

5. As the **Dimension** tool is still active, you are prompted again to select the geometry to be dimensioned. Select lines 1 and 5 and then right-click; a Marking menu is displayed. Choose **Linear Diameter** from the Marking menu; the linear dimension is changed to the linear diameter dimension. Place the dimension on the left of the previous dimension. Next, modify its value in the **Edit Dimension** edit box to **20** and press ENTER.

6. Select lines 1 and 7. Right-click to display the Marking menu, and then choose **Linear Diameter** from it. Place the dimension on the left of the previous dimension and change its dimension value in the **Edit Dimension** edit box to **32**. Next, press ENTER.

*Tip. Sometimes while dimensioning a sketch, some existing dimensions move from the location where they have been placed. In this case, you need to exit the **Dimension** tool and then drag the existing dimensions back to their original locations. To resume dimensioning, invoke the **Dimension** tool again.*

7. Select lines 1 and 9, and then right-click; a Marking menu is displayed. In the Marking menu, choose **Linear Diameter**. Place the dimension on the right of

the sketch and change its value in the **Edit Dimension** edit box to **50** and then press ENTER.

8. Select lines 1 and 11, and then right-click to display the Marking menu. In this menu, choose **Linear Diameter**. Place the dimension on the right of the previous dimension and change its value in the **Edit Dimension** edit box to **60** and then press ENTER.

Now, you need to add linear dimensions to the sketch.

9. Select lines 12 and 8, and then place the dimension above the sketch. Modify its value in the **Edit Dimension** edit box to **5** and press ENTER.

10. Select line 11 and then place the dimension above the previous dimension. Modify its value in the **Edit Dimension** edit box to **20** and press ENTER.

11. Select line 1 and then place the dimension below the sketch. Modify its value in the **Edit Dimension** edit box to **22** and press ENTER.

12. Select lines 12 and 4, and then place the dimension below the previous dimension. Modify its value in the **Edit Dimension** edit box to **36** and press ENTER.

13. Select lines 12 and 6, and then place the dimension below the previous dimension. Modify its value in the **Edit Dimension** edit box to **44** and press ENTER.

With this, all dimensions have been added to the sketch. However, entities in the sketch are still displayed in green, indicating that the sketch is not fully constrained. Therefore, you need to add more dimensions or constraints to make the sketch fully constrained. In this sketch, add Coincident constraint to the origin and the intersection point of lines 1 and 2.

14. Invoke the **Coincident Constraint** tool; you are prompted to select the first curve or point. Select the intersection point of lines 1 and 2, which is the lower left vertex of the sketch; you are prompted to select the second curve or point.

15. Next, select the origin; the entire sketch shifts from its original location and is relocated such that the lower left vertex of the sketch now lies at the origin. Also, all entities in the sketch are displayed in purple, indicating that the sketch is fully constrained.

Note

If the entities of the sketch are not fully constrained, you need to apply the Vertical constraint to the vertical lines on the right of the sketch.

16. Choose the **Zoom All** tool from the **Navigation Bar > Zoom** flyout to fit the sketch into the drawing window. The fully constrained sketch after adding all the dimensions is shown in Figure 3-55.




Figure 3-55 Fully constrained sketch for Tutorial 2

Adding Fillets to the Sketch

After dimensioning the sketch, you need to add fillets to it.

1. Choose the **Fillet** tool from **Sketch > Create > Fillet** drop-down; the **2D Fillet** dialog box is displayed. In this dialog box, set the value of fillet to **1.5**. Now, select lines 8 and 9; the fillet is automatically added between these two lines and the dimension of the fillet is displayed.
2. Similarly, select lines 4 and 5 as well as lines 7 and 8 to add fillets between these lines. Exit the **2D Fillet** dialog box. The final sketch after adding fillets is shown in Figure 3-56.




Figure 3-56 Fully dimensioned sketch after adding fillets

Note

*To modify the radius of the fillet, double-click on it; the **Edit Dimension** edit box is displayed. Modify the value in this edit box and press **ENTER**.*

Saving the Sketch

1. Choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab to exit the sketching environment.
 2. Save this sketch with the name *Tutorial2* at the location *C:\Inventor_2016/c03*.
 3. Choose **Close > Close** from **Application Menu** to close the file.
-

Tutorial 3

In this tutorial, you will draw the sketch for the model shown in Figure 3-57. After drawing the sketch, you will add the required constraints to it and then dimension it. The dimensioned sketch required for this model is shown in Figure 3-58. The solid model shown in Figure 3-57 is only for reference.

The sketch shown in Figure 3-58 is the combination of multiple closed loops: the outer loop and inner circles. As the numbers of loops increase, so does the complexity of the sketch. This is because the numbers of constraints and dimensions in a sketch increase in case of multiple loops. Now, to draw sketches without using the Dynamic Input, it is recommended that you first draw the outer loop of the sketch and then add constraints and dimensions to it. This is because once the outer loop has been constrained and dimensioned, the inner circles can be constrained and dimensioned easily with reference to the outer loop.

(Expected time: 30 min)




Figure 3-57 Model for Tutorial 3




Figure 3-58 Dimensioned sketch of the model

The following steps are required to complete this tutorial:

- a. Start a new metric template and draw the outer loop of the sketch, refer to Figure 3-59.
- b. Invoke the Sketching environment and add the required dimensions and constraints to the outer loop, refer to Figure 3-61.
- c. Draw inner circles and add constraints and dimensions to them, refer to Figure 3-62.
- d. Save the sketch with the name *Tutorial3.ipt* and close the file.

Starting a New File and Invoking the Sketching Environment 1.

Choose the **New** button from the **Quick Access Toolbar** and start a new metric standard part file using the **Metric** tab of the **Create New File** dialog box.

2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
4. Select the **XY** plane as the sketching plane from the graphics window; the Sketching environment is invoked and the **XY** Plane becomes parallel to the screen.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose ***Set Current View as > Top/Front*** from the flyout.

Drawing the Outer Loop

1. To draw the outer loop, invoke the **Line** tool from the **Draw** panel in the **Sketch** tab, refer to Figure 3-59.




Figure 3-59 Profile with geometries numbered

You can also draw the tangent arcs while using the **Line** tool. This can be done by invoking the **Line** tool and by pressing the left mouse button and then dragging it in the required direction. Move the cursor close to the endpoint of the last line until the yellow circle snaps to that point. When the yellow circle snaps to the endpoint, it turns gray. Next, press and hold the left mouse button and drag the mouse through a small distance in the upward direction. Refer to Tutorial 3 of Chapter 2 to learn more about drawing this type of arc.

For your reference, all the geometries in the sketch are numbered. You will draw inner holes in the sketch after dimensioning the outer loop.

Note

The outer loop that you created in the previous step might be different from the one shown in Figure 3-59. You can find the missing constraints by following the next step and applying constraints accordingly.

Adding Constraints to Sketched Entities As evident from Figure 3-59, some of the constraints such as tangent and equal are missing in the sketch. The sketch shown in Figure 3-59 may not be symmetrical and all the lines in the sketch may not be tangent to the arcs. Therefore, you need to add these missing constraints manually to the sketch to complete it. You can choose the **Show Constraint** option from the Marking menu that is displayed when you right-click on an entity.

1. In Figure 3-59, the **Tangent** constraint is missing between line 1 and arc 10. To add this constraint between the line and the arc, choose the **Tangent** tool from the **Constrain** panel of the **Sketch** tab; you are prompted to select the first curve. Select arc 10 as the first curve; you are prompted to select the second curve. Select line 1 as the second curve. Similarly, add this constraint to all the places in the sketch wherever it is missing.

The geometries 5 and 7, and 3 and 9 are the lines that must be of equal length. Also, the geometries 2 and 10, and 4 and 8 are the arcs that must be of equal radii. Therefore, you need to add the Equal constraint between the respective pairs of all these geometries.

2. Choose the **Equal** tool from the **Constrain** panel of the **Sketch** tab.
3. Select line 5 as the first line and then line 7 as the second line to apply the Equal constraint to them; you are prompted again to select the first entity.
4. Select line 3 and then line 9 to apply the **Equal** constraint to them; you are prompted to select the first entity again.
5. Select arc 2 and then arc 10 to apply the **Equal** constraint to them. Applying this constraint to arcs or circles forces their radii or diameters to be equal.

6. Similarly, apply the **Equal** constraint to arc 4 and arc 8.
7. Apply the **Coincident Constraint** between the center point of arc 4 and line 5, and the center point of arc 8 and line 7, if it is not applied automatically.
8. Choose the **Symmetric** tool from the **Constrain** panel of the **Sketch** tab to apply **Symmetric** constraint between line 3 and line 9.
9. Choose the **Coincident Constraint** tool from the **Constrain** panel; you are prompted to select the first curve or point.
10. Select the origin; you are prompted to select the second curve or point.
11. Select the center point of arc 6; the entire sketch moves to make the origin coincident with the center point of the arc. The sketch after applying all the constraints is shown in Figure 3-60.




Figure 3-60 The sketch after applying all constraints

Note

The shape of the sketch that you have drawn may be a little different from the final sketch at this stage because of the difference in specifying points while drawing the sketch. However, once all the dimensions are applied, the shape of the sketch will be the same as of the final sketch. Also, you may need to add vertical constraint to lines 5 and 7 and horizontal constraint to line 1 to fully constrain the sketch.

Dimensioning the Sketch

1. Choose the **Dimension** tool from the **Constrain** panel of the **Sketch** tab. Next, right-click to display the Marking menu. From the Marking menu, choose **Edit Dimension** if the check mark is not available on the left of the **Edit Dimension** option. If it shows the check mark, press the ESC key once to exit the Marking Menu. On doing so, you are prompted to select the geometry to be dimensioned. Select line 1 and place the dimension below the sketch. Modify the value of this dimension in the **Edit Dimension** edit box to **20**.
2. Select arc 4 and place the dimension on the left of the sketch; the radius dimension of the sketch is placed. Modify the dimension value in the **Edit Dimension** edit box to **7.5**. The size of arc 8 is also modified because the Equal constraint is applied between these two entities.

Note

As discussed in the previous tutorial, you may need to use the combination of hot keys to zoom or pan the model.

3. Select arc 2 and place the radius dimension on the left of the sketch. Modify the dimension value in the **Edit Dimension** edit box to **10** and press ENTER. The size of arc 10 is also modified because of the **Equal** constraint applied between these two entities.
4. Select line 5 and then line 7, and then place the dimension above the sketch. Modify the value of this dimension in the **Edit Dimension** edit box to **15** and press ENTER.
5. Select line 7 and place the dimension on the right of the sketch. Modify the value of this dimension in the **Edit Dimension** edit box to **20** and press ENTER.
6. Select the upper endpoint of line 7 and select line 1, and then place the dimension on the right of the previous dimension. Modify the value of this dimension to **40** and press ENTER. Next, exit the **Dimension** tool.

With this step, all the dimensions have been applied to the sketch, refer to Figure 3-61, except the horizontal dimension between the center points of arcs 4 and 6 or arcs 8 and 6. The need of these dimensions depends on the constraints and dimensions assumed while drawing the sketch. If the sketch gets overconstrained, the **Autodesk Inventor Professional** message box is displayed. Choose **Cancel** from the message box. In this case, the dimension has already been assumed.

Drawing Circles

Once all the required dimensions and constraints have been applied to the sketch, you need to draw circles. Figure 3-58 indicates that circles are concentric with arcs 2 and 10.

1. To draw concentric circles, choose the **Center Point Circle** tool from the **Create** panel; you are prompted to select the center of the circle. Move the cursor close to the center of arc 2. Specify the center point when the cursor snaps to the center point of arc 2 and turns green. Next, move the cursor away from the center and specify a point to size the circle.
2. Similarly, draw the other circle taking the reference of the center of arc 10.

Adding Constraints to Circles

As both the circles have the same diameter, you can apply the **Equal** constraint to them. On applying the dimension to one of the circles, the other circle will automatically be forced to the specified diameter value because of the **Equal** constraint.

1. Invoke the **Equal** constraint tool from the **Constrain** panel. Select the first circle and then the second circle to apply the **Equal** constraint.

Dimensioning Circles 1. Choose the **Dimension** tool from the **Constrain** panel and select the left circle. Place the dimension on the left of the sketch. In the **Edit Dimension** edit box, change the value of the diameter of the circle to **8** and press **ENTER**.

Notice that because of the **Equal** constraint, the size of the right circle is automatically modified to match the dimension of the left circle. The final sketch for Tutorial 3 after drawing and dimensioning circles is shown in Figure 3-62.




Figure 3-61 Dimensioned sketch for Tutorial 3




Figure 3-62 The final dimensioned sketch for Tutorial 3

Saving the Sketch 1. Choose the **Return** tool from the **Quick Access Toolbar** to exit the sketching environment. Save this sketch with the name *Tutorial3* at the location given below:

C:\Inventor_2016/c03

Note

If the **Return** tool is not available in **Quick Access Toolbar**, you need to add this tool to the toolbar. To do so, choose the down arrow on the right of **Quick Access Toolbar**; a flyout is displayed. Next, choose the **Return** option from the flyout.

2. Choose **Close > Close** from the **Application Menu** to close the file.

Tutorial 4

In this tutorial, you will draw the sketch of the model shown in Figure 3-63. The dimensions of the sketch are shown in Figure 3-64. After drawing the sketch, add constraints and then dimension it. The solid model is given for reference only. **(Expected time: 30 min)**




Figure 3-63 Model for the sketch of Tutorial 4




Figure 3-64 The final dimensioned sketch for Tutorial 4

The following steps are required to complete this tutorial:

- a. Start a new metric standard part file and invoke the Sketching environment.
- b. Draw the outer loop of the sketch.
- c. Add the required dimensions and constraints to the sketch.
- d. Add the inner circle to the sketch and dimension it.
- e. Save the sketch with the name *Tutorial4.ipt* and close the file.

Starting a New File and Invoking the Sketching Environment 1.

Choose the **New** tool from the **Quick Access Toolbar** to display the **Create New File** dialog box. Start a new metric standard part file from the **Metric** tab of this dialog box.

2. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
4. Select the **XZ** plane as the sketching plane from the graphics window; the Sketching environment is invoked and the **XZ** Plane becomes parallel to the screen. Alternatively, you can select **XZ** plane from the **Browser Bar**.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Drawing the Outer Loop

1. Choose the **Line** tool from the **Create** panel of the **Sketch** tab to draw the outer loop, as shown in Figure 3-65. As mentioned earlier, you should draw the inner loop after drawing and dimensioning the outer loop. This is because once the outer loop is dimensioned, you can draw the inner loop by taking the reference of the outer loop.

You can draw the arc while the **Line** tool is active. You can also use the temporary tracking option to draw this sketch. For your reference, the geometries in the sketch are numbered, see Figure 3-65.




Figure 3-65 Initial sketch with the geometries numbered

Adding Constraints to the Outer Loop

1. Add the Equal constraint to lines 1 and 9, 2 and 8, 3 and 5, 5 and 7, and 4 and 6.
2. Add the Perpendicular Constraint to lines 2 and 3, and 7 and 8.
3. Add the Horizontal Constraint to the lower endpoints of lines 4 and 6.
4. Add the Tangent Constraint to lines 1 and 9 with arc 10, if it is missing.

Dimensioning the Outer Loop 1. Choose the **Dimension** tool from the **Constrain** panel of the **Sketch** tab; you are prompted to select the

geometry to dimension. Select line 9 and place the dimension on the left of the sketch. Modify the dimension value in the **Edit Dimension** edit box to **25** and press ENTER.

2. Select the center of the arc and then the lower endpoint of line 6. Place the dimension on the left of the previous dimension. Modify the dimension value in the **Edit Dimension** edit box to **60** and press ENTER.
3. Select line 3 and then right-click to display the Marking menu. Choose **Aligned** from the Marking menu and then place the dimension below the sketch. Modify the dimension value in the **Edit Dimension** edit box to **12.5** and press ENTER.

Notice that the length of lines 5 and 7 is also modified because of the Equal constraint.

4. Select lines 1 and 2 and then place the angular dimension on the right of the sketch. Modify the value of the angular dimension in the **Edit Dimension** edit box to **135** and press ENTER.
5. Select arc 10 and then place the radius dimension above the sketch. Modify the value of the radius of the arc in the **Edit Dimension** edit box to **15** and press ENTER.

With this, the required dimensions have been applied to the outer loop. Even after adding all dimensions, the color of entities in the sketch remains green.

6. Select the origin. Now, you can use the origin to fully constrain the initial sketch.
7. Choose the **Coincident Constraint** tool from the **Constrain** panel; you are prompted to select the first curve or point.
8. Select the center of the arc; you are prompted to select the second curve or point.
9. Select the origin. The entire sketch shifts itself such that the center of arc of

the sketch is at the origin. After the sketch is shifted to a new place, it may not be visible completely in the drawing window.

10. Choose the **Zoom All** tool from the **Navigation Bar > Zoom** flyout to fit the sketch into the drawing window. You will notice that all the entities in the sketch turn purple, indicating that the sketch is fully constrained. Press the ESC key to exit the **Coincident Constraint** tool.

Drawing the Circle

1. Choose **Center Point Circle** from the **Create** panel of the **Sketch** tab; you are prompted to select the center of the circle.
2. Move the cursor close to the center of the arc; the cursor snaps to the center point and turns green. Select this point as the center of the circle and then move the cursor away from the center to size the circle. Specify a point to give it an approximate size.

Dimensioning the Circle

1. Choose **Dimension** from the **Constrain** panel of the **Sketch** tab and select the circle. Place the diameter dimension below the arc dimension. Enter **25** in the **Edit Dimension** edit box and then press ENTER. This completes the sketch for Tutorial 4. The final dimensioned sketch is shown in Figure 3-66.




Figure 3-66 The final dimensioned sketch for Tutorial 4

Saving the Sketch

1. Choose the **Finish Sketch** option from the **Exit** panel of the **Sketch** tab to exit the sketching environment. Alternatively, choose the **Finish 2D Sketch** option from the Marking menu to exit the sketching environment
2. Save the sketch with the name *Tutorial4* at the location given below:
C:\Inventor_2016\c03
3. Choose **Close > Close** from **Application Menu** to close the file.

Self-Evaluation Test

Answer the following questions and then compare them to those given at the end of this chapter:

1. The _____ nature of Autodesk Inventor ensures that a selected entity is driven to a specified dimension value irrespective of its original size.
2. When you select a circle to be dimensioned, the _____ dimension is applied to it, by default.
3. The _____ dimension has one arrowhead and is placed outside a circle or an arc.
4. The _____ dimension displays the distance between two selected line segments in terms of diameter and the distance shown is twice the original length.
5. The _____ tool is used to measure the radius of an arc.
6. A _____ constrained sketch is the one whose entities are completely constrained to their surroundings using constraints and dimensions.
7. The Perpendicular Constraint forces a selected entity to become perpendicular to a specified entity. (T/F)
8. The Coincident Constraint can be applied to two line segments. (T/F)
9. The Collinear Constraint can only be applied to line segments. (T/F)
10. If an unnecessary constraint is applied to a sketch, Autodesk Inventor

displays a message box informing that adding this constraint will overconstrain the sketch. (T/F)

Answer the following questions:

1. You cannot apply the Concentric Constraint between a point and a circle. (T/F)
2. You can use the Horizontal Constraint or the Vertical Constraint to line up arcs, circles, or ellipses in the same horizontal or vertical direction. (T/F)
3. You can view all or some of the constraints applied to a sketch. (T/F)
4. There are twelve types of geometrical constraints that can be applied to the sketched entities. (T/F)
5. The linear dimensions are the dimensions that define the shortest distance between two points. (T/F)
6. A sketch in which the number of dimensions or constraints exceeds the required numbers is called as Overconstrained sketch. (T/F)
7. To which of the following toolbars does the **Measure Distance** toolbar change when you invoke the **Distance** tool and select two lines?

(a) **Length** (b) **Distance** (c) **Minimum Distance** (d) None of these

8. Which of the following dimensions is applied by default to an arc whenever it is dimensioned?

(a) **Radius** (b) **Diameter** (c) **Linear** (d) **Linear Diameter**

9. In addition to lines, which of the following entities can be selected to apply the Collinear constraint?

(a) Arc (b) Circle

(c) Ellipse (d) Ellipse axis

10. Which of the following combinations of entities cannot be used to apply the Tangent constraint?

(a) Line, line (b) Line, arc (c) Circle, circle (d) Arc, circle

Exercises

Exercise 1

Draw the sketch of the model shown in Figure 3-67. The sketch to be drawn is shown in Figure 3-68. After drawing the sketch, add the required constraints to it and then dimension it. **(Expected time: 30 min)**




Figure 3-67 Model for Exercise 1




Figure 3-68 Sketch for Exercise 1

Exercise 2

Draw the sketch of the model shown in Figure 3-69. The sketch to be drawn is shown in Figure 3-70. After drawing the sketch, add the required constraints to it and then dimension it.

(Expected time: 30 min)




Figure 3-69 Model for Exercise 2




Figure 3-70 Sketch for Exercise 2

Exercise 3

Redraw the sketch given in Exercise 1 of Chapter 2. After drawing the sketch, add the required constraints to it and then dimension it. The dimensioned sketch is shown in Figure 3-71. **(Expected time: 30 min)**

Exercise 4

Redraw the sketch given in Exercise 2 of Chapter 2. After drawing the sketch, add the required constraints to it and then dimension it. The dimensioned sketch is shown in Figure 3-72. **(Expected time: 30 min)**




Figure 3-71 Dimensioned sketch for Exercise 3




Figure 3-72 Dimensioned sketch for Exercise 4

Exercise 5

Draw the sketch of the model shown in Figure 3-73. The sketch to be drawn is shown in Figure 3-74. After drawing the sketch, add the required constraints to it and then dimension it.

(Expected time: 30 min)




Figure 3-73 Model for Exercise 5




Figure 3-74 Sketch for Exercise 5

Exercise 6

Draw the sketch of the model shown in Figure 3-75. The sketch to be drawn is shown in Figure 3-76. After drawing the sketch, add the required constraints to it and then dimension it.

(Expected time: 30 min)




Figure 3-75 Model for Exercise 6




Figure 3-76 Sketch for Exercise 6

Answers to Self-Evaluation Test **1.** parametric, **2.** diameter, **3.** radius, **4.** linear diameter, **5. Measure Distance**, **6.** fully, **7.** T, **8.** F, **9.** F, **10.** T

Chapter 4

Editing, Extruding, and Revolving the Sketches

Learning Objectives

After completing this chapter, you will be able to:

- Edit sketches using various editing tools.

- ***Create rectangular and circular patterns.***
- ***Write text in the Sketching environment and convert it into a feature.***
- ***Insert external images, Word documents, and Excel spreadsheets in the sketching environment.***
- ***Convert sketches into base features using the Extrude tool.***
- ***Convert sketches into base features using the Revolve tool.***
- ***Manipulate features by using the mini toolbar.***
- ***Dynamically change the view of a model using Free Orbit, ViewCube, and SteeringWheels.***
- ***Create primitive freeform shapes.***

EDITING SKETCHED ENTITIES

Autodesk Inventor provides you with a number of tools that can be used to edit the sketched entities. These tools are discussed next.

Extending Sketched Entities

Ribbon: Sketch > Modify > Extend You can extend or lengthen the selected entity up to a specified boundary by using the Extend tool. For using this tool, you should have at least two entities such that when extended, they meet at a point. Taking the reference of one of the entities, the other will be extended. The entities that can be extended using this tool are lines, splines, and arcs. On invoking this tool, you will be prompted to select the curve to be extended. As you move the cursor close to the curve to be extended, the original curve will be displayed in white and the portion to be extended will be displayed in black. While extending the arcs, the point where you select the arc will determine the side that will be extended. Figures 4-1 and 4-2 show the entities before and after their extension. In Autodesk Inventor, you can also dynamically extend lines and curves upto the nearest boundary. To do so, choose the Extend tool from the Modify panel, press and hold the left mouse button, and drag the cursor on the entities to be extended; the entities through which cursor passes will be extended to the nearest boundary.




Figure 4-1 Line before and after extending it




Figure 4-2 Arc before and after extending it

Trimming Sketched Entities

Ribbon: Sketch > Modify > Trim In Inventor, you can cut the length of an entity. You can do so by using the Trim tool. This tool chops the selected sketched entity by using an edge (also called the knife-edge). The knife-edge, in its current form, may or may not actually intersect the entity to be trimmed. However, when extended, the knife-edge must intersect the entity to be trimmed. On invoking this tool, you will be prompted to select the portion of the curve to be trimmed. As you move the cursor close to the curve to be trimmed, the entity will be highlighted and the portion of the entity to be trimmed will be displayed as a dashed line. Once you select the portion of the entity to be trimmed by clicking on it, the selected portion will be trimmed to the nearest intersection point with the next closest entity. Figure 4-3 shows the curves to be selected for trimming and Figure 4-4 shows the sketch after trimming the curves. If you use this tool on an isolated entity, it will work as the Delete tool and will delete the isolated entity.




Figure 4-3 Curves to be selected for trimming




Figure 4-4 Sketch after trimming the curves

To trim the entities within a boundary, press and hold the CTRL key after invoking the **Trim** tool; you will be prompted to select the geometry used for trimming. Select the geometry to be used as boundary for trimming. Next, release the CTRL key; you will be prompted to select the portion of the curve to be trimmed. Select the portion by clicking on it; the portion within the boundary will be trimmed. In Autodesk Inventor, you can also dynamically trim lines and curves. To do so, choose the **Trim** tool from the **Ribbon**, press and hold the left mouse button and drag the cursor on the entity to be trimmed.

*Tip. If you are using the **Extend** or **Trim** tool while editing, you can also temporarily switch between these tools by pressing and holding the SHIFT key. For example, if the active tool is **Trim** and you press and hold the SHIFT key, then this tool will act as the **Extend** tool, but on releasing the SHIFT key, the original tool will resume its function.*

Splitting Sketched Entities Ribbon: Sketch > Modify > Split The **Split** tool is used to break a sketched entity into two or more entities at the intersection point(s) with another sketched entity. On invoking this tool, you will be prompted to select a curve to split. As you move the cursor close to the sketched entity, it is highlighted in white and a red cross-mark will be displayed at the nearest intersection point or the apparent intersection point. The intersection point will be selected depending on the selection point on the sketched entity. It means that the intersection point nearest to the point of selection will be selected as the point of break for the sketched

entity. Click on the entity highlighted in red; the entity will split into two parts. Each part of the split entity will now act as an individual sketched entity and can be modified or deleted independent of the other part. However, the broken parts will be joined through the **Coincident** constraint. As a result, if you drag the broken entity to a new position, the entire entity will also move.

*Tip. If you are editing sketched entities using the **Trim** tool, you can switch to the **Extend** or **Split** tool. To do so, right-click in the drawing area; a Marking menu will be displayed. You will observe a check mark on the left of the active tool. Choose the editing tool as per your requirement to switch to that tool.*

Offsetting Sketched Entities

Ribbon: Sketch > Modify > Offset Offsetting is one of the easiest methods of drawing parallel lines, concentric arcs and circles. You can select the entire loop as a single entity or select the individual entities to be offset. When you invoke the Offset tool, you will be prompted to select the curve to offset. If you right-click at this point, a Marking menu will be displayed, as shown in Figure 4-5. The Loop Select option is chosen by default in this Marking menu, see Figure 4-5. This option allows you to select the entire loop as a single entity. However, if this option is cleared, the entire loop will be considered as a combination of individual segments and you will be allowed to select individual entities. The Constrain Offset option applies the constraints automatically when the loop or the individual entity is offset.




Figure 4-5 The Marking menu for offsetting the entities

If you choose the **Loop Select** option from the Marking menu, you will be prompted to specify the offset position for the new loop immediately after selecting the original loop. If you specify the location inside the original loop, the new loop will be smaller than the original loop. If you specify the location outside the original loop, the new loop will be bigger.

In case of individual entities, once you have selected the entity to be offset, right-click to display the Marking menu and choose **Continue**, or press the ENTER key to continue. You will be prompted to specify the location for the new entity. If the selected entity is a line segment, its length will remain the same and if it is an arc or a circle, the size of the new entity will depend on the location of the new point. Figure 4-6 shows the offset of a loop and Figure 4-7

shows the offset of an individual entity of a loop.




Figure 4-6 *Creating a new loop by offsetting the original loop*




Figure 4-7 *Offsetting an individual line segment to a new location*

Mirroring Sketched Entities

Ribbon: Sketch > Pattern > Mirror **The Mirror tool is used to create mirror images of the selected entities. The entities are mirrored about a straight line segment. This tool is used to draw sketches that are symmetrical about a line or sketches. When you invoke this tool, the Mirror dialog box will be displayed, as shown in Figure 4-8. The Select button is chosen by default. As a result, you will be prompted to select the geometry to be mirrored. You can select multiple entities to be mirrored. Once you have selected the entities, choose the Mirror line button; you will be prompted to select the line about which the entities should be mirrored. After selecting the mirror line, choose the Apply button; the selected entities will be mirrored about the mirror line. If the mirror line is at an angle, the resultant entities will also be at an angle. After mirroring the entities, choose the Done button to exit this dialog box. Figure 4-9 shows various sketched entities selected for mirroring and the mirror line that will be used to mirror the entities. Figure 4-10 shows the sketch after mirroring the entities.**



Figure 4-8 The Mirror dialog box

Figure 4-11 shows the entities selected to be mirrored about an inclined mirror line and Figure 4-12 shows the sketch after mirroring the entities. In Autodesk Inventor, the **Self Symmetric** check box is provided in the **Mirror** dialog box. By default, this check box is not activated. It is activated only when the geometry selected to mirror is an open spline and intersects the mirror line. On selecting this check box, the mirror command creates a single spline that is symmetric about the mirror line, refer to Figure 4-13. If this check box is cleared, the mirror copy of the sketched entity will be created about the mirror line, refer to Figure 4-14.




Figure 4-9 *Selecting the geometries to be mirrored about the mirror line*




Figure 4-10 *Sketch after mirroring the geometries and deleting the mirror line*




Figure 4-11 *Selecting the geometries to be mirrored about an inclined mirror line*






Figure 4-12 Sketch after mirroring the geometries and deleting the mirror line



*Figure 4-13 Sketch mirrored after selecting the **Self Symmetric** check box*



*Figure 4-14 Sketch mirrored after clearing the **Self Symmetric** check box*

Moving Sketched Entities

Ribbon: Sketch > Modify > Move **The Move tool is used to move one or more selected sketched entities from one point to the other. The points that can be used to move the entities include the sketched points, hole centers, the endpoints of lines, arcs, splines, and the center points of arcs, circles, and ellipses. When you invoke this tool, the Move dialog box will be displayed, as shown in Figure 4-15. You can also use this dialog box to create copies of the selected entities.**




Figure 4-15 The Move dialog box

Note

*R Remember that while moving constrained entities, the behavior of the entities depends on the constraints applied to them. If the selected entities are constrained with some other entities, the constrained entities will also move. However, if the other entities have a **Fix** constraint applied to them, because of which they cannot move from their location, the original entities will also not be able to move.*

Options in the Move Dialog Box

The options in the **Move** dialog box are discussed next.

Select

This button is used to select the entities to be moved. When you invoke the **Move** tool, this button is automatically chosen. Entities can also be selected using the Window Crossing options, or by selecting them one by one using the left mouse button.

Base Point

This button is chosen to specify the point that will act as the base point for moving the selected entities. Once you have selected all the entities to be moved, choose this button to select the point from where the movement will start.

Copy

This check box is selected to create a copy of the selected entities as they are moved. If this check box is selected, a copy of the selected entities will be created and placed at the destination point, keeping the original entities intact.


Precise Input

This check box, if selected, allows you to specify the coordinates for the base point and the destination point using the **Inventor Precise Input** toolbar.

Optimize for Single Selection

If this check box is selected, the **Base Point** button will be activated automatically, after making a single selection or the window selection of geometry. But if you clear this check box, you can make multiple geometry selections before choosing the **Base Point** button.

Autodesk Inventor allows you to control the geometric and dimensional constraints of the entity being moved. To do so, choose the >> button at the lower right corner of the **Move** dialog box; the **Move** dialog box will expand, as shown in Figure 4-16.



*Figure 4-16 The expanded **Move** dialog box*

The radio buttons in the **Relax Dimensional Constraints** area are used to control the behavior of the dimensional constraints that are applied to the sketched entities. Different radio buttons in this area are discussed next.

Never

If this radio button is selected then while moving the sketched entities, the existing dimensional constraints will not be ignored. If moving the sketched entities conflicts with the constraints applied to them earlier, then the **Autodesk Inventor Professional** message box will display warning about the conflicts.

If No Equation

This radio button, if selected, modifies the dimensions that are not a function of any other dimension, while the move operation is being performed.

Always

This radio button, if selected, modifies the dimensions of the entities that are outside the selection box, after moving the selected entities to a new position.

Prompt

This radio button is selected by default, and if the move operation cannot be performed with the existing dimensions and constraints, a dialog box offering possible solutions will be displayed.

Similarly, the radio buttons in the **Break Geometric Constraints** area control the behavior of the geometric constraints that are applied to the sketched entities. These radio buttons are discussed next.

Never

This radio button, if selected, will not ignore the geometric constraints that are applied to the sketched entities while moving them.

Always

This radio button, if selected, deletes only the geometric constraints that are associated with the selected entity.

Prompt

This radio button is selected by default and will display the possible solutions for moving the sketched entities.

Figures 4-17 through 4-20 show moving and copying of various sketched entities from one specified point to the other specified point after selecting the base point in the graphics window.




Figure 4-17 Moving the entities using the sketch points




Figure 4-18 Objects after moving




Figure 4-19 Moving and copying the entities using the center points of circles




Figure 4-20 Objects after moving and copying

Rotating Sketched Entities

Ribbon: Sketch > Modify > Rotate **The Rotate tool is used to rotate the selected sketched entities about a specified center point. You can also use this tool to create a copy of the selected entities while rotating them. When you invoke this tool, the Rotate dialog box will be displayed, as shown in Figure 4-21.**

Options in the Rotate Dialog Box

The options in the **Rotate** dialog box are discussed next.

Select

This button is chosen to select the entities to be rotated.




Figure 4-21 The Rotate dialog box

When you invoke the **Rotate** tool, the **Rotate** dialog box will be displayed and the **Select** button will be automatically chosen. You can use any object selection technique to select one or more objects.

Center Point Area

The **Select** button in the **Center Point** area helps you to specify a center point for rotation. The **Precise Input** check box, if selected, allows you to input the coordinates for the center point of rotation.

Angle

This edit box is used to define the value of the angle through which the selected entities will be rotated. You can enter the value in this edit box or choose the arrow on the right of this edit box to specify the predefined angle values. Remember that a positive angle will rotate the selected entities in the counterclockwise direction and a negative angle will rotate the selected entities in the clockwise direction.

Copy

This check box is selected to create a copy of the selected entities as they are rotated. If this check box is selected, a copy of the selected entities will be created and placed at the angle that you have specified in the **Angle** edit box. The original entities will be intact at their original location.

Optimize for Single Selection

If this check box is selected, then as soon as you select geometry, the **Select** button of the **Center Point** area will be activated automatically. But if you clear this check box, you can select multiple geometries before choosing the **Select** button from the **Center Point** area.

Autodesk Inventor allows you to control the dimensional and geometrical constraints that are applied to the sketched entities while rotating them. These options are available when you choose the >> button at the lower right corner of the **Rotate** dialog box. These options are the same as discussed in the previous section on moving the sketched entities. Figure 4-22 shows the rotation of the selected entities at various angles after selecting the base point.

*Tip. You can also create a copy of the sketched entities using the Marking menu. Select the sketched entities and right-click to display a Marking menu. In this menu, choose **Copy**. Again, right-click to display a Marking menu and choose **Paste** to paste the selected entities, thus creating a copy of the selected entities.*




Figure 4-22 Position of the entities at various angles

CREATING PATTERNS GENERALLY, IN THE MECHANICAL INDUSTRY, YOU COME ACROSS VARIOUS DESIGNS THAT CONSIST OF MULTIPLE

COPIES OF A SKETCHED FEATURE ARRANGED IN A PARTICULAR FASHION. FOR EXAMPLE, IT CAN BE MULTIPLE GROOVES AROUND AN IMAGINARY CIRCLE. IT CAN ALSO BE ALONG THE EDGES OF AN IMAGINARY RECTANGLE, SUCH AS THE GROOVES IN THE PEDESTAL BEARING. DRAWING THE SKETCHES FOR SUCH FEATURES AGAIN AND AGAIN IS A VERY TEDIOUS AND TIME-CONSUMING PROCESS. TO AVOID THIS LENGTHY PROCESS, AUTODESK INVENTOR PROVIDES YOU WITH AN OPTION FOR CREATING PATTERNS OF THE SKETCHED ENTITIES DURING THE SKETCHING STAGE ITSELF. THE PATTERNS ARE DEFINED AS THE SEQUENTIAL ARRANGEMENT OF THE COPIES OF THE SELECTED ENTITIES. YOU CAN CREATE THE PATTERNS IN A RECTANGULAR OR CIRCULAR FASHION. BOTH THESE TYPES OF PATTERNS ARE DISCUSSED NEXT.

Creating Rectangular Patterns Ribbon: Sketch > Pattern > Rectangular Pattern Rectangular patterns are the patterns that arrange the copies of the selected entities in rows and columns. When you invoke this tool, the **Rectangular Pattern** dialog box will be displayed, as shown in Figure 4-23. The options in this dialog box are discussed next.




Figure 4-23 The *Rectangular Pattern* dialog box

Geometry

This button is chosen by default and is used to select the entities to be patterned. You can select one or more entities to be patterned using any object selection technique.

Direction 1 Area

This area provides the option for defining the first direction of pattern creation, the number of copies to be created in this direction, and the spacing between the entities. These options are discussed next.

Direction

This button is with an arrow and is chosen to select the first direction of the rectangular pattern. The other options in the **Direction 1** area will be available only after you define the first direction of the pattern creation. The direction can be defined by selecting a line segment, which can be at any angle. The resultant pattern will also be created at an angle, if the line selected to specify the direction is at an angle. As you define the first direction, you can preview the pattern created using the current values in the drawing window. The pattern in the preview will be modified dynamically on changing the values in this dialog box.

Flip

This button is available on the right of the **Direction** button and is chosen to reverse the first direction of the pattern creation. When you define the first direction using the **Direction** button, an arrow appears on the sketch. This arrow displays the direction in which the items of the pattern will be created. If you choose this button, the direction will be reversed and the arrow will point in the opposite direction.

Count

This edit box is used to specify the number of items in the pattern along the first direction. Remember that this value includes the original selected item. On increasing the value in this edit box, you can dynamically preview the increased items in the pattern in the drawing window. You can also select a predefined number of items by clicking the arrow on the right of this edit box. When you click on the arrow, a list with predefined values is displayed. However, if you are using this tool for the first time in the current session of Autodesk Inventor, this list will not provide any value.

Spacing

This edit box is used to define the distance between the individual items of the pattern in the first direction. You can enter a value or choose the arrow on the right of this edit box to use the **Measure** or **Show Dimensions** options to define this value. The **Measure** option allows you to select a line segment, the length of which will specify the distance between the individual items. The **Show Dimensions** option allows you to use an existing dimension to specify the distance between the individual items of the pattern. The selected dimension will automatically appear in the edit box. You need to delete the existing value in this edit box to use the measured value.

Direction 2 Area

This area provides the option for defining the second direction of the pattern creation, the number of copies to be created in this direction, and the spacing between the entities. All these options are discussed next.

Direction

This button is chosen to select the second direction for arranging the items of the rectangular pattern.

Flip

This button is available on the right of the **Direction** button and is chosen to reverse the second direction of pattern creation.

Count

This edit box is used to specify the number of items in the pattern along the second direction.

Spacing

This edit box is used to define the distance between the individual items of the pattern in the second direction. Similar to the **Spacing** edit box in the **Direction 1** area, you can directly enter a value in this edit box or use the **Measure** or the **Show Dimension** options to define this value.

Figure 4-24 shows various parameters involved in creating a rectangular pattern with three items along direction 1 and four items along direction 2.





Figure 4-24 *Creating a rectangular pattern*

More

This button is provided on the lower right corner of the **Rectangular Pattern** dialog box. On choosing this button, the **Rectangular Pattern** dialog box expands, providing you with more options for creating the pattern, see Figure 4-25. These options are discussed next.

Suppress

This button is chosen to suppress the selected item from the pattern. When you select any item of the pattern using this button, it will change into dashed lines. The items that are suppressed will be displayed on the screen, but will not participate in the feature creation when you finish the sketch. You can unsuppress these items later, if required.



*Figure 4-25 More options in the **Rectangular Pattern** dialog box*

Note

T The process of editing sketches of the features will be discussed in the later chapters.

Associative

This check box is selected by default. As a result, all items of the pattern are associated with each other. All the items of the associative pattern are automatically updated, if any one of the entity is modified. For example, if you modify the dimension of any of the items of the pattern, the dimensions of all the other items will also be modified. However, if you clear this check box before creating the pattern, all the items will be individual entities and you can modify them individually.

Fitted

This option works in combination with the **Spacing** option in the **Direction 1** and **Direction 2** areas. If you select this option, the specified number of items will be created in the distances specified in the **Spacing** edit boxes in the **Direction 1** and **Direction 2** areas. Figure 4-26 shows the pattern created by clearing this check box (spacing is incremental) and Figure 4-27 shows the pattern created by selecting this check box (included spacing between all the items).




Figure 4-26 Pattern created with the **Fitted** check box cleared




Figure 4-27 Pattern created with the **Fitted** check box selected

Creating Circular Patterns

Ribbon: Sketch > Pattern > Circular Pattern **Circular patterns are the patterns created around the circumference of an imaginary circle. To create the circular pattern, you will have to define the center of that imaginary circle. When you invoke this tool, the Circular Pattern dialog box will be displayed, as shown in Figure 4-28. The options provided in this dialog box are discussed next.**




Figure 4-28 The Circular Pattern dialog box

Geometry

This button is chosen to select the entities to be patterned. As you select the individual entities, they turn blue, indicating that they are selected.

Axis

This button is provided on the right of the **Geometry** button. This button is chosen to select the center of the imaginary circle, around which the circular pattern will be created. The points that can be used to define the center of the pattern creation are the endpoints of lines, splines, and arcs, center points of arcs, circles, and ellipses, and the points/hole centers. Most of the options in the **Circular Pattern** dialog box are enabled only after you select the axis of rotation. You can dynamically preview the pattern using the current values. If you modify the other values in this dialog box, the preview of the pattern will also be modified.

Tip. If you select an arc or a circle to define the axis of the circular pattern, its center will be automatically selected as the center of the circular pattern. However, this is not possible in case of an ellipse. You cannot select an ellipse to define the center of the circular pattern. In such cases, you will have to select the center of ellipse.

Flip

This button is provided on the right of the **Axis** button, and when chosen, reverses the direction of pattern creation. By default, the circular pattern will be created in the counterclockwise direction. If you choose this button, the circular pattern will be created in the clockwise direction.

Tip. If the circular pattern is created through 360 degrees, you cannot notice the difference in the change of the direction of the pattern creation from counterclockwise to clockwise.

Count

This edit box is used to specify the number of items in the circular pattern. You can enter a value in this edit box or choose the arrow provided on the right of this edit box for using the predefined values or for using the **Measure** or **Show Dimension** option. These options are the same as those discussed in the rectangular pattern.

Angle

This edit box is used to define the angle for creating the circular pattern. You can directly enter an angle in this edit box or use the predefined values by choosing the arrow on the right of this edit box. You can also use the **Measure** or the **Show Dimensions** options to define the angle. Figures 4-29 and 4-30 show the circular patterns created using various angles.




Figure 4-29 Circular pattern with 6 items and a 270-degree angle




Figure 4-30 Circular pattern with 6 items and a 180-degree angle

More

This button is available on the lower right corner of the **Circular Pattern** dialog box. When you choose this button, the **Circular Pattern** dialog box expands, providing more options, see Figure 4-31. These options are discussed next.



*Figure 4-31 More options in the **Circular Pattern** dialog box*

Suppress

This button is chosen to suppress the selected item from the pattern. Similar to the rectangular pattern, when you select any item of the circular pattern, it will change into dashed lines. Although the items that are suppressed will be displayed in the drawing window, they will not participate in the feature creation when you finish the sketch. However, you can unsuppress these items later, if you need them.

Associative

This check box is selected so that all the items of the pattern are associated with each other. All the items of the associative pattern are automatically updated if any entity of the pattern is modified. If you clear this check box before creating the pattern, all items will become individual entities and you can modify them individually.

Fitted

This option works in combination with the **Angle** edit box. If you select this check box, the specified number of items will be created such that the angle specified in the **Angle** edit box defines the included angle between all the items. This check box is selected by default in the **Circular Pattern** dialog box. If you clear this check box, the angle that you specify in the **Angle** edit box will be considered as the incremental angle between each item. Figure 4-32 shows the pattern created by selecting this check box (included angle between all the items) and Figure 4-33 shows the pattern created by clearing this check box (angle is incremental).




Figure 4-32 Pattern created with the **Fitted** check box selected




Figure 4-33 Pattern created with the **Fitted** check box cleared

Tip. If you create a circular pattern through an angle of 360 degrees and clear

*the **Fitted** check box, you will see only one item in the drawing window. This is because the incremental angle between the individual items is 360 degrees and all the items will be arranged on top of each other, displaying only one copy.*

WRITING TEXT IN THE SKETCHING ENVIRONMENT AUTODESK INVENTOR ALLOWS YOU TO WRITE TEXT IN THE SKETCHING ENVIRONMENT. THE TEXT BEHAVES LIKE OTHER SKETCHED ENTITIES AND CAN BE CONVERTED INTO FEATURES USING THE MODELING TOOLS OF AUTODESK INVENTOR. THERE ARE TWO METHODS TO WRITE THE TEXT. THESE METHODS ARE DISCUSSED NEXT.

Writing Regular Text

Ribbon: Sketch > Create > Text drop-down > Text **To write text, choose the Text tool from the Create panel, refer to Figure 4-34; you will be prompted to select the location of the text. You can also drag a window to define the text box. Specify a point in the drawing window to start the text or press and hold the left mouse button and drag the mouse to define a window; the Format Text dialog box will be displayed, as shown in Figure 4-35. The options in this dialog box are discussed next.**




Figure 4-34 Tools in the Text drop-down




Figure 4-35 The Format Text dialog box

Style

This drop-down list is used to specify the text style to be applied to the text. To apply a particular text style to the text, you need to select the corresponding option from this drop-down list.

Bullets and Numbering in Text

The **Bullet and Numbering** buttons are available below the **Style** drop-down list. You can create bulleted or numbered lists using these buttons. To create a bulleted list, choose the **Bullet** button. Similarly, to create a numbered list click on the down arrow next to **Numbering** button and select the required numbering style from the drop-down list displayed.

Text Justification You can adjust the justification of the written text by choosing the buttons on the right of the **Numbering** drop-down of this dialog box. The justification of a text is defined using a combination of two buttons. By default, the **Left Justification** and **Top Justification** buttons are chosen. As a result, the justification for the text is top left. You can select other justifications by choosing their respective buttons. The **Baseline Justification** button is activated only when you choose the **Single Line Text** button on the left of **Line Space** drop-down list.

Spacing

You can select an option to define the spacing between the text lines using the **Line Space** drop-down list. If you select the **Multiple** option from this drop-down list, the **Spacing Value** edit box will be enabled and you can enter the multiplication factor for the line spacing in this edit box.

Fit Text

This button is activated only when you choose the **Single Line Text** button and is used to fit the text in a single line inside the window that you defined by dragging the mouse.

Stretch

You can define the percentage of text stretching in the **Stretch%** edit box. The default value in this edit box is 100. As a result, there is no stretching of the text. If you enter a value more than 100, the text width will be increased. If you enter a value less than 100, the width of the text will be reduced.

Font

The **Font** drop-down list is located below the **Bullet** and **Numbering** buttons. You can select the font for the text using this drop-down list.

Size

The **Size** edit box is used to specify the height of the text. You can enter the height in this edit box or select the standard values using the down arrow on the right of this edit box.

Color

The default color of the text is black. You can change the color of the text by choosing the **Color** button on the left of the **Bold** button. When you choose this button, the **Color** dialog box is displayed. You can specify the color of the text using this dialog box.

Text Style

You can define the text style by choosing the **Bold**, **Italic**, **Underline**, and **Strikethrough** buttons on the right of the **Size** drop-down list.

Stack

Stack button is used to create diagonal or horizontal stacked fractions, and superscript or subscript strings.

Text Case

This button is used to change the case of the selected string.

Text Box

If this button is chosen, a construction line box is placed around the text.

Rotation

The **Rotation** flyout is activated only if the **Text Box** button is not chosen. This flyout is used to specify the orientation of the text.

Text Window

You can enter the text in the **Text Window** area available in the **Format Text** dialog box. You can also paste the text copied from any other source. The text written in this window will appear on the screen.

Note

*The remaining options in the **Format Text** dialog box are used in the **Drawing** module and therefore, they are not discussed here.*

Writing Text Aligned to a Geometry Ribbon: Sketch > Create > Text drop-down > Geometry Text In Autodesk Inventor, you can write a text aligned to a line, arc, or circle. To do so, choose the arrow on the right of the **Text** tool and invoke the **Geometry Text** tool from the **Create** panel, refer to Figure 4-34; you will be prompted to select a geometry. Select the required line, circle, or arc; the **Geometry-Text** dialog box will be displayed, as shown in Figure 4-37. Most of the options in this dialog box are similar to the **Format Text** dialog box. The remaining options are discussed next.

Geometry

You can choose this button to change the default geometry and select a new one.

Direction Area

In this area, there are two buttons, **Clockwise** and **Counterclockwise**. These buttons are used to specify the orientation of the text.

Position Area

This area is used to specify the position of the text. Choose the **Outside** button to place the text outside the geometry. Choose the **Inside** button to place the text inside the geometry.




Figure 4-37 The Geometry-Text dialog box

Start Angle

This edit box is used to specify the angle between the left quadrant point of the selected geometry and the starting point of the text.

Offset Distance

This edit box is used to specify the offset distance between the text and the selected geometry.

Figure 4-38 shows the text created by using the **Outside** and **Clockwise** options. Figure 4-39 shows the text created using the **Inside** and **Counterclockwise** options. Note that in Figure 4-39, the text is created at an offset from the circle.




Figure 4-38 Geometry text created using the **Outside** and **Clockwise** options




Figure 4-39 Geometry text created using the **Inside**, **Offset Distance**, and **Counterclockwise** options

Note

You cannot write a geometry text along an ellipse, spline, or polygon.

INSERTING IMAGES AND DOCUMENTS IN

SKETCHES Ribbon: Sketch > Insert > Insert Image The **Insert Image** tool allows you to insert the external images such as JPG, BMP, PCX, TIFF, TGA, and so on in the sketch. You can also insert Word documents or Excel spreadsheets using this tool. To insert an image, invoke this tool; the **Open** dialog box will be displayed, as shown in Figure 4-40.




Figure 4-40 *The Open dialog box*

Select the image or document using this dialog box and then choose the **Open** button; the dialog box will be closed and you will be prompted to select the sketch point. The point you specify on the screen will be taken as the insertion point for the image. After inserting the image, right-click and choose **OK** from the Marking Menu to exit this tool.

Note

You may need to modify the drawing display area using the **Zoom All** tool to view the image on the screen.

Tip. To modify the size of the image inserted in the sketch, drag it by holding one of its four edges. Depending on the direction in which you drag it, the size will increase or decrease. To rotate the image, hold it at one of the corners and drag. The image will be rotated in the direction in which you drag the cursor. To move the image, press and hold the left mouse button anywhere on the image and drag the cursor.

EDITING SKETCHED ENTITIES BY DRAGGING AUTODESK INVENTOR ALLOWS YOU TO EDIT THE SKETCHED ENTITIES BY DRAGGING THEM. DEPENDING ON THE TYPE OF ENTITY SELECTED AND THE POINT OF SELECTION, THE OBJECT WILL BE MOVED OR STRETCHED. FOR EXAMPLE, IF YOU SELECT A CIRCLE AT ITS CENTER AND DRAG, IT WILL BE MOVED. HOWEVER, IF YOU SELECT THE SAME AT A POINT ON ITS CIRCUMFERENCE, IT WILL BE STRETCHED TO A NEW SIZE. SIMILARLY, IF YOU SELECT A LINE AT ITS ENDPOINTS, IT WILL BE STRETCHED AND IF YOU SELECT A LINE AT A POINT OTHER THAN ITS ENDPOINTS, IT WILL BE MOVED. THEREFORE, EDITING THE SKETCHED ENTITIES BY DRAGGING IS ENTIRELY DEPENDENT ON THE SELECTION OF POINTS. THE TABLE GIVEN NEXT WILL GIVE YOU THE

DETAILS OF THE OPERATION THAT WILL BE PERFORMED WHEN YOU DRAG VARIOUS OBJECTS.

Object

Selection point

Operation

Circle

On circumference	Stretch/Shrink
------------------	----------------

Center point

Move

Arc

On circumference	Stretch/Shrink
------------------	----------------

Center point

Move

Polygon

Any of the edges

Move

Endpoints

Move

Center point	Stretch/Shrink/ Rotate
--------------	------------------------

Single line	Any point other than the endpoints
-------------	------------------------------------

Move

Endpoints	Stretch/Shrink
-----------	----------------

Rectangle


All lines selected together

Move	
Any one line or any endpoint	Stretch/Shrink

TOLERANCES

In simple words, tolerance is defined as a permissible variation from the actual value. As it is an allowed variation, you can vary the dimension of the component through the specified value while manufacturing.

Adding Tolerances to the Dimensions in the Sketching Environment In Autodesk Inventor, tolerances are added to the sketch after dimensioning it. To add tolerance to a dimension, right-click on the dimension and choose **Dimension Properties** from the Marking menu; the **Dimension Properties** dialog box will be displayed. You can use the options in the **Dimension Settings** tab of this dialog box to add tolerances, refer to Figure 4-41.



*Figure 4-41 The **Dimension Settings** tab of the **Dimension Properties** dialog box*

By default, the **Default** option is selected in the **Type** drop-down list of the **Tolerance** area. As a result, no tolerance is added to the dimension. To add tolerance, select the required tolerance type from this drop-down list. Next, specify the value of the upper and lower limits in the **Upper** and **Lower** edit boxes. However, note that you can specify the upper and lower limits only if you select the **Deviation**, **Limits-Stacked**, or **Limits-Linear** option from the **Type** drop-down list. If you select any fit tolerance from this drop-down list, you can select the values of the hole fit and the shaft fit from the **Hole** and **Shaft** drop-down lists.

Note

*While specifying tolerances for a geometry, you need to make sure that the **Dimension** command is terminated.*

Once you have defined all the tolerance values, choose the **Apply** button in the **Dimension Properties** dialog box. You will notice that the tolerance is applied to the selected dimension. Now, choose **OK** to exit this dialog box. Figure 4-42 shows a sketch with the tolerance applied to the dimensions.




Figure 4-42 Sketch with the tolerance applied to the dimensions

In this figure, the vertical dimension is applied the deviation tolerance type. The upper deviation value for this tolerance is 0.05 mm and the lower deviation value is 0.02 mm. The horizontal dimension in the same figure is applied the symmetric tolerance of 0.05 mm.

CONVERTING THE BASE SKETCH INTO A BASE FEATURE AS MENTIONED EARLIER, ANY 3D DESIGN IS A COMBINATION OF VARIOUS SKETCHED, PLACED, AND WORK FEATURES. THE FIRST FEATURE, GENERALLY, IS A SKETCHED FEATURE. YOU HAVE ALREADY LEARNED TO DRAW THE SKETCHES AND TO

DIMENSION THEM. AFTER YOU HAVE FINISHED DRAWING AND DIMENSIONING THE SKETCH, CHOOSE THE **FINISH SKETCH** BUTTON FROM THE **EXIT** PANEL OF THE **SKETCH** TAB. ON CHOOSING THIS BUTTON, YOU WILL EXIT THE SKETCHING ENVIRONMENT AND ENTER THE **PART** MODULE. YOU WILL ALSO NOTICE THAT THE **SKETCH** TAB IS REPLACED BY THE **3D MODEL** TAB. AUTODESK INVENTOR PROVIDES YOU WITH A NUMBER OF TOOLS SUCH AS **EXTRUDE**, **REVOLVE**, **LOFT**, **SWEEP**, AND SO ON TO CONVERT THESE SKETCHES INTO BASE FEATURES. HOWEVER, IN THIS CHAPTER, YOU WILL LEARN THE USE OF THE **EXTRUDE** AND **REVOLVE** TOOLS FOR CONVERTING THE SKETCH INTO A BASE FEATURE. THE REMAINING TOOLS WILL BE DISCUSSED IN THE LATER CHAPTERS.

Note

On exiting from the Sketching environment, the sketch will be displayed in the Isometric view. Now, if you create any feature, you can dynamically preview the result while specifying the required options in the respective dialog boxes.

*Tip. From the Sketching environment, you can also proceed to the **Part** module by using the Marking menu. To do so, right-click in the graphics window and choose the **Finish 2D Sketch** option.*

EXTRUDING THE SKETCH RIBBON: 3D MODEL > CREATE > EXTRUDE THE **EXTRUDE** TOOL IS ONE OF THE MOST EXTENSIVELY USED TOOLS FOR CREATING A DESIGN. EXTRUSION IS A PROCESS OF ADDING OR REMOVING MATERIAL DEFINED BY A SKETCH, NORMAL TO THE CURRENT SKETCHING PLANE. IF YOU CREATE THE FIRST FEATURE, THE OPTIONS AVAILABLE TO YOU WILL BE USED FOR ADDING THE MATERIAL AND NOT FOR REMOVING IT. THIS IS BECAUSE THERE IS NO EXISTING FEATURE FROM WHICH YOU CAN REMOVE THE MATERIAL. WHEN YOU INVOKE THIS TOOL FROM THE CREATE PANEL IN THE RIBBON, THE **EXTRUDE** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 4-43. ALTERNATIVELY, CHOOSE THE EXTRUDE TOOL FROM THE MARKING MENU THAT IS DISPLAYED ON RIGHT-CLICKING IN THE GRAPHICS WINDOW. IN ADDITION TO THIS DIALOG BOX, A MINI TOOLBAR WILL BE DISPLAYED IN THE DRAWING WINDOW. THE MINI TOOLBAR IS A NEW USER INTERFACE THAT PROVIDES YOU WITH DIFFERENT OPTIONS TO CONTROL THE EXTRUSION PROCESS. THE OPTIONS IN THIS TOOLBAR WILL BE DISCUSSED LATER. THE

TABS IN THE **EXTRUDE** DIALOG BOX ARE DISCUSSEDNEXT.




Figure 4-43 The Extrude dialog box

Shape Tab

The options in this tab are discussed next.

Profile

This button is used to select the sketch to be extruded. If the sketch consists of a single loop, it will be automatically selected. In this case, because the sketch is already selected, the **Profile** button will not be chosen. However, if the sketch consists of more than one loop, this button will be chosen and you will be prompted to select the profile that you want to extrude. As you move the cursor close to one of the loops, it will be highlighted. After you have selected the sketch to be extruded, the preview of the resultant solid will be displayed in the drawing window. Also, the **Profile** selection tag attached to the preview of the solid feature will be displayed in the drawing window. The selection tag will be discussed later in this chapter. Note that if you select any of the inner loops, only that loop will be extruded. Also, after the extrusion of the selected inner loops, the remaining loops will no more be displayed on the screen. But, if you select the profile by specifying a point inside the outer loop but outside the inner loops, the sketch will be extruded such that the resultant solid will have the inner loops subtracted from the outer loop, refer to Figures 4-44 and 4-45.

*Tip. To remove the closed loop that has been selected using the **Profile** button, hold down **SHIFT** or **CTRL** key and then select the closed loop to be removed. As you move the cursor close to the sketch, different loops in the sketch will be highlighted and you can select the loop you want to remove by clicking inside that loop.*




Figure 4-44 Specifying the selection point inside the inner loop




Figure 4-45 *Specifying the selection point between the inner and outer loops*

Solids

The **Solid** button is used to select a body in a multi-body environment so that the resultant extruded feature becomes a portion of the body. You can join, cut, or intersect the resultant extruded feature to the selected body. This button will be active only when there are multiple bodies in the graphics window. The procedure to create multiple bodies will be discussed later in Chapter 5.

Output Area

The buttons in the **Output** area are used to specify the type of resulting feature. If you select a closed sketch to extrude, the **Solid** button is chosen automatically. As a result, a solid feature will be created. If you choose the **Surface** button, the resultant feature will be a surface. Remember that the sketches for surface models do not need to be closed loops. If you select an open sketch to extrude, the **Surface** button is chosen automatically in the **Extrude** dialog box.

Operation Area

This area is provided on the left of the **Extents** area and has four buttons. As the first feature created will be essentially a protrusion feature, no buttons except the **New solid** button will be enabled in this area. However, if a feature already exists in the drawing window and you want to extrude another sketch, the buttons namely **Join**, **Cut**, and **Intersect** will be enabled. These buttons are discussed in Chapter 5.

Extents Area

You can select the method of terminating the extruded feature using the options in the drop-down list available in the **Extents** area or mini toolbar. These options are discussed next.

Distance

By default, the **Distance** option is selected in this drop-down list. This option is used to define the extrusion depth by specifying its numeric value. The value of extrusion can be specified in the **Depth** edit box available below this drop-down list. If this feature termination option is selected, four buttons will be displayed below the **Distance** edit box. These buttons are used to specify the direction of extrusion. The current direction will be displayed by the **Direction 1** button. You can reverse the direction of feature creation by choosing the **Direction 2** button. The third button is used to extrude the feature equally in both directions of the current sketching plane. This button is also called the **Symmetric** button. For example, if the specified extrusion depth is 20 mm, the resultant feature will have extrusion depth of 10 mm above the current sketch plane and 10 mm below the current sketch plane. In Autodesk Inventor, you can extrude a sketch asymmetrically about the sketching plane. You can do so by using the **Asymmetric** button. After choosing this button, two edit boxes and two drop-down lists will be displayed in the **Extents** area of the **Extrude** dialog box. Also, two arrows will be displayed on the preview of the extruded model. Enter the required extrusion depths in the edit boxes or drag the arrows on the sides of the sketching plane to specify the depths of extrusion. You can interchange the extrusion depths of feature on two sides by choosing the **Flip** button. You can also specify the extrusion depth by using the mini toolbar.

Note

*You can also select **Measure** or **Show Dimensions** option, or specify a predefined distance value by choosing the arrow on the right of the **Depth** edit box to specify the depth of extrusion.*

Tip. You can dynamically modify the depth of asymmetric extrusion by using the manipulators. These manipulators are displayed as arrows pointing in opposite directions on the preview of the extrusion. Drag the required manipulator arrow to change the extrusion depth dynamically in the corresponding direction.

To

This is the second option in the **Distance** drop-down list and is used to define the termination of the extruded feature using an extended face, a work plane or planar face. When you select this option, all other options in the **Extents** area are removed and only the **Select surface to end the feature creation** button is displayed. If you select a plane or a face that does not intersect the extruding feature to terminate the extrusion, the **Check to terminate feature on the extended face** check box is displayed. This check box is selected to terminate the feature on the plane or the planar face as if it was extended.

Between

This is the third option in the **Distance** drop-down list. This option uses two planes to define a feature. The first plane defines the plane from which the feature will start and the second plane defines the plane for terminating the feature. When you select this option, all the remaining options in the **Extents** area are replaced by two buttons. The upper button is the **Select surface to start the feature creation** button and is used to define the plane where the feature starts. The lower button is the **Select the surface to end the feature creation** button and is used to define the plane where the feature terminates.

Match shape


This button will be activated only when you extrude an open profile. The procedure to create Match shape is discussed later in Chapter 5.

Note

*The methods of creating work planes will be discussed in the later chapters. The **Distance** drop-down list will display more options once you have created the base feature. These options will be discussed in Chapter 5.*

More Tab

The **Taper** option in the **More** tab is discussed in the next section, refer to Figure 4-46. The remaining options will be discussed in later chapters.



*Figure 4-46 The **More** tab of the **Extrude** dialog box*

Taper

This edit box is used to define the taper angle for the resulting solid model. Taper angles are generally provided to solid models for their easy withdrawal from the molds. A negative taper angle will force the solid to taper inwards, thus creating a negative taper. A positive taper angle will force the resultant solid to taper outwards, thus creating a positive taper. When you define a taper angle, an arrow will be displayed in the preview of the solid model in the drawing window. Depending on the positive or negative value of the taper angle, this arrow will point inwards or outwards from the sketch. Figures 4-47 and 4-48 show the model created using the negative and positive taper angles. Figure 4-49 shows a model extruded with a positive taper angle using the **Symmetric** option.




Figure 4-47 Model extruded with a negative taper angle




Figure 4-48 Model extruded with a positive taper angle




Figure 4-49 Model extruded with a positive taper angle using the **Symmetric** option

REVOLVING THE SKETCH

Ribbon: 3D Model > Create > Revolve The Revolve tool is used to create circular features like shafts, couplings, pulleys, and so on. You can also use this tool for creating cylindrical cut features.

A revolved feature is created by revolving the sketch about an axis. You can use a normal line segment, a center line, or a construction line of a sketch as the axis for revolving the sketch. On invoking this tool, the Revolve dialog box, as shown in Figure 4-50, and a mini toolbar will be displayed in the drawing window. This mini toolbar provides you with different options to control the revolution of sketches and will be discussed later. The options in the Revolve dialog box are discussed next.




Figure 4-50 The Revolve dialog box

Shape Tab

The buttons in this tab are used to select the sketch to be revolved and the axis of revolution. These buttons are discussed next.

Profile

This button is chosen to select the sketch to be revolved. If there is only one loop in the drawing window, the sketch will be automatically selected. Also, the **Profile** button will not be chosen. However, if there are more than one loops, this button will be chosen and you will be prompted to select the profile to be revolved. Also, two selection tags, **Profile** and **Axis**, will be displayed near the profile in the drawing window. The selection tag will be discussed later in this chapter.

Axis

This button is chosen to select the axis for revolving the sketch. As mentioned earlier, you can select a line segment in the sketch as the axis for creating the revolved feature. When you select the axis, the preview of the feature that is created using the current values will be displayed in the drawing window.

Solids

The **Solids** button is used to select a body in a multi-body environment so that the resultant revolved feature becomes a portion of the body. You can join, cut, or intersect the resultant revolved feature to the selected body. This button will be active only when there are multiple bodies in the graphic window.

Output Area

The buttons in the **Output** area are used to specify the type of output for the revolved feature. If you choose the **Solid** button, the resulting feature will be a solid. However, if you choose the **Surface** button, the resulting feature will be a surface. The sketch for the surface may or may not be closed. But for a solid feature, the sketch needs to be closed.

Operation Area

This area is provided on the left of the **Extents** area and has four buttons, namely **New solid**, **Join**, **Cut**, and **Intersect**. As the first feature created will essentially be a new revolved feature, no button except the **New solid** button will be active in this area. However, if a feature already exists in the drawing window and you want to extrude another sketch, all four buttons will be available. These buttons are discussed in Chapter 5.

Extents Area

The drop-down list provided under this area is used to specify the method of termination of a revolved feature. You can also specify the termination option by using the mini toolbar. These options are discussed next.

Full

This option is selected to create a feature by revolving the sketch through 360-degree. This is the default option.

Angle

This option is used to terminate the revolved feature at the specified angle. You can specify the angle of revolution by first selecting the **Angle** option and then entering the value in the edit box displayed below this drop-down list. Alternatively, you can specify the angle in the mini toolbar. You can also use a predefined value by choosing the arrow provided on the right side of this edit box. You can also use the **Measure** and **Show Dimensions** options to define the angle of revolution.

When you select the **Angle** option, four buttons will be displayed in this area. These buttons are used to define the direction of rotation. You can also revolve the sketch equally in both directions by choosing the **Symmetric** button. Figures 4-51 and 4-52 show the features created by revolving the sketches through different angles.




Figure 4-51 *Revolving the sketch through 360 degrees*




Figure 4-52 *Revolving the sketch through 270 degrees*

In Autodesk Inventor, you can revolve a sketch asymmetrically about the sketching plane. You can do so by using the **Asymmetric** button. After choosing this button, two edit boxes and two drop-down lists will be displayed in the **Extents** area of the **Revolve** dialog box. Also, two arrows will be displayed in the preview of the revolved feature. Enter the values for the revolution angle in the edit boxes or drag the arrows on the sides of the sketching plane to specify the angle on the respective sides. You can interchange the angle values of the feature by choosing the **Flip** button. You can also specify the revolution angle values by using the mini toolbar.

To

This is the third option in the **Extents** drop-down list and is used to define the termination of the revolved feature using an extended face, a work plane, or a planar face. When you select this option, the **Select surface to end the feature creation** button will be displayed. If you select a plane or a face that does not intersect the revolved feature to terminate revolution, the **Check to terminate feature on the extended face** check box will be displayed. This check box is selected to terminate the feature on the plane or the planar face as if it was extended toward it.

Between

This is the fourth option in the **Extents** drop-down list and uses two planes to create a revolved feature. The first plane defines the plane from which the feature will start and the second plane defines the plane for terminating the feature. When you select this option, the **Select surface to start the feature creation** and **Select surface to end the feature creation** buttons are displayed. The **Select surface to start the feature creation** button is used to define the plane where the feature starts and the **Select surface to end the feature creation** button is used to define the plane where the feature terminates.

DIRECT MANIPULATION OF FEATURES BY USING THE MINI TOOLBAR MINI TOOLBAR ALLOWS YOU TO DIRECTLY MANIPULATE OR MODIFY A FEATURE BY SPECIFYING VALUES OR OPTIONS OF THE FEATURE CREATION TOOLS SUCH AS **EXTRUDE**, **REVOLVE**, **HOLE**, **FILLET**, **CHAMFER**, **FACE DRAFT**, AND OTHER WORK FEATURE TOOLS. THIS TOOLBAR IS ACTUALLY A USER INTERFACE WITH COMBINATION OF SELECTION TAGS, COMMAND OPTIONS, AND MANIPULATORS. FIGURES 4-53 AND 4-54 SHOW THE MINI TOOLBARS THAT ARE DISPLAYED ON SELECTING THE SKETCHES FOR THE EXTRUDE AND REVOLVE OPERATIONS, RESPECTIVELY. DIFFERENT COMPONENTS OF THE MINI TOOLBAR, SHOWN IN FIGURE 4-55, ARE DISCUSSED NEXT.




Figure 4-53 Mini toolbar for the extrude feature




Figure 4-54 Mini toolbar for the revolve feature

Command Options The options that define the extent, direction, and value for the feature to be created are called command options. For example, in case of revolved feature, the extent options such as **Angle**, **To next face/body**, **To selected face/plane**, **Between two faces/planes**, and **Full**, and the direction options such as **Direction1**, **Direction2**, **Symmetric**, and **Asymmetric**, **Select Profile**, and **Axis** options are available. You can also enter the angle of revolution in the edit box provided in the mini toolbar. After setting these options, choose **OK** to finish the creation of revolve feature or

choose **Cancel**.




Figure 4-55 Components of the mini toolbar

Manipulators The manipulators appear in the form of arrows. The manipulators for the **Extrude**, **Revolve**, and **Hole** tools are represented by a straight arrow, a curved arrow, and a sphere, respectively. With the help of these manipulators, you can specify the extrusion depth of an extruded feature, angle of revolution for a revolved feature, and the location of the hole dynamically.

The function of the mini toolbar differs, based on the selection of the feature. If you have not invoked any tool and you click on the face of a model, the mini toolbar displays the options that can be used to create or edit sketches and edit the feature, refer to Figure 4-56. If a command is not active and you select an edge, the mini toolbar will provide you with options to create a fillet or a chamfer feature, refer to Figure 4-57. Similarly, if you select a sketch without invoking any command, the mini toolbar displays the options to create extruded feature, revolved feature, and hole as well as the option to edit a sketch, refer to Figure 4-58.




Figure 4-56 Mini toolbar displayed on selecting a face

Note

In Autodesk Inventor, when a calculation error occurs in the active command mode, an  error glyph is displayed in the Graphics window, next to the mini toolbar. If you click on the error glyph, the **Autodesk Inventor Professional** message box describing the error will be displayed on the screen. Error glyphs are commonly displayed while performing fillet, chamfer, and shell operations.




Figure 4-57 Mini toolbar displayed on selecting an edge




Figure 4-58 Mini toolbar displayed on selecting a sketch

ROTATING THE VIEW OF A MODEL IN 3D SPACE
AUTODESK INVENTOR PROVIDES THREE
DIFFERENT TOOLS TO ROTATE THE VIEW OF
THE MODEL. THESE TOOLS ARE DISCUSSED
NEXT.

Rotating the View of a Model Using the Orbit Ribbon: View > Navigate > Orbit drop-down > Orbit Autodesk Inventor provides you with an option to rotate the view of a solid model freely in 3D space. This feature allows you to visually maneuver the solid model and view it from any direction. To maneuver the model, choose the **Orbit** tool from the **Navigate** panel of the **View** tab, refer to Figure 4-59. When you choose this tool, a circle will be displayed with small lines at all four quadrant points and a cross at the center of the circle. The circle is called the rim, the small lines at four quadrants are called handles, and the cross at the center is called the center point. Also, when you invoke this tool, the shape of the cursor changes and the new shape thus created will depend on its current position. For example, if the cursor is inside the rim, it will show two elliptical arrows, suggesting that the model can be freely rotated in any direction. If you move the cursor close to the horizontal handles, the cursor will change to a horizontal elliptical arrow. The methods to rotate the view of a model are discussed next.




Figure 4-59 Tools in the **Orbit** drop-down

Rotating the View of a Model Freely in 3D Space To freely rotate the view of a model, move the cursor inside the rim; the cursor will be replaced by two elliptical arrows. Click inside the rim and then drag it anywhere in the drawing window. The model will dynamically rotate as you drag the cursor around the drawing window.

Rotating the View of a Model Around the Vertical Axis To rotate the view of a model around the vertical axis, move the cursor close to one of the horizontal handles; the cursor will be replaced by a horizontal elliptical arrow. Next, click and drag the cursor to rotate the model along the vertical axis.

Rotating the View of a Model Around the Horizontal Axis To rotate the view of a model around the horizontal axis, move the cursor close to one of the vertical handles; the cursor will be replaced by a vertical elliptical arrow. Now, click and drag the cursor to rotate the model along the horizontal axis.

Rotating the View Around the Axis Normal To the View To rotate the view of a model around an axis normal to the current view, move the cursor close to the rim; the cursor will be replaced by a circular arrow. Now, press and hold the left mouse button down and drag the cursor; the model will be rotated around the center point.

Figure 4-60 shows the view of a model being rotated freely in 3D space. To exit this tool, right-click to display the Marking Menu and choose **Done [ESC]**.




Figure 4-60 Rotating the view of a model freely in 3D space

Changing the View Using the ViewCube Autodesk Inventor provides you with an option to change the view of a solid model freely in 3D space using the ViewCube. A ViewCube is a 3D navigation tool, which allows you to switch between the standard and isometric views in a single click. By default, ViewCube remains in the inactive state, as shown in Figure 4-61. When you move the cursor closer to the ViewCube, it gets activated, as shown in Figure 4-62. You can control the visibility of the ViewCube by using the **Ribbon**. To do so, click on the **User Interface** drop-down in the **Windows** panel of the **View** tab and select /clear the **ViewCube** check box to view/hide the ViewCube, refer to Figure 4-63.



Figure 4-61 Inactive ViewCube



Figure 4-62 Active ViewCube

The faces, vertices, and the edges of the ViewCube are called clickable areas. If you place the cursor on any clickable area of the ViewCube, they will be highlighted. Click on the required area to orient the model such that the clicked area and the model becomes parallel to the screen. If you press and drag the left mouse button over the ViewCube, it will provide a visual feedback of the current viewpoint of the model. When you right-click on the ViewCube, a shortcut menu

will be displayed, as shown in Figure 4-64. The options in this shortcut menu are discussed next.




Figure 4-63 Options in the **User Interface** drop-down




Figure 4-64 The shortcut menu

Go Home

It is used to display the default view of the model. On choosing this option, you can switch over to the home view of the model.

Orthographic

Choose this option to display the model in the orthographic view.

Perspective

Choose this option to display the model in the perspective view.

Perspective with Ortho Faces

Choose this option to display the model in the orthographic projection when one of the faces of the ViewCube is active.

Lock to Current Selection

By default, this option remains inactive. To activate it, first you need to select the sketch or the model. If you choose this option, the View Cube will use the selected object as the center of the view and zoom to the extents of the selected object.

Set Current View as Home

This option is used to set the current view as the default view. When you move the cursor over the **Set Current View as Home** option, a small flyout will be displayed. The options in this flyout are **Fixed Distance** and **Fit to View**.

Fixed Distance is used to set a Home view, which defines direction of the view as well as extent of the model that fills the view. **Fit to View** is used to set a Home view which defines direction of the view as well as extent of the model always taken as **Zoom All** or view all mode.

Set Current View as

This option is used to set the current view of the model as **Front** or **Top** view depending upon your requirement. When you move the cursor to the **Set Current View as** tab, a small flyout will be displayed. You can select the options displayed in the flyout and make your current view as Top view or Front view.

Reset Front

This option is used to reset the front view to the default setting.

Options

Choose this option to invoke the **ViewCube Options** dialog box, as shown in Figure 4-65. Alternatively, you can access this dialog box by choosing the **Application Options** button from the **Options** panel of the **Tools** tab; the **Application Options** dialog box will be displayed. Next, choose the **Display** tab from the **Application Options** dialog box and then choose the **ViewCube** button; the **ViewCube Options** dialog box will be displayed, refer to Figure 4-65. The options in this dialog box are discussed next.




Figure 4-65 The ViewCube Options dialog box

Show the ViewCube on window create

By default, this check box is selected. As a result, the ViewCube will be displayed in the graphics window. Also, two radio buttons, **All 3D Views** and **Only in Current View** will be activated. By default, the **All 3D Views** radio button is selected and is used to display the ViewCube in all views. If you

select the **Only in Current View** radio button, the ViewCube will be displayed in the current view only.

Display Area

This area is used to display the on-screen position of the ViewCube, its size, and its inactive opacity. Select the required option from the **On-Screen Position** drop-down list in this area to set the position of ViewCube at any corner of the window such as **Top Right**, **Bottom Right**, **Top Left**, or **Bottom Left**. In this area, the default selection is **Top Right**.

Select the required option from the **ViewCube Size** drop-down list; the size of the ViewCube will be set. You can also set the opacity of the ViewCube in the inactive state using the **Inactive Opacity** drop-down list in this area. The default selection in this drop-down is **Automatic**.

When Dragging on the ViewCube Area

If the **Snap to closest view** check box is selected in this area, the view point will snap to one of the fixed views when the model is rotated using the ViewCube.

When Clicking on the ViewCube Area

This area is used for setting the preferences while clicking on the ViewCube.

Default ViewCube Orientation Area

The options in this area are used to set the alignment of the front and top plane of the ViewCube with the model-space plane, when you create a new part or assembly from a template.

Document Settings Area This area is used to set the preference for the default display of the Compass. If you select the **Show the Compass below the ViewCube** check box, the Compass will be displayed below the ViewCube in the graphics window, as shown in Figure 4-66. The **Angle of North (degrees)** spinner is used to set the angle between the **FRONT** face of the ViewCube and the **N** (North direction) of the Compass.



Figure 4-66 The ViewCube with Compass

Navigating the Model

Autodesk Inventor Professional allows you to navigate the model using different navigating tools such as **Zoom**, **Pan**, **Track**, and so on. Different navigating tools in Autodesk Inventor are discussed next.

SteeringWheels The **SteeringWheels** are the tracking tools that are divided into different wedges. Each wedge represents a single navigation tool such as **PAN**, **ORBIT**, **ZOOM**, **REWIND**, **LOOK**, **CENTER**, **WALK**, and **UP/DOWN**. You can activate any wedge of the SteeringWheels by pressing and holding the cursor over it. The SteeringWheels travels along with the cursor to provide a quick access to common navigation controls. To display the SteeringWheels, choose the **Full Navigation Wheel** drop-down and then choose the required option corresponding to the SteeringWheels. Figure 4-67 shows a Steering Wheels. You can also change the type of a SteeringWheels. To do so, right-click on the SteeringWheels; a shortcut menu will be displayed. Different types of SteeringWheels are available in this shortcut menu. You can choose any type of SteeringWheels by clicking on it




Figure 4-67 The Steering Wheels

Previous View

The **Previous View** tool in the **Navigate** panel of the **View** tab is used to view the previous orientation of the model.

Next View

The **Next View** tool in the **Navigate** panel of the **View** tab is used to activate the view that was current before you chose the **Previous View** tool. You can also switch to the previous view by pressing the F5 key and to the next view, by holding down the SHIFT key and then pressing the F5 key.

Note

*The **Pan** and **Zoom All** options are the same as those discussed in Chapter 2.*

CONTROLLING THE DISPLAY OF MODELS

Autodesk Inventor allows you to control the display of the models by setting various display modes and the camera type for displaying them. You can also control the display of the shadows of the model. The options for controlling the display of the models are discussed next.

Setting the Visual Styles

Ribbon: View > Appearance > Visual Style drop-down Visual style of a model determines the display of edges and face of a model in the graphics window. You can set the visual style for the solid models by using the Visual Style drop-down provided in the Appearance panel of the View tab, refer to Figure 4-68. Various visual styles available in this drop-down are discussed next.




Figure 4-68 Tools in the Visual Style drop-down

Realistic

The realistic visual style is used to shade the faces of a model with realistic materials. To apply this visual style, choose the **Realistic** tool from the **Appearance** panel. In this style, the visibility of the visible and hidden edges is turned off.

Shaded

This style is used to shade the faces of a model with standard materials and colors. To apply this visual style, choose the **Shaded** tool from the **Appearance** panel. In this style, the visibility of the visible and hidden edges is turned off.

Shaded with Edges

This visual style is selected by default. In this style, the model appears shaded with all external edges clearly visible. To apply this visual style, choose the **Shaded with Edges** tool from the **Appearance** panel. In this style, the standard materials and colors are assigned to the model.

Shaded with Hidden Edges

This style is used to shade a model with standard materials and colors keeping all the edges visible. To apply this visual style, choose the **Shaded with Hidden Edges** tool from the **Appearance** panel. In this style, the visibility of both the visible and hidden edges is turned on. The visible edges are displayed as solid lines and the hidden edges are displayed as dashed lines.

Wireframe

This style is used to display a model in wireframe with the shading turned off. To apply this visual style, choose the **Wireframe** tool from the **Appearance** panel. In this style, the visibility of both the visible and hidden edges is turned on and these edges are displayed as solid lines.

Wireframe with Hidden Edges

This style is used to display a model in wireframe with the shading turned off. To apply this visual style, choose the **Wireframe with Hidden Edges** tool from the **Appearance** panel. In this style, the visibility of the visible and hidden edges is turned on. In this style, all visible edges are displayed as solid lines, and all the hidden edges are displayed as dashed lines.

Wireframe with Visible Edges Only

This style is used to display a model in wireframe with the shading turned off. To apply this visual style, choose the **Wireframe Visible Edges Only** tool from the **Appearance** panel. In this style, the visibility of visible edges is turned on, and the visibility of hidden edges is turned off.

Monochrome

This style is used to give the model a simple monochromatic appearance. To apply this visual style, choose the **Monochrome** tool from the **Appearance** panel. In this style, the visibility of both the visible and hidden edges is turned off.

Watercolor

This style is used to give the visible components of a model a watercolor appearance. To apply this visual style, choose the **Watercolor** tool from the **Appearance** panel. In this style, the model appears to be hand-painted with water color. Also, the visibility of both the visible and hidden edges is turned off.

Sketch Illustration


This style is used to give the visible components of the model a hand drawn appearance. To apply this visual style, choose the **Sketch Illustration** tool from the **Appearance** panel. The visibility of the visible and hidden edges is turned off in this style.

Technical Illustration

This style is used to give the visible components of a model a shaded technical drawing appearance. To apply this visual style, choose the **Technical Illustration** tool from the **Appearance** panel. The visibility of the visible and hidden edges is turned off in this style.

Setting the Shadow Options

Ribbon: View > Appearance > Shadows drop-down In Autodesk Inventor, you can make your design look realistic by casting the shadows of objects. By default, the shadow option is turned off. You can cast three types of shadows. You can use the Shadows drop-down in the Appearance panel to cast different types of shadows, refer to Figure 4-69. The three types of shadows are discussed next.



*Figure 4-69 Options in the **Shadows** drop-down*

Ground Shadow

A ground shadow is a flat shadow appearing below the model. To cast a flat shadow, select the **Ground Shadow** check box from the **Shadows** drop-down in the **Appearance** panel; the shadow of the model will appear below it, as shown in Figure 4-70.

Object Shadows

The object shadows, also known as self shadows, are those that cast on the object itself. These shadows depend on the shape of the object and the lighting arrangement surrounding it. To cast an object shadow, select the **Object Shadows** check box from the **Shadows** drop-down in the **Appearance** panel; the object shadow of the model will be cast, as shown in Figure 4-71.




Figure 4-70 Model with the ground shadow




Figure 4-71 Model with the object shadows

Ambient Shadows The ambient shadows are those that are cast on the transition regions of the model such as cavities, grooves, and corners. These shadows are significant for enhancing the visual display of these transition regions. To cast the ambient shadow, select the **Ambient Shadows** check box from the **Shadows** drop-down in the **Appearance** panel.

All Shadows

You can have an object with all above mentioned shadows cast on it. To do so, you need to select the **All Shadows** check box from the **Shadows** drop-down in the **Appearance** panel.

Note

You can cast shadows only below the model and not on any other plane. The distance of the shadow from the model gets modified as you zoom the model.

Setting the Camera Type By default, the models are displayed in the orthographic camera type. You can change the camera type from the default orthographic to the perspective camera. This is done by choosing the **Perspective** tool from the **Appearance** panel of the **View** tab. On doing so, the model will be displayed in the perspective camera. Figure 4-72 shows the view of the model when the perspective camera is on.




Figure 4-72 Displaying a model in the perspective camera

-
-

CREATING FREEFORM SHAPES

The Solid primitives freeform shapes form the basic building blocks of a complex solid. In Autodesk Inventor 2016, you can directly create the primitive freeform shapes such as Box, Plane, Cylinder, Sphere, Torus, and Quadball. The procedure of creating various freeform shapes is discussed next.

Creating a Box

Ribbon: 3D Model > Create Freeform > Create Freeform drop-down > Box

You can create a box primitive by using the **Box** tool. To do so, invoke the **Box** tool from the **Freeform** drop-down in the Create **Freeform** panel of the **3D Model** tab, refer to Figure 4-73; the **Box** dialog box will be displayed and you will be prompted to select a plane. Select a plane from the **Browser Bar** or from the **Graphics window**; you will be prompted to specify the center of the box. Specify the center point; the preview of the box feature with distance manipulator arrows will be displayed, as shown in Figure 4-74. Specify the length, width, and height parameters for creating a box primitive in the **Box** dialog box. You can also specify number of face divisions along the width, length, and height in their respective edit fields of the **Box** dialog box. After specifying the required values, choose the **OK** button; the box will be created. By using the buttons in the **Direction** area of the dialog box, you can specify the direction in which the box will be created. By default, **Single Direction** button is activated. As a result, the box will be created on one side of the sketching plane. On activating the **Both Directions** button, the box will be created symmetrically on both side of the sketching plane.

Note that the **Length Symmetry**, **Width Symmetry**, and **Height Symmetry** check boxes are used to apply the symmetry condition along the **length**, **width**, and **height** of the model.




Figure 4-73 Options available in the Freeform drop-down




Figure 4-74 The Extrude Distance Manipulator displayed after the center point is specified

Creating a Plane Ribbon: 3D Model > Create Freeform > Freeform drop-down > Plane To create a plane primitive on an origin plane, a work plane, or a planar face, choose the **Plane** tool from the **Freeform** drop-down in the **Create Freeform** panel of the **3D Model** tab; the **Plane** dialog box will be displayed and you will be prompted to select a plane. Select a plane from the **Browser Bar** or from the graphics window; you will be prompted to specify the center of the plane. Specify the center of the plane; the preview of the plane with manipulator arrows will be displayed in the graphics window. In the dialog box, specify the length and width of the plane in the **Length** and **Width** edit boxes, respectively and choose the **OK** button; the freeform plane will be created, as shown in Figure 4-75. The remaining options are the same as discussed while creating freeform box feature.




Figure 4-75 The plane created after specifying the centre point

Note that the **Length Symmetry** and **Width Symmetry** check boxes are used to apply the symmetry condition along the length and width of the model, respectively.

Creating a Cylinder Ribbon: 3D Model > Create Freeform > Freeform drop-down > Cylinder To create a cylindrical primitive, choose the **Cylinder** tool from the **Freeform** drop-down in the **Create Freeform** panel of the **3D Model** tab; the **Cylinder** dialog box will be displayed and you will be prompted to select a plane. Select a plane from the Browser Bar or from the Graphics window; you will be prompted to specify the center of the cylinder by clicking the left mouse button. Specify the center of the cylinder by clicking the left mouse button, the preview of the cylinder with Manipulator arrows will be displayed. In the dialog box, specify the radius and height of the cylinder in the Radius and Height edit boxes, respectively and choose the OK button; the freeform cylinder will be created, as shown in Figure 4-76. The remaining options are the same as discussed while creating box freeform feature.




Figure 4-76 The freeform cylindrical feature

Note that the **X Symmetry**, **Y Symmetry**, and **Z Symmetry** check boxes are used to apply the symmetry condition in the **X**, **Y**, and **Z** axis directions, respectively.

Creating a Sphere

Ribbon: 3D Model > Create Freeform > Freeform drop-down > Sphere To create a spherical shaped freeform, choose the **Sphere** tool from the **Freeform** drop-down in the **Create Freeform** panel of the **3D Model** tab; the **Sphere** dialog box will be displayed. Also, you will be prompted to select a plane. Select a plane from the **Browser Bar** or from the **Graphics window**; you will be prompted to specify the center of the sphere. Specify the center of the sphere by clicking the left mouse button; the preview of the sphere will be displayed. In the **Sphere** dialog box, specify the radius of the sphere. Also, you can specify number of face divisions along the **Longitude** and **Latitude** directions in their respective edit fields of the dialog box. Next, choose the **OK** button; the freeform sphere will be created, as shown in **Figure 4-77**.




Figure 4-77 The freeform sphere feature

Note that the **X Symmetry**, **Y Symmetry**, and **Z Symmetry** check boxes are used to apply the symmetry condition in the **X**, **Y**, and **Z** directions, respectively.

Creating a Torus

Ribbon: 3D Model > Create Freeform > Freeform drop-down > Torus To create a torus in Autodesk Inventor, choose the **Torus** tool from the **Freeform** drop-down of the **Create Freeform** panel of the **3D Model** tab; the **Torus** dialog box will be displayed, refer to Figure 4-78. Also, you will be prompted to select a plane. Select a plane from the **Browser Bar** or from the **Graphics window**; you will be prompted to specify the center of the torus. Specify the center of the torus; the preview of the torus will be displayed. In the **Torus** dialog box, specify the radius and the ring of the torus in their respective edit boxes. Next, choose the **OK** button; the freeform torus feature will be created, refer to Figure 4-79.




Figure 4-78 The Torus dialog box




Figure 4-79 The freeform torus feature

Note that the **X Symmetry**, **Y Symmetry**, and **Z Symmetry** check boxes are used to apply the symmetry condition in the **X**, **Y**, and **Z** directions respectively.

Creating a Quadball

Ribbon: 3D Model > Create Freeform > Freeform drop-down > Quadball **To create a spherical shaped freeform**




Figure 4-80 The freeform quadball feature

quadball, choose the **Quadball** tool from the **Freeform** drop-down in the **Create Freeform** panel of the **3D Model** tab; the **Quadball** dialog box will be displayed; you will be prompted to select a plane. Select a plane from the **Browser Bar** or from the Graphics window; you will be prompted to specify the center of quadball. Specify the center point; the preview of the quadball will be displayed. In the **Quadball** dialog box, specify the radius and the faces for the quadball in their respective edit boxes. Next, choose the **OK** button; the freeform quadball feature will be created, refer to Figure 4-80.

Note that the **X Symmetry**, **Y Symmetry**, and **Z Symmetry** check boxes are used to apply the symmetry conditions in the **X**, **Y**, and **Z** directions, respectively.

TUTORIALS

Tutorial 1

In this tutorial, you will open the sketch drawn in Tutorial 1 of Chapter 3. You will then convert this sketch into a solid model by extruding it to a distance of 20 mm. After creating the solid model, you will rotate its view in 3D space by using the **SteeringWheels**. **(Expected time: 30 min)**

The following steps are required to complete this tutorial:

- Save the sketch from the *c03* folder to the *c04* folder with another name.
- Open the sketch from the *c04* folder and extrude it to a distance of 20 mm using the **Extrude** tool.
- Change the material of the model by using the **Color Override** drop-down list from the **Quick Access Toolbar**.
- Rotate the model in 3D space using the **SteeringWheels** tool.

Opening the Sketch Drawn in Chapter 3

- Start Autodesk Inventor by double-clicking on its shortcut icon on the desktop of your computer or by using the **Start** menu. Next, choose the **Open** tool from the **Launch** panel of the **Get Started** tab; the **Open** dialog box is displayed.
- Open the *c03* folder from the location *C:\Inventor_2016* and then open the *Tutorial1.ipt* file.

When you open an existing part drawing, by default, you get into the **Part** module even if the drawing is just a sketch. Also, the sketch is displayed in the isometric view, see Figure 4-81.




Figure 4-81 Sketch displayed in the isometric view

Saving the Sketch with Another Name After opening the sketch, you need to first save it with another name so that the original sketch drawn in Chapter 3 is not modified. To do so, make sure you save a copy of the file with a different name in *c04* folder.

1. Choose **Save As > Save As** from the **Application Menu**; the **Save As** dialog box is displayed.
2. Browse to the location *C:\Inventor_2016\c04* in the **Save in** drop-down list.
3. Save the sketch with the name *Tutorial1.ipt*.

*Tip. If you have not created a folder with the name c04, you can create it by using the **Save Copy As** dialog box. To do so, select the *Inventor_2016* folder from the **Save in** drop-down list. Next, choose the **Create New Folder** button and specify *c04* as the name of the folder.*

Extruding the Sketch

As mentioned earlier, when you open an existing part file, you are by default, in the part modeling environment and the sketch is displayed in the isometric view. Sometimes, when you open an existing sketch, the dimensions of the sketch are not displayed in the current view. In such a case, use the **Zoom All** tool to increase the drawing display area so that all the dimensions are displayed in the current view. As you are in the part modeling environment, all tools of this module are available in the **3D Model** tab.

1. Choose the **Extrude** tool from the **Create** panel of the **3D Model** tab to invoke the **Extrude** dialog box. Alternatively, choose the **Create Extrude** tool from the mini toolbar, which is displayed when you select any sketched entity in the graphics window.

As the sketch consists of two loops, the sketch is not automatically selected. Therefore, the **Profile** button in the **Shape** tab gets activated and you are prompted to select the profile to be extruded. Also, the **Profile** selection tag is displayed in the mini toolbar in the graphics window. The mini toolbar also provides you with various options to browse through and make the work easier for you. It comprises almost all commands that are displayed in the **Extrude** dialog box.

2. Move the cursor outside the inner loop but inside the outer loop; the profile is highlighted, as shown in Figure 4-82.

As shown in Figure 4-82, the area inside the inner loop is not highlighted. This shows that the selected profile, when extruded, will have a cavity at the center. This cavity is defined by the inner loop.

3. Click anywhere in the highlighted area, refer to Figure 4-82; the preview of the extruded model along with the mini toolbar interface is displayed in the drawing window.
4. Enter **20** in the **Depth** edit box available in the **Extents** area. Alternatively, enter **20** in the input edit box of the mini toolbar. You can also drag the extrude manipulator to specify the extrusion depth.

5. Choose **OK** from the dialog box to create the model and exit the **Extrude** tool. Alternatively, choose **OK** from the mini toolbar. The extruded model is shown in Figure 4-83.




Figure 4-82 Selecting the profile to be extruded




Figure 4-83 The model created on extruding the profile

Changing the Material of the Model

After extruding the sketch, you need to change the material of the extruded part.

1. Click on the down arrow on the right of the **Material** option in the **Quick Access Toolbar**; a drop-down list is displayed.
2. Select the **Brass, Soft Yellow** option from this drop-down list; the material of the extruded model changes to metallic brass. Also, the color of the model gets changed in the graphics window.

Rotating the View of the Model in 3D Space 1. Choose the **Full**

Navigation Wheel tool from the **Navigation Bar** or from the **Navigate** panel of the **View** tab; the SteeringWheel is attached to the cursor.

2. Move the cursor over the model and then move it inside the **Zoom** wedge, as shown in Figure 4-84.




Figure 4-84 Zooming the model freely in 3D space

3. Press and hold the left mouse button; the **Zoom** tool is activated. Next, drag the cursor front and back to zoom the model in or out.
4. After releasing the left mouse button, move the cursor inside the **ORBIT** wedge and press and hold the left mouse button; the **Orbit** tool is activated. Now, as you drag the cursor, the model rotates about the **PIVOT** point displayed in green color in the Graphics window.
5. Move the cursor inside the **PAN** wedge and press and hold the left mouse button; the **Pan** tool is activated. Drag the cursor; the model moves along with the cursor.
6. Move the cursor inside the **REWIND** wedge and press and hold the left mouse button; the previous views are displayed in small boxes in a row. Drag the cursor along the row and select a view.

7. Move the cursor over the model and then move it inside the **CENTER** wedge. Next, press and hold the left mouse button on the **CENTER** wedge; a pivot is attached to the model. Release the left mouse button; the pivot is moved to the center of the drawing area.
8. Click on the cross mark at the top right corner of the SteeringWheels to exit this tool. Alternatively, right-click to display the shortcut menu and choose **Close Wheel** from the shortcut menu to exit this tool.
9. Again, right-click and choose **Home View** from the shortcut menu; the current view is changed to the isometric view.

Saving the Model

1. Choose **Save > Save** from the **Application Menu** to save the changes made to the model. As the file is already saved once, the **Save As** dialog box is not displayed.
 2. Choose **Close > Close** from the **Application Menu** to close this file.
-

Tutorial 2

In this tutorial, you will open the sketch drawn in Tutorial 2 of Chapter 3 and then convert it into a fully revolved model. Next, you will change the projection type to perspective and then view the model. **(Expected time: 30 min)**

The following steps are required to complete this tutorial:

- a. Open the sketch in *Tutorial2* from the *c03* folder and save it in the *c04* folder.
- b. Open the sketch from the *c04* folder and revolve it through an angle of 360 degrees by using the **Revolve** tool.
- c. Change the projection type and view the model.

Opening the Sketch Drawn in Chapter 2

1. Choose **Open** from the **Application Menu** to display the **Open** dialog box.
2. Using the **Open** dialog box, open the *Tutorial2.ipt* file from the location *C:\Inventor_2016\c03*; the sketch is displayed in the **Part** module in the isometric view.

Saving the Sketch with Another Name 1. Choose **Save As > Save As** from the **Application Menu**; the **Save As** dialog box is displayed.

2. Browse to the location *C:\Inventor_2016\c04* and save the sketch with the name *Tutorial2*.

Sometimes, the dimensions of the sketch are not be displayed completely in the current drawing display area. In such a case, you can increase the drawing display area using the **Zoom All** and **Pan** tools to fit the dimensions in the current view, refer to Figure 4-85.




Figure 4-85 Sketch in the isometric view after zooming and panning

Revolving the Sketch

As mentioned earlier, you need an axis of revolution to revolve a profile. This axis can be a sketched line segment.

1. Choose the **Revolve** tool from the **Create** panel to display the **Revolve** dialog box. Alternatively, choose the **Revolve** tool from the mini toolbar that is displayed on selecting any of the sketched entities in the graphics window. Since the sketch has just one loop, therefore it is automatically selected and highlighted. Also, the **Axis** button is activated and you are prompted to select the axis.
2. Select the bottom horizontal line that measures 22 mm as the axis of revolution.

When you move the cursor close to this line, it is highlighted. On selecting this line, the preview of the revolved model is displayed in the drawing window. Also, the mini toolbar with the **Full** option selected in the **Extents** drop-down list is displayed in the drawing window.

3. Accept the default values and choose **OK** from the mini toolbar to complete the process of creating the revolved model.

Changing the View of the Model

The current view, in which the model is displayed, does not show the model properly. Therefore, you will have to change the view of the model.

1. In case, the ViewCube is hidden, select the **ViewCube** check box from the **User Interface** drop-down in the **Windows** panel of the **View** tab.
2. To view the component from another direction, click on the top-most corner of the ViewCube, as shown in Figure 4-86.
3. Press and hold the left mouse button on any face of the ViewCube and drag the cursor. As the cursor moves, the model also reorients to give you a better view of the model.
4. Choose the **Zoom All** tool from the **Navigate** panel of the **View** tab or from the **Navigation Bar** to modify the drawing display area.

Changing the Camera Type

By default, the orthographic camera type is selected to display the model and therefore the orthographic view of the model is displayed. However, in this tutorial, you need to display the model in perspective camera or view.

1. Choose the **Perspective** tool from the **Appearance** panel in the **View** tab; the perspective view of the model is displayed, refer to Figure 4-87.




Figure 4-86 Selecting the corner of the ViewCube




Figure 4-87 Model displayed using the perspective projection

Saving the Model

1. Choose **Save > Save** from the **Application Menu** to save the model.
 2. Now, choose **Close > Close** from the **Application Menu** to close this file.
-

Tutorial 3

In this tutorial, you will create the model shown in Figure 4-88. Its dimensions are shown in Figure 4-89. The extrusion height for the model is 10 mm. After extruding it, you will set the option to cast the X-ray ground shadow. **(Expected time: 45 min)**




Figure 4-88 Model for Tutorial 3




Figure 4-89 Dimensions of the model

The following steps are required to complete this tutorial:

- a. Start a new metric standard part file. Draw the sketch of the outer loop and add constraints to it.

- b. Draw the inner circles and add the required constraints. Dimension the complete sketch.
- c. Extrude the sketch to a distance of 10 mm using the **Extrude** tool.
- d. Cast the object and ambient shadows on the final model.

Starting a New Part File

If you have installed Autodesk Inventor with millimeter as the unit of measurement, you can directly start a new metric standard part file, thus avoiding the use of the **Create New File** dialog box for opening a new part file.

1. Choose the **New** tool from the **Quick Access Toolbar**; a flyout is displayed.
2. Choose the **Part** option from this flyout to start a new metric part file. If Autodesk Inventor was not installed with millimeter as the measurement unit, you need to choose the **Metric** tab of the **Create New File** dialog box to start the new metric standard part file.

Note

*You can change the units used in Inventor file by using the **Document Settings** dialog box. To invoke this dialog box, choose the **Document Settings** tool from the **Options** panel in the **Tools** tab. Next, choose the **Units** tab in this dialog box to display various options related to units. Select the required unit from the **Length** drop-down list in the **Units** area of this dialog box. Next, choose **Apply** and then **Close** to exit the dialog box.*

Y

Creating the Sketch of the Model

As shown in Figure 4-89, the sketch is a combination of an outer loop and three circles. First, you will create the outer loop. This outer loop will be created by drawing three circles, two at the ends and one at the center, and then connecting the middle circle with the other two circles through tangent lines. Finally, you will trim the unwanted portions of the circles.

1. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select a sketching plane.
2. Choose the **Home** button from the ViewCube; the current orientation of the sketch plane is changed.
3. Now, select the **XY** plane from the **Browser Bar** as the sketching plane; the Sketching environment is invoked and the **XY** plane becomes parallel to the screen. Alternatively, you can also select **XY** plane from the Graphics window.

*Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout .*

4. Draw the sketch, which is a combination of three circles and tangent lines. Add the **Tangent** constraint to the lines wherever it is missing. Also, add the **Equal** constraint to all four lines, and the circles on the left and right sides. Finally, add the **Horizontal** constraint to the centers of the circles. The sketch, after drawing and adding constraints, should look similar to the one shown in Figure 4-90.




Figure 4-90 Sketch after drawing and adding constraints

Next, you need to remove the unwanted portions of the circles using the **Trim** tool.

5. Choose the **Trim** tool from the **Modify** panel of the **Sketch** tab; you are prompted to select the portion of the curves to be trimmed.
6. Move the cursor close to the right half of the left circle.

As you move the cursor close to the circle, the color of the circle turns white and it appears as dashed on the right side.

7. Specify a point on the right half of the left circle; the right half of this circle is trimmed. Similarly, select portions of the other circles to trim, as shown in Figure 4-91.

8. Next, draw three circles concentric to the three trimmed arcs. Add the **Equal** constraint between the left and right circles. The sketch after drawing the circles and applying the **Equal** constraint to them should look similar to the one shown in Figure 4-92.




Figure 4-91 *Selecting the portions to be trimmed*




Figure 4-92 Sketch after creating the outer loop and the three circles

Dimensioning the Sketch

1. Dimension the sketch as required. The sketch, after it has been dimensioned, will look similar to the one shown in Figure 4-93.




Figure 4-93 Sketch after adding dimensions

Extruding the Sketch

The sketch consists of four loops: the outer loop and the three circles. When you extrude this sketch, the three circles will be automatically subtracted from the outer loop. As a result, you will get the required model. However, this is possible only if the point specified for selecting the profile is inside the outer loop but outside all three circles.

1. Choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab to exit the sketching environment. Alternatively, choose the **Finish 2D Sketch** option from the Marking Menu that is displayed on right-clicking anywhere in the graphics window. You will notice that the current view is changed to the Home view.
2. Choose the **Extrude** tool from the **Create** panel of the **3D Model** tab; the **Extrude** dialog box is invoked. You can also invoke the **Create Extrude** tool from the mini toolbar, which is displayed when you select the sketched entity. As the sketch consists of more than one loop, the **Profile** button is chosen in the **Shape** tab of the **Extrude** dialog box and you are prompted to select the profile to be extruded.
3. Move the cursor to a point anywhere inside the outer loop but outside all three circles; the profile is selected and highlighted. Notice that the area inside any of these circles is not shaded. This shows that the area inside these circles will not be extruded. This is also one of the methods to cross check whether the profile selected is the one you need to extrude or not.
4. Click inside the shaded profile; the preview of the model is displayed in the drawing window. Also, the mini toolbar is displayed in the drawing window.
5. Accept the default values and then choose **OK** from the mini toolbar to extrude the profile to a depth of 10 mm.

You may need to change the camera type from perspective to orthographic if the camera type currently used is perspective. To change the camera type, choose the **Orthographic** button from the **Appearance** panel of the **View** tab. The final model is shown in Figure 4-94.

Casting the Object Shadow and the Ambient Shadow Next, you need to apply the object shadow and ambient shadow to the model. You can cast these shadows using the options in the **Shadows** drop-down list in the **Appearance** panel of the **View** tab.

1. Click on the down arrow on right of **Shadows** in the **Appearance** panel; a drop-down is displayed.
2. In this drop-down, the **Ambient Shadows** check box is selected by default. Select the **Object Shadows** check box from the drop-down; the object and ambient shadows are cast on the model, as shown in Figure 4-95.

Saving the Model

1. Choose the **Save** tool from the **Quick Access Toolbar**; the **Save As** dialog box is displayed.
2. Save the model with the name *Tutorial3* at the location given below:
C:\Inventor_2016\c04
3. Choose **Close > Close** from the **Application Menu** to close the file.




Figure 4-94 Final model for Tutorial 3




Figure 4-95 Object and ambient shadows applied on the model

Tutorial 4

In this tutorial, you will extrude the text and then change the visual style of the extruded text, as shown in Figure 4-96. The font size of the text is 5 mm and the height of extrusion of the text is 2.5 mm. **(Expected time: 45 min)**




Figure 4-96 *Extruded text with the hand drawn appearance*

The following steps are required to complete this tutorial:

- a. Start a new metric standard part file and write the text in the sketching environment.
- b. Extrude the text to a distance of 2.5 mm using the **Extrude** tool.
- c. Change the visual style of the extruded text.

Starting a New File and Writing the Text 1. Start a new metric standard part file using the **Metric** tab of the **Create New File** dialog box. Also, ensure that the display of the shadow is turned off.

2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Choose the Home button from the **ViewCube**; the current orientation of the sketch plane is changed.
4. Now, select the **XY** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **XY** plane becomes parallel to the screen. Alternatively, you can also select the **XY** plane from the Graphics window.

Note If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the

*ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

If

5. Choose the **Text** tool from the **Create** panel of the **Sketch** tab; you are prompted to click on the location of the text.
6. Specify a point anywhere in the drawing window; the **Format Text** dialog box is displayed.
7. Select the **Arial** font from the **Font** drop-down list and then set the font height to 5 mm in the **Size** edit box.
8. Type the text **Autodesk Inventor** in the **Text Window** in two lines. Choose **OK** to exit the dialog box; the typed text is displayed in the drawing window, as shown in Figure 4-97.

Extruding the Text Next, you need to exit the sketching environment and extrude the text.

1. Choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab and exit the sketching environment. Alternatively, choose the **Sketch** option from the Marking Menu that is displayed when you right-click anywhere in the graphics window. Note that the current view is changed to the home or isometric view.

Note

*The **Finish Sketch** button will not be available if you have already exited the sketching environment.*

2. Choose the **Extrude** tool from the **Create** panel of the **3D Model** tab; the **Extrude** dialog box is invoked and the mini toolbar is displayed in the drawing window. Also, you are prompted to select the profile to extrude.
3. Move the cursor over the text and select it when it is highlighted.

4. Specify **2.5** as the extrusion depth in the input edit box of the mini toolbar. Choose **OK** from the mini toolbar; the text is extruded to a distance of 2.5 mm, refer to Figure 4-98.

Changing the Visual Style

After extruding the text, you need to change its visual style.

1. Click the **Visual Style** in the **Appearance** panel of the **View** tab; a drop-down is displayed.




Figure 4-97 Text in the Sketching environment




Figure 4-98 Text after extrusion

2. Choose the **Sketch Illustration** tool from this drop-down to give the extruded text a hand-drawn appearance. The final extruded text with the hand-drawn appearance is shown in Figure 4-98.




Figure 4-99 Text after changing the visual style

Saving the Sketch

1. Choose the **Save** tool from the **Quick Access Toolbar**; the **Save As** dialog box is displayed. Save the model with the name *Tutorial4* at the location given below:

C:\Inventor_2016\c04

2. Choose **Close > Close** from the **Application Menu** to close the file.

Self-Evaluation Test Answer the following questions and then compare them to those given at the end of this chapter:

1. The _____ tool is used to switch between the different standard views in a single click.
2. In the shortcut menu, you need to clear the _____ option if you want to select only one entity from a closed loop for offsetting.
3. To create a copy of an existing sketched entity by rotating it, select the _____ check box in the **Rotate** dialog box.
4. Autodesk Inventor is used to create two types of sketch patterns, namely _____ and _____.
5. The _____ option is used to select a line segment whose length will define the distance between the individual items.
6. The _____ angles are generally provided to solid models so that the models can be easily taken out from the casting.
7. If the _____ button is chosen in the **Extrude** dialog box, the resulting feature will be a surface and not a solid.
8. In Autodesk Inventor, you cannot reduce the length of a line once it is drawn. (T/F)
9. The copies of the sketched entities can be arranged along the length and width of an imaginary rectangle using the **Circular Pattern** tool. (T/F)

10. When you select a profile by using a point that is inside the outer loop but outside the inner loops, the resultant solid will have the inner closed loops subtracted from the outer closed loop. (T/F)

Review Questions Answer the following questions: 1.

Which of the following tools can be used to reposition the sketched entity from one place to another place by using two points?

(a) **Move** (b) **Rotate** (c) **Mirror** (d) **Extend**

2. Which of the following tools can be used to arrange multiple copies of sketched entities around an imaginary circle?

(a) **Move** (b) **Rotate** (c) **Rectangular Pattern** (d) **Circular Pattern**

3. Which of the following options allows you to use an existing dimension to define the distance between individual items of a pattern?

(a) **Dimension** (b) **Show Dimensions** (c) **Measure** (d) None of these

4. Which of the following check boxes should be selected to ensure that all items in the pattern are automatically updated, if any one of the entities is modified?

(a) **Associative** (b) **Fitted** (c) **Suppress** (d) None of these

5. Which of the following options in the ViewCube shortcut menu is used to the display the home view of the model?

(a) **Go Home** (b) **Reset Front** (c) **Options** (d) **Orthographic**

6. You can invoke the **Trim** tool from within the **Extend** tool by pressing the SHIFT key. (T/F)

7. Offsetting is one of the easiest methods of drawing parallel lines or concentric arcs and circles. (T/F)

8. If you select a circle by clicking on a point on its circumference and then drag it, the circle will move from its location. (T/F)

9. Selecting a line at its endpoint and dragging it will stretch the line. (T/F)

10. You can move a rectangle by selecting and then dragging it. (T/F)

Exercises

Exercise 1

In this exercise, you will extrude the sketch drawn in Exercise 5 of Chapter 3, refer to Figure 4-100. The extrusion depth for the model is 15 mm. **(Expected time: 30 min)**




Figure 4-100 Sketch for Exercise 1

Exercise 2

In this exercise, you will extrude the sketch drawn in Exercise 1 of Chapter 3, refer to Figure 4-101. The extrusion depth for the model is 80 mm. **(Expected time: 30 min)**




Figure 4-101 Sketch for Exercise 2

Exercise 3

In this exercise, you will extrude the sketch drawn in Exercise 3 of Chapter 2, refer to Figure 4-102. The extrusion depth for the model is 40 mm.

(Expected time: 30 min)




Figure 4-102 Sketch for Exercise 3

Exercise 4

In this exercise, you will extrude the sketch drawn in Exercise 3 of Chapter 3, refer to Figure 4-103. The extrusion depth for the model is 35 mm. **(Expected**

Exercise 6

In this exercise, you will extrude the sketch drawn in Exercise 4 of Chapter 2, see Figure 4-105. The extrusion depth for the model is 30 mm. **(Expected time: 30 min)**




Figure 4-105 Sketch for Exercise 6

Exercise 7

In this exercise, you will extrude the sketch, as shown in Figure 4-106. The extrusion depth for the model is 30 mm. **(Expected time: 30 min)**




Figure 4-106 Sketch for Exercise 7


Answers to Self-Evaluation Test 1. **1. ViewCube**, **2. Loop Select**, **3. Copy**, **4. Rectangular**, **Circular**, **5. Measure**, **6. taper**, **7. Surface**, **8. F**, **9. F**, **10. T**

Chapter 5

Other Sketching and Modeling Options

Learning Objectives

- *Create features on planes other than the default XY plane.*
- *Create work features such as work planes, work axes, and work points.*
- *Use other extrusion and revolution options for creating models.*



NEED FOR OTHER SKETCHING PLANES

In the earlier chapters, you created basic models by extruding or revolving the sketches. All those models were created on a single sketching plane, either XY, YZ, or XZ plane. But most mechanical designs consist of multiple sketched features, referenced geometries, and placed features. These features are integrated together to complete a model. Most of these features lie on different planes. When you start a new Autodesk Inventor part file and try to invoke a sketching plane, you are prompted to select the plane on which you want to draw the sketch. On the basis of design requirements, you can select any plane to create the base feature. To create additional sketched features, you need to select an existing plane or a planar surface, or you need to create a plane that will be used as a sketching plane. For example, consider the model shown in Figure 5-1.




Figure 5-1 Model created by combining various features

The base feature for this model is shown in Figure 5-2. The sketch for the base feature is drawn on the XY plane. As mentioned earlier, after creating the base feature, you need to create other sketched features, placed features, and work features, refer to Figure 5-3. The extrude features shown in Figure 5-3 require additional sketching planes on which the sketch for the other features will be created.

It is evident from Figure 5-3 that the additional features created on the base feature do not lie on the same sketching plane. They are created by defining additional sketching planes. Also, appropriate extrusion options are selected at the time of creating these features.




Figure 5-2 Base feature for the model




Figure 5-3 Model after adding other features

Note

When you define a new sketching plane to draw the sketch for the next feature, by default the sketching environment will be invoked and the selected sketching plane will become parallel to the screen. This is because the **Look at sketch plane on sketch creation and edit** check box is selected by default under the **Sketch** tab of the **Application Options** dialog box. This dialog box will be displayed on choosing the **Application Options** button from the **Options** panel of the **Tools** tab in the **Ribbon**.

If the **Look at sketch plane on sketch creation and edit** check box is cleared then on invoking the sketching environment, the orientation of the model will remain same as it was before invoking the Sketching environment. In this case before proceeding further, you need to orient the sketching plane parallel to

your screen. You can do so by choosing the **Look At** tool from the **Navigate** panel. This tool is used to reorient the view using an existing plane or sketched entity. On invoking this tool, you will be prompted to select the entity to look at. Select the new sketching plane or an entity; the view will be changed to the plane view of the selected plane. You can also use the ViewCube to orient the sketching plane.

WORK FEATURES

Work features are parametric features that are associated with a model. Autodesk Inventor has provided three types of work features to assist you in creating a design. The three types of work features are:

- Work Planes
- Work Axes
- Work Points




Figure 5-4 The Plane drop-down showing various tools for creating work planes

The methods of creating these work features are discussed next.

Creating Work Planes

Ribbon: 3D Model > Work Features > Plane drop-down

Work planes are similar to sketching planes and are used to draw sketches of sketched features or create placed features like holes. The reason for preferring work planes over sketching planes is that the latter has some limitations. For example, it is not possible to define a sketching plane at an offset distance from an existing plane. Also, it is not possible to define a sketching plane that is tangent to a cylindrical feature. In such situations, you can define a work plane and use it as the sketching plane. In Autodesk Inventor, there are many tools that can be used to create work planes. You can choose the desired tool from the **Plane** drop-down in the **Work Features** panel of the **3D Model** tab, see Figure 5-4. The procedures of creating work planes using these tools are discussed next.

Creating a Work Plane through Selected Objects

Ribbon: 3D Model > Work Features > Plane drop-down > Plane

You can create a work plane based on the reference objects selected and the sequence of their selection. To do so, choose the **Plane** tool from the **Work Features** panel (see Figure 5-4) and then select the required entity from the model in the drawing window. Figure 5-5 shows a planar face and a point to be selected for creating a work plane and Figure 5-6 shows the resulting work plane.

Note

The new work plane will be displayed on the screen as a shaded plane. If required, you can turn off the display of this work plane. The procedure to do so will be discussed later in this chapter.




Figure 5-5 *The face and a point to be selected to define a work plane*




Figure 5-6 *Resulting work plane*

Creating a Work Plane Using Two Coplanar Edges, Axes, or Lines

Ribbon: 3D Model > Work Features > Plane drop-down > Two Coplanar Edges

You can create a work plane that passes through any two coplanar edges, axes, or lines. To do so, choose the **Two Coplanar Edges** tool from the **Work Features** panel (see Figure 5-4) and then select the two coplanar edges, axes, or lines from the model. Figure 5-7 shows the edges to be selected for creating a work plane and Figure 5-8 shows the resulting work plane.

Creating a Work Plane Using Three Vertices or Points

Ribbon: 3D Model > Work Features > Plane drop-down > Three Points

You can create a work plane that passes through three points. These points can be the vertices of the model or the point/hole center. To create such a plane, choose the **Three Points** tool from the **Work Features** panel (see Figure 5-4). Next, move the cursor close to a vertex; a yellow circle with a cross is snapped to it, suggesting that the vertex can be selected. Select any three vertices or points; the work plane will be created. Figure 5-9 shows three vertices selected to create a work plane and Figure 5-10 shows the resulting work plane.




Figure 5-7 Edges to be selected




Figure 5-8 Resulting work plane




Figure 5-9 Vertices to be selected




Figure 5-10 Resulting work plane

Tip. You can also select work axes to define the work plane. You will learn more about work axes later in this chapter.

Creating a Work Plane through an Edge/Axis and at an angle to a Plane/Planar Face

Ribbon: 3D Model > Work Features > Plane drop-down > Angle to Plane around Edge

You can create a work plane that passes through an edge or axis and lies at the specified angle to a plane or a planar face. To do so, choose the **Angle to Plane**

around Edge tool from the **Work Features** panel (see Figure 5-4). Select the work plane or the planar face to which the resulting work plane will be at an angle. Next, select the edge through which the work plane will pass; a preview of the plane along with the mini toolbar will be displayed. Enter the required angle value in the edit box of the mini toolbar and then choose **OK**. You can also drag the manipulator arrow to specify the angle value of the plane. Figure 5-11 shows the edge and the planar face selected to create the work plane and Figure 5-12 shows the work plane created at an angle of -30 degrees. With the help of the mini toolbar, you can create a plane parallel or perpendicular to the selected plane/planar face. To create a plane parallel to the selected plane/planar face, enter **0** in the edit box of mini toolbar and then choose **OK**. Figure 5-13 shows a planar face and an edge selected for creating the work plane and Figure 5-14 shows the resulting work plane. To create a plane perpendicular to the selected plane/planar face, enter **90** in the edit box of the mini toolbar and then choose **OK**. FFigure 5-15 shows a planar face and an edge selected for creating a work plane and Figure 5-16 shows the resulting work plane.




Figure 5-11 An edge and a planar face selected to define a work plane at -30 degrees to the selected plane




Figure 5-12 Resulting work plane




Figure 5-13 A planar face and an edge selected to define a work plane parallel to the selected plane




Figure 5-14 Resulting work plane




Figure 5-15 An edge and a planar face to be selected to create a work plane normal to the selected plane




Figure 5-16 Resulting work plane

Creating a Work Plane Passing through a Point and Parallel to a Plane/Planar Face

Ribbon: 3D Model > Work Features > Plane drop-down > Parallel to Plane through Point

You can create a work plane that passes through a specified point and is parallel to a plane or a planar face. To do so, choose the **Parallel to Plane through Point** tool from the **Work Features** panel (see Figure 5-4). Next, select the point and the plane or planar face. You can select the point first and then the plane or the planar face to which the new work plane will be parallel and vice-versa. Figure 5-17 shows a point and a planar face to be selected to define a work plane and Figure 5-18 shows the resulting work plane.




Figure 5-17 A point and a planar face to be selected to define the work plane




Figure 5-18 Resulting work plane

Creating a Work Plane Tangent to a Circular Face and Parallel to a Plane/Planar Face

Ribbon: 3D Model > Work Features > Plane drop-down > Tangent to Surface and Parallel to Plane

You can create a work plane that is tangent to a circular face and parallel to a plane or a planar face. To do so, choose the **Tangent to Surface and Parallel to Plane** tool from the **Work Features** panel (see Figure 5-4). Next, select the cylindrical face and then select the XY, YZ, or XZ plane or the planar face to which the resulting work plane should be parallel. Figure 5-19 shows a circular face to which the new work plane will be tangent and a planar face to which the resulting work plane will be parallel. Figure 5-20 shows the resulting work plane.




Figure 5-19 Circular feature and a planar face to be selected to define a work plane




Figure 5-20 Resulting work plane

Tip. To select the XY, YZ, and XZ planes, click on the (+) sign located on the left of the **Origin** node in the **Browser Bar**. The three default planes along with three axes and center point will be displayed. You can now select the required plane from the **Browser Bar**.

Creating a Work Plane Normal to a Line Passing through a Point

Ribbon: 3D Model > Work Features > Plane drop-down > Normal to Axis through Point

You can create a work plane that is normal to an axis and passes through a point. The axis can be a line, an edge, or a work axis and the point can be any vertex in

the model, a sketched point, hole center, or a work point. To create a work plane normal to an axis through a point, choose the **Normal to Axis through Point** tool from the **Work Features** panel (see Figure 5-4). Next, select the point and the edge in any sequence to create the plane. Figure 5-21 shows an edge and a point selected to create a work plane and Figure 5-22 shows the resulting work plane.

You can also use the **Normal to Axis through Point** tool to create a work plane that is normal to a line and passes through the intersection of the line with an arc or a circle. To do so, first you need to draw a circle or an arc and then a line or a centerline. Note that one endpoint of the line should lie on the circumference of the circle. After drawing the circle/arc and the line or the centerline, exit the sketching environment. Next, choose the **Normal to Axis through Point** tool from the **Work Features** panel (see Figure 5-4); you will be prompted to define the work plane by highlighting and selecting the geometry. Select the line or the centerline and then select the point of intersection of the line and the circle/arc; the work plane will be created at the intersection of the line/centerline and the circle/arc. Also, the new work plane will be normal to the centerline, see Figures 5-23 and 5-24.




Figure 5-21 Selecting an edge and a point to define a work plane




Figure 5-22 Resulting work plane




Figure 5-23 Selecting a centerline and an intersection point to define a work plane




Figure 5-24 Resulting work plane

Note

1. The size of the work plane in Figure 5-24 has been modified to improve its clarity. The work planes are the planes which are constructed with respect to the features. The size displayed on the graphics screen is just for reference. To resize a work plane, move the cursor over one of its corners and then click.
2. If you want to move the work plane, then drag the mouse when the cursor turns into a four-sided arrow.

Creating a Work Plane Tangent to a Circular Face and Passing through an Edge/Axis

Ribbon: 3D Model > Work Features > Plane drop-down > Tangent to Surface through Edge

You can create a work plane that is tangent to a circular face and passes through the selected edge. To do so, choose the **Tangent to Surface through Edge** tool from the **Work Features** panel (see Figure 5-4). Next, select an edge or an axis and then select a circular face; a work plane passing through the selected edge and tangent to the circular face will be created. Figure 5-25 shows a circular face and an edge selected to create a work plane and Figure 5-26 shows the resulting work plane.




Figure 5-25 Selecting a circular face and an edge to define a work plane




Figure 5-26 Resulting work plane

Creating a Work Plane Parallel to a Plane/Planar Face and at an Offset

Ribbon: 3D Model > Work Features > Plane drop-down > Offset from Plane

You can create a work plane that is parallel to a plane or a planar face and is at some offset distance from the selected plane or planar face. To do so, choose the **Offset from Plane** tool from the **Work Features** panel (see Figure 5-4). Next, select the plane or the planar face to which the resulting plane will be parallel; a preview of the work plane along with a mini toolbar will be displayed. Specify the offset distance in the edit box of the mini toolbar or drag the arrow manipulator to specify it. After specifying the offset distance, choose **OK** from the mini toolbar. If you specify a negative offset value, the work plane will be offset in the opposite direction. Figure 5-27 shows a plane selected to define the offset work plane and Figure 5-28 shows the new work plane created at an offset of 30 mm.

Note

To create more than one work features in succession, you can choose to repeat the command even after it has been used once. To invoke the **Repeat command**, first invoke any work feature tool and then right-click in the graphics window. From the shortcut menu, choose the **Repeat command** option. Choosing this option ensures that the work feature tool invoked earlier will repeat until you terminate it.




Figure 5-27 Selecting a planar face to define the offset work plane




Figure 5-28 Resulting work plane

Creating a Work Plane in the Middle of Two Planes or Planar Faces

Ribbon: 3D Model > Work Features > Plane drop-down > Midplane between Two Planes

You can create a work plane in the middle of two parallel planes or planar faces. To do so, choose the **Midplane between Two Planes** tool from the **Work**

Features panel (see Figure 5-4). Next, select two planes/faces; a plane will be created in the middle of the selected planes/faces. Figure 5-29 shows two planar faces to be selected and Figure 5-30 shows the resulting work plane.




Figure 5-29 *Selecting two planar faces to define a work plane*




Figure 5-30 *Resulting work plane*

Creating a Work Plane Tangent to a Surface and Passing through a Point

Ribbon: 3D Model > Work Features > Plane drop-down > Tangent to Surface through Point

You can create a work plane that is tangent to a surface and passes through a specified point. To do so, choose the **Tangent to Surface through Point** tool from the **Work Features** panel (see Figure 5-4). Next, select a surface and then a point or a vertex; a work plane passing through the selected point and tangent to the surface will be created. Figure 5-31 shows a surface and a point to be selected to create a work plane and Figure 5-32 shows the resulting work plane.




Figure 5-31 A surface and a point to be selected to define a work plane




Figure 5-32 Resulting work plane

Creating a Work Plane through the Center or the Midplane of a Torus

Ribbon: 3D Model > Work Features > Plane drop-down > Midplane of Torus

You can create a work plane that passes through the center or the midplane of a torus. To do so, choose the **Midplane of Torus** tool from the **Work Features** panel (see Figure 5-4). Move the cursor to the torus; the preview of the plane will be displayed. Next, select the torus; the work plane will be created on its midplane. Figure 5-33 shows the torus to be selected and Figure 5-34 shows the resulting work plane.



Figure 5-33 Torus to be selected to define the work plane



Figure 5-34 Resulting work plane

Note

The features/models created by using the freeform tools cannot be used as reference for creating work plane.

Creating a Work Plane Normal to a Curve

Ribbon: 3D Model > Work Features > Plane drop-down > Normal to Curve at Point

You can create a work plane that is normal to a curve at the specified point. The curve can be a line, a spline, or an arc. The point can be any control vertex or the endpoint of the curve or spline. To create a work plane normal to a curve, choose the **Normal to Curve at Point** tool from the **Work Features** panel (see Figure 5-4). Next, select the curve and then the point. Figure 5-35 shows a curve and a point to be selected to create a work plane and Figure 5-36 shows the resulting work plane.




Figure 5-35 Spline (curve) and point to be selected to define the work plane




Figure 5-36 Resulting work plane

-

Creating Work Axes

Ribbon: 3D Model > Work Features > Axis drop-down

Work axes are parametric axes that pass through a model or feature. These axes are used as a reference to create work planes, work points, and circular patterns. The work axis is displayed both in the model and in the **Browser Bar**. In Autodesk Inventor, there are eight tools that can be used to create work axes. You can choose the desired tool from the **Axis** drop-down in the **Work Features** panel of the **3D Model** tab, see Figure 5-37. The procedures of creating work axes using these tools are discussed next.

Creating a Work Axis through Selected Objects

Ribbon: 3D Model > Work Features > Axis drop-down > Axis

You can create a work axis through selected objects depending upon the reference objects and the sequence in which they are selected. To do so, choose the **Axis** tool from the **Work Features** panel, see Figure 5-37, and then select the required entities from the model in the drawing window.




Figure 5-37 The Axis drop-down with various tools for creating work axes

Creating a Work Axis passing through a Revolved or Cylindrical Feature

Ribbon: 3D Model > Work Features > Axis drop-down > Through Revolved Face or Feature

You can create a work axis that passes through the center of a revolved or cylindrical feature. To do so, choose the **Through Revolved Face or Feature** tool from the **Work Features** panel (see Figure 5-37); you will be prompted to select a cylindrical or a revolved surface. Select a cylindrical or revolved feature from the drawing window; a work axis passing through the center of the selected feature will be created, see Figure 5-38.




Figure 5-38 Work Axis passing through the center of a circular feature

Creating a Work Axis Normal to a Plane/Planar Face and Passing through a Point

Ribbon: 3D Model > Work Features > Axis drop-down > Normal to Plane through Point

You can create a work axis that is normal to a plane or a planar face and passes through a specified point. To do so, choose the **Normal to Plane through Point** tool from the **Work Features** panel. Next, select a plane or a planar face to which the axis will be normal and then select the point through which the axis will pass, see Figure 5-39.




Figure 5-39 *Creating a work axis through a planar face and a sketched point*

Creating a Work Axis Passing through the Intersection of Two Planes/Planar Faces

Ribbon: 3D Model > Work Features > Axis drop-down > Intersection of Two Planes

You can create a work axis that passes through the intersection of two planes or planar faces. To do so, choose the **Intersection of Two Planes** tool from the **Work Features** panel. Next, select two intersecting planar faces; a work axis will be created at their intersection. If you select two planar faces that do not intersect in the model but intersect when extended, the resulting axis will pass through the extended intersection, see Figure 5-40.

Creating a Work Axis Passing through Two Points

Ribbon: 3D Model > Work Features > Axis drop-down > Through Two Points

You can create a work axis that passes through two specified points. The points can be the vertices, midpoints of edges, sketched points, hole centers, or work points. To create a work axis passing through two points, choose the **Through Two Points** tool from the **Work Features** panel (see Figure 5-37). Next, select two points from the drawing window; an axis passing through the selected points will be created. Figure 5-41 shows a work axis created using the midpoints of two edges of a model.




Figure 5-40 Work axis passing through the intersection of two planes




Figure 5-41 Creating a work axis through the midpoints of two edges

Creating a Work Axis along a Linear Edge/Sketch Line/3D Sketch Line

Ribbon: 3D Model > Work Features > Axis drop-down > On Line or Edge

You can create a work axis along a linear edge/sketch line/3D sketch line. To do so, choose the **On Line or Edge** tool from the **Work Features** panel (see Figure 5-37) and select a linear edge, sketch line, or 3D sketch line of a model.

Creating a Work Axis Passing through a Point and along a Line/Edge

Ribbon: 3D Model > Work Features > Axis drop-down > Parallel to Line through Point

You can create a work axis that is parallel to a linear edge or a line and passes through a point. To do so, choose the **Parallel to Line through Point** tool from the **Work Features** panel. Next, select a point and then a line or a linear edge; an axis parallel to the selected line or edge and passing through the selected

point will be created. Figure 5-42 shows a work axis that is parallel to a line and passes through a specified point.

Creating a Work Axis Coincident with the Axis of the Circular, Elliptical, or Fillet Edge of a Feature

Ribbon: 3D Model > Work Features > Axis drop-down > Through Center of Circular or Elliptical Edge

You can create a work axis that is coincident with the axis of an elliptical, a circular, or a fillet edge of a feature. To do so, choose the **Through Center of Circular or Elliptical Edge** tool from the **Work Features** panel (see Figure 5-37). Next, select the circular, elliptical, or fillet edge from the feature; a work axis coincident with the axis of the selected edge will be created. Figure 5-43 shows a work axis created. This work axis coincides with the axis of the circular edge of the feature.




Figure 5-42 Creating a work axis parallel to a line passing through a point





Figure 5-43 Creating a work axis coincident with the axis of the circular edge

Creating Work Points

Ribbon: 3D Model > Work Features > Point drop-down

Work points are parametric points that can be created on an existing model. These points help create work planes, work axes, or other features. In Autodesk Inventor, there are nine tools that can be used to create work points. You can choose the desired tool from the **Work Point** drop-down in the **Work Features** panel of the **3D Model** tab, see Figure 5-44. The procedure of creating work points using these tools is discussed next.



*Figure 5-44 The **Point** drop-down with various tools for creating work points*

Creating a Work Point through Selected Objects

Ribbon: 3D Model > Work Features > Point drop-down > Point

You can create various types of work points depending upon the reference objects selected and the sequence in which they are selected. To do so, choose the **Point** tool from the **Work Features** panel (see Figure 5-44) and then select the required entities from the model in the drawing window.

Creating a Work Point at a Vertex or at the Midpoint of an Edge

Ribbon: 3D Model > Work Features > Point drop-down > On Vertex, Sketch

point, or Midpoint

You can create a work point at any vertex of a model or at the midpoint of any of its edges. To do so, choose the **On Vertex**, **Sketch point**, or **Midpoint** tool from the **Work Features** panel (see Figure 5-44). Next, select a vertex of the model; a new work point will be created on the selected vertex. To create a work point at the midpoint of an edge, move the cursor close to the midpoint of the edge; the midpoint will be highlighted. Next, select the midpoint; the work point will be created. You can also right-click and choose **Select Other** from the shortcut menu to cycle through various entities and select the midpoint when it is displayed. Figure 5-45 shows work points created at the vertices and at the midpoints of the edges of the model.

Creating a Work Point at the Intersection of Two Edges/Axes

Ribbon: 3D Model > Work Features > Point drop-down > Intersection of Two Lines

You can create a work point at the intersection or extended intersection of two edges or axes. To do so, choose the **Intersection of Two Lines** tool from the **Work Features** panel (see Figure 5-44). Select the two intersecting edges or axes; the work point will be created at the intersection point. Figure 5-46 shows two edges to be selected to create the work point and the resulting work point.




Figure 5-45 Work points at the vertices and at the midpoints of edges




Figure 5-46 Work point at the intersection of two edges

Creating a Work Point at the Intersection of a Plane/Planar Face and an Edge/Axis

Ribbon: 3D Model > Work Features > Point drop-down > Intersection of Plane/Surface and Line

You can create a work point at the intersection of a plane or a planar face and an edge or axis. To do so, choose the **Intersection of Plane/Surface and Line** tool from the **Work Features** panel (see Figure 5-44). Next, select the plane or the planar face and then the line or linear edge normal to it in any sequence; a work point will be created at their intersection, see Figure 5-47.

Creating a Work Point at the Intersection of Three Planes/Planar Faces

Ribbon: 3D Model > Work Features > Point drop-down > Intersection of Three Planes

You can create a work point at the intersection of three planes or planar faces. To do so, choose the **Intersection of Three Planes** tool from the **Work Features** panel (see Figure 5-44). Select the three planes or planar faces; a work point will be created at their intersection, see Figure 5-48.




Figure 5-47 Work point created at the intersection of an edge and a work plane




Figure 5-48 Work point created at the intersection of three planes

Note

*If you delete work features such as work planes, work axes, or work points, the features created with reference to these work features will also be deleted. To hide the work features, right-click on the desired feature in the **Browser Bar** and clear the **Visibility** option from the shortcut menu; the display of the selected work feature will be turned off. Select this option again to turn the visibility on.*

Creating a Work Point at the Center Point of a Loop of Edges

Ribbon: 3D Model > Work Features > Point drop-down > Center Point of Loop of Edges

You can create a work point at the center point of a closed loop of edges of a feature. To do so, choose the **Center Point of Loop of Edges** tool from the **Work Features** panel (see Figure 5-44). Next, select an edge that forms a closed loop with other edges; a work point will be created at the center point of the loop of the selected edges, see Figure 5-49. Note that before selecting the edge for

creating a work point, you need to right-click and then choose the **Loop Select** option from the shortcut menu.

Creating a Work Point through the Center or Midplane of a Torus

Ribbon: 3D Model > Work Features > Point drop-down > Center Point of Torus

You can create a work point that passes through the center or midplane of a torus. To do so, choose the **Center Point of Torus** tool from the **Work Features** panel (see Figure 5-44). Move the cursor to the torus; the preview of the work point will be displayed. Next, select the torus; the work point will be created at its center or midplane. Figure 5-50 shows a torus with a work point created at its center.




Figure 5-49 Creating work point at the center point of an edge of a closed loop




Figure 5-50 Work point created at the center of a torus

Note

The features/models created by using the freeform tools cannot be used as reference for creating work point.

Creating a Work Point through the Center or Midplane of a Sphere

Ribbon: 3D Model > Work Features > Point drop-down > Center Point of Sphere

You can create a work point that passes through the center or midplane of a sphere. To do so, choose the **Center Point of Sphere** tool from the **Work Features** panel, refer to Figure 5-44. Next, select the sphere; the work point will be created at its center or midplane. To view the center point in the drawing area if not visible, change the view style to **Wireframe**. Figure 5-51 shows a sphere with a work point created at its center.




Figure 5-51 Work point created at the center of a sphere

Note

The features/models created by using the freeform tools cannot be used as reference for creating work point.

Creating a Grounded Point

Ribbon: 3D Model > Work Features > Point drop-down > Grounded Point

You can create a grounded point by using the **Grounded Point** tool. To create a grounded point, choose the **Grounded Point** tool from the **Work Features** panel (see Figure 5-44); you will be prompted to select a vertex or work point to specify the initial position of the point. Select a vertex or a work point; a triad will be placed at the selected vertex or point, as shown in Figure 5-52. Also, a mini-tool bar will be displayed, as shown in Figure 5-53. You can move the triad in the required direction by clicking on the corresponding axis and then dragging it. You can also rotate the triad about its axis. After specifying the position and orientation of the grounded point, choose the **OK** button; the grounded point will be placed at the specified position.




Figure 5-52 Triad placed at the selected vertex



Figure 5-53 The mini-tool bar

Tip. 1. To understand the geometrical dependency of an axis, work plane, or work point, select the **Work Point**, **Work Axis**, or **Work Plane** in the **Browser Bar** or in the graphic window and right-click; a shortcut menu will be displayed. Choose the **Show Inputs** option from the shortcut menu; the geometry that was

used to create the work plane, work axis, or work point will be highlighted in the graphic window.

*2. The work features can also be created in-line. The in-line features are created while you are in the process of creating some other feature. For example, while creating a work axis, if you right-click, a shortcut menu will be displayed. This shortcut menu provides the options, **Create plane** and **Create point** for creating work features. The work plane and the work point created using this shortcut menu will be the in-line work features. Note that all in-line features are dependent on the parent features.*

OTHER EXTRUSION OPTIONS

The **Extrude** dialog box cannot be invoked until the base feature is created in the sketch environment. Once you create the base feature in the Sketching environment and choose the **Finish Sketch** option from the Marking menu, you will automatically be taken to the **3D Model** tab of the **Ribbon**. If you choose the **Extrude** tool in this tab, the **Extrude** dialog box will be displayed.

Some of the options of the **Extrude** dialog box will not be available until you have created the base feature. Once the base feature is created, all the options in the tabs of this dialog box will be available. These options are discussed next.

Shape Tab

The options in the **Shape** tab of the **Extrude** dialog box, shown in Figure 5-54, are discussed next.

Join



This is the first button on the left of the **Extents** area and is used to create an extruded feature by adding new material to an existing feature. This button will be activated only after you have created the base feature. You can also choose this button from the mini toolbar, refer to Figure 5-55. Figure 5-56 shows the join feature created using a sketch.




Figure 5-54 The **Extrude** dialog box with the **Shape** tab chosen




Figure 5-55 The **Cut** option in the mini toolbar

Cut

This is the second button on the left of the **Extents** area. This button will be available only after you have created the base feature. The **Cut** option is used to create an extruded feature by removing material from the existing feature. You can also choose this option from the mini toolbar that is displayed on invoking the **Extrude** tool, refer to Figure 5-55. The material to be removed will be defined by the sketch that you have drawn. Figure 5-57 shows the cut feature created using the same sketch.

Intersect

This button is available below the **Cut** button and is used to create an extruded feature by using the material that is common to both the existing feature and the sketch, see Figure 5-58. You can also choose this option from the mini toolbar, refer to Figure 5-55.




Figure 5-56 Extruding the sketch using the **Join** option




Figure 5-57 Extruding the sketch using the **Cut** option




Figure 5-58 Extruding the sketch using the **Intersect** option

New solid


On choosing this button, the resultant feature will be a new body. The new body thus created will be independent of the existing body and will be listed in the **Solid Bodies** node of the **Browser Bar**. You can also choose this option from the mini toolbar, refer to Figure 5-55.

Extents Area

The **Extents** area is used to specify the termination options for the feature to be extruded. These options are also available in the mini toolbar, refer to Figure 5-59. Some of the options in this area were discussed in Chapter 4 and the rest of them are discussed next.

To Next

This option is used to terminate the extruded feature on the first plane or the first face that it comes across in the specified direction. On selecting this option, the **Terminator** button will appear in the **Extents** area. This button is used to define the end of the extruded feature. You can also invoke this option by choosing the **To next face/body** option from the mini toolbar, refer to Figure 5-59.



*Figure 5-59 Choosing the **To next face/body** option from the mini toolbar*

Note

*The **Symmetric** option will not be available with the **To Next** termination option because you cannot select planes or planar faces in both directions of the current sketch plane in a single attempt*

.

All

The **All** option is used to create a feature by extruding the sketch through all the features that it comes across. You can also invoke this option by choosing the **Through All** option from the mini toolbar, refer to Figure 5-59. You can extrude the sketch in either direction of the current sketching plane by using the direction buttons in the **Extents** area. You can also extrude the sketch in both the directions of the current sketch plane by choosing the **Symmetric** button.

Figure 5-60 shows a sketch drawn on an offset plane. Figures 5-61 and 5-62 show the profile extruded using the **To Next** and **All** options, respectively.




Figure 5-60 Sketch drawn on an offset plane




Figure 5-61 Sketch extruded using the To Next option

Match shape

This check box is available only when you are extruding an open sketch. If this check box is selected, the open sketch is extruded in such a way that it extends up to the last face of the model that it comes across. The sketch fills the material in all the features up to the last face of the model. For example, refer to the open sketch shown in Figure 5-63. This sketch is drawn at a plane offset from the bottom face of the model.




Figure 5-62 Sketch extruded using the All option




Figure 5-63 Sketch drawn on the offset plane

When you invoke the **Extrude** tool and select this open profile, you are allowed to extrude it on either of the two sides, as shown in Figures 5-64 and 5-65.




Figure 5-64 First side for extruding the profile




Figure 5-65 Second side for extruding the profile

While selecting the side to be extruded, you need to be careful because the feature creation will be successful only when you extrude it in the direction in which the sketch will find faces to terminate the feature. In this case, the feature will not be created if you select the side shown in Figure 5-65 because there is no face available in the front direction to terminate the feature.

After you select the side of the sketch to be extruded, you will be prompted to define the extent of the feature. You can select the type of termination from the **Distance** drop-down list and define the direction using the two buttons. If the **Match shape** check box is selected, the sketch will fill the model with the material and the feature will be created similar to that shown in Figure 5-66. But if the **Match shape** check box is cleared, the feature will be created similar to that shown in Figure 5-67. As evident from this figure, the shape of the sketch is not retained while creating the feature.




Figure 5-66 Result with the **Match shape** check box selected




Figure 5-67 Result with the **Match shape** check box cleared

More Tab

While creating a feature after creating the base feature, you can also use the remaining options of the **More** tab shown in Figure 5-68. These options are discussed next.




Figure 5-68 The Extrude dialog box with the More tab chosen

Alternate Solution Area

The options in the **Alternate Solution** area are used in combination with the **To** and the **To Next** termination options. These options are used for creating those extruded features that terminate on the curved faces, resulting in more than one possible solution. These options are discussed next.

Flip

The **Flip** buttons are used to reverse the direction of the extruded features.

Minimum Solution

By default, in case of more than one solution, the extruded feature terminates at the face that is at maximum distance from the sketch. Figure 5-69 shows the sketch and the face at which the extruded feature will terminate. Notice that the resultant feature shown in Figure 5-70 is stretched up to the face that is at the maximum distance from the sketch. However, if you select the **Minimum Solution** check box, the feature will terminate at the face that is at minimum distance from the sketch, see Figures 5-71 and 5-72.

Note

In Figures 5-70 and 5-72, the visibility of work planes has been turned off.




Figure 5-69 *The sketch and the termination face*




Figure 5-70 *Resulting extruded feature*




Figure 5-71 *The sketch and the termination face*




Figure 5-72 Resulting extruded feature

Infer iMates


iMates are references that allow you to define the mating references such as planar surfaces, axes, edges, and so on before assembling a component. The **Infer iMates** check box in the **More** tab is selected to apply an iMate to the edge of a solid. Note that only the edge of cylindrical feature can be selected for this purpose.

OTHER REVOLUTION OPTIONS

Most of the options in the **Revolve** dialog box were discussed in Chapter 4. The remaining options are discussed next.

Operations Area

Once you have created the base feature, the **Join**, **Cut** and **Intersect** buttons will be activated in the **Operations** area of the **Revolve** dialog box, see Figure 5-73. These options are also available in the mini toolbar. The functions of these options are discussed next.



*Figure 5-73 The **Revolve** dialog box*

Join

This is the first button on the left of the **Extents** area and is used to create a revolved feature by adding new material to an existing feature. This button will be available only after you have created the base feature. You can also invoke this option from the mini toolbar, refer to Figure 5-74.




Figure 5-74 Choosing an option from the mini toolbar

Cut

This is the second button on the left of the **Extents** area. This button will be available only after you have created the base feature. You can also choose this option from the mini toolbar, see Figure 5-74. The **Cut** option is used to create a revolved feature by removing the material from the feature. The material to be removed is defined by the sketch you have drawn and the axis of revolution.

Intersect

This button is available below the **Cut** button and is used to create a revolved feature by retaining the material common to the existing feature and the sketch. You can also choose the **Intersect** option from the mini toolbar, refer to Figure 5-74.

New Solid

On choosing the **New solid** button, the resultant revolved feature will be a new body. The new body will be independent of the existing body and will be listed in the **Solid Bodies** node of the **Browser Bar**. You can also choose this option from the mini toolbar, refer to Figure 5-74.

Match shape

This check box is available only when you revolve an open sketch. Similar to the **Extrude** tool, in this case also, the **Match shape** check box is used to revolve the open sketch in such a way that it extends to the axis of revolution. On doing so, the sketch floods all features up to the last face of the model with material. Figure 5-75 shows the open sketch and Figures 5-76 and 5-77 show the revolved feature created by selecting and clearing this check box respectively.






Figure 5-75 Sketch for the revolve feature



*Figure 5-76 Revolve feature with the **Match shape** check box selected*



*Figure 5-77 Revolve feature with the **Match shape** check box cleared*

Infer iMates

This check box is selected to apply an iMate to a full circular edge of the solid feature.

THE CONCEPT OF SKETCH SHARING

Generally, while creating a design, you will frequently come across situations where you have to use a consumed sketch for creating another feature in the same plane and along the same direction of extrusion. As mentioned at the start of this chapter, a consumed sketch is the one that has already been converted into a feature. For example, consider a case where you have to create a join feature by extruding the sketch to different distances in both the directions about the current sketch plane.

In some solid modeling programs, to use the consumed sketch, you will have to copy it to new location. After placing the sketch, you will have to add dimensions to locate it on its exact location. However, in Autodesk Inventor, you can directly use the same sketch by sharing it. This concept of using the consumed sketch again is termed as sharing the sketches. This concept has drawn a very distinct line between Autodesk Inventor and other solid modeling programs as it reduces the design time appreciably.

Sharing Sketches

As mentioned in Introduction, all the operations that were used to create a model are displayed in the form of a tree view in the **Browser Bar**. All these operations will be arranged in the sequence in which they were performed. Also, once the sketch is converted into a feature, the sketch will be hidden and the feature will be displayed in the **Browser Bar**. For example, when you create the sketch for the base feature, the **Browser Bar** will display **Sketch1** below **Origin**. When this sketch is extruded and converted into the base feature, the **Browser Bar** will display **Extrusion1** below **Origin** and it will have a plus sign (+) located on the left. If you click on this plus sign, it will expand and will display **Sketch1**. Similarly, if you click on the plus sign of any sketched feature, it will expand and display the sketch.




Figure 5-78 Shortcut menu displaying the **Share Sketch** option

To share the sketch, right-click on the sketch that you want to share; a shortcut menu will be displayed, see Figure 5-78. In this shortcut menu, choose **Share Sketch**; another sketch with the same name will be displayed in the **Browser Bar**. Also, the shared sketch will be displayed in the graphics window. You can now convert this sketch into a feature.

Note

By default, the visibility of the shared sketch is set to ON. As a result, after converting into a feature, the sketch will also be displayed along with the new feature. You need to manually turn off the visibility of this sketch. This is done by

using the shortcut menu that is displayed upon right-clicking on the sketch. In this shortcut menu, the **Visibility** option will have a check mark on its left. Choose this option again to turn off the visibility. You will notice that the sketch is no more visible on the screen. Similarly, right-click on any work feature and turn off its visibility using the **Visibility** option in the shortcut menu.

TUTORIALS

Tutorial 1

In this tutorial, you will create the model of the Standard Bracket shown in Figure 5-79. The views and dimensions of the model are shown in the same figure.

(Expected time: 30 min)






Figure 5-79 Views and dimensions for Tutorial 1





The following steps are required to complete this tutorial:

- On the XY plane, create the base feature with two holes, refer to Figures 5-80 and 5-81.
- Define a new sketch plane on the back face of the base feature and create the join feature with a hole, refer to Figure 5-83.
- Define a new sketch plane on the front face of the model and create the rectangular join feature, refer to Figure 5-86.

Creating and Dimensioning the Sketch of the Base Feature

- Start Autodesk Inventor and then start a new metric standard part file.
- Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketch plane.
- Choose the **Home** button from the **ViewCube**; the current orientation of the

sketch plane is changed.

4. Select the **XY** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **XY** Plane becomes parallel to the screen. Alternatively, you can select the **XY** plane from the graphics window.
5. Draw the sketch of the base feature using various sketching tools, see Figure 5-80.
6. Add the required constraints and dimensions to the sketch to make it fully constrained.
7. Choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab; you will exit the Sketching environment and the current view is changed to the home view or isometric view.

Note

*If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

Extruding the Base Sketch

After creating the sketch, you need to extrude it to create the base feature.

1. Using the **Extrude** tool, extrude the sketch to a distance of 32 mm.

As the sketch has multiple loops, you need to specify the profile to be extruded. Make sure you define the profile to be extruded by specifying a point outside the circles but inside the outer loop. The model after creating the base feature is shown in Figure 5-81.




Figure 5-80 Sketch of the base feature




Figure 5-81 Base feature of the model

Creating a Feature on the Back Face of the Base Feature

To create a feature on the back face of the base feature, you first need to define the sketching plane on the back face.

1. Choose the **Start 2D Sketch** tool from **3D Model > Sketch > Start 2D**

Sketch drop-down; you are prompted to select the sketching plane.

2. As the **Start 2D Sketch** tool is active, move the cursor close to the back face of the model and hover it for sometime. On doing so, the **Select Other** flyout is displayed on the model. Choose the desired face option from this flyout to select the back face of the model, refer to Figure 5-82. Next, click on the model to confirm your selection.

Sometimes, while reorienting the model, the X axis of the model (displayed red in the 3D Indicator) points vertically downward.

3. In case the X axis points vertically downward, choose the arrow on the top right corner of the ViewCube to reorient the model. However, this step can be skipped if this axis points horizontally toward the left.




Figure 5-82 Selecting the back face of the model using the options in the **Select Other** flyout

Once you orient the model, you will notice that the red arrow in the 3D Indicator has become horizontal and is pointing toward the left. This shows that the X axis of the model is now in the horizontal direction. Note that you may not need to reorient the model toward the X axis.

4. Draw the sketch of the feature using various sketching tools, see Figure 5-83.
5. Add the required constraints to the sketch and then dimension it to make it

fully constrained. The sketch after dimensioning should look similar to the one shown in Figure 5-83.

6. Choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab and exit the Sketching environment.

Extruding the Sketch

1. Change the current view to isometric and then extrude the sketch upto a distance of 32 mm by using the **Extrude** tool.

You can change the direction of the depth in the mini toolbar. To do so, select the **Direction 2** option from the **Direction** drop-down list. The model after creating the feature on the back face will look similar to the one shown in Figure 5-84.




Figure 5-83 Sketch of the feature on the back face




Figure 5-84 Model after creating the feature

Creating the Sketch on the Front Face of the Base Feature

1. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab; you are prompted to select the plane on which the sketch will be created.
2. Select the front face of the model; the Sketching environment is activated and

a rectangle defining the contour of the front face is created.

3. Delete the reference geometries, if any, and then draw a rectangle as the sketch for the next feature, as shown in Figure 5-85. Add the **Collinear Constraint** between the lower edge of the rectangle and the upper edge of the front face of the base feature.




Figure 5-85 Dimensioned sketch for the feature on the front face

4. Add the required dimensions to the sketch, refer to Figure 5-85.
5. Exit the Sketching environment and then change the current view to isometric view.

*Tip. Whenever you apply the **Collinear** Constraint between a sketched line and an edge, another line will be created. It is recommended that you do not delete this line. If you delete this line, the **Collinear** Constraint will also be deleted.*

Extruding the Sketch

1. Choose the **Extrude** tool from the Marking menu; the **Extrude** dialog box is displayed. Select the rectangle as the profile to be extruded.
2. Choose the **To selected face/point** option from the mini toolbar, as shown in Figure 5-86. Alternatively, select **To** from the **Distance** drop-down list in the **Extents** area of the **Extrude** dialog box; the **Select surface to end the feature creation** button is displayed below the drop-down list. This button is chosen by default.
3. Select the front face of the second feature as the face where the current feature will terminate; the **Check to terminate feature on the extended face** check box is displayed on the right of the **Select surface to end the feature creation** button in the **Extrude** dialog box. This check box is selected by default.

As the current feature will terminate on the selected face, you need to clear this check box.

4. Clear the **Check to terminate feature on the extended face** check box and then choose the **OK** button. Alternatively, choose **OK** from the mini toolbar. The final model for Tutorial 1 is shown in Figure 5-87.




Figure 5-86 Choosing the *To selected face/point* option




Figure 5-87 Final model for Tutorial 1

Saving the Model

1. Save the model with the name *Tutorial1* at the location given below and then close the file.


C:\Inventor_2016\c05

Tutorial 2

In this tutorial, you will create the model shown in Figure 5-88. Its views and dimensions are shown in the same figure. **(Expected time: 30 min)**

The following steps are required to complete this tutorial:

- a. Create the base feature on the YZ plane by defining a new sketch plane on it, refer to Figures 5-89 and 5-90.
- b. Define a new sketch plane on the front face of the model and create a cut feature, refer to Figures 5-91 and 5-92.
- c. Create the next cut feature by defining a new sketch plane on the back face of the model, refer to Figures 5-93 and 5-94.
- d. Define a new sketch plane on the new face that is exposed by creating the last cut feature and create a circular cut feature, refer to Figure 5-95.
- e. Create the final cut feature on the top face of the horizontal base of the first feature, refer to Figure 5-95.








Figure 5-88 Views and dimensions for Tutorial 2

Changing the Sketch Plane

The base feature for this model is an L-shaped feature. You have to create the sketch in the YZ plane.

1. Start a new metric standard part file.
2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
4. Select the **YZ** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **YZ** Plane becomes parallel to the screen. Alternatively, you can select **YZ** plane from the graphics window.

Note

*If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

If

Creating and Dimensioning the Sketch of the Base Feature

1. Draw the L-shaped sketch for the base feature and add the required constraints to it.
2. Add dimensions to the sketch. The sketch after adding the dimensions is shown in Figure 5-89.
3. Choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab to exit the Sketching environment. Change the current view to the isometric view.

Extruding the Sketch

1. Choose the **Extrude** tool from the **Create** panel of the **3D Model** tab to invoke the **Extrude** dialog box. Next, extrude the sketch to a distance of 72 mm using the **Symmetric** button. You can also choose the **Symmetric** option from the mini toolbar. Choose **OK** to exit the **Extrude** dialog box. The base feature is created, as shown in Figure 5-90.




Figure 5-89 Sketch for the base feature




Figure 5-90 Base feature

Creating the Sketch for the Cut Feature on the Front Face

The next feature is a rectangular cut feature and is to be created on the front face of the base feature.

1. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab; you are prompted to select the sketching plane. Select the front face of the base feature as the Sketching plane; the Sketching environment is invoked.

2. If required, reorient the model by using the ViewCube. Draw the sketch for the cut feature and delete the reference geometries, if any, created while defining the sketch plane.
3. Next, add required constraints and dimensions to it. The dimensioned sketch is shown in Figure 5-91.
4. Choose the **Finish Sketch** button from the Marking menu and then change the current view to the isometric view.

Creating the Cut Feature on the Front Face of the Model

1. Extrude the profile defined by the rectangle to a distance of 50 mm using the **Cut** operation. The isometric view of the model with the cut feature is shown in Figure 5-92.




Figure 5-91 Sketch for the cut feature




Figure 5-92 Model after creating the cut feature on the front face

Creating the Sketch for the Cut Feature on the Left Face

The next feature is a cut feature and is to be created on the left face of the model.

1. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab; you are prompted to select a plane for creating the sketch. Select the left face of the model; the Sketching environment is activated.
2. Delete all the reference geometries and then draw the sketch for the cut feature. Add required constraints and dimensions to the sketch, as shown in Figure 5-93.
3. Exit the Sketching environment and then change the current view to the isometric view.

Extruding the Sketch to Create a Cut Feature

1. Extrude the profile to a distance of 12 mm using the **Cut** operation. The model after creating a cut feature on the left face is shown in Figure 5-94.

Creating a Hole

1. Define a new sketch plane on the face that is exposed after creating the cut feature in the previous step.
2. Draw a circle on this face and then add dimensions to it; refer to Figure 5-88 for dimensions.
3. Invoke the **Extrude** tool and extrude the circle using the **Cut** operation. Note that to create this cut feature, you need to select the **All** option from the **Distance** drop-down list in the **Extents** area.




Figure 5-93 Sketch for the cut feature




Figure 5-94 Model after creating the cut feature on the left face

Creating the Last Cut Feature

1. Define a sketch plane on the horizontal face of the base feature and then reorient the model using the ViewCube.
2. Delete all the reference geometries, if any, and then create the sketch for the cut feature, refer to Figure 5-88 for dimensions. Add required constraints and dimensions to the sketch.
3. Extrude the sketch using the **Cut** operation. Use the **All** option from the **Distance** drop-down list in the **Extents** area. The final model for Tutorial 2 is shown in Figure 5-95.




Figure 5-95 Solid model for Tutorial 2

Saving the Model

1. Save the sketch with the name *Tutorial2* at the location given next.

C:\Inventor_2016\c05

2. Choose **Close** from the **Application** menu to close this file.


Tutorial 3

In this tutorial, you will create the model shown in Figure 5-96. Its dimensions and views are shown in the same figure. **(Expected time: 45 min)**

The model for this tutorial is a combination of a base feature, two join features, and six cut features (Holes).

The following steps are required to complete this tutorial:

- a. Create the base feature on the YZ plane, refer to Figures 5-97 and 5-98.
- b. Create a join feature on the top face of the base feature, refer to Figure 5-100.
- c. Create a work plane at an offset of 10 mm from the bottom face of the join feature and then create a cylindrical join feature on it, refer to Figure 5-102.
- d. Create a hole in the cylindrical feature by defining a new sketch plane on its top face, refer to Figure 5-103.
- e. Create two holes by defining a sketch plane on the left face of the model, refer to Figure 5-103.
- f. Define a new sketch plane on the top face of the groove which is on the top face of the model. Then, create three holes on it, refer to Figure 5-103.








Figure 5-96 Views and dimensions for Tutorial 3

Creating the Base Feature

1. Start Autodesk Inventor and then start a new metric standard part file.
2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketch plane.
3. Choose the **Home** button from the **ViewCube**; the current orientation of the sketch plane is changed.
4. Now, select the **YZ** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **YZ** Plane becomes parallel to the screen. Alternatively, you can select **YZ** plane from the graphics window.
5. Create the sketch for the base feature and then add the required constraints and dimensions to it. The dimensioned sketch for the base feature is shown in Figure 5-97.
6. Exit the Sketching environment and then change the current view to the isometric view by choosing the **Home** button of the ViewCube. Next, choose the **Extrude** tool from the **Create** panel of the **3D Model** tab; the **Extrude** dialog box is displayed. As the sketch has a single loop, it is automatically selected.
7. Extrude the sketch to a distance of 60 mm using the **Symmetric** option. The base feature is created, as shown in Figure 5-98.




Figure 5-97 Dimensioned sketch for the base feature




Figure 5-98 Base feature created

Note

If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

If

Creating the First Join Feature on the Top Face

1. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab and select the top face of the base feature as the new Sketching plane.
2. Reorient the view using the ViewCube, see Figure 5-99. Draw the sketch for the first join feature and add the required constraints and dimensions to it, as shown in Figure 5-99.
3. Exit the Sketching environment and change the current view to the isometric view.
4. Extrude the sketch in the downward direction to a distance of 10 mm, see Figure 5-100.

Note

*If the join feature is extruded in an opposite direction, reverse its direction by choosing the **Direction 2** button from the mini toolbar or from the **Extents** area of the **Extrude** dialog box.*

Creating the Cylindrical Feature

As shown in Figure 5-96, the cylindrical feature starts at a distance of 10 mm below the bottom face of the feature you just created. Therefore, you first need to define a work plane offset at a distance of 10 mm from the bottom face of the first join feature. But first, you need to change the orientation of the model such that the bottom face of the first join feature is visible.




Figure 5-99 Sketch for the first join feature




Figure 5-100 Model after extruding

1. Reorient the model using the **Free Orbit** tool such that the bottom face of the first join feature is visible.
2. Choose the **Offset from Plane** tool from **3D Model > Work Features > Plane** drop-down. Click on the bottom face of the first join feature; the mini toolbar is displayed.
3. Enter **10** in the edit box available in the mini toolbar and make sure the arrow

manipulator in the mini toolbar points downward. Next, press ENTER; a work plane is created at an offset of 10 mm from the bottom face of the first join feature.

4. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab and select the work plane as the plane for drawing the sketch of the cylindrical feature. Next, reorient the model, if required, using the ViewCube, see Figure 5-101. Increase the drawing display area using the scroll wheel of the mouse, if required.
5. Draw a circle and then add the required constraints and dimensions to it, see Figure 5-101.
6. Exit the Sketching environment.
7. Extrude the sketch to a distance of 60 mm in the upward direction and then increase the drawing display area. The extruded feature is shown in Figure 5-102.

After extruding the sketch, you will notice that the work plane is still visible in the drawing window. As the work plane is not required, you need to turn off its visibility. This is done using the **Browser Bar**.

8. Right-click on **Work Plane1** in the **Browser Bar** to display the shortcut menu.

In the shortcut menu, you will notice that there is a check mark beside the **Visibility** option. This indicates that the work plane is visible in the drawing window.

9. Choose the **Visibility** option from the shortcut menu; the check mark is cleared making the work plane invisible. Figure 5-102 shows the model after turning off the visibility of the work plane and changing the current view to the isometric view.




Figure 5-101 Sketch for the cylindrical feature




Figure 5-102 Model after creating the cylindrical feature

Creating the Remaining Cut Features

1. Create the remaining cut features by creating their respective sketches on the sketching planes. For dimensioning, refer to Figure 5-96. The final model after creating all the cut features is shown in Figure 5-103.




Figure 5-103 Final model for Tutorial 3

Saving the Model

1. Save the model with the name *Tutorial3* at the location given below and then close the file.

C:\Inventor_2016\c05

Self-Evaluation Test

Answer the following questions and then compare them to those given at the end of this chapter:

1. The work axes are the _____ lines passing through the model or the feature.
2. When you select a vertex after invoking the _____ tool, a triad is displayed on the selected vertex.
3. When you select a planar face or a plane for defining a work plane and then drag it, the _____ toolbar is displayed.
4. All the operations that have been used to create a model are displayed in the form of _____ in the **Browser Bar**.
5. The _____ check box in the **More** tab is selected to apply an iMate to the edge of the solid body.
6. The _____ planes are not visible on the screen, but the _____ planes are visible both on the screen and in the **Browser Bar**.
7. In mechanical designs, all the features are created on the XY plane. (T/F)
8. As you select a sketching plane, the Sketching environment is activated. (T/F)
9. You cannot define a sketch plane on the circular face of a cylindrical feature. (T/F)

10. The visibility of the shared sketches is turned off by default. (T/F)

Review Questions

Answer the following questions:

1. Which of the following features is not a work feature?

- (a) Work line (b) Work axis
- (c) Work plane (d) Work point

2. How many planes are displayed when you click on the plus sign on the left of the **Origin** folder in the **Browser Bar**?

- (a) 2 (b) 3
- (c) 4 (d) 1

3. Which of the following options in the shortcut menu is used to turn off the display of the work features?

- (a) **Display** (b) **Show**
- (c) **Visible** (d) **Visibility**

4. Which of the following operations is used to create a feature by retaining the material common to the existing feature and the sketch?

- (a) **Cut** (b) **Join**
- (c) **Intersect** (d) None of these

5. In Autodesk Inventor, which of the following options displays the geometrical dependency of a selected work point, work axis, or work plane?

- (a) **Show Inputs** (b) **Visibility**
- (c) **Adaptive** (d) **Show dimensions**

6. Whenever you open a new file, by default you start drawing in the XY plane. (T/F)

7. You can create a work plane tangent to a cylinder by selecting its cylindrical face and then the XY, YZ, or XZ plane to which the resulting work plane should be parallel. (T/F)
8. You can create a work axis on a cylindrical feature by directly selecting it. (T/F)
9. The **All** option in the **Distance** drop-down list of the **Extents** area in the **Extrude** dialog box cannot be used with the **Join** operation. (T/F)
10. A consumed sketch can be used again for creating another feature. (T/F)

Exercise 1

Create the model shown in Figure 5-104. Its dimensions are also given in the same figure.

(Expected time: 45 min)





Figure 5-104 Model and its dimensions for Exercise 1



Exercise 2

Create the model shown in Figure 5-105. Its dimensions are given in Figure 5-106. **(Expected time: 30 min)**

Figure 5-105 Model for Exercise 2






Figure 5-106 The dimensions of the model for Exercise 2

Exercise 3

Create the model shown in Figure 5-107. Its dimensions are also given in the same figure.

(Expected time: 30 min)





Figure 5-107 Model and its dimensions for Exercise 3



Exercise 4

Create the model shown in Figure 5-108. Its dimensions are given in Figure 5-109. (Expected time: 45 min)

Figure 5-108 Model for Exercise 4





Figure 5-109 Dimensions of the model for Exercise 4

Answers to Self-Evaluation Test

1. parametric, 2. **Grounded Point**, 3. **Offset**, 4. tree view, 5. **Infer iMates**, 6. sketch, work, 7. F, 8. T, 9. T, 10. F

Chapter 6

Advanced Modeling Tools-I

Learning Objectives

After completing this chapter, you will be able to:

- ***Create various types of holes.***
- ***Create fillets on a model.***
- ***Chamfer the edges of a model.***
- ***Mirror features.***
- ***Create rectangular patterns of features.***
- ***Create circular patterns of features.***
- ***Create rib features.***
- ***Thicken faces or surfaces, offset faces or surfaces.***
- ***Emboss or engrave sketched entities on a feature.***
- ***Use the Decal tool to apply an image on a feature.***
- ***Assign different colors/styles to a model.***

ADVANCED MODELING TOOLS

Autodesk Inventor has a number of advanced modeling tools to assist you in creating a design. These advanced modeling tools appreciably reduce the time taken in creating the features in the models, thus reducing the designing time. For example, to create a hole in a cylindrical feature, one option is that while sketching the cylindrical feature, you sketch the hole also. But, to edit the dimensions of the hole, you will have to edit the complete sketch. Also, if the hole is drawn along with the sketch of the cylindrical feature, it will be extruded to the same distance. However, if you want the hole to terminate before the end of the cylindrical feature, you will have to draw another sketch. But, if you

create the hole using the **Hole** tool, you can specify its depth and other parameters. The advanced modeling tools used in Autodesk Inventor are listed below.

1. Hole
2. Fillet
3. Chamfer

4. Mirror

5. Rectangular Pattern
6. Circular Pattern

7. Rib

8. Thicken/Offset
9. Emboss
10. Decal
11. Sweep

12. Loft

13. Coil
14. Thread
15. Shell
16. Face Draft
17. Split
18. Boundary Patch
19. Stitch Surface
20. Replace Face
21. Delete Face
22. Move Face
23. Sculpt
24. Extend

Note

All features created using the advanced modeling tools are parametric in nature and can be modified at any time.

Creating Holes

Ribbon: 3D Model > Modify > Hole **Holes are circular cut features that are created on an existing feature. Holes are generally provided to accommodate fasteners in an assembly. You can create drilled, counterbore, spotface, and countersink holes using the Hole tool. On invoking this tool, the Hole dialog box will be displayed, as shown in Figure 6-1. Alternatively, select the sketch created on an existing feature; a mini toolbar will be displayed in the Graphics window. Choose the Create Hole tool from the mini toolbar to invoke the Hole tool. You can also invoke the Hole tool from the Marking Menu which is displayed when you right-click anywhere in the graphics window. You can also specify whether a hole is a simple, tapped, taper tapped, or clearance hole using the options in the Hole dialog box. The options in this dialog box are discussed next.**




Figure 6-1 The Hole dialog box

Placement Area

The options in this area are used to specify the placement of a hole. These options are discussed next.

Linear

If there is no unconsumed sketch in the model, this option is selected by default in the drop-down list in the **Placement** area. This option is used to place a hole by defining its location from two linear edges in the model. When you select this option, the **Face** button will be enabled and chosen. As a result, you will be prompted to select a planar face or a work plane as the placement

plane. As soon as you select the placement plane, the preview of the hole along with the hole manipulator (sphere) will be displayed on the selected face. Also, the **Reference 1** button will be chosen and you will be prompted to select a linear edge to reference the dimension. You can change the location of the hole dynamically by dragging the hole manipulator. If you select a linear edge, the **Dimension** edit box and the lock icon will be displayed. Using this edit box, you can specify the distance from the center of the hole to the selected edge. After specifying the distance value, lock this value by clicking the lock icon; the **Reference 2** button will be chosen and you will be prompted to select a linear edge to reference the dimension. When you select the second linear edge, the **Dimension** edit box and the lock icon will be displayed. Using this edit box, you can specify the distance from the center of the hole to the selected edge. Figure 6-2 shows the preview of a hole placed using two linear edges.

Note

The lock icon, when enabled, helps you to keep the entered values intact. You cannot move the hole along its references.

From Sketch

This option is used to specify the center point of a hole by selecting a sketch point or endpoint of an unconsumed sketch. This option is selected by default if there is an unconsumed sketch in the model. When you select this option, the **Centers** button is automatically chosen in the **Placement** area. If the sketch has a predefined center, it will be automatically selected as the center of the hole. But to use the endpoints of the entities you need to select them manually. Figure 6-3 shows the preview of a hole with a center point.

*Tip. In case the **From Sketch** option is selected, you need to press the **SHIFT** key and select the hole centers once again to exclude them from being selected. You will notice that the preview of the hole is not displayed. It suggests that the hole center is removed from the selection set and no hole will be created on it.*




Figure 6-2 Hole placed using two linear edges




Figure 6-3 Hole placed on a center point

Concentric

This option is used to place the hole concentric to a circular feature. When you select this option, the **Plane** button will be chosen in the **Placement** area and you will be prompted to select a planar face or work plane as the reference plane. This is the plane where the hole will be placed. On selecting the placement plane, the **Concentric Reference** button will be chosen and you will be prompted to select a circular edge or a cylindrical face to reference the hole center. Select the circular edge. Figure 6-4 shows the preview of a hole placed concentric to the cylindrical face of the fillet feature.




Figure 6-4 Preview of a hole placed concentric to the fillet

On Point

This option is used to place the hole on a work point. The work point can be created by using the **Grounded Point** option from the **Work Features** panel in the **3D Model** tab. When you invoke this option, you will be prompted to select a work point for the hole placement. After selecting the work point, the **Direction** button will be chosen in the **Placement** area and you will be prompted to select a planar face, work plane, edge, or axis. Select the required direction; the preview of the hole to be created will be displayed, as shown in Figure 6-5. Figure 6-6 shows the preview of the hole at the same work point but the direction is defined by the side planar face.

Drilled

This is the first radio button in the area to the right of the **Placement** area. This radio button is selected by default and is used to create a drilled hole. A drilled hole is the one that has a uniform diameter throughout its length. The hole diameter and depth have to be specified in the preview window on the right side of this dialog box. Figure 6-7 shows the section view of a drilled hole.




Figure 6-5 Direction defined using the top plane




Figure 6-6 Direction defined using the side plane

Counterbore

This radio button is available below the **Drilled** radio button and is used to create a counterbore hole. A counterbore hole is a stepped hole and has two diameters: a bigger diameter and a smaller diameter. The bigger diameter is called the counterbore diameter and the smaller diameter is called the drill diameter. In this type of hole, you also have to specify two depths. The first depth is the counterbore depth. The counterbore depth is the depth up to which the bigger diameter will be defined. The second depth is the depth of the hole, including the counterbore depth. All these values are defined in the preview window on the right side of the **Hole** dialog box. Figure 6-8 shows the section view of a counterbore hole.




Figure 6-7 Section view of a drilled hole




Figure 6-8 Section view of a counterbore hole

Spotface

This radio button is available below the **Counterbore** radio button and is selected to create spotfaced holes. Spotfacing provides a seat or a flat surface at the entrance and the surrounding area of a hole. It also allows a cap screw or bolt to seat squarely with the material, even if the clearance hole is not normal to the surrounding material. Spotfacing is generally carried out on castings that have irregular surfaces. It has two diameters: a bigger diameter and a smaller diameter. The bigger diameter is called the spotface diameter and the smaller diameter is called the drill diameter. In this type of hole, you also have to specify two depths. The first depth is the spotface depth, which is the depth up to which the bigger diameter will be defined. The second depth is the depth of the hole, excluding the spotface depth. The cross-section of a spotfaced hole is similar to that of a counterbore hole. Figure 6-9 displays the section view of a spotface hole.




Figure 6-9 Section view of a spotface hole

Countersink

This radio button is provided below the **Spotface** radio button and is used to create a countersink hole. A countersink hole also has two diameters, but the transition between the bigger diameter and the smaller diameter is in the form of a cone. You need to define the countersink diameter, drill diameter, depth of the hole, and the countersink angle. Figure 6-10 shows the section view of a countersink hole.

Drill Point Area

The options in the **Drill Point** area are used to specify whether the end of the hole will be a flat or a tapered face. These options are discussed next.

Flat

If this radio button is selected, the end of the hole will be a flat plane.

Angle

If this radio button is selected, the end of the hole will be tapered and will converge to a point. The angle of the taper can be defined in the **Drill Point Angle** edit box provided on the right of this radio button. Figure 6-11 shows a countersink hole with a tapered end.




Figure 6-10 Section view of a countersink hole




Figure 6-11 Countersink hole with a tapered end

Termination Area

The drop-down list under this area is used to define the termination of the holes. The options available in this drop-down list are discussed next.

Distance

This option is used to create a hole by defining its depth up to a certain distance. The depth of the hole is defined in the preview window. You can

reverse the direction of hole creation by choosing the **Flip** button available on right of this drop-down list.

Through All

The **Through All** option is used to create a hole through all features that it comes across. The direction of the hole creation can be reversed by using the **Flip** button. When you select this option, the depth of the hole is no more displayed in the preview window because the hole will be created automatically by cutting through all features in the specified direction. Also, the **Drill Point** area will be deactivated.

To

The **To** option is used to terminate the hole feature at a specified plane, planar face, or an extended face. When you select this option, the **Flip** button is replaced by the **Select surface to end the feature creation** button. Using this button, you can select the face to terminate the hole feature.

Note

*The end condition of a hole depends on the option selected from the **Termination** drop-down list. If you select the **Through All** option from this drop-down list, the end of the hole will be flat (refer to Figures 6-7 and 6-8). If you select the **Distance** option from it, the end of the hole will have a drill point (refer to Figures 6-9 and 6-11).*

Simple Hole

This radio button is selected by default and is used to create simple holes.

Clearance Hole

The **Clearance Hole** radio button is selected to create clearance holes to accommodate standard fasteners. When you select this radio button, the **Hole** dialog box expands and displays the **Fastener** area, as shown in Figure 6-12. This area provides the options to create a tapped hole. These options are discussed next.




Figure 6-12 The expanded portion of the **Hole** dialog box displaying the **Fastener** area

Standard

The **Standard** drop-down list is used to select the standard of the fastener to be accommodated in the hole.

Fastener Type

The **Fastener Type** drop-down list is used to select the type of fastener to be accommodated in the hole.

Size

This drop-down list is used to select the size of the fastener.

Fit

This drop-down list is used to specify the type of hole fit. The default option selected is **Normal**.

Tapped Hole

The **Tapped Hole** radio button is selected to create threaded holes. When you select this radio button, the **Hole** dialog box expands and displays the **Threads** area, as shown in Figure 6-13. This area provides the options to create a tapped hole. These options are discussed next.




Figure 6-13 The expanded portion of the **Hole** dialog box

Thread Type

The **Thread Type** drop-down list is used to select the type of threads. You can select the default type of threads in this drop-down list.

Size

This drop-down list is used to select the nominal size of the threads. The designation and the class value will be different for different nominal sizes.

Designation

This drop-down list is used to specify the designation of the thread profile.

Class

The **Class** drop-down list is used to select the class of threads. Also, higher the numeric value in this drop-down list, more accurate is the fitting.

Diameter

The options in the **Diameter** drop-down list are used to specify whether the diameter defined for creating threads is the major, minor, pitch, or drill diameter. Note that you can change this option only by using the **Modeling** tab of the **Document Settings** dialog box. This dialog box can be invoked by choosing the **Document Settings** tool from the **Options** panel in the **Tools** tab.

Full Depth

If the **Full Depth** check box is selected, the threads will run through the length

of the hole. If this check box is not selected, you will have to specify the depth up to which the threads will be created. This depth is defined in the preview window on the right side of the **Hole** dialog box.

Direction Area

The options in the **Direction** area are used to specify the direction of the threads. These options are discussed next.

Right Hand

The **Right Hand** radio button is used to create right-handed threads. A right-handed thread enters a nut when you turn it in the clockwise direction.

Left Hand

The **Left Hand** radio button is used to create left-handed threads. A left-handed thread enters a nut when you turn it in the counterclockwise direction.

Figure 6-14 shows a hole without threads and Figure 6-15 shows a hole with threads.



Figure 6-14 A counterbore hole without threads




Figure 6-15 A counterbore hole with threads

Taper Tapped Hole

The **Taper Tapped Hole** radio button is selected to create taper threaded holes. When you select this radio button, the **Hole** dialog box expands and displays the **Threads** area, as shown in Figure 6-16. This area provides the options to create different types of taper threaded holes. These options are discussed next.




Figure 6-16 The expanded portion of the Hole dialog box

Thread Type

The **Thread Type** drop-down list is used to select the type of threads. You can select the default type of threads in this drop-down list.

Size

This drop-down list is used to select the nominal size of the threads. The designation and the class value will be different for different nominal sizes.

Designation

This drop-down list is used to specify the designation of the thread profile.

Class

The **Class** drop-down list is used to select the class of threads. Also, higher the numeric value in this drop-down list, more accurate is the fitting.

Diameter

The **Diameter** drop-down list is used to specify whether the diameter defined for creating the threads is the major, minor, pitch, or the drill diameter of the original hole. The default option selected is **Minor**.

Direction Area

The options in the **Direction** area are used to specify the direction of the threads. These options are discussed next.

Right Hand

The **Right Hand** radio button is used to create right-handed threads. A right-handed thread enters a nut when you turn it in the clockwise direction.

Left Hand

The **Left Hand** radio button is used to create left-handed threads. A left-handed thread enters a nut when you turn it in the counterclockwise direction.

Figure 6-17 shows the section view of a straight hole with threads and Figure 6-18 shows the section view of a tapered hole with threads.




Figure 6-17 Section view of a straight hole with threads




Figure 6-18 Section view of tapered hole with threads

Infer iMates

This check box is available below the **Termination** area and is selected to create an iMate on the hole feature.

Note

*The **Taper Tapped Hole** radio button in the dialog box is not active in case of creating counterbore hole.*

Creating Fillets

Ribbon: 3D Model > Modify > Fillet

In Autodesk Inventor, you can add fillets or rounds using the **Fillet** tool. Fillets are generally used to apply curves on the interior edges of a model and result in concave surfaces by adding material. Rounds are generally used to apply curves on the exterior edges and result in convex surface by removing the material.

Autodesk Inventor allows you to create different types of fillets. You will learn about these fillets in the following topics.

Creating Edge Fillets

To create edge fillets, choose the **Fillet** tool; the **Fillet** dialog box will be displayed, as shown in Figure 6-19. Alternatively, invoke the **Fillet** dialog box by choosing the **Create Fillet** tool from the mini toolbar that is displayed when you select the edge to be filleted. By default, the **Edge Fillet** button is chosen in the **Fillet** dialog box. As a result, the options to create the edge fillet are displayed. Also, the preview of the fillet along with the modified mini toolbar will be displayed on the selected edge, as shown in Figure 6-20. You can enter the radius of the fillet in the edit box of the mini toolbar and choose **OK** to create the fillet. The options available under various tabs of the **Fillet** dialog box are discussed next.




Figure 6-19 The Fillet dialog box




Figure 6-20 Mini toolbar displayed on invoking the Fillet tool

Constant Tab

The options under this tab are used to fillet the selected edges such that they have a constant radius throughout their length. However, different edges can have a different fillet radius.

Edges: This column displays the number of edges you selected. However, note that all the edges selected will have the same fillet radius. If you want to specify a different fillet radius to some edges, click on the text **Click to add**; another row will be added. Now, if you select an edge, it will be displayed in the second row. The second row can be assigned a different fillet radius.

Radius: In this column, you can specify the fillet radius for the selected edges. Different rows can have different radii. You can also specify the fillet radius for the selected edges by entering the radius value in the edit box of the mini toolbar or by dragging the arrow manipulator.

Continuity: This drop-down list is available on the right of the **Radius** column. In this drop-down list, you can select the option to apply tangent continuity or smooth (G2) continuity.

Select Mode Area: The options under this area are used to set the priorities of selection for filleting.

Edge: If the **Edge** radio button is selected, you can select the individual edges of a model for filleting. As you move the cursor close to any of the edges, the edge is highlighted.

Loop: The **Loop** radio button is used to select all the edges of a face of the model. To use this option, select the **Loop** radio button and move the cursor close to an edge of the face; all its edges will be highlighted. Click at this stage to select all the edges of the face. Remember that edges selected using this option will have the same fillet radius.

Feature: If the **Feature** radio button is selected, all edges in the selected feature will be selected for filleting. In this case, all the selected edges will also be applied with the same fillet radius.

Solids: The **Solids** button is used to select a body in a multi-body environment

so that the resultant fillet feature becomes a portion of the body. When you choose this button, you can create rounds or fillets on all edges of the selected body. It will only be active in a multi-body environment.

All Fillets: The **All Fillets** check box is selected to create concave-shaped fillets at all possible edges. Note that the fillet radius is same at all places. Figure 6-21 shows a model with fillets.

All Rounds: The **All Rounds** check box is selected to create convex-shaped fillets at all possible edges. All exterior corners will also be curved if you select this check box. The radius for all rounds will be the same. Figure 6-22 shows a model with rounds.




Figure 6-21 Model with fillets




Figure 6-22 Model with rounds

Enable/Disable feature preview: This check box is used to enable or disable the preview of a fillet feature. If this check box is selected, the preview of the fillet will be displayed in the drawing window.


Note

In Autodesk Inventor, if any of the edges in a fillet selection set is not fit to create a fillet of the specified radius, a message box will be displayed showing the number of edges that can not be filleted at the specified radius.

Variable Tab

The options in the **Variable** tab, as shown in Figure 6-23, are used to fillet the selected edges such that they can be applied different radii along their length. If you select a linear or a curved edge, there will be two points on the edge, one at the start point and the other at the end point. However, if you select a circular edge, no point will be defined. You can add points by specifying their desired location on the edge.

Edges: This column displays the number of edges selected to be filleted. You can select more edges by clicking on **Click to add** option. Figure 6-23 shows the **Fillet** dialog box with the **Variable** tab active.



*Figure 6-23 The options in the **Variable** tab*

Continuity Drop-down List: This drop-down list is used to specify the type of fillet to be created. The options in the drop-down list are discussed next.

Tangent Fillet

When the **Tangent Fillet** option is selected in the drop-down list, the resulting

fillet feature maintains tangent continuity (G1) with the adjacent faces.


Smooth (G2) Fillet

When the **Smooth (G2) Fillet** option is selected in the drop-down, the resulting fillet feature maintains smooth continuity (G2) with the adjacent faces. When this option is selected, the curvature is applied gradually, which makes the resulting fillets more smooth.


Figure 6-24 shows the fillet created with the **Tangent Fillet** option and Figure 6-25 shows the fillet created with the **Smooth (G2) Fillet** option.

Point: This column displays the points selected on the edge. By default, there will be only two points, **Start** and **End**, in this column. These two points refer to the start and end points of a linear or curved edge. To add a point, move the cursor on the edge; the preview of the point is displayed. Click to place the point. As soon as you add a point by specifying its location on the edge, it will be added in this column. Similarly, you can add as many points as required on the edge. As mentioned earlier, if you select a circular edge for adding a variable fillet, no point will be added by default. You need to add all the points manually by clicking on the edge.

Radius: The **Radius** column displays the radius at a point selected on an edge. When you click on a value field in this column, it changes to an edit box. Also, the point selected on the edge is displayed under the **Point** column. You can change the radius value of a point by selecting its corresponding value field in the **Radius** edit box and entering a new value in it. You can access all options explained previously using a more compact and user-friendly mini toolbar.



*Figure 6-24 Fillet created using the **Tangent Fillet** option*



*Figure 6-25 Fillet created using the **Smooth (G2) Fillet** option*

Position: This edit box is used to define the position of the point specified on an edge. Remember that the position is defined in terms of the percentage of the selected edge. This edit box will not be available until you select a point other than the default points on an edge. The length of the selected edge is taken as 1 (100 percent) and the position of the new point will be defined anywhere between 0 and 1. For example, a value of 0.5 will suggest that the point is placed at the midpoint of the edge. Figures 6-26 and 6-27 show the variable fillets on the edges of a model.




Figure 6-26 Defining the fillet radius




Figure 6-27 Model after creating the variable fillet

Smooth radius transition: This check box is selected to allow a smooth transition between all the points defined in an edge. If this check box is selected, there will be a smooth blending between all points, as shown in Figure 6-28. If it is cleared, the blending will be linear, as shown in Figure 6-29.




Figure 6-28 *Edges with Smooth transition*




Figure 6-29 *Edges with Linear transition*

Setbacks Tab

The options in the **Setbacks** tab are used to specify the setbacks of the transition between the three edges that comprise a vertex. The setback smoothly blends the transition surfaces between the selected edges and the vertex that you define to fillet. To add a setback fillet, first you need to select the three edges that intersect at a corner by using the **Constant** tab and then choose the **Setbacks** tab, refer to Figure 6-30. The options in this tab are discussed next.



*Figure 6-30 The options in the **Setbacks** tab*

Vertex: After you have selected three edges and set the radius of the fillet using the **Constant** tab, invoke the **Setbacks** tab; you will be prompted to select the common vertex to add the setback. Select the vertex common to the three selected edges. The selected vertex will be displayed in this column. You can also add more vertices by clicking on **Click to add**.

Minimal: This check box is selected to define the minimum allowable setback for a given vertex. You can solve difficult vertex fillets with smoothest transition by using this option.

Edge: This column displays the edges common to the vertex selected on a model. The edge that will have the arrow in front will be highlighted in the drawing window.

Setback: This column displays the setback value for the transition along the edge selected. You can modify this value by clicking on it. Figures 6-31 and 6-32 show the fillets created using different setback values.




Figure 6-31 Fillet with setback value = 2




Figure 6-32 Fillet with setback value = 10

Note

You cannot set the radius of a fillet by using the **Setbacks** tab. It will be set in the **Constant** tab where you have selected the edges.

>> (More)

This button is available at the lower right corner of the **Fillet** dialog box. When you choose this button, the **Fillet** dialog box will expand and display some more options, refer to Figure 6-33. All these options are discussed next.



Figure 6-33 More options of the **Fillet** dialog box

Roll along sharp edges: This check box is selected to modify the radius of the fillet in order to retain the shape and the sharpness of the edges of the adjacent faces. If this check box is cleared, the adjacent faces will extend in case the fillet radius is more than what can be adjusted in the current face. Figure 6-34 shows the fillet created with the **Roll along sharp edges** check box cleared and Figure 6-35 shows the fillet created with this check box selected.

Rolling ball where possible: This check box is selected to create a rolling ball fillet, wherever it is possible. If this check box is cleared, the transition at the sharp corners will be continuously tangent. Figure 6-36 shows the rolling ball fillet created by selecting this check box and Figure 6-37 shows the tangent fillet created by clearing the check box. Note that you need to select all the edges in a single fillet sequence to use this option.




Figure 6-34 Fillet created with the **Roll along sharp edges** check box cleared




Figure 6-35 Fillet created with the **Roll along sharp edges** check box selected




Figure 6-36 Rolling ball fillet




Figure 6-37 Tangent fillet

Automatic Edge Chain: If this check box is selected, all tangent edges will also be selected on selecting an edge to fillet.

Preserve All Features: This check box is selected to calculate the intersection of all the features that intersect with the fillet. If this check box is cleared, the intersection of only the edges that are a part of the fillet will be calculated.

Creating Face Fillets

You can create the face fillets using the **Face Fillet** tool. When you create the fillet using this tool, the material is added or removed completely or partially based on the geometric conditions, to accommodate the fillet. To create a fillet between two faces, invoke the **Fillet** dialog box. Next, choose the **Face Fillet** button located below the **Edge Fillet** button in the **Fillet** dialog box; the dialog box will be modified, as shown in Figure 6-38 and you will be prompted to select faces to blend. The options used to create a face fillet are discussed next.




Figure 6-38 The *Fillet* dialog box for creating the face fillet

Face Set 1: This button is chosen by default and is used to select the first face to create the face fillet. You can choose the **Flip** button on the right of this button to reverse the direction in which the fillet will be created. The **Flip** button will be activated only if you are creating the face fillet between two surfaces. As soon as you select the first face, it will be highlighted in blue and the **Face Set 2** button will be chosen. If you have to select multiple faces to create the fillet, you need to clear the **Optimize for Single Selection** check box available in this dialog box.

Face Set 2: This button is used to select the second face to create the face fillet. You can choose the **Flip** button on the right of this button to reverse the direction in which the fillet will be created. The face that you select as the second face to blend will be highlighted.

Radius Area: The edit box available in this area is used to specify the face fillet radius. If the default value specified in this edit box is valid to create the fillet, the preview of the fillet will also be displayed as soon as you select the face set 2.

Include Tangent Faces: If this check box is selected, all faces tangent to the selected face sets will also be selected to create the fillet.

Optimize for Single Selection: If this check box is selected, then on selecting the first face the **Face Set 2** button will be automatically chosen. If this check box is cleared, you can select multiple faces.

>> (More): This button is available at the lower right corner of the **Fillet** dialog box. When you choose this button, the **Fillet** dialog box will expand and display some more options, refer to Figure 6-39. The **Help Point** area in the **More** option is discussed next.



Figure 6-39 More options for creating the face fillet

Help Point Area: This area is available when you choose the **More** button from the **Fillet** dialog box. When you select this check box, the **Point** button will be enabled this button allows you to place help point on one of the faces selected to be filleted if there are multiple fillet solutions. Figure 6-40 shows the faces selected to create the face fillet and Figure 6-41 shows the resulting face fillet.




Figure 6-40 Faces selected to create a face fillet




Figure 6-41 Resulting face fillet

Tip. You can also apply different types of fillet by using the mini toolbar displayed in the graphics window, refer to Figure 6-42.



Figure 6-42 The mini toolbar displayed on choosing the **Fillet** tool

Creating Full Round Fillets

A full round fillet is a semicircular fillet created between two side faces that are separated by a centre face. In this case, the system determines the required radius value, based on the side faces and center face. To create this type of fillet, choose the **Full Round** button available below the **Face Fillet** button of the **Fillet** dialog box; the options for creating the full round fillet will be displayed in the dialog box, as shown in Figure 6-43. Also, you will be prompted to select the faces to blend. The options used for creating a full round fillet are discussed next.




Figure 6-43 The options in the **Fillet** dialog box to create the full round fillet

Side Face Set 1

This button is chosen by default and is used to select the first side face. As soon as you select the first side face, the **Center Face Set** button is chosen. The side face 1 is highlighted.

Center Face Set

This button is chosen to specify the center face for the full round fillet. Note that this face will be removed from the fillet. As soon as you select the center side face, the **Side Face Set 2** button is chosen. The center face is highlighted.

Side Face Set 2

This button is chosen to specify the second side face. As soon as you select the second side face, the preview of the fillet will be displayed. The side face 2 is highlighted.

Figure 6-44 shows the faces to be selected to create the full round fillet and Figure 6-45 shows the resulting fillet.

Note

The remaining options to create the full round fillet are the same as those discussed while creating the face fillet.

T




Figure 6-44 Faces to be selected to create the fillet




Figure 6-45 Resulting face fillet

Creating Chamfers

Ribbon: 3D Model > Modify > Chamfer Chamfering is a process of beveling the sharp edges of a model to reduce stress concentration. In Autodesk Inventor, chamfers are created using the Chamfer tool. To create a chamfer, choose the Chamfer tool from the Modify panel of the 3D Model tab; the Chamfer dialog box will be displayed, as shown in Figure 6-46. Alternatively, choose the Create Chamfer tool from the mini toolbar that is displayed on selecting the edge to be chamfered. In the Chamfer dialog box, the Edges button will be active by default. As a result, you will be prompted to select an edge. Select the

required edge(s); the preview of the chamfer along with the modified mini toolbar will be displayed on the selected edge(s), refer to Figure 6-47. You can enter the chamfer value(s) either in the edit box(es) of the mini toolbar or in the Distance edit box(es) of the Chamfer dialog box. Next, specify the chamfer option and then choose OK to create the chamfer with the specified options.




Figure 6-46 The Chamfer dialog box




Figure 6-47 Mini toolbar displayed on the selected edge by invoking the Chamfer tool

The options in the **Chamfer** dialog box are discussed next.

Distance

This is the first button in the dialog box and is provided on the upper left corner of the **Chamfer** dialog box. This button is chosen to create a chamfer such that the selected edge is equidistant from both the faces. The chamfer thus created will be at 45-degree angle. Since both the distance values are the same, therefore, there will be only one edit box in the **Distance** area. You can specify the chamfer distance in it. You can also invoke the **Distance** option from the mini toolbar and specify the chamfer distance by dragging the arrow head manipulator.

Distance and Angle

This is the second method of creating chamfers. This option is used to create a chamfer by defining the chamfer distance and angle. On choosing this button, you will be prompted to select the face to be chamfered. This is the face from which the angle will be calculated. After selecting the face, you will be prompted to select an edge. Select the edge to be chamfered. The distance value and the angle value can be specified in their respective edit boxes in the dialog box. You can also invoke the **Distance and Angle** option from the mini toolbar and then specify the chamfer distance and the angle by dragging the corresponding manipulators in it.

Two Distances

This button is chosen to create a chamfer by using two different distances. You can also invoke this option from the mini toolbar. The distance values can be specified in the **Distance1** and **Distance2** edit boxes. These edit boxes are displayed when you choose this button. You can also specify the chamfer distances by dragging the corresponding manipulators in the mini toolbar. The distance values can be interchanged by choosing the **Flip** button available below the **Edge** button.

Figure 6-48 shows the **Chamfer** dialog box with the **Distance and Angle** option chosen and Figure 6-49 shows the **Chamfer** dialog box with the **Two Distances** option chosen.




Figure 6-48 The **Chamfer** dialog box with the **Distance and Angle** option chosen




Figure 6-49 The **Chamfer** dialog box with the **Two Distances** option chosen

Figure 6-50 shows the model before chamfering and Figure 6-51 shows the model after chamfering.




Figure 6-50 Edges selected for chamfering





Figure 6-51 Model after chamfering

>> (More)



*Figure 6-52 More options in the **Chamfer** dialog box*

This button is available at the lower right corner of the dialog box. When you choose this button, the **Chamfer** dialog box will expand and display some more options, refer to Figure 6-52. These options are discussed next.

Edge Chain Area

The buttons in this area are used to set the priorities for selecting the edges to be chamfered. If you choose the **All tangentially connected edges** button, all the edges that are tangent to the selected edge will also be selected for chamfering. If you choose the **Single edge** button, the tangent edges will be ignored.

Setback Area

The buttons in this area are used to specify whether or not a setback will be applied to the model. If you choose the **Setback** button, the setback will be applied and the vertex will be flattened. However, if you choose the **No setback** button, the setback will not be applied and the vertex will be pointed. Figure 6-53 shows the chamfer created with a setback and Figure 6-54 shows the chamfer without a setback.




Figure 6-53 Chamfer with a setback




Figure 6-54 Chamfer without a setback

Note

1. The **Preserve All Features** check box is the same as that discussed in the **Fillet** dialog box.
2. The **Setback** area will be activated only when you select the **Distance** button in the **Chamfer** dialog box.

Mirroring Features and Models

Ribbon: 3D Model > Pattern > Mirror The **Mirror** tool is used to create the mirrored copies of selected features or to mirror the entire model by using a mirror plane. The plane that can be used to mirror the features can be a planar face or a work plane. On using this tool, an exact replica of the selected entities will be created on the other side of the mirror plane. On choosing

the **Mirror** tool, the **Mirror** dialog box will be displayed, as shown in Figure 6-55, and you will be prompted to select the feature to be mirrored. The options in the **Mirror** dialog box are discussed next.

Mirroring Features

In Autodesk Inventor Professional, you can create symmetric models using the Mirror tool, you can mirror filleted features in symmetrical models. To mirror a fillet feature, choose the Mirror individual features button from the Mirror dialog box; the Features button will be activated and you will be prompted to select the feature that you want to mirror. Select the filleted feature, as shown in Figure 6-58. Next, select the Mirror Plane button in the Mirror dialog box and then specify the midplane across which you want to create the mirror feature. Choose OK to apply the mirror and exit the Mirror dialog box. Figure 6-59 shows the mirrored feature with the midplane. You can turn off the visibility of the midplane from the Browser Bar. To do so, select the work plane and then right-click; a shortcut menu will be displayed. Choose the Visibility option from the shortcut menu; the plane will become invisible. You can turn on the visibility of the plane by choosing the Visibility option again.



*Figure 6-55 The **Mirror** dialog box*




Figure 6-56 The features to be mirrored and the mirror plane




Figure 6-57 Model after mirroring the features and hiding the work plane

Mirroring Fillets

In Autodesk Inventor Professional, you can create symmetric models using the **Mirror** tool, you can mirror filleted features in symmetrical models. To mirror a fillet feature, choose the **Mirror individual features** button from the **Mirror** dialog box; the **Features** button will be activated and you be will prompted to select the feature that you want to mirror. Select the filleted feature, as shown in Figure 6-58. Next, select the **Mirror Plane** button in the **Mirror** dialog box and then specify the midplane across which you want to create the mirror feature. Choose **OK** to apply the mirror and exit the **Mirror** dialog box. Figure 6-59 shows the mirrored feature with the midplane. You can turn off the visibility of the midplane from the **Browser Bar**. To do so, select the work plane and then right-click; a shortcut menu will be displayed. Choose the **Visibility** option from the shortcut menu; the plane will become invisible. You can turn on the visibility of the plane by choosing the **Visibility**

option again.




Figure 6-58 Fillet to be mirrored




Figure 6-59 Mirrored fillet feature

Mirroring Models

To mirror the entire model, choose the **Mirror solids** button from the **Mirror** dialog box; the entire model will be selected and highlighted. Also, the **Mirror Plane** button will be chosen and you will be prompted to select a plane to mirror about. You can choose the **Include Work/Surface Features** button to select the work features that you want to mirror. Selecting the **Remove Original** check box allows you to remove the original model after it has been mirrored. You can select one body from a set of multiple bodies to pattern by choosing the **Solid** button from the **Mirror** dialog box. Choose the **Join** button to merge the selected solid body to the pattern. Figure 6-60 shows the model selected to be mirrored, the highlighted mirror plane, and the preview of the

mirrored model. Figure 6-61 shows the mirrored model.




Figure 6-60 Selecting a model to be mirrored and the mirror plane




Figure 6-61 The model after mirroring the entire model

>> (More)

This button is available at the lower right corner of the **Mirror** dialog box. If you choose this button, the **Mirror** dialog box will expand and display some other options, refer to Figure 6-62. These options are discussed next.




Figure 6-62 Other options in the **Mirror** dialog box

Optimized

This radio button is selected to mirror the model as the direct copy of the

original model without any overlapping.

Identical

This radio button is selected to create a mirrored feature that is exactly similar to the original feature, even if it intersects other features. This radio button is active by default.

Adjust

This radio button is available only when you mirror features and is selected if the feature to be mirrored terminates on a face of the model. In this case, the mirror feature will modify its termination such that it adjusts in the model.

Creating Rectangular Patterns

Ribbon: 3D Model > Pattern > Rectangular

You can use the **Rectangular** tool to create a rectangular pattern of the selected features or surfaces, or the entire model. When you invoke this tool, the **Rectangular Pattern** dialog box will be displayed, as shown in Figure 6-63. The options in this dialog box are discussed next.




Figure 6-63 The Rectangular Pattern dialog box

Pattern individual features

This button is chosen to create a pattern of the selected features. You can select the features using the **Features** button that is available on the right of this

button.

Pattern a solid

This button is chosen to select the entire model to create a pattern. You can choose the **Include Work/ Surface Features** button on the right of this button to select the work features that you want to include in the pattern of the model.

Direction 1/Direction 2 Area

Most of the options in the **Direction 1** and **Direction 2** areas are similar to those discussed in the **Rectangular Pattern** dialog box in the Sketching environment. However, there are some additional options and they are discussed next.

Midplane

This button is selected to place the items symmetrically on both sides of the original feature. If there are even number of items in the pattern, the additional item is placed on the side in which the direction arrow points.

Spacing

The **Spacing** option, which is the default selected option, is used to specify the distance between the items in terms of the spacing between individual items.

Distance

The **Distance** option is used to specify the total distance between the first and the last instances of the feature to be patterned in a particular direction.

Curve Length

The **Curve Length** option is used to select the length of the edge selected to define direction 1 or 2 as the distance between all the items in the pattern. When you select this option, the **Spacing** edit box is not enabled.

Figure 6-64 shows the hole to be selected for creating a rectangular pattern and Figure 6-65 shows the model after creating a rectangular pattern.




Figure 6-64 Hole to be patterned




Figure 6-65 Model after creating the pattern

If you choose the >> **(More)** button at the lower right corner of the dialog box, the dialog box will expand and display more options, as shown in Figure 6-66. These options are discussed next.




Figure 6-66 More options in the **Rectangular Pattern** dialog box

Direction 1/Direction 2 Area

The **Start** buttons in these areas are used to specify the start point of the path along the first or second direction. You can use this option in association with the **Curve Length** option. For example, when you define the first and second directions using the edges, two green points are displayed at their corners. These points specify the start points of the path along both the directions. Now, select the **Curve Length** option from the drop-down list available in the **Direction 1** and **Direction 2** areas and then select the start points in direction 1 and direction 2. You will notice that the selected feature starts patterning from the start points specified.

Compute Area

The options under this area are discussed next.

Optimized

The **Optimized** radio button is used to create optimized pattern instances for a lesser calculation time. This option is not useful while working on complex patterns such as when the pattern instances are intersected by some other features.

Identical

The **Identical** radio button is selected, if you want the patterned features to be exactly similar to the original feature, even if they intersect other features.

Adjust

The **Adjust** radio button is selected if any of the patterned features terminate at a face of the model. In this case, the patterned features will be modified such that they adjust in the model. But the pattern calculation time in such cases is longer.

Orientation Area

The options under this area are discussed next.

Identical

The **Identical** radio button is selected to specify the orientation of the patterned items to be the same as that of the original item.

Direction 1

The **Direction 1** radio button is selected to orient the items with reference to the first direction.

Direction 2

The **Direction 2** radio button is selected to orient the items with reference to the second direction.

Note

*All instances of the rectangular pattern are arranged in the **Browser Bar** with the name **Rectangular Pattern** and a number suffixed to it. The number indicates the order in which a particular pattern was created. To suppress a feature pattern, right-click on it in the **Browser Bar** and choose **Suppress Features**. The remaining options in the **Rectangular Pattern** dialog box are similar to those discussed under the **Rectangular Pattern** dialog box in Chapter 4.*

For a better understanding of the **Orientation** options, create a pattern only in the first direction and use a circular edge to define the first direction. Now, one by one, set the orientation to **Identical** and **Direction 1** and notice the difference in the orientation of the items. For example, Figure 6-67 shows the preview of the rectangular pattern oriented using the **Identical** option and Figure 6-68 shows the preview of the rectangular pattern oriented using the **Direction1** option. Note that in both these options, the first direction of the pattern is defined using the circular edge.




Figure 6-67 Preview of the pattern oriented using the **Identical** option




Figure 6-68 Preview of the pattern oriented using the **Direction1** option


Note

In Figures 6-67 and 6-68, the pattern is created only along one direction that is defined by the circular edge of the cylindrical feature.

Creating Circular Patterns

Ribbon: 3D Model > Pattern > Circular

In the Part module, you can use the **Circular** tool to arrange the selected features around an imaginary cylinder, thereby creating a circular pattern. When you invoke this tool, the **Circular Pattern** dialog box will be displayed. If you choose the >> button from this dialog box, this dialog box will expand, as shown in Figure 6-69.



*Figure 6-69 The expanded **Circular Pattern** dialog box*

Most options in the **Placement** and **Positioning Method** areas are similar to those discussed in the sketching environment. The remaining options of this dialog box are discussed next.

Pattern individual features

This button is chosen by default and is used to select the individual features to create the circular pattern.

Pattern a solid

This button is chosen to pattern the entire solid. You can also select work features to be patterned along with solid by choosing the **Include Work/Surface Features** button.

Rotation Axis

The **Rotation Axis** button is chosen to select the axis about which the features will be arranged. The entities that can be selected as the rotation axis include a work axis or a linear edge of any face of the model. You can also select a cylindrical feature, whose central axis will be selected as the axis of rotation.

Midplane

This button is selected to place the items symmetrically on both sides of the

original feature. If there are even number of items in the pattern, the additional item is placed on the side in which the direction arrow points.

Creation Method Area

The options under this area will be displayed when you choose the button with two arrows provided at the lower right corner of this dialog box. These options are discussed next.

Optimized

The **Optimized** radio button is used to create optimized pattern instances for a lesser calculation time. This option is not useful while working on complex patterns such as when the pattern instances are intersected by some other features.

Identical

This radio button is selected if you want the patterned features to be exactly similar to the original feature, even if they intersect other features.

Adjust

This radio button is selected if any patterned feature terminates at a face of the model. In this case, the patterned features will be modified such that they adjust in the model.

Figure 6-70 shows a model before creating the circular pattern and Figure 6-71 shows the model after creating the circular pattern. In this case, the cylindrical feature is selected for defining the axis of rotation. By doing so, you will select its central axis as the axis of rotation.




Figure 6-70 Model before creating the pattern




Figure 6-71 Model after creating the pattern

Positioning Method Area


This area is used to define the spacing between instances of the features. The options in this area work in combination with the **Angle** edit box and they are discussed next.

Incremental


This option is used to determine the orientation of each pattern with respect to the previous pattern. If you select this radio button, the angle that you specify in the **Angle** edit box will be considered as the incremental angle between patterns. Therefore, the circular pattern will be created such that the angle between the two items is equal to the angle specified in the **Angle** edit box. Figure 6-72 shows the pattern created by selecting this radio button and at an incremental angle of 20 degrees.

Fitted

If you select this radio button, the circular pattern will be created such that all items are fitted within the angle specified in the **Angle** edit box. This radio button is selected by default in the **Circular Pattern** dialog box. Figure 6-73 shows the pattern created by selecting this radio button and within an angle of 20 degrees.



*Figure 6-72 Pattern created using the **Incremental** radio button*



*Figure 6-73 Pattern created using the **Fitted** radio button*

Creating Rib Features

Ribbon: 3D Model > Create > Rib

Ribs are defined as thin wall-like structures used to bind joints together so that they do not fail under an increased load. They are used to increase the stiffness of the whole structure. In Autodesk Inventor, ribs are created using an open profile, refer to Figures 6-74 and 6-75.




Figure 6-74 Sketch for the rib feature





Figure 6-75 The rib feature

Remember that before invoking the **Rib** tool, you must have an unconsumed sketch. When you invoke the **Rib** tool, the **Rib** dialog box will be displayed, refer to Figure 6-76. The options in this dialog box are discussed next.



*Figure 6-76 The **Rib** dialog box*

Type Specification Area

This area is located on extreme left of the **Rib** dialog box. It has two options: **Normal to Sketch Plane** and **Parallel to Sketch Plane**. These options are discussed next.

Normal to Sketch Plane

This button is chosen by default. When this option is selected, the rib sketch is extruded normal to the sketch plane and the thickness of the rib feature is added parallel to the sketch plane. Additionally, on choosing this button, three tabs, **Shape**, **Draft**, and **Boss** become available in the **Rib** dialog box.

Parallel to Sketch Plane

This is the second button available in the Type Specification area of the **Rib** dialog box. If this button is chosen, then the rib sketch will be extruded parallel to sketch plane but the thickness of the rib will be added normal to the sketch plane. On choosing this button, only the **Shape** tab is available in the **Rib** dialog box.

Shape Tab

The options under this area are used to select the profile of the rib or the web feature as well as the direction of the feature creation. These options are discussed next.

Profile

The **Profile** button is chosen to select the sketch of the rib or the web feature. If there is a single unconsumed sketch, it will be automatically chosen when you invoke the **Rib** tool.

Solid

This button will be active only when there are multiple solid bodies in the graphics window. Choose this button to select the required body from the graphics window for creating the rib feature.

Direction1/Direction2

The **Direction1/Direction2** button is chosen to define the direction in which the rib or the web feature will be created. The feature can be created in a direction normal to the selected sketch or parallel to it. After selecting the sketch for the rib feature, choose the **Direction 1** or **Direction 2** button and

the direction of rib extrusion will change accordingly. A dynamic preview of the resulting feature can also be seen along with the direction. Note that the rib feature will be successful only if it is created in the direction in which it intersects the existing model faces.

Thickness Area

The options under this area are used to define the thickness of the rib or the web feature. The thickness is specified in the **Thickness** edit box. This area also has three buttons that are used to define the direction, in which the thickness will be applied. You can apply the thickness on either side of the sketch or equally on both sides.

Extents Area

The buttons in this area are used to specify whether the feature will be extended to the next face or to a specified distance. The two buttons in this area are discussed next.

To Next

If this button is chosen, the rib or web feature will be created such that it merges with the next face, refer to Figure 6-77.

Finite

Choose the **Finite** button to create the rib or web feature to a specified distance, refer to Figure 6-78. The distance is specified in the **Extent** edit box that will be displayed in this area when you choose the **Finite** button. The direction is controlled using the **Direction** button in the **Shape** area.




Figure 6-77 Rib created by extending the sketch to the next face




Figure 6-78 Rib created by extending the sketch to a specified distance

Extend Profile

The **Extend Profile** check box will be activated when you select the direction to apply the thickness parallel to the sketch or choose the **Finite** button from the **Extents** area. If the sketch of the rib feature does not intersect with a face of the model, and this check box is selected, the rib feature will be extended such that it intersects the face of the model.

Draft Tab

This tab will be only available when the **Normal to Sketch Plane** button is chosen from the **Rib** dialog box, as shown in Figure 6-79. The options available in the **Draft** tab are used to provide a draft angle to the web feature. When a draft angle is applied to parts, it becomes easier to take them out of the mould without any damage.

Different options available in the **Draft** tab of the **Rib** dialog box are discussed next.

Hold Thickness Area

This area has two radio buttons: **At Top** and **At Root**. These radio buttons are used to control the origin of draft angles. If the **At Top** radio button is selected, the draft will be applied to the top of the rib feature, but if the **At Root** radio button is selected, the draft will be applied to the bottom of the feature. The bottom of the sketch is the point where the rib feature ends. The preview of the draft when the **At Top** radio button is selected is shown in Figure 6-79. The **Draft Angle** edit box is used to specify the draft angle to be

applied to the rib feature.




Figure 6-79 The **Draft** tab of the **Rib** dialog box

Note

While applying draft, all angles are applied with respect to the vertical axis, as the direction of the draft is always vertical.

Boss Tab

The **Boss** tab of the **Rib** dialog box is only available when the **Normal to Sketch Plane** button is chosen in the Type Specification area of the **Rib** dialog box.

In most of the injection moulding components, the mounting bosses are used to hold internal and external parts together. Figure 6-80 shows the **Boss** tab of the **Rib** dialog box.




Figure 6-80 The **Boss** tab of the **Rib** dialog box

The options available in the **Boss** tab of the **Rib** dialog box are discussed next.

Centers

The **Centers** button is chosen by default. This button is used to select the center of the draft.

Diameter

This edit box is used to specify the diameter of the boss feature to be created, refer to Figure 6-80.

Offset

This edit box is used to specify the offset distance of the boss feature, refer to Figure 6-80.

Draft Angle

This edit box is used to specify the draft angle to be applied to the boss feature, refer to Figure 6-80.

Thickening or Offsetting the Faces of Features

Ribbon: 3D Model > Modify > Thicken/Offset


You can thicken a specified face or offset it using the **Thicken/Offset** tool. You can achieve the resulting output as a solid face or a surface. You can also use this tool to offset or thicken a surface. The resulting feature can be a surface or a solid face of the specified thickness. On invoking this tool, the **Thicken/Offset** dialog box will be displayed. The options provided in various tabs of this dialog box are discussed next.

Thicken/Offset Tab

The options in the **Thicken/Offset** tab, shown in Figure 6-81, are discussed next.

Select

The **Select** button is chosen to select the face or the surface to thicken or offset. When you invoke the **Thicken/Offset** dialog box, this button is chosen by default and you are prompted to select faces.



*Figure 6-81 The **Thicken/Offset** tab of the **Thicken/Offset** dialog box*

Solids

Choose this button to select the required multi-body from the Graphics window for offsetting the selected face or surface.

Filter Area

This area is available on upper right side of the **Thicken/Offset** dialog box and it provides two radio buttons. The **Face** radio button is selected to restrict the selection to the faces of the solid models. The **Quilt** radio button is selected to restrict the selection to the surfaces only. Note that if you select the **Face** radio button, you can also select a surface. This is because a surface is also considered as a face.

Distance

The **Distance** edit box is used to specify the offset distance or the thickness value of the resulting feature. Note that you are also allowed to offset a selected face or a surface with a zero distance, making a copy at the same location. However, in this case, the output can only be a surface.

Output Area

The two buttons in the **Output** area are used to specify the output of using the **Thicken/Offset** tool. If you choose the **Solid** button, the resulting feature will be a solid face. If you choose the **Surface** button, the resulting feature will be a surface. Figure 6-82 shows a surface and Figure 6-83 shows a solid face

created by offsetting the surface by a distance of 4 mm.

Figure 6-84 shows the output of this tool in the form of an offset surface. In this case, the offset distance is also 4 mm.




Figure 6-82 Original surface




Figure 6-83 Solid face created by offsetting the surface by a distance of 4 mm





Figure 6-84 Output in the form of an offset surface

Operation Area

The **Operation** area is on the right of the **Output** area and has four buttons. These four buttons **Join**, **Cut**, **Intersect** and **New solid** are used to specify the resulting operation to be performed using the **Thicken/Offset** tool. Note that these buttons will not be available if the output of this tool is a surface. The functions of these buttons are the same as those discussed in the **Extrude** dialog box. The **Join** button is chosen for creating a join feature, the **Cut** button for a cut feature; and the **Intersect** button for an intersect feature. The **New solid** button is used to create a new solid that is independent of other solid bodies in the Graphics window. Figure 6-85 shows a feature created by offsetting the top face of the base feature by using the **Join** operation. Figure 6-86 shows the feature created by offsetting the same face by using the **Cut** operation.

Note

It is evident from Figures 6-85 and 6-86 that the resultant feature is always normal to the selected face or surface.



*Figure 6-85 Offsetting the top face by using the **Join** operation*




Figure 6-86 Offsetting the top face by using the **Cut** operation

Direction Area

This area with three buttons is located below the **Distance** edit box. The buttons in this area are used to specify the direction in which the resulting feature will be created.

More Tab

The options in the **More** tab, as shown in Figure 6-87, are discussed next.




Figure 6-87 The **More** tab of the **Thicken/Offset** dialog box

Automatic Face Chain

This check box is used to automatically select all tangent faces that form a chain with a selected face. To use this option, invoke the **Thicken/Offset** dialog box and then choose the **More** tab. Select this check box and then select the face by using the **Select** button in the **Thicken/Offset** tab. You will

notice that all tangent faces that form a chain with the selected face are automatically selected.

Create Vertical Surfaces

This check box is used to create the vertical sides of internal surfaces. Remember that this option is available only if the output of this tool is a surface. Also, it works only if the original face selected to be offset is a surface. Figure 6-88 shows a surface selected to be offset and Figure 6-89 shows the resulting offset surface with the side faces created by selecting the **Create Vertical Surfaces** check box. Note that the original surface selected to be offset in this case is removed.




Figure 6-88 Surface selected to be offset




Figure 6-89 Resulting offset surface with side faces

Allow Approximation

This check box is selected to allow Autodesk Inventor to make some

assumptions if the exact thicken or offset solution of the model cannot be determined. When you select this check box, the options in this area will be enabled. The drop-down list in this area is used to specify the type of approximation to be made. You can select the **Mean**, **Never too thin**, or **Never too thick** option from this drop-down list. The **Optimized** radio button is selected to make an optimized approximation such that minimum time is required. Selecting the **Specify Tolerance** radio button allows you to specify the tolerance that will be used to make the approximation. If the tolerance is more, the time required to compute the feature will be increased.

Creating the Embossed and Engraved Features

Ribbon: 3D Model > Create > Emboss

The **Emboss** tool allows you to create an embossed or engraved feature. Generally, this tool is used to emboss or engrave text on an existing feature. This tool remains inactive until a sketch or a text is available in the graphics window. When you invoke this tool, the **Emboss** dialog box will be displayed, as shown in Figure 6-90. The options in this dialog box are discussed next.



Figure 6-90 The Emboss dialog box

Profile

The **Profile** button is chosen to select the profile or the text to be engraved or embossed. When you invoke this dialog box, this button is chosen automatically and you are prompted to select the profile.

Solid

This button is used to select the required body from the graphics window for offsetting the selected face or surface.

Depth

The **Depth** edit box is used to enter the depth of the embossed or engraved feature.

Top Face Appearance

The **Top Face Appearance** button, present below the **Depth** edit box, is chosen to assign a different color to the top face of the embossed or engraved feature. When you choose this button, the **Appearance** dialog box will be displayed. This dialog box has a drop-down list that can be used to select a color to assign to the top face of the new feature.

Emboss from Face

The **Emboss from Face** button is used to create an embossed feature. The selected profile or text is projected on a face and then a join feature is created. The shape of the join feature is defined using the profile or text selected to be embossed. Note that the depth you define is calculated from the plane on which the feature is created and not from the sketching plane. Figure 6-91 shows a model with an embossed text.

Engrave from Face

The **Engrave from Face** button is used to create an engraved feature. The selected profile or text is projected on a face and then a cut feature is created. A material equivalent to the shape of the profile or text is removed from the feature on which it is projected. Figure 6-92 shows a model with text engraved in it.




Figure 6-91 Model with the embossed text




Figure 6-92 Model with the engraved text

Emboss/Engrave from Plane

The **Emboss/Engrave from Plane** button is used to create a feature that is embossed and engraved feature. The profile or the text is extruded in both the directions of the sketch plane. When you select this option, the **Taper** edit box appears in the **Emboss** dialog box. You can enter the taper value for the emboss/engrave feature in it. Note that when you choose this button, the **Depth** edit box is not displayed. Figure 6-93 shows a model with the embossed text.

Direction

The direction buttons are used to reverse the direction of the embossed or engraved features.

Wrap to Face

The **Wrap to Face** check box is selected to wrap the embossed or engraved feature such as the face of a revolved feature around a curved face. When you select this check box, the **Face** button will become available. This button allows

you to select the face on which the feature will be embossed or engraved. Figure 6-94 shows a bottle with an embossed text wrapped on the outer face.




Figure 6-93 Model with the embossed text



Figure 6-94 Bottle with an embossed text wrapped on the outer face

Applying Images on a Feature

Ribbon: 3D Model > Create > Decal

While designing a product, you may need to apply an image to the product. The image can be the label of a company, a bar code, an instruction for handling the component, and so on. These images can be applied on the feature using the **Decal** tool. When you invoke this tool, the **Decal** dialog box will be displayed, as shown in Figure 6-95. The options in this dialog box are discussed next.




Figure 6-95 The Decal dialog box

Image

The **Image** button is chosen by default and is used to select the image to be applied to the feature. Note that before invoking the **Decal** tool, you need to insert an image in the sketch by using the **Insert Image** tool from the **Insert** panel of the **Sketch** tab.

Face

The **Face** button is chosen to select the face on which the image will be applied.

Wrap to Face

The **Wrap to Face** check box is selected to wrap an image about a circular face. This check box will not be active if you select a non-circular face. Figure 6-96 shows a bottle after wrapping an image on it. In this figure, the circular face of the bottle was selected as the face to transfer the image.



Figure 6-96 Image wrapped on a bottle

Chain Faces

The **Chain Faces** button is chosen to select all tangentially connected chain faces to transfer an image. Figure 6-97 shows a model with the side edges filleted and an image. The top face of this model is selected to transfer the image. Notice that the image appears on the filleted chain faces automatically, as shown in Figure 6-98.




Figure 6-97 Model and image




Figure 6-98 Model after applying the image

ASSIGNING DIFFERENT COLORS/STYLES TO A MODEL

Autodesk Inventor allows you to change the color/style of a model to improve its appearance. You can apply a different color/style to a model by selecting an appropriate option from the **Appearance** drop-down list available on the extreme right of the **Quick Access Toolbar**. Note that this drop-down list will be activated only when a model is available in the graphics window. By default, the **Default** style will be applied to the model. To change the color/style of the model, click on the **Appearance** drop-down list; the list of all available styles and colors will be displayed, as shown in Figure 6-99. Select the required style/color from the list displayed; the selected style or color will automatically be applied to the model.

If you want to change the style/color of a particular feature in a model, select the required feature from the **Browser Bar** or from the drawing window and then choose the required style or color from the **Appearance** drop-down list.

You can also assign a different color/style to feature by right-clicking on it in the **Browser Bar**. On doing so, a shortcut menu will be displayed. Choose the **Properties** option from the shortcut menu; the **Feature Properties** dialog box will be displayed. Select the required color/style from the **Feature Appearance** drop-down list of this dialog box.

To change the style/color of a particular face, select the required face and right-click; a shortcut menu will be displayed. Choose **Properties** from the shortcut menu; the **Face Properties** dialog box will be displayed, refer to Figure 6-100. Select the required style/color from the **Face Appearance** drop-down list and choose the **OK** button.




Figure 6-99 The Appearance Override drop-down list




Figure 6-100 The Face Properties dialog box

ASSIGNING DIFFERENT MATERIAL TO A MODEL

Autodesk Inventor allows you to change the material of a model. You can apply a different material to a model by selecting the appropriate option from the **Material** drop-down list available in the **Quick Access Toolbar**. By default,

generic material will be applied to the model. To change the material of the model, click on the **Material** drop-down list; a list of available materials will be displayed, as shown in Figure 6-101. Select the required material from the list displayed; the selected material will be applied to the model.

If you want to override the material of the model, select the required component from the Browser Bar or from the drawing window and then choose the required material from the **Material** drop-down list; the existing material will be overridden with the selected material.

Modifying the Properties of an Existing Material

In Autodesk Inventor, you can also edit the material properties of an existing material with the help of the **Material Browser** dialog box. To invoke the **Material Browser** dialog box, choose the **Material** tool from the **Quick Access Toolbar**; the **Material Browser** dialog box will be displayed, as shown in Figure 6-102. To edit the material properties, move the cursor over the material that you want to edit; two buttons, **Add material to documents** and **Add material to document and displays in editor** are highlighted. Choose the **Adds materials to documents and displays in editor** button; the **Material Editor** dialog box will be displayed, as shown in Figure 6-103. Now, you can edit the identity, appearance, and physical properties of the material by specifying appropriate values in their respective edit boxes in the **Identity**, **Appearance**, and **Physical** tabs of this dialog box. After changing the properties of the material, the material is added in the **Document Material** area of the **Material Browser** dialog box. Now choose **Apply**, and then the **OK** button from the **Material Editor** dialog box.




Figure 6-101 The **Material** drop-down list





Figure 6-102 The **Material Browser** dialog box



TUTORIALS

Tutorial 1

In this tutorial, you will create the model of a Fixture Base shown in Figure 6-104. Its dimensions are given in the same figure. After creating the solid model, you will change its color to yellow. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- Start a new part file and invoke the Sketching environment. Create the sketch for the base feature on the XZ plane and extrude it to a distance of 102 mm, refer to Figure 6-105.
- Define a new sketch plane on the back face of the base feature and create the join feature, refer to Figure 6-108.
- Create two cylindrical features with holes on the front face of the second feature, refer to Figure 6-110.
- Create the fillet on the base feature, refer to Figure 6-111.
- Create two counterbore holes taking the reference of the cylindrical faces of fillets by using the **Hole** tool, refer to Figure 6-112.
- Finally, draw an open sketch and convert it into a rib using the **Rib** tool to complete the model, refer to Figure 6-114.
- Change the appearance of the model by using the **Appearance** drop-down list in the **Quick Access Toolbar**.




Creating the Base Feature

You need to create the base feature on the XZ plane.

1. Start a new metric standard part file.
2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Select the **XZ** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **XZ** plane becomes parallel to the screen. Alternatively, select the **XZ** plane from the Graphics window.

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*
2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*
4. Create the sketch for the base feature. Add the required constraints and dimensions to it. The sketch after adding constraints and dimensions is shown in Figure 6-105.
5. Exit the Sketching environment and extrude the sketch to a distance of 102 mm using the **Extrude** tool to create the base feature. The base feature is shown in Figure 6-106.






Figure 6-104 Views and dimensions of the model for Tutorial 1




Figure 6-105 Sketch for the base feature




Figure 6-106 Base feature

Creating a Join Feature on the Back Face of the Base Feature

1. Define a new sketch plane on the back face of the base feature. Draw the sketch for the join feature and then add the required constraints and dimensions to it. The sketch after adding constraints and dimensions is shown in Figure 6-107.
2. Exit the Sketching environment and then extrude the sketch to a distance of 20 mm toward the front of the base feature, as shown in Figure 6-108.




Figure 6-107 Sketch for the join feature




Figure 6-108 Model after creating the join feature

Creating Cylindrical Features on the Front Face of the Second Feature

To create two cylindrical features, you need to draw a sketch consisting of two concentric circles. The reason for drawing the sketch for both the features together is that both the cylindrical features are to be extruded to the same distance.




Figure 6-109 Sketches for the cylindrical features

1. Define a new sketch plane on the front face of the second feature and draw the sketches for both the cylindrical features, as shown in Figure 6-109.
2. Invoke the **Extrude** tool and extrude the sketches to a distance of 10 mm.

While selecting profiles for extrusion, in both sketches make sure that you click between the inner and outer circles. As a result, the inner circles are subtracted from the outer circles when you extrude the sketch, thus creating holes. The model after creating the cylindrical features is shown in Figure 6-110.




Figure 6-110 Model after creating cylindrical features

Creating Fillets

The vertical edges of the front face of the base feature need to be filleted so that you can use the cylindrical faces of fillets to define the center of the counterbore holes.

1. Choose the **Fillet** tool from the **Modify** panel of the **3D Model** tab; the **Fillet** dialog box is displayed and you are prompted to select the edges to be filleted. By default, the **Constant** tab is chosen in this dialog box.
2. Select the outer left and outer right vertical edges on the front face of the base feature.

On selecting the edges, the **Edges** column displays **2 selected** edge and the preview of the fillet is displayed on the model with 2 mm as the default radius value.




Figure 6-111 Model after creating fillets

3. Click on the default radius value in the **Radius** column and enter **30** in the edit box displayed. Alternatively, enter **30** in the edit box of the mini toolbar. You will notice that the fillet in the preview of the model has also increased accordingly. Choose the **OK** button to exit the **Fillet** dialog box; the fillets are created, as shown in Figure 6-111.

Creating Counterbore Holes

As mentioned earlier, in Autodesk Inventor, you can create holes concentric to cylindrical faces. To create two counterbore holes, you need to use the cylindrical faces of the fillet.

1. Choose the **Hole** tool from the **Modify** panel of the **3D Model** tab to invoke the **Hole** dialog box.
2. Select the **Counterbore** radio button from the area located on the right of the **Placement** area.
3. Select the **Concentric** option from the drop-down list in the **Placement** area; the **Plane** button is chosen in the **Placement** area and you are prompted to select a planar face or a work plane for the placement plane.
4. Select the top planar face of the base feature as the face to place the hole; the preview of the counterbore hole with the current values is displayed. Also, the **Concentric Reference** button is chosen automatically and you are prompted to select a circular edge or a cylindrical face to reference the hole center.
5. Select the cylindrical face of the fillet on the right; the preview of the hole is relocated.
6. Select the **Through All** option from the drop-down list in the **Termination** area. Modify the value of the counterbore diameter in the preview window to **38**. Similarly, modify the value of the bore diameter to **20** and the counterbore depth to **6**.

7. Without closing the **Hole** dialog box, choose the **Apply** button to create the hole.
8. Similarly, using the options already set in the **Hole** dialog box, create another hole concentric to the fillet on the left.
9. Choose **Cancel** to close the **Hole** dialog box. The model after creating the counterbore holes is shown in Figure 6-112.




Figure 6-112 Model after creating counterbore holes

Creating the Rib Feature

The rib feature is created at the center of the model. Therefore, you need to define an offset work plane at the center on which the rib feature will be created.

1. Choose the **Offset Plane** tool from **3D Model > Work Features > Plane** drop-down and select the right face of the base feature; the preview of the work plane along with the mini toolbar is displayed in the Graphics window.
2. Enter **-108** in the edit box available in the mini toolbar and then choose **OK** from it. The negative value ensures that the work plane gets created inside the model. Select this work plane as the sketching plane.
3. Draw an open sketch for the rib feature and then add the required constraints and dimensions to it, as shown in Figure 6-113.

When you apply the **Coincident** constraint between the lines in the sketch and the edges of the model, the lines defining the edges are drawn. Make sure these lines are not selected when you select the sketch for creating the rib feature.

4. Exit the Sketching environment. Next, invoke the **Rib** dialog box and choose the **Parallel to Sketch Plane** button from the **Rib** dialog box. Select the open profile. You need not select the direction button and move the cursor.
5. Set the value in the edit box in the **Thickness** area to **30**. Choose to exit the **Rib** dialog box. The final model after creating all features is shown in Figure 6-114.




Figure 6-113 Sketch for the rib feature




Figure 6-114 Final model for Tutorial 1

Changing the Appearance of the Model

When a model is created, the default color is applied to it. However, in Autodesk Inventor, you can change the default color/style of the model.

1. Select the **Yellow** option from the **Appearance** drop-down list on the right of the **Quick Access Toolbar**; the color of the model changes to yellow. Note that you do not need to select the model to apply color to it.
2. Save the model with the name *Tutorial1* at the location *C:\Inventor_2016\c06* and then close the file.

Tutorial 2

In this tutorial, you will create a model of the Pivot Base shown in Figure 6-115. Its dimensions are given in the same figure. Change the color/style of the model to Zinc Chromate. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- a. Create the base feature on the XZ plane, refer to Figure 6-116.
- b. Create the join feature on the back face of the base feature, refer to Figure 6-119.
- c. Create another join feature on the front face of the second feature, refer to Figure 6-121.
- d. Create the cut feature on the third feature, refer to Figure 6-123.
- e. Create the rib and the join feature on the right of the model, refer to Figure 6-127.
- f. Mirror the rib and the join feature on the left of the model, refer to Figure 6-128.
- g. Create a hole on the top face of the base feature, refer to Figure 6-130.
- h. Change the style of the model by using the **Appearance** drop-down list in the **Quick Access Toolbar**.






Figure 6-115 Views and dimensions of the model for Tutorial 2

Creating the Base Feature

1. Start a new metric part file.
2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the

sketching plane.

3. Select the **XZ** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **XZ** plane becomes parallel to the screen. Alternatively, select the **XZ** plane from the Graphics window.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.

2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

4. Draw the sketch of the base feature, as shown in Figure 6-116.
5. Exit the Sketching environment.
6. Click on the sketch in the Graphics window; the mini toolbar with the **Create Extrude**, **Create Revolve**, and **Edit Sketch** tools is displayed.
7. Choose the **Create Extrude** tool; the **Extrude** dialog box is displayed. Also, the preview of the extrude feature along with the mini toolbar is displayed.
8. Enter **96** in the edit box of the mini toolbar and choose **OK** to create the base feature of the model, as shown in Figure 6-117.




Figure 6-116 Sketch of the base feature





Figure 6-117 Base feature

Creating a Join Feature on the Back Face of the Base Feature

1. Rotate the model by using the ViewCube such that its back face is visible.
2. Select the back face of the base feature; the mini toolbar along with the **Edit Extrude**, **Edit Sketch**, and **Create Sketch** tools is displayed in the Graphics window.
3. Choose the **Create Sketch** tool and draw the sketch for the next feature on it, as shown in Figure 6-118.
4. Extrude the sketch to a distance of 14 mm toward the front of the base feature by using the **Extrude** tool, see Figure 6-119.

Figure 6-118 Sketch of the join feature






Figure 6-119 Model after creating the join feature

Creating the Join Feature on the Front Face of the Second Feature

1. Define a new sketch plane on the front face of the second feature.
2. Draw two disjoint sketches of the join feature, as shown in Figure 6-120.
3. Extrude both sketches to a distance of 14 mm using the **Extrude** tool. The model after creating the join feature is shown in Figure 6-121. Note that the two sketches are displayed as a single feature in the **Browser Bar** because both the sketches are extruded together.





Figure 6-120 Sketches of the join feature on the front face

Figure 6-121 Join feature on the front face of the second feature



Creating the Cut Feature

Next, you need to create a cut feature that will remove material from the previous feature. You need to draw two disjoint sketches for the cut feature at the same time and then extrude them using the **Cut** operation. As the sketches are to be extruded through the model, you need to select both of them together while selecting the profile for creating the cut feature.

1. Define a new sketch plane on the front face of the semicircular feature. When you define the sketch plane on the semicircular feature, a sketch defining the semicircular feature is drawn. Offset this sketch inside, refer to Figure 6-122. Note that after invoking the **Offset** tool, you need to right-click, and then choose the **Loop Select** option from the shortcut menu. This ensures that the entire loop is offset. Since you have used a reference entity to draw the inner sketch, you need to specify just one dimension value, that is, the radius of any of the arcs.
2. Draw the sketch for the cut feature and the circle for the hole, refer to Figure 6-122.
3. Extrude the sketch and the circle by using the **Through All** option of the **Cut** operation in the mini toolbar to create the cut feature, see Figure 6-123.




Figure 6-122 Offset sketch for the cut feature




Figure 6-123 Model after creating the cut feature

Creating the Rib Feature

The sketch for the rib will be created on the sketch plane defined on the right face of the second feature. The sketch will be extruded toward the left to create the feature.

1. Define a new sketch plane on the right face of the second feature and then draw the sketch of the rib feature. Add the required dimensions and constraints to the sketch, as shown in Figure 6-124.
2. Exit the Sketching environment and choose the **Rib** tool from the **Create** panel of the **3D Model** tab; the **Rib** dialog box is displayed. By default, the **Normal to Sketch Plane** button is chosen in the **Type Specification** area. Choose the **Parallel to Sketch Plane** button in this area.
3. Select the open sketch. Choose the second direction button in the **Thickness** area to extrude the feature toward left. Next, choose the **Direction2** button from the dialog box; the preview of the rib feature is displayed, showing the sketch extruded toward the left of the sketch.

4. Enter **10** in the **Thickness** edit box in the **Thickness** area.
5. Choose **OK** to exit the **Rib** dialog box; the rib is created, as shown in Figure 6-125.




Figure 6-124 Sketch of the rib




Figure 6-125 Model after creating the rib

Creating the Join Feature on the Right Face of the Base Feature

1. Define a new sketch plane on the right face of the base feature.
2. Draw the sketch of the join feature. Draw a circle inside the sketch such that when extruded, a hole is created automatically. Add the required constraints and dimensions to it, as shown in Figure 6-126, and then exit the Sketching environment.
3. Extrude the sketch to a distance of 12 mm to create the feature. Make sure that you select the profile by using a point inside the outer loop but outside the circle. The model after creating the join feature is shown in Figure 6-127.




Figure 6-126 Sketch of the join feature




Figure 6-127 Model after creating the join feature

Mirroring Features on the other Side of the Model

The second set of rib and join features will be created by mirroring the first set of these features on the other side of the model. The features will be mirrored about the offset work plane created at the center of the model.

1. Choose the **Offset From Plane** tool from **3D Model > Work Features > Plane** drop-down; you are prompted to select a planar surface.
2. Select the right face of the base feature; the preview of the plane along with the mini toolbar is displayed.
3. Enter **-111** in the edit box of the mini toolbar and then choose **OK**; the plane is created.

4. Choose the **Mirror** tool from the **Pattern** panel of the **3D Model** tab; the **Mirror** dialog box is displayed and you are prompted to select the features to be patterned. Select the rib feature and the feature created on the right face of the base feature.
5. Choose the **Mirror Plane** button and select the offset work plane as the mirror plane; the preview of the mirrored features is displayed. Choose **OK** to exit this dialog box.
6. Right-click on the work plane in the **Browser Bar** to display the shortcut menu. Choose the **Visibility** option from the shortcut menu to turn off the visibility of the work plane. The model after mirroring the features is shown in Figure 6-128.




Figure 6-128 Model after mirroring the features

Creating the Hole on the Top Face of the Base Feature

1. Choose the **Hole** tool from the **Modify** panel of the **3D Model** tab to invoke the **Hole** dialog box.
2. Select the **Linear** option from the drop-down list in the **Placement** area; the **Face** button is chosen and you are prompted to select a planar face or a work plane.
3. Select the top planar face of the base feature. Next, select the edge labeled 1 on the top face of the base feature, refer to Figure 6-129; the mini toolbar is displayed.

4. Modify the value in the edit box of the mini toolbar to **88**.
5. Similarly, select the edge labeled 2 on the top face of the base feature and modify the value to **41**, refer to Figure 6-129.
6. Select the **Through All** option from the drop-down list in the **Termination** area.
7. Set the value of the diameter of the hole in the preview window to **22**; the diameter of the hole in the preview also increases automatically. Choose the **OK** button. The final model for Tutorial 2 is shown in Figure 6-130.

Changing the Style and Saving the Model

As mentioned earlier, the style of the feature is changed using the **Appearance** drop-down list in the **Quick Access Toolbar**.

1. Select the **Zinc Chromate 2** option from the **Appearance** drop-down list available on the extreme right of the **Quick Access Toolbar**; the material of the model is changed to Zinc Chromate.
2. Save the model with the name *Tutorial2* at the location *C:\Inventor_2016\c06* and then close the file.




Figure 6-129 The preview of the hole feature




Figure 6-130 Final model for Tutorial 2

Tutorial 3

In this tutorial, you will create the model shown in Figure 6-131. Its views and dimensions are also given in the same figure. After creating a solid model, you will change the color of the front face of base feature to green color. **(Expected time: 30 min)**

The following steps are required to complete this tutorial:

- a. Create the sketch of the base feature on the YZ plane and extrude it using the **Symmetric** option, refer to Figures 6-132 and 6-133.
- b. Create the second feature on the YZ plane and extrude it using the **Symmetric** option, refer to Figures 6-134 and 6-135.
- c. Create one of the holes on the front face of the second feature and then create a circular pattern of this hole, refer to Figures 6-136 and 6-137.
- d. Create the cylindrical join feature and then create a hole in it, refer to Figure 6-140.
- e. Create the circular patterns of the last join feature and the hole, refer to Figure 6-141.
- f. Finally, create the central hole, refer to Figure 6-142.
- g. Change the color of the front face of the base feature.

The base feature of this model will be created on the **YZ** plane. Also, all features in this model will be extruded using the Symmetric option because they extend equally from the front face and the back face of the base feature.






Figure 6-131 Views and dimensions of the model for Tutorial 3

Creating the Base Feature

The base feature of this model will be created on the YZ plane. Therefore, you need to invoke the Sketching environment and then define a new sketch plane on the YZ plane.

1. Start a new metric standard part file.
2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.
2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

3. Select the **YZ** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **YZ** plane becomes parallel to the screen. Alternatively, select the **YZ** plane from the Graphics window.

Draw the sketch of the base feature, as shown in Figure 6-132.

4. Add the required constraints and dimensions to the sketch, refer to Figure 6-132. Exit the Sketching environment and then extrude the sketch to a distance of 22 mm using the **Symmetric** option. The base feature of the model is shown in Figure 6-133.





Figure 6-132 Sketch of the base feature

Figure 6-133 Base feature of the model



Creating the Next Join Feature

As the last feature was created on the YZ plane and extruded using the **Symmetric** option, you can also create other features on the same plane and extrude them using the **Symmetric** option.

1. Choose the **Start 2D Sketch** tool from **3D Model > Sketch > Sketch** drop-down; you are prompted to select a plane or a planar face to create the sketch.
2. Select YZ plane from the **Browser Bar**; the Sketching environment is invoked. As the sketch is drawn inside the model, it is hidden by the faces that lie between the sketch and the user. Therefore, you need to slice the model.
3. Right-click in the drawing window to display a shortcut menu and choose **Slice Graphics** from it.
4. Draw the sketch of the join feature, as shown in Figure 6-134. For dimensions, refer to Figure 6-131.
5. Exit the Sketching environment and then extrude the sketch to a distance of 32 mm using the **Symmetric** option. The model after creating the join feature is shown in Figure 6-135.




Figure 6-134 Sketch of the join feature




Figure 6-135 Model after creating the join feature

Note

It is recommended that you create a big circle and a small circle on the periphery of the base feature. Trim the unwanted portion of the small circle and then pattern the small circle, refer to Figure 6-134.

Creating the Hole and its Pattern

Next, you need to create six holes on the previous feature. Instead of creating all holes, create one hole and then create a circular pattern of this hole. To create the pattern, you need to create one hole by defining the sketch plane on the front face of the previously created feature.

1. Choose the **Hole** tool from the **Modify** panel of the **3D Model** tab; the **Hole** dialog box is displayed. Select the **Concentric** option from the drop-down list in the **Placement** area.
2. Select the front planar face of the second feature as the plane to place the hole and then select one of the six semicircular features.
3. Select the **Through All** option from the drop-down list in the **Termination** area.

4. Modify the value of the diameter of the hole in the preview window to **6**. Choose **OK** to exit the dialog box. The model after creating one of the holes is shown in Figure 6-136.
5. Choose the **Circular** tool from the **Pattern** panel of the **3D Model** tab; the **Circular Pattern** dialog box is displayed and you are prompted to select the feature to be patterned.
6. Select the hole from the Graphics window. Next, choose the **Rotation Axis** button from the dialog box and then select the outer cylindrical face of the second join feature.

As you select the cylindrical face to specify the rotation axis, an axis passing through its center is displayed and the preview of the hole pattern is displayed on the model. Also, a copy of the hole is displayed on each of the semicircular features.

7. In the **Circular Pattern** dialog box, accept the default values and choose **OK** to exit this dialog box. The model after creating the hole pattern is shown in Figure 6-137.




Figure 6-136 Model after creating the hole




Figure 6-137 Model after creating the hole pattern

Creating the Cylindrical Join Feature

The cylindrical join feature will also be created on the YZ plane and will be extruded using the **Symmetric** option.

1. Define a new sketch plane on the YZ plane and then slice the graphics. Draw a circle as the sketch of the cylindrical join feature, as shown in Figure 6-138. Add the required constraints and dimensions to the sketch.
2. Exit the sketching environment and then extrude the circle to a distance of 32 mm using the **Symmetric** option, refer to Figure 6-139.




Figure 6-138 Sketch of the cylindrical join feature




Figure 6-139 The cylindrical join feature

Creating the Hole in the Join Feature

1. Choose the **Hole** tool from the **Modify** panel of the **3D Model** tab; the **Hole** dialog box is displayed.
2. Select the **Concentric** option from the drop-down list in the **Placement** area, if it has not already been selected.
3. Select the front face of the previous feature and then the cylindrical face of the same feature to place the hole.
4. Select the **Through All** option from the drop-down list in the **Termination** area, if it has not already been selected.
5. Modify the value of the diameter of the hole in the preview window to **20**. Choose **OK**; the dialog box is closed and a hole is created. The model after creating the hole on the join feature is shown in Figure 6-140.

Creating Circular Patterns

1. Choose the **Circular** tool from the **Pattern** panel of the **3D Model** tab; the **Circular Pattern** dialog box is displayed and you are prompted to select the feature to be patterned.
2. Select the cylindrical join feature and the hole from the Graphics window or the **Browser Bar** to pattern; both the features are displayed with a blue outline.
3. Choose the **Rotation Axis** button and select the bottom cylindrical face of the base feature to define the axis of rotation for the pattern.

The preview of the pattern with six items arranged through an angle of 360 degrees is displayed on the model. As the pattern shown in the preview is not the required pattern, you need to modify values in the **Circular Pattern** dialog box.

4. Enter **3** and **81** in the **Occurrence Count** and **Occurrence Angle** edit boxes, respectively in the **Placement** area.

Note

*Sometimes the orientation of the pattern features in the preview does not match with the required orientation. In such a case, you need to choose the **Flip** button that is located on the right of the **Rotation Axis** button in the **Circular Pattern** dialog box.*

5. Accept the other default values and choose **OK** to create the circular pattern. The model after creating the pattern is shown in Figure 6-141.




Figure 6-140 Model after creating the hole on the join feature




Figure 6-141 Model after creating the circular pattern of the join feature and the hole

Creating the Hole on the Second Feature (Join Feature)

1. Choose the **Hole** tool from the **Modify** panel of the **3D Model** tab; the **Hole** dialog box is displayed. Select the **Concentric** option from the drop-down list in the **Placement** area.
2. Select the front face of the second feature and then the cylindrical face of the same feature to place the hole.
3. Select the **Through All** option from the drop-down list in the **Termination** area, if it has not already been selected.
4. Modify the value of the diameter of the hole in the preview window to **40**.
5. Choose **OK** to create the hole and exit the dialog box. The isometric view of the final model for Tutorial 3 is shown in Figure 6-142.




Figure 6-142 Final model

Changing the Color of the Front Face of the Base Feature

As mentioned earlier, you need to change the color of the face by using the **Properties** option.

1. Select the front face of the base feature and right-click; a Marking menu is displayed.
2. Choose the **Properties** option from the Marking menu; the **Face Properties** dialog box is displayed.
3. Click on the **Face Appearance** drop-down list and select the **Green Polished** option from it. Next, choose the **OK** button; the color of the front face of the base feature turns green.
4. Save the model with the name *Tutorial3* at the location *C:\Inventor_2016\c06* and then close the file.

Tutorial 4

In this tutorial, you will create a bottle and then write text on the upper circular face of the bottle, as shown in Figure 6-143. The wall thickness of the bottle is 1 mm. Also, apply an external image from your computer, to the bottle. The dimensions of the bottle are shown in Figure 6-144. **(Expected time: 30 min)**



Figure 6-143 Bottle with an image and text wrapped on it




Figure 6-144 Dimensions of the bottle

The following steps are required to complete this tutorial:

- a. Create the bottle by revolving a sketch drawn on the XZ plane, refer to Figure 6-145.
- b. Write the text such that it can be wrapped on the upper circular face of the bottle, refer to Figure 6-147.
- c. Emboss the text on the bottle such that it is wrapped on it, refer to Figure 6-150.
- d. Insert an image into the Sketching environment and then apply it to the bottle such that it is wrapped around it, refer to Figure 6-150.

Creating the Bottle

First, you need to create the sketch of the bottle on the XZ plane.

1. Start a new metric template file.
2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Now, select the **XZ** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **XZ** plane becomes parallel to the screen. Alternatively, select the **XZ** plane from the Graphics window.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the View Cube in order to maintain the right orientation of the model.
 2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.
4. Draw the sketch of the bottle and then offset it outward to a distance of 1 mm to create a hollow bottle. Join the endpoints of the sketch using the **Line** tool to create a closed sketch, as shown in Figure 6-145.




Figure 6-145 Sketch for the bottle

5. Add the required constraints and specify the dimensions, refer to Figure 6-145.

Note

In Figure 6-145, the display of grids has been turned off for the clarity of the sketch.

6. Exit the Sketching environment and then invoke the **Revolve** tool.
7. Select the sketch from the Graphics window and then select **Z Axis** as the axis of revolution from the **Browser Bar**; the preview of the revolved feature is displayed in the Graphics window. Choose **OK** to create the revolved feature and exit the dialog box.
8. Next, select the **Glass** option from the **Materials and Appearance** drop-down list. On doing so, the material of the bottle is changed to the selected material, as shown in Figure 6-146.

Embossing the Text on the Bottle

Next, you need to write the text and emboss it on the bottle. The text is written on a work plane created tangent to the outer face of the bottle and parallel to the YZ plane.

1. Choose the **Tangent to Surface and Parallel to Plane** tool from **3D Model > Work Features > Plane** drop-down; you are prompted to select a curved face or a planar face.
2. Select the **YZ** plane from the **Browser Bar** and then select the lower cylindrical part of the bottle; a work plane tangent to the bottle and parallel to the YZ plane is created. Note that the plane needs to be created in the front of the bottle.
3. Select the new work plane as the sketching plane and then invoke the **Start 2D Sketch** tool.

4. Choose the **Text** tool from **Sketch > Create > Text** drop-down and then drag the cursor or click in the drawing window; the **Format Text** dialog box is displayed.

*Tip. If the text is written in the reverse direction, you need to flip the normal of the work plane. To do so, exit all tools and then select the work plane. Next, right-click on the selected work plane, and then choose **Flip Normal** from the shortcut menu.*

5. Select **3.50 mm** from the **Size** drop-down list and enter **CADCIM Technologies** in the **Text Window** of the **Format Text** dialog box. Choose to exit the dialog box; the text is displayed in the drawing window, as shown in Figure 6-147. If the text created is not at the position shown in Figure 6-147, you can select it and drag it to the required position.



Figure 6-146 *Bottle with the selected material*



Figure 6-147 Partial view of the bottle displaying the position of the text

6. Exit the Sketching environment and then choose the **Emboss** tool from the **Create** panel of the **3D Model** tab in the **Ribbon**; the **Emboss** dialog box is displayed and you are prompted to select the profile.
7. Select the text and then choose the **Top Face Appearance** button below the **Depth** edit box; the **Appearance** dialog box is displayed. Select the **Gold - Metal** option from the drop-down list in the **Appearance** dialog box. Choose **OK** to exit this dialog box.
8. Select the **Wrap to Face** check box. Next, choose the **Face** button, if it is not already been chosen and select the neck of the bottle on which you need to wrap the text. Choose **OK** to exit the dialog box. The partial view of the bottle after wrapping the text on it is shown in Figure 6-148.



Figure 6-148 Partial view of the bottle after wrapping the text

Note

*If the embossed feature is created on the backside of the neck, you need to reverse its direction by choosing the corresponding direction button from the **Emboss** dialog box. The direction buttons are available above the **Wrap to Face** check box.*

Wrapping the Image on the Bottle

Next, you need to insert an image into the Sketching environment and then wrap it on the bottle. It is recommended that you copy the image to the current folder and then insert in the Sketching environment.

1. Copy any external image to the current folder and then choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab; you are prompted to select the plane.
2. Select the tangent work plane created earlier as the sketching plane to invoke the Sketching environment.
3. Choose the **Image** tool from the **Insert** panel of the **Sketch** tab; the **Open** dialog box is displayed.
4. In the **Open** dialog box, select the image that you have copied and then choose the **Open** button; the preview of the image attached to cursor is

displayed in the Graphics window and you are prompted to select the sketch point.

5. Click in the Graphics window to place the image. Right-click, and then choose **OK** from the shortcut menu. You may need to resize and relocate the image such that its size and location is close to that shown in Figure 6-149.
6. Exit the Sketching environment and then choose the **Decal** tool from the **Create** panel of the **3D Model** tab; the **Decal** dialog box is displayed and you are prompted to select the image.
7. Select the image inserted in the Sketching environment. Next, select the face of the bottle to transfer the image.
8. Select the **Wrap to Face** check box and then choose **OK** to exit the dialog box; the image is wrapped on the bottle. The final model of the bottle after wrapping the text and the image on it is shown in Figure 6-150.



Figure 6-149 Image inserted in the Sketching environment

Figure 6-150 Final model of the bottle



9. Save the model with the name *Tutorial4* at the location *C:\Inventor_2016\c06* and then close the file.

Tutorial 5

In this tutorial, you will create the model shown in Figure 6-151. Its dimensions are given in the same figure. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- a. Start a new metric template file **Standard (mm).ipt**.
- b. Use the **Line** tool to draw the sketch of the base feature in the YZ plane.
- c. Extrude the base feature.
- d. Create the second feature on the top of the base feature.
- e. Create the cut feature on the bottom of the model.
- f. Create the hole features on the model.
- g. Create the fillet on the base feature, refer to Figure 6-154.
- h. Mirror the fillets and features using the **Mirror** tool, refer to Figure 6-155.
- i. Save the model.




Figure 6-151 Views and dimensions of the model for Tutorial 5

Creating the Base Feature

You need to create the base feature on the YZ plane.

1. Start a new metric file

2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Now, select the **YZ** plane as the sketching plane from the **Browser Bar**; the Sketching environment is invoked and the **YZ** plane becomes parallel to the screen. Alternatively, select the **YZ** plane from the Graphics window.

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*

2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

4. Next, create the sketch for the base feature on the YZ plane. Add the required constraints and dimensions to it. The sketch after adding constraints and dimensions is shown in Figure 6-152.
5. Exit the Sketching environment. To do so, right-click and then choose the **Finish 2D Sketch** option from the Marking menu displayed.
6. Invoke the **Extrude** tool and extrude the base feature symmetrically about the YZ plane to a distance of 110 mm, as shown in Figure 6-153.




Figure 6-152 Sketch for the base feature




Figure 6-153 Base feature

Note

If the orientation of the model is not similar to the Figure 6-153, change the current orientation by using the ViewCube.

Creating the Fillet Feature and Mirroring it

1. Create the fillet feature of radius 22, as shown in Figure 6-154.




Figure 6-154 Model after creating the fillet feature

2. Invoke the **Mirror** tool from the **Pattern** tab of the **Ribbon**; the **Mirror** dialog box is displayed with the **Features** button chosen by default.
3. Select the fillet feature. After selecting the fillet feature, choose the **Mirror Plane** button from the **Mirror** dialog box and then choose the **YZ** plane from the **Origin** tab of the **Browser Bar**; the preview of the mirror feature is displayed in the Graphics window, as shown in Figure 6-155.
4. Choose **OK** from the **Mirror** dialog box to create the mirror feature, as shown in Figure 6-156.



Note

*You may have to adjust the orientation of the model according to your convenience. Use the **Orbit** tool to adjust the screen appearance.*




Figure 6-155 Preview of the mirror




Figure 6-156 Mirrored fillet feature

Creating a Join Feature on the Back Face of the Base Feature

1. Define a new sketch plane on the back face of the base feature. Draw the sketch for the join feature and then add the required constraints and dimensions to it. The sketch after adding constraints and dimensions is shown in Figure 6-157.
2. Exit the Sketching environment and adjust the view of the model using the ViewCube. Next, extrude the sketch to a distance of 10 mm toward the front of the base feature, as shown in Figure 6-158.

While selecting profiles for extrusion, make sure that you select a point inside the loop sketch but outside the circle. As a result, the new sketch is extruded along the circle, thus creating a hole. The model after creating the second feature is shown in Figure 6-158.




Figure 6-157 Sketch for the join feature




Figure 6-158 Model after creating the join feature

Creating Fillets

As evident from the Figure 6-158, the fillets need to be created on the side surfaces of the second feature with respect to the first feature. In this tutorial, you will create only one fillet feature and then mirror it to the other side of the feature by using the **Mirror** tool.

1. Choose the **Fillet** tool from the **Modify** panel of the **3D Model** tab; the **Fillet** dialog box is displayed and you are prompted to select the edges to be filleted. By default, the **Constant** tab is chosen in this dialog box.
2. Select the right edge that is common to both the first and the second feature. As soon as you select the edge, **1 selected** is displayed on the **Edges** column and the preview of the fillet is displayed on the model with the default radius value 2 mm.
3. Enter **10** in the **R:** edit box of the mini toolbar and choose **OK**. Alternatively, enter **10** in the **Radius** column of the **Fillet** dialog box and then choose **OK**. The fillet feature is created, as shown in Figure 6-159.

Mirroring the Fillets

To mirror the fillet created earlier, you need to use the **Mirror** tool.

1. Invoke the **Mirror** tool from the **Pattern** panel of the **3D Model** tab; the **Mirror** dialog box is displayed. By default, the **Mirror individual features** button is chosen.
2. Select the filleted feature which is to be mirrored. Figure 6-160 shows the selected fillet feature.
3. In the **Mirror** dialog box, choose the **Mirror Plane** button; you are prompted to select a plane for the mirror operation.
4. Select the YZ plane from the **Origin** tab of the **Browser Bar**; a preview of the fillet is displayed on the other side of the second feature.




Figure 6-159 Model after creating one of the fillet features




Figure 6-160 Selected fillet feature and the midplane

5. Choose **OK** from the **Mirror** dialog box; the fillet feature is created on the other side of the second feature as shown in Figure 6-161.




Figure 6-161 Mirrored fillets on the second feature

Creating Holes for the First Feature

As mentioned earlier, in Autodesk Inventor, you can create holes concentric to cylindrical faces. In this tutorial, you can create the holes using the **Hole** tool. But it is recommended that you create one hole with the help of the **Hole** tool and the other one with the help of the **Mirror** tool.

1. Invoke the **Hole** tool from the **Modify** panel of the **3D Model** tab; the **Hole** dialog box is displayed.
2. Select the **Drilled** radio button from the area located on the right of the **Placement** area, if it is not already selected.
3. Select the **Concentric** option from the drop-down list in the **Placement** area; the **Plane** button is chosen in the **Placement** area and you are prompted to select a planar face or a work plane for the placement plane.
4. Select the top planar face of the base feature as the face to place the hole; the preview of the hole with the current values is displayed. Also, the **Concentric Reference** button is chosen automatically and you are prompted to select a circular edge or a cylindrical face to reference the hole center.
5. Select the cylindrical face or circular edge of the fillet on the right; the preview of the hole is relocated.
6. Select the **Through All** option from the drop-down list in the **Termination** area. Modify the value of the hole diameter in the preview window to **11**.
7. Choose the **OK** button to create the hole and exit the **Hole** dialog box. The hole is displayed in Figure 6-162.




Figure 6-162 Model with the hole Feature

8. Choose the **Mirror** tool; the **Mirror** dialog box is displayed.
9. Select the hole on the base feature. Next, choose the **Mirror Plane** button on the **Mirror** dialog box.
10. Select the YZ plane for the mirror operation; the preview of the mirrored feature is displayed.
11. Choose **OK** from the **Mirror** dialog box to complete the mirror operation; the final model after filleting and mirroring is shown in Figure 6-163.

Saving the Model

1. Save the model with the name *Tutorial5* at the location *C:\Inventor_2016\c06* and then close the file.




Figure 6-163 Model after creating counterbore holes

Self-Evaluation Test

Answer the following questions and then compare them to those given at the end of this chapter:

1. The diameter of a hole is defined in the _____ of the **Hole** dialog box.
2. _____ is a process of beveling the sharp edges of a model in order to reduce stress concentration.
3. A rib feature is created by using an _____ sketch.
4. The _____ radio button is selected in the **Mirror** dialog box to create a mirrored feature similar to the original feature, even if they intersect other features.
5. _____ are defined as the thin wall-like structures used to bind joints together so that they do not fail under an increased load.
6. A _____ hole is a stepped hole with a bigger diameter and a smaller diameter.
7. A hole created by using the **Hole** tool is parametric in nature. (T/F)
8. You can remove any entity from the current selection set by pressing the SHIFT key and then selecting the entity once again. (T/F)
9. You can create both fillets and rounds by using the **Fillet** dialog box. (T/F)
10. You can only mirror the entire model. (T/F)

Review Questions

Answer the following questions:

1. Which of the following is not a type of hole?

- (a) Counterbore (b) Countersink
- (c) Countercut (d) Drilled

2. Which of the following tabs provides you with an option to create a flat base hole?

- (a) **Type** (b) **Options**
- (c) **Size** (d) **Thread**

3. How many edges are used to define the setback for a vertex?

- (a) 2 (b) 3
- (c) 4 (d) None of these

4. Which of the following check boxes is displayed in the **Rib** dialog box when you select the direction of applying a thickness parallel to the sketch or choose the **Finite** button from the **Extents** area?

- (a) **Extend Profile** (b) **Clear Profile**
- (c) **Trim Profile** (d) None of these

5. In how many ways can you create chamfers in Inventor?

- (a) 2 (b) 3
- (c) 4 (d) None of these

6. In Autodesk Inventor, you can create holes only on the points/hole centers. (T/F)

7. In the Part module, you can use the **Circular Pattern** tool to arrange the selected features around the circumference of an imaginary circle. (T/F)

8. By using the **Distance** button, you can create a chamfer at an angle of 45 degrees. (T/F)

9. The options in the **Variable** tab of the **Fillet** dialog box are used to fillet

selected edges by applying different radius values along the length of the edge.
(T/F)



10. You can use the options in the **Hole** dialog box to create a tapped hole. (T/F)

Exercises

Exercise 1

Create the model shown in Figure 6-164. Its dimensions are shown in Figure 6-165. **(Expected time: 45 min)**

Figure 6-164 Model for Exercise 1








Figure 6-165 Views and dimensions of the model

Exercise 2

Create the model shown in Figure 6-166. Its dimensions are shown in the same Figure. **(Expected time: 45 min)**






Figure 6-166 The model and its Views and dimensions

Exercise 3

Create the model shown in Figure 6-167. Its views and dimensions are shown in Figure 6-168 (**Expected time: 45 min**)




Figure 6-167 Model for Exercise 3




Figure 6-168 Views and dimensions of the model for Exercise 3

Answers to Self-Evaluation Test

1. preview window, 2. Chamfering, 3. open, 4. **Identical**, 5. Ribs, 6.

counterbore, **7. T, 8. T, 9. T, 10. F**

Chapter 7

Editing Features and Adding Automatic Dimensions to Sketches

Learning Objectives

After completing this chapter, you will be able to:

- Edit features in a model.
- **Update a model after editing.**
- **Edit the sketches of sketched features.**
- **Redefine the sketching plane of a feature.**
- **Suppress and unsupress features.**
- **Copy and delete features.**
- **Add automatic dimensions to sketches.**

CONCEPT OF EDITING FEATURES

Editing is one of the most important parts of designing. Most of the designs require editing either during or after their creation. As mentioned earlier, Autodesk Inventor is a feature-based solid modeling tool. As a result, the model created in Autodesk Inventor is a combination of various features. All these features are individual components and can be edited separately. This property gives this solid modeling software an edge over the other non-feature-based solid modeling tools. For example, Figure 7-1 shows a cylindrical part with six countersink holes created at some pitch circle diameter (PCD).

Now, in case you have to edit the features such that the countersink holes are to be changed into counterbore holes and the number of holes is to be increased, you just need to perform two editing operations. The first editing operation will open the **Holes** dialog box, in which you can modify the countersink holes to counterbore holes. For this, you can specify various parameters for the counterbore hole in this dialog box. When you exit this dialog box, all the six countersink holes will be modified into counterbore holes. The second editing operation will open the **Circular Pattern** dialog box. In this dialog box, you can change the number of instances to eight, refer to Figure 7-2.




Figure 7-1 Part with six countersink holes





Figure 7-2 Modified part with counterbore holes

Similarly, you can also edit work features or sketches of the sketched features. The features created using the work features will be modified automatically when you edit the work features. For example, if you have created a feature on a work plane that is at an offset of 100 mm, the feature will be automatically repositioned on the change in the offset value of the work plane. In Autodesk Inventor, all the editing operations are performed using the **Browser Bar**.

Editing Features of a Model

As mentioned earlier, all editing operations are performed using the **Browser Bar**. To edit a feature, select it in the **Browser Bar**; the selected feature will be highlighted in the model. Right-click on the selected feature in the **Browser Bar** to display a shortcut menu. Next, choose **Edit Feature** from it, refer to Figure 7-3. Depending on the feature selected for editing, a dialog box will be displayed. For example, if you right-click on an extruded feature, the **Extrude** dialog box will be displayed. Also, the feature selected to edit will be highlighted in bold in the **Browser Bar**. The dialog box will also have the sequence number of the feature. This means if you right-click on the first extruded feature in a model to display a shortcut menu and then choose **Edit Feature**; the **Extrude : Extrusion1** dialog box will be displayed, refer to Figure 7-4.



*Figure 7-3 Choosing the **Edit Feature** option from the shortcut menu*




Figure 7-4 The **Extrude : Extrusion1** dialog box for editing an extruded feature

You can perform the required editing operations using this dialog box. These operations include reselecting the sketch to be extruded, modifying the taper angle, changing the type of operation, and so on. Similarly, if you right-click on a hole feature and then choose **Edit Feature** from the shortcut menu, the **Hole : Hole1** dialog box will be displayed, as shown in Figure 7-5. You can also edit a hole feature by right-clicking on the hole feature in the **Browser Bar** and then choosing the **Show Dimensions** option from the shortcut menu; the hole with all its dimensions will be displayed in the drawing window. Double-click on the diameter dimension; the **Hole Dimensions** dialog box will be displayed, as shown in Figure 7-6. The options in this dialog box will be available depending on whether the hole type is drill, countersink, counterbore, or spotface. Figure 7-6 shows the **Hole Dimensions** dialog box for a counterbore hole.

You can also edit the features (extrusion, revolve feature, hole, fillet, chamfer, and work features) using the mini toolbar. To do so, select the required feature in the graphics window or from the **Browser Bar**; the corresponding mini toolbar will be displayed. Choose the required editing option from the mini toolbar to edit the feature.




Figure 7-5 The **Hole : Hole1** dialog box for editing the hole feature




Figure 7-6 The **Hole Dimensions** dialog box

Updating Edited Features

If you edit a feature using the **Browser Bar**, you do not have to update the feature to view the effect of the editing operation. This is because as soon as you exit the editing operation, the feature will be automatically updated. However, if you modify the feature using dimensions, you will have to update the feature manually. Until the feature is updated after editing, it will not display the modified values. To update the feature with the modified values, choose the **Local Update** button in the **Quick Access Toolbar**. This button will be activated when you modify the dimensions of any features.

Editing Features Dynamically by Using 3D Grips

Dynamic editing is a concept introduced in Autodesk Inventor. Using dynamic editing, you can edit the extruded, revolved, or swept features dynamically. To invoke this editing tool, right-click on the feature in the **Browser Bar** or in the graphics window and then choose **3D Grips** from the shortcut menu; the original sketch of the feature will be displayed. The feature will be displayed in wireframe, and all its dependable features will become transparent. You will notice that small circles are displayed on all the faces of the model except the one that lies on the sketching plane. These small circles will also be displayed on all the edges that are normal to the sketching plane, refer to Figure 7-7. This figure shows a rectangular block after invoking 3D grips.




Figure 7-7 *Editing of a block using 3D grips*

To edit the feature, move the cursor over the circle on any face or edge. If you move the cursor over the circle on a face, an arrow normal to the face will be displayed on the circle. Press and hold the left mouse button at that point and then drag the cursor; the feature will be resized along the normal of that face. Figure 7-8 shows the model, being resized normal to the front face. The value by which the feature will be resized is displayed on the right of the cursor.

If you move the cursor on the circles displayed on the edges of the feature and drag, the feature will be simultaneously modified along the X and Y directions of the sketch, as shown in Figure 7-9.




Figure 7-8 *Resizing the feature normal to a plane*




Figure 7-9 Resizing the feature using an edge

The values by which the feature will be resized along the X and Y axes are displayed on the right of the cursor.

After dynamically editing the feature using 3D grips, right-click in the graphics window and choose **Done** from the shortcut menu. Note that the model will be updated only after you choose the **Done** option.

Editing the Sketches of Features Autodesk Inventor also provides you with the flexibility of editing sketches of the sketched feature. You can add additional entities to a sketch or remove some of the entities from it. Once you have made necessary changes, you just have to update the sketched feature using the **Local Update** button in the **Quick Access Toolbar**. However, you have to make sure that the sketch after editing remains a closed loop. In case the sketch is not a closed loop, the **Autodesk Inventor Professional - Exit Sketch Mode** message box will be displayed. It will show an error message that the loop could not be repaired after editing.

To edit the sketch of a sketched feature, right-click on the sketch in the **Browser Bar** to display a shortcut menu. In this shortcut menu, choose **Edit Sketch**; the sketching environment will be activated. Once you have made the necessary changes, choose the **Local Update** button from the **Quick Access Toolbar**.

Dynamically Moving and Rotating Features In Autodesk Inventor, you can also move and rotate the extruded, revolved, or swept features dynamically. To do so, right-click on the extruded, revolved, or swept feature in the **Browser Bar** and then choose **Move Feature** from the shortcut menu displayed; the **3D Move / Rotate** mini toolbar will be displayed, as shown in Figure 7-10. Also, a triad will be displayed on the model, as shown in Figure 7-11. Depending on where you click on the triad, you can move or rotate the model as required. The details of using this triad to move or rotate the model are discussed in the next section. Note that, in case, the **3D Move / Rotate** mini toolbar is not displayed on choosing **Move Feature** from the shortcut menu, then you need to right-click on the object and choose **Triad Move** from the shortcut menu.



Figure 7-10 The 3D Move / Rotate mini toolbar

Moving a Selected Feature

The triad allows you to move the feature along the direction of the specified axis in a specified plane or in 3D. The methods of moving a feature are discussed next.

Moving the Feature along the Direction of the Selected Axis To move the feature along the direction of a specified axis, choose the **Reposition Triad** tool from the mini toolbar. Next, move the cursor over the arrowhead of that axis of the triad; it will be highlighted, as shown in Figure 7-12. Make sure you do not drag the cursor over the axis because that will rotate the model. Select the arrowhead when it is highlighted; the edit box of the selected direction will be enabled in the **3D Move / Rotate** mini toolbar. You can enter the exact value in it and choose **OK**. You can also drag the mouse to move the feature in the selected direction and then right-click in the drawing window. Next, choose **Done** from the shortcut menu.




Figure 7-11 Triad displayed on the model




Figure 7-12 Selecting the Y axis to move the feature

Tip. You can modify the default snap value for moving or rotating a feature dynamically. To do so, choose **Document Settings** from the **Tools** tab of the **Ribbon**; the **Document Settings** dialog box will be displayed. In the dialog box, choose the **Modeling** tab and modify the values in the **Distance Snap** and **Angle Snap** edit boxes.

Moving the Feature in a Selected Plane To move the feature in a specified plane, select one of the planes displayed in the triad, as shown in Figure 7-13; the related edit boxes will be enabled in the **3D Move / Rotate** mini toolbar. To move the feature dynamically in the selected plane, you can enter the exact values in the edit boxes or drag the mouse. Next, choose **OK** from the dialog box to execute the editing operation.

Moving the Feature Freely in 3D Space To move the feature in 3D space, select the sphere of the triad, as shown in Figure 7-14; the edit boxes of all the three axes will be enabled in the **3D Move / Rotate** mini toolbar. To move the feature dynamically in 3D Space, you can enter the exact values in the edit boxes or drag the mouse. Next, choose **OK** to exit the **3D Move / Rotate** mini toolbar.




Figure 7-13 Selecting a plane to move the feature




Figure 7-14 *Selecting the sphere to move the feature freely in 3D space*

Rotating a Selected Feature

You can rotate the selected feature about any of the three axes of the triad. To rotate the feature, move the cursor over any one of the triad axes; the axis will be highlighted, as shown in Figure 7-15. Select the axis at this stage; the edit box corresponding to the selected axis will be enabled in the **3D Move / Rotate** mini toolbar. You can enter the exact value of rotation in the edit box or drag the mouse to rotate the feature dynamically. Choose **OK** from the mini toolbar to complete the editing operation. Figure 7-16 shows a model with the top cut feature at its default orientation and Figure 7-17 shows the same model after rotating the feature.




Figure 7-15 Selecting an axis to rotate the feature




Figure 7-16 Original orientation of the feature




Figure 7-17 Feature after rotation

Redefining the Sketching Plane of a Sketched Feature

Sometimes, you may need to relocate a feature drawn on one of the planes to another plane. For example, you may need to relocate a cylinder drawn on the XY plane to the YZ plane. Autodesk Inventor allows you to relocate features on other planes by redefining the sketching plane. After redefining it, the necessary changes are automatically made in the orientation of the model. For example, a cylinder drawn on the XY plane stands vertically. However, the same cylinder drawn on the YZ plane lies horizontally. You can select work planes in the graphics window. Alternatively, you can expand the **Origin** tab in the **Browser Bar** and then choose the desired plane in which you want the model to be reoriented.

To redefine the sketching plane of a sketched feature, click on the plus sign (+) located on the left of the sketched feature in the **Browser Bar**; the name of the sketch of the corresponding feature will appear below it in the **Browser Bar**. Right-click on the sketch and choose **Redefine** from the shortcut menu; you will be prompted to select a work plane or planar face to redefine the sketch. Select

the new work plane or planar face for the sketched feature; the sketch of the feature will be relocated on the new plane and the model will reorient, based on the new parameters. Also, all the features created with reference to the current features will be updated automatically.

Figure 7-18 shows a model with the base feature created on the XY plane. Figure 7-19 shows the model after redefining the sketching plane of the base feature to the YZ plane. Notice that the base feature and all other features in the model are reoriented based on the new sketching plane.




Figure 7-18 Base feature created on the XY plane




Figure 7-19 Model after redefining the sketching plane of the base feature to the YZ plane

Note

If one or more features of a model do not get relocated after you redefine the sketching plane, a message box will be displayed, informing about the features that are not resolved.

SUPPRESSING AND UNSUPPRESSING THE FEATURES SOMETIMES, THERE MAY BE A SITUATION WHERE YOU WANT THAT SOME OF THE FEATURES SHOULD NOT SHOW UP IN THE DRAWING VIEWS OF THE MODEL OR IN THE PRINTOUT OF THE MODEL. IN ANY OF THE NON-FEATURE BASED SOLID MODELING TOOLS, YOU WILL HAVE TO EITHER DELETE THE FEATURE OR CREATE IT AFTER TAKING THE PRINTOUT. HOWEVER, IN AUTODESK INVENTOR, YOU CAN SIMPLY SUPPRESS THE FEATURE NOT REQUIRED. ONCE THE FEATURE IS SUPPRESSED, IT WILL NEITHER BE DISPLAYED IN THE DRAWING VIEWS NOR IN THE PRINTOUT OF THE MODEL. REMEMBER THAT IN SUCH CASES THE FEATURES ARE NOT DELETED, THEY ARE TEMPORARILY TURNED OFF. NOTE THAT ALL THE FEATURES THAT ARE DEPENDENT ON THE FEATURE THAT YOU SELECT ARE ALSO SUPPRESSED. TO SUPPRESS A FEATURE, RIGHT-CLICK ON IT IN THE **BROWSER BAR** AND THEN CHOOSE **SUPPRESS FEATURES** FROM THE SHORTCUT MENU.

Note

*All features that are suppressed will be displayed in light gray color in the **Browser Bar**. Also, they will have a line that will strike through the name of the feature in the **Browser Bar**.*

Tip. After generating the drawing views of the current model, if you suppress any feature in the model, it will not be displayed in the drawing views. However, as soon as you unsuppress the feature, it will be displayed in the drawing views.

The suppressed features can be resumed in the model. To do so, right-click on the suppressed feature in the **Browser Bar** to display the shortcut menu. In this shortcut menu, choose **Unsuppress Features**; the selected feature will be displayed in the model again.

EDITING OF A FEATURE USING THE DIRECT TOOL RIBBON: 3D MODEL > MODIFY > DIRECT ONE OF THE UNIQUE FEATURES OF AUTODESK INVENTOR IS ITS ABILITY TO LET YOU MOVE, SIZE, ROTATE, OR DELETE A SELECTED FACE OR FEATURE OF A MODEL. THIS FEATURE IS EXTENSIVELY USED WHEN YOU EDIT AN IMPORTED MODEL. TO MOVE A FACE OF A MODEL, CHOOSE THE **DIRECT** TOOL FROM THE **MODIFY** PANEL IN THE **3D MODEL** TAB; A MINI TOOLBAR WILL BE DISPLAYED, AS SHOWN IN FIGURE 7-20. THE TOOLS IN THE MINI TOOLBAR ARE DISCUSSED NEXT.



*Figure 7-20 The mini toolbar on choosing the **Direct** tool*

Move

The **Move** tool is chosen by default. As a result, you will be prompted to select the face or solid to be moved. Select the face to be moved; a triad will be displayed on the selected face. Drag the triad to move the face, as shown in Figure 7-21. You can align the direction of the triad by using the **Align Triad to Geometry** button in the mini toolbar. To do so, select the required direction from the model; the triad will be aligned to the selected direction. You can choose the **Measure From** and **Snap To** tools from the mini toolbar. The **Measure From** tool is used for controlling the start location for the distance by selecting existing geometry as a reference and the **Snap To** tool is used for maintaining the alignment with other geometry. After specifying the required options in the mini toolbar, you need to choose the **Apply** button from the mini toolbar.

Size

Using the **Size** tool, you can scale the size of the selected face. To scale the size of the face, choose the **Size** tool; you will be prompted to select the face to be scaled. Select the required face; a triad will be displayed, as shown in Figure 7-22. To scale the selected face in the particular direction, drag the triad in that direction. Alternatively, specify the value in the edit box. After specifying the required options in the mini toolbar, you need to choose the **Apply** button.




Figure 7-21 Selected face moved along the Z-axis




Figure 7-22 Scale the size of the selected faces

Scale

Using the **Scale** tool, you can scale




Figure 7-23 Preview of the scaled body

a body or multibodies. To scale the size of a solid body, choose the **Scale** tool; you will be prompted to select the solid body to be scaled. Also the **Solids** button will get automatically selected. Select the desired body; a triad will be displayed. Now, drag the triad in the desired axis or enter the values in the edit box; the solid body will be scaled accordingly and its preview will be displayed, refer to Figure 7-23. You can set a new desired location for triad by using the **Locate** tool. Also, you can scale the selected body uniformly or non-uniformly by using the **Uniform** or **Non-Uniform** button, respectively. After specifying the required options in the mini toolbar, you need to choose the **Apply** button from the mini toolbar.

Rotate

Using the **Rotate** tool, you can rotate the selected face of a model as well as you can also rotate a solid body at an angle. To rotate a face, choose the **Rotate** tool; you will be prompted to select the face to be rotated. Select the required face; a triad will be displayed on it. Drag the triad to rotate the face, refer to Figure 7-24. You can also rotate the selected face in the direction other than the default one. To do so, choose the **Align Triad to Geometry** button; you will be prompted to select an edge or point. Select the required edge; the triad will be aligned to the selected edge. Now, drag the required axis of the triad. The selected face will be rotated in the required direction. Alternatively, specify the value of rotation angle in the edit box displayed in the preview and then choose the **Apply** button.

Delete

Using the **Delete** tool, you can delete the selected face. To delete the face, choose the **Delete** tool; you will be prompted to select the face to be deleted. Select the required face; the selected face will be highlighted with a preview of the deleted face, as shown in Figure 7-25. Next, choose the **Apply** button to delete the face.




Figure 7-24 The face being rotated





Figure 7-25 Preview of the deleted face

DELETING FEATURES



*Figure 7-26 The **Delete Features** dialog box*

You can delete all unwanted features from a model. To do so, right-click on the feature to be deleted in the **Browser Bar**; a shortcut menu is displayed. Choose the **Delete** option from the shortcut menu; the **Delete Features** dialog box will be displayed, as shown in Figure 7-26. This dialog box will prompt you to specify whether or not you want to delete the dependent features and sketches. The options that you can select for deleting include the sketch of the feature, the dependent sketches and features, and the dependent work features. The options that are not applicable to the selected feature will be disabled in this dialog box. For example, if you delete a feature that does not have any work feature created with reference to it, the last option in the **Delete Features** dialog box will be disabled.

COPYING AND PASTING FEATURES

Autodesk Inventor allows you to copy and paste a sketch-based feature from the current file to any file or at some other place in the same file. However, the method of copying a feature in Autodesk Inventor is different from that in the other solid modeling tools. To copy a feature, right-click on its name in the **Browser Bar** and then choose **Copy** from the shortcut menu. Note that this option will be available only for the sketch-based features and not for other features. Now, to paste the feature in another file, open it. Else, open any other existing file. Right-click in the drawing window to display the Marking menu and then choose **Paste** from it; the **Paste Features** dialog box will be displayed, as shown in Figure 7-27, and the dynamic preview of the feature will be displayed in the drawing window. The copied feature will be pasted in the graphics window.

By default, the feature will be attached to any planar face in the model. However, you can attach the feature to the desired face using the options in the **Paste Features** dialog box. The options in this dialog box are discussed next.




Figure 7-27 The Paste Features dialog box

Paste Features

This drop-down list is used to select the option for pasting the features. By default, the **Selected** option is selected in this drop-down list. As a result, only the selected feature will be pasted and the features that are dependent on the selected features will not be pasted. However, if you want to paste all the dependent features, select **Dependent** from this drop-down list.

Parameters

You can select the required option from this drop-down list to specify whether the parameters of the feature are to be independent or dependent.

Name

This column displays the plane on which the feature will be pasted. When you invoke the **Paste Features** dialog box, by default the feature will be temporarily pasted on any plane. As you move the mouse on any plane, the feature will be temporarily snapped to that plane. You can view all this in the dynamic preview of the feature on the model. Once you select the plane on which the feature should be pasted, the dynamic preview will fix to that plane. You can select a plane by expanding the **Origin** tab in the **Browser Bar**. You can also change the orientation of the feature anytime during the operation by changing the plane using the **Plane 1** option. To do so, choose the **Plane 1** option under the **Name** column in the **Paste Features** dialog box and then select the required orientation. Until you select the plane to paste the feature, an icon will be displayed on the left of the profile plane in this column. This icon will display an arrow on the face of a box. This suggests that you have not selected the plane for placing the feature. When you select any plane, this icon is replaced by a box that has a check mark, suggesting that the plane for placing the feature has been selected. In case you want to change the plane for the feature placement, click on **Profile Plane** in this column and then select the required plane.

Angle

This column is used to specify the angle by which the pasted feature can be rotated. The preview of the feature will be dynamically rotated through the specified angle.

Refresh

The **Refresh** button will be active only after you have selected a plane for pasting the feature. This button is chosen to refresh the feature such that it adjusts to the selected plane. For example, if a feature has a dependent feature that is cut using the **All** option, a preview of the model will display the cut feature extending beyond the plane on which the feature is pasted, refer to Figure 7-28. However, when you choose the **Refresh** button, the cut feature will be adjusted such that it is not extended beyond the selected plane, refer to Figure 7-29.




Figure 7-28 Preview of the dependent cut feature extending beyond the selected plane




Figure 7-29 Preview of the dependent cut feature adjusted to fit the plane

Finish

The **Finish** button is used to paste the required feature on the selected face. The paste operation completes only after you have chosen this button. Figure 7-30 shows a model with the original cut feature and the dependent cut feature and Figure 7-31 shows the model after copying the original cut feature and the dependent cut feature on two different planes.




Figure 7-30 Model with the original cut feature and the dependent cut feature




Figure 7-31 Cut features copied on two different planes of the model

Note

You can also shift or reorient the position of a feature on the selected face using the symbols provided on the pasted feature. To do so, move the cursor over the plus symbol; it will turn red, as shown in Figure 7-32. Drag the mouse to the new location and place the feature by clicking the mouse button. You can also dynamically rotate the pasted feature. To do so, move the cursor over the circular symbol; it will turn red, as shown in Figure 7-33. Drag the mouse; the feature will rotate accordingly. To place the feature, release the mouse button.



Figure 7-32 Active Plus symbol



Figure 7-33 Active Circular symbol

MANIPULATING FEATURES BY EOP

The **End of Part** marker is usually available at the end of the **Browser Bar**. In Autodesk Inventor, you can manipulate the display of features by manually dragging the **End of Part** marker in the **Browser Bar**. In Autodesk Inventor, you can also manipulate the features of the solid model by right-clicking on the **End of Part** and choosing the required option from the shortcut menu displayed, refer to Figure 7-34. If you choose **Move EOP to Top**, the **End of Part** marker will move upward in the **Browser Bar** and nothing will be displayed in the Graphics window. If you select **Move EOP to End**, the **End of Part** marker will be displayed at the end of the **Browser Bar** and all features will be displayed in the Graphics window. If you choose **Delete All Features Below EOP**, all the features below the **End of Part** marker will be deleted. You can also move **End of Part** marker directly under the selected features. To do so, right-click on a feature in the **Browser Bar** and then choose **Move EOP Marker** from the shortcut menu; the **End of Part** marker will be displayed below that feature in the **Browser Bar**. Note that **Delete All Features Below EOP** option is not available when the **End of Part** marker is located at the bottom of the **Browser Bar**.




Figure 7-34 Options available in the shortcut menu

ADDING AUTOMATIC DIMENSIONS TO SKETCHES RIBBON: SKETCH > CONSTRAIN > AUTOMATIC DIMENSIONS AND CONSTRAINTS

Autodesk Inventor allows you to add dimensions and constraints automatically. Note that if you cannot apply all dimensions and constraints required in a sketch. The

dimensions are used in association with the general dimensions to fully constrain the sketch. In Autodesk Inventor, automatic dimensions are added using the **Automatic Dimensions and Constraints** tool. When you invoke this tool, the **Auto Dimension** dialog box will be displayed, as shown in Figure 7-35. The options in this dialog box are discussed next.




Figure 7-35 The *Auto Dimension* dialog box

Curves

The **Curves** button is chosen to select the sketch for applying automatic dimensions. By default, the complete sketch is selected to be dimensioned. As a result, all the entities in the sketch are dimensioned. However, if you want to add automatic dimensions to some of the selected entities, choose this button and then select the required entities from the graphics window. The selected entities will be highlighted in blue. Choose the **Apply** button to apply the automatic dimensions to the selected entities of the sketch.

Dimensions Required

The **Dimensions Required** display box will display the number of dimensions that are required to fully constrain the sketch. You cannot modify the value in this box.

Dimensions

The **Dimensions** check box is selected to add automatic dimensions to the sketch. If this check box is cleared, the dimensions will not be added to the sketch.

Constraints

The **Constraints** check box is also selected to add constraints to the sketch while applying the automatic dimensions. If this check box is cleared, the constraints will not be added.

*Tip. You can use the **Automatic Dimensions and Constraints** tool to verify if the sketch you have drawn is fully constrained or not. After adding all the required dimensions and constraints, invoke this tool. On doing so, the Auto Dimension dialog box will be displayed. If this dialog box shows 0 dimensions required, the sketch is fully constrained.*

Apply

The **Apply** button is chosen to apply the automatic dimensions to the selected sketch. Invoke the **Auto Dimension** dialog box and then choose this button to add the dimensions. Note that until this button is chosen, the automatic dimensions will not be applied to the sketch.

Remove


The **Remove** button is chosen to remove the automatic dimensions from the sketch.

Done

The **Done** button is chosen to exit the **Auto Dimension** dialog box.

PROJECTING ENTITIES IN THE SKETCHING ENVIRONMENT

Autodesk Inventor allows you to project the edges of an existing feature to a sketching plane while drawing the sketches. The projected edges are converted into sketched entities and can be used as a part of the sketch. You can project the selected edge or face of a feature, or project the part of the model that is cut by the sketching plane. You can project the entities using various tools available in the **Project Geometry** drop down. To invoke this drop down, choose the down arrow available below the **Project Geometry** button of the **Create** panel in the **Sketch** tab, refer to Figure 7-36. The tools available in the **Project Geometry** drop-down are discussed next.



*Figure 7-36 Tools in the **Project Geometry** drop-down*

Projecting Edges or Faces

Ribbon: Sketch > Create > Project Geometry drop-down > Project Geometry

You can project the selected edges or faces of a feature on a sketching plane by choosing the **Project Geometry** tool from the **Create** panel of the **Sketch** tab, refer to Figure 7-36. On invoking this tool, you will be prompted to select an edge, vertex, work geometry, or sketch geometry to be projected. If you move the cursor over a face, it will be highlighted. Similarly, if you move the cursor over an edge, it will be highlighted. Select the geometry to be projected; the selected geometry will be projected on the current sketching plane as the sketched entity. Figure 7-37 shows a model in which a sketching plane is defined at the center of the model. Figure 7-38 shows the model after projecting the spline edge.




Figure 7-37 Sketching plane at the center of the model




Figure 7-38 Model after projecting the spline edge

Projecting Cutting Edges

Ribbon: Sketch > Create > Project Geometry drop-down > Project Cut Edges

The cutting edges are meant to define the contour of the model that is created when you define a sketching plane on the face of a model or inside the model. When you define a sketching plane inside the model, it cuts the model, thus forming cutting edges. You can project these cutting edges by choosing the Project Cut Edges tool from the Create panel of the Sketch tab, refer to Figure 7-36. As soon as you choose this tool, the edges that are cut by the sketching plane will be projected. Figure 7-39 shows a model and the sketching plane cutting through it and Figure 7-40 shows the sketch after projecting the cutting edges.




Figure 7-39 Sketch plane at the center of the model




Figure 7-40 Sketch after projecting the cutting edges

Note The models shown in Figures 7-39 and 7-40 are created using the **Loft** tool.

This tool is discussed in the next chapter.

Projecting 2D Sketch on a 3D Face Ribbon: Sketch > Create >

Project Geometry drop-down > Project to 3D Sketch  With the introduction of the **Project to 3D Sketch** tool in Autodesk Inventor, you can now project a 2D sketch onto a 3D face. To do so, invoke the **Project to 3D Sketch** tool; the **Project to 3D Sketch** dialog box will be displayed. In this dialog box, the **Faces** button is activated by default. If it is not activated by default, then select the **Project** check box; the **Face** button will be activated. If you move the cursor over the faces of the model, they will be highlighted. Select the faces on which you want to project the 2D sketch; the sketch will be projected on the selected faces. You can also see the preview of the projection while the **Project to 3D Sketch** dialog box is active. You can choose more than one face for the 2D sketch to be projected. On doing so, the sketch to be projected will be wrapped around the face of the model and it will take the shape of the face. Figure 7-41 shows the sketch to be projected and Figure 7-42 shows the model after the sketch is projected.

Note You can invoke the **Project to 3D Sketch** tool only in the Sketching environment.




Figure 7-41 Sketch plane with a 2D sketch to be projected on the circular face of the model




Figure 7-42 Model after projecting a zig-zag sketch

Projecting DWG Geometry

Ribbon: Sketch > Create > Project Geometry drop-down > Project DWG Geometry **You can project a DWG geometry by using the Project DWG Geometry tool from the Create panel of the Sketch tab, refer to Figure 7-36. On invoking this tool, you will be prompted to select a DWG line, arc, polyline or other single geometry. Select the geometry that you want to project by choosing the corresponding option from the mini toolbar; the selected geometry will be projected on the sketching plane or face. Figure 7-43 shows the geometry to be projected by using the Projecting Single Geometry option and Figure 7-44 shows the model after the geometry is projected.**




Figure 7-43 Sketch plane with a DWG geometry to be projected on the selected face





Figure 7-44 Model after projecting a DWG geometry

TUTORIALS TUTORIAL 1

In this tutorial, you will create the model of the Gear-Shifter Link shown in Figure 7-45. Its views and dimensions are shown in the same figure. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- a. Create the base feature, which is a reverse C-like feature. Its sketch will be created on the XZ plane and extruded using the **Symmetric** option, see Figure 7-46.
- b. Define a new sketch plane on the XZ plane and add the first join feature to the circular face of the base feature, refer to Figure 7-49.
- c. Again, define a new sketch plane on the XZ plane and draw the sketch for the second join feature. Extrude this feature using the **Symmetric** option, refer to Figure 7-51.
- d. Define a new sketch plane on the front face of the second join feature and draw the sketch for the cut feature. Extrude this sketch using the **Cut** operation, refer to Figure 7-53.
- e. Suppress all features, except the base feature, and then define a work plane at an offset of 17.5 mm from the left face of the base feature. Draw the sketch for the third join feature and extrude it using the **Symmetric** option, refer to Figure 7-55.
- f. Add fillet to the third join feature, refer to Figure 7-57.
- g. Suppress the last two features and create the slots and hole on the front face of the base feature, refer to Figure 7-59.
- h. Finally, unsuppress all features to complete the model, refer to Figure 7-61.






Figure 7-45 Views and Dimensions for Tutorial 1

Creating the Base Feature

1. Start a new metric standard part file and then draw the sketch of the base feature on the XZ plane, as shown in Figure 7-46.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.
 2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.
2. Exit the sketching environment and then extrude the sketch to a distance of 55 mm using the **Symmetric** option. The base feature of the model is shown in Figure 7-47.




Figure 7-46 Sketch of the base feature




Figure 7-47 Base feature of the model

Creating Curved Features

As the base feature was created on the XZ plane and was extruded using the **Symmetric** option, you can create the sketches for the curved features on the same plane and then extrude them as required using the **Symmetric** option.

1. Draw the sketch of the curved feature on the XZ plane. Add the required constraints and dimensions to it. The sketch of the first join feature after applying all dimensions and constraints is shown in Figure 7-48.
2. Exit the sketching environment and then extrude the sketch of the first join feature to a distance of 12 mm using the **Join** operation. Use the **Symmetric** option for creating the feature. The isometric view of the model is shown in Figure 7-49.
3. Draw the sketch of the second join feature on the XZ plane, as shown in Figure 7-50. After drawing the sketch, apply the **Concentric** and **Equal** constraints to it and to the existing feature.




Figure 7-48 Sketch of the first join feature




Figure 7-49 The isometric view of the model

Note

You can use the **Slice Graphics** option for slicing a feature to create the sketch of the second join feature. This option can be invoked from the **Marking** menu that is displayed when you right-click in the graphics window in the sketching environment. Alternatively, press the **F7** key to slice graphics.

- Exit the sketching environment and then extrude the sketch to a distance of 18 mm using the **Join** operation and the **Symmetric** option, see Figure 7-51.




Figure 7-50 Sketch of the second join feature in the wireframe display




Figure 7-51 Model after creating the second join feature

- Specify a new sketch plane on the front face of the second join feature and then create the sketch of the cut feature on this plane. If required, you can project the existing sketch. You can offset and dimension the reference entities to create the sketch of the cut feature, as shown in Figure 7-52.
- Exit the sketching environment and then click on the sketch; a mini toolbar is

displayed.

7. Choose the **Create Extrude** button from the mini toolbar; the **Extrude** dialog box along with the modified mini toolbar is displayed.
8. Click inside the sketch created for the cut feature and then choose the **Cut** option from the **Operation** area of the mini toolbar.
9. Select the **All** option from the **Extents** area and then choose **OK** from the mini toolbar; the cut feature is created, as shown in Figure 7-53.

Suppressing Features

As mentioned earlier, in a complex model, it is better to suppress the features not required while creating a particular feature. After creating all the features, you can unsuppress the suppressed features. In Autodesk Inventor, the features are suppressed using the **Browser Bar**.




Figure 7-52 Sketch of the cut feature




Figure 7-53 Model after creating the cut feature

1. Right-click on **Extrusion2** (first join feature) in the **Browser Bar** to display a shortcut menu.
2. Choose **Suppress Features** from the shortcut menu displayed; the **Autodesk Inventor Professional-Suppress Feature** dialog box is displayed. Also, the first join feature is no more visible. However, the second join feature and the cut feature remain visible on the model.
3. Choose **Accept** from the **Autodesk Inventor Professional - Suppress**

Feature dialog box. Now, right-click on **Extrusion3** (second join feature) in the **Browser Bar** and then choose **Suppress Features** from the shortcut menu displayed to suppress the second join feature and the cut feature.

The only feature that is visible now is the base feature of the model.

Creating the Third Join Feature The third join feature is created on an offset work plane. This work plane will be at an offset distance of -17.5 mm from the left face of the base feature. The negative value will make sure that the work plane is offset inside the model.

1. Choose the **Offset from Plane** tool from **3D Model > Work Features > Plane** drop-down and define a new work plane at an offset of -17.5 mm from the left face of the base feature. Create the sketch for the third join feature on the new plane.
2. Create a circle inside the sketch so that when you extrude the sketch, a hole is also created, see Figure 7-54.
3. Extrude the sketch to a distance of 8 mm using the **Join** operation and the **Symmetric** option. If the **Autodesk Inventor** warning window is displayed, choose **Accept** from it. The model after creating the third join feature is displayed in Figure 7-55.

Creating the Fillet Feature on the Third Join Feature 1. Invoke the **Fillet** tool from the Marking menu.




Figure 7-54 Sketch for the third join feature




Figure 7-55 Model after creating the third join feature

2. Select the **Loop** radio button from the **Select mode** area and enter **1** in the **Radius** edit box; you are prompted to select the loop on the model.
3. Select the loop on the third join feature of the model, as shown in Figure 7-56. Next, choose **OK** from the **Fillet** dialog box; the fillet feature is created, as shown in Figure 7-57.




Figure 7-56 Loop selected for creating the fillet




Figure 7-57 Model after creating the fillet on the third join feature

Suppressing the Third Join Feature 1. Right-click on **Extrusion5** (third join feature) in the **Browser Bar** to display a shortcut menu. Choose **Suppress Features** from the shortcut menu; the fillet feature is suppressed because it is dependent on the third join feature. Now, the only visible feature is the base feature.

Creating Slots and the Hole

In this section, the slots will be created on the front face of the base feature. As both the slots will be cut to the same distance, you can draw the sketch for both the slots together and then extrude them using the **Cut** operation.

1. Define a new sketch plane on the front face of the base feature.
2. Draw the sketch for both slots, as shown in Figure 7-58.
3. Invoke the **Extrude** tool and then create the slots of depth 8 mm using the **Cut** operation, as shown in Figure 7-59.




Figure 7-58 Sketch for slots




Figure 7-59 Model after creating slots

4. Create a drilled hole of 2.5 mm diameter on the left face of the slot, refer to Figure 7-60. For the location of the hole, refer to Figure 7-45. The depth of the hole is 4 mm. The model after creating the hole is shown in Figure 7-61.

Note

The orientation of the models in Figures 7-59 and 7-60 has been changed using the ViewCube for clarity and better understanding.

Unsuppressing Features

Once all the features of the model have been created, you can unsuppress the suppressed features and save the model. As you know, all the suppressed features will be displayed in light gray color and will have a line striking out their names in the **Browser Bar**.

1. Right-click on **Extrusion2** (first join feature) in the **Browser Bar** and then choose **Unsuppress Features** from the shortcut menu displayed.

If the Autodesk Inventor encounters an error while updating the features, the **Autodesk Inventor Professional - Unsuppress Feature** dialog box is displayed. Choose **Accept** from the dialog box displayed; the second join feature is unsuppressed.

2. Similarly, unsuppress the remaining suppressed features. Choose **Accept** in the **Autodesk Inventor Professional -Unsuppress Feature** dialog box, whenever it is displayed. The final solid model of the Gear-shifter link after unsuppressing all the suppressed features is shown in Figure 7-61.

Saving the Model

1. Save the model with the name *Tutorial1* at the location *C:\Inventor_2016/c07* and then close the file.




Figure 7-60 Model after creating the hole




Figure 7-61 Final solid model of the Gear-shifter link

Tutorial 2

In this tutorial, you will create the model shown in Figure 7-62. Its views and dimensions are shown in the same figure. **(Expected time: 45 min)**

the base feature consists of a square with fillets on all four corners.

- b. On the front face of the base feature, create counterbore holes by using the center points of fillets as the center of holes, refer to Figure 7-64.
- c. Suppress the holes and create the cylindrical join feature on the front face of the base feature.
- d. Add two rectangular join features to the cylindrical feature and create the rectangular cut feature on one of the rectangular join features, refer to Figure 7-72.
- e. Create drilled holes by defining the sketch plane on the required planes. Once all features are created, unsuppress the holes on the base feature, refer to Figure 7-74.
- f. Finally, create the fillet of radius 5 mm, refer to Figure 7-74.

Creating the Base Feature

1. Start a new metric part file and then draw the sketch of the base feature on the XZ plane.

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*
2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

The sketch of the base feature will be a square of side 105 mm with all the four corners filleted with a radius of 20 mm.

2. Exit the sketching environment and extrude the sketch to a distance of 12 mm. The base feature of the model is shown in Figure 7-63.

Creating the Holes

The base feature has four counterbore holes. You can create these holes concentric with the cylindrical faces of the fillets at the corners. Alternatively, you can create one of the holes and then create a rectangular pattern for creating the remaining three holes.

1. Invoke the **Hole** tool and then create four counterbore holes using the **Concentric** placement option. Refer to Figure 7-62 for dimensions.

The model after creating the counterbore holes is shown in Figure 7-64.




Figure 7-63 Base feature of the model




Figure 7-64 Model after creating the counterbore holes

Note

*You need to use the **Through All** option from the drop-down list given under the **Termination** area to create through holes.*

Suppressing Holes

As you have created four holes, the **Browser Bar** will display these holes with names **Hole1**, **Hole2**, **Hole3**, and **Hole4**. You need to select all the four holes and suppress them.

1. Press and hold the SHIFT or the CTRL key and select all the four holes from the **Browser Bar**.
2. Right-click on the selected holes in the **Browser Bar** to display a shortcut menu. From the shortcut menu, choose **Suppress Features**; all four holes are suppressed. The only feature that is visible is the base feature.

Creating Cylindrical and Rectangular Join Features 1. Define a new sketch plane on the front face of the base feature and then draw a circle of 44 mm diameter, as shown in Figure 7-65. Exit the sketching environment.

2. Invoke the **Extrude** tool and then extrude the circle to a distance of 96 mm, as shown in Figure 7-66.




Figure 7-65 Sketch for the cylindrical feature




Figure 7-66 Cylindrical feature created

3. Define a new sketch plane on the front face of the cylindrical feature and create the sketch of the first rectangular feature, as shown in Figure 7-67. Exit the sketching environment.

4. Invoke the **Extrude** tool and then extrude the sketch to a distance of 76 mm, as shown in Figure 7-68.




Figure 7-67 Sketch of the first rectangular feature




Figure 7-68 Model after creating the first rectangular feature

5. Similarly, create the sketch of the second rectangular feature and extrude it to a distance of 57 mm, refer to Figures 7-69 and 7-70.




Figure 7-69 Sketch of the second rectangular feature




Figure 7-70 Model after creating the second rectangular feature

Creating the Cut Feature and Holes 1. Define a new sketch plane on the front face of the cylindrical feature and then create a rectangular cut feature of depth 50 mm, refer to Figures 7-71 and 7-72.




Figure 7-71 Sketch of the rectangular cut feature




Figure 7-72 Model after creating the rectangular cut feature

2. Create a hole of 20 mm diameter and 96 mm depth on the front face of the cylindrical feature. The model after creating the hole and the cut feature is shown in Figure 7-73.
3. Similarly, create holes one by one on the faces of the rectangular join features, see Figure 7-73. For the dimensions and location of holes, refer to Figure 7-62.




Figure 7-73 Model after creating holes and the cut feature

Unsuppressing Counterbore Holes 1. From the **Browser Bar**, select all the holes created on the base feature. Right-click on the selected holes and choose **Unsuppress Features** from the shortcut menu displayed; all the counterbore holes will again be displayed on the base feature.

Creating the Fillet and Saving the File 1. Invoke the **Fillet** tool and create a fillet of radius 5 mm on the circular edge created between base feature and the cylindrical join feature. The final model for

Tutorial 2 after unsuppressing the counterbore holes and creating the fillet is shown in Figure 7-74.

2. Save the model with the name *Tutorial2* at the location *C:\Inventor_2016\c07* and then close the file.




Figure 7-74 Final model for Tutorial 2

Tutorial 3

In this tutorial, you will create the model of the body of the Butterfly Valve assembly shown in Figure 7-75. Its views and dimensions are shown in the same figure. After creating the model, modify the location of the curved feature on the top face by changing the dimension 175mm to 200mm. The dimensions of the remaining five instances should also change automatically.




(Expected time: 45 min)

The following steps are required to complete this tutorial:

- a. Create the base feature on the XY plane, refer to Figure 7-76. The sketch of the base feature consists of two circles. These circles will be extruded using the **Symmetric** option.
- b. Define two new offset work planes to create two cylindrical join features on the cylindrical face of the base feature, refer to Figure 7-80.
- c. Add the counterbore hole and three smaller holes on the front face of the second feature, refer to Figure 7-81.
- d. Suppress the second and third features and then create the curved sketch feature with a hole on the top face of the model, refer to Figure 7-82.
- e. Pattern the last feature using the **Circular Pattern** tool. Finally, mirror all three instances of the circular pattern on the bottom face of the model, see

Figure 7-84.

f. After creating the features, edit them as mentioned in the tutorial description; refer to Figure 7-85.






Figure 7-75 Views and dimensions for Tutorial 3

Creating the Base Feature

1. Open a new metric part file and then create the base feature on the XY plane. Take the origin as the center of the two circles in the sketch of the base feature. For the dimensions of circles, refer to Figure 7-75.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.
2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Tip. While creating the sketch for the base feature, it is recommended that you project the origin and then use it to locate the centers of both the circles. The origin is the point at which the X and Y axes meet in the drawing window or the point at which all the three planes meet in the **Part** mode. Now, if the origin is selected as the center of the base feature, you can use the XZ plane to create the offset planes. If the origin is not selected as the center of the base feature, you will have to first create a work plane tangent to the cylindrical face of the base feature and then use it to define the offset work plane.

2. Extrude the sketch to a distance of 225 mm using the **Symmetric** option.



Figure 7-76 Base feature of the model

The advantage of extruding the sketch using the **Symmetric** option is that you can use the XY plane as a plane for mirroring the features on the top face of the model as well as the bottom face of the model. If the base feature is not extruded using the **Symmetric** option, you will have to create a new work plane for mirroring the features. The base feature of the model is shown in

Figure 7-76.

Creating Join Features on the Cylindrical Faces of the Base Feature
Since the base feature was created taking the origin as the center of the circles, you can use the XZ plane to create the offset work plane.

1. Create a new work plane at an offset of -160 mm from the XZ plane. The negative value ensures that the work plane is created toward the front side of the base feature and not toward the back side.
2. Define a new sketch plane on **Work Plane1** and draw the sketch of the first join feature using the origin of the new sketch plane as the center, as shown in Figure 7-77. Refer to Figure 7-75 for the placement and dimensions of the first join feature.
3. Invoke the **Extrude** tool and then extrude the sketch using the **To Next** option from the **Extents** area. The model after creating the join feature is shown in Figure 7-78.




Figure 7-77 Sketch for the first join feature




Figure 7-78 Model after creating the first join feature

4. Similarly, define a new work plane at an offset of 325 mm from **Work Plane1**. Next, create the sketch of the second join feature, as shown in Figure 7-79. Refer to Figure 7-75 for the placement of the second join feature.
5. Invoke the **Extrude** tool and then extrude the sketch using the **To Next** option from the **Extents** area. The model after creating the second join feature is shown in Figure 7-80.




Figure 7-79 Sketch of the second join feature




Figure 7-80 Model after creating the second join feature

Creating the Counterbore Hole and Drilled Holes on the Front Face of the First Join Feature 1. Using the **Concentric** option, create the flat-ended counterbore hole on the front face of the first join feature. Refer to Figure 7-75 for the dimensions and placement of the hole.

2. Create a sketch point on the front face of the first join feature to locate the

hole. Refer to Figure 7-75 for the location of the hole. Invoke the **Hole** tool and create one of the drilled holes. For the dimensions of the hole, refer to Figure 7-75.

3. Create a circular pattern containing three instances of the drilled holes. The model after creating the counterbore hole and the three smaller drilled holes is shown in Figure 7-81.




Figure 7-81 Model after creating the holes

Suppressing Features As the features other than the base feature are not required for creating the remaining features in the model, you can suppress them. This will reduce the complicity of the model and make it easier for you to create the remaining features.

1. Right-click on **Extrusion2** (first join feature) in the **Browser Bar** and then choose **Suppress Features** from the shortcut menu displayed; the first join feature is suppressed.

In this step, you will see that the counterbore hole and the three drilled holes are also suppressed. This is because the holes are created on the first join feature and therefore, are dependent on the first join feature.

2. Similarly, right-click on **Extrusion3** (second join feature) in the **Browser Bar** and then choose **Suppress Features** from the shortcut menu displayed; the second join feature is suppressed.

Creating the Third Join Feature on the Top Face of the Base Feature 1. Define a new sketch plane on the top face of the base feature and draw the sketch of the third join feature; refer to Figure 7-75 for dimensions. Include the circle in the sketch so that the hole is created automatically.

2. Extrude the sketch to a distance of 32 mm. The model after creating the third join feature on the top face of the base feature is shown in Figure 7-82.

Creating the Circular Pattern of the Third Join Feature 1. Create a circular pattern of the third join feature on the top face of the base feature. The model after creating the circular pattern is shown in Figure 7-83.



Figure 7-82 Third join feature created




Figure 7-83 Model after creating the circular pattern

Mirroring the Features on the Bottom Face of the Base Feature As the base feature was extruded using the **Symmetric** option, you can use the XY plane for mirroring the feature on the bottom face of the base feature.

1. Choose the **Mirror** tool and then select the third join feature created on the top face of the base feature and the circular pattern as the features to be mirrored.
2. Mirror the features using the XY plane as the mirror plane and choose **OK**.

- Unsuppressing Features 1. Right-click on **Extrusion2** (first join feature) in the **Browser Bar**. Next, choose **Unsuppress Features** from the shortcut menu displayed; the first join feature and the holes are unsuppressed.
2. Right-click on **Extrusion3** (second join feature) and then choose the **Unsuppress Features** option from the shortcut menu to unsuppress the second join feature also. The model after creating all features is shown in Figure 7-84.




Figure 7-84 Model after creating all features

Modifying the Dimensions of Feature on the Top Face of the Model Out of the three instances of the third join feature on the top face of the model and the three instances on the bottom face, only one was actually sketched. The rest were created either using the **Circular Pattern** tool or using the **Mirror** tool. Therefore, if you modify the original feature, the rest of the features will be automatically modified.

1. Right-click on **Extrusion4** (third join feature) in the **Browser Bar** to display a shortcut menu. From this menu, choose **Show Dimensions**; the basic sketch of the third join feature is displayed along with its dimensions. You can double-click on any dimension to display the **Edit Dimension** toolbar. This toolbar can be used to edit the selected dimension value.
2. Double-click on the dimension 175 mm to display the **Edit Dimension** toolbar and then enter **200** as the dimension value.

On changing the dimension value of the sketch of the third join feature, the sketch gets modified. If feature is not modified, you need to update it by using the **Update** button.

3. Choose the **Update** button from the **Update** panel of the **Manage** tab; all the six instances of the third join feature are automatically modified. The model after editing the feature is shown in Figure 7-85.

Note

While drawing the sketch for the feature modified in the last step, if you do not apply the **Coincident Constraint** between the lower endpoint of the lines of the sketch and the outer circle of the base feature, the feature will get separated from the base feature when you modify it. You can also apply the **Coincident Constraint** between the arc of the sketch and the outer circle of the base feature to avoid separation.




Figure 7-85 Final model after editing the features

4. Save the model with the name *Tutorial3* at the location *C:\Inventor_2016\c07* and then close the file.

Answer the following questions and then compare them to those given at the end of this chapter:

1. If you right-click on the third extruded feature in a model and then choose **Edit Feature** from the shortcut menu, the _____ dialog box will be displayed.
2. The features edited using the dimensions can be updated by choosing the _____ button from the _____.
3. The features in a model can be suppressed by first right-clicking on the feature and then choosing _____ from the shortcut menu displayed.




4. The _____ dialog box is used to paste the copied features in a new file.
5. The _____ button in the **Paste Features** dialog box is used to adjust the preview of the pasted feature on the selected plane.
6. When a feature is suppressed, its _____ features also get suppressed.
7. The _____ toolbar is used to project a face or an edge of an existing object onto a working plane.
8. Most of the designs require editing either during or after their creation. (T/F)
9. In Autodesk Inventor, all the editing operations are performed using toolbars. (T/F)
10. You can edit a hole feature by right-clicking on it in the **Browser Bar** and then choosing **Show Dimensions** from the shortcut menu displayed. (T/F)
11. You can display the dimensions of a feature on a model by double-clicking on the feature in the **Browser Bar**. (T/F)

Answer the following questions:

1. In Autodesk Inventor, you can copy features from one file to the other. (T/F)
2. In Autodesk Inventor, you can edit the sketches of the sketched features. (T/F)
3. When you choose an option from the Browser bar to display the dimensions of a feature for editing, the dimensions will be retained on the screen even after the editing operation is over. (T/F)
4. The feature to be copied can be rotated at any angle. (T/F)
5. After editing the sketch of a feature, you need to make sure that the sketch is still a closed loop. (T/F)
6. You can redefine the sketching plane of a sketched feature. (T/F)
7. You can specify whether or not to delete the dependent sketches and features. (T/F)
8. In the **Paste Features** dialog box, you can specify whether to paste only the selected feature or both the selected feature and the dependent features. (T/F)
9. All suppressed features are displayed in light gray color in the **Browser Bar**. (T/F)
10. If you edit a feature using the **Browser Bar**, you do not need to update it to view the effect of the editing operation. (T/F)

Exercise 1

Create the model of the Slide Bracket shown in Figure 7-86. Its views and dimensions are shown in the same figure. **(Expected time: 45 min)**








Figure 7-86 The model, its views and dimensions

Exercise 2

Create the model shown in Figure 7-87. Its views and dimensions are shown in the same figure. **(Expected time: 45 min)**









Figure 7-87 The model, its views and dimensions

Exercise 3

Create the model shown in Figure 7-88. Its views and dimensions are shown in the same figure. **(Expected time: 45 min)**








Figure 7-88 The model, its views and dimensions

Exercise 4

Create the model shown in Figure 7-89. Its views and dimensions are shown in the same figure. **(Expected time: 45 min)**






Figure 7-89 Views and dimensions of the model

Exercise 5

In this exercise, you will create the model of the Bottom Seat shown in Figure 7-

90a. After creating this model, you will perform the modifications given below. The model after performing the modifications is shown in Figure 7-90b. The views and dimensions of the original model are shown in Figure 7-90c.

1. Change the two holes on the front face of the model to countersunk holes.
2. Change the hole on the right face of the model to counterbore hole.
3. Change the curved pocket feature on the upper face of the model to a rectangular slot.

(Expected time: 45 min)




Figure 7-90a Model of the Bottom Seat




Figure 7-90b Model after performing the modifications




Figure 7-90c Views and dimensions of the original model

Answers to Self-Evaluation Test 1. **Extrude: Extrusion3, 2. Local Update, Quick Access Toolbar, 3. Suppress Features, 4. Paste Features, 5. Refresh, 6. dependent, 7. Project Geometry, 8. T, 9. F, 10. T, 11. T**

Chapter 8

Advanced Modeling Tools-II

Learning Objectives

After completing this chapter, you will be able to:

- ***Create sweep features.***
- ***Create lofted features.***
- ***Create coil features.***
- ***Create internal or external threads.***
- ***Create shell features.***
- ***Apply drafts on the faces of a model.***
- ***Split the faces of a model or a complete model.***
- ***Delete the selected faces of a model.***
- ***Replace the selected faces of a model with surfaces.***
- ***Add surface patches.***
- ***Stitch multiple surfaces to a single surface.***
- ***Create sculpt features.***
- ***Understand the use of sketch doctor and design doctor.***

ADVANCED MODELING TOOLS

The first few advanced modeling tools are discussed in Chapter 6, Advanced Modeling Tools-I. In this chapter, you will learn about the remaining tools.

Figure 8-2 Resulting sweep feature

To create the sweep feature, choose the **Sweep** tool from the **Create** panel of the **3D Model** tab; the **Sweep** dialog box will be displayed, as shown in Figure 8-3. The options in this dialog box are discussed next.

Shape Area

This area is available on the top left corner of the dialog box and has the following buttons:

Profile

The **Profile** button is used to select the profile for the sweep feature. Remember that the profile has to be a closed loop for creating the solid sweep feature. If the profile is not a closed loop, the resulting sweep feature will be a surface. When you invoke the **Sweep** dialog box, the **Profile** button is chosen by default. As a result on invoking this dialog box, you are prompted to select the profile for the sweep feature.




Figure 8-3 The Sweep dialog box

Path

The **Path** button is used to select the path for the sweep feature.

Solids

The **Solids** button is used to select participating solid bodies from multiple bodies. This button will be activated only when there are multiple solid bodies in the graphics window.

Output Area

The buttons in the **Output** area are chosen to specify the type of output of the **Sweep** tool. If the profile selected is closed, the **Solid** button is chosen by default. As a result, a solid sweep feature will be created. If you choose the **Surface** button, the resulting sweep will be a surface feature. The **Surface** button is chosen automatically, if you select an open profile.

Operation Area

This area contains the following buttons:

Join

The **Join** button is the first button provided in the area that is on the right side of the **Shape** area. This button is used to create a sweep feature by adding material to the model.

Cut

The **Cut** button is provided below the **Join** button and is used to create a sweep feature by removing material from the model. If the sweep feature is the first feature, this button will not be activated.

Figure 8-4 shows the profile and path curves and Figure 8-5 shows the sweep features created using the **Join** and **Cut** operations.




Figure 8-4 Profile and path curves created for the sweep feature




Figure 8-5 Join and cut sweep features

Intersect

The **Intersect** button is provided below the **Cut** button and is used only when you have an existing feature. This means that this button will not be activated if the sweep feature is the first feature in the model. This operation is used to create a sweep feature such that the material common to the profile and the existing feature is retained. The remaining material is removed from the model.

Note

*While creating the base feature, the **Join**, **Cut**, and **Intersect** buttons will not be activated in their respective dialog box.*

New solid

This button is chosen by default and is used to create a new solid body. The new solid body is independent of other solid bodies, if present in the part file.

Optimize for Single Selection

If this check box is selected, the next selection step is activated automatically after you complete the first selection. For example, the **Path** button is automatically chosen as soon as you select any one sketch as the profile. If you clear this check box, you can select nested sketches as the profile.

Type Area

The options available in this area allow you to create three types of sweeps: using only the path, using a path and a guide curve, and using a path and a guide surface. The procedure to create all these sweep types is discussed next.

Creating Sweep Features by Using a Path Curve

By default, the **Path** option is selected from the drop-down list in the **Type** area. As a result, the option to create the sweep feature with the path curve is active. This option allows you to create a sweep feature that follows the specified path. You can specify whether the orientation of the profile will be constant to the path or parallel to the sketching plane. The options that are available when you select the **Path** option from the **Type** drop-down list are discussed next.

Path

This radio button is selected by default. It forces the profile to remain constantly oriented to the path at all points.

Parallel

This radio button forces the sketch to remain parallel to the sketching plane throughout the sweep feature.

Figure 8-6 shows the profile and the path to create the sweep feature. Figure 8-7 shows the sweep feature created with the **Path** radio button selected. As evident from this figure, the profile remains oriented to the path throughout the sweep feature. Figure 8-8 shows the sweep feature with the **Parallel** radio button selected. As evident from this figure, the profile is oriented parallel to the sketching plane throughout the sweep feature.




Figure 8-6 Profile and path for the sweep feature




Figure 8-7 Sweep feature created using the **Path** radio button




Figure 8-8 Sweep feature created using the **Parallel** radio button

Taper

This edit box is used to define the taper angle for the sweep feature. A positive taper angle tapers the sweep feature outward and a negative taper angle tapers it inward. Figure 8-9 shows a sweep feature with a positive taper angle and Figure 8-10 shows a sweep feature with a negative taper angle.

You can also create a sweep feature from a profile and a path even if they are non-intersecting. Figure 8-11 shows a path and a profile and Figure 8-12 shows the sweep feature created by using them. Notice that in this figure, the sweep feature has maintained the same distance from the path throughout the sweep.




Figure 8-9 Sweep feature created with a positive taper angle




Figure 8-10 Sweep feature created with a negative taper angle




Figure 8-11 Sweep profile and the path




Figure 8-12 Sweep feature created at a distance from the path

Twist

This edit box is used to define the twist angle for the sweep feature. A positive value of twist angle results in a sweep feature twisted anticlockwise whereas a negative results in a sweep feature twisted clockwise. Figure 8-13 shows a sweep feature with a positive twist angle and Figure 8-14 shows a sweep feature with a negative twist angle.

Note that this edit box available only on creating sweep feature by using the **Path** option.



Figure 8-13 Sweep feature with positive twist angle



Figure 8-14 Sweep feature with negative twist angle

Creating Sweep Features by Using Path and Guide Rail Curves

To create a sweep feature with the path and guide curves, select the **Path & Guide Rail** option from the drop-down list in the **Type** area; the options in this area will be modified, as shown in Figure 8-15. These options are discussed next.




Figure 8-15 The *Type* area with modified options

Guide Rail

This button is used to select the guide curve for creating the sweep feature.

Profile Scaling

The radio buttons available in this area are used to specify the scaling method for the profile that is swept using a path and a guide curve. Selecting the **X & Y** radio button ensures that the sweep feature is scaled in both X and Y directions. Figure 8-16 shows the profile, path, and guide curve to create the sweep feature and Figure 8-17 shows the preview of the sweep feature scaled in the X and Y directions.




Figure 8-16 Profile, path, and guide curve for creating the sweep feature




Figure 8-17 Sweep feature scaled in both X and Y directions

Selecting the **X** radio button ensures that the sweep feature is scaled only along the X direction, as shown in Figure 8-18. Selecting the **None** radio button ensures that there is no scaling in the sweep feature. However, if there is any rotation in the guide curve, it will reflect in the sweep feature also. Figure 8-19 shows the preview of the feature with no scaling.




Figure 8-18 Sweep feature scaled only along the X direction




Figure 8-19 Sweep feature with no scaling

Creating Sweep Features by Using Path and Guide Surface

To invoke this option, select the **Path & Guide Surface** option from the drop-down list in the **Type** area; the **Guide Surface** button will be displayed in this area and you will be prompted to select the surface to control the profile twist. Figure 8-20 shows the profile and the path for the sweep feature. Figure 8-21 shows a sweep feature created using the **Path** option and Figure 8-22 shows the sweep feature with the same profile and path, but created using the **Path & Guide Surface** option with the top face of the base feature taken as the guide surface. As evident from Figure 8-22, the shape and twist of the sweep feature is controlled by the guide surface.






Figure 8-20 Profile and path for creating the sweep feature



*Figure 8-21 Sweep feature created using the **Path** option*



*Figure 8-22 Sweep feature created using the **Path & Guide Surface** option*

Creating Self-intersecting Sweep Features

In Autodesk Inventor, you can sweep a large profile along a path having comparatively small bending radius, refer to Figures 8-23 and 8-24.




Figure 8-23 Sweep profile and the path




Figure 8-24 Self intersecting sweep feature created

Sweep Along Tangent Edge

In Autodesk Inventor, you can sweep a profile along a complete edge or loop. This makes the task of creating a sweep easier as you do not have to create a path specifically for the profile to sweep along. Figure 8-25 shows the profile and the edge along which the profile has to be swept. Figure 8-26 shows the sweep feature created along the edge.

When you invoke the **Sweep** tool, the **Sweep** dialog box will be displayed. The procedure to create a sweep along an edge is similar to that of creating a sweep along a path. Instead of creating a separate path for the sweep profile, you can select the existing edge for creating the sweep feature. For sweeping a profile along an entire edge, you need to select a continuous edge. In case all the entities of the edge are not selected while selecting the path, you need to select each profile individually.




Figure 8-25 The profile along with the highlighted edge




Figure 8-26 Sweep feature created along an edge

Creating Non Tangent Surface Path Sweep

In Autodesk Inventor, you can sweep a profile along a path which has G0 continuity (entities non-tangent to each other). In this case, you need to create a

profile normal to the path. Figure 8-27 shows the profile and the path and Figure 8-28 shows the resultant sweep feature.




Figure 8-27 Sweep profile and the G0 path



Figure 8-28 Non Tangent path sweep feature created

Tip. The procedure to create a non tangent sweep along with a G0 path is similar to that of creating a sweep along a path.

Creating Lofted Features

Ribbon: 3D Model > Create > Loft **Lofted features are created by blending more than one geometry together. The geometries may or may not be parallel to each other. The sketches for the solid loft features should be closed profiles or points. However, for a surface model, the sketches can be open profiles. Figure 8-29 shows a circle, a triangle, and a point drawn on planes parallel to each other, but at some offset. Figure 8-30 shows the resulting lofted feature.**




Figure 8-29 Three dissimilar sketches drawn on parallel planes



Figure 8-30 Lofted feature created after blending the sketches

In Autodesk Inventor, lofted features are created using the **Loft** tool. When you invoke this tool, the **Loft** dialog box will be displayed. The options in various tabs of this dialog box are discussed next.

Curves Tab

The options in the **Curves** tab, as shown in Figure 8-31, are used to select sketches, rails, and center lines for creating loft features. These options are discussed next.



Figure 8-31 The **Curves** tab of the **Loft** dialog box

Operation Area

The options in the **Operation** area are used to specify the type of operation performed using the **Loft** tool. If this is the first feature, only the **Join** button will be available in this area. The buttons in this area are discussed next.

Join: The **Join** button is the first button in the **Operation** area and is used to create a loft feature by adding material to the model.

Cut: The **Cut** button is chosen to create a loft feature by removing material common to the loft and the model. This button will not be available if the loft feature is the first feature.

Intersect: The **Intersect** button is provided below the **Cut** button and is chosen to create a loft feature by retaining material common to the loft and the model. The remaining material will be removed from the model. This button will also not be available if the loft feature is the first feature.

New solid: This button is chosen by default and is used to create a new solid body. The new solid body is independent of other solid bodies, if present in the part file.

Sections Area

When you invoke the **Loft** dialog box, you will be prompted to select a sketch for creating the loft feature. The **Sections** area prompts you to select the sketched and displays them in the list box. When you select the sketches, a green arrow will appear on the graphics screen showing the path for the loft feature. For example, if you select three sketches: Sketch1, Sketch2, and Sketch3 in the same sequence, two arrows will appear on the graphics screen. The first arrow will point from Sketch1 to Sketch2 and the second arrow will point from Sketch2 to Sketch3. This suggests that the resulting loft feature is a blend of Sketch1-Sketch2 and Sketch2-Sketch3.

*Tip. You can also modify the sequence in which the sketches are selected using the **Sections** area. To modify the sequence, select the sketch in this area and drag it above or below the other sketch. The arrow direction will also change*

automatically in the preview of the model.

Output Area

The options in the **Output** area are used to specify the output of the **Loft** tool. If you select closed loops to blend, the **Solid** button is chosen in this area. As a result, a solid loft feature is created. If you choose the **Surface** button, the resulting loft will be a surface.

Rails

This is the first radio button available on the right of the **Sections** area and is selected by default. As a result, the **Rails** area will be displayed in the **Loft** dialog box. You can use the options in this area to select rails for the loft feature. Rails are used to control the shape of the entire body of the loft. You can use open sketches as rails for controlling the shape of the loft. Note that rails should intersect all sections selected to loft and they must be tangent continuous. To add rails, click on **Click to add** in the **Rails** area and then select rails; the names of the selected rails will be displayed in this area. Figure 8-32 shows the sections and rails used to create the loft feature. Figure 8-33 shows the loft feature without selecting rails and Figure 8-34 shows the loft feature with rails.




Figure 8-32 Sections and rails for the loft feature




Figure 8-33 Loft feature created without using rails



Figure 8-34 Loft feature created by using rails

*Tip. The rails used to guide the shape of the loft should intersect all sections of the loft. If rail does not intersect the sections, an error message will be displayed. You can make sure that the sketch of the rail intersects the sections by projecting the sections on the sketching plane of rails and then adding the **Coincident** constraint between the rail and the projected sections. Make sure you convert projected entities into construction elements before exiting the Sketching environment.*

Closed Loop

The **Closed Loop** check box is selected to close the loft feature by joining the end section with the start section. This check box will function only when you select the **Rails** radio button from the **Loft** dialog box. Figure 8-35 shows an open-ended loft feature and Figure 8-36 shows a closed-ended loft feature.




Figure 8-35 Open-ended loft feature




Figure 8-36 Closed-ended loft feature

Merge Tangent Faces

If this check box is selected, the tangent faces are merged together and no edge is created between the tangent faces of the loft feature.

Center Line

This radio button is available below the **Rails** radio button. If this radio button is selected, the **Center Line** area to select the center line for the loft feature will be displayed in the **Loft** dialog box. A center line is a curve to which the resulting loft feature is normal at every point. A center line may or may not intersect the sections. Figure 8-37 shows the two sections that are drawn on parallel planes and the curve to be used as the center line. Figure 8-38 shows the loft feature without selecting the center line and Figure 8-39 shows the loft feature with the center line.




Figure 8-37 Sections and centerline for the loft feature




Figure 8-38 Loft without selecting the center line



Figure 8-39 Loft with center line

Area Loft

This radio button is available below the **Center Line** radio button and is used to create a loft feature with varying cross-sections at required points on a center line. After specifying cross-sections for the loft feature, select the **Area Loft** radio button; you will be prompted to select a sketch to define the center line. Click once in the **Center Line** list box in the **Loft** dialog box and then select the center line from the graphics window; the preview of the loft feature will be displayed along with the callouts displaying the position and area of the sections defined at the start and the end of the center line. Also, you will be prompted to select a point. Figure 8-40 shows the preview of the loft feature created with the **Area Loft** radio button selected. This figure also shows the sections and the center line for the loft feature along with the default callouts displayed at the start point and the endpoint of the center line.




Figure 8-40 Sections and center line for the loft feature with default callouts

Notice that as you move the cursor toward the center line, the cursor will be attached to a yellow dot. Click at the desired location on the center line; a new cross-section will be created at that location and a callout displaying the position and area of the cross-sections will be displayed, as shown in Figure 8-41. Also, the corresponding **Section Dimensions** dialog box will be displayed, as shown in Figure 8-42. You can edit the dimensions and position of the new cross-section by using this dialog box. On doing so, the name of the newly added sections will be displayed in the **Placed Sections** list box. After

modifying the parameters, choose the **OK** button from the **Section Dimensions** dialog box.





Figure 8-41 The new sections of the loft feature and their callouts



*Figure 8-42 The **Section Dimensions** dialog box*

Figure 8-43 shows a loft feature created between a hexagonal section and a circular section. This feature is created by selecting the **Rails** radio button from the **Loft** dialog box. Figure 8-44 shows a loft feature created between a hexagonal section and a circular section by selecting the **Area Loft** radio button from the **Loft** dialog box after defining the new cross-section with modified parameters from the **Section Dimensions** dialog box.



*Figure 8-43 Loft feature created by selecting the **Rails** radio button*



Figure 8-44 Loft feature created by selecting the **Area Loft** radio button

Conditions Tab

The options in the **Conditions** tab, as shown in Figure 8-45, are used to control the shape of a lofted feature by applying end conditions to the sections at the two ends. The two end sections or edges selected to create the loft feature are displayed in the list box of this tab.

You can apply different types of end conditions using the drop-down list that is available when you click on the field on the left of the **Angle** column.




Figure 8-45 The **Conditions** tab of the **Loft** dialog box

Free Condition

If this option is selected, no end condition is applied to the end sections of the loft feature. In this type of end condition, the **Angle** and **Weight** columns will not be enabled.

Tangent Condition

The **Tangent Condition** option will be available only if the start section or the end section is a planar face of an existing feature. If this option is selected, the resulting loft feature will be tangent to the adjacent faces of the planar face selected as one of the end sections. Figure 8-46 shows the preview of the loft feature in which the upper section is a hexagon and the lower section is a cylindrical edge of the top face of a cylinder. In this preview, no end condition is applied by selecting the **Free Condition** option. Figure 8-47 shows the preview using the same conditions. But in this figure, the tangent condition is applied. As evident from Figure 8-47, the loft feature is tangent to the base cylinder at the start section because of the tangent condition.




Figure 8-46 Loft feature with no end condition applied




Figure 8-47 Loft feature with tangent end condition

Tip. An angle value greater than 90 degrees will create an obtuse section in the loft feature. Similarly, an angle value less than 90 degrees will create an acute section in the loft feature.

Smooth (G2) Condition

This option is available below the **Tangent Condition** option. If this option is selected, the resulting loft feature will have curvature continuity (G2 continuity) with the adjacent faces of the planar face, as shown in Figure 8-48. You can visualize the curvature continuity by using the **Zebra** tool in the **Analysis** panel of the **Inspect** tab.




Figure 8-48 Loft with smooth end condition

Direction Condition

The **Direction Condition** option is selected to define the end conditions using the **Angle** and **Weight** edit boxes. This type of end condition is available only when the profiles or sections for the loft feature are 2D sections.

Angle

The **Angle** edit box will be activated only when the value in the **Weight** edit box is more than zero (default value). This edit box is used to define the angle at the start and end sections of the loft. This angle specifies the transition between the section or rail plane and the face of the loft feature created. Remember that you cannot define an angle for the intermediate sketches. To specify the value of the angle at the start section, select the first sketch from the **Conditions** area and then set the value in this edit box. Similarly, to specify the value of the angle at the end section, select the last sketch from the **Conditions** area and then set the value in this edit box. Figure 8-49 shows angles at the start and end sections of the loft.




Figure 8-49 Angle at the start and end section of a loft feature

Figure 8-50 shows a loft with weight 0.75 at the tangent end and weight 4 at the other end. Figure 8-51 shows the same loft with weight 1.5 at the tangent end and 8 weight at the other end.



Figure 8-50 Start weight=0.75, end weight=4



Figure 8-51 Start weight=1.5, end weight=8

Note

*The **Angle** option will remain activated when the **Rails** radio button is selected in the **Curves** tab.*

Transition Tab

The options in the **Transition** tab are used to set the mapping options for the segments of the various sections while blending. These are discussed next.

Automatic Mapping

This check box is selected by default when you invoke the **Loft** dialog box. As a result, all segments of various sections map to each other using the default options and there is minimum or no twisting in the loft feature. If this check box is cleared, the remaining areas in the **Transition** tab will be activated, as shown in Figure 8-52. Figure 8-53 shows the preview of the loft feature. The lines at the vertices in this figure show how various segments and points map to each other while blending. Figure 8-54 shows the loft feature created by using automatic mapping.




Figure 8-52 The Transition tab of the Loft dialog box




Figure 8-53 Preview of the automatic mapping




Figure 8-54 Resulting loft feature

Point Set

The **Point Set** area will be enabled only when the **Automatic Mapping** check box is cleared. This area displays all sets of points used to map the segments and points of various sections in the loft feature. The number of sets of points in this area is equal to the number of green lines in the preview of the loft feature. The first set of points will be displayed in the preview. Similarly, the set of points you click on in this area will be displayed in red in the preview. To introduce twist in the loft feature, delete all sets of points in this area by clicking on them and then pressing the DELETE key. Next, click on **Click to add**; you will be prompted to select a point. Select point on section sketches.

Similarly, to create the second set of points, click on **Click to add** and then select the set of points on all sections. Follow this procedure to create the required number of sets and then choose **OK** from the **Loft** dialog box. The loft feature will follow the path created by the mapping points. Figure 8-55 shows the path created by defining the mapping points and Figure 8-56 shows the resulting twisted loft feature.




Figure 8-55 Path created by defining the mapping points




Figure 8-56 Resulting twisted loft feature

Map Point Area

The **Map Point** area displays the section points corresponding to the point set selected in the **Point Set** area. For example, **Sketch1** in this area represents the mapping point of the first section corresponding to the point set selected in the **Point Set** area. The number of items in this area depends on the number of sections in the loft.

Position Area

The **Position** area displays the position of the mapping point in terms of the length of the edge on which it lies. The total length of the edge on which the point lies is considered as 1. As a result, if the mapping point lies on the start point of the edge, its position is taken as 0 and so it is displayed as 0 in this area. Similarly, if the mapping point lies on the endpoint of the edge, its position is displayed as 1 in this area. You can select any intermediate point on the edge or sketch to define the location of the mapping point.

Creating Coil Features

Ribbon: 3D Model > Create > Coil A coil feature is created by sweeping a profile about a helical path. The examples of coil feature are springs, filaments of light bulbs, and so on. To create a coil feature, you need a profile and an axis, refer to Figure 8-57. You can also select the standard X, Y, Z axes, or a new work axis to create the coil feature. Coil features are created using various tabs from the Coil dialog box. This dialog box is invoked by choosing the Coil tool from the Create panel of the 3D Model tab. Depending on the parameters specified in the Coil dialog box, an imaginary helical path is created and the profile is swept along that path. Therefore, to create a coil feature, you need only one unconsumed sketch, which defines the profile of the coil section. The options in the Coil dialog box are discussed next.

Coil Shape Tab

The options in the **Coil Shape** tab, as shown in Figure 8-58, are used to select the profile of the coil feature and the axis about which the imaginary helical path is created. You can also specify whether the coil will be created in the clockwise or counterclockwise direction by using the rotation options in this tab. All options in this tab are discussed next.





Figure 8-57 Profile and axis for creating a coil feature



*Figure 8-58 The **Coil Shape** tab of the **Coil** dialog box*

Shape Area

The options in this area are used to select the profile and the axis of the coil.

Profile: The **Profile** button is chosen to select the profile of the coil. If the drawing consists of a single unconsumed sketch, it will be automatically selected as the profile of the coil feature.

Axis: The **Axis** button is chosen to select the axis for creating the coil feature. When you select the axis, an imaginary helical path will be displayed around the selected axis in the graphics window. The entities that can be selected as the axis for creating the coil feature are work axes, linear edges of a model, line segments, and so on. You can reverse the direction of the path by choosing the **Flip** button provided on the right of the **Axis** button.

Join

The **Join** button is the first button in the area between the **Shape** area and the **Rotation** area. This operation is used to create a coil feature by adding material to a model, refer to Figure 8-59.

Cut

The **Cut** button is provided below the **Join** button and is chosen to create a coil feature by removing material from a model, refer to Figure 8-60.

Note

The **Cut** operation of the **Coil** tool can be used to create internal or external threads in the model. However, it is recommended that you use the **Thread** tool for creating the threads directly. The use of this tool will be discussed later in this chapter.




Figure 8-59 Coil feature created on a cylinder using the **Join** operation




Figure 8-60 Coil feature created on a cylinder using the **Cut** operation

Intersect

The **Intersect** button is provided below the **Cut** button. This operation is used to create a coil feature by retaining material common to the model and the coil. The remaining material will be removed.

Note

*The area with the **Join**, **Cut**, and the **Intersect** buttons will not be available, if the coil is the first feature.*

New solid

This button is located below the **Intersect** button and is chosen by default. As a result, the resulting coil will be a new solid body.

Output Area

This area is used to specify whether the resulting coil will be a solid feature or a surface.

Coil Size Tab

The options in this tab are used to define the method and the other parameters that will be used for creating the coil, refer to Figure 8-61.

Type

The **Type** drop-down list is used to select the method for creating the coil feature. The methods that are available in this drop-down list for creating the coil are discussed next.

Pitch and Revolution: The **Pitch and Revolution** method is used to create coil by defining the pitch and the number of revolutions in the coil. The pitch value can be specified in the **Pitch** edit box and the number of revolutions can be specified in the **Revolution** edit box. You can also define a taper angle for the coil feature in the **Taper** edit box. A positive taper angle tapers the coil outward and a negative taper angle tapers the coil inward. Figure 8-62 shows a coil feature created with a positive taper and Figure 8-63 shows a coil feature created with a negative taper.




Figure 8-61 The Coil Size tab of the Coil dialog box




Figure 8-62 Coil feature created with a positive taper angle




Figure 8-63 Coil feature created with a negative taper angle

Revolution and Height: The **Revolution and Height** method is used to create the coil by defining the number of revolutions in it and its total height. The number of revolutions can be defined in the **Revolution** edit box and the height can be defined in the **Height** edit box.

Pitch and Height: The **Pitch and Height** method is used to create the coil by defining the pitch of the coil and the total height of the coil. The value of the pitch can be defined in the **Pitch** edit box and the height can be defined in the **Height** edit box.

Spiral: The **Spiral** method is used to create a spiral coil in a single plane. The spiral coil can be created using the pitch of the coil and the number of revolutions in the coil. As the spiral coil is created in a single plane, the **Height** edit box will not be available when you use this method. Also, you cannot define the taper angle for a spiral coil and so the **Taper** edit box will not be available. Figure 8-64 shows a spiral coil.

Coil Ends Tab

The options in this tab are used to specify the type of ends of the imaginary helical path to be used to create the coil, refer to Figure 8-65. These options are discussed next.

Start Area

The options in the **Start** area are used to specify the end type at the start section of the imaginary helical path. The type of start section can be selected from the drop-down list in this area. These options are discussed next.

Natural: The **Natural** option is selected by default. As a result, no other option in the **Start** area is activated.



Figure 8-64 A spiral coil




Figure 8-65 The Coil Ends tab of the Coil dialog box

Flat: If the **Flat** option is selected, you can specify a different start section of the helical path. The other options in the **Start** area will be activated only if this option is selected.

Transition Angle: The **Transition Angle** edit box is used to specify the angle of transition of the coil at the start section of the coil. This option works in association with the number of revolutions in the coil and is

generally used in coils with less than one revolution. The value of the transition angle can vary from 0 degree to 360 degrees.

Flat Angle: The **Flat Angle** edit box is used to specify the angle through which the coil will extend beyond the transition at the start section of the coil. The value of the transition angle can vary from 0 degree to 360 degrees.

End Area

The options in the **End** area are similar to those discussed in the **Start** area. The only difference is that these options are used to specify the end type at the end section of the imaginary helical path.

Creating Threads

Ribbon: 3D Model > Modify > Thread

Autodesk Inventor allows you to create internal or external threads directly on a model. Internal threads are created on the inner surface of a feature. For example, the threads created on the hole inside a cylinder are called internal threads, refer to Figure 8-66. External threads are created on the outer surface of a feature or a model. For example, threads created on a bolt, refer to Figure 8-67. You can create threads using the **Thread** tool. When you invoke this tool, the **Thread** dialog box will be displayed. The options in the **Thread** dialog box are discussed next.




Figure 8-66 Internal threads in a cylinder




Figure 8-67 External threads on a bolt

Location Tab

The options in the **Location** tab are used to define the location, length, and offset of threads, refer to Figure 8-68. These options are discussed next.




Figure 8-68 The Location tab of the Thread dialog box

Face

The **Face** button is chosen to select the face on which the threads will be created. When you invoke the **Thread** dialog box, this button will be automatically chosen and you will be prompted to select the face on which the threads will be created.

Display in Model

The **Display in Model** check box is selected by default to display the threads in the model. If this check box is cleared, the threads will be created, but will not be displayed in the model. They will be displayed only in the **Browser Bar**.

Thread Length Area

The options in the **Thread Length** area are used to specify the length of the threads. These options are discussed next.




Figure 8-69 Full length threads on a bolt

Full Length: The **Full Length** check box is used to create threads through the length of the selected face. By default, this check box is selected. As a result, no other option in the **Thread Length** area will be activated. Figure 8-69 shows a bolt with threads created through its length. If you clear this check box, the remaining options in this area will be activated.

Flip: The **Flip** button is used to reverse the direction of thread creation.

Offset: The **Offset** edit box is used to define distance by which threads will be offset from the starting edge of the face selected for creating threads. By default, the value of the offset distance is zero. If you specify any offset value, the start point of threads will move away from the start of the face selected for threading. Figure 8-70 shows the threads created at an offset distance of 0 mm from the top face and Figure 8-71 shows the threads created at an offset distance of 20 mm from the top face.




Figure 8-70 Threads created at an offset of 0 mm




Figure 8-71 Threads created at an offset of 20 mm from the top face

Length: The **Length** edit box is used to specify the length up to which the threads will be created on the selected face.

Note

*You cannot define a negative value for the length of the threads or the offset of the threads. If you want to create the threads in the opposite direction, choose the **Flip** button. The direction will reverse automatically.*

Specification Tab

The options in this tab are used to define the type of threads to be created and the other parameters related to these threads, refer to Figure 8-72.




Figure 8-72 The **Specification** tab of the **Thread** dialog box

Thread Type

The **Thread Type** drop-down list is used to select the predefined thread types. These predefined thread types are saved in Microsoft Excel spreadsheet. This spreadsheet is stored in the directory with the name Thread.xls. You can also add custom thread types in this spreadsheet and use them in the model.

Size

The **Size** drop-down list is used to select the nominal diameter of the threads. Depending on the type of thread selected from the **Thread Type** drop-down list, the values in this drop-down list will change. You can select the required value of the diameter of the threads from this drop-down list.

Designation

The **Designation** drop-down list is used to select the designation of the required threads. The designation depends on the type and size of threads.

Class

The **Class** drop-down list is used to select the predefined class of threads, which will depend on the face on which the threads will be created.

Right hand/Left hand

These radio buttons are selected to specify whether the resulting threads will be the right hand threads or the left hand threads. The right hand threads are those that allow the screw to be tightened when rotated in the clockwise direction. The left hand threads are those that allow the screw to be tightened when rotated in the counterclockwise direction.

Note

*For some of the thread types, the **Designation** and the **Class** drop-down lists will not be available.*

Creating Shell Features

Ribbon: 3D Model > Modify > Shell

Shelling is a process of scooping out material from a model to make it hollow. The resulting model will be a structure of walls with cavity. You can also remove some of the faces of the model or apply different wall thicknesses to some of the faces. Figure 8-73 shows a model with constant shelling and with the front face removed.

The **Shell** tool is used to create shell features. In Autodesk Inventor, when you invoke this tool, the **Shell** dialog box will be displayed along with the mini toolbar. If you click on the down-arrow in this dialog box it will be expanded. refer to Figure 8-74. The options in the **Shell** tab are discussed next. Note that the options in the **More** tab are similar to those discussed in the **Thicken/Offset** tool. Therefore, these options are not discussed here.

Remove Faces

The **Remove Faces** button is used to select the faces that you want to remove from a model. If you invoke the **Shell** dialog box, this button will be chosen by default and you will be prompted to select the faces to be removed. The selected faces will be highlighted. Figure 8-75 shows the face selected to be removed along with mini toolbar and Figure 8-76 shows the resulting shelled model.




Figure 8-73 Model after creating the shell feature




Figure 8-74 The Shell tab of the Shell dialog box




Figure 8-75 Face selected to be removed




Figure 8-76 Resulting shelled model

Tip. If you have selected a wrong face for removed purpose then press and hold the SHIFT key and click on to deselect it.

Automatic Face Chain

If you select a face with the **Automatic Face Chain** check box selected, then all faces that are tangentially connected to the selected face will be selected automatically.

Solids

The **Solids** button is used to select a body from multiple part bodies from the graphics window.

Thickness

The **Thickness** edit box is used to specify the wall thickness of the resulting shelled model.

Inside

The **Inside** button is the first button in the area provided on the left of the **Shell** tab of the **Shell** dialog box. This button is chosen to define the wall thickness inside, with respect to the outer faces of the model. In this case, the outer faces of the model will be considered as the outer walls of the resulting shell feature.

Outside

The **Outside** button is provided below the **Inside** button and is chosen to define the wall thickness outside the model with respect to its outer faces. In this case, the outer faces of the model will be considered as the inner walls of the resulting shell feature.

Both

The **Both** button is provided below the **Outside** button and is chosen to calculate the wall thickness equally in both the directions of the outer faces of the model.

>>

This button has two arrows and is provided at the lower right corner of the **Shell** dialog box. On choosing this button, the **Shell** dialog box will expand and display the **Unique face thickness** area, refer to Figure 8-77. Using the options in this area, you can select faces and apply different wall thicknesses to them.




Figure 8-77 The Unique face thickness area

To select faces, click on **Click to add**; you will be prompted to select surfaces to apply different wall thicknesses. The thicknesses of the selected surfaces can be specified in the **Thickness** column of the **Unique face thickness** area. Similarly, you can select another set of faces by clicking on **Click to add** and specifying different wall thicknesses to them. Figure 8-78 shows a model with different wall thicknesses applied to various faces




Figure 8-78 Shell feature with different wall thicknesses

Applying Drafts

Ribbon: 3D Model > Modify > Draft

Face draft is a process of tapering the outer faces of a model for its easy removal from casting during manufacturing. You can add a face draft using the **Draft** tool. On invoking this tool, the **Face Draft** dialog box will be displayed, see Figure 8-79. The options in this dialog box are discussed next.




Figure 8-79 The Face Draft dialog box

Fixed Edge

This is the first button on the left side of the **Face Draft** dialog box. The **Fixed Edge** button is chosen when you want to draft a face using an edge. Note that all edges tangent to the edge that you select to create the face draft are automatically selected.

Fixed Plane

The **Fixed Plane** button is available below the **Fixed Edge** button. This button is used to create a face draft by using a fixed plane. Figure 8-80 shows the top planar face of the model selected as the fixed plane to create the face draft and shows various parameters associated with the face draft.

Pull Direction/Fixed Plane

This is the first button available in the area in the center of the **Face Draft** dialog box. Depending on whether you choose the **Fixed Edge** or **Fixed Plane** button, the name of this button will be **Pull Direction** or **Fixed Plane**. This button is used to define the pull direction in case of a fixed edge and draft plane in case of a fixed plane. The pull direction is the direction defined by a plane that will be used to apply the face draft. The draft angle for the selected faces will be calculated using the plane selected to define the pull direction. Once you have selected the plane or the edge to define the pull direction, an arrow will be displayed. This arrow will define the pull direction for applying the draft angles, refer to Figure 8-80. You can reverse the pull direction by choosing the **Flip pull direction** button provided on the right of the **Pull Direction** button. Alternatively, you can pull the manipulator in the desired direction.

Faces

The **Faces** button is chosen to select the faces on which the draft angle will be applied. If the selected face has some tangent faces, they will also be selected for applying the face draft. After you have selected the pull direction, this button will be automatically chosen and you will be prompted to select the faces and the fixed edges to apply the face draft. If you move the cursor close to a face, it will be highlighted and an arrow will be displayed on selecting that face. This arrow will define the direction in which the draft angle will be applied. Depending upon the point that is used to select the face, the nearest edge parallel to the pull direction will be selected. This edge is defined as the fixed edge. The direction of the draft angle will be calculated using this fixed edge.




Figure 8-80 Various parameters associated with face draft

Draft Angle

The **Draft Angle** edit box is used to specify a draft angle for the selected faces. Remember that the value of the draft angle should be less than 90-degree.

Figure 8-81 shows the model to which the face draft has been applied using the tangent edge of the bottom face as the fixed edge, top face as the face to be drafted and with the pull direction upward. Figure 8-82 shows a model after applying the face draft using the same fixed edge, but after reversing the pull direction by using the **Flip pull direction** button. In both these figures, the value of the draft angle is 15 degrees.




Figure 8-81 Face draft with the pull direction upward





Figure 8-82 Face draft with the pull direction downward

Tip. You can also change the direction of draft angle by using the negative angle value.

Parting Line

The **Parting Line** button is available below the **Pull Direction** button. This button is used to create a face draft about a 2D or 3D sketch. When the Parting Line draft is applied to the model, it will be drafted across the parting line. Figure 8-83 shows the **Face Draft** dialog box with the **Parting Line** button chosen. Figure 8-84 shows the model with the highlighted face and the parting line about which the sides will be drafted. Figure 8-85 shows the preview of the model with a positive draft and the direction of pull. Figure 8-86 shows the preview of the model with a negative draft and the direction of pull.



*Figure 8-83 Face draft dialog box with the **Parting Line** button chosen*




Figure 8-84 Selected face and the parting line




Figure 8-85 Preview of the draft with a positive draft angle of 15 degrees




Figure 8-86 Preview of the draft with a negative draft angle of 15 degrees

Note

*The **Parting Tool** button will be available only when you choose the **Parting Line** button available below the **Fixed Plane** button.*

Creating Split Features

Ribbon: 3D Model > Modify > Split In Autodesk Inventor, the Split tool can be used for splitting the entire part or the faces of the part. The three uses of the Split tool are discussed next.

Splitting Faces

The **Split** tool allows you to split all or selected faces




Figure 8-87 The **Split** dialog box

of a model. Generally, faces are split in order to apply different draft angles to both sides of a model. When you invoke the **Split** tool, the **Split** dialog box is displayed, as shown in Figure 8-87. By default, the **Split Face** button is chosen in the **Method** area, refer to Figure 8-87, and is used to split the faces of a model. As the **Split Face** button is chosen in the **Split** dialog box, the options for splitting faces will be available in this dialog box. These options are discussed next.

Split Tool

The **Split Tool** button is chosen to select the tool that will be used to split the faces of the model. The tools that can be used to split the faces are the sketched lines, existing faces of the model, surfaces, or work planes.

Tip. If you want to use a sketched line to split the faces of the model, make sure the sketched line intersects the faces to be split in its current form or when it is projected normal to the plane on which it is sketched.

Faces

This button is chosen to select the faces to be split.

Faces Area

The options in this area are used to select all faces of a model to split, or to specify the faces to split. These options are discussed next.

All: If the **All** button is chosen, all faces that the splitting tool intersects in its current form or when projected will be selected for splitting.

Select: The **Select** button is chosen to select faces to split. Faces can be selected by choosing the **Faces** button. On choosing the **Faces** button, you will be prompted to select the faces to be split. Select the faces; the selected faces will be split and the rest of the faces will remain unchanged even if they intersect the split tool. Figure 8-88 shows the sketched lines to be used for splitting the faces of the model and Figure 8-89 shows the split faces.




Figure 8-88 Sketched lines for splitting the faces of the model




Figure 8-89 Model after splitting the faces and making the work plane invisible

Trimming the Model

In addition to splitting the faces, you can trim a solid by using the **Split** dialog box. To do so, choose the **Trim Solid** button from the **Split** dialog box and then select the part to be trimmed. Next, select the required sketch, plane, or surface as a split tool and choose **OK**; the solid will be trimmed. The options displayed in the **Split** dialog box when you choose the **Trim Solid** button are discussed next, refer to Figure 8-90.




Figure 8-90 Various options displayed in the **Split** dialog box on choosing the **Trim Solid** button

Split Tool

The **Split Tool** button is chosen to select the entity that will be used as the trimming tool.

Solid

This button is chosen to select the body participating in feature creation from multiple bodies in the graphics window.

Figure 8-91 shows the solid part to be trimmed and the sketched line to be used as the split tool. Figure 8-92 shows the solid part after trimming.

Remove Area

The buttons in this area are used to select the portion of the model to be removed while splitting. When you select the splitting tool, an arrow will appear on the model. This arrow points toward the portion of the model to be removed after splitting. To remove the other portion from the model, choose the other button in the **Remove** area.




Figure 8-91 Solid part and split tool




Figure 8-92 Solid part after trimming

Splitting the Model

The **Split** tool is used to split a model. This is done by choosing the **Split Solid** button from the **Split** dialog box. On choosing this button, the options related to splitting a part are displayed, refer to Figure 8-93. These options have been discussed earlier. Figure 8-94 shows the solid part shown in Figure 8-91 after splitting.




Figure 8-93 Various options displayed in the **Split** dialog box on choosing the **Split Solid** button




Figure 8-94 Model after splitting

Trimming Surfaces

Ribbon: 3D Model > Surface > Trim

Trim tool is used to trim surfaces by using another surface, a non-intersecting sketch, a work plane, or a face of an existing model. On invoking this tool, the **Trim Surface** dialog box will be displayed, as shown in Figure 8-95, and you will be prompted to select surfaces, work planes, or sketches as the cutting tool. As soon as you select the cutting tool, the **Remove** button is chosen and you are prompted to select faces to remove. If you move the cursor on the face to be removed, it will be highlighted. Click on the face to select it, the selected surface portion is highlighted in green. You can choose the **Invert Selection** button to select the part of the surface that lies on the other side of the cutting tool. The **Invert Selection** button is on the right of the **Remove** button and is activated after you select a face to be removed.




Figure 8-95 The Trim Surface dialog box

Figure 8-96 shows two intersecting surfaces. In this figure, the horizontal surface has been used as the cutting tool. You can trim the upper part or the lower part of this surface. Figure 8-97 shows the surfaces after trimming the top part of the vertical surface.




Figure 8-96 Cutting tool and the surface to be trimmed




Figure 8-97 Surfaces after trimming

Figure 8-98 shows a sketch selected as the cutting tool and the part of the surface to be trimmed. Note that in this figure, the sketch is drawn on a plane that is at some offset from the surface. Figure 8-99 shows the surface after trimming.




Figure 8-98 Sketch to be used as the cutting tool and the surface to be trimmed



Figure 8-99 Surface after trimming

Extending Surfaces

Ribbon: 3D Model > Surface > Extend

You can extend or stretch the edges of a surface by using the **Extend** tool. On invoking this tool, the **Extend Surface** dialog box will be displayed, as shown in Figure 8-100. The options available in this dialog box are discussed next.




Figure 8-100 The Extend Surface dialog box

Edges

This button is chosen by default when you invoke the **Extend Surface** dialog box. It is used to select the edges for extending or stretching. On selecting an edge, the preview of the extension along with an arrow is displayed. Drag the arrow to specify the extension. Alternatively, specify the extension in the edit box below the **Extents** drop-down list.

Edge Chain

If this check box is selected, all edges that are tangentially connected to the selected edge will also be selected.

Extents

This area provides the options to specify the values of the extended or stretched surfaces. You can select the **Distance** or **To** options from the drop-down list in this area. These options are similar to those discussed in the **Extrude** dialog box.

>> (More)

This button is available at the lower right corner of the dialog box. On choosing this button, the **Extend Surface** dialog box will expand and display the **Edge Extension** area, as shown in Figure 8-101. The options in this area are discussed next.



Figure 8-101 The Edge Extension area of the Extend Surface dialog box

Extend

This radio button is selected by default. As a result, the surface is extended along the direction of the edges adjacent to the selected edges. Figure 8-102 shows the surface in which the top edge is being extended using this option. As evident from this figure, the edge is being extended along the direction of the vertical edges adjacent to the top edge of the surface.

Stretch

This radio button is selected to extend a surface by stretching it in 3D space. Figure 8-103 shows a surface in which the top edge is being extended using this option. As evident from this figure, the edge is being extended proportionately in the 3D space.




Figure 8-102 Surface being extended along the direction of the adjacent edges




Figure 8-103 Surface being extended in the 3D space

Deleting Faces

Ribbon: 3D Model > Modify > Delete Face Autodesk Inventor allows you to delete one or more planar faces or non-planar lumps in a model or in a surface. Depending on the face selected to be deleted, the resulting model is converted into a surface. You can also force the adjacent faces to extend and intersect such that they heal the surface. This tool can also be used to fill the hollow model created using the Shell tool without removing any face. On invoking the Delete Face tool, the Delete Face dialog box will be displayed, as shown in Figure 8-104. The options in this dialog box are discussed next.



Figure 8-104 The Delete Face dialog box

Faces

The **Faces** button is used to select the faces to be deleted. When you invoke the **Delete Face** dialog box, this button is chosen automatically and you are prompted to select the faces to be deleted.

Select individual face

The **Select individual face** button is chosen to select the individual faces to be deleted. Figure 8-105 shows a surface model with the top face selected for removal and Figure 8-106 shows the resulting surface model.




Figure 8-105 Top face selected to be deleted




Figure 8-106 Resulting surface model

Select lump or void

The **Select lump or void** button is used to select a lump or void. Generally, this button is used to delete the lump or void face that cannot be deleted individually. To remove such a face, choose this button and select the face to be removed; the selected face will be deleted.

Heal

The **Heal** check box is selected to force the adjacent faces to extend and meet so that the deleted face is healed. For example, if you delete a filleted or chamfered face and select this check box, the adjacent faces forming the fillet or chamfer will be extended to recover the lost face. Note that when you heal the face, the model is not converted into a surface model. Figure 8-107 shows a model with all fillets and rounds applied. In this model, all fillets and rounds are applied with a different color. Figure 8-108 shows the model after deleting some of the fillets and rounds and healing the faces.




Figure 8-107 Model with fillets and rounds applied




Figure 8-108 Model after healing some faces

Replacing Faces with Surfaces

Ribbon: 3D Model > Surface > Replace Face

Autodesk Inventor allows you to replace the selected faces of a model with one or more selected surfaces or work planes. Note that the surface must intersect the complete face that you want to replace. Figure 8-109 shows a model and a surface. The top face of the model is replaced by the surface. The surface in this model has been created by sweeping a spline about another spline. Figure 8-110 shows the model after replacing the top face with the surface and making the surface invisible.




Figure 8-109 Surface and model before replacing the face




Figure 8-110 Model after replacing the top face with the feature

As evident from Figure 8-110, this tool is used not only to remove material from the model, but also to add material to the model to match the profile of the surface. This is the basic difference between splitting a part by using the surface and by replacing the face. While splitting a part, Autodesk Inventor only removes material and does not add material to a model.

You can select one or more than one surface to replace a face. To replace a face, invoke the **Replace Face** tool; the **Replace Face** dialog box will be displayed, as shown in Figure 8-111. The options in this dialog box are discussed next.



Figure 8-111 The Replace Face dialog box

Existing Faces

The **Existing Faces** button is chosen to select the faces of the model to be replaced. When you invoke the **Replace Face** dialog box, this button is chosen by default.

New Faces

The **New Faces** button is chosen to select the surfaces that will replace the selected faces. Note that the surfaces should completely intersect the selected faces or should extend beyond them. If the surfaces do not intersect the faces, the feature will not be created and an error message will be displayed.

Automatic Face Chain

The **Automatic Face Chain** check box is selected to automatically select all tangent faces that form a continuous chain with a selected face.

Figure 8-112 shows a model with two surfaces that have to be used for replacing the top face of the model and Figure 8-113 shows the model after replacing the face and making the surfaces invisible using the **Browser Bar**.




Figure 8-112 Surfaces to replace the top face




Figure 8-113 Model after replacing the face

Creating Planar Boundary Patches

Ribbon: 3D Model > Surface > Patch

Autodesk Inventor allows you to create planar boundary patches on one or more closed loops or edges using the **Patch** tool. On invoking this tool, the **Boundary Patch** dialog box will be displayed, as shown in Figure 8-114, and you will be prompted to select a profile that defines the boundary of the planar patch. This dialog box has two areas: **Boundary** and **Condition**. These areas are discussed next.




Figure 8-114 The **Boundary Patch** dialog box

Boundary Area

The **Boundary** area displays the number of closed loops you select to create the boundary patch.


Condition Area

The **Condition** area displays the entity selected to create the boundary patch. If you select the edges, it will list all edges that you selected to create the boundary. Similarly, if you select a sketch, it displays the name of the sketch in this area. The third column in this area displays a drop-down list that can be used to specify the edge condition for the boundary patch. You can specify free, tangent, or smooth(G2) condition, depending on the edge selected.

Automatic Edge Chain

If the **Automatic Edge Chain** check box is selected then on selecting an edge of a loop, all the edges of that loop will be selected. If you clear this check box, you can select individual edges of the loop. Figures 8-115 and 8-116 show the model when the **Automatic Edge Chain** check box is selected and cleared, respectively.

*Figure 8-115 Model after selecting the **Automatic Edge Chain** check box*



*Figure 8-116 Model after clearing the **Automatic Edge Chain** check box*

Figure 8-117 shows a surface model before creating the boundary patch and Figure 8-118 shows the surfaces after creating contact boundary patches on the top and bottom faces. Note that both these surfaces are created separately one by one.



Figure 8-117 Surfaces before creating the boundary patch



Figure 8-118 Surfaces after creating the contact boundary patches

Figure 8-119 shows the tangent boundary patch created at the ends of the faces of the model.




Figure 8-119 Tangent boundary patch on one of the ends

Stitching Surfaces

Ribbon: 3D Model > Surface > Stitch



Sometimes, while splitting parts, you may need to use more than one surface as the splitting tool. The **Split** tool allows you to select only one surface to split parts or faces. In such cases, you can join more than one surface together so that they form a single surface. You can stitch surfaces using the **Stitch** tool. On invoking this tool, the **Stitch** dialog box will be displayed, as shown in Figure 8-120. The tabs in this dialog box are discussed next.

Stitch Tab

The options in this tab are used to select the surfaces to be stitched and specify tolerances for stitching. By default, the **Surfaces** button is chosen and you are prompted to select the bodies to be stitched. Note that if there is a small gap between the selected surfaces, the gap will be filled with a new surface and the stitched surface will be displayed as **Stitch Surface** in the **Browser Bar**. You cannot see the stitched surface in the graphics window. You can specify tolerance between free edges by entering a value in the **Maximum Tolerance** edit box. You can view the remaining free edges and their tolerance values in the **Find Remaining Free Edges** area.




Figure 8-120 The Stitch dialog box

By default, the **Maintain as surface** check box is cleared. As a result, if you stitch the surfaces that form a closed volume, the resultant feature will be a solid feature. However, if you select this check box, the resultant feature after stitching the surfaces that form a closed volume, will be a surface.

Note

*Tutorial 5 in Chapter 14 uses the concept of hybrid surface-solid modeling. You will use the **Stitch Surface** tool in that tutorial to stitch surfaces.*




Figure 8-121 The *Analyze* tab of the **Stitch** dialog box

Analyze Tab

The options in the **Analyze** tab, as shown in Figure 8-121, are used to analyze the edges of the stitched surfaces, end conditions of edges, and errors associated with the edges. If you select the **Show Edge Conditions** check box, the stitched edges will be displayed in black, whereas the edges that fail to stitch will be displayed in red. You can view the edges that are nearly tangent to each other by selecting the **Show Near Tangent** check box. On doing so, the nearly tangent edges will be highlighted.

Working with the Sculpt Tool

Ribbon: 3D Model > Surface > Sculpt

The **Sculpt** tool is used to add or remove material from an existing model by using a surface or a datum plane. The existing model can be a solid model or a surface model, refer to Figure 8-122. This figure shows an existing solid base plate and a revolved surface. Figure 8-123 shows the material added to the base plate using the **Sculpt** tool. As evident from this figure, the shape and size of the material added is defined by the surface.





Figure 8-122 The base plate and the surface to create the sculpt feature



*Figure 8-123 The base plate after adding the material using the **Sculpt** tool*

To create a sculpt feature, invoke the **Sculpt** tool; the **Sculpt** dialog box will be displayed, as shown in Figure 8-124. The options in this dialog box are discussed next.

Add

This button is used to add material to an existing model, refer to Figure 8-123. Remember that the shape and size of the material added is determined by the shape and size of the surface selected.




Figure 8-124 The **Sculpt** dialog box

Remove

This button is chosen to remove material from an existing model.

Note

*Sometimes, while removing material from the model using the **Sculpt** tool, you may get an error message. In that case, you need to change the side of material removal by using the **More** button of the **Sculpt** dialog box. The use of the **More** button will be discussed later in this topic.*

New solid

If you choose this button, the resultant sculpt feature will be a new solid body.

Surfaces

This button is chosen to select the surface to create the sculpt feature.

Enable/Disable feature preview

This check box is selected to enable or disable the dynamic preview of the sculpt feature in the drawing window.

More

When you choose this button, the **Sculpt** dialog box expands and displays the **Side Selection** area. The surfaces that you select to create the sculpt feature are displayed in the **Surfaces** column of this area. Also, an icon corresponding to the selected surface appears on the right of surface name. When you click on this icon, a drop-down list appears. You can use this drop-down list to specify the side along which the sculpt feature will be created.

Note

*While removing the material using the **Remove** option of the **Sculpt** tool, the side of the model that turns pink will be removed.*

Working with the Bend Part Tool

Ribbon: 3D Model > Modify > Bend Part

The **Bend Part** tool is used to bend components or portions of components by using different options. To bend a component, first you need to sketch a line about which the component will be bent. This line is called the Bend Line. It can also be defined as the tangency line at which the component transforms into a bend. After specifying the tangency conditions between the bend line and the component, you can define the side of the component to be bent, the direction and angle of the bend, and other parameters. To bend components, choose the **Bend Part** tool from the **Modify** panel of the **3D Model** tab, the **Bend Part** dialog box will be displayed, as shown in Figure 8-125, and you will be prompted to select a bend line. Note that the bend line has to be sketched tangential to a cylindrical component or to the surface intended to be bent. The options in the **Bend Part** dialog box are discussed next.

Bend Line

This button is chosen by default when you invoke the **Bend Part** dialog box and allows you to specify the bend line for component. The bend line can also be defined as the line about which a component hinges or folds.




Figure 8-125 The Bend Part dialog box

The drop-down list below the **Bend Line** button is used to bend components by three methods namely, **Radius + Angle**, **Radius + Arc Length**, and **Arc Length + Angle**. These three methods are discussed next.

Radius + Angle

This option is selected by default and is used to bend components by specifying the bend radius and angle. Figure 8-126 shows the preview of a component bent with a radius value 2 mm and angle 180 degrees.




Figure 8-126 Preview of a component bent with the radius 2 mm and angle 180 degrees

Radius + Arc Length

This option is used to bend components by specifying the bend radius and arc

length. Figure 8-127 shows the preview of a component bent with a radius value 5 mm and arc length 10 mm.

Arc Length + Angle

This option is used to bend components by specifying the arc length and angle. Figure 8-128 shows the preview of a component bent with arc length 10 mm and angle 150 degrees.




Figure 8-127 Preview of a component bent with the radius 5 mm and arc length 10 mm




Figure 8-128 Preview of a component bent with the arc length 10 mm and angle 150 degrees

Solid

This button is chosen to select the participating body from the graphics window.

Side

The **Side** buttons allow you to specify the direction of the bend by using three buttons. These three buttons are discussed next.

Bend left

This button is chosen by default and is used to bend the portion that is on the left of the bend line. Figure 8-129 shows the preview of the component bent by choosing the **Bend left** button.

Bend right

This button is used to bend the portion that is on the right of the bend line. Figure 8-130 shows the preview of the component bent by using the **Bend right** button.




Figure 8-129 Preview of the component bent by using the **Bend left** button




Figure 8-130 Preview of the component bent by using the **Bend right** button

Bend Both

When this button is chosen, the portions on the right and left of the bend line are bent.

Direction

This button is used to flip the direction of the bend to the left or right of the neutral plane. The plane used to create the bend line acts as a neutral plane while creating the bend.

Figure 8-131 shows a cylindrical component with the bend line and the neutral plane. Figure 8-132 shows the component bent by choosing the **Bend Both** button and selecting the **Radius + Angle** option from the drop-down list.




Figure 8-131 Component before bending



Figure 8-132 Component after bending

More

When you choose this button, the **Bend Part** dialog box expands and displays the **Bend Minimum** check box. This check box is selected by default. If the bend line intersects a component at multiple points, select the **Bend Minimum** check box to specify the portion of the component to be bent.

REORDERING THE FEATURES

Autodesk Inventor allows you to change the order of the feature creation in a model. You can move a feature before or after another feature. However, note that reordering is possible only between the features that are independent of each other. For example, if the fourth feature of a model is dependent on the third feature, you cannot reorder the fourth feature before the third.

In Autodesk Inventor, features are reordered using the **Browser Bar**. To reorder a feature, select it in the **Browser Bar** and drag it above or below other features. If a black circle with a line appears while dragging a feature, you cannot reorder the feature because the selected feature is dependent on the feature before which you want to place it in some way or the other. However, if the feature is not dependent, a black line appears while dragging the feature. Figure 8-133 shows a model that has a base feature, a cut feature on the base feature, rectangular pattern of the cut feature, a shell feature, and finally a split feature.

Note that in this model, the shell feature is created after the rectangular pattern of the cut feature on the base feature. As a result, the same wall thickness is retained around all instances of the rectangular cut features.

Now, if you reorder the features such that the shell feature is placed before the extruded cut feature and the pattern of the cut feature, all walls around the rectangular cuts will be removed. Figure 8-134 shows the reordering of the features in the **Browser Bar**.




Figure 8-133 Model with the shell feature created after the cut feature and its pattern




Figure 8-134 Reordering the shell feature

Figure 8-135 shows the model after reordering the shell feature. Notice that because the shell feature is now created before the rectangular pattern, the resulting model has simple cuts without any walls around them.




Figure 8-135 Model after reordering the shell feature before the cut feature and its pattern

Tip. Similar to reordering the features, you can also rollback the model using the **Browser Bar**. To rollback the model, select the text **End of Part** that appears at the end of the list of features in the **Browser Bar**. Next, drag and drop this text before the features in the **Browser Bar**. All the features that are placed after this text are automatically suppressed in the model. To resume the features, drag this text to the end of the features in the **Browser Bar**.

USING THE SKETCH DOCTOR

Sketch doctor is a diagnostic tool. It provides information about the problems that occur while sketching. For example, if you try to extrude an open loop by choosing the **Solid** button from the **Output** area in the **Extrude** dialog box, as shown in Figure 8-136, the **Examine Profile Problems**(with red plus sign) button will be displayed in the dialog box. Choose this button; the **Sketch Doctor** dialog box with the description of the problem in the **Examine** page will be displayed, as shown in Figure 8-137. Also, the endpoints of the open loop will be highlighted in the drawing area. Choose the Next button; the **Select a treatment** area will be displayed in the **Treat** page. Choose the **Edit Sketch** option and then choose the **Finish** button to invoke the sketching environment for editing the sketch.




Figure 8-136 The Extrude dialog box

If you need more information about the sketch, choose the **Diagnose Sketch** option from the **Select a treatment** area and choose the **Finish** button; the possible error in the sketch will be displayed in the **Diagnose Sketch** dialog box. Choose the **OK** button from this dialog box; the problem to be rectified will be listed in the **Sketch Doctor** dialog box. In this case, it indicates that the sketch is an open loop. Choose the **Next** button again; the description of the problem will be displayed. Choose the **Next** button once again to view the diagnostics and select a suitable treatment from the **Select a treatment** area. After selecting a treatment, choose the **Finish** button; a message box will be displayed. Choose the **OK** button from the message box; the sketching environment will be displayed, where you can edit the sketch.




Figure 8-137 The Sketch Doctor Examine dialog box

USING THE DESIGN DOCTOR

Design doctor is a diagnostic tool, which is very similar to the sketch doctor. It provides information about the problems that occur while designing, modifying previous sketches or features, and so on. For example, if you convert the closed loop of a sketch that is already extruded to an open loop and exit the sketching environment, the **Autodesk Inventor Professional - Exit Sketch Mode** dialog box will be displayed. Expand the + node, refer to Figure 8-138 and then choose the red plus sign icon from this dialog box; the **Autodesk Inventor Professional** message box will be displayed. Choose the **Yes** button from this message box; the problem to be solved will be listed in the **Design Doctor** dialog box, as shown in Figure 8-139. In this case, it indicates the broken loop in Extrusion1. Select **Extrusion1:Broken loop** from the **Select problem to recover** area and then choose the **Next** button; the **Problem diagnosis/description** area will be displayed in the **Design Doctor** dialog box. Again, choose the **Next** button to view the diagnostics and to select a suitable treatment from the **Select a treatment** area. This area will have the options to edit and diagnose the sketch. If you need more information about the problem, choose the **Diagnose Sketch** option from the **Select a treatment** area and then choose the **Finish** button; the possible error in the sketch will be displayed in the **Diagnose Sketch** dialog box. Choose the **OK** button from this dialog box; the problem to be solved will be listed in the **Sketch Doctor** dialog box. Rectify the problem as discussed in the earlier section. If you need to edit the sketch, choose the **Edit Sketch** option from the **Select a treatment** area and then choose the **Finish** button; the sketching environment will be invoked. Rectify the sketch and return to the **Part** module.




Figure 8-138 The Autodesk Inventor Professional - Exit Sketch Mode dialog box




Figure 8-139 The Design Doctor dialog box

TUTORIALS

Tutorial 1

In this tutorial, you will create the model shown in Figure 8-140a. Its dimensions are given in Figure 8-140b. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- a. The base feature of the model is a sweep feature. Create the path of the sweep feature on the XZ plane, refer to Figure 8-141. Next, define a work plane normal to the path and position it at the start point of the path, refer to Figure 8-142. Create the profile of the sweep feature on this work plane, refer to Figure 8-143. Use the **Sweep** tool to create the sweep feature, refer to Figure 8-144.
- b. Create the inner cavity using the **Shell** tool, refer to Figure 8-145.
- c. Add the remaining features (join features, drilled holes and their patterns, and counterbore hole) on both ends of the sweep feature.




Figure 8-140a Model for Tutorial 1




Figure 8-140b Views and dimensions of the model for Tutorial 1

Creating the Path for the Sweep Feature

As mentioned earlier, the base feature of the model is a sweep feature. To create the sweep feature, first you need to create its path on the XZ plane. The path is a combination of two lines and an arc.

1. Start a new metric standard template file and create the path of the sweep feature on the XZ plane. Add the required dimensions. Exit the Sketching environment, and if required, change the view to the isometric view, as shown in Figure 8-141.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.
2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Creating the Work Plane Normal to the Start Section of the Path

After creating the path, you need to create a work plane normal to the start section of the path and position it at the start point of the path. A work plane is used to draw profile for a sweep feature. The start section of the path can be either the horizontal line or the vertical line of 35 mm length. In this tutorial, the horizontal line is taken as the start section of the path.

1. Choose the **Normal to Axis through Point** tool from **3D Model > Work Feature > Plane** drop-down; you are prompted to select an edge/axis or a point.
2. Select the line that is at the bottom-left of the sketch and then click on its endpoint.

As soon as you select the start point of the line, a work plane normal to the line is created and is positioned at the start point of the line. The work plane at the start point of the path is shown in Figure 8-142.




Figure 8-141 Isometric view of the Path for the sweep feature




Figure 8-142 Work plane normal to the path

Drawing the Profile of the Sweep Feature

The profile of the sweep feature will be created on the new work plane.

Therefore, you need to define a sketch plane on the new work plane.

1. Choose the **Start 2D Sketch** tool from **3D Model > Sketch** drop-down and then select the new work plane as the sketching plane.

As soon as you select the new work plane as the plane for sketching, the sketching environment is invoked. Notice that the origin of the Sketching environment coincides with the start point of the start section of the path. This helps you position the profile of the sweep feature.

2. Draw a circle of 97 mm diameter as the profile of the sweep feature. Take the center of the circle as the origin of the Sketching environment. Exit the sketching environment and change the view to the isometric view, if required. The profile of the sweep feature is shown in Figure 8-143.

Sweeping the Profile

1. Choose the **Sweep** tool from the **Create** panel of the **3D Model** tab; the profile of the sweep feature is selected automatically in the Graphics window. Also, the **Path** button is chosen in the **Sweep** dialog box and you are prompted to select the path.
2. Select the path and then choose **OK** from the **Sweep** dialog box. The sweep feature after changing the viewing direction is shown in Figure 8-144.




Figure 8-143 Profile of the sweep feature




Figure 8-144 The sweep feature

Creating the Shell Feature

The shell feature scoops out material from the sweep feature and leaves behind a model with some wall thickness. You need to remove the left and top faces of the sweep feature to view the cavity inside.

1. Choose the **Shell** tool from the **Modify** panel of the **3D Model** tab; the **Shell** dialog box is displayed and you are prompted to select the surfaces to be removed. Next, select the **Inside** option from the **Shell** dialog box to define the direction of shell creation which is inwards of the model.
2. Select the left and top faces of the sweep feature; the selected faces are highlighted in blue. The diameter of the inner cavity is 65 mm and the diameter of the sweep feature is 97 mm. As a result, the wall thickness comes out to be 16 mm.
3. Enter **16** in the **Thickness** edit box and choose the **OK** button. The model after creating the shell feature is shown in Figure 8-145.

*Tip. An alternative way of creating the shell feature is by using the **Sweep** tool. In case of **Sweep** tool, you need to create a path curve and two concentric circles of required size. When you sweep both circles along the path curve, the inner circle is subtracted from the outer one. This way the inner cavity can be created automatically. In this tutorial, you will use the **Shell** tool to create the inner cavity.*

Creating the Remaining Features

1. Create the remaining features by defining new sketch planes at the left face of the first feature that you created. Draw a circle of 225 mm. Exit the Sketching environment and then extrude the circle to a distance of 25 mm. For dimensions, refer to Figure 8-140b. Similarly, create the same feature on the top face of the first feature.
2. Select the back face of the feature that you created in the last step. Draw a circle of 129 mm diameter and extrude it to the depth of 16 mm in the required direction. Next, create a fillet of 16 mm on the outer edge of this feature.

The join feature at the cylindrical tangent surface can be created by defining an offset work plane. You can create a hole on the join feature by using the **Hole** tool. Similarly, create a hole on the top and bottom features of the model and then create the pattern of these holes. The final model for Tutorial 1 is shown in Figure 8-146.




Figure 8-145 Model after creating the shell feature




Figure 8-146 Final model for Tutorial 1

3. Save the model with the name *Tutorial1.ipt* at the location *C:\Inventor_2016\c08* and close the file.
-

Tutorial 2

In this tutorial, you will create the model of the Joint shown in Figure 8-147a. Its dimensions are shown in Figures 8-147b and 8-147c. The threads to be created are ANSI Metric M Profile of size 14 and designation M14x2. The class of the threads is 6g. Make sure the threads are right-handed. **(Expected time: 30 min)**




Figure 8-147a Solid model of the Joint




Figure 8-147b Left side view of the model




Figure 8-147c Front view of the model

The following steps are required to complete this tutorial:

- a. Create the base feature of the model on the YZ plane, refer to Figure 8-148.
- b. Create the cut feature, refer to Figure 8-149.
- c. Create the cylindrical join feature on the left face and then create the chamfer feature.
- d. Finally, create threads on the cylindrical join feature using the **Thread** tool.

Creating the Base Feature

1. Create the base feature of the model on the YZ plane, as shown in Figure 8-148. For dimensions of the base feature, refer to Figures 8-147b and 8-147c.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.
2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Creating the Cut Feature in the Base Feature

1. Create the cut feature by defining a sketch plane on the right face of the base feature, as shown in Figure 8-149. For dimensions of the cut feature, refer to Figure 8-147b.




Figure 8-148 Base feature for the model




Figure 8-149 Model after creating the cut feature

Creating the Join and Chamfer Features

1. Create the cylindrical join feature, as shown in Figure 8-150. For dimensions,

refer to Figures 8-147b and 8-147c.

2. Create the chamfer feature on the end face of the cylindrical feature using the **Distance and Angle** button of the **Chamfer** dialog box, refer to Figure 8-151. For dimensions, refer to Figure 8-147c.




Figure 8-150 Model after creating the join feature




Figure 8-151 Model after chamfering

Creating Threads

1. Choose the **Thread** tool from the **Modify** panel of the **3D Model** tab to invoke the **Thread** dialog box. Select the cylindrical join feature; the preview of threads is displayed on the model.
2. In the **Thread Length** area of the **Location** tab, clear the **Full Length** check box. Next, enter **34** in the **Length** edit box.
3. Choose the **Specification** tab to display the options related to the specifications of the threads. Select **ANSI Metric M Profile** from the **Thread Type** drop-down list and **14** from the **Size** drop-down list.
4. Select **M14x2** from the **Designation** drop-down list and **6g** from the **Class** drop-down list. Make sure that the **Right hand** radio button is selected. Choose **OK** from the dialog box to create the threads. The model after creating threads is shown in Figure 8-152.




Figure 8-152 Final model for Tutorial 2

5. Save the model with the name *Tutorial2.ipt* at the location *C:\Inventor_2016\c08* and then close the file.

Tutorial 3

In this tutorial, you will create the model of the Nut shown in Figure 8-153a. Its dimensions are shown in Figure 8-153b. The threads to be created are ANSI Metric M Profile with the designation M10x1.5. The class of threads is 6H and it

is a right-handed thread.
(Expected time: 30 min)



Figure 8-153a Model of the Nut with threads




Figure 8-153b Dimensions of the Nut

The following steps are required to complete this tutorial:

- Create the base feature, refer to Figure 8-154.
- Create a hole concentric with the base feature, refer to Figure 8-155.
- Fillet the top and bottom faces of the cylindrical feature, refer to Figure 8-156.
- Define a new sketch plane on the top face of the base feature. Draw a hexagon on this plane and extrude it using the **Intersect** operation, refer to Figure 8-157.
- Finally, create internal threads using the **Thread** tool, refer to Figure 8-158.

Creating the Base Feature

1. Create the base feature (cylinder) of the Nut on the XY plane, as shown in Figure 8-154. The diameter of the cylinder is 20 mm.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.
2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

Creating the Hole Feature Concentric with the Base Feature

1. Invoke the **Hole** tool and create a through hole of diameter 10 mm on the base feature. Figure 8-155 shows the hole feature created on the base feature.




Figure 8-154 Base feature of the Nut




Figure 8-155 Model after creating the hole feature

Filleting the Top and Bottom Edges

1. Fillet the top and bottom edges of the model using the **Fillet** tool. The radius of the fillet is 3 mm. The model after creating the fillets is shown in Figure 8-156.



Figure 8-156 Model after creating fillets at the top and bottom edges

Creating the Intersect Feature

The next feature is the intersect feature. You need to create this feature by defining a new sketch plane on the top or bottom face of the model. After defining the sketch plane, you will draw an inscribed hexagon.

1. Define a new sketch plane on the top face of the base feature. Draw an inscribed hexagon on the new sketch plane.

The diameter of the circle in which the hexagon is inscribed should be equal to the diameter of the base feature.

2. Exit the Sketching environment. Extrude the sketch using the **Intersect** operation and the **All** extents. The model after creating the cut feature is shown in Figure 8-157.

Creating Threads

1. Choose the **Thread** tool from the **Modify** panel of the **3D Model** tab to invoke the **Thread** dialog box.
2. Select the hole as the face for creating threads.
3. Choose the **Specification** tab and select **ANSI Metric M Profile** from the **Thread Type** drop-down list.
4. Select **10** from the **Size** drop-down list and **M10x1.5** from the **Designation** drop-down list.
5. Select **6H** from the **Class** drop-down list and select the **Right hand** radio button, if it is not selected.
6. Choose **OK** to exit the **Thread** dialog box and create threads. The final model after creating threads is shown in Figure 8-158.




Figure 8-157 Model after creating the intersect feature




Figure 8-158 Final model of Nut

7. Save the model with the name *Tutorial3.ipt* at the location *C:\Inventor_2016\c08* and then close the file.
-

Tutorial 4

In this tutorial, you will create the model shown in Figure 8-159a. Its dimensions are shown in Figures 8-159b and 8-159c. After creating the model, apply a face draft of 1 degree on its left and right faces. The angle for the face draft should be 1 degree. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- a. Create the base feature with a hole on the YZ plane, refer to Figure 8-160.
- b. Add cut features and holes to the base feature, refer to Figure 8-161.
- c. Create the face draft by selecting the top face of the model as the pull direction.
- d. Finally, create the fillet of radius 2 mm.

Creating the Base Feature

1. Create the base feature of the model on the YZ plane, as shown in Figure 8-160. For dimensions of the base feature, refer to Figures 8-159b and 8-159c.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.

2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.




Figure 8-159a Model for Tutorial 4




Figure 8-159b Front view of the model




Figure 8-159c Right-side view of the model

Creating the Cut Features

1. Create the cut features on the model. Figure 8-161 shows the model after creating the cut features. For dimensions of the cut features, refer to Figures 8-159b and 8-159c.

Adding the Face Draft

1. Choose the **Draft** tool from the **Modify** panel of the **3D Model** tab to invoke the **Face Draft** dialog box.
2. Choose the **Fixed Plane** button; you are prompted to select the planar face or the work plane.
3. Select the top face of the model as the pull direction and make sure the arrow points downward. If the arrow points upward, choose the **Flip pull direction** button located on the right of the **Fixed Plane** button to reverse the direction.




Figure 8-160 Base feature of the model




Figure 8-161 Model after creating the cut features

As soon as you specify the pull direction, the **Faces** button is chosen and you are prompted to select the faces to draft.

4. Select both side faces one by one, refer to Figure 8-162.

5. Change the value of the draft angle in the **Draft Angle** edit box to **1** and then choose **OK**; the **Face Draft** dialog box is closed and the face draft is applied to the model.
6. Add a fillet of radius 2 mm to the edges on the bottom face of the model. The final model for Tutorial 4 is shown in Figure 8-163.
7. Save the model with the name *Tutorial4.ipt* at the location *C:\Inventor_2016\c08* and then close the file.




Figure 8-163 Final model for Tutorial 4




Figure 8-162 Selecting the options for the face draft

Tutorial 5

In this tutorial, you will create the solid model of the receiver of a phone shown in Figure 8-164a. The dimensions of Section 1 and Section 2 of the receiver are

shown in Figures 8-164b and 8-164c. Section 3 is a mirror image of Section 1, but you need to create it separately as an individual sketch. **(Expected time: 45 min)**



Figure 8-164a Solid model of the receiver




Figure 8-164b Dimensions of Section 1




Figure 8-164c Dimensions of Section 2

The model consists of three sections blended together using the **Loft** tool. Section 1 is created on the XZ plane; Section 2 on the XY plane; and Section 3

on the XZ plane. However, you will create Section 3 below the origin. To maintain accuracy while creating these sections, you need to dimension them with reference to the origin point. Next, you need to dimension the section with respect to the origin.

The following steps are required to complete this tutorial:

- a. Start a new metric template file and draw the sketch for Section 2 on the XY plane. As sketches can be created in any sequence while creating a loft feature.
- b. Draw the sketch for Section 1 on the XZ plane. Exit the Sketching environment.
- c. Again, define the sketch plane on the XZ plane and draw the sketch for Section 3.
- d. Exit the Sketching environment and invoke the **Loft** tool. Select three sections to create the loft feature.

Drawing the Sketch for Section 2

1. Start a new metric part file.
2. Choose the **Start 2D Sketch** button from the **Sketch** panel of the **3D Model** tab; the default planes are displayed and you are prompted to select the sketching plane.
3. Choose the **Home** button from the ViewCube; the current orientation of the sketching plane is changed.
4. Now, select the XY plane as the sketching plane from the graphics window; the Sketching environment is invoked and the XY plane becomes parallel to the screen.
5. Draw the sketch for Section 2 on the XY plane. Dimension it with respect to the origin (0,0,0). Refer to Figure 8-164c for the dimensions of Section 2.
6. Exit the Sketching environment.

Note

*If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

Drawing the Sketch for Section 1

1. Define a new sketch plane on the XZ plane.
2. Draw the sketch for Section 1 and dimension it with respect to the origin. Refer to Figure 8-164b for the dimensions of Section 1.
3. Exit the sketching environment.

Drawing the Sketch for Section 3

The sketch for Section 3 is the mirror image of the sketch of Section 1.

1. Define a new sketch plane on the XZ plane.
2. Draw the sketch for Section 3 and dimension it with respect to the origin.
3. Exit the sketching environment. The three sketches are shown in Figure 8-165.

Blending Sections Using the Loft Tool

You need to blend the sections using the **Loft** tool.

1. Choose the **Loft** tool from the **Create** panel of the **3D Model** tab; the **Loft** dialog box is invoked and you are prompted to select a sketch.

In this dialog box, the **Curves** tab is chosen by default.

2. Select Section 1 as the first sketch; the sketch is highlighted in blue and you are prompted again to select a sketch.
3. Select Section 2 and then Section 3; the preview of the feature is displayed in

the drawing window. However, this is not the kind of feature you require. You need to add some weight at the start and end sections.

4. Choose the **Conditions** tab; an arrow appears on the left of Sketch3 in the **Conditions** area of this tab. This indicates that the settings that you configure will be for this sketch.
5. Choose the **Direction Condition** option from the drop-down list (end condition) in this tab. This option allows you to add direction conditions at the start and end sections.
6. Enter 5 in the **Weight** edit box. This value is for the end section.
7. Next, select Sketch2 from the **Conditions** area and then choose the **Direction Condition** option.
8. Enter 5 in the **Weight** edit box. This value is for the start section. Choose **OK** to create the loft feature.
9. Apply the **Blue-Glazing** color to the model. Change the viewing direction of the model. The model of the receiver is shown in Figure 8-166.
10. Save the model with the name *Tutorial5.ipt* at the location *C:\Inventor_2016\c08* and then close the file.




Figure 8-165 Sketches of three sections



Figure 8-166 Solid model of the receiver

Self-Evaluation Test

Answer the following questions and then compare them to those given at the end of this chapter:

1. The _____ method is used to create a spiral coil in a single plane.
2. You can trim a solid by using the _____ button from the **Split** dialog box.
3. In Autodesk Inventor, features are reordered using the _____.
4. _____ is applied to the faces of a model so that it can be removed easily from casting.
5. You can create face drafts by using a fixed _____ or _____.
6. If the faces on which you want to apply the face draft have some _____, they will be selected automatically for applying the face draft.
7. To create a solid sweep feature, the profile should be a closed sketch. (T/F)
8. The lofted features are created by blending more than one dissimilar geometry. (T/F)

9. You can apply different wall thicknesses to different faces of a shell feature. (T/F)
10. You need to select the **Area Loft** radio button to create a lofted feature with varying cross-sections at required points on a centerline. (T/F)

Review Questions

Answer the following questions:

1. The _____ operation of the **Coil** tool can also be used to create internal or external threads in a model.
2. In Autodesk Inventor, the _____ tool is used to split the faces of models or a complete model.
3. The _____ dialog box is used to create external or internal threads directly.
4. The _____ tool is used to combine more than one surface into a single surface.
5. _____ is defined as a process of scooping out material from a model and making it hollow.
6. Which of the following options is used to create a coil in a single plane?
(a) **Revolution and Height** (b) **Pitch and Revolution**
(c) **Spiral** (d) **Pitch and Height**
7. Which of the following check boxes in the **Delete Face** dialog box needs to be selected to recover faces by extending adjacent faces?
(a) **Heal** (b) **Delete**
(c) **Remove** (d) None of these
8. Which of the following check boxes in the **Thread** dialog box needs to be selected to create threads through the length of the selected face?
(a) **Length** (b) **Full Length**
(c) **Full** (d) None of these

9. Which of the following check boxes needs to be cleared in the **Thread** dialog box to turn off the display of threads in a solid model?

- (a) **Display in Model** (b) **Display**
- (c) **Off** (d) None of these

10. Which of the following check boxes needs to be cleared to enable the **Point Set** area?

- (a) **Display in Model** (b) **Automatic Mapping**
- (c) **Merge Tangent Faces** (d) None of these




Figure 8-167c Left side view of the model




Figure 8-167d Sectioned front view of the model

Exercise 2

Create a solid model of the hexagonal Cap Screw shown in Figure 8-168a. Its dimensions are shown in Figure 8-168b. The threads to be created are ANSI Metric M Profile of size 10 and designation M10x1.5. The class of threads is 6g. Make sure the threads are right-handed. **(Expected time: 30 min)**



Figure 8-168a Solid model of the Cap Screw




Figure 8-168b Dimensions of the Cap Screw

Answers to Self-Evaluation Test

1. Spiral, 2. Trim Solid, 3. Browser Bar, 4. Face draft, 5. edge, plane, 6. tangent faces, 7. T, 8. T, 9. T, 10. T

Chapter 9

Assembly Modeling-I

Learning Objectives


After completing this chapter, you will be able to:

- Understand the concept of the bottom-up and top-down assemblies.

- ***Create components of the top-down assemblies in the assembly file.***
- ***Insert components of the bottom-up assemblies in the assembly file.***
- ***Understand various assembly constraints and use them to assemble components.***
- ***Move and rotate individual components in the assembly file.***
- ***Use constraint limits to assemble components.***

ASSEMBLY MODELING

An assembly design consists of two or more components assembled at their respective working positions. In Autodesk Inventor, the components of the assembly can be bound using the parametric assembly constraints. As the assembly constraints are parametric in nature, you can modify or delete them whenever you want. In Autodesk Inventor, the assemblies are created in the **Assembly** module. To proceed to the **Assembly** module, invoke the **Create New File** dialog box and open the **Standard (mm).iam** file, as shown in Figure 9-1.



*Figure 9-1 Opening a new assembly file from the **Metric** tab of the **Create New File** dialog box*

When you select the assembly file, the Assembly environment is activated. The screen display of Autodesk Inventor in the **Assembly** module is shown in Figure 9-2. This figure displays the **Browser Bar** and various tools in the **Assemble** tab.

Note

*When you enter the **Assembly** module, you will notice that only some of the tools are active in the **Assemble** tab. The other tools in this tab will become active only when you insert or create a component.*

TYPES OF ASSEMBLIES

In Autodesk Inventor, you can create two types of assemblies: top-down assemblies and bottom-up assemblies. Both these assemblies are discussed next.

Top-down Assemblies

A top-down assembly is an assembly whose components are created within the assembly file. In this type of assembly, first the components are created in the assembly file and then assembled using the assembly constraints. The process of creating the components in the **Assembly** module of Autodesk Inventor is designed in such a way that the components you create in the **Assembly** module are also saved as individual parts or assembly files. This eliminates the risk of losing the individual components, in case there is an error in the assembly file. Also, the assembly file contains the information related to only the assembly, which helps in keeping the size of the assembly file to the minimum.




Figure 9-2 Interface screen of the Assembly module

Bottom-up Assemblies

A bottom-up assembly is an assembly whose components are created as separate part files and are referenced in the assembly file as external components. In this type of assembly, the components are created in the **Part** module as part files (.ipt). Once all components of the assembly are created, you will open an assembly file (.iam) and then insert all the component files using the tools in the

Assembly module. After inserting the components, they are assembled using the assembly constraints. Because the assembly file has information related only to the assembling of components, this file size is not large and requires less storage space.

Note

*An assembly that uses a combination of bottom-up and top-down approaches is called a middle-out assembly. Also, if a component referenced in the assembly is moved from its original location, it will not show up when you open the assembly next time. Autodesk Inventor will look for the component only in the folder in which it was originally stored. If the component is not found at its original location, then the **Resolve Link** dialog box will be displayed. In this dialog box, you need to specify the new location of the component.*

CREATING TOP-DOWN ASSEMBLIES

As mentioned earlier, in top-down assemblies, all components are created within the assembly file. To create the components, you require the environment where you can draw the sketches of the sketched features and also the environment where you can convert the sketches into features. In other words, to create the components in the assembly file, you require the Sketching environment and the Part modeling environment. Autodesk Inventor provides you the liberty of invoking both these environments in the **Assembly** module by using the **Create** tool. The use of this tool is discussed next.

Creating Components in the Assembly Module Ribbon:
Assemble > Component > Create In Autodesk Inventor,
you can create components in the **Assembly** module. One of the advantages of creating the components in the **Assembly** module is that these components can also be saved as a separate part file (*.ipt*) or an assembly file (*.iam*). Therefore, if you again need any of the components created in the **Assembly** module, you can use the individual part or assembly file. The components in the **Assembly** module are created using the **Create** tool. When you invoke this tool, the **Create In-Place Component** dialog box will be displayed, as shown in

Figure 9-3. The options in this dialog box are discussed next.




Figure 9-3 The *Create In-Place Component* dialog box

New Component Name

The **New Component Name** text box is used to specify the name of the component to be created.

Template

The **Template** drop-down list is used to select the template for the new file. There are four default templates in this drop-down list: **Sheet Metal.ipt**, **Standard.iam**, **Standard.ipt**, and **Weldment.iam**. You can also select the template by choosing the **Browse Templates** button on right of the **Template** drop-down list. On choosing this button, the **Open Template** dialog box will be displayed, as shown in Figure 9-4. Select the **Standard.iam** template and then choose **OK** to start a new assembly file. Alternatively, double-click on the **Standard.iam** template to start a new assembly file.

Tip. The assembly template is used to create smaller assemblies that consist of a few components. These smaller assemblies can be assembled later in a separate assembly file to form the main assembly.




Figure 9-4 The **Open Template** dialog box

New File Location

The **New File Location** edit box is used to specify the location for saving the new file. You can either specify the location in this edit box or choose the **Browse to New File Location** button provided on the right of the edit box to specify the location. When you choose this button, the **Save As** dialog box will be displayed, as shown in Figure 9-5. Using this dialog box, you can select the folder in which you want to save the new file.




Figure 9-5 The Save As dialog box

Default BOM Structure

This drop-down list is used to specify the type of Bill of Material (BOM) structure for the new component. You will learn more about BOM structure in the next chapter.

Virtual Component

This check box is used to create a virtual component only for the purpose of adding a row in the BOM.

After setting all options in the **Create In-Place Component** dialog box, choose **OK**; you will be prompted to select a sketch plane for the base feature. Select a plane; the Part modeling environment will be invoked. Next, invoke the Sketching environment by choosing the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab and then select the desired plane. Next, draw the sketch for the base feature of the model. After creating the sketch, choose the **Finish 2D Sketch** option from the Marking menu or choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab. On doing so, the Sketching environment will be exit and the part modeling environment will be activated with all part modeling tools. Once you have created the part using the Sketching and the Part modeling environments, you can switch back to the **Assembly** module by choosing the down arrow below the **Return** tool in the **Return** panel of the **3D Model** tab. On doing so, a flyout will be displayed. Choose the **Return to Top** option from the flyout; the **3D Model** tab will be replaced by the **Assemble** tab and all tools in this tab will be activated.

The alternative method of switching from the **Part** module to the **Assembly** module is using the **Quick Access Toolbar**. In this method, first you need to create a sketch and then click on the down arrow on the right of the **Return** tool in the **Quick Access Toolbar**. On doing so, a flyout will be displayed. Choose the **Return to Parent** option from the flyout; the Part modeling environment will be activated. Create the component and then click on the down arrow on the right of the **Return** tool again; a flyout will be displayed. Choose the **Return to Top** option from the flyout to switch back to the **Assembly** module.

Note To add the **Return** tool in the **Quick Access Toolbar**, you need to select it from the **Customize Quick Access Toolbar** drop-down.

In this way, you can create as many components as you want in the assembly. Once all the components are created, you can start assembling them using the assembly constraints.

Tip. In the **Browser Bar**, you can easily distinguish between a grounded and an ungrounded component. A grounded component will have a push pin icon on the left of its name in the **Browser Bar**. To make a grounded component ungrounded, right-click on the grounded component in the **Browser Bar**. You will notice a tick mark in front of the **Grounded** option in the shortcut menu. To unground the component, choose this option; the push pin icon will be replaced with the original part icon, suggesting that the component is now ungrounded.

CREATING BOTTOM-UP ASSEMBLIES

As mentioned earlier, in the bottom-up assemblies, the components are created as separate part files. All the individual part files are then inserted in an assembly file and are assembled using the assembly constraint. The first component inserted in the assembly will be grounded and its origin will coincide with that of the assembly file. Also, the three default planes of the part file will be placed in the same orientation as that of the default planes of the assembly file. The individual components are inserted in the assembly file using the **Place** tool. This tool is discussed next.

Placing Components in the Assembly File Ribbon:

Assemble > Component > Place The **Place** tool is used to insert an inventor file in the current assembly file. On invoking this tool, the **Place Component** dialog box is displayed, as shown in Figure 9-6. This dialog box is similar to the **Open** dialog box used for opening the files. In this dialog box, you can also preview the component before inserting it in the current assembly file. The file type you want to insert can be selected from the **Files of type** drop-down list.




Figure 9-6 The Place Component dialog box

Select the file to be inserted from this dialog box and then choose the **Open** button; the selected component will be attached to the cursor and you will be prompted to place an instance of the selected component. Click in the graphics area to specify the placement point for the first instance of the component; the component will be placed in the graphics area and one more instance of the same component will be attached with the cursor. It means that you can place as many copies of the selected component as you want by specifying the points on the screen.

By default, the components you will place in the graphics area are floating components whose all the DOFs are free. In Autodesk Inventor, you can also ground the components with the assembly origin while inserting them in the graphics area. To do so, while inserting a component, right-click in the drawing area and choose the **Place Grounded at Origin** option from the Marking menu displayed. Next, click in the graphic area; the component will be placed as a grounded component and its origin will coincide with the origin of the assembly. A grounded component is a component whose all the degrees of freedom are fixed. Once you have placed the required number of instances of the component, right-click to display a Marking menu and then choose the **OK** option from it.

Tip. While inserting a component in the graphics area, you can change the orientation of the component by rotating it at 90-degree increments about X, Y,

and Z axes. To do so, right-click in the drawing area; a Marking menu will be displayed. Choose the required option from the Marking menu.

Similarly, you can place other components in the assembly. However, remember that if one or more components are already placed in the current assembly file, then no instance of the selected component will be placed automatically and, therefore, you will have to manually specify the location of the first instance of the component.

Note

*In Autodesk Inventor, you can also specify settings so that the first component placed in the assembly file is grounded automatically. To do so, choose the **Application Option** tool from the **Option** panel of the **Tool** tab; the **Application Option** dialog box will be displayed. Next, choose the **Assembly** tab from this dialog box and select the **Place and ground first component at origin** check box. Next, choose the **Apply** button.*

*Tip. There are two more methods to place a component in an existing assembly file. In the first method, you need to open a part file and then choose the **Tile All** tool from **View > Windows > Tile** drop-down. On doing so, both the assembly and part files will be displayed on the screen. Alternatively, choose the **Arrange** button available below the Graphics window. This button will be available only when you open multiple files that may include part files or assembly files. Now, click on the name of a part in the **Browser Bar** and drag and drop the part file in the assembly window. In the second method, you can drag and drop the part file from the Windows Explorer to the current assembly.*

ASSEMBLING COMPONENTS BY USING THE CONSTRAIN TOOL RIBBON: ASSEMBLE > RELATIONSHIPS > CONSTRAIN IN AUTODESK INVENTOR, THE COMPONENTS ARE ASSEMBLED USING FIVE TYPES OF ASSEMBLY CONSTRAINTS, TWO TYPES OF MOTION CONSTRAINTS, AND A TRANSITIONAL CONSTRAINT. ALL THESE CONSTRAINTS ARE AVAILABLE IN THE **PLACE CONSTRAINT** DIALOG BOX THAT IS DISPLAYED ON CHOOSING THE **CONSTRAIN** TOOL. THE DIALOG BOX CONSISTS OF DIFFERENT TABS AND EACH OF THEM HAS ONE OR MORE TYPES OF


CONSTRAINTS. THESE TABS AND THEIR RESPECTIVE CONSTRAINTS ARE DISCUSSED NEXT.

Assembly Tab

This tab is activated by default in the **Place Constraint** dialog box. The constraints that can be applied using this tab are displayed in the **Type** area. When you choose a constraint from this area, the options in these areas are also changed. The constraints in the **Type** area and their respective options displayed in different areas are discussed next.

Mate

You can invoke the Mate constraint by choosing the **Mate** button which is available in the **Type** area of the **Assembly** tab, see Figure 9-7. This constraint is used to make the selected planar face, axis, or point of a component coincident with that of another component. Depending on the solution selected from the **Solution** area, the components will be assembled with the normal of the faces pointing in the same direction or in the opposite direction. When you choose the **Mate** button, various options will be displayed in different areas of the **Assembly** tab of the **Place Constraint** dialog box. These options are discussed next.



*Figure 9-7 The Mate constraint options in the **Assembly** tab of the **Place Constraint** dialog box*


Selections Area

The options in this area are used to select the faces, axes, edges, or points of the selected model for applying the **Mate** constraint. These options are discussed next.

Tip. You can press and hold the F4 key to rotate the view of the model for selection purpose. Later in this chapter, you will learn to rotate the view of an individual component.

1 (First Selection) This button is automatically chosen when you invoke the **Mate** constraint. This button is used to select a face, axis, edge, or point on the first component to apply the **Mate** constraint. Move the cursor close to the component that you want to select. If the cursor is close to a face, it will be highlighted and an arrow will be displayed along with a cross. This arrow will point in the direction of the normal of the selected face. The components are assembled along the normal of the faces. Similarly, if you move the cursor close to an edge, axis, or a point, it will be highlighted.

2 (Second Selection) This button is automatically chosen after you select the first component. It is used to select a face, axis, edge, or point on the second component to apply the **Mate** constraint. Figure 9-8 shows the **Mate** constraint being applied on the faces of two components. In Figure 9-8, notice the arrows displayed on the selected faces of both the components. These arrows point in the direction of the normals of the selected faces. The selected components will be assembled in the direction of these faces.



*Figure 9-8 Applying the **Mate** constraint on the faces of two components*

Pick part first

The **Pick part first** check box is provided on the right side in the **Selections** area. This check box is used for the assembly that has a large number of components and it is difficult to select the axis, edge, face, or point of one of the components due to the complicacy. If this check box is selected, you will first have to select the component and then select the element in that component to apply the constraint.

Note

*You can preview the assembly of the components on the screen after you have selected both the components to apply the constraint. However, remember that until you choose the **Apply** button from the **Place Constraint** dialog box, the constraint will not be actually applied.*

Offset

The **Offset** edit box is used to specify the offset distance between the mating components. If the offset distance is zero, the mating entities will be in contact with each other. If there is an offset distance between the mating components, then they will be placed at a distance from each other. Figure 9-9 shows the components assembled with an offset distance of 0 mm and Figure 9-10 shows the components assembled with an offset distance of 10 mm between the faces.




Figure 9-9 Components assembled with an offset distance of 0 mm




Figure 9-10 Components assembled with an offset distance of 10 mm

Tip. Generally, components are not assembled using a single constraint. Depending on the components, you may require two to three constraints. The same constraint can be applied several times.

Show Preview

The **Show Preview** check box is selected to display the preview of the assembled components. When you select two components to apply the constraint, a preview of the assembly will be displayed in the graphics window even if you have not chosen the **Apply** button. This is because the **Show Preview** check box is selected. If this check box is cleared, the preview of the assembly will not be displayed.

Predict Offset and Orientation

The **Predict Offset and Orientation** check box is selected to allow Autodesk Inventor to predict the offset and the orientation of the selected components. The predicted offset value is automatically specified in the **Offset** edit box.

Solution Area

The buttons in the **Solution** area are used to specify whether the components being assembled should be placed in a mating position or in a flushing position. The options in this area are discussed next.

Mate

Choose this button if you want to position the faces of the components normal to each other. Also, the faces will be coincident. Figure 9-11 shows an assembly assembled using the **Mate** button.

Flush

Choose the **Flush** button if you want to position the faces of the components next to one another in such a manner that normals of their faces point in the same direction. Figure 9-12 shows an assembly assembled using the **Flush** button.




Figure 9-11 A mating position




Figure 9-12 A flushing position

Angle Constraint

This is the second constraint from the left in the **Type** area of the **Assembly** tab. This constraint is used to specify the angular position of the selected planar faces or edges of two components. Figure 9-13 shows the options that will be displayed in various areas when you choose the **Angle** button. Some of the options in this constraint are the same as those discussed in the Mate constraint. The remaining options are discussed next.

Selections Area

The first two buttons in this area have been discussed earlier in the **Mate** Constraint heading.

3 (Third Selection)

The **3 (Third Selection)** button will be enabled only when you choose the **Explicit Reference Vector** button from the **Solution** area. This button is used to select a face, an edge, an axis, or a work plane to apply the **Angle** constraint.




Figure 9-13 The Angle constraint options in the Assembly tab of the Place Constraint dialog box

Angle

This edit box is used to specify the angle between the selected planar faces or edges of two components. The components will be separated by an angle value specified in this edit box. You can specify a positive or a negative value in this edit box.

Solution Area

The options in this area that are displayed on choosing the **Angle** button from the **Type** area are discussed next.

Directed Angle

Choose the **Directed Angle** button when you want to apply angle in the counter-clockwise direction.

Undirected Angle This button is available while applying angle constraint. You can choose this button to constrain the orientation of the component in both the directions about the default alignment.

Explicit Reference Vector Choose this button when you want to allow the movement of the component in the explicit Z direction. Choosing this button also allows you to limit the tendency of angle constraint to switch to an alternative solution.

Figure 9-14 shows the components selected to apply the **Angle** constraint and Figure 9-15 shows the components after applying the **Angle** constraint of 90 degrees. Figure 9-16 shows the vertical component selected using the **Explicit Reference Vector** button to apply the **Angle** constraint and Figure 9-17 shows the components at an angle of 90 degrees after using the **Explicit Reference Vector** button.







Figure 9-14 Selecting the faces to apply the **Angle** constraint



*Figure 9-15 Components after applying the **Angle** constraint of 90 degrees*



*Figure 9-16 Selecting the third face to apply the **Angle** constraint*




*Figure 9-17 Components after applying the **Angle** constraint by using the **Explicit Reference Vector** button*

Note

*The options in the **Place** constraint dialog box for applying the **Angle** constraint are same as those discussed in the **Mate** constraint.*

Tangent Constraint

You can invoke the **Tangent** constraint by choosing the **Tangent** button in the **Type** area of the **Assembly** tab. This constraint forces the selected circular face of the component to become tangent to the circular or planar face of the other component. The options that are displayed when you choose the **Tangent** button are shown in Figure 9-18. Some of the options are similar to those discussed earlier. The remaining options are discussed next.



*Figure 9-18 The **Tangent** constraint options in the **Assembly** tab of the **Place Constraint** dialog box*

Solution Area

The **Solution** area provides the **Inside** and **Outside** buttons for the **Tangent** constraint in the **Type** area of the **Assembly** tab. These buttons are discussed next.


Inside

If you choose this button, the component selected first will be placed inside the component that will be selected later at a point that is tangent to both the components.


Outside

When you choose this button, the component that you select first will be placed outside the component that will be selected later at a point that is tangent to both the components.

Figure 9-19 shows the **Tangent** constraint applied with the **Inside** button chosen and Figure 9-20 shows the **Tangent** constraint applied with the **Outside** button chosen.




*Figure 9-19 The **Tangent** constraint with the **Inside** button chosen*



*Figure 9-20 The **Tangent** constraint with the **Outside** button chosen*

Insert Constraint

Choose the **Insert** button from the **Type** area of the **Assembly** tab to apply the **Insert** constraint. This constraint is used to force two different cylindrical or conical components or features of components to share the same location and orientation of the central axis. This constraint also makes the selected face of the first component coplanar with the selected face of the second component. The options in various areas displayed on choosing the **Insert** button in the **Assembly** tab are shown in Figure 9-21. These options are discussed next.



*Figure 9-21 The **Insert** constraint options in the **Assembly** tab of the **Place Constraint** dialog box*

Solution Area

The options provided in the **Solution** area are used to specify whether the normal of the mating faces will point in the same direction or in the opposite directions. The options available in this area displayed on choosing the **Insert** constraint are discussed next.

Opposed

If you choose this button, the mate direction of the first selected component will be reversed. You can also apply limits and resting positions to both the components.

Aligned

If you choose this button, the mate direction of the second selected component will be reversed. You can also apply limits and resting positions to both the components.

Figure 9-22 shows two edges selected for applying the **Insert** constraint. Figure 9-23 shows an assembly after the **Insert** constraint is applied.




Figure 9-22 Selecting the components for applying the **Insert** constraint




Figure 9-23 Components after applying the **Insert** constraint

Note

The remaining options in the **Tangent** and **Insert** constraints are same as those discussed in the **Mate** constraint.

Symmetry Constraint This constraint is used to make two components symmetric about a plane. To apply this constraint, choose the **Symmetry** button from the **Type** area of the **Assembly** tab; you will be prompted to select first geometric entity. You need to select two entities from the two components to which you want to apply the **Symmetric** constraint. The entities can be edges, vertices, planar faces and so on. Select an entity of the first component; you will be prompted to select the second geometric entity. Select an entity of the second component; you will be prompted to select the symmetric plane. Select the symmetric plane; both the components will become symmetric about the symmetric plane. You can observe the effect of the constraint in the preview. The options displayed in various areas on choosing the **Symmetry** button in the **Assembly** tab are shown in Figure 9-24. Figure 9-25 shows the selected faces and plane for applying the **Symmetry** constraint. Figure 9-26 shows an assembly after the Symmetry constraint is applied.




Figure 9-24 The **Symmetry** constraint options in the **Assembly** tab of the **Place Constraint** dialog box




Figure 9-25 *Selecting the components for applying the **Symmetry** constraint*





Figure 9-26 *Components after applying the **Symmetry** Constraint*

Motion Tab

The **Motion** tab is the second tab in the **Place Constraint** dialog box. The options in this tab are used to specify the rotational and translation motions of the two components. The constraints that can be applied using this tab are displayed in the **Type** area. Depending on the constraint chosen from this area, the options in this area are changed. The constraints and their respective options displayed in other areas are discussed next.

Rotation Constraint

The **Rotation** constraint is invoked by choosing the **Rotation** button in the **Type** area of the **Motion** tab. This constraint is used to rotate one of the components with respect to other component at the specified ratio. The components rotate about the specified central axis. To apply this constraint, choose the **Rotation** button from the **Type** area of the **Motion** tab; you will be prompted to select the first geometric component to constrain. Select the central axis of the first component; you will be prompted to select the second geometric component. Select the central axis of the second component. Click **Apply** to continue to place constraints or click **OK** to create the constraint and close the dialog box. The options that are displayed in various areas when you choose the **Rotation** button from the **Type** area are shown in Figure 9-27. These options are discussed next.



*Figure 9-27 The **Rotation** constraint options in the **Motion** tab of the **Place Constraint** dialog box*

Ratio

The **Ratio** edit box is used to specify the ratio by which the second component will rotate with respect to one complete rotation of the first component. For example, if you enter **2** in this edit box and then rotate the first component once, then the second component will rotate twice. Similarly, if you enter **10** and then rotate the first component once, the second component will rotate ten times.

Solution Area

The options in the **Solution** area are used to specify the direction of rotation of the components. The buttons in this area displayed on choosing the **Rotation** constraint are **Forward** and **Reverse**. The buttons are discussed next.

Forward

If you choose this button, the mating components will be allowed to rotate in the same direction.

Reverse

If you choose this button, the mating components will be allowed to rotate in the reverse direction.

Note

1. To view the results after applying the **Rotation** constraint, you need to move the first component by dragging it. The constraints in the **Motion** tab of the **Place Constraint** dialog box work only with the unrestricted degree of freedom. These constraints do not interfere with the other assembly constraints.
2. The remaining options in the **Rotation** constraint are the same as those discussed in the **Mate** constraint.

Rotation-Translation Constraint

The **Rotation-Translation** constraint is invoked by choosing the **Rotation-Translation** button in the **Type** area of the **Motion** tab. This constraint is used to rotate the first component in relation with the translation of the second component. To apply this constraint, the choose **Rotation-Translation** button from the **Type** area of the **Motion** tab; you will be prompted to select the first geometric component. Select a cylindrical face or edge to specify the distance; you will be prompted to select second geometric component. Select a linear face. Click **Apply** to continue placing constraints or click **OK** to create the constraint and close the dialog box. Various options in different areas displayed on choosing the **Rotation-Translation** button from the **Type** area are as shown in Figure 9-28. These options are discussed next.




Figure 9-28 The Rotation-Translation constraint options in the **Motion** tab

Distance

The **Distance** edit box is used to specify the distance by which the second component will move in relation with one complete rotation of the first component. For example, if you enter 2 in this edit box, the second component will move a distance of 2 mm for one complete rotation of the first component.

Solution Area

The buttons in the **Solution** area are used to specify whether the second component will move in the forward direction or the reverse direction for every forward rotation of the first component. Choose the **Forward** button to move the component in the forward direction and the **Reverse** button to move the component in the reverse direction.

The options in the **Selections** area have already been discussed earlier in this chapter.

Transitional Tab

The **Transitional** tab is the third tab in the **Place Constraint** dialog box. The options in this tab are discussed next.

Transitional Constraint

The **Transitional** constraint is invoked by choosing the **Transitional** button from the **Type** area of the **Transitional** tab, see Figure 9-29. This constraint ensures that the selected face of the cylindrical component maintains contact with the other selected face when you slide the cylindrical component. The options in this tab are similar to those discussed in the previous constraints.




Figure 9-29 The Transitional tab with various options

Constraint Set Tab


The **Constraint Set** tab is the fourth tab in the **Place Constraint** dialog box. The constraint available in this tab is discussed next. Figure 9-30 shows the **Place Constraint** dialog box with the **Constraint Set** tab active.

UCS to UCS Constraint


This constraint is used to constrain two UCSs together. You can use this constraint type to locate the X, Y, and Z axes at a point and to constrain together two UCSs of different parts. Note that to use this constraint, you have to create UCS in parts to be constrained in the part modeling environment by using the **UCS to UCS** tool. It allows you to quickly put components together based on the mating UCS axes, points, and planes.

SPECIFYING THE LIMITS FOR CONSTRAINING

In Autodesk Inventor, you can specify the limits (maximum and minimum) for constraining the components. Specifying the limits enables you to define an allowable range for the movement of components which can translate or rotate. You can specify these limits by using the options in the expanded **Place Constraint** dialog box. To expand the **Place Constraint** dialog box, choose the >> button given on the lower right corner of this dialog box; different options will be displayed in this dialog box, refer to Figure 9-31. These options are discussed next.



*Figure 9-30 The UCS to UCS constraint options in the **Constraint Set** tab of the **Place Constraint** dialog box*



*Figure 9-31 The expanded **Place Constraint** dialog box*

Name

This edit box is used to specify a unique name for a constraint. If you leave this edit box blank, the default name will be assigned to the constraint.

Use Offset As Resting Position

Select this check box to use the offset value as the resting position of a constraint with the specified limits. On selecting this check box, the offset value will be used to specify the maximum limit of the constraint.

Maximum

Select this check box to specify the maximum limit of the constraint movement. On selecting this check box, the edit box below this option will be enabled. You can enter the maximum limit of constraint movement in this edit box. To deactivate this edit box, clear the **Maximum** check box.

Minimum

Select this check box to specify the minimum limit of the constraint movement. On selecting this check box, the **Minimum** edit box will be enabled. You can enter the minimum limit of constraint movement in this edit box. To deactivate this edit box, clear the **Minimum** check box.

The constraint with the specified limits will be displayed with a unique specified name along with +/- symbols on its left in the **Browser Bar**. Drag the components to view the effect of the specified maximum and minimum limits on them. On dragging the component, the movement or rotation of the component will be restricted within these specified limits.

ASSEMBLING PARTS BY USING THE ASSEMBLE TOOL RIBBON: ASSEMBLE > RELATIONSHIPS > ASSEMBLE IN AUTODESK INVENTOR, YOU CAN CONSTRAIN THE PARTS BY USING THE **ASSEMBLE** TOOL. THE CONSTRAINT TYPES THAT CAN BE APPLIED USING THIS TOOL CHANGE DEPENDING UPON THE TYPE OF GEOMETRY OR FEATURE YOU HAVE SELECTED. TO DEFINE THE CONSTRAINT USING THIS TOOL, CHOOSE THE **ASSEMBLE** TOOL FROM THE **RELATIONSHIP** PANEL; A MINI TOOLBAR WILL BE DISPLAYED, REFER TO FIGURE 9-32. ALSO, YOU WILL BE PROMPTED TO SELECT THE FIRST GEOMETRY TO CONSTRAIN. SELECT THE GEOMETRY ON THE PART THAT CAN MOVE, REFER TO FIGURE 9-33. IN OTHER WORDS, SELECT THE GEOMETRY ON THE PART THAT IS NOT GROUNDED; THE SELECTED COMPONENT

WILL BECOME TRANSLUCENT AND WILL GET ATTACHED TO THE CURSOR. IF YOU MOVE THE CURSOR TOWARD THE MATCHING GEOMETRY ON THE FIXED PART, THE SELECTED COMPONENT WILL BE SNAPPED TO THE FIXED COMPONENT, REFER TO FIGURE 9-33. ALSO, YOU WILL BE PROMPTED TO SELECT THE SECONDARY GEOMETRY TO CONSTRAIN. SELECT THE GEOMETRY ON THE FIXED/GROUNDED PART FROM THE DRAWING AREA; THE CONSTRAINTS WILL BE DEFINED FOR BOTH PARTS. YOU CAN CHANGE THE TYPE OF CONSTRAINT FROM THE DROP-DOWN LIST AVAILABLE IN THE MINI TOOLBAR. YOU CAN ALSO SPECIFY THE OFFSET VALUE, ANGLE VALUE, OR THE SOLUTION BY USING THE MINI TOOLBAR. AFTER SPECIFYING THE PARAMETERS, CHOOSE **APPLY** AND THEN **OK** FROM THE MINI TOOLBAR; THE PARTS WILL BE ASSEMBLED USING THE SPECIFIED CONSTRAINTS, REFER TO FIGURE 9-34.




Figure 9-32 Fixed component, component to be assembled, and the mini toolbar




Figure 9-33 The selected component snapped to the fixed component




Figure 9-34 Assembled components

Note that at a time, you can constrain only one component with another component by using the **Assemble** tool. If conflicting constraints are found in the parts to be assembled, then the **Relationships Management** dialog box will be displayed, as shown in Figure 9-35. If conflicts exist, then this dialog box will show you the option suggesting to either suppress or to delete the constraints for

resolving the conflicts.



Figure 9-35 The Relationships Management dialog box

USING ALT+DRAG TO APPLY ASSEMBLY CONSTRAINTS

Autodesk Inventor allows you to apply the assembly constraints without invoking the **Place Constraint** dialog box. This is done by pressing the ALT key and then dragging the component. The following steps explain the procedure to apply assembly constraints using the ALT+Drag method.

1. Press and hold the ALT key and then drag the required component toward the component with which it needs to be assembled; the symbol of the **Mate** constraint will be displayed below the cursor. This is because when you use the ALT+Drag method, by default, the **Mate** constraint is applied.
2. Release the ALT key but make sure you do not release the left mouse button. If you release the left mouse button, the constraints cannot be applied. Press SPACEBAR to change the mate position to the flush position. Drag the first component to the component that you want to select as the second component and then release the left mouse button; the assembly constraint will be applied.

APPLYING JOINTS TO THE ASSEMBLY

Ribbon: Assemble > Relationships > Joint **In Autodesk Inventor, you can**

create joints between the components with the help of the Joint tool. Joints are special type of constraints that allow the movement between two components. You can apply different types of joints to the bodies. These joints allow motion between the connected components or the assembly. To apply the joint, choose the Joint tool from the Relationship panel in the Assemble tab; the Place Joint dialog box will be displayed. This dialog box contains the Joint and Limits tabs, refer to Figure 9-36. The options in these tabs are discussed next.




Figure 9-36 The Place Joint dialog box

Joint Tab

This tab is activated by default in the **Place Joint** dialog box. You can apply different types of joints by using the options in the **Type** drop-down list. The options in the **Type** drop-down list are discussed next.

Automatic

This option is selected by default. As a result, the joint will be applied according to the type of entity selected. For example, if you select cylindrical faces of two components, the cylindrical joint will be applied between the components. Figure 9-37 shows two cylindrical faces selected and Figure 9-38 shows cylindrical joint applied between them.




Figure 9-37 *Selecting the components for applying the **Automatic** joint*




Figure 9-38 *Components after applying the **Automatic** joint*

Connect

The options in this area are used to select the entities to be connected. These options are discussed next.

1(First origin)

This button is activated by default and is used to select the entity of the first component. The selected entity can be end points, mid points, or center points of the first component.

2(Second origin)

This button is activated after you select the entity of the first component and is used to select the entity of the second component. The selected entity can be end points, mid points, or center points of the second component.

Flip component

This button is used to change the contact direction of the selected components.

Pick part first

The **Pick part first** check box is provided on the right side in the **Connect** area. This check box is used for the assembly that has a large number of components and it is difficult to select the axis, face, or point of one of the components due to the complexity. If this check box is selected, you will first have to select the component and then select the element in that component to make the connection.

Gap

This edit box is used to specify the offset distance between the two connected components.

Align

The options in this area are used to specify the alignment for assembly. The **First alignment** and **Second alignment** buttons in this area are used to specify the direction of the faces or axis for the first and second components, respectively. The **Invert alignment** button is used to reverse the direction of the alignment.

Name

This text box is used to enter name of the joint or edit an existing name.

Animate

This button is used to animate the mechanism of the components in the assembly. In the **Animate** area, if you change a joint type in the assembly and clear the **Automatic Playing** check box then the preview of the joint behavior will not be displayed in the graphics window. However, if you select this check box then the preview of the changed joint behavior will be displayed.

Rigid

You can create a Rigid joint by selecting the **Rigid** option from the **Type** dropdown list of the **Joint** tab. This joint removes all the degrees of freedom of the component. The Rigid joint is used to fix two parts rigidly. All DOFs between the selected parts get eliminated and they start working as a single component. Welded joints are examples of a Rigid connection. Figure 9-39 shows two points selected and Figure 9-40 shows the Rigid joint applied between them.




Figure 9-39 *Selecting the components for applying the Rigid joint*




Figure 9-40 *Components after applying the Rigid joint*

Note

The remaining options in the Rigid joint are the same as those discussed in the Automatic joint.

Rotational

You can create the Rotational joint by choosing the **Rotational** option from the **Type** drop-down list of the **Joint** tab. The Rotational joint is used to create a joint between two components such that one component rotates with respect to the other component about the common axis. Figure 9-41 shows two points selected and Figure 9-42 shows the Rotational joint applied between them.




Figure 9-41 Selecting the components for applying the Rotational joint




Figure 9-42 Components after applying the Rotational joint

Note

The remaining options in the Rotational joint are the same as those discussed in the Automatic joint.

Slider

You can create the Slider joint by choosing the **Slider** option from the **Type** drop-down list of the **Joint** tab. The Slider joint allows the movement of a component along a specified path. The component will be joined to translate in one direction only. You can specify only one translation degree of freedom in slider joint. Slider joints are used to simulate the motion in linear direction. Figure 9-43 shows two points selected and Figure 9-44 shows Slider joint applied between them.




Figure 9-43 Selecting the components for applying the Slider joint




Figure 9-44 Components after applying the Slider joint

Note

The remaining options in the Slider joint are the same as those discussed in the Automatic joint.

Cylindrical

You can create a Cylindrical joint by selecting the **Cylindrical** option from the **Type** drop-down list of the **Joint** tab. The Cylindrical joint allows you to slide a part in linear direction as well as rotate about the axis of the other component. You can specify one translation degree of freedom and one rotational degree of freedom in cylindrical joint. You can use the Cylindrical joint to simulate the motion of cylinder on another cylinder. Figure 9-45 shows two points selected and Figure 9-46 shows Cylindrical joint applied between them.




Figure 9-45 Selecting the components for applying the Cylindrical joint




Figure 9-46 Components after applying the Cylindrical joint

Planar

You can create a Planar joint by selecting the **Planar** option from the **Type** drop-down list of the **Joint** tab. The Planar joint is used to connect the planar faces of two components. The components can slide or rotate on the plane with two translation and one rotational degree of freedom. Figure 9-47 shows two points selected and Figure 9-48 shows Planar joint applied between them.




Figure 9-47 Selecting the components for applying the Planar joint




Figure 9-48 Components after applying the Planar joint

Ball

You can create the Ball joint by selecting the **Ball** option from the **Type** drop-down list of the **Joint** tab. The Ball joint is used to create a joint between two components such that both the components remain in touch with each other and at the same time the movable component can freely rotate in any direction. To create a ball joint between two components, you need to specify one point from each component. The joints thus created will generate three undefined rotational DOFs and restrict the other three DOFs at a common point. Figure 9-49 shows two points selected and Figure 9-50 shows Ball joint applied between them.




Figure 9-49 Selecting the components for applying the Ball joint



Figure 9-50 Components after applying the Ball joint

Limits Tab

The options in this tab are used to specify the rotational and translation motion of the two joined components, see Figure 9-51.




Figure 9-51 The **Place Joint** dialog box with the **Limits** tab chosen

Angular

You can assign the value of start, current, and end position of the rotational movement with the help of the options in the **Angular** area. The edit boxes in the **Angular** area are activated if their corresponding check boxes are selected, refer to Figure 9-51.

Linear

You can assign the value of start, current, and end position of the translation movement with help the **Linear** area. The edit boxes in the **Linear** area are activated if their respective check boxes are selected.

SHOWING AND HIDING RELATIONSHIPS IN AUTODESK INVENTOR, YOU CAN SHOW AND HIDE RELATIONSHIPS FROM THE ASSEMBLY BY USING THE SHOW, HIDE ALL, AND SHOW SICK TOOLS. THESE TOOLS ARE DISCUSSED NEXT.

-

Show Relationship

Ribbon: Assemble > Relationships > Show You can display the relationship of an assembly by using the **Show** tool. To show a relationship, choose the **Show** tool from the **Relationships** panel of **Assemble** tab. Next, select the component; the relationship will be displayed, refer to Figure 9-52.

Hide Relationship

Ribbon: Assemble > Relationships > Hide All This tool is used to hide all relationships from an assembly. To hide relationship, choose the **Hide All** tool from the **Relationships** panel of **Assemble** tab; all visible relationships will be hidden, refer to Figure 9-53.



Figure 9-52 Relationships displayed




Figure 9-53 Relationships hidden

Show Sick Relationship

Ribbon: Assemble > Relationships > Show Sick This tool is used to display unsolved relationship in an assembly. To display unsolved relationship, you can choose the **Show Sick** tool from the **Relationships** panel of the **Assemble** tab; the relationship will be displayed. To solve the relationship, double-click on the error symbol displayed on it; the **Design Doctor** dialog box will be displayed. You can specify settings in this dialog box to solve the relationship.

Note

*The **Show Sick** tool is not activated if all the relationships of the assembly are solved .*

MOVING INDIVIDUAL COMPONENTS RIBBON:
ASSEMBLE > POSITION > FREE MOVE AUTODESK INVENTOR ALLOWS YOU TO MOVE THE INDIVIDUAL COMPONENTS WITHOUT DISTURBING THE POSITION AND LOCATION OF THE OTHER COMPONENTS IN THE ASSEMBLY FILE. THIS IS DONE USING THE **FREE MOVE** TOOL. ON INVOKING THIS TOOL, YOU WILL BE PROMPTED TO DRAG THE COMPONENT TO A NEW LOCATION. IF YOU MOVE THE CURSOR CLOSE TO A COMPONENT, THE COMPONENT WILL BE HIGHLIGHTED. SELECT THE COMPONENT AND THEN DRAG IT TO THE DESIRED LOCATION; THE COMPONENT WILL BE RELOCATED WITHOUT DISTURBING THE OTHER COMPONENTS IN THE ASSEMBLY FILE.

ROTATING INDIVIDUAL COMPONENTS IN 3D SPACE RIBBON: ASSEMBLE > POSITION > FREE ROTATE

You can also rotate individual components in the current assembly file without changing the orientation of the other components. This is done using the **Free Rotate** tool. When you invoke this tool, you will be prompted to drag the component to a new location. Select the component that you want to rotate. Note that you cannot drag the grounded component. As soon as you select an ungrounded component to rotate, a rim along with the handles will be displayed

around the model. Also, the cursor will be changed to rotation mode cursor.

You can use the same tool to rotate other individual components as well. After you have finished rotating a component, right-click and choose **Done** from the Marking menu displayed. Similarly, you can select any individual component to rotate in the 3D space.

TUTORIALS

Tutorial 1

In this tutorial, you will create the components for a Butterfly Valve assembly and then assemble them, refer to Figure 9-54. The Body and the Shaft will be created in the assembly file and the remaining components will be created as individual parts in separate part files. Therefore, you need to use a combination of top-down and bottom-up assembly approaches. The views and dimensions of the components are shown in Figures 9-55 through 9-62. Assume the missing dimensions for the components and the parameters for the threads.

(Expected time: 3 hrs 30 min)




Figure 9-54 Butterfly Valve assembly




Figure 9-55 Inside view of the Butterfly Valve assembly




Figure 9-56 Solid model of the Body




Figure 9-57 Top view of the Body




Figure 9-58a Left view of the Body




Figure 9-58b Sectioned front view of the Body




Figure 9-59a Top view of the Arm




Figure 9-59b Dimensions of the Shaft




Figure 9-60 Sectioned front view of the Arm




Figure 9-61 Dimensions of the Retainer




Figure 9-62 Dimensions of the Plate, Nut, and Screw

The following steps are required to complete this tutorial:

- a. Start new metric standard part files and then create the other individual components.
- b. Create the Body and the Shaft in the assembly file and then assemble these two components using the options in the **Place Constraint** dialog box. Save and close the assembly file.
- c. Open the assembly file and insert the individual components in the assembly file using the **Place** tool.
- d. Assemble the components using the **Place Constraint** dialog box to complete the Butterfly Valve assembly.

Creating a New Project for the Assembly Before creating the new project file for the assembly, create a folder with the name *Butterfly Valve* at the location *C:\Inventor_2016\c09*.

1. Close all Autodesk Inventor files and then choose the **Projects** tool from the **Launch** panel of the **Get Started** tab; the **Projects** dialog box is displayed.
2. Choose the **New** button from the **Projects** dialog box; the **Inventor project wizard** dialog box is displayed.
3. Select the **New Single User Project** radio button and then choose the **Next** button from the **Inventor project wizard** dialog box.
4. Enter **Butterfly Valve** as the name of the new project in the **Name** edit box.
5. Choose the **Browse for project location** button available on the right of the **Project (Workspace) Folder** edit box; the **Browse for Folder** dialog box is displayed.
6. Browse to the location *C:\Inventor_2016\c09* and select the folder *Butterfly Valve*. Next, choose the **OK** button from the **Browse for Folder** dialog box.
7. Choose the **Next** button and then the **Finish** button from the **Inventor project wizard** dialog box to exit it.
8. Double-click on the newly added project in the **Project name** area to make it

current and then choose the **Done** button to exit the **Projects** dialog box.

Creating the Body

You need to create the Body and the Shaft in the assembly file by using the top-down approach of assembly modeling. To create these two components, you first need to start a new metric assembly file.

1. Choose the **New** tool from the **Quick Access Toolbar** to invoke the **Create New File** dialog box. Next, choose the **Metric** tab from this dialog box and double-click on **Standard (mm).iam** to start a metric assembly file. The assembly environment is invoked.

You will notice that only a few tools are enabled in the **Assemble** tab. This is because no component is present in the assembly file. Once a component is placed or created, all other tools will be available for use.

2. Choose the **Create** tool from the **Component** panel of the **Assemble** tab or choose the **Create Component** tool from the Marking menu to invoke the **Create In-Place Component** dialog box.
3. Enter **Body** as the name of the new part file in the **New Component Name** edit box.
4. Choose the **Browse Templates** button; the **Open Template** dialog box is displayed. Select **Standard (mm).ipt** from the **Metric** tab of this dialog box. Choose the **OK** button from the **Open Template** dialog box to exit.
5. Specify the location of the new part file in the **New File Location** edit box as C:\Inventor_2016\c09\Butterfly Valve.
6. Next, choose the **OK** button from the **Create In-Place Component** dialog box; you are prompted to specify a sketching plane for the base feature. You can now create the Body of the Butterfly Valve assembly.

Tip. It is recommended that you create separate folders for saving individual component files of assemblies because a number of assemblies have components

with similar names. For example, the name Body is commonly used for a number of assemblies. Therefore, if you create a part, name it as Body and then store it in the folder of a particular assembly, so that there is no confusion in placing the components. Also, when you open the assembly next time, there will be no confusion in referring to the required component.

Note

*Remember that if you save the file when the part modeling environment is active, then only the part file will be saved, and not the assembly file. This means while creating the Body, if you choose the **Save** tool from the **Quick Access Toolbar**, the Body .ipt file will be saved, and not the current assembly file. To save the current assembly file, you need to exit the part modeling environment and then choose the **Save** tool in the assembly modeling environment.*

7. Create the Body of the Butterfly Valve using the dimensions given in Figures 9-57 to 9-58b. The assembly file after creating the Body is shown in Figure 9-63.

You will notice that the part modeling environment is still active in the assembly file. To proceed further, you need to save the part file and then exit the part modeling environment.

8. Choose the **Save** tool to save the part file and then choose the **Return** tool from the **Return** panel of the **Model** tab to exit the part modeling environment.

When you choose the **Return** tool, you will notice that the **Assemble** tab is chosen in place of the **3D Model** tab.

As mentioned earlier, if you choose the **Save** tool before exiting the part modeling environment, only the part file will be saved. The assembly file will be saved only after you exit the part modeling environment.

9. Choose the **Save** tool from the **Quick Access Toolbar** and save the assembly with the name *Butterfly Valve* in the *Butterfly Valve* folder.




Figure 9-63 Assembly file in the part modeling environment after creating the Body

Creating the Shaft The second component that has to be created in the assembly file is the Shaft. Therefore, you need to again activate the part modeling environment and the sketching environment to create the Shaft. But, as the Body is already present in the assembly file, it might restrict the view of the part that you will be creating next. Considering this, the part modeling environment is designed in such a way that when you start creating the components in the assembly file, all existing components become transparent and the view of the newly created parts is not restricted.

1. Choose the **Create** tool from the **Component** panel of the **Assemble** tab or choose the **Create Component** option from Marking menu to invoke the **Create In-Place Component** dialog box.
2. Choose the **Browse Templates** button on the right of the **Template** drop-down list to invoke the **Open Template** dialog box. In this dialog box, choose the **Metric** and then open the **Standard (mm).ipt** template.
3. Enter the name of the new part file as **Shaft** in the **New Component Name**

edit box of the **Create In-Place Component** dialog box.

4. Specify the location of the new part file in the **New File Location** edit box as *C:\Inventor_2016\c09\Butterfly Valve*.
5. Clear the **Constrain sketch plane to selected face or plane** check box and then choose **OK**; you are prompted to select the plane for the base feature.
6. Select **XY Plane** from the **Browser Bar**.
7. Invoke the sketching environment by choosing the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab and then select **XY Plane** from the **Browser Bar**; the Body becomes transparent. You can now start creating the Shaft.
8. Create the Shaft and then save it. Next, exit the part modeling environment by choosing the **Return** tool from the **Return** panel of the **3D Model** tab. Save the assembly file by choosing the **Save** tool from the **Quick Access Toolbar**.

When you exit the part modeling environment, you will notice that the Body is no more transparent. Also, both components in the assembly file interfere with each other. Therefore, before proceeding with assembling of these components, you need to move one of the components such that it does not interfere with the other. You can move the individual component by using the **Free Move** tool.

9. Choose the **Free Move** tool from the **Position** panel of the **Assemble** tab and then move the cursor over the Body; you are prompted to drag the component to a new location. Select the Body and drag it to a new location where it does not interfere with the Shaft. Choose the **Zoom All** tool to increase the display area. The assembly file with both the components is shown in Figure 9-64.




Figure 9-64 The assembly file after creating the Body and the Shaft

Note

*If the orientation of the Shaft and the Body on your computer screen is different from the one shown in Figure 9-64, you can reorient them using the **Free Rotate** tool from the Marking menu.*

Assembling the Components

The Shaft has to be inserted in the counterbore hole of the Body. Therefore, you can use the **Insert** constraint to assemble these components. As mentioned earlier, the **Insert** constraint forces the selected components or features to share the same location and orientation of the central axis. It also makes the selected faces coplanar. Therefore, the Shaft will be assembled with the Body using the **Insert** constraint.

1. Choose the **Constrain** tool from the **Relationships** panel of the **Assemble** tab or choose **Constraint** from the Marking menu to invoke the **Place Constraint** dialog box.

By default, the **Mate** constraint is selected. But you need the **Insert** constraint for assembling the Shaft with the Body.

2. Choose the **Insert** button from the **Type** area of the **Assembly** tab in the **Place Constraint** dialog box; you will notice that the **Insert** constraint symbol is attached to the cursor. This symbol moves along with the cursor when you move the cursor in the drawing window.

3. Select the first edge on the Shaft, as shown




Figure 9-65 Selecting the edges to apply the **Insert** constraint in Figure 9-65.

You will notice that the selected edge is highlighted and an arrow is displayed along the direction of the central axis of the Shaft. This arrow will also point in the direction in which the Shaft will be assembled. Also, the **2** (Second Selection) button in the **Selections** area of the **Place Constraint** dialog box is automatically chosen. Choose the **Opposed** option from the **Solution** area.

4. Select the inner edge of the counterbore hole as the second edge, refer to Figure 9-65. As soon as you select the second edge for applying the constraint, the preview of the Shaft assembled with the Body is displayed. This is because the **Show Preview** check box is selected by default in the **Place Constraint** dialog box.

5. Choose the **Apply** button to assemble the Shaft with the Body and then choose **Cancel** from the dialog box to exit. The Body and the Shaft will be constrained together.

Creating Other Components

1. Save the current assembly file and then close it by choosing **Close > Close** from the **Application Menu**.
2. Create the other components as individual part files and save them with their names in the *Butterfly Valve* folder.
3. Exit the part files and then again open the *Butterfly Valve.iam* file.

Note

*It is recommended that you create the holes in the Retainer using the **Circular Pattern** tool and assemble the Screws with the Retainer using the **Pattern** tool. You will learn about this tool in Chapter 10.*

Assembling the Retainer

The next component to be assembled is the Retainer. The Retainer is a circular part and so it can be assembled using the **Insert** constraint. The three holes of the Retainer have to match those on the front planar face of the Body. Also, the central hole of the Retainer has to match with the central hole of the front planar face of the Body. Therefore, you need to apply the **Insert** constraint twice - first time to align one of the smaller holes on the Retainer with one of the smaller holes on the front flat face of the Body, and second time to align the central holes. But first you need to place the Retainer in the assembly using the **Place** tool.

1. Choose the **Place** tool from the **Component** panel of the **Assemble** tab; the **Place Component** dialog box is invoked.
2. Select Retainer and then choose the **Open** button; the **Open** dialog box is closed and the Retainer is attached to the cursor. Also, you are prompted to place the component.
3. Place the Retainer at a location where it does not interfere with the existing components.

After you have placed an instance of the Retainer, you are again prompted to place the component. As you need to place only one instance of the Retainer, you can exit the component placement option.

4. Right-click in the drawing window and choose **OK** from the Marking menu to exit the component placement option.
5. Choose the **Constrain** tool from the **Relationships** panel of the **Assemble** tab; the **Place Constraint** dialog box is displayed. If the **Place Constraint** dialog box is restricting the viewing of the components in the drawing window, you can move it by selecting its title bar and dragging it.
6. Choose the **Insert** button from the **Type** area. Select the circular edge of one of the smaller holes on the top face of the Retainer as the first edge, see Figure 9-66.

7. Select the circular edge of one of the smaller holes on the front planar face of the circular feature on the Body to apply the constraint, see Figure 9-66. Next, choose the **Apply** button.

As soon as you select the second edge, the Retainer moves from its location and is assembled with the Body such that both the selected holes are concentric and the top face of the Retainer is coplanar with the front planar face of the circular feature on the Body. However, you will notice that the central hole of the Retainer is not concentric with the central hole of the left circular feature of the Body and the Shaft. Therefore, you need to apply the **Insert** constraint once again to align these components.

8. Select the circular edge of the Retainer that is coplanar with the Body as the first edge to apply the constraint, see Figure 9-67. You may have to rotate the model to select this edge.

9. Select the circular edge of the front circular feature on the Body as the second face to apply the constraint, see Figure 9-67. Choose **Apply** to assemble the components and then choose **Cancel** to exit the dialog box.




Figure 9-66 Selecting the edges to apply the **Insert** constraint




Figure 9-67 Selecting the edges to apply the **Insert** constraint again

Assembling the Arm

The next component to be assembled is the Arm. You need to use two constraints to assemble it. The first constraint is the **Insert** constraint and the second constraint is the **Angle** constraint which will be used to apply an angle between the XZ plane of the Arm and the top face of the Body. You will place the Arm using the **Place** tool.

1. Choose the **Place** tool from the **Component** panel of the **Assemble** tab to invoke the **Place Component** dialog box.
2. Double-click on the Arm; the Arm gets attached to the cursor.
3. Place the Arm at a location where it does not interfere with the existing components.
4. Right-click in the drawing window and choose **OK** from the Marking menu to exit the component placement option.
5. Choose the **Constrain** tool from the **Relationship** panel of the **Assemble** tab or from the Marking menu; the **Place Constraint** dialog box is displayed.
6. Choose the **Insert** button and then select the top circular edge of the hole with the keyway in the Arm as the first edge, as shown in Figure 9-68.
7. Select the circular edge on the front planar face of the Retainer as the second edge to apply the **Insert** constraint, refer to Figure 9-68. Next, choose the **Apply** button.

After performing the above steps, the Arm will be assembled with the Retainer and the Shaft will be inserted in the bigger hole of the Arm. The second constraint will be used to reorient the Arm such that it is assembled at an angle to the top face of the Body. This angle is the same as the angle between the top face of the Body and the flat face of the Shaft.

Note

*In this case, it is presumed that the cylindrical features of the Arm are created on the XY plane. Also, the bigger and smaller cylindrical features are created from left to right along the X axis when placed on the XY plane. Therefore, the XZ plane will pass through the center of the two cylindrical features. This XZ plane will be used to apply the **Angle** constraint.*

Figure 9-69 shows the assembly after the Arm was assembled.

t




Figure 9-68 Selecting the edges to apply the **Insert** constrain





Figure 9-69 Assembly after assembling the Arm

8. Now, it is important to apply the **Mate** constraint between the Shaft and the Arm in such a manner that the Arm rotates with the Shaft. To do so, invoke the **Constrain** tool from the Marking menu; the **Place Constraint** dialog box is displayed.

9. Next, choose the **Mate** button from the **Type** area of the dialog box.

10. Select the top flat face of the Shaft. Next, select the XZ plane of the Arm, as shown in Figure 9-70.

The assembly after applying the constraint is shown in Figure 9-71.



*Figure 9-70 Selection of face and plane for applying the **Mate** constraint*





Figure 9-71 Assembly after applying the constraint between the Shaft and the Arm

11. Next, choose the **Constrain** tool from the Ribbon to display the **Place Constraint** dialog box again.
12. Choose the **Angle** button from the **Type** area in this dialog box; the symbol of the **Angle** constraint icon is attached to the cursor, suggesting that the process of assembling the components is resumed.
13. Select the flat face of the Shaft as the first face to apply the **Angle** constraint, refer to Figure 9-72.
14. Select the top face of the Body as the second face to apply the **Angle** constraint, refer to Figure 9-72.
15. Next, choose the **Undirected Angle** button from the **Solutions** area and then choose the **More** button.



*Figure 9-72 Selecting faces to apply the **Angle** constraint*

16. Select the **Maximum** check box in the **Limits** area and clear the **Use Angle As Resting Position** check box, if it is not cleared.
17. Enter **135** in the **Maximum** edit box and **0** in the **Minimum** edit box. Next, choose **Apply** and then **Cancel** from the **Place Constraint** dialog box to apply the constraint and exit the dialog box.

The **Angle** constraint is applied between the components of the assembly.

Assembling the Plate

The next component to be assembled is the Plate. You first need to place the Plate in the assembly file and then assemble it on the flat face of the Shaft. You need to apply the **Insert** constraint twice to assemble the Plate with the Shaft. The first application of the constraint will align one of the holes on the Plate with one of the holes on the Shaft. The second application of the constraint will align the second hole on the Plate with a hole on the Shaft.

Since the Shaft is assembled inside the Body, the Body will restrict viewing of the components being assembled. To avoid this, Autodesk Inventor allows you to turn off the display of the components that you do not require for assembling the other components. Therefore, before proceeding with assembling of the Plate, you can turn off the display of the Body. This is done using the **Browser Bar**.

1. Right-click on the Body in the **Browser Bar** to display the shortcut menu. You will notice that a tick mark is displayed in front of the **Visibility** option in the shortcut menu. This suggests that the display of this component is turned on. Choose the **Visibility** option again to turn off the display of the Body.

Note that the component whose visibility is turned off will be displayed in gray color in the **Browser Bar**.

*Tip. If you clear the **Enabled** check box instead of the **Visibility** check box in the shortcut menu, then the selected part in the **Browser Bar** will turn green in color and the component will become transparent.*

2. Choose the **Place** tool from the **Component** panel of the **Assemble** tab to invoke the **Place Component** dialog box.
3. Double-click on the Plate; the Plate gets attached to the cursor.
4. Place the Plate at a location where it does not interfere with the existing components.
5. Right-click in the drawing window and choose **OK** from the Marking menu to

exit the component placement option.

6. Choose the **Constrain** tool from the **Relationship** panel of the **Assemble** tab; the **Place Constraint** dialog box is displayed.
7. Choose the **Insert** button and then select the circular edge of one of the holes on the top face of the Plate as the first edge to apply the constraint, refer to Figure 9-73.
8. Select the circular edge of the right hole on the flat face of the Shaft as the second edge to apply the constraint, see Figure 9-73. Then, choose the **Apply** button to apply the constraint.

As soon as you select the second face to apply the constraint, the Plate will move from its location and will be assembled with the Shaft. Now, the second constraint has to be applied to the other hole of the Plate. To do so, you need to select the face that is made coplanar with the flat face of the Shaft. Therefore, you need to reorient the model such that the back face of the Plate is visible and you can select the hole on that face to apply the constraint.

9. Rotate the assembly using the ViewCube such that the back face of the Plate is visible.
10. Select the circular edge on one of the holes on the back face of the Plate as the first edge to apply the constraint.

Since you have rotated the model such that the back face of the Plate is visible, the flat face of the Shaft is not visible in the current view. Therefore, you need to switch back to the previous view. Sometimes when you use the **Place** tool, you cannot use the F5 key to invoke the previous view. In such cases, you need to invoke the **Free Rotate** tool and then right-click to display a shortcut menu. Then, you need to choose **Previous View** from this menu to switch back.




Figure 9-73 Selecting the faces to apply the constraint

11. Press the F5 key or choose the **Free Rotate** tool from the **Position** panel, and then right-click in the drawing window to display a shortcut menu. Choose the **Previous View** option to switch back to the previous view. Again, right-click and choose **Done** to exit the **Free Rotate** tool.
12. Select the other hole on the flat face of the Shaft to apply the constraint. Choose the **Apply** button to apply the constraint and then choose the **Cancel** button to exit the dialog box. The assembly after assembling the Plate is shown in Figure 9-74.
13. Turn on the visibility of the Body by using the **Browser Bar**.




Figure 9-74 Assembly after assembling the Plate

Assembling the Screws

There are three instances of the Screw that need to be assembled such that they are inserted into three holes on the Retainer.

1. Turn off the display of the Arm by using the **Browser Bar**.
2. Choose the **Place** tool from the **Component** panel to invoke the **Place Component** dialog box.
3. Double-click on the Screw; the Screw gets attached to the cursor.
4. Place three instances of the Screw at a location where they do not interfere with the existing components.
5. Choose the **Constrain** tool from the **Relationship** panel of the **Assemble** tab; the **Place Constraint** dialog box is displayed.
6. Choose the **Insert** button, and then select the circular edge on the flat face of the head of the Screw as the first face to apply the constraint.
7. Select the circular edge of one of the smaller holes on the front face of the Retainer as the second face to apply the constraint. Next, choose the **Apply** button to apply the constraint.
8. Similarly, assemble the other two Screws with the other two smaller holes on the Retainer.
9. Turn on the visibility of the Arm by using the **Browser Bar**.

Assembling the Nut

Next, you need to assemble the Nut with the Shaft. Since the threaded portion of the Shaft has to be inserted inside the hole of the Nut, you need to use the **Insert** constraint to assemble these components.

1. Choose the **Place** tool from the **Component** panel to invoke the **Place Component** dialog box.
2. Double-click on the Nut; the Nut gets attached to the cursor.
3. Place the Nut at a location where it does not interfere with the existing components. Next, rotate the Nut using the **Free Rotate** tool such that the flat face of the Nut is visible in the current view.
4. Choose the **Constrain** tool from the **Relationship** panel of the **Assemble** tab; the **Place Constraint** dialog box is displayed.
5. Choose the **Insert** button and then select the circular edge of the hole on the flat face of the Nut as the first face to apply the constraint.
6. Select the end face (not on the side of the chamfered edge) of the threaded feature of the Shaft. Choose the **Apply** button to apply the constraint and then choose **Cancel** to exit the dialog box. The final Butterfly Valve assembly is shown in Figure 9-75.




Figure 9-75 Final Butterfly Valve assembly

7. Save the assembly and close the file.

Tutorial 2

In this tutorial, you will create the components of a Plummer Block assembly. Note that you need to create all components as separate part files. After creating the components, place them in the assembly file and then assemble them. The dimensions of the components are shown in Figures 9-76 through 9-81. Assume the missing dimensions and the parameters for the threads. **(Expected time: 3 hrs)**



Note The orientation of the Casting that you will draw should match the orientation of the Casting shown in the assembly in Figure 9-76. This is because when you place the first component in the assembly file, it is placed on the same plane on which it was originally created in the part file. Since the Casting will be the first component to be placed in the assembly file, its base should be created on the XY plane. The orientation of the other components also depends on the first component that you place in the assembly file.




Figure 9-76 *Plummer Block assembly*




Figure 9-77 *Half-sectioned isometric view of the Plummer Block assembly*




Figure 9-78a *Top view of the Casting*




Figure 9-78b Top view of the Cap




Figure 9-79a Front view of the Casting




Figure 9-79b Front view of the Cap




Figure 9-80 Dimensions of the Brasses




Figure 9-81 Dimensions of the Lock Nut, Nut, and Bolt

The following steps are required to complete this tutorial:

- Create all the components of the assembly as separate part files and save them in the *Plummer Block* folder at the location *Inventor_2016\c09*.
- Start a new metric assembly file and then place the Casting and the Brasses by using the **Place** tool.
- Assemble the two components using the assembly constraints.
- Next, turn off the display of the Brasses and then place the Cap in the assembly. Assemble the Cap with the assembly.
- Turn on the display of the Brasses.
- Place two instances of the Bolt in the assembly file and then assemble them with the Casting.
- Place two instances of the Nut and the Lock Nut. Assemble both the instances of the Nut with the Cap and then assemble the Lock Nut with the Nut.
- Finally, turn on the display of the Brasses to complete the Plummer Block

assembly.

Creating a New Project for the Assembly 1. Create a new folder with the name *Plummer Block* in the *c09* folder and set it as the current project folder using the procedure described in Tutorial 1.

Creating the Components

1. Create all components of the Plummer Block assembly as separate part files. Then, save the files with their respective names, refer to Figures 9-78a through 9-81. The files should be saved at the location *C:\Inventor_2016\c09\Plummer Block*.

Assembling the Casting and the Brasses

The Casting and the Brasses will be assembled using two **Mate** constraints. The **Mate** constraint is first applied between the axis of the snug on the Brasses and the axis of the hole available on the Casting. The **Mate** constraint is again applied between the cylindrical face of the Brasses and the cylindrical face of the Casting.

1. Start a new assembly file and save it with the name *Plummer Block* in the *Plummer Block* folder at the location *C:\Inventor_2016\c09*. The *Plummer Block* is the folder in which all the individual part files are saved.
2. Choose the **Place** tool from the **Component** panel of the **Assemble** tab to invoke the **Place Component** dialog box.
3. Double-click on the Casting; the Casting gets attached to the cursor and you are prompted to place the component. Next, you can use context menu to ground a component at the origin.
4. As you need to place only one instance of casting, right-click and choose **place Grounded at origin** from the Marking menu and click in the graphics window. Next, place one instance of the Brasses in the current assembly file. Note that the Brasses should not be inserted as grounded component and its location should be such that it does not interfere with the Casting.
5. Choose the **Free Rotate** tool from the **Position** panel of the **Assemble** tab and rotate the Brasses such that its snug is visible in the current view.
6. Choose the **Constrain** tool from the **Relationships** panel of the **Assemble** tab; the **Place Constraint** dialog box is displayed.
7. In this dialog box, the **Mate** button is chosen by default. Select the axis of the snug as the first selection and axis of the hole on the Casting as the second

selection, as shown in Figure 9-82.

8. Choose **OK** from the **Place Constraint** dialog box to apply the constraint and exit the dialog box. Next, you need to apply another Mate constraint to make sure that the Brasses rest on the top of the cylindrical face of the Casting.
9. Move the Brasses up so that the bottom of the cylindrical face of the Brasses is visible. Next, invoke the **Place Constraint** dialog box. The **Mate** button is chosen by default in this dialog box.
10. Select the cylindrical face of the Brasses as the first selection and then select the cylindrical face of the Casting as the second selection, as shown in Figure 9-83. Next, choose the **Apply** button in the **Place Constraint** dialog box; the constraints are applied, as shown in Figure 9-84.




Figure 9-82 *Selecting the axes for applying the **Mate** constraint*




Figure 9-83 *Selecting the cylindrical faces of the Brasses and the Casting for*

*applying the **Mate** constraint*

Assembling the Brasses and the Cap

After the Brasses are assembled, you now need to assemble the Cap with the assembly.

1. Place one instance of the Cap in such a manner that it does not interfere with the current assembly. Rotate the Cap in such a way that the inner cylindrical face of the Cap is visible.
2. Invoke the **Place Constraint** dialog box. In this dialog box, the **Mate** button is chosen by default. Select the axis of the hole on the cap as the first selection and then select the axis of the hole in the Brasses as the second selection, as shown in Figure 9-85. Next, choose **OK** to apply the constraint and exit the **Place Constraint** dialog box.





Figure 9-84 *The Brasses after applying the **Mate** constraint*



*Figure 9-85 Selecting the axes for applying the **Mate** constraint*

3. Now, you need to apply another **Mate** constraint between the cylindrical face of the Cap and the cylindrical face of the Brasses. To do so, move the Cap up in such a way that the cylindrical face of the Brasses is visible and then invoke the **Place Constraint** dialog box. In this dialog box, the **Mate** button is chosen by default. Move the cursor over the inner cylindrical face of the Cap and then right-click; a shortcut menu is displayed. Choose **Select Other**; the **Select Other** flyout is displayed. Click on the down arrow and then select the cylindrical face by using the **Select Other** flyout.
4. Similarly, select the top cylindrical face of the Brasses as the second selection, as shown in Figure 9-86. Next, choose **OK** from the **Place Constraint** dialog box to apply the constraint and close the dialog box. The assembly after the Cap is assembled is shown in Figure 9-87.




Figure 9-86 Faces selected for applying the **Mate** constraint




Figure 9-87 The Cap after applying the **Mate** constraint

Assembling the Bolts

There are two instances of the Bolts that have to be assembled in the current assembly. Since the Brasses are not required for assembling the Bolts or the Nuts, you can turn off their display. After turning off the display of the Brasses, you need to assemble the Bolts.

1. Turn off the display of the Brasses using the **Browser Bar**. Next, place two instances of the Bolt using the **Place** tool.
2. Change the display mode to Wireframe. Invoke the **Place Constraint** dialog box and then choose the **Insert** button from the **Type** area.
3. Select the circular edge on the top face of the base square feature of the Bolt as the first face to apply the constraint, refer to Figure 9-88.
4. Next, select the circular edge on the top face of the square cut of the bottom face of the Casting, see Figure 9-88. Choose the **Apply** button to apply the constraint.
5. Similarly, assemble the other Bolt and then change the display mode to shaded.




Figure 9-88 *Selecting the edges to apply the constraint*

6. You now need to apply the **Angle** constraint between the flat face of the head of the Bolt and the inner flat face of the slot so that the bolts do not rotate in the slots provided to them. To do so, invoke the **Place Constraint** dialog box and then choose the **Angle** button from the **Type** area of this dialog box.
7. Select the side planar face of the Bolt head and the inner planar face of the slot, as shown in Figure 9-89.
8. Choose the **Undirected Angle** button from the **Solution** area of the **Place Constraint** dialog box and enter **0** in the **Angle** edit box. Next, choose the **Apply** button in the **Place Constraint** dialog box.
9. Similarly, constrain the other Bolt in the assembly.
10. Turn on the visibility of the Brasses from the **Browser Bar** and change the display type to shaded.
11. Choose the **Home** button in the ViewCube. The home view of the assembly is enabled. The assembly after the Bolts are constrained is shown in Figure 9-90.




Figure 9-89 Faces selected for applying the **Angle** constraint




Figure 9-90 The assembly after the Bolts are assembled

Assembling the Nuts and the Lock Nuts

1. Place two instances each of the Nut and the Lock Nut using the **Place** tool.
2. Invoke the **Place Constraint** dialog box and choose the **Insert** button. Select the circular edge of the hole on the top face of one of the Nuts as the first face to apply the constraint.
3. Select the circular edge of the left hole on the top face of the Cap as the second edge to apply the constraint. On doing so, the Nut is assembled with the Cap. Next, choose the **Apply** button to apply the constraint.
4. Select the circular edge of the hole on the top face of one of the Lock Nuts as the first face to apply the constraint.
5. Now, select the circular edge of the hole on the top face of the Nut that is assembled with the Cap to apply the constraint. Next, choose the **Apply** button to apply the constraint.
6. Similarly, assemble the other Nut and the Lock Nut. Turn on the display of all the hidden components using the **Browser Bar**. The final Plummer Block assembly is shown in Figure 9-91.
7. Save the assembly by choosing the **Save** tool from the **Quick Access Toolbar**.




Figure 9-91 Final Plummer Block assembly

Tutorial 3

In this tutorial, you will create the components of the Anti Vibration Mount and then assemble them, as shown in Figure 9-92. You need to create all the components as separate part files. The views and dimensions of the components are shown in Figures 9-93a through 9-93e. **(Expected time: 2 hours)**




Figure 9-92 The Anti Vibration Mount assembly for Tutorial 3





Figure 9-93a Top and front views of Body







Figure 9-93b Top and front views of Hex Bolt



Top view



Front view



Side view

Figure 9-93c Top, front, and side views of Yoke Plate




Figure 9-93d Top and front views of Nut




Figure 9-93e Top and front views of Bushing Rubber

The following steps are required to complete this tutorial:

- Create all components of the assembly as separate part files and save them at the location *\Inventor_2016\c09\Anti Vibration Mount*.
- Start a new metric assembly file and place the Body and two instances of Bushing Rubber using the **Place** tool.
- Assemble the components by using the assembly constraints.
- Place the Yoke Plate using the **Place** tool and then assemble it using the assembly constraints.
- Place the Hex Bolt and assemble it by using the assembly constraints.
- Place the Nut and then assemble it by using the assembly constraints.

Creating the Components

Before creating the assembly, you need to create its components as separate part files and then you need to save them at a common location for ease of assembling.

1. Start a new metric part file and then create the sketch on the XY plane, as shown in Figure 9-94. Apply the required dimensions and constraints to the sketch.

Note

Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.

If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.

2. Exit the Sketching environment by choosing the **Finish Sketch** button from the Marking menu.
3. Click on any entity of the sketch and choose the **Extrude** tool from the mini toolbar. Next, extrude the sketch to a depth of 16 mm, as shown in Figure 9-95.
4. Turn on the visibility of the YZ plane by using the **Browser Bar**.
5. Choose the **Tangent to Surface and Parallel to Plane** tool from **3D Model > Work Features > Plane drop-down** and then select the **YZ Plane** from the graphics window or from the **Browser Bar**.
6. Next, select the rounded face on left of the YZ plane; a plane tangent to the selected face and parallel to the YZ plane is created.




Figure 9-94 Sketch created for the body



Figure 9-95 Sketch extruded

7. Similarly, create the work plane on right of the YZ plane and then turn off the visibility of the YZ plane by using the **Browser Bar**. The extruded feature after creating the work planes is shown in Figure 9-96. The work planes created are named as Work Plane 1 and Work Plane 2. These work planes are displayed in the **Browser Bar**.
8. Choose the **Start 2D Sketch** tool from **3DModel** > **Sketch** > **Sketch** drop-down and select Work Plane 1 as the sketching plane.
9. Create the sketch for extrusion feature, as shown in Figure 9-97 and exit the Sketching environment. The model in this figure is displayed in wireframe for clarity of the sketch.




Figure 9-96 Work planes created




Figure 9-97 Sketch for the extrusion feature

10. Choose the **Extrude** tool from the Create panel of the **3DModel** tab and extrude the sketch up to Work Plane 2.
11. Hide both work planes by using the **Browser Bar**. Choose the **Bar** icon from the ViewCube to display the model in isometric view, as shown in Figure 9-98.
12. Create three holes of 12 mm diameter on the triangular face of the model by using the Hole tool. You can use the rounded faces of the triangular feature as the concentric references for the holes. Figure 9-99 shows the model after creating the holes.




Figure 9-98 Model in isometric view




Figure 9-99 Holes created on the model

13. Save the file with the name *Body* at the following location:
\Inventor_2016\c09\Anti Vibration Mount
14. Similarly, create the other components of the assembly and save them at the same location. For dimensions of the components, refer to Figures 9-93b through 9-93e.


Placing the Body and Bushing Rubber in the Assembly You need to start a new assembly file and then place the Body in it. Next, you need to place two instances of Bushing Rubber in the same assembly.

1. Start a new metric assembly file, and then choose the **Place** tool from the **Component** panel in the **Assemble** tab; the **Place Component** dialog box is displayed.
2. Browse to the *Anti Vibration Mount* folder and double-click on **Body** in this dialog box; the *Body* gets attached to the cursor. Next, place it in the graphics window.
3. Right-click in the graphics window and then choose the **OK** button from the Marking menu to exit the **Place** tool.
4. Similarly, place two instances of the Bushing Rubber in the graphics window.

Assembling the Components

After placing the components in the assembly file, you need to assemble them.

1. Choose the **Constrain** tool from the **Relationship** panel of the **Assemble** tab; the **Place Constraint** dialog box is displayed.
2. Choose the **Insert** button from the **Type** area of the **Assembly** tab in this dialog box. Next, select the cylindrical edges of the Body and the Bushing Rubber, as shown in Figure 9-100; the selected components are aligned axially with each other.
3. Choose **Apply** from the **Place Constraint** dialog box to confirm the constraint applied. The assembled components are shown in Figure 9-101.



*Figure 9-100 Edges selected to apply the **Insert** constraint*




Figure 9-101 Assembly after assembling the Body with one instance of Bushing Rubber

4. Similarly, assemble the other instance of the Bushing Rubber with the Body.
5. To exit the **Place Constraint** dialog box, choose **Cancel**.

6. Next, you need to save the sub-assembly. Save it with the name *Body-Bushing Rubber*.

Assembling the Yoke Plate with the Assembly Next, you need to place the *Yoke Plate* in the assembly and then assemble it with the other components in the assembly.

1. Start a new metric assembly file and then choose the **Place** tool from the **Component** panel in the **Assemble** tab; the **Place Component** dialog box is displayed.
2. Place the *Yoke Plate* in the drawing area using the **Place Component** dialog box, as discussed earlier in the tutorial. The *Yoke Plate* after it is placed in the assembly file is shown in Figure 9-102.
3. Invoke the **Place Component** dialog box again to place the *Body-Bushing Rubber* sub-assembly in the main assembly.
4. Place one instance of the *Body-Bushing Rubber* sub-assembly in the main assembly that you created earlier in this tutorial.
5. Use the **Free Move** tool and the **Free Rotate** tool to place the sub-assembly at the position shown in Figure 9-103.
6. Choose the **Constrain** tool from the **Position** panel of the **Assemble** tab; the **Place Constraint** dialog box is displayed.




Figure 9-102 The Yoke Plate placed in the assembly




Figure 9-103 *Placing the sub-assembly in the main assembly*

7. Choose the **Insert** button from the **Type** area of the **Assembly** tab in this dialog box. Next, select the cylindrical edges of the Bushing Rubber and the Yoke Plate, as shown in Figure 9-104; the selected components are aligned axially with each other.
8. Choose **Apply** from the **Place Constraint** dialog box to confirm the constraint applied.

Similarly, apply the **Insert** constraint to the other Bushing Rubber. The assembly after applying the **Insert** constraint is shown in Figure 9-105.






Figure 9-104 *Edges selected to apply the **Insert** constraint*




*Figure 9-105 Assembly after applying the **Insert** constraint*

9. Choose the **Angle** button from the **Type** area of the **Assembly** tab in the **Place Constraint** dialog box.
10. Choose the >> button in the **Place Constraint** dialog box to expand it if the dialog box is collapsed.
11. Select the **Maximum** and **Minimum** check boxes in the **Limits** tab of the dialog box; the edit boxes below these check boxes are activated.
12. Enter **45** and **0** in the **Maximum** and **Minimum** edit boxes, respectively.
13. Select the faces of the components in the assembly in the order shown in Figure 9-106.
14. Select **Reference Vector** from the **Selection** Area and move the cursor over the cylindrical edge of the Yoke Plate and select the axis.
15. Next, choose **OK** from the **Place Constraint** dialog box; the assembly after applying the **Angle** constraint is shown in Figure 9-107.

As you have provided the maximum and minimum limits as 45-degree and 0-degree respectively, you can rotate the Yoke Plate around its central axis from 0-degree to 45 degrees by dragging it. This provides some degree of freedom to the Yoke Plate.



*Figure 9-106 Faces selected to apply the **Angle** constraint*



*Figure 9-107 Assembly after applying the **Angle** constraint*

Assembling the Hex Bolt with the Assembly Next, you need to assemble the Hex Bolt with the assembly.

1. Place the Hex Bolt in the assembly by using the **Place** tool.
2. Choose the **Free Rotate** tool from the **Position** panel of the **Assemble** tab and rotate the Hex Bolt to the view shown in Figure 9-108. Note that if you rotate the components, you can easily select the entities for assembling the components.
3. Invoke the **Place Constraint** dialog box as discussed earlier.
4. Choose the **Insert** button from the **Type** area of the **Assembly** tab in this

dialog box. Next, select the cylindrical edges of the Yoke Plate and the Hex Bolt, as shown in Figure 9-109; the selected components are aligned axially with each other.

5. Choose **Apply** from the **Place Constraint** dialog box to confirm the constraint applied.
6. Next, choose the **Angle** button from the **Type** area of the **Assembly** tab in the **Place Constraint** dialog box.
7. Choose the **Directed Angle** button from the **Solutions** area of the **Assembly** tab in the **Place Constraint** dialog box and enter **0** in the **Angle** edit box.






Figure 9-108 Rotated Hex bolt



*Figure 9-109 Edges selected to apply the **Insert** constraint*

8. Select the planar faces of the Body and the Hex Bolt in the assembly, as shown in Figure 9-110.
9. Next, choose **OK** from the **Place Constraint** dialog box; the assembly after

assembling the Hex Bolt is shown in Figure 9-111.



*Figure 9-110 Faces selected for applying the **Angle** constraint*





Figure 9-111 Hex bolt assembled in the assembly

Assembling the Nut

Finally, you need to assemble the Nut with the assembly.

1. Place the Nut in the assembly by using the **Place** tool.
2. Rotate the assembly by using the ViewCube such that the back face of the Yoke Plate is visible.
3. Invoke the **Place Constraint** dialog box as discussed earlier. By default, the **Mate** button is chosen from the **Type** area in the **Assembly** tab.
4. Select the planar faces on the Yoke Plate and the Nut, as shown in Figure 9-112; the selected components are mated.
5. Select the axes of the Hex Bolt and the Nut, as shown in Figure 9-113 to apply the **Insert** constraint; the Hex Bolt and the Nut are aligned axially with each other.



*Figure 9-112 Faces selected on Yoke Plate and Nut for applying the **Mate** constraint*




Figure 9-113 Axes selected for applying the **Mate** constraint

6. Choose **OK** from the **Place Constraint** dialog box to confirm the constraints applied and to exit the dialog box.
7. Choose the **Home** icon from the ViewCube to display the final assembly in the isometric view, as shown in Figure 9-114.




Figure 9-114 Isometric view of the final assembly

Saving and Closing the Assembly

After assembling all components, you need to save the assembly.

1. Choose the **Save** tool from the **Quick Access Toolbar**; the **Save As** dialog box is displayed.
 2. Enter **Anti Vibration Mount** as the name of the assembly and save it at the following location:
\Inventor_2016\c09\Anti Vibration Mount
 3. Choose **Close > Close** from the **Application Menu** to close the assembly file.
-

1. The _____ tool is used to place the components in the assembly file.
2. The _____ icon is displayed adjacent to the grounded component in the **Browser Bar**.
3. When you invoke the **Constrain** tool, the _____ dialog box is displayed.
4. The _____ constraint is used to make the selected planar face, axis, or point of a component coincident with that of another component.
5. By default, the first component placed in the assembly file is _____.
6. The individual components in the assembly file can be moved using the _____ tool.
7. In Autodesk Inventor, you can use the bottom-up approach as well as the top-down approach for creating assemblies. (T/F)
8. An assembly that uses a combination of top-down and bottom-up approaches is called a middle-out assembly. (T/F)
9. You can rotate individual components in the assembly file. (T/F)

10. You cannot invoke the Sketching environment in the assembly file. (T/F)

1. How many types of assembly constraints are available in Autodesk Inventor?

(a) 4 (b) 5

(c) 7 (d) 8

2. How many types of motion constraints are available in Autodesk Inventor?

(a) 2 (b) 3

(c) 4 (d) 5

3. Which of the following tools is used to rotate the individual components in the assembly file?

(a) **Free Rotate** (b) **Free move** (c) **Place** (d) None of these

4. Which of the following constraints is used to rotate one of the components in relation to other component?

(a) **Rotation** (b) **Rotation-Translation** (c) **Mate** (d) **Tangent**

5. You can change the display type of the components even when you are using a tool to perform a function. (T/F)

6. You can rotate or move a component while assembling it with the base feature. (T/F)

7. The components that are not grounded by default can also be grounded if required. (T/F)

8. The display of the components that are not required for assembling other components can be turned off using the **Browser Bar**. (T/F)

9. If the component files are moved from their original location, they will not show up the next time you open the assembly file. (T/F)

10. The top-down assemblies are those in which all the components are created as individual part files and are placed in the assembly file. (T/F)

Create the components of the Drill Press Vice assembly and then assemble them, as shown in Figure 9-115. The dimensions of the components are shown in Figures 9-116 through 9-119. Create a folder with the name *Drill Press Vice* at the location *C:\Inventor_2016\c09* and save all the components and the

assembly file in this folder. Assume the missing dimensions. You will use the bottom-up approach for creating this assembly. **(Expected time: 3 hrs 15 min)**




Figure 9-115 Drill Press Vice assembly




Figure 9-116 Dimensions of the Clamp Screw, Handle Stop, and Clamp Screw Handle




Figure 9-119 Top and Front views of the Base

Answers to Self-Evaluation Test **1. Place**, **2. push pin**, **3. Place Constraint**, **4. Mate**, **5. ungrounded**, **6. Free Move**, **7. T**, **8. T**, **9. T**, **10. F**

Chapter 10

Assembly Modeling-II

Learning Objectives


After completing this chapter, you will be able to: • Edit assembly constraints.

- *Create subassemblies.*
- *Create and edit the pattern of components in the assembly file.*
- *Replace components in an assembly file with other components.*
- *Mirror subassemblies or components of an assembly.*
- *Create the section view of assemblies in an assembly file.*
- *Analyze assemblies for interference.*
- *Create design views of assemblies.*
- *Drive assembly constraints.*
- *View the Bill of Material of the current assembly.*
- *Understand and create assembly features.*

EDITING ASSEMBLY CONSTRAINTS

Generally, after creating an assembly or during the process of assembling the components, you have to edit the assembly constraints that were used to assemble the components. The editing operations that can be performed on the assembly constraints include modifying the type of assembly constraint, the offset or angle values, the type of solution, or changing the component to which the constraint was applied. In Autodesk Inventor, the assembly constraints are edited using the **Browser Bar**. By default, the constraints that are applied on the components will not be displayed in the **Browser Bar**. To display the assembly constraint applied on a component, click on the plus (+) sign located on the left of the component in the **Browser Bar**; the **Origin** folder will be displayed along with the list of constraints that are applied to that component. To edit a

constraint, right-click on it in the **Browser Bar** and choose **Edit** from the shortcut menu, see Figure 10-1.



*Figure 10-1 Choosing the **Edit** option from the shortcut menu*


Note

*When you select the assembly constraint in the **Browser Bar**, an edit box is displayed below the **Browser Bar**. This edit box will display the value of the offset or angle for the selected constraint. You can modify the angle or the offset value using this edit box.*

When you choose **Edit** from the shortcut menu, the **Edit Constraint** dialog box will be displayed, see Figure 10-2. This dialog box is similar to the **Place Constraint** dialog box and can be used to edit the assembly constraints. This dialog box can also be used to change the constraint type, edit the offset or the angle value, modify the solution, or change the components to which the constraints are applied.

EDITING COMPONENTS

Sometimes after assembling the components in an assembly, you need to edit the components. In Autodesk Inventor, you can edit the components by two methods. These methods are discussed next.




*Figure 10-2 The **Edit Constraint** dialog box for editing the assembly constraints*

Editing Components in the Assembly File The first method of editing components is to invoke the part modeling environment and the sketching environment in the assembly file and then edit the component. This method of editing components is similar to the top-down approach of assembly modeling. To edit a component in the assembly file, right-click on the component in the **Browser Bar**; a shortcut menu will be displayed. From this menu, choose the **Edit** option, as shown in Figure 10-3; the part modeling environment will be activated in the assembly file. You will notice that the other components in the assembly file have become transparent. This is

because the **Transparency On** tool is chosen by default in the **Appearance** panel of the **View** tab. Also, the name of the feature will be displayed with a gray background in the **Browser Bar** and the component selected for editing will be displayed with a white background. The component that is displayed in white background is called active component. You can edit the active component in the assembly file. Remember that only one component can be active at a time. Note that you can switch off the transparency of the component by choosing the **Transparency Off** tool that will be available on clicking the down arrow on the right of the **Transparency On** tool. Once you have edited the component, choose the **Return** tool from the **Return** panel to switch back to the **Assembly** module.

*Tip. 1. If you move the cursor on the assembly constraint in the **Browser Bar**, the components on which that constraint is applied are highlighted in the assembly on the graphics screen.*

*2. Autodesk Inventor allows you to locate the other half of the selected constraint in the **Browser Bar**. This enables you to locate the other component on which the selected constraint has been applied in large assemblies with a huge number of components. To locate the other half of the constraint, choose **Other Half** from the shortcut menu, refer to Figure 10-1; the other half of the selected constraint will be highlighted in the **Browser Bar**.*



*Figure 10-3 Choosing the **Edit** option from the shortcut menu*

After making changes in the component of the assembly file, when you save it, the **Save** dialog box will be displayed, see Figure 10-4. If you want to save the changes made in the part files, choose **Yes to All** and then choose **OK**; the changes in all parts will be saved. If you do not want to save the changes in any part, choose **No to All**.

If you want to save the changes in a particular file, click on the **No** option corresponding to it in the **Save** column of this dialog box; you will notice that **No** is replaced by **Yes**. As a result, the changes will be saved in the selected file. However, the changes will not be saved in the remaining files that show **No** in the **Save** column.




Figure 10-4 The Save dialog box

Editing Components by Opening Their Part Files The second method of editing the components is by opening their part files and making the necessary changes in them. To open the part file for editing, right-click on the component in the **Browser Bar**; a shortcut menu will be displayed. Choose **Open** from this shortcut menu, as shown in Figure 10-5. When you choose the **Open** option, the part file of the selected component will be opened in the **Modeling** environment. Make the necessary changes in the part file and then save the changes by choosing the **Save** tool from the **Quick Access Toolbar**. Now, exit the part file by choosing **Close > Close** from the **Application Menu**. The changes that you made in the part file will be automatically reflected in that component in the assembly file. This is because Autodesk Inventor is bidirectionally associative. This

means that the changes made to the components in any module of Autodesk Inventor will be automatically reflected in the other modules.




Figure 10-5 Opening the part file for editing

CREATING SUBASSEMBLIES AUTODESK INVENTOR ALLOWS YOU TO CREATE ASSEMBLIES WITH SMALL UNITS. THESE SMALL UNITS ARE CALLED AS SUBASSEMBLIES. YOU CAN ASSEMBLE PARTS AND SUBASSEMBLIES TO CREATE THE MAIN ASSEMBLY. A LARGE ASSEMBLY CAN HAVE MULTIPLE SUBASSEMBLIES. YOU CAN CONSTRUCT VERY

LARGE ASSEMBLIES EFFICIENTLY BY PLANNING AND BUILDING SUBASSEMBLIES. DIFFERENT METHODS OF CREATING SUBASSEMBLIES IN THE MAIN ASSEMBLY ARE DISCUSSED NEXT.

Creating a Subassembly Using the Bottom-up Design Approach In the bottom-up subassembly design approach, the subassemblies are created separately and then saved as individual assembly files. To place a subassembly in the main assembly, open the main assembly and then place the subassembly by using the **Place** tool, just as you place the parts. After placing the subassembly, you will observe that an assembly icon is displayed on left of the subassembly in the **Browser Bar**. If you double-click on the subassembly icon, the corresponding subassembly and its children (components) will be activated, and now you can place or create a component in that subassembly. In this way, you can create multilevel subassemblies. To activate the parent assembly, you need to double-click on it.

Creating a Subassembly Using the Top-down Design Approach To create a subassembly using the top-down approach, open an assembly file and then create a component in it using the **Create** tool. Next, select the component from the **Browser Bar** and right-click on it; a

shortcut menu will be displayed. Now, choose **Component > Demote** from the shortcut menu; the **Create In-Place Component** dialog box will be displayed. You can use the options in the dialog box to save the component at the required location, as explained in the previous chapter.

CHECKING DEGREES OF FREEDOM OF A COMPONENT AS MENTIONED EARLIER, YOU CAN RESTRICT THE DEGREES OF FREEDOM OF A COMPONENT BY APPLYING ASSEMBLY CONSTRAINTS TO IT. YOU CAN VIEW THE DEGREES OF FREEDOM THAT ARE NOT RESTRICTED IN A COMPONENT BY CHOOSING THE **DEGREES OF FREEDOM** TOOL FROM THE **VISIBILITY** PANEL OF THE **VIEW** TAB. WHEN YOU CHOOSE THIS TOOL, THE SYMBOL OF THE DEGREES OF FREEDOM WILL BE DISPLAYED ON THE SCREEN. IN AUTODESK INVENTOR, EVERY COMPONENT HAS SIX DEGREES OF FREEDOM. THESE ARE LINEAR MOVEMENT ALONG X, Y, AND Z AXES AND ROTATIONAL MOVEMENT ABOUT X, Y, AND Z AXES. THESE DEGREES OF FREEDOM ARE DISPLAYED USING AN ICON SIMILAR TO THE 3D INDICATOR AT THE LOWER LEFT CORNER OF THE DRAWING WINDOW. FOR A COMPONENT WITH ALL DEGREES OF

FREEDOM, THE SYMBOL OF DEGREES OF FREEDOM WILL CONSIST OF THREE LINEAR AXES POINTING IN THE X, Y, AND Z DIRECTIONS AND CIRCULAR ARROWS ON ALL THREE AXES, AS SHOWN IN FIGURE 10-6.




Figure 10-6 Component with all degrees of freedom

When you apply the assembly constraints, these movements are restricted and therefore, the degrees of freedom are removed. When a particular degree of freedom is removed, it will not be displayed in the symbol of the degrees of freedom. For example, if you apply the assembly constraint such that the linear movement of the component is restricted along the Z axis, the linear axis along the Z axis will not be displayed in the symbol of degrees of freedom. However, the circular axis along the Z axis will still be displayed because you have not restricted that movement. Therefore, for a component whose all degrees of freedom are restricted, there will be no symbol of the degrees of freedom.

Tip. By default, the first component that you place or create in an assembly file is not grounded. A grounded component has all its degrees of freedom restricted, and therefore, the symbol of the degrees of freedom is not displayed on it.

However, if the first component is ungrounded after assembling other components with it, you will notice that the symbol of the degrees of freedom is displayed on it, indicating that all degrees of freedom of the component are not restricted. You will also notice that a small green color cube is displayed on all other components that were assembled with the grounded component. This cube indicates that all these components are assembled with an under-constrained component. Note that the component became under-constrained when you ungrounded it. To view the under-constrained component, move the cursor on the green color cube on any one of the assembled components; the green color cube will be highlighted. The component will change back to its original color when you move the cursor away from the cube.

CREATING THE PATTERN OF COMPONENTS IN AN ASSEMBLY RIBBON: ASSEMBLE > PATTERN > PATTERN WHILE CREATING THE ASSEMBLIES, YOU HAVE TO SOMETIMES ASSEMBLE MORE THAN ONE INSTANCE OF A COMPONENT ABOUT A SPECIFIED ARRANGEMENT. FOR EXAMPLE, IN CASE OF A BUTTERFLY VALVE ASSEMBLY, YOU HAVE TO ASSEMBLE THREE INSTANCES OF SCREW WITH THE RETAINER AND THE BODY (REFER TO TUTORIAL 1 OF CHAPTER 9). ALL THESE THREE INSTANCES WERE RECALLED IN THE CURRENT ASSEMBLY FILE AND THEN ASSEMBLED USING THE ASSEMBLY CONSTRAINT. ALSO, IF YOU HAVE TO INCREASE THE NUMBER OF HOLES IN THE RETAINER AND THE BODY FROM THREE TO FOUR, YOU WILL HAVE TO RECALL ANOTHER INSTANCE OF THE SCREW AND INSERT IT USING THE ASSEMBLY

CONSTRAINT. HOWEVER, THIS IS A VERY TEDIOUS AND TIME-CONSUMING PROCESS. THEREFORE, TO REDUCE THE TIME FOR ASSEMBLING THE COMPONENTS, AUTODESK INVENTOR HAS PROVIDED A TOOL FOR CREATING THE PATTERN OF THE COMPONENTS. YOU CAN USE THIS TOOL TO CREATE CIRCULAR OR RECTANGULAR PATTERNS. THIS WILL REDUCE THE ASSEMBLING TIME AS WELL THE TIME TAKEN IN RECALLING THE NUMBER OF INSTANCES OF THE COMPONENTS. ANOTHER ADVANTAGE OF CREATING THE PATTERN IS THAT IF YOU INCREASE THE NUMBER OF INSTANCES IN THE PATTERN FEATURE ON THE ORIGINAL PART, THE NUMBER OF INSTANCES OF THE COMPONENTS IN THE PATTERN WILL INCREASE AUTOMATICALLY. FOR EXAMPLE, IF YOU INCREASE THE NUMBER OF HOLES FROM THREE TO FOUR IN THE RETAINER OF THE BUTTERFLY VALVE ASSEMBLY, ONE MORE INSTANCE OF THE SCREW WILL BE AUTOMATICALLY RECALLED IN THE ASSEMBLY FILE AND INSERTED IN THE FOURTH HOLE OF THE RETAINER.


The pattern of components in the assembly file is created using the **Pattern** tool. On invoking this tool, the **Pattern Component** dialog box will be displayed, as shown in Figure 10-7. The options in this dialog box are discussed next.

Component

You can choose the **Component** button to select the component that you want to pattern in an assembly file. When you invoke the **Pattern Component** dialog box, this button is chosen automatically and you are prompted to select the component to be patterned. The options in various tabs of this dialog box are discussed next.

Associative Tab

The **Associative** tab (Figure 10-7) will be active by default when you invoke the **Pattern Component** tool. The options in this tab are used to select the pattern of the feature on the base part to which the pattern of components will be associated. This pattern can be selected by choosing the **Associated Feature Pattern** button provided in the **Feature Pattern Select** area of this tab. When you choose this button, you will be prompted to select the feature pattern to which the pattern of components will be associated. You can select the pattern of the feature on the base part. Depending on whether the pattern selected is rectangular or circular, it will be displayed in the display box provided on the right of the **Associated Feature Pattern** button. Also, the selected component will be assembled with all the instances of the feature pattern. Remember that the number of instances of components assembled using this tool will be updated on modification in the number of instances in the pattern of feature only if the pattern of the component is created using the **Associative** tab.



*Figure 10-7 The **Pattern Component** dialog box*

Figure 10-8 shows the selection of the hexagonal bolt after choosing the **Component** button from the **Pattern Component** dialog box. Note that the bolt is assembled with a base plate using the **Insert** constraint. The holes in the plate are created as a pattern feature. Figure 10-9 shows the selection of the hole feature after choosing the **Associated Feature Pattern** button. Figure 10-10 shows the resultant model.





Figure 10-8 Selection of the component to be patterned



*Figure 10-9 Selection of the hole feature on using the **Associated Feature Pattern** button*

Rectangular Tab

The options in this tab are used to create a rectangular pattern of the selected component in the assembly file, see Figure 10-11. The options in this tab are similar to those discussed in the **Rectangular Pattern** dialog box in Chapter 6.




Figure 10-10 Resultant model

Note

Similar to the **Rectangular Pattern** dialog box, the options in the **Rectangular** tab of the **Pattern Component** dialog box will be available only after you specify the directions for the column and row placement.

Circular Tab

The options in the **Circular** tab of the **Pattern Component** dialog box are used to create a circular pattern of the selected component, see Figure 10-12. The options in this tab are similar to those discussed in the **Circular Pattern** dialog box in Chapter 6.




Figure 10-11 The **Rectangular** tab of the **Pattern Component** dialog box




Figure 10-12 The **Circular** tab of the **Pattern Component** dialog box

Note

The **Angle** edit box in the **Circular** tab is used to specify the incremental angle between the individual instances of the pattern.

Tip. While creating an assembly, you may need to place a particular component more than once. In such cases, select the required component from the **Browser Bar** and then drag it to the graphics area. By default, the dragged component will be oriented as it was oriented in the **Part** environment. But if you need to place the dragged component according to the last orientation in the **Assembly** environment, choose the **Applications Options** tool from the **Options** panel of the **Tools** tab. On doing so, the **Application Options** dialog box will be displayed. Choose the **Assembly** tab in this dialog box and then select the **Use last occurrence orientation for component placement** check box. Next, choose the **OK** button to exit the **Application Options** dialog box.

REPLACING A COMPONENT FROM THE ASSEMBLY FILE WITH ANOTHER COMPONENT

AUTODESK INVENTOR ALLOWS YOU TO REPLACE A COMPONENT IN THE ASSEMBLY FILE WITH ANOTHER COMPONENT. YOU CAN REPLACE THE SINGLE INSTANCE OF THE COMPONENT OR ALL THE INSTANCES OF THE SELECTED COMPONENT WITH ANOTHER COMPONENT. IF THE SHAPE OF THE NEW COMPONENT IS THE SAME AS THAT OF THE ORIGINAL COMPONENT THAT YOU REPLACED, THE ASSEMBLY CONSTRAINTS WILL BE RETAINED. HOWEVER, IF THE SHAPE OF THE NEW COMPONENT IS NOT SIMILAR TO THAT OF THE ORIGINAL COMPONENT, THE ASSEMBLY CONSTRAINTS WILL BE LOST AND YOU WILL HAVE TO APPLY THE CONSTRAINTS AGAIN. THE NEW COMPONENT WILL BE PLACED AT THE SAME LOCATION AS THAT OF THE ORIGINAL COMPONENT. THE METHODS OF REPLACING THE COMPONENTS ARE DISCUSSED NEXT.

Replacing a Single Instance of the Selected Component
Ribbon: Assemble > Component > Replace The single instance of a component can be replaced by using the **Replace** tool. When you invoke this tool, you will be prompted to select the component to be replaced. Select the component to be replaced. Next, right-click in the graphics window; a marking menu will be displayed.

Choose **Continue** from it; the **Place Component** dialog box will be displayed, as shown in Figure 10-13.

Note

*You can select the component to be replaced before or after invoking the **Replace** tool. If you select the component from the graphics window or from the **Browser Bar** and then invoke the **Replace** tool, the **Place Component** dialog box will be displayed directly.*

You can use this dialog box to specify the name and location of the new component. You can either double-click on the component or select it and choose the **Open** button. The selected component will be placed at the location of the previous component. Remember that the assembly constraints will be retained only if the shape of the new component is the same as that of the original component.

If there are chances that the assembly constraints that you have applied on the component to be replaced are going to be lost, the **Possible Constraint Loss** message box will be displayed, as shown in Figure 10-14. This dialog box will inform you that the constraints and notes associated with the component may be lost. Choose the **OK** button to continue with the process of replacement of the component. To abort the process, choose the **Cancel** button.




Figure 10-13 The *Place Component* dialog box

Note

Sometimes when you choose the **OK** button from the **Possible Constraint Loss** message box, the **Autodesk Inventor Professional - Replace Component** information box is displayed. Choose the **Accept** button from this dialog box to continue with the part replacement.




Figure 10-14 The *Possible Constraint Loss* message box

Replacing All Instances of the Selected Component

Ribbon: Assemble > Component > Replace drop-down >

Replace All You can replace all instances of a component by choosing the **Replace All** tool from the **Component** panel. When you choose this tool, you will be prompted to select the component to be replaced. Select the component to be replaced from the screen or the **Browser Bar**. Next, right click in the graphics window; a marking menu will be displayed. Choose **Continue** from it; the **Place Component** dialog box will be displayed. You can use this dialog box to select the new component. All the instances of the selected component will be replaced with the component selected from the **Place Component** dialog box.

MIRRORING SUBASSEMBLIES OR COMPONENTS OF AN ASSEMBLY RIBBON: ASSEMBLE > PATTERN > MIRROR AUTODESK INVENTOR ALLOWS YOU TO MIRROR ASSEMBLIES OR ASSEMBLY COMPONENTS USING THE **MIRROR** TOOL. YOU CAN USE THIS TOOL TO SPECIFY WHETHER THE MIRRORED COMPONENTS OR SUBASSEMBLIES WILL BE INSERTED IN THE CURRENT FILE OR IN A NEW ASSEMBLY FILE. WHEN YOU INVOKE

THIS TOOL, THE **MIRROR COMPONENTS: STATUS** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 10-15. THE OPTIONS IN THIS DIALOG BOX ARE DISCUSSED NEXT.




Figure 10-15 The Mirror Components: Status dialog box

-

Components When you invoke the **Mirror Components: Status** dialog box, the **Components** button is chosen by default and you are prompted to select the components to be mirrored. You can select the components from the drawing window or from the **Browser Bar**. The components or subassemblies that you select are added to the list box in the **Mirror Components: Status** dialog box. Note that the constraints will be copied only if all

the components on which the constraints are applied are selected to be mirrored.

Mirror Plane

This button is chosen to select the mirror plane. This is the plane about which the assembly or components will be mirrored.

List Box

The list box in the **Mirror Component: Status** dialog box lists the components and subassemblies selected to be mirrored. You can also use the list box to specify whether the resultant components will be mirrored or reused. By default, the components are mirrored. These components have a green circle icon with two arrows pointing in the opposite directions on the left of their names in the **Mirror Components: Status** dialog box. They are displayed in transparent green in the mirror preview. The components that are mirrored using this option are saved as separate files when you save the assembly file. You can also mirror the selected component as mirror, reused, or excluded component by choosing the corresponding buttons on the right of the **Status** area. To specify the names of the files, choose **Next** from the **Mirror Components: Status** dialog box.

If you click once on the green circle icon, it changes to a yellow circle with a plus sign in between. This suggests that the selected components are mirrored as reused. The reused components are displayed in transparent yellow in the preview.

If you click again on the yellow circle icon, it changes to gray with an inclined line. This suggests that the components are excluded from the current selection set and will not be mirrored.

Copy list of unsuitable reuse components to clipboard 

This button will be activated only when the Autodesk Inventor fails to reuse the constraints of the parts to be reused. It is present on the top right area of the dialog box and is used to copy the list of components that are not

suitable for reusing in Assembly. These components are also highlighted in the **Mirror Components** dialog box. You can paste the name of these components to any document.

More

This button is located on the lower right side of the **Mirror Components: Status** dialog box. When you choose this button, the **Mirror Components: Status** dialog box expands and provides the options discussed next.

Reuse Standard Content and Factory Parts The **Reuse Standard Content and Factory Parts** check box is selected to make sure that the content library components and factory parts are reused and not mirrored.

Preview Components Area

The check boxes in this area are used to specify whether the mirrored, reused, or content library components will be shown in the preview.

After selecting the components to mirror and setting the parameters in the **Mirror Components: Status** dialog box, choose **Next**; the **Mirror Components: File Names** dialog box will be displayed, as shown in Figure 10-16. This dialog box is used to specify whether the resultant components are placed in the same assembly file or copied in a new assembly file. The options in this dialog box are discussed next.

List Box

The list box in this dialog box lists all subassemblies and components that were selected to be mirrored. This list box has four columns, which are discussed next.




Figure 10-16 The *Mirror Components: File Names* dialog box

Name

This column lists the names of the original components or subassemblies selected to be mirrored.

New Name

This column lists the new name by which the selected components will be saved. You can click on the name field to change the name of the new component. The default naming options also depend on the parameters defined in the **Naming Scheme** area of this dialog box.

File Location

This column lists the location of the part file, in which the new component will be saved. By default, it shows **Source Path**. As a result, the new component file will be saved in the same folder, in which the original file is saved. You can right-click on **Source Path** to change the path to a user defined path or the current work place.

Status

This column defines the status of the resultant component. By default, it shows the status of **New File**. As a result, the file will be saved as a new part file. If you specify the name of the new component that already exists in the folder in which the part file will be saved, the status changes to **Reuse Existing**. This suggests that a part file with the same name already exists and that you can reuse the existing file.

Naming Scheme Area

This area is used to set the parameters for the default name of the new part files that are listed in the **New Name** column of the list box in this dialog box. By default, the **Suffix** check box is selected and **_MIR** is entered in the text box on the right of the **Suffix** check box. As a result, the name of the new part file is the name of the original part file which is selected to be mirrored with **_MIR** as suffix. Similarly, you can also add some prefix to the default name by selecting the **Prefix** check box. The prefix that you want to add can be entered in the text box available on the right of the **Prefix** check box. You can select the **Increment** check box to add an incremental number to the name of the new file. Remember that after setting the parameters in this area, you need to choose the **Apply** button. You can restore the original name settings by choosing the **Revert** button.

Component Destination Area

This area is used to specify whether the new components will be placed in the current assembly file or inserted in a new assembly file. Select the **Insert in Assembly** radio button to insert the parts in the current assembly file. If you want to copy the parts in a new assembly file, select the **Open in New Window** radio button. The selected components will be copied in a new assembly file and that assembly file will be opened on the screen. Note that if you select the **Open in New Window** radio button, you can also modify the name of the new assembly in the **New Name** column of the list box.

Return to Selection

You can choose the **Return to Selection** button to return to the **Mirror Components: Status** dialog box.

After setting the parameters in the **Mirror Components: File Names** dialog box, choose the **OK** button. The selected components will be mirrored in the current assembly file or will be copied in a new assembly file, depending on the parameters selected.

COPYING SUBASSEMBLIES OR COMPONENTS OF AN ASSEMBLY RIBBON: ASSEMBLE > PATTERN >

COPY SIMILAR TO MIRRORING THE COMPONENTS, YOU CAN ALSO COPY A SUBASSEMBLY OR COMPONENTS OF AN ASSEMBLY USING THE **COPY** TOOL. ON INVOKING THIS TOOL, THE **COPY COMPONENTS: STATUS** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 10-17 AND YOU WILL BE PROMPTED TO SELECT THE COMPONENTS; SELECT THE COMPONENT TO COPY. THIS DIALOG BOX IS SIMILAR TO THE MIRROR COMPONENTS: STATUS DIALOG BOX.

After selecting the components to copy, when you choose **Next** from this dialog box, the **Copy Components: File Names** dialog box will be displayed. The options in this dialog box are similar to those discussed in the **Mirror Components: File Names** dialog box.

Note

In Autodesk Inventor, you can copy the components with joints, constraints, and orientation.




Figure 10-17 The Copy Components: Status dialog box

DELETING COMPONENTS

You can delete the unwanted instances or the unwanted components from the assembly using the **Browser Bar**. In the **Browser Bar**, right-click on the unwanted component and choose **Delete** from the shortcut menu; the selected component will be deleted from the assembly.

To delete the components that were assembled using the **Pattern** tool, right-click on **Component Pattern** in the **Browser Bar**. Choose **Delete** from the shortcut menu; all instances of the component assembled will be deleted. Note that the original component will not be deleted. You can delete the original instance by right-clicking on it in the **Browser Bar** and choosing **Delete** from the shortcut menu.

EDITING THE PATTERN OF COMPONENTS

AUTODESK INVENTOR ALLOWS YOU TO EDIT THE PATTERN OF THE COMPONENTS CREATED USING THE **PATTERN** TOOL. TO EDIT THE PATTERN OF COMPONENTS, RIGHT-CLICK ON

COMPONENT PATTERN IN THE **BROWSER BAR** AND CHOOSE **EDIT** FROM THE SHORTCUT MENU; THE **EDIT COMPONENT PATTERN** DIALOG BOX WILL BE DISPLAYED THAT CAN BE USED TO EDIT THE PATTERN. NOTE THAT THIS DIALOG BOX WILL HAVE ONLY THE TAB THAT WAS USED FOR CREATING THE PATTERN OF THE COMPONENT. FOR EXAMPLE, IF THE PATTERN OF THE COMPONENT WAS CREATED USING THE **ASSOCIATIVE** TAB OF THE **PATTERN COMPONENT** DIALOG BOX, THE **EDIT COMPONENT PATTERN** DIALOG BOX WILL HAVE ONLY THE **ASSOCIATIVE** TAB, AS SHOWN IN FIGURE 10-18. SIMILARLY, IF THE PATTERN OF THE COMPONENT WAS CREATED USING THE **CIRCULAR** TAB OF THE **PATTERN COMPONENT** DIALOG BOX, THE **EDIT COMPONENT PATTERN** DIALOG BOX WILL HAVE ONLY THE **CIRCULAR** TAB.




Figure 10-18 The Edit Component Pattern dialog box

Note

*The options in the **Edit Component Pattern** dialog box are similar to those discussed in the **Pattern Component** dialog box.*

MAKING A PATTERN INSTANCE INDEPENDENT
YOU CAN ALSO MAKE A SELECTED INSTANCE
INDEPENDENT, WHICH WILL BE DISPLAYED AS
A SEPARATE COMPONENT IN THE **BROWSER
BAR** AND WILL NOT BE DELETED WHEN YOU
DELETE ITS PATTERN. TO MAKE THE SELECTED
INSTANCE INDEPENDENT, CLICK ON THE PLUS
(+) SIGN LOCATED ON THE LEFT OF
COMPONENT PATTERN IN THE **BROWSER BAR**.
ALL INSTANCES OF THE PATTERN WILL BE
DISPLAYED AS ELEMENTS IN THE **BROWSER
BAR**. NOTE THAT THE FIRST ELEMENT IS THE
ORIGINAL COMPONENT AND YOU CANNOT
MAKE THIS ELEMENT INDEPENDENT BECAUSE

IT IS NOT DEPENDENT ON THE PATTERN. TO MAKE ANY OTHER COMPONENT INDEPENDENT, RIGHT-CLICK ON IT AND THEN CHOOSE **INDEPENDENT** FROM THE SHORTCUT MENU. YOU WILL NOTICE THAT A RED CROSS IS DISPLAYED ON THE LEFT OF THE INDEPENDENT ELEMENT IN THE **BROWSER BAR**.

You can again make the independent element dependent. To do so, right-click on the independent element in the list of elements in the **Browser Bar** to display the shortcut menu. You will notice that a check mark is displayed on the left of the **Independent** option. Choose this option again. The red cross on the element will no more be displayed, suggesting that it has again become dependent on the pattern. Note that when you make a component dependent again, the instance of the component that was placed in the assembly as a separate component and displayed in the **Browser Bar**, will not be removed. You will have to manually delete the component.

DELETING ASSEMBLY CONSTRAINTS

You can delete the unwanted assembly constraints using the **Browser Bar**. To delete the assembly constraint, click on the plus (+) sign located on the left of the component in the **Browser Bar**. The **Origin** folder, along with all the constraints that are applied on the component, will be displayed. Right-click on the constraint to be deleted and choose **Delete** from the shortcut menu; the selected constraint will be deleted.

CREATING ASSEMBLY SECTION VIEWS IN THE ASSEMBLY FILE RIBBON: VIEW > APPEARANCE > SECTION VIEW DROP-DOWN SOMETIMES, WHILE ASSEMBLING COMPONENTS IN AN ASSEMBLY, SOME OF THE COMPONENTS ARE HIDDEN BEHIND THE

OTHER COMPONENTS OF THE ASSEMBLY. TO VISUALIZE SUCH COMPONENTS, AUTODESK INVENTOR ALLOWS YOU TO CREATE THE SECTION VIEWS OF THE ASSEMBLY. THESE SECTION VIEWS ARE FOR REFERENCE ONLY AND COMPONENTS ARE NOT ACTUALLY CHOPPED WHEN YOU CREATE THE SECTION VIEWS. YOU CAN CREATE FOUR TYPES OF SECTION VIEWS: QUARTER SECTION VIEW, HALF SECTION VIEW, AND THREE QUARTER SECTION VIEW.




Figure 10-19 Tools in the Section View drop-down

To create the quarter section view, choose the **Quarter Section View** tool from **Section View** drop-down available in the **Appearance** panel of the **View** tab, see Figure 10-19. On doing so, you will be prompted to select work planes or planar faces that will be used to section the assembly. Select a planar face or a work plane and choose the **Continue** button from the mini toolbar; you will be prompted to select the second plane. Select a plane perpendicular to the previous plane; the assembly will be sectioned. You can flip the direction of quarter section by right-clicking and then choosing **Flip Section** from the shortcut menu. Continue choosing this option until the required quarter is displayed. Once the required quarter is displayed, right-click and choose **OK** from the Marking menu.

To create the half section view, choose the **Half Section View** tool from the **Section View** drop-down, refer to Figure 10-19. On doing so, you will be prompted to select the planar face or the work plane for creating the section view. Select a planar face or a work plane. Since you require only one plane for creating a half section, the assembly will be sectioned about the planar face on the work plane as soon as you select it. You can flip the section by right-clicking and choosing **Flip Section** from the shortcut menu displayed. Once the required section is displayed, right-click and choose **OK** from the Marking menu.

To create the three quarter section view, choose the **Three Quarter Section View** tool from the **Section View** drop-down, refer to Figure 10-19. On doing so, you will be prompted to select the work plane or the planar face for creating the section view. Select a planar face or a work plane and choose the **Continue** button from the mini toolbar; you will again be prompted to select the work plane or planar face. Select the second work plane or planar face; the three quarter section view will be created. Once the required section is displayed, right-click and choose **OK** from the Marking menu.

You can exit the section views by choosing the **End Section View** tool from the **Section View** drop-down, refer to Figure 10-19. On choosing this tool, the whole assembly is displayed.

Figure 10-20 shows the quarter section view of an assembly and Figure 10-21 shows the three quarter section view of the same assembly.




Figure 10-20 Quarter section view of an assembly





Figure 10-21 Three quarter section view of the same assembly

ANALYZING ASSEMBLIES FOR INTERFERENCE
RIBBON: INSPECT > INTERFERENCE > ANALYZE
INTERFERENCE WHENEVER YOU ASSEMBLE
THE COMPONENTS OF AN ASSEMBLY, NO
COMPONENT SHOULD INTERFERE WITH THE
OTHER COMPONENTS OF THE ASSEMBLY. IF
THERE IS AN INTERFERENCE BETWEEN THE
COMPONENTS, IT SUGGESTS THAT THE
DIMENSIONS OF THE COMPONENTS ARE
INCORRECT OR THE COMPONENTS ARE NOT
ASSEMBLED PROPERLY. YOU WILL HAVE TO
ELIMINATE THE INTERFERENCE IN THE
ASSEMBLY TO INCREASE THE EFFICIENCY OF
THE ASSEMBLY AND ALSO ELIMINATE THE
MATERIAL LOSS. IN AUTODESK INVENTOR, YOU
CAN ANALYZE THE ASSEMBLIES
FOR INTERFERENCE USING THE **ANALYZE
INTERFERENCE** TOOL. THIS TOOL CAN
BE INVOKED FROM THE **INTERFERENCE** PANEL

OF THE **INSPECT** TAB. YOU NEED TO SELECT TWO SETS OF COMPONENTS TO ANALYZE INTERFERENCE. WHEN YOU INVOKE THIS TOOL, THE **INTERFERENCE ANALYSIS** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 10-22. THE OPTIONS IN THIS DIALOG BOX ARE DISCUSSED NEXT.



*Figure 10-22 The **Interference Analysis** dialog box*

Define Set # 1

The **Define Set # 1** button is used to select the first set of components. When you invoke the **Interference Analysis** dialog box, this button is chosen by default and you will be prompted to select the component to add to the selection set. The selected components will be highlighted and displayed in a blue outline.

Define Set # 2

The **Define Set # 2** button is used to select the second set of components. When you choose this button, the objects selected using the **Define Set # 1** button will be displayed in a green outline. The components that you select now will be displayed in a blue outline.

OK

After selecting the components in the first set and the second set, choose the **OK** button to analyze the assembly. If there is no interference between the components, the **Autodesk Inventor Professional 2016** message box will be displayed, informing you that there is no interference between the components.

However, if there is an interference, the **Interference Detected** dialog box will be displayed and the portion of the interfering components will be displayed in red in the assembly. The **Interference Detected** dialog box will inform you about the number of interferences found and the total volume of interference. This dialog box has a button with two arrows at the lower right corner. If you choose this button, this dialog box will expand and will provide you additional information about the interfering components, see Figure 10-23. You can copy this information on the clipboard and later paste it in a file or print it.




Figure 10-23 The expanded Interference Detected dialog box

CREATING DESIGN VIEW REPRESENTATIONS
THE DESIGN VIEW REPRESENTATIONS ARE
USER-DEFINED VIEWS THAT ARE USED TO VIEW
ASSEMBLIES OR GENERATE PRESENTATION OR
DRAWING VIEWS OF A PARTICULAR VIEW OF
AN ASSEMBLY. YOU CAN SPECIFY ANY
ORIENTATION AS A DRAWING VIEW BY USING

THE COMBINATION OF DRAWING DISPLAY TOOLS AND THEN SAVE THE ASSEMBLY VIEW WITH THAT ORIENTATION. ONCE THE VIEW IS SAVED, YOU CAN OPEN IT BY ITS NAME, WHENEVER REQUIRED. IN ADDITION TO THE ASSEMBLY FILE, YOU CAN ALSO USE DESIGN VIEWS FOR GENERATING VIEWS BOTH IN THE PRESENTATION FILE AND IN THE DRAWING FILE.

To create a design view representation, first you need to define the viewing characteristics that you want to save in the representation. To define the viewing characteristics, use the display control tools such as ViewCube, SteeringWheels, Zoom, and so on. After a representation is created, you need to save it. To do so, right-click on the **Representations** node in the **Browser Bar** and choose the **Expand All Children** option from the shortcut menu; the **View: Default** node along with various representations will be displayed in the **Browser Bar**. Next, right-click on the **View: Default** node and choose the **New** option from the shortcut menu; the new representation with a different name **View1** will be added to the **View: Master** node. You can rename this representation by entering a new name in the edit box that is displayed when you double-click on it. Now, right-click on the **View1** representation and choose the **Lock** option from the shortcut menu; the design view representation will be created. For creating other design view representations, follow the same procedure. You can activate any design view by right-clicking on it and then choosing the **Activate** option from the shortcut menu.

You can view different view representations in the **Representation** dialog box. To invoke this dialog box, right-click on the **Representation** node; a shortcut menu will be displayed. Choose the **Representation** option from it. The **Representation** dialog box is shown in Figure 10-24. The options available in this dialog box are discussed next.




Figure 10-24 The Representation dialog box

Design View Representation Area The **Design View Representation** drop-down list in this area contains all the design view representations of the assembly. The options in this drop-down list are used to view user-defined design views, Master View, and Default View.

You can create a design view representation as discussed earlier in this chapter. You can save it as current design view representation by selecting it from the drop-down list and then choosing the **OK** button from the **Representation** dialog box. You can also activate the required design view representation by double-clicking on it in the **Browser Bar** under the **View** node. Alternatively, right-click on the required design view representation to display the shortcut menu. Next, choose **Activate** from the shortcut menu displayed. You will notice that the assembly on the graphics screen is reoriented such that it displays the selected design views.

Positional Representation Area This area contains the **Positional Representation** drop-down list. Positional representations are the views of the assembly that represent assemblies in different component positions. This drop-down list contains all the positional

representations created for the particular assembly. The detailed information on creating positional representations has been discussed later in this chapter.

Level Of Detail Representation The **Level of Detail Representation** area is used to suppress the level of representations. Using the options in this area, you can suppress unnecessary parts/components. As a result, the assembly requires less memory.

SIMULATING THE MOTION OF COMPONENTS OF AN ASSEMBLY BY DRIVING ASSEMBLY CONSTRAINTS AUTODESK INVENTOR ALLOWS YOU TO SIMULATE THE MOTION OF THE COMPONENTS OF AN ASSEMBLY BY DRIVING THE ASSEMBLY JOINTS AND CONSTRAINTS. REMEMBER THAT IN THE **ASSEMBLY** MODULE, YOU CAN SIMULATE THE MOTION OF THE COMPONENT USING ONLY ONE CONSTRAINT AT A TIME. HOWEVER, YOU CAN CREATE SOME RELATION PARAMETERS AND EQUATIONS FOR SIMULATING THE MOTION OF THE COMPONENTS USING MORE THAN ONE CONSTRAINT AT A TIME. TO DRIVE JOINTS OR CONSTRAINT, RIGHT-CLICK ON IT IN THE **BROWSER BAR** AND CHOOSE **DRIVE**, SEE FIGURE 10-25. ON DOING SO, THE **DRIVE** DIALOG

BOX WILL BE DISPLAYED, SEE FIGURE 10-26. THE OPTIONS IN THIS DIALOG BOX ARE DISCUSSED NEXT.




Figure 10-25 Choosing the Drive option




Figure 10-26 The Drive dialog box

Start

The **Start** edit box is used to specify the position of the starting point of simulation. The value in this edit box depends on the type of constraint or connection you have selected to drive. For example, if you have selected the **Insert** constraint to drive, the value in this edit box will be entered in millimeter. If you have selected the **Angle** constraint to drive, the value in this edit box will be entered in degrees. The default value of the angle or offset in this edit box will be the value that you have specified for the constraint. For example, if you have applied an angle value of 90 degrees between two components, the default value in the **Start** edit box will be 90.

Note

*The value in the **Start** edit box will also be displayed on the title bar of the **Drive Constraint** dialog box. Therefore, if the value of start point of the*

*constraint simulation is -90 degrees, the name of the dialog box will be **Drive Constraint (-90 deg)**.*

End

The **End** edit box is used to specify the position for ending the simulation. Similar to the **Start** edit box, the values in this edit box will be dependent on the type of constraint selected for simulation. The default value in this edit box will be the default value in the **Start** edit box plus 10.

Pause Delay

The **Pause Delay** edit box is used to specify some delay in the simulation of the components. The value in this edit box is entered in terms of seconds. By default, the value in this edit box is zero. Therefore, there will be no delay in the simulation of the components. If you enter 2 in this edit box, there will be a delay of 2 seconds between the steps of the simulation.

Forward

The **Forward** button is used to start the simulation of the component in the forward direction.

Reverse

The **Reverse** button is used to start the simulation of the component in the reverse direction.

Pause

The **Pause** button is used to temporarily stop the simulation of the component. The simulation can be resumed by choosing the **Forward** button or the **Reverse** button again.

Minimum

The **Minimum** button is chosen to reset the simulation such that the component is positioned at the start point of the simulation.

Reverse Step

The **Reverse Step** button is chosen to position the component one step behind the current step in the simulation. This button will not be available if the component is positioned at the start point of the simulation.

Forward Step

The **Forward Step** button is chosen to position the component one step ahead of the current step in the simulation. This button will not be available if the component is positioned at the endpoint of the simulation.

Maximum

The **Maximum** button is chosen to reset the simulation such that the component is positioned at the endpoint of the simulation.

Record

The **Record** button is chosen to record the simulation of the component in the form of *.avi* or *.wmv* file. When you choose this button, the **Save As** dialog box will be displayed. Using this dialog box, you can specify the name of the *.avi* file, in which you want to record the simulation. After specifying the name and location of the *.avi* or *.wmv* file, choose the **Save** button; the **Video Compression** or the **WMV Export Properties** dialog box will be displayed, respectively. These dialog boxes are used to specify the settings of the *.avi* or *.wmv* files, respectively. After specifying the options, close the respective dialog boxes. Next, choose the **Forward** or the **Reverse** button from the **Drive Constraint** dialog box to record the simulation. You can also choose both the buttons one by one to record the complete cycle of simulation. After recording the simulation, choose the **Record** button again to exit recording.


Note

*While recording the simulation, whatever is displayed inside the graphics window will be recorded. Remember that if you activate another application while the simulation is being recorded, the work done in that application will also be recorded in the *.avi* or the *.wmv* file.*

More

The **More** button is the one with two arrows on the lower right corner of the **Drive Constraint** dialog box. When you choose this button, the dialog box

expands and displays more options to simulate components, see Figure 10-27. These options are discussed next.



*Figure 10-27 More options in the **Drive** dialog box*

Drive Adaptivity

If the **Drive Adaptivity** check box is selected, the adaptive components will adapt during the process of simulation.

Collision Detection

If the **Collision Detection** check box is selected, the simulation will stop at the point where the collision is detected. The collision will be displayed in red and the **Autodesk Inventor Professional** information box will also be displayed. This information box will inform you that a collision has been detected.

Increment Area

The options in the **Increment** area are used to specify the method for defining the increment during the simulation of the component. These options are discussed next.

amount of value

The **amount of value** radio button is selected to specify the increment of simulation in terms of value of the steps. The value of the steps can be entered in the edit box available in the **Increment** area.

total # of steps

The **total # of steps** radio button is selected to specify the increment of simulation in terms of the total number of steps in the simulation. The number

of steps can be entered in the edit box in the **Increment** area.

Repetitions Area

The options in the **Repetitions** area are used to specify the method for defining the number of repetitions of the cycles in the simulation. These options are discussed next.

Start/End

The **Start/End** radio button is selected to simulate a component from the start position to the end position. If the number of repetitions is more than one, the component will be repositioned at the start position after the first cycle is over. Since the component is repositioned at the start position after the completion of the first cycle, the second cycle begins from the start position and the simulation process gets repeated.

Start/End/Start

The **Start/End/Start** radio button is selected to simulate a component such that the simulation is between the start position and the end position, and then again from the end position to the start position. If the number of repetitions is more than one, the second cycle will begin from the end position and the third cycle will start from the begin position, thus forming a loop. In other words, the start position of one cycle is the end position of the other cycle. So, if you want to simulate an assembly from the start position to the end position and then again from the end position to the start position, you need to enter **2** in the edit box provided in this area.

In addition to these radio buttons, there is an edit box in the **Repetitions** area, which is used to specify the number of cycles in the simulation.

Avi rate

The **Avi rate** edit box is used to specify the number of steps that will be removed before a step of simulation is recorded in the *.avi* file.

**CREATING POSITIONAL REPRESENTATIONS
POSITIONAL REPRESENTATIONS ARE THE
VIEWS OF THE ASSEMBLY THAT REPRESENT**

ASSEMBLIES IN DIFFERENT COMPONENT POSITIONS. FOR EXAMPLE, YOU CAN CREATE A POSITIONAL REPRESENTATION OF AN ASSEMBLY IN WHICH THE COMPONENTS ARE DRIVEN TO A CERTAIN DISTANCE FROM THEIR ORIGINAL ASSEMBLY POSITION. BY DEFAULT, EVERY ASSEMBLY HAS A MAIN DEFAULT POSITIONAL REPRESENTATION. THIS POSITIONAL REPRESENTATION REPRESENTS THE COMPONENTS AT THEIR DEFAULT ASSEMBLY POSITION. YOU CAN CREATE ADDITIONAL POSITIONAL REPRESENTATIONS IN WHICH YOU CAN MOVE THE COMPONENTS FROM THEIR DEFAULT LOCATION BY DRIVING THEIR CONSTRAINTS.

To create positional representations, click on the plus (+) sign located on the left of **Representations** in the **Browser Bar**; the tree view expands. Right-click on **Position** and choose **New** from the shortcut menu, as shown in Figure 10-28; the




Figure 10-28 Choosing the **New** option from the shortcut menu

name **Position** is changed to **Position : Position1** in the **Browser Bar** and the plus (+) sign is added to its left. Click on the plus (+) sign; the tree view expands and shows **Master** and **Position1** in the **Browser Bar**. Also, a check mark is displayed on the left of **Position1**, suggesting that this representational view is


current by default. Now, drive the constraints of the assembled components to create a positional representation of the assembly.

Before saving and exiting the assembly document, you need to restore the master positional representation. To do so, double-click on **Master** in **Position: Position 1** in the **Browser Bar**.

Note

*Whenever you try to save an assembly in a positional representation, an error message will be displayed informing you that the assembly cannot be saved in a positional representation. Further, you will be prompted to specify whether you want to save the master assembly. If you choose **OK** from this dialog box, the master representation will be invoked and the assembly will be saved. To restore a positional representation, double-click on it in the **Browser Bar**.*

VIEWING THE BILL OF MATERIAL OF THE CURRENT ASSEMBLY RIBBON: MANAGE > MANAGE > BILL OF MATERIALS AUTODESK INVENTOR ALLOWS YOU TO VIEW THE BILL OF MATERIAL OF THE CURRENT ASSEMBLY IN THE ASSEMBLY DOCUMENT ITSELF. TO VIEW THE BILL OF MATERIALS, CHOOSE THE **BILL OF MATERIALS TOOL FROM THE **MANAGE** PANEL OF THE **MANAGE** TAB; THE **BILL OF MATERIALS** DIALOG BOX, WHICH LISTS THE COMPONENTS OF THE CURRENT ASSEMBLY IN A TABULAR FORM WILL BE DISPLAYED, AS SHOWN IN FIGURE 10-29.**



*Figure 10-29 The **Bill of Materials** dialog box*

By default, the **Model Data** tab is chosen in this dialog box. As a result, the BOM data displayed will be similar to the modeling structure of the assembly. However, this data cannot be reported as the actual BOM in the parts list. Choose the **Structured** tab to view the actual BOM of the assembly. Alternatively, choose the **Parts Only** tab to invoke the **Parts Only** BOM view that shows all components of the subassembly as separate components. If the BOM data is not displayed, choose the down arrow on the right of the **View Options** button that is in the toolbar provided above the tabs in the **Bill of Materials** dialog box. On doing so, a flyout will be displayed. Choose the **Enable BOM View** option from the flyout; all components of assembly and the subassembly will be displayed as separate components in the BOM. The **Bill of Materials** dialog box has two toolbars: **Bill of Materials Toolbar** and **Expression Toolbar**. The **Bill of Materials Toolbar** located on top of this dialog box is used to export bill of materials, sort and renumber items, control the display of BOM data, update the mass properties of items, and so on. The **Expression Toolbar** located below the **Bill of Materials Toolbar** helps you to create or edit an expression for the selected BOM cell in the **Bill of Materials** dialog box. You can import the BOM customization setting into the current assembly by choosing the **Import** button. On doing so, the **Import BOM**

Customization dialog box will be displayed. In this dialog box, open the required *.xml* file to import the BOM customization setting. You can also export the BOM customization setting of the current assembly to the required location by choosing the **Export** button from the **Bill of Materials** dialog box. On doing so, the **Export BOM Customization** dialog box will be displayed. Specify the name and location of the *.xml* file to be exported and then save it.

WORKING WITH ASSEMBLY FEATURES
AUTODESK INVENTOR ALLOWS YOU TO PERFORM SOME METAL CUTTING OPERATIONS SUCH AS EXTRUDE, REVOLVE, SWEEP CUTS, CHAMFER, AND HOLES IN AN ASSEMBLY FILE. NOTE THAT THESE OPERATIONS ARE RESTRICTED ONLY TO THE ASSEMBLY FILE AND ARE NOT PERFORMED ON INDIVIDUAL COMPONENTS. FOR EXAMPLE, IF YOU CREATE AN EXTRUDED CUT FEATURE ON A COMPONENT IN THE ASSEMBLY ENVIRONMENT, THE CUT FEATURE CREATED IN THE ASSEMBLY WILL NOT BE CREATED ON THE ORIGINAL COMPONENT. AS A RESULT, THIS CUT FEATURE WILL BE DISPLAYED ONLY IN THE ASSEMBLY ENVIRONMENT AND NOT IN THE ORIGINAL COMPONENT FILE. NOTE THAT THESE OPERATIONS ARE NOT RESTRICTED TO A PARTICULAR COMPONENT, BUT EXTEND TO ALL THE COMPONENTS OF THE ASSEMBLY. FOR EXAMPLE, IF YOU CREATE A THROUGH-ALL CUT FEATURE IN AN ASSEMBLY, THE MATERIAL

WILL BE REMOVED NOT ONLY FROM THE COMPONENT ON WHICH THE SKETCH IS CREATED, BUT ALSO FROM THE COMPONENTS THAT COME ACROSS THE SKETCH.

To create assembly cut features such as extruded, revolved, and swept cuts, first you need to select a sketching plane on which the sketches will be drawn. To create a sketch, choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab and then select a planar face of any component or a work plane. The sketching environment will be activated and all the sketching tools will become available in the **Sketch** tab.

Note

The basic difference between editing the components in the assembly file and working with the assembly features is that the assembly features are not created on the original component. On the other hand, the editing operations performed on a component while editing them are actually made on the original component.

TUTORIALS

Tutorial 1

In this tutorial, you will open the Butterfly Valve assembly created in Tutorial 1 of Chapter 9 and then analyze the assembly for interference. Next, you will delete the last two instances of the Screw and assemble the remaining instances by creating a pattern of the first instance.

(Expected time: 30 min) The following steps are required to complete this tutorial:

- a. Copy the *Butterfly Valve* folder from the *c09* folder to the *c10* folder.
- b. Open the *Butterfly Valve.iam* file and analyze it for interference using the **Analyze Interference** tool.
- c. Delete the two instances of the Screw assembled with the Retainer and then create the two instances using the **Pattern** tool.

Copying the Butterfly Valve Folder In this tutorial, you will open the

Butterfly Valve assembly created in *c09* folder. However, it is recommended that before opening the assembly file, you should copy the entire folder of the Butterfly Valve in the *c10* folder. This helps you keep the *c09* folder unaffected when you make changes in the Butterfly Valve Assembly. Therefore, first you will copy the *Butterfly Valve* folder in the *c10* folder and then open the *Butterfly Valve.iam* file from this folder.

1. Start a new session of Autodesk Inventor. Open the folder *c09* available at the location *C:\Inventor_2016*.

You will notice that there is a folder with the name *Butterfly Valve* in *c09* folder. This is the folder, where you have stored all part files and the assembly file of the Butterfly Valve.

2. Right-click on the *Butterfly Valve* folder and choose **Copy** from the shortcut menu.
3. Now, open the folder *C:\Inventor_2016\c10*. If this folder does not exist, you can create it using the **Create New Folder** button in the **Open** dialog box.
4. Right-click in the folder and paste the *Butterfly Valve* folder in it. Open the *Butterfly Valve* folder and then open the *Butterfly Valve.iam* file from it.

The Butterfly Valve assembly is displayed on the screen.

Analyzing the Assembly for Interference After displaying the assembly on the screen, you will invoke the **Analyze Interference** tool and analyze the assembly for interference. There should be no interference in the assembly.

1. Choose the **Analyze Interference** tool from the **Interference** panel of the **Inspect** tab to display the **Interference Analysis** dialog box. In this dialog box, the **Define Set # 1** button is chosen by default. As a result, you are prompted to select the components to add to the selection set.
2. Select Body from the graphics screen and then choose the **Define Set # 2**

button from the dialog box. On doing so, you are again prompted to select the components to add to the selection set. Select the remaining components using the **Browser Bar**.

3. Choose the **OK** button; the **Analyzing Interference** dialog box is displayed. Also, you will notice that the system is analyzing the assembly for interference. After the analysis is completed, the **Autodesk Inventor Professional 2016** dialog box is displayed, informing you that no interference is detected. Choose **OK** from this dialog box to exit it.

Creating the Pattern of the Screw While creating the Butterfly Valve assembly in Chapter 9, you assembled three instances of the Screw with the Retainer. You will retain the first instance of the Screw and delete the other two instances from the assembly. The other two instances will be assembled using the **Pattern** tool.

1. Select **Screw:2** from the **Browser Bar** and then press the SHIFT/CTRL key. Next, select **Screw:3** from the **Browser Bar**; you will notice that both the selected components are displayed in blue color in the **Browser Bar**. Also, the components are displayed with a blue outline on the graphics screen.
2. Press the DELETE key to delete the two instances of the Screw.

Since the holes on the Retainer are not visible in the current view, you need to turn off the visibility of the Arm.

3. Turn off the visibility of the Arm using the **Browser Bar**.
4. Choose the **Pattern** tool from the **Pattern** panel of the **Assemble** tab; the **Pattern Component** dialog box is invoked. In this dialog box, the **Component** button is chosen and you are prompted to select the component to be patterned.
5. Select Screw as the component to be patterned. Choose the **Associated Feature Pattern** button from the **Feature Pattern Select** area of the

Associative tab; you are prompted to select the feature pattern to associate to.


6. Select the hole on the lower right of the Retainer. You will notice that the two instances of the Screw are assembled with the two holes on the Retainer. Also, the display box on the right of the **Associated Feature Pattern** button displays **Circular Pattern1**. This is the name of the pattern of holes on the Retainer.

Note

*If you have created holes on the Retainer as circles while creating its basic sketch, you cannot use them to create associative component patterns because you can only associate the pattern to the feature pattern, and not to the sketch pattern. In this case, you can create a non-associative pattern using the **Circular** tab of the **Pattern Component** dialog box. However, as mentioned earlier, the pattern created using a tab other than the **Associative** tab will not be modified if the number of instances of the feature in the feature pattern are increased.*

7. Choose **OK** to create the pattern of the component and exit the **Pattern Component** dialog box.

You will notice that the Screw is not displayed in the **Browser Bar**, instead the **Component Pattern 1** node is displayed in it. If you click on the plus (+) sign on the left of this node, the three instances of the Screw with the name **Element:1**, **Element:2**, and **Element:3** are displayed in the **Browser Bar**.



*Figure 10-30 Display of the **Browser Bar** for Tutorial 1*

8. Turn on the visibility of the Arm using the **Browser Bar**. Next, choose the **Save** tool from the **Quick Access Toolbar** to save the changes made in the assembly. The display of the **Browser Bar**, after making all changes in the assembly, is shown in Figure 10-30.
 9. Next, close the file.
-

Tutorial 2

In this tutorial, you will open the Drill Press Vice assembly created in *Exercise 1* of *c09* folder and then check the interference between the Base and the remaining components of the assembly. After checking the interference, you will drive the **Mate** constraint applied between the Clamp Screw and the Movable Jaw. **(Expected time: 30 min)**

The following steps are required to complete this tutorial:

- a. Copy the Drill Press Vice assembly from the *c09* folder to the *c10* folder.
- b. Open the *Drill Press Vice.iam* file and analyze it for interference.
- c. Drive the **Mate** constraint applied between the vertical faces of the Jaw Face and the Base.

Copying the Drill Press Vice Assembly As you do not want to modify the assembly created in *c09* folder, you need to copy the entire folder of the Drill Press Vice assembly to the *c10* folder. After copying the folder, you will open the assembly file and check components for interference. Note that there should be no interference between the components.

1. Choose the **Open** tool from the **Launch** panel of the **Get Started** tab; the **Open** dialog box is displayed. Using this dialog box, open the folder *c09* from the location *C:\Inventor_2016*.
2. Right-click on the *Drill Press Vice* folder and then choose **Copy** from the shortcut menu.
3. Open the folder *C:\Inventor_2016\c10*. Right-click and choose **Paste** to paste the *Drill Press Vice* folder in the *c10* folder.

4. Open the *Drill Press Vice.iam* file from the *Drill Press Vice* folder.

Checking the Assembly for Interference 1. Choose the **Analyze Interference** tool from the **Interference** panel of the **Inspect** tab; the **Interference Analysis** dialog box is invoked.

In this dialog box, the **Define Set # 1** button is chosen by default. As a result, you are prompted to select the components to add to the selection set.

2. Select Base from the graphics screen. Next, choose the **Define Set # 2** button from the dialog box and then select the remaining components in the **Browser Bar**.

3. Choose **OK** from the **Interference Analysis** dialog box; the **Analyzing Interference** dialog box is displayed, informing you that the interference is being analyzed.

4. After the analysis is complete, the **Autodesk Inventor Professional 2016** dialog box is displayed, informing you that no interference was found in the assembly.

Driving the Constraint to Simulate the Motion of the Assembly The Clamp Screw Handle and the two instances of the Handle Stop were assembled with the Clamp Screw using assembly constraints.

Therefore, when you simulate the Clamp Screw by driving its constraint, you will notice that the Clamp Screw Handle and both the instances of the Handle Stop will also move along with the Clamp Screw.

1. Click on the plus (+) sign located on the left of the **Jaw Face** node in the **Browser Bar**; the node is expanded and the **Origin** folder along with various constraints applied to it is displayed.

2. Move the cursor over the **Mate 7** constraint; the mating faces of the Jaw Face:1 and the Jaw Face:2 are highlighted on the graphics screen. This is done to ensure that the constraint you selected is the correct one. Next, right-click

on the **Mate 7** constraint, and then choose **Drive** from the shortcut menu; the **Drive** dialog box is displayed.

3. Enter **10** and **60** in the **Start** and **End** edit boxes as the start and end values of the simulation.
4. Choose the **More (>>)** button to expand the dialog box. Select the **Start/End/Start** radio button from the **Repetitions** area and then enter **2** in the edit box provided in the same area.

As you enter **2** in the edit box, two cycles of simulation of the assembly are created. The first cycle will be from the start position to the end position and the second cycle will be from the end position to the start position.

5. Choose the **Forward** button; you will notice that there is horizontal simulation of the Jaw face. Also, the other components assembled to it will move along with it. As there are two repetitions, first the components will move 30 mm away from the Movable Jaw and then move back to the start position.
6. Exit the **Drive** dialog box by choosing the **Cancel** button. Save the changes made to the assembly and then close the file.

Tutorial 3

In this tutorial, you will create the components of the Double Bearing assembly and then assemble them, as shown in Figure 10-31. Figure 10-32 shows the required positional representation of the assembly. Use the **Pattern** tool while assembling the Bolts. The dimensions of various components are given in Figures 10-33 through 10-35. After assembling the components, drive the **Insert** constraint of the first Bolt such that the remaining three instances are also simulated. Create a positional representation of the assembly with the Bolts at the new location. **(Expected time: 2 hrs)**




Figure 10-31 *The Double Bearing assembly*




Figure 10-32 *Required positional representation of the Double Bearing assembly*




Figure 10-33a *Top view of the Cap*




Figure 10-33b Top view of the Base




Figure 10-34a Front view of the Cap




Figure 10-34b Front view of the Base




Figure 10-35 Dimensions of the Bushing and Bolt

The following steps are required to complete this tutorial:

- Create a folder with the name *Double Bearing* inside the *c10* folder. Create all components of the Double Bearing assembly and save them in this folder.
- Open a new assembly file and assemble the components of the Double Bearing assembly. Only two instances of Bolt should be assembled and the rest should be assembled by patterning.
- Create a new positional representation of the assembly.
- Drive the **Insert** constraint applied between one of the Bolts and the Cap so that the Bolts are moved to a new location in the current positional representation.

Creating Components

- Create a folder with the name *Double Bearing* at the location *C:\Inventor_2016\c10* and then create all components in individual part files and save them in this folder.
- Open a new assembly file and save it with the name *Double Bearing.iam* at the location *C:\Inventor_2016\c10\Double Bearing*.

Assembling Components

The first component that has to be restored is the Base. Next, you need to restore the Cap. Then, you need to assemble the base and the cap using the assembly

constraints. Next, you need to assemble two instances of the Bushing and then two instances of the Bolt. The remaining instances of the Bolt will be assembled using the **Pattern** tool.

1. Place one instance each of the Base and the Cap in the assembly file by using the **Place** tool and make the base grounded. If required, you can choose the **Rotate** tool from the Marking Menu to retain the orientation of the Assembly, shown in Figure 10-36.
2. Assemble these components using the **Constrain** tool. The assembly after assembling the Base and the Cap is shown in Figure 10-36.




Figure 10-36 Assembly after assembling the Base and the Cap to it

3. Place two instances of the Bushing and then assemble them using the **Constrain** tool, refer to Figure 10-37.
4. Similarly, place two instances of the Bolt and then assemble them using the **Constrain** tool, as shown in Figure 10-37. You also need to make sure that you place the bolts in the parent holes in the cap part of the model. To check the parent or the primary holes of the cap, check the part file.




Figure 10-37 Assembly after two instances of Bolts are assembled with the Base and the Cap

It is presumed that one of the four holes at the corners of the Cap was created and the other three were patterned. Similarly, one of the holes in the middle of the Cap was created and the other was patterned. Since you have not created all the six holes using the single pattern, you need to use the **Pattern** tool twice. First time, the tool will assemble the Bolt on the three holes at the corners and the second time, it will assemble the Bolt in the remaining hole in the middle of the Cap.

5. Choose the **Pattern** tool from the **Pattern** panel of the **Assemble** tab; the **Pattern Component** dialog box is invoked. Also, you are prompted to select the component to be patterned.
6. Select the Bolt at the upper left corner of the Cap.
7. Choose the **Associated Feature Pattern** button from the **Feature Pattern Select** area; you are prompted to select the feature pattern to associate to.
8. Select one of the three holes at the corners of the Cap; the three instances of the Bolt are assembled at three holes.

Note The pattern of bolts created depends on the pattern of hole created on the cap and the location of the first hole on the cap. Therefore, you need to be careful while specifying the location of the first instance of the hole on the cap in the **Part** environment.

9. Choose **OK** to assemble the remaining three instances of the Bolt and exit this dialog box.
10. Invoke the **Pattern Component** dialog box again and select the Bolt assembled with the hole in the middle of the Cap.
11. Choose the **Associated Feature Pattern** button from the **Feature Pattern Select** area; you are prompted to select the feature pattern to associate to.
12. Select the other hole in the middle of the Cap and choose **OK**. The final Double Bearing assembly is shown in Figure 10-38.
13. Choose the **Save** tool from the **Quick Access Toolbar** to save the assembly.




Figure 10-38 Double Bearing assembly

Creating the Positional Representation of the Assembly As mentioned in the tutorial description, you need to create the positional representation of the assembly, with the Bolts moved to an offset position of 30 mm. To do so, you first need to create a positional representation and then drive the constraints of Bolts such that the Bolts are moved to a new location in the current positional representation. The positional representations are created using the **Browser Bar**.

1. Click on the plus (+) sign located on the left of the **Representations** node in the **Browser Bar** to expand the tree view.

2. Right-click on **Position** in the **Browser Bar** and choose **New** from the shortcut menu; the **Position** changes to **Position : Position 1** node and a plus (+) sign is added on its left.
3. Click on the plus (+) sign located on the left of **Position : Position1** in the **Browser Bar**; the tree view expands. You will notice that a check mark is displayed on the left of **Position1**, suggesting that this is the current representation.


Driving the Constraint of the Bolt When you drive the constraint of the first Bolt at the lower right corner of the cap, you will notice that the remaining three instances at the corners of the cap also simulate along with the first Bolt because the remaining three instances were assembled using the **Pattern** tool. This tool will force the three instances to behave in the same way as the original Bolt does.

1. Click on the plus (+) sign located on the left of **Component Pattern 1:1** in the **Browser Bar**. You will notice that four instances of the Bolts are displayed with the name **Element:1**, **Element:2**, **Element:3**, and **Element:4**.
2. Click on the plus (+) sign on the left of **Element:1**; the **Bolt:1** is displayed. Similarly, click on the plus (+) sign on the left of **Bolt:1** to display the **Insert** constraint.
3. Right-click on the **Insert** constraint, and then choose **Drive** from the shortcut menu; the **Drive** dialog box is displayed.
4. Enter **30** in the **End** edit box and then choose the **More** button to expand the dialog box.
5. Select the **Start/End/Start** radio button from the **Repetitions** area and then enter **2** in the edit box available in this area.
6. Choose the **Forward** button; all four bolts at the corners of cap will be simulated and moved to a distance of 30 mm in the upward direction. All the

four bolts are then moved back to their original positions without any pause between the cycles.

As you need to create a positional representation of the assembly with the bolts at an offset of 30 mm from the original location, you need to stop the movement of the Bolts at the top most position. To do this, you need to modify the value in the edit box in the **Repetitions** area of the **Drive Constraint** dialog box.

7. Enter **1** in the edit box of the **Repetitions** area and then choose the **Forward** button; the Bolts move up to a distance of 30 mm in the upward direction. Figure 10-39 shows the assembly with four bolts at the new position.



*Figure 10-39 Position of the Bolts after using the **Drive** option*

8. Choose the **OK** button to exit the **Drive** dialog box. Choose **Yes**, if the **Autodesk Inventor Professional** message box is displayed. This message box informs you that the value of the constraint must be overridden in the current positional representation to preserve it.
9. Choose the **Save** tool from the **Quick Access Toolbar**; the **Autodesk Inventor Professional 2016** dialog box is displayed and you are informed that you cannot save the assembly when the assembly is in the positional representation.
10. Choose **OK** from this dialog box to restore the master representation and

save the assembly file.

11. Close the assembly document.

Self-Evaluation Test Answer the following questions and then compare them to those given at the end of this chapter:

1. In Autodesk Inventor you can edit the feature by right-clicking on the component in the **Browser Bar** and choosing _____ from the shortcut menu.
2. If a component is assembled using an under-constrained component, a small green color cube will be displayed on the component after choosing _____ from the **View** tab.
3. The assembly constraints applied on a component can be edited by right-clicking on the constraint in the **Browser Bar** and choosing _____ from the shortcut menu.
4. The three types of assembly section views that can be created in an assembly file are _____, _____, and _____.
5. To analyze an assembly for interference, choose _____ from the **Interference** panel of the **Inspect** tab.
6. The motion of assembly components can be simulated using the _____ dialog box.
7. The components assembled using the **Pattern** tool can be replaced by the other components. (T/F)
8. You can edit components in an assembly file. (T/F)
9. For a grounded component, the symbol of degrees of freedom is not displayed. (T/F)
10. The pattern of a component will be automatically modified, if the pattern of the feature is modified. (T/F)

Review Questions Answer the following questions:

1. Which of the following tools can be used to replace only one instance of a component in an assembly?

(a) **Create** (b) **Replace All** (c) **Replace** (d) None of these

2. Which of the following buttons in the **Drive** dialog box is used to store the information related to the simulation of components in an *avi* file?

(a) **Record** (b) **Forward** (c) **Reverse** (d) None of these

3. Which of the following formats is used to save the design view files?

(a) **.avi* (b) **.idv* (c) **.ipt* (d) **.iam*

4. Which of the following tools is used to exit section views in an assembly file?

(a) **Full Section View** (b) **No Section View** (c) **Half Section View** (d) **End Section View**

5. Which of the following tabs will be available in the **Edit Component Pattern** dialog box if the pattern of a component is created using the **Circular** tab of the **Pattern Component** dialog box?

(a) **Associative** (b) **Rectangular** (c) **Circular** (d) None of these

6. You can replace all instances of a component in the assembly file. (T/F)

7. Any instance of a component assembled using the **Pattern** tool can be made independent. (T/F)

8. You can flip the section of a section view in an assembly. (T/F)

9. The information of interference between components can be printed. (T/F)

10. The simulation of the components of an assembly can be saved to an *.avi* file. (T/F)

Exercise Exercise 1

Open the Plummer Block assembly created in Tutorial 2 of Chapter 9 and then create a design view representation with the name Plummer Block, refer to Figure 10-40. After creating the design view, analyze the assembly for interference and then simulate the motion of the two Bolts. Note that the bolts should move in the downward direction.

(Expected time: 30 min)




Figure 10-40 Design view representation of the Plummer Block assembly

Answers to Self-Evaluation Test **1. Open, 2. Degrees of Freedom, 3. Edit, 4. quarter section view, half section view, three quarter section view, 5. Analyze Interference, 6. Drive 7. T, 8. T, 9. T, 10. F**

Chapter 11

Working with Drawing Views-I

Learning Objectives

After completing this chapter, you will be able to:

- Understand the use of drawing module.

- ***Understand various types of drawing views in Autodesk Inventor.***
- ***Generate, edit, delete, move, copy, and rotate drawing views.***
- ***Assign different hatch patterns to different components in assembly section views.***
- ***Exclude components in assembly section views.***

THE DRAWING MODULE

After creating a solid model or an assembly, you need to generate their drawing views. Drawing views are the two-dimensional (2D) representations of a solid model or an assembly. Autodesk Inventor provides you with a specialized environment for generating drawing views. This specialized environment is called the **Drawing** module and has only those tools that are related to drawing views. As mentioned earlier, all modules of Autodesk Inventor are bidirectionally associative. This property ensures that changes made in a part or an assembly are reflected in drawing views. Also, changes in the dimensions of a component or an assembly in the **Drawing** module are reflected in the part or assembly file. You can invoke the **Drawing** module for generating drawing views by selecting any *.idw* format file from the **Metric** tab of the **Create New File** dialog box, see Figure 11-1. Autodesk Inventor has various *.idw* files with predefined drafting standards such as the ISO standard, BIN standard and DIN standard. You can use the required standard file and proceed to the **Drawing** module for generating drawing views. The selected sheet follows its standard in generating and dimensioning the drawing views. However, you can change the standards that will be followed by modifying the standards in the sheet.




Figure 11-1 Various *.idw* format files for starting a new file using the **Create New File** dialog box

The default screen appearance of a sheet in the **Drawing** module is shown in Figure 11-2. Note that a default sheet with a title block is available when you start this module. This drawing sheet is similar to that on which the drawing views are drawn using the manual methods. This sheet is your working

environment and you can generate as many views as you want on it. You can also change the sheet style, title block style, or add more sheets for generating drawing views.




Figure 11-2 Screen display in the **Drawing** module

TYPES OF VIEWS

In Autodesk Inventor, you can generate various types of views from a model, assembly, or presentation. Additionally, you can also draft a view using the sketcher entities. The technique of generating drawing views from models, assemblies, and presentations is called generative drafting. This is because you generate the drawing views. The technique of drafting a drawing view using the sketcher entities is called interactive drafting. The types of drawing views that you can generate are discussed next.

Base View

The base view is the first view generated in the drawing sheet. This view is generated using the original model, assembly, or presentation. The base view is an independent view and is not affected by changes in any other view in the drawing sheet. Most of the other views in the sheet will be generated taking this view as the parent view.

Projected View

The projected view is generated taking any of the existing views as the parent view. This view is generated by projecting the lines normal to the parent view or at an angle to the parent view to generate a 3D view. If the lines are projected normal to the parent view, the resulting view will be an orthographic view such as top view, front view, side view, and so on. If the lines are projected at an angle, the resulting view will be a 3D view such as an isometric view. In this view, you can visualize the X, Y, and Z axes of the model. These views are 2D representations of a three-dimensional (3D) model.

Auxiliary View

An auxiliary view is a drawing view that is generated by projecting the lines normal to a specified edge of an existing view.

Section View

A section view is generated by chopping a part of an existing view using a plane and then viewing the parent view from a direction normal to the section plane.

Detail View

A detail view is used to display the details of a portion of an existing view. You can select the portion whose detail view has to be shown in the parent view. The portion that you have selected will be magnified and placed as a separate view. You can control the magnification of the detail view.

Overlay View

An overlay view is used to display an alternate position of the components in an assembly. It uses positional representations created in the assembly environment for generating the drawing view.

Break

A broken view is used to display a component by removing a portion of it from the middle and keeping the ends of the drawing view intact. This type of view is used for displaying the components whose length to width ratio is very high. This means that either the length is more as compared to the width or the width is more as compared to the length. The broken view will break the view along the horizontal or vertical direction such that the drawing view fits the area you require. Note that in these views, the dimension of the edge that is broken will still be displayed as the actual value. However, this dimension will have a broken symbol suggesting that the dimension value is for the edge that is broken in the view.

Break Out View

A break out view is used to remove a part of the existing view and display the area of the model or the assembly behind the removed portion. This type of view is generated using a closed sketch that is associated with the parent view.

Slice

A slice view is used to indicate important portions of a part or an assembly file as a zero depth section. It is generated on a target view by creating a sketch for the material to be removed on the source view.

Crop

A crop view is used to crop an existing view enclosed in a closed sketch associated to that view. The portion of the view that lies inside the associated sketch will be retained and the remaining portion will be removed. You can also crop a view by creating the rectangular trap by using the **Crop** tool. In this method the portion lies inside the rectangular trap will be retained.

Note

*To create sketches that are associated with the drawing view, select the drawing view from the drawing sheet and then choose the **Start Sketch** tool from the **Sketch** panel of the **Place Views** tab. On doing so, the sketching environment will be invoked. Also, the sketch to be drawn in this environment will be associated with the drawing view.*

GENERATING DRAWING VIEWS

The methods of generating all nine types of views are discussed next.

Generating the Base View

Ribbon: Place Views > Create > Base As mentioned earlier, the first view that will be generated in the drawing sheet is the base view. This view is generated using the Base tool. To create a base view, choose the Base tool from the Create panel. Alternatively, right-click on the sheet or in the Browser Bar and then choose Base View from the shortcut menu. On invoking this tool, the Drawing View dialog box will be displayed. You can browse the model file whose base view is to be generated and choose OK to place the base view automatically. Alternatively, right click on the drawing sheet; a marking menu will be displayed. Choose OK from the marking menu to place the base view. The options in this dialog box are discussed next.

Note

*By default, the **Base View** command selects the model opened in the current session of Inventor as a source for generating the views. If there is no active model, no file gets selected for generating views.*

Component Tab

The options in the **Component** tab are used to select the component or the assembly whose drawing view you want to generate as well as change the scale orientation and display style of the drawing view, refer to Figure 11-3. These options are discussed next.




Figure 11-3 The Component tab of the Drawing View dialog box

File

The **File** drop-down list displays the files that are selected for creating the drawing views. By default, this drop-down list is grayed out. This is because no file is selected. To select a file for generating the drawing views, choose the **Open an existing file** button located on the right of the **File** drop-down list; the **Open** dialog box will be displayed. Using this dialog box, you can select a part, sheet metal, assembly, or presentation file to generate the drawing views. After you have selected the file, you will notice that its name and location is displayed in the **File** drop-down list.

Representation Area

This area is used to specify the representation of an assembly or part. The options displayed in this area depends upon the selection of part or an assembly.

View: If the selected file has some design view representations associated to it, they will be displayed in the **View** drop-down list. You can select a view representation from the drop-down list.

Associative: This check box is selected to make the design view associative to the view to be generated. As a result, if the design view representation is changed in the assembly environment, the drawing view also changes automatically.

Position: This drop-down list is used to select the positional representation of an assembly using which the drawing views will be generated. If different positional representations are not created in an assembly then this drop-down remains deactivated.

Level of Detail: This drop-down list is used to select the level of detail that is required for a drawing view.

Note

*To access all the options in the **Representation** area, you need to open different files like assembly, sheet metal, and part.*

Presentation Area

This area will be displayed if the selected file is a presentation file. The presentation views created in the presentation file will be displayed in the list box. You can make the drawing view associated to the presentation view by selecting the **Associative** check box.

Style The buttons in the **Style** area are used to specify the display type for drawing views. You can generate a view with hidden lines, without hidden lines, or with shaded display by choosing their respective buttons from this area. Figure 11-4 shows the drawing view with hidden lines and Figure 11-5 shows the drawing view without hidden lines.




Figure 11-4 Drawing view with hidden lines




Figure 11-5 Drawing view without hidden lines

Style from Base

By default, this check box will be deactivated. It is used to set the display style of a dependent view same as that of its parent view. To change the display style of a dependent view, right click on it in the graphics window and choose the **Edit View** tool from the marking menu; the **Drawing View** dialog box will be displayed. Now, clear this check box from the **Style** area.

Raster view only

If this check box is selected, you can create annotations to review a drawing. After the annotations are created, the raster view will be marked by green corner glyphs in the graphics window.

Label

This text box allows you to specify a label for the view. You can enter the name of the label in this text box for the identification of the view. You can edit the view label text in the **Format Text** dialog box with the help of the **Edit view label** button. Note that the label will appear on the drawing sheet only if the **Toggle Label Visibility** button is chosen.

Scale

The **Scale** edit box is used to specify the scale relative to the part, assembly, or parent view. You can enter the scale value in this edit box or select the predefined standard scale by choosing the down arrow on the right in this edit box.

Model State Tab

The options in the **Model State** tab of the **Drawing View** dialog box are discussed next, refer to Figure 11-6.

Member Area


The drop-down list in this area is available only for the assemblies with positional representations and is used to select the member that should be selected from an iAssembly file to be displayed in the drawing views.

Reference Data Area

The options in the **Reference Data** area are used to set the line style for the reference data. You can select the desired line style from the **Line Style** drop-down list. The **Hidden Line Calculation** area is used to set the options for the calculation of hidden lines by using **Reference Data Separately** or **All Bodies** radio button. You can set the option to calculate hidden lines separately for reference data. The **Margin** edit box is used to specify the value by which the view boundaries will be extended on all sides to display additional reference data in the drawing view.

Weldment Area

The **Weldment** area will be activated only when you select the weldment file to generate the drawing views. You can specify the weldment state, details, symbols, and annotations to be displayed in the drawing view by selecting the required options from the **Weldment** area.



*Figure 11-6 The **Model State** tab of the **Drawing View** dialog box*

Display Options Tab

The options in the **Display Options** tab of the **Drawing View** dialog box are used to specify the parameters that you want to display in the drawing views, refer to Figure 11-7. For example, if you select the **All Model Dimensions** check box, the parametric dimensions that were used to create the model in the **Part** module will be displayed in the drawing view. Similarly, you can also specify whether or not the thread features or tangent edges should be displayed in the drawing view.




Figure 11-7 The Display Options tab of the Drawing View dialog box

Standard Parts Area

The options in this area are used to control the display of hidden lines and the sectioning of standard parts inserted in an assembly from the Content Library. These options are discussed next.

Hidden Lines This drop-down list has options such as **Obey Browser** and **Never**. By default, the **Obey Browser** option is selected. As a result, the settings that you configure in the Browser Bar will be used. On selecting **Never**, the standard parts will never display hidden lines.

Section The **Section** drop-down list is used to select an option to specify whether or not the standard parts inserted from the Content Library will be sectioned in the assembly section view. By default, the **Obey Browser Settings** option is selected. As a result, the settings that you configure in the **Browser Bar** will be used. On selecting **Always**, the standard parts in the assembly section view will be sectioned and on selecting **Never**, the standard parts will never be sectioned.

The **View Justification** drop-down list is used to specify the justification for the drawing view. By default, **Centered** option is selected. Therefore the justification is centered. You can also select the **Fixed** option from this drop-down list to make the justification fixed.

Tip. By default, the model dimensions are displayed in the drawing view using the default dimensioning standards and dimension style. If the default dimension standard uses dimensions in inches, the dimensions in the drawing views will be displayed in inches even if the dimensions were specified in millimeters in the model. However, you can modify the dimension standards as well as the dimension style. This will be discussed in later chapters.

Note

*In the **Display Options** tab, only the options that are applicable to the selected view will be enabled. Some of these options also depend on whether you select a part file or an assembly file to generate the drawing view. For example, the option to display model dimensions will not be available while generating the drawing views of an assembly.*

The **Cut Inheritance** area is used to display the sectional views of a component. Each of the check boxes in this area, namely **Break Out**, **Break**, **Slice**, and **Section**, if selected, display the corresponding sectional view that has been generated from the base view of the component. The options in the **Cut Inheritance** area will be available only while editing the drawing views and not while creating them.

Generating Projected Views

Ribbon: Place Views > Create > Projected As mentioned earlier, the projected views are generated by projecting lines from an existing view. You can generate the projected views by using the Base tool as well as the Projected tool. In case of the Base tool, place the base view; the preview of the projected view will be attached to the cursor and you need to specify the location of the projected view. After specifying the location of the projected view, right-click in the graphics window; a marking menu will be displayed. Choose OK from the marking menu to create the projected view. Another method of creating the projected views is by invoking the Projected tool and then selecting the base view that you want to use to generate the projected view. Note that you need to have a base view before creating a projected view. After selecting the base view, you will be prompted to specify a location for the projected view. Left-click on the drawing sheet to specify the location. If you move the cursor in the horizontal or vertical direction, an orthographic view will be generated. If you move the cursor at an angle from the parent view, a 3D view will be generated. You can preview the resulting view on the drawing sheet. Once you have specified the location for the projected view, a rectangle will be displayed at that location and you will be prompted again to specify the location of the projected view. To generate the view, right-click on the drawing sheet and then choose Create from the shortcut menu.

*Tip. By using the **Base** tool you can create the projected view at the default location. To do so, place the base view and then click on the triangular icon of the base view border; the projected view is placed at default location. Next, right click in graphics window and select the **OK** button from the marking menu.*

Note

The display type of the projected views will be the same as that of the parent view. However, you can later modify the display type of the projected view.

Figure 11-8 shows the drawing sheet with the base view and the projected views. The base view is the top view placed on the top of the drawing sheet. The front and isometric views are generated as projected views using the top view as the parent view.




Figure 11-8 Drawing sheet with the base view and the projected views

Tip. While generating the projected view, if you move the cursor in the horizontal or vertical direction from the parent view, a centerline will be displayed from the center of the parent view to the center of the projected view. This centerline indicates that the view being projected is normal to the parent view. Therefore, the resulting view will be an orthographic view.

Generating Auxiliary Views

Ribbon: Place Views > Create > Auxiliary As mentioned earlier, auxiliary views are generated by projecting the lines normal to a specified edge in the parent view. To generate an auxiliary view, invoke the Auxiliary tool and then select the parent view. On selecting the parent view, the Auxiliary View dialog box will be displayed, as shown in Figure 11-9, and an inclined line will get attached to the cursor. Most of the options in the View / Scale Label and Style areas are similar to those discussed earlier in the Drawing View dialog box. The other option in this dialog box is discussed next.




Figure 11-9 The Auxiliary View dialog box

Definition in Base View

Select this check box to create a definition line parallel to the edge selected for generating the auxiliary view.

After specifying the required parameters, select an edge in the parent view that will be used for generating the auxiliary view; the preview of the auxiliary view will be generated and displayed on the sheet in the shaded mode. You will notice that the view being generated is parallel to the selected edge. Also, a center line will be displayed, which is normal to the edge as well as to the auxiliary view, see Figure 11-10. The centerline and the **Auxiliary View** dialog box will automatically disappear once you place the view.




Figure 11-10 *Generating the auxiliary view*

Generating Section Views

Ribbon: Place Views > Create > Section **As mentioned earlier, section views are generated by chopping a portion of an existing view using a cutting plane (defined by sketched lines) and then viewing the parent view from the direction normal to the cutting plane. To create a section view, invoke the Section tool and then select the parent/base view from the drawing sheet. The cursor, which was originally an arrow, will be replaced by a plus (+) cursor. The plus (+) cursor is used to specify a cutting plane. In Autodesk Inventor, a cutting plane is defined by sketching one or more than one line. You can use the temporary tracking option for drawing the lines that will define the section plane. Click in the drawing area to specify the start point of the section line and then click to specify the end point. After you have drawn the lines, right-click on the drawing sheet and then choose Continue from the shortcut menu; the Section View dialog box will be displayed, as shown in Figure 11-11, and you will be prompted to specify the location for the section view. You will notice that the line that you have drawn is converted into a section plane and the preview of the section view is displayed on the drawing sheet. The preview will move as you move the cursor on the drawing sheet. However, it always remains parallel to the section plane. Click on the drawing window to specify the location of the view, refer to Figure 11-12.**

While creating the section view, you can use the options in the **Section Depth** area to specify the offset distance of another section plane behind the original section plane. By default, the **Full** option is selected. To define the depth of sectioning, select the **Distance** option and then set the distance value in the **Distance** edit box in the **Section Depth** area. Another section plane will be defined parallel to the original section plane at the distance that you define. This will lead to chopping of the model. To observe the use of this option, generate the isometric view of the section view.




Figure 11-11 The *Section View* dialog box




Figure 11-12 Base view and section view

The **Slice** area allows you to display the sliced section view that was created for the base view. Select the **Include Slice** check box to display the sliced section view along with the section view. The **Slice All parts** check box will be available only if the selected base view is an assembly. If you select this check box, the sliced section view of all parts of the assembly passing through the specified section plane will be displayed. You will learn about slicing the views later in this chapter.

The **Method** area is used to specify the method of projection while sectioning a component with multiple line segments. By default, the **Projected** radio button is selected in this area. As a result, the section view defined by the section line normal to the plane is generated. Select the **Aligned** radio button to create an aligned section view. In an aligned section view, the sectioned portion revolves around an axis normal to the viewing plane such that it is straightened, refer to

Figure 11-13. This figure shows the aligned section view of a model. Notice that the inclined feature that is sectioned in this view is straightened. Therefore, the section view is longer than the parent view.




Figure 11-13 The base view and the aligned section view

Generating Detail Views Ribbon: Place Views > Create > Detail Detail views are used to display the details of a portion of an existing view by magnifying that portion and displaying it as a separate view. To create a detail view, invoke the **Detail View** tool from the **Ribbon** and then select a view; the selected view will become the parentview for the detailed view. On selecting the parent view, the **Detail View** dialog box will be displayed, as shown in Figure 11-14. The options in this dialog box are similar to those discussed in the **Auxiliary View** dialog box.




Figure 11-14 The Detail View dialog box

When you invoke the **Detail View** dialog box and select the parent view, a circle with a cross mark at its center will get attached to the cursor and you will be prompted to specify the center point of the fence. The fence is the boundary that encloses the portion of the parent view to be magnified and displayed as the detail view. You can select the option to draw a rectangular or a circular boundary by choosing the respective button from the **Fence Shape** area. The **Cutout Shape** area allows you to define the boundary of the detail view and has two buttons, **Jagged** and **Smooth**. The **Jagged** button is chosen by default and displays the boundary of the detailed view as an irregular toothed pattern. The **Smooth** button, if chosen, displays the boundary of the detail view as a smooth continuous curve. The **Display Full Detail Boundary** check box will be activated only when the **Smooth** button is chosen from the **Cutout Shape** area and displays a circular or rectangular boundary around the detail view. The **Display Connection Line** check box will be activated only when you select the **Display Full Detail Boundary** check box. This check box generates a centerline between the fence specified on the parent view and the full boundary of the detail view.

After specifying the options in the **Detail View** dialog box, select a point on the parent view that will act as the center point of the fence. This point should lie on the area that you want to magnify. The specified point will be taken as the center of the circular or rectangular boundary. After specifying a point, you will be prompted to specify the endpoint of the fence. Click to specify the endpoint; the portion that is enclosed within the boundary will be magnified by the value defined in the **Scale** drop-down list and the view will be attached to the cursor. Also, you will be prompted to specify the location for the view. Specify the placement point for the drawing view; the detail view will be placed at the point that you specify. Figure 11-15 shows the parent view and the detail view of a component with a circular fence after choosing the **Jagged** button. Figure 11-16 shows the parent view and the detail view of a component with the circular fence after choosing the **Smooth** button.




Figure 11-15 The parent and detail views displayed with a circular fence after choosing the **Jagged** button




Figure 11-16 The parent and detail views displayed with a circular fence after choosing the **Smooth** button

Figure 11-17 shows the parent view and the detail view of a component with the **Smooth** button chosen and the **Display Full Detail Boundary** check box selected. Figure 11-18 shows the parent view and the detail view of a component with the **Smooth** button chosen and the **Display Full Detail Boundary** and **Display Connection Line** check boxes selected.




Figure 11-17 The parent and detail views displayed on selecting the **Display Full Detail Boundary** check box




Figure 11-18 The parent and detail views displayed on selecting the **Display Connection Line** and **Display Full Detail Boundary** check boxes

Generating Broken Views

Ribbon: Place Views > Modify > Break The broken view is the one in which a user-defined portion of the drawing view is removed, keeping the ends of the drawing view intact. The broken view is generally used to display the drawing view of the models that have a high length to width ratio. Note that this tool will not create a separate view.




Figure 11-19 The Break dialog box

It will break an existing view such that a specified portion of the view is removed and the remaining portion is displayed along with the ends of the views. The views will be broken with the help of two planes defined by lines. You do not have to draw the lines for defining the cutting planes. You just have to specify the location of the first and the second cutting plane. The portion of the view that lies inside the two cutting planes will be removed and the remaining view will be displayed. To break a view, invoke the **Break** tool from the **Ribbon** and then select the view to be broken; the **Break** dialog box will be displayed, as shown in Figure 11-19, and you will be prompted to select the start point of the material to be removed. The options in this dialog box and the methods to define break lines are discussed next.

Style Area

The buttons in the **Style** area are used to specify the style for displaying the break symbol. The style options provided in this area are discussed next.

Rectangular Style

The **Rectangular Style** button is used to break the views of a non-cylindrical component.

Structural Style

The **Structural Style** button is used to break the views of a cylindrical component.

Orientation Area

The buttons in the **Orientation** area are used to specify the break in the horizontal or the vertical direction. Depending on whether the view is vertical or horizontal, you can choose the required button from this area.

Display Area

The options in the **Display** area are used to control the display of break lines in the broken view. The preview window in this area will display the break lines that will be displayed on the broken view. As you modify the options in the **Break** dialog box, the preview in the preview window will also change. The scale of break lines can be modified using the slider bar in this area. The preview of the change in scale will be displayed in the preview window and in the drawing sheet when you move the cursor on the drawing sheet.

Gap

The **Gap** edit box is used to specify the value of the break gap in the broken view.

Symbols

The **Symbols** spinner is used to specify the number of break symbols in the break line when the **Structural Style** button is chosen from the **Style** area. The maximum number of symbols that are allowed is three. This spinner will not be activated if you choose the **Rectangular Style** button from the **Style** area.

The **Propagate to parent view** check box will be activated only when the broken view is created for a projected view. This check box, if selected, removes material from the projected view and will also display the parent view as a broken view with the same amount of material removed.

You will notice that when you select the view to be broken, two lines with a break symbol will be attached to the cursor and you will be prompted to specify the start point for the material to be removed. This will be the point where the first cutting plane will be placed. After you specify the first point, you will notice that the two break lines are placed at that point. These break lines will be based on the style that you have selected from the **Style** area. You will now be prompted to specify the endpoint for the material to be removed. This point will define the position of the second cutting plane. After you specify the location of the second cutting plane, notice that the view will shrink because the material between the two cutting planes is removed. Also, the break lines of the selected style will be displayed on the view. Figure 11-20 shows a broken view created using the rectangular style and Figure 11-21 shows a broken view created using the structural style with three symbols.




Figure 11-20 Broken view created using the rectangular style




Figure 11-21 Broken view created using the structural style with three symbols

Note

If you break a view that is used as a parent view for generating other views, the dependent views will also be converted into broken views. Note that the isometric view generated by projecting the lines from an existing view is not dependent on the parent view; therefore, it will not be converted into a broken view.

Generating Break Out Views

Ribbon: Place Views > Modify > Break Out As mentioned earlier, break out views are generated to remove a portion of the drawing view and display the area that lies behind the removed portion. These views are generated using the closed sketches that are associated with the view. Therefore, first you need to create a closed sketch associated with the view by selecting the view and choosing the Start Sketch tool from the Sketch panel in the Place Views tab. Next, choose the Break Out tool; you will be prompted to select a view. Select the view that has the closed associated sketch with it; the Break Out dialog box will be displayed, see Figure 11-22 and the associated sketch will be highlighted in blue. If you select a view that has no sketch associated with it, a message box will be displayed, informing that the selected view has no sketch associated with it.




Figure 11-22 The Break Out dialog box

The options in the **Break Out** dialog box are discussed next.

Boundary Area

This area has the **Profile** button that is chosen to select the closed sketch associated with the view to create the break out view. When you invoke this dialog box, the closed sketch gets automatically selected.

Depth Area

The options in the **Depth** area are used to select the method for specifying the depth of the break out view. You can select the method for specifying the depth from the drop-down list in this area. The options in this drop-down list are discussed next.

From Point

The **From Point** option is used to select a point from which you define the depth of a break out view. The depth is defined in the edit box available below this option. Figure 11-23 shows the point from which the depth is defined. Figure 11-24 shows the resulting break out view. The depth from the point in this view is 20 mm.




Figure 11-23 The point to define the break out view




Figure 11-24 The resulting break out view

To Sketch

This option is selected to use a sketch for defining the depth of a break out view. Note that to get a better view, it is recommended that you associate the sketch with a different view. Figure 11-25 shows the drawing views with the sketch used to specify the depth and the resulting break out view. Note that in this figure, the sketch used to define the depth is the one on the front view, and the sketch to define the break out is the same as that in Figure 11-23.




Figure 11-25 Sketch to define the depth and the resulting break out view

*Tip. You can open the part file for editing a component whose drawing views you are generating. To open the part file, right-click on the drawing view and then choose the **Open** option from the shortcut menu.*

To Hole

This option is selected to use the hole on the selected view to define the depth of the break out view. Figure 11-26 shows a break out view created using the central hole of Brasses as the hole to define the depth of the break out view.




Figure 11-26 Break out view generated up to the central hole of Brasses

Through Part

This option is selected to use the depth of a selected part to define the depth of the break out view. When you select this option, you will be prompted to select a part to define the depth.

The **Display** area also has the **Show Hidden Edges** button that is chosen to show the hidden edges in the selected view. The hidden edges help you to define the depth of the break out view. Note that the display type of the view will change to the original one after the view is created.

Generating Overlay Views

Ribbon: Place Views > Create > Overlay **As mentioned earlier, overlay views are used to show the alternative position of the components in an assembly. This view can be generated only if you have created positional representations for the assembly in the assembly environment. The alternate position of the components is shown by dashed lines in an existing view.**

To create an overlay view, choose the **Overlay** tool from the **Create** panel of the **Place Views** tab; you will be prompted to select a view. Select the drawing view of the assembly for which the positional representations were created; the **Overlay View** dialog box will be displayed, as shown in Figure 11-27. Most of the options in this dialog box are similar to those discussed while generating earlier drawing views. The remaining options are discussed next.




Figure 11-27 The Overlay View dialog box

Positional Representation Area The drop-down list in this area lists all the available positional representations for the selected assembly. You can select the desired positional representation to generate the overlay view from this drop-down list.

View Representation Area

The drop-down list in this area lists all the available design views for the selected assembly. The overlay view will use the design view you select from this drop-down list.

After specifying the parameters in the **Overlay View** dialog box, choose **OK**; the overlay view will be generated in the selected view and the alternate position of the components will be displayed using the dashed lines. Figure 11-28 shows the overlay view generated on an isometric view. In this figure, the alternative position of the components is shown using dashed lines.




Figure 11-28 The overlay view generated on an isometric view

Generating Slice Views

Ribbon: Place Views > Modify > Slice **The Slice tool is used to create zero-depth sectional views. The sliced sectional views can be used in complex assemblies or part files to highlight a specific component or a feature. The sketch for the slice views is created on the parent views, and the resulting sliced view is created on the target view. The procedure to create slice views is discussed next.**

Generate a base view and an associated projection. Next, select the base view and choose the **Start Sketch** tool from the **Sketch** panel of the **Place Views** tab; the sketching environment will be activated. Create the sketch that consists of one or more open profiles on the base view and exit the sketching environment. Choose the **Slice** tool from the **Modify** panel of the **Place Views** tab; you will be prompted to select a view. Select the projected view; the **Slice** dialog box will be displayed, as shown in Figure 11-29, and you will be prompted to select a sketch.




Figure 11-29 The Slice dialog box

The **Select Sketch** button is chosen by default in the **Slice Line Geometry** area. Select the sketch that is created on the parent view and choose the **OK** button from the **Slice** dialog box; the resultant sliced view will be created on the target view. The **Slice All Parts** check box will be available only when the slice view is created for an assembly and if selected, it will slice all the parts that intersect the slice profile. Figure 11-30 shows the parent view with the sketch of the slice view and the resultant slice view of the Plummer Block assembly.




Figure 11-30 *The parent view and the sliced view of the Plummer Block assembly*

DRAFTING DRAWING VIEWS

Ribbon: Place Views > Create > Draft In addition to generating various views from the model, Autodesk Inventor also allows you to draft a drawing view using the sketching tools. After sketching, these views will behave similar to the generated views. The drawing views can be sketched using the Draft tool. On invoking this tool, the Draft View dialog box will be displayed, as shown in Figure 11-31. The options in the View / Scale Label area are similar to those discussed earlier in the Drawing View dialog box while generating drawing views. After you have set the parameters in this dialog box and chosen the OK button, the sketching environment will be activated and you can create a draft view.




Figure 11-31 The Draft View dialog box

EDITING DRAWING VIEWS

Autodesk Inventor allows you to edit a drawing view according to your requirement. If you move the cursor over a drawing view in the sheet, you will notice that a red box with dotted lines is displayed around the view. This box is the bounding box of the view. To edit a view, double-click when the bounding box is displayed. Alternatively, right-click on the view when the bounding box is displayed; the Marking menu is displayed. Next, choose **Edit View** from the Marking Menu; the **Drawing View** dialog box is displayed. You can also invoke this dialog box by double-clicking on the required view in the **Browser Bar**. Figure 11-32 shows the **Drawing View** dialog box invoked for editing a drawing view.




Figure 11-32 The Drawing View dialog box

While editing the dependent/projected view, you can change its display style by clearing the **Style from Base** check box in the **Style** area. If you clear this check box, the remaining buttons in this area will be activated. You can choose any of these buttons to change the display style of the dependent view based on your requirements.

Note


*The options in the **Component**, **Model State**, and **Display Options** tabs of this dialog box will be available based on the type of view selected for editing.*

DELETING DRAWING VIEWS AND DRAWING SHEET


The unwanted drawing views can be deleted from the sheet using the **Browser Bar** or directly from the sheet. To delete a drawing view, move the cursor over the drawing view in the **Browser Bar** or on the drawing sheet; a dotted rectangle which is actually the bounding box of the drawing view will be displayed. Select the drawing view when the bounding box is displayed and then press the DELETE key; the **Autodesk Inventor Professional 2016** message box will be displayed. Choose **OK** from this message box; the selected view will be deleted. You can also delete a view by right-clicking on it and then choosing **Delete** from the shortcut menu.

If the selected drawing view has some dependent drawing views, the **Delete View** dialog box will be displayed. This dialog box will confirm whether you want to delete the selected view and its dependent views. Choose **OK** to delete the views. To display the views that are dependent on the selected view, choose the **More** button at the lower right corner of this dialog box. The dialog box will expand and provide a list of dependent views, see Figure 11-33.

By default, this dialog box will show **Yes** for all dependent views in the **Delete** column of the expanded area. This suggests that all dependent views will be deleted if you delete the parent view. If you do not want to delete a dependent view, click on **Yes** once; **Yes** will be replaced with **No**. This suggests that the selected dependent view will not be deleted if you delete the parent view.



*Figure 11-33 The expanded **Delete View** dialog box*



*Figure 11-34 The expanded **Delete Sheet** dialog box*

In Autodesk Inventor, you can delete multiple drawing sheets in a single step. To do so, select the drawing sheets to be deleted from the Browser Bar. Next, right-click and then choose the Delete Sheet option from the shortcut menu displayed; the Delete Sheet dialog box will be displayed in the Graphics window. Next, expand the dialog box, refer to Figure 11-34. In this dialog box, choose the Yes from the Delete column of the corresponding row of the sheet to be deleted. Next, choose the OK button; the respective sheet will be deleted.

*Tip. If you select a view to delete, you will notice that red rectangles are drawn around all the dependent views. If you change **Yes** to **No** for a view in the **Delete***

View dialog box, refer to Figure 11-34, the red box will not be displayed. This indicates that the drawing view will not be deleted.

MOVING DRAWING VIEWS

You can relocate the existing drawing view by moving it from its current location to a new location. However, remember that if the selected view has some dependent views, they will also move along with the parent view. To move the view, move the cursor over the view; the bounding box of the view is displayed. Move the cursor over one of the edges of the bounding box. Now, press and hold the left mouse button and drag the view to a new location in the sheet. Note that only section views, auxiliary views, and the projected orthographic views can be moved only along the axis, in which they were projected. The isometric views and detail views can be moved to any location in the drawing sheet.

*Tip. If you do not want to move the dependent views along with the parent view, then clear the **Align to Base** check box in the **Display Options** tab of the **Drawing View** dialog box displayed on double-clicking on the dependent views.*

COPYING DRAWING VIEWS YOU CAN COPY AN EXISTING VIEW TO A NEW LOCATION IN A NEW SHEET. YOU CAN ALSO COPY THE EXISTING VIEW IN A NEW DRAWING FILE. TO COPY THE VIEW, MOVE THE CURSOR OVER THE VIEW AND RIGHT-CLICK WHEN THE BOUNDING BOX OF THE VIEW IS DISPLAYED. CHOOSE **COPY FROM THE SHORTCUT MENU THAT IS DISPLAYED ON RIGHT-CLICKING. YOU CAN ALSO RIGHT-CLICK IN THE DRAWING VIEW IN THE **BROWSER BAR** AND THEN CHOOSE **COPY** FROM THE SHORTCUT MENU DISPLAYED. AFTER COPYING, PASTE THIS DRAWING VIEW AT A NEW LOCATION IN A NEW SHEET OR IN A NEW**

DRAWING FILE. NOTE THAT IF THE SELECTED DRAWING VIEW HAS SOME DEPENDENT VIEWS, THEY WILL NOT BE COPIED ALONG WITH THE PARENT VIEW. IN AUTODESK INVENTOR, YOU CAN COPY MORE THAN ONE VIEW FROM THE DRAWING AREA. TO DO SO, PRESS THE CTRL KEY AND SELECT THE VIEWS. NEXT, RIGHT-CLICK IN THE DRAWING AREA. CHOOSE THE **COPY** OPTION FROM THE SHORTCUT MENU DISPLAYED AND THEN PASTE THE COPIED VIEWS AT THE REQUIRED LOCATION.

Note

The process of adding more sheets will be discussed in the next chapter.

ROTATING DRAWING VIEWS AUTODESK INVENTOR ALLOWS YOU TO ROTATE THE SELECTED DRAWING VIEW ABOUT ITS CENTER POINT. IF YOU ROTATE A BASE VIEW THAT HAS A DEPENDENT DETAIL VIEW, THE DETAIL VIEW WILL ALSO ROTATE TO MAINTAIN ITS RELATIONSHIP WITH THE BASE VIEW. IN ANY CASE, IF YOU ROTATE THE DEPENDENT VIEW, THE PARENT VIEW WILL NOT BE AFFECTED. YOU CAN ROTATE AN EXISTING DRAWING VIEW BY RIGHT-CLICKING ON IT IN THE **BROWSER BAR** OR ON THE SHEET AND THEN BY CHOOSING **ROTATE** FROM THE SHORTCUT MENU. ON CHOOSING THIS OPTION, THE **ROTATE VIEW** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 11-35. THE OPTIONS IN THIS DIALOG BOX ARE DISCUSSED NEXT.




Figure 11-35 The Rotate View dialog box

Note

Generally, you should not try to rotate a drawing view that has dependent sectional and auxiliary views or an associated section.

By Area

The drop-down list in the **By** area is used to select the method of rotating the selected drawing view. There are three methods for rotating the drawing views. These methods are discussed next.

Edge

The **Edge** method is used to force the orientation of the selected view such that the selected edge becomes horizontal or vertical. Select the **Edge** option from the drop-down list in the **By** area; the **Horizontal** and **Vertical** radio buttons will be displayed in this area. The orientation will depend on whether you select the **Horizontal** or the **Vertical** radio button. To rotate the view using the **Edge** method, select the **Horizontal** or the **Vertical** radio button and then select the edge in the selected view.

Absolute angle

The **Absolute angle** method is used to rotate the drawing view with respect to the world coordinate system by specifying the rotation angle of the view. The angle can be specified in the **Angle** edit box that is displayed in the **By** area when you select the **Absolute angle** option from the drop-down list.

Relative angle

The **Relative angle** method is used to rotate the drawing view with respect to the current position of the drawing view by specifying the rotation angle of the view. The angle can be specified in the **Angle** edit box that is displayed in the **By** area when you select the **Relative angle** option from the drop-down list.

Counter clockwise

The **Counter clockwise** button is the first button in the area that is on the right of the **By** area. This button is chosen to rotate the selected view in the counterclockwise direction.

Clockwise

The **Clockwise** button is available below the **Counter clockwise** button and is chosen to rotate the selected view in the clockwise direction.

CHANGING THE ORIENTATION OF DRAWING VIEWS IN AUTODESK INVENTOR, YOU CAN CHANGE THE ORIENTATION OF THE DRAWING VIEW THAT IS ALREADY CREATED. FOR EXAMPLE, IF YOU HAVE CREATED FRONT OR LEFT VIEW AS THE BASE VIEW, YOU CAN CHANGE ITS ORIENTATION AS PER YOUR NEED. TO DO SO, DOUBLE-CLICK ON THE BASE VIEW; THE **DRAWING VIEW** DIALOG BOX AND VIEWCUBE WILL BE DISPLAYED IN THE GRAPHICS WINDOW. NEXT, CHANGE THE ORIENTATION OF THE VIEW USING VIEWCUBE AND CHOOSE **OK** BUTTON FROM THE **DRAWING VIEW** DIALOG BOX, SEE FIGURES 11-36 THROUGH 11-38.




Figure 11-36 The default view of the model




Figure 11-37 The top view of the model




Figure 11-38 The view after changing the orientation

You can also create a drawing view with a user-defined orientation by choosing the **Custom View Orientation** option from the flyout that is displayed on right-clicking on the ViewCube. On choosing this option, the **Custom View** tab of Autodesk Inventor will be activated and the default view of the model will be displayed in the Custom View environment, as shown in Figure 11-39.




Figure 11-39 The Custom View tab for creating a user-defined view

The **Custom View** tab has only those drawing display tools that can be used to modify the view orientation. Once you have achieved the required view orientation by using ViewCube, right-click and then choose the **Finish Custom View** option from the marking menu; the **Custom View** tab will be closed and you will return to the **Drawing** module of the Autodesk Inventor. Next, right click in the graphics window and choose **OK** from the marking menu to get the desired oriented view.

ASSIGNING DIFFERENT HATCH PATTERNS TO COMPONENTS IN ASSEMBLY SECTION VIEWS WHENEVER YOU GENERATE THE SECTION

VIEWS OF AN ASSEMBLY, BY DEFAULT, SIMILAR HATCH PATTERNS ARE ASSIGNED TO ALL OF THEM. ALTHOUGH THE ANGLE OF HATCHING LINES BETWEEN THE ADJACENT COMPONENTS IS DIFFERENT YET IT CREATES CONFUSION IF THE ASSEMBLY HAS A NUMBER OF COMPONENTS. FOR EXAMPLE, FIGURE 11-40 SHOWS THE DRAWING VIEWS OF THE PLUMMER BLOCK ASSEMBLY. IN THIS FIGURE, THE COMPONENTS IN THE SECTION VIEW ARE ASSIGNED SIMILAR HATCH PATTERNS.




Figure 11-40 Similar hatch patterns of components in the section view

You can avoid this confusion by assigning different hatch patterns to the components of the assembly. To modify the hatch pattern, move the cursor over the hatching lines in the section view. The hatch pattern will turn red. Once the hatch pattern turns red, right-click to display the shortcut menu. In this shortcut menu, choose the **Edit** option; the **Edit Hatch Pattern** dialog box will be displayed, see Figure 11-41. The options in this dialog box are discussed next.




Figure 11-41 The Edit Hatch Pattern dialog box

By Material

This check box, if selected, displays the hatch pattern defined for a particular type of material in the **Style and Standard Editor** dialog box.

Pattern The **Pattern** drop-down list is used to select the hatch pattern for the selected hatching. You can select the required hatch pattern from the list of patterns in this drop-down list. The preview of the selected pattern will be displayed in the window to the right of this drop-down list and in the drawing sheet. The selected hatch pattern will be assigned to the selected component. However, note that this hatch pattern will not be assigned to the other instances of the selected component. The other instances of the selected component will still be hatched using the default hatch pattern.

Angle

The **Angle** edit box is used to specify the angle of the hatching lines.

Line Weight

The **Line Weight** drop-down list is used to specify the line weight of the hatching lines. You can specify the required line weight by selecting it from the predefined line weights available in this drop-down list.

Scale

The **Scale** edit box is used to specify the scale factor of the hatching lines.

Shift

The **Shift** edit box is used to offset the hatch pattern from its location through the specified distance. The hatch pattern is shifted to avoid confusion with the hatch pattern of the adjacent component. Generally, the shift value should lie between 1 and 5. You can view the effect of shifting the hatch pattern on the sheet when you enter a value in this edit box.

Color

The **Color** button is used to modify the color of the selected hatch pattern. When you choose this button, the **Color** dialog box is displayed. Select the required color for hatching lines from this dialog box.

Double

The **Double** check box is used to double the hatching lines by drawing another set of lines perpendicular to the original lines in the hatch pattern. Figure 11-42 shows the drawing views of the Plummer Block assembly with different hatch patterns assigned to the components.




Figure 11-42 Different hatch patterns assigned to the components in the section view

EDITING THE DEFAULT HATCH STYLE OF THE SECTIONED OBJECTS IN AUTODESK INVENTOR, YOU CAN EDIT THE DEFAULT HATCH STYLE OF THE SECTIONED OBJECTS. YOU CAN CHANGE THE DEFAULT HATCH PATTERN PROPERTIES SUCH AS HATCH ANGLE, HATCH PATTERN, HATCH SCALE, AND SO ON. BEFORE CHANGING THE HATCH PROPERTIES, IT IS RECOMMENDED TO VIEW THE DEFAULT HATCH PROPERTIES OF THE CUT SECTION. TO DO SO, RIGHT-CLICK ON THE HATCHING LINES IN THE SECTION VIEW; A SHORTCUT MENU WILL BE DISPLAYED. CHOOSE

EDIT FROM THE SHORTCUT MENU; THE **EDIT HATCH PATTERN** DIALOG BOX WILL BE DISPLAYED, REFER TO FIGURE 11-41. USING THIS DIALOG BOX, YOU CAN VIEW OR EDIT THE HATCH PROPERTIES OF THE CURRENT SECTION VIEW. HOWEVER, IF YOU WANT TO CHANGE THE HATCH PATTERN PROPERTIES SUCH THAT WHENEVER YOU CREATE A SECTIONED VIEW, THE DEFAULT HATCH PROPERTIES WILL BE OVERRIDDEN BY THE NEW HATCH PATTERN PROPERTIES, THEN YOU NEED TO INVOKE THE **STYLE AND STANDARD EDITOR** DIALOG BOX. TO INVOKE THIS DIALOG BOX, RIGHT-CLICK ON THE HATCHING LINES AND THEN CHOOSE THE **EDIT HATCH STYLE** OPTION FROM THE SHORTCUT MENU; THE **STYLE AND STANDARD EDITOR** DIALOG BOX WILL BE DISPLAYED. MAKE SURE THAT HATCH STYLE SHOULD BE SELECTED UNDER THE **HATCH** NODE. CHOOSE THE **NEW** BUTTON; THE **NEW LOCAL STYLE** DIALOG BOX WILL BE DISPLAYED. ENTER THE NAME OF THE HATCH STYLE IN THE **NAME** EDIT BOX. NEXT, CHOOSE **OK** TO CREATE THE HATCH STYLE. IN THE **HATCH STYLE** AREA OF THE **STYLE AND STANDARD EDITOR** DIALOG BOX, SPECIFY DIFFERENT HATCH PROPERTIES SUCH AS HATCH PATTERN, HATCH ANGLE, SCALE,

AND SO ON. AFTER SPECIFYING THE HATCH PROPERTIES, CHOOSE THE **SAVE** BUTTON TO SAVE THE HATCH STYLE.

Next, you need to modify the default hatch properties with the new hatch properties by using the **Object Defaults** node in the **Style and Standard Editor** dialog box. Expand the **Object Defaults** node to display the **Object Defaults (Current Units)** option. Select this option; the object types along with their default styles and layers will be listed in the **Style and Standard Editor** dialog box. Drag the vertical scroll bar located on the right of the dialog box to view all styles. Next, in the **Object Style** column, click on the object style corresponding to the **Section Hatch** object type; a drop-down list will be displayed. In this drop-down list, select the hatch style created earlier, as shown in Figure 11-43. Next, choose the **Save** button and then the **Done** button from the dialog box; the selected style will be set as the default hatching style.

Note

1. You can create any number of hatch styles using the **Style and Standard Editor** dialog box.

2. Make sure you select the **All Objects** or **Model/View Objects** option in the **Filter** drop-down list of the **Style and Standard Editor** dialog box. This will ensure that the **Section Hatch** along with its default style and default layer is displayed in the **Style and Standard Editor** dialog box.




Figure 11-43 Selecting the required object style for the **Section Hatch** object type

EXCLUDING COMPONENTS FROM ASSEMBLY SECTION VIEWS WHEN YOU GENERATE THE SECTION VIEWS OF AN ASSEMBLY, ALL THE COMPONENTS THAT ARE INTERSECTED BY THE CUTTING PLANE ARE SECTIONED, AS SHOWN IN

FIGURE 11-44.




Figure 11-44 All components intersected by the cutting plane

However, according to the drawing standards, the components such as nuts, bolts, lock nuts, and so on should not be sectioned while generating the section view. Therefore, you will have to exclude these components before or after generating the assembly section view.

To prevent the components from being sectioned, click on the plus (+) sign located on the left of the section view; the name of the assembly will be displayed in the **Browser Bar**. Click on the plus (+) sign located on the left of the assembly name to display all the components of the assembly in the **Browser Bar**. Now, hold the CTRL key and then use the left mouse button to select all the components that you want to exclude from sectioning. Once all the components are selected, they will be displayed in a blue background in the **Browser Bar**. Right-click on any of the selected components to display the shortcut menu. Choose **Section Participation > None** from the shortcut menu; all the selected components will be excluded from the section view, see Figure 11-45.

Note

If the file that you have selected for generating the drawing views is not in the current project, the **Autodesk Inventor Professional** information box will be displayed informing that the location of the selected file is not in the current project folder.




Figure 11-45 Drawing views with components excluded from the section view

TUTORIALS

Tutorial 1

In this tutorial, you will generate the top view, full sectioned front view, and isometric view of the sectioned front view of the model created in Tutorial 2 of the *c07*. Use the JIS standard template file for generating the views. **(Expected time: 30 min)**

The following steps are required to complete this tutorial:

- a. Copy the model of Tutorial 2 of the *c07* folder to the current folder.
- b. Open a JIS template file and generate the base view using the **Base** tool.
- c. Generate the section view by sketching the section plane.
- d. Use the **Projected** tool to project lines at an angle from the section view to generate the isometric view.

Copying the Model to the Current Folder Before generating the drawing view of the model, it is important to copy the model to the current folder. This is necessary because when you open the drawing file next time, the component will be searched in the current *c11* folder. If the component is not available in the current folder, the **Resolve Link** dialog box will be displayed. This dialog box will prompt you to specify the location and path of the component file. Therefore, all the components or the assemblies should be copied into the current folder, or the drawing file should be saved in the folder in which the component and assembly file are located.

1. Create a folder with the name *c11* at the location *C:\Inventor_2016* and then copy the *Tutorial 2.ipt* file from the location *C:\Inventor_2016\c07* to the *c11* folder. Next, rename this file as *Tutorial 1.ipt*.

Starting a New Drawing File As mentioned in the tutorial description, you need to use the JIS standard template for generating the drawing views. Therefore, you will use the *JIS.idw* file for generating the drawing views.

1. Start a new session of Autodesk Inventor and choose the **New** tool from the

Launch panel of the **Get Started** tab to invoke the **Create New File** dialog box.

2. Choose the **Metric** tab and then double-click on the **JIS.idw** option to open a JIS standard drawing file, see Figure 11-46.




Figure 11-46 Screen display of the JIS standard drawing file

Generating the Base View

As mentioned earlier, the base view is the first view in the drawing sheet. Once you have generated the base view, you can use it as the parent view for generating other views. The base view is generated using the **Base View** tool.

1. Choose the **Base View** tool from the Marking menu which is displayed when you right-click anywhere in the graphics window; the **Drawing View** dialog box is displayed.

The preview of the drawing view is not displayed on the sheet because you have not selected any part file. Therefore, first you need to select the part file for which the drawing view will be generated.

2. Choose the **Open an existing file** button on the right of the **File** drop-down list in the **Component** tab of the **Drawing View** dialog box; the **Open** dialog box is displayed.
3. In this dialog box, select *Tutorial1.ipt* from *C:\Inventor_2016\c11* and then choose the **Open** button.

You will notice that the preview of the drawing view with default orientation is displayed. Also, its projected view gets attached to the cursor. The projected view moves as you move the cursor and will be generated at the point that you specify in the graphic window.

4. Modify the scale value to **1.5 : 1** in the **Scale** edit box.

Make sure that the **Hidden Line** button is chosen from the **Style** area in the **Component** tab of the **Drawing View** dialog box.

5. Next, choose the **OK** button to exit the drawing view dialog box; the drawing view is created.
6. Select and drag the drawing view to the top left corner of the sheet, see Figure 11-47.



Note The **Drawing View** dialog box can be moved by dragging from its title bar, if it hinders the specifying of point on the sheet.

Generating the Section View The section view can be generated using the **Section** tool. To generate the view using this tool, first you need to select the drawing view that has to be sectioned and then define the section plane. But, if you use the shortcut menu that is displayed by right-clicking on the base view in the **Browser Bar** or in the drawing sheet, you do not need to select the drawing view as it is already selected. Therefore, you will use this shortcut menu to generate the section view.

1. Move the cursor over the base view on the sheet to display the red dotted box, which is the bounding box of the view. When the bounding box is displayed, right-click and choose **Create View > Section View** from the shortcut menu; the cursor changes to the sketch cursor and you are prompted to enter the endpoints of the section line.
2. Move the cursor close to the midpoint of the extreme left vertical edge of the base view; the cursor snaps at the midpoint and turns green, refer to Figure 11-48.




Figure 11-47 Drawing sheet with the drawing view




Figure 11-48 Cursor snapping at the midpoint of the left vertical edge

3. Move the cursor horizontally toward the left of the view. You will notice that an imaginary horizontal line is drawn from the midpoint of the left vertical edge. This is due to the temporary tracking option.
4. Click to specify a point after moving the cursor horizontally toward the left of the view to a small distance. The specified point is selected as the first point of

the section plane.

When you move the cursor toward the right, the symbol of the perpendicular constraint is attached to the cursor which confirms that the line defining the section view is horizontal. This symbol also indicates that the line is normal to the extreme left vertical edge of the base view. This perpendicular constraint is applied because you snapped to the midpoint of the left vertical edge of the base view.

5. Move the cursor horizontally toward the right of the view. You will notice that a horizontal line is drawn. Move the cursor on the right of the extreme right vertical edge of the base view. Make sure that the cursor does not snap to the midpoint of the right vertical edge and the line drawn is horizontal.
6. Specify a point on the right of the right vertical edge of the base view. This point is selected as the second point of the section plane.
7. Right-click and then choose **Continue** from the Marking menu; the **Section View** dialog box is displayed and the preview of the section view attached to the cursor appears on the sheet. You are prompted to specify the location of the section view. Note that hatching lines will not be displayed in the preview of the section view.
8. Specify the location of the section view below the base view, see Figure 11-49. The **Section View** dialog box is automatically closed when you specify the location of the section view.




Figure 11-49 Drawing sheet with the base and section views

Generating the Isometric View of the Section View The isometric view of the section view can be generated using the shortcut menu.

1. Move the cursor over the section view and right-click when the dotted rectangle is displayed; a shortcut menu is displayed.
2. Choose **Create View > Projected View** from the shortcut menu; you are prompted to select the view location.
3. Move the cursor toward the right of the section view and then move it upward until the preview of the isometric view appears. Now, specify the location of the view. Right-click on the view; a Marking menu is displayed. Choose **Create** from the Marking menu; the isometric view of the model is generated, as shown in Figure 11-50.
4. Save the drawing file with the name *Tutorial1.idw* at the location *C:\Inventor_2016\c11* and close it.




Figure 11-50 Drawing sheet after generating the isometric view of the model

Tutorial 2

In this tutorial, you will generate the top view, full sectioned front view, and isometric view of the section view of the Plummer Block assembly created in Tutorial 2 of the *c09* folder. The Nuts and Bolts should be excluded from the section view. Also, all sectioned components should have different hatch patterns. Use the JIS standard drawing file for generating the drawing views of the assembly. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- a. Copy the *Plummer Block* folder from the *c09* folder to the *c11* folder.
- b. Generate the top view of the assembly.
- c. Show the contents of the base view and then exclude the Bolts, Nuts, and Lock Nuts so that they are not sectioned.
- d. Use the top view as the parent view to generate the full section front view.
- e. Modify the hatch of Casting and Cap.
- f. Generate the projected isometric view of the sectioned front view.

Copying the Plummer Block Folder As mentioned earlier, you will have to copy the file that will be used to generate drawing views in the current folder. To generate the drawing views of the assembly in this

tutorial, you will have to copy the folder in which the files of the assembly are stored. Also, note that the drawing file will be saved in the folder of the assembly, and not in the *c11* folder.

1. Copy the Plummer Block folder from the location *C:\Inventor_2016\c09* to the location *C:\Inventor_2016\c11*.

Starting a New Drawing File 1. Choose the **New** tool from the **Launch** panel of the **Get Started** tab to invoke the **Create New File** dialog box.

2. In this dialog box, choose the **Metric** tab and then double-click on the **JIS.idw** option to open a JIS standard drawing file.

Generating the Top View of the Assembly 1. Choose the **Base** tool from the **Create** panel of the **Place Views** tab; the **Drawing View** dialog box is displayed.

2. In the **Component** tab of this dialog box, choose the **Open an existing file** button on the right of the **File** drop-down list; the **Open** dialog box is displayed.
3. Browse to the *Plummer Block* folder at the location *C:\Inventor_2016\c11* and then select the *Plummer Block.iam* file from it.
4. Next, choose the **Open** button to select the assembly for generating the drawing views; the preview of the view of the assembly is displayed in the graphics window.
5. Change orientation of view as top view by using ViewCube in the graphics window, as shown in Figure 11-51.
6. Modify the view scale to **1.25 : 1** in the **Scale** edit box.

Make sure that **Hidden Line Removed** button is chosen from the **Style** area in the **Component** tab of **Drawing View** dialog box.

- Next, choose the **OK** button to exit the **Drawing View** dialog box; the drawing view is created.
- Select and drag the drawing view close to the top left corner of the sheet, refer to Figure 11-51.




Figure 11-51 Top view of the assembly

Excluding Components from the Section Views As mentioned in the tutorial description, the Nuts, Bolts, and Lock Nuts need to be excluded from the section view. Therefore, you need to exclude these components such that they are not sectioned in the section view.

- Click on the plus sign (+) located on the left of the view node in the **Browser Bar** to display the *Plummer Block.iam* assembly. Also, a plus (+) sign is displayed on the left of this assembly in the **Browser Bar**.
- Click on the plus sign (+) located on the left of **Plummer Block.iam** to display all components of the assembly. Press and hold the CTRL key and select both instances of Nut, Bolt, and Lock Nut using the left mouse button.

The selected components are displayed in blue background in the **Browser Bar**.

3. Right-click on any selected component in the **Browser Bar**; a shortcut menu is displayed. Choose **Section Participation > None** from the shortcut menu.
4. Pick a point on the sheet to clear the selection of components.

Generating the Section View Since you have turned off the option for sectioning some of the components, they will not be sectioned while generating the section view.

1. Choose the **Section** tool from the **Create** panel of the **Place Views** tab; you are prompted to select the view to be sectioned.
2. Select the top view from the Graphics window; the cursor turns into a sketch cursor and you are prompted to enter the endpoints of the section line.
3. Move the cursor close to the midpoint of the extreme left vertical edge of the top view; the cursor snaps to the midpoint and turns green.
4. When the cursor snaps to the midpoint, move it horizontally toward the left and specify a point as the start point of the section plane.
5. Now, move the cursor horizontally toward the right.
6. Specify a point on the right of the extreme right vertical edge of the top view as the second point of the section plane. Note that the line should be horizontal, not inclined.
7. Right-click and then choose **Continue** from the Marking menu to display the **Section View** dialog box. The preview of the section view attached to the cursor is displayed and you are prompted to specify the location of the section view. Specify the location below the top view, as shown in Figure 11-52.




Figure 11-52 Sheet with the top view and the sectioned front view

Modifying Hatch Patterns

The section view displays three components in section: Casting, Cap, and Brasses. One of these components can retain the current hatching style and the hatching style in the remaining two components will be modified. In this tutorial, Brasses will retain the current style and you will modify the hatching in Casting and Cap.

1. Move the cursor over the hatching in Casting; the hatching lines turn red. Next, right-click and choose **Edit** from the shortcut menu to display the **Edit Hatch Pattern** dialog box.
2. In this dialog box, select **ISO02W100** from the **Pattern** drop-down list and then select the **Double** check box. Choose **OK** to exit this dialog box; the hatching style of the selected component is modified.
3. Move the cursor over the hatching in Cap; the hatching lines turn red. Next, right-click to display the shortcut menu. Choose **Edit** from the shortcut menu to display the **Edit Hatch Pattern** dialog box.
4. Select the **Double** check box and then choose **OK** to exit this dialog box. All three components that are sectioned have different hatch patterns now.

Generating the Isometric View of the Section View The third view that you need to generate is the isometric view of the section view. This view is generated using the shortcut menu.

1. Move the cursor on the section view to display the bounding box. Note that the cursor should not be over any hatch pattern. When the bounding box is displayed, right-click to display the shortcut menu. Choose **Create View > Projected View** from the shortcut menu; the preview of the projected view is attached to the cursor.
2. Move the cursor toward the right of the section view in the horizontal direction and then move the cursor upward until the preview of the isometric view attached to the cursor is displayed. When the isometric view is displayed, click to specify the point to define the location of this view.

3. Right-click and then choose **Create** from the Marking menu; the isometric view of the section view is generated. The drawing sheet with all drawing views is shown in Figure 11-53.
4. Save the drawing sheet with the name *Tutorial2.idw* at the location below and then close the file.

C:\Inventor_2016\c11\Plummer Block

The file is saved in the Plummer Block folder because the Plummer Block assembly file that was used to generate drawing views is stored in it.




Figure 11-53 Drawing sheet after generating all three views

Self-Evaluation Test Answer the following questions and then compare them to those given at the end of this chapter:

1. While generating the base view, you can display model dimensions by selecting the _____ check box in the **Display Options** tab of the **Drawing View** dialog box.

2. By default, the display style of the projected views is the same as that of the _____.
3. _____ views are generated by projecting the lines normal to a specified edge in the parent view.
4. The part of the original view that is sectioned will be displayed with _____ in the section view.
5. The **Slice** tool is used to create the _____ section views.
6. You cannot generate the drawing views of an assembly file. (T/F)
7. The **Drawing** module of Autodesk Inventor is not bidirectional in nature. (T/F)
8. You can add more sheets for generating drawing views. (T/F)
9. The display type of a view set once can be modified later. (T/F)
10. In Autodesk Inventor, the cutting plane is defined by sketching one or more than one line. (T/F)

Review Questions Answer the following questions:

1. Which of the following tools is used to sketch a drawing view?
(a) **Draft** (b) **Base** (c) **Section** (d) None of these
2. Which of the following tabs is used to modify the orientation of the base view.
(a) **Place Views** (b) **Getting Started** (c) **Custom View** (d) None of these
3. Which of the following tools is used to generate a drawing view by removing a small portion from its middle, keeping the ends of the component intact?
(a) **Draft** (b) **Base** (c) **Break** (d) None of these
4. Which of the following tools is used to display the details of a portion of an existing view by magnifying that portion and displaying it as a separate view?
(a) **Detail** (b) **Base** (c) **Overlay** (d) None of these
5. Which of the following tools in Autodesk Inventor can be used to generate isometric views?

- (a) **Draft** (b) **Base** (c) **Projected** (d) None of these
6. You cannot prevent dependent views from getting deleted if the parent view is deleted. (T/F)
 7. The hatch pattern of a component can be modified in the section view. (T/F)
 8. You can prevent some components from getting sectioned in the section view. (T/F)
 9. You can suppress the option to move the dependent views along with the parent view if you do not want to move them with the parent view. (T/F)
 10. You can copy a drawing view in a new drawing file. (T/F) *Exercise Exercise 1*

Generate the top view, right half sectioned front view, isometric view, and overlay view of the Double Bearing assembly with a scale of 2.5:1. Note that the overlay view should be created using positional reference. This assembly was created in Tutorial 3 of the *c10* folder. The Nut that is intersected by the cutting plane should not be be sectioned and the components should have different hatch patterns, as shown in Figure 11-54. Use the JIS standards for generating the views. **(Expected time: 45 min)**




Figure 11-54 Drawing views to be generated for Exercise 1

Answers to Self-Evaluation Test **1. All Model Dimensions**, **2. parent view**, **3. Auxiliary**, **4. hatching lines**, **5. zero-depth**, **6. F**, **7. F**, **8. T**, **9. T**, **10. T**

Chapter 12

Working with Drawing Views-II

Learning Objectives

After completing this chapter, you will be able to:

- Modify drawing standards.
- ***Insert additional sheets in the current drawing.***
- ***Activate a drawing sheet.***
- ***Add parametric and reference dimensions to drawing views.***
- ***Modify the current sheet style.***
- ***Create dimension styles.***
- ***Modify a dimension and its appearance using the shortcut menu.***
- ***Create and edit the parts list for assembly drawing views.***
- ***Set the standard for the parts list.***
- ***Add balloons to assembly drawing views.***

MODIFYING DRAWING STANDARDS AS MENTIONED IN CHAPTER 11, BY DEFAULT, A SELECTED SHEET FOLLOWS ITS STANDARDS IN GENERATING AND DIMENSIONING THE DRAWING VIEWS. HOWEVER, YOU CAN MODIFY

THE STANDARDS OF THE CURRENT SHEET. FOR EXAMPLE, YOU CAN OPEN A JIS STANDARD DRAWING FILE AND ASSIGN THE ANSI STANDARDS TO IT SUCH THAT WHEN YOU GENERATE THE DRAWING VIEWS AND DIMENSION THEM, THE ANSI DRAFTING STANDARDS ARE FOLLOWED. YOU CAN MODIFY THE STANDARDS OF THE CURRENT SHEET BY CHOOSING THE **STYLES EDITOR** TOOL FROM THE **STYLES AND STANDARDS** PANEL OF THE **MANAGE** TAB. ON DOING SO, THE **STYLE AND STANDARD EDITOR [LIBRARY - READ ONLY]** DIALOG BOX WILL BE DISPLAYED. SELECT **ALL STYLES** FROM THE **FILTER STYLES** DROP-DOWN LIST ON THE TOP RIGHT CORNER OF THIS DIALOG BOX; ALL AVAILABLE STANDARDS WILL BE DISPLAYED UNDER THE **STANDARD** HEADING IN THE LEFT PANE OF THIS DIALOG BOX AND THE CURRENT SHEET STANDARD WILL BE DISPLAYED IN BOLD FACE, AS SHOWN IN FIGURE 12-1.




Figure 12-1 *The Style and Standard Editor [Library - Read Only] dialog box*

To assign a different standard to the current sheet, right-click on any standard and then choose the **Active** option from the shortcut menu; the selected standard will be assigned to the current sheet.

Using the options in the **Standard** area on the right pane of this dialog box, you can change the projection type from first angle to third angle in the **View Preferences** tab, and vice-versa. You can also select other headings from the left pane and expand them to display the standards for that heading. By selecting a standard, you can modify the options in it.


INSERTING ADDITIONAL SHEETS INTO DRAWING RIBBON: PLACE VIEWS > SHEETS > NEW SHEET WHEN YOU OPEN A NEW DRAWING FILE, ONLY ONE SHEET IS AVAILABLE.

HOWEVER, YOU CAN INSERT MORE DRAWING SHEETS FOR GENERATING THE DRAWING VIEWS USING THE **NEW SHEET** TOOL. YOU CAN ALSO INSERT A NEW DRAWING SHEET BY USING THE **BROWSER BAR**. TO DO SO, RIGHT-CLICK ON THE **BROWSER BAR**; A SHORTCUT MENU WILL BE DISPLAYED. CHOOSE **NEW SHEET** FROM THE SHORTCUT MENU.

ALTERNATIVELY, RIGHT-CLICK ANYWHERE ON THE DRAWING SHEET AND CHOOSE **NEW SHEET** FROM THE MARKING MENU DISPLAYED. WHEN YOU INVOKE THIS TOOL, A NEW SHEET IS AUTOMATICALLY ADDED AND IT WILL BE THE ACTIVE SHEET. AN ACTIVE SHEET IS THE ONE ON WHICH YOU CAN GENERATE THE DRAWING VIEWS. THE ACTIVE SHEET WILL BE DISPLAYED WITH A WHITE BACKGROUND IN THE **BROWSER BAR**. THE OTHER DRAWING SHEETS WILL BE DISPLAYED WITH A GRAY BACKGROUND IN THE **BROWSER BAR**.

ACTIVATING A DRAWING SHEET YOU CAN ACTIVATE ANY DRAWING SHEET BY RIGHT-CLICKING ON IT IN THE **BROWSER BAR** AND THEN CHOOSING **ACTIVATE** FROM THE SHORTCUT MENU, AS SHOWN IN FIGURE 12-2. NOTE THAT IF A SHEET HAS ALREADY BEEN

ACTIVATED, THIS OPTION WILL NOT BE AVAILABLE WHEN YOU RIGHT-CLICK ON A SHEET IN THE **BROWSER BAR**. YOU CAN ALSO MAKE A SHEET ACTIVE BY DOUBLE-CLICKING ON IT IN THE **BROWSER BAR**.



*Figure 12-2 Choosing the **Activate** option from the **Browser Bar***

DISPLAYING DIMENSIONS IN DRAWING VIEWS AS MENTIONED IN CHAPTER 11, YOU CAN DISPLAY THE MODEL DIMENSIONS ON THE DRAWING VIEWS WHILE GENERATING THEM. MODEL DIMENSIONS ARE ALSO CALLED PARAMETRIC DIMENSIONS AND ARE THE DIMENSIONS THAT WERE USED TO CREATE THE MODEL IN THE PART FILE. THESE ARE THE DIMENSIONS THAT WERE APPLIED ON THE SKETCHES OR IN VARIOUS DIALOG BOXES WHILE DEFINING FEATURES. TO DISPLAY MODEL DIMENSIONS WHILE GENERATING A DRAWING VIEW, SELECT THE **ALL MODEL**


DIMENSIONS CHECK BOX IN THE DISPLAY OPTIONS TAB OF THE DRAWING VIEW DIALOG BOX. NOTE THAT THIS OPTION WILL NOT BE AVAILABLE WHEN YOU GENERATE THE DRAWING VIEWS OF AN ASSEMBLY.

You can retrieve the model dimensions after placing the drawing views and select the dimension that you need to retain. In addition to the model dimensions, Autodesk Inventor also allows you to add reference dimensions to the drawing views. The reference dimensions are those which were not applied to the model in the **Part** module. These dimensions are used only for reference and not during the manufacturing of a part. The methods of retrieving the model dimensions and placing the reference dimensions are discussed next.

Retrieving Parametric Dimensions in Drawing Views

Ribbon: Annotate > Dimension > Retrieve The **Retrieve** tool is used to retrieve the dimensions of a model after placing the drawing view. On invoking this tool, the **Retrieve Dimensions** dialog box will be displayed and you will be prompted to select a view, a draft view, or a drawing sheet sketch. When you select a view, the options in this dialog box will be enabled, refer to Figure 12-3. You can also select a drawing view and then right-click on it to display the shortcut menu. In the Marking Menu, choose **Retrieve Dimensions**. You can use this dialog box to select the parts or features whose dimensions you want to retrieve. In Autodesk Inventor, you can also retrieve dimensions from isometric drawing views and assembly views. The options in the **Retrieve**

Dimensions dialog box are discussed next.



*Figure 12-3 The **Retrieve Dimensions** dialog box*

*Tip. Before retrieving dimensions, it is recommended that you first set the dimension style parameters first by expanding the **Dimension** option in the left pane of the **Style and Standard Editor [Library - Read Only]** dialog box and then by modifying the required dimension style. You may have to select the **All Styles** option from the **Filter Style** drop-down list on the top right corner of the dialog box to display all styles. Before you exit from this dialog box, choose the **Save** button to save changes in the current style. Now, after invoking the **Retrieve Dimensions** dialog box, make the dimension style current by selecting it from the second drop-down list in the **Format** panel of the **Annotate** tab.*

Select View

This button is chosen to select the view, in which you want to retrieve the dimensions. Note that when you invoke the **Retrieve** tool using the **Ribbon** or the Marking menu, the **Select View** button is chosen by default. Also, you will be prompted to select the view, in which you want to retrieve the dimensions. Also, after retrieving the required dimensions in the selected view, you can choose this button again to select another view to retrieve the dimensions.

Select Source Area The options in the **Select Source** area are used to specify whether you want to retrieve the dimensions of a selected feature or of the entire part. Depending on the source using which you want to retrieve the dimensions, select the radio button. Next, select the part or the feature in the view; the dimensions of the selected part or feature will be retrieved in that view.

Select Dimensions

You will notice that even after retrieving the dimensions of a selected feature or part, the **OK** button in the **Retrieve Dimensions** dialog box is not activated. This is because this command is not completed until you choose the **Select Dimensions** button and also select the dimensions that you want to retain. You can select the dimensions to be retained by using a crossing or a window, or by selecting the dimensions individually.

After retrieving and selecting the dimensions, choose the **Apply** button to select another view to retrieve the dimensions. In this case, the retrieved dimensions will turn gray in color and the **Select View** button will be chosen to let you select another view for retrieving the dimensions. You can choose the **OK** button, if you do not want to select any other view to retrieve the dimensions.

Adding Reference Dimensions Ribbon: Annotate > Dimension > Dimension Autodesk Inventor allows you to add reference dimensions to a drawing view. You can do so by using the **Dimension** tool of the drafting environment. The function of this tool is similar to that of the **Dimension** tool in the **Part** module. When you add a dimension to a drawing view, the **Edit Dimension** dialog box will be displayed. Using this dialog box, you can change different parameters of dimensions such as text, tolerance, and so on.

MODIFYING THE MODEL DIMENSIONS
AUTODESK INVENTOR ALLOWS YOU TO
MODIFY MODEL DIMENSIONS DISPLAYED IN A
DRAWING VIEW. HOWEVER, AS MENTIONED
EARLIER, ALL MODULES OF AUTODESK
INVENTOR ARE BIDIRECTIONALLY

ASSOCIATIVE. THIS NATURE OF AUTODESK INVENTOR ENSURES THAT IF YOU MODIFY A DIMENSION VALUE IN THE **DRAWING** MODULE, THE MODIFICATIONS WILL REFLECT ON THE MODEL IN THE **PART** MODULE. THEREFORE, YOU NEED TO BE VERY CAREFUL WHILE MODIFYING THE MODEL DIMENSIONS. TO MODIFY A MODEL DIMENSION, RIGHT-CLICK ON IT AND THEN CHOOSE **EDIT MODEL DIMENSION** FROM THE SHORTCUT MENU, SEE FIGURE 12-4. BASED ON THE DIMENSION SELECTED TO BE EDITED, THE **EDIT DIMENSION** EDIT BOX WILL BE DISPLAYED WITH THE CURRENT DIMENSION VALUE. YOU CAN MODIFY THE DIMENSION VALUE IN THE EDIT BOX AND THEN EXIT THE EDIT BOX. YOU WILL NOTICE THAT THE DIMENSION IS MODIFIED AND IS REFLECTED IN THE FEATURE OF THE DRAWING VIEWS.




Figure 12-4 Choosing **Edit Model Dimension** from the shortcut menu

EDITING DRAWING SHEETS

Autodesk Inventor allows you to edit a selected drawing sheet. You can modify the size of a sheet, relocate a title block, modify the orientation of a drawing sheet, and so on. To edit a drawing sheet, right-click on its name in the **Browser Bar** and then choose **Edit Sheet** from the shortcut menu; the **Edit Sheet** dialog box will be displayed, as shown in Figure 12-5. The options in this dialog box are discussed next.

Format Area

The options in the **Format** area are used to define the name and size of the drawing sheet. These options are discussed next.




Figure 12-5 The Edit Sheet dialog box

Name

The **Name** edit box is used to enter the name of the drawing sheet. The name you enter in this edit box will be displayed in the **Browser Bar**.

Size

The **Size** drop-down list is used to define the size of the drawing sheet. You can select predefined drawing sheet sizes from this drop-down list. To specify a user-defined size, select **Custom Size (inches)** or **Custom Size (mm)** from this drop-down list. Using these options, you can specify a user-defined size in inches or in millimeters. The height and width of the user-defined size will be defined in the **Height** and **Width** edit boxes. These edit boxes will be activated below the **Size** drop-down list when you select the option to specify the user-defined size.

Revision

The **Revision** edit box allows you to specify the revision number of the drawing sheets.

Orientation Area

The options in the **Orientation** area are used to specify the orientation of the sheet and the location of the title block. This area displays a sheet and has four radio buttons close to the four corners of the sheet. These radio buttons define the location of the title block in the sheet. By default, the radio button provided close to the lower right corner of the sheet is selected. This forces the title block to be placed on the lower right corner of the sheet. You can place the title block on any of the four corners by selecting their respective radio buttons. You can also define whether the orientation of the drawing sheet should be portrait or landscape by selecting the **Portrait** or **Landscape** radio button.

Options Area

The options in the **Options** area are discussed next.

Exclude from count

By default, when you open a drawing file, one sheet is available. This sheet is assigned number 1. If you add more sheets, they will be numbered 2, 3, and so on. Select the **Exclude from count** check box if you do not want the current sheet to be included in this count. On selecting this check box, the current sheet will not be assigned any number and the sheet numbers of the other sheets will be adjusted accordingly.

Exclude from printing

The **Exclude from printing** check box is selected to exclude the current sheet from printing. If this check box is selected, the current sheet will not be considered while printing.

CREATING DIMENSION STYLES DIMENSION STYLES ARE USED TO CONTROL THE APPEARANCE AND POSITIONING OF THE PARAMETERS RELATED TO DIMENSIONS.

AUTODESK INVENTOR PROVIDES A NUMBER OF DIMENSION STYLES THAT CAN BE USED TO DISPLAY DIMENSIONS. HOWEVER, IF A PREDEFINED DIMENSION STYLE DOES NOT MEET YOUR REQUIREMENTS, YOU CAN DEFINE A NEW DIMENSION STYLE AND SET ITS OPTIONS BASED ON YOUR REQUIREMENT. TO CREATE A NEW DIMENSION STYLE, CHOOSE THE **STYLES EDITOR** TOOL FROM THE **STYLES AND STANDARDS** PANEL OF THE **MANAGE** TAB; THE **STYLE AND STANDARD EDITOR [LIBRARY - READ ONLY]** DIALOG BOX WILL BE DISPLAYED. EXPAND THE **DIMENSION** OPTION FROM THE LEFT PANE AND THEN SELECT THE REQUIRED DIMENSION STYLE. THE OPTIONS RELATED TO THE **DEFAULT - MM (ANSI)** DIMENSION STYLE WILL BE DISPLAYED IN THE RIGHT PANE OF THE DIALOG BOX, AS SHOWN IN FIGURE 12-6.




Figure 12-6 The Style and Standard Editor [Library - Read Only] dialog box

As evident from this figure, the right pane of the dialog box provides various tabs to set the options related to a dimension style. You can also create a new dimension style using this dialog box. To do so, choose the **New** button; the **New Local Style** dialog box will be displayed. Enter the name of the dimension style in this dialog box. Now, make the necessary changes in the parameters related to dimensions in the tabs of the **Style and Standard Editor [Library - Read Only]** dialog box. After making all necessary changes, choose the **Save** button. The new drawing views will be dimensioned using this dimension style.

APPLYING DIMENSION STYLES TO APPLY A NEW DIMENSION STYLE TO A DIMENSION, SELECT THE REQUIRED DIMENSION FROM THE DRAWING VIEW AND THEN RIGHT-CLICK; A SHORTCUT MENU WILL BE DISPLAYED. CHOOSE

NEW DIMENSION STYLE FROM THE SHORTCUT MENU; THE NEW DIMENSION STYLE DIALOG BOX WILL BE DISPLAYED. SELECT THE REQUIRED DIMENSION STYLE FROM THE LIST BOX IN THIS DIALOG BOX; THE OPTIONS IN THE DIALOG BOX WILL BE MODIFIED ACCORDINGLY. NEXT, CHOOSE **OK TO APPLY THE SELECTED DIMENSION STYLE TO THE DIMENSION.**

MODIFYING A DIMENSION AND ITS APPEARANCE USING THE SHORTCUT MENU YOU CAN ALSO MODIFY A DIMENSION AND ITS APPEARANCE USING THE SHORTCUT MENU. THIS SHORTCUT MENU IS DISPLAYED WHEN YOU RIGHT-CLICK ON A DIMENSION. DEPENDING UPON THE TYPE OF DIMENSION SELECTED, THE OPTIONS ARE DISPLAYED IN THE SHORTCUT MENU. FOR EXAMPLE, FIGURE 12-7 SHOWS THE SHORTCUT MENU THAT WILL BE DISPLAYED WHEN YOU RIGHT-CLICK ON A LINEAR DIMENSION.

You can use this menu to control the display of extension lines, dimension text, leaders, arrowheads, and so on. To modify the dimension text, choose the **Edit** option from the shortcut menu; the **Edit Dimension** dialog box will be displayed, as shown in Figure 12-8. Select the **Hide Dimension Value** check box from the **Text** tab in this dialog box and enter the required value in the text box. Next, choose the **OK** button to exit this dialog box. To hide the extension

lines of a dimension, right-click on an extension line; a shortcut menu will be displayed. Next, choose the **Hide Extension Line** option from the shortcut menu; the extension lines will be hidden.




Figure 12-7 Shortcut menu displayed




Figure 12-8 The Edit Dimension dialog box

ADDING THE PARTS LIST

Ribbon: Annotate > Table > Parts List **The parts list is a table, which provides information about the items, quantity, and other related description of components in an assembly. It is extremely useful for providing information related to the components of an assembly in the drawing views. On invoking the Parts List tool, the Parts List dialog box will be displayed, as shown in Figure 12-9. The options in this dialog box are discussed next.**




Figure 12-9 The Parts List dialog box

Source Area

This area provides the options for selecting the source for generating the parts list. These options are discussed next.

Select View

This button is chosen by default in the **Parts List** dialog box and is used to select an existing drawing view as the source for generating the parts list.

Browse for file

This button is chosen to select a file that will be used as a source to generate the parts list. When you choose this button, the **Open** dialog box will be displayed that can be used to select the file for generating the parts list. The name and location of the selected file is displayed in the drop-down list on the left of this button.

BOM Settings and Properties Area The options in this area are used to specify the settings and properties related to BOM (Bill of Materials). These options are discussed next.

BOM View

This drop-down list is used to specify the Bill of Material view to be used for generating the parts list. You can select the **Structured**, **Parts Only**, **Structured (legacy)**, or **Parts Only (legacy)** options. If the **Structured** option is selected, the subassemblies in the main assembly will be displayed as a single item in the parts list and the individual components of the subassemblies will not be listed. However, if you select the **Parts Only** option, the components of the subassemblies will also be displayed. The **Structured (legacy)** option, if selected, determines and displays the nested components in an assembly and the changes made to them.

Note 1. If the **Parts Only** option is not turned on in the assembly document, an error message box will be displayed, stating that this option is not enabled. You can enable this option in the assembly document using this error message box.

*2. The view properties are not available for the **Parts only (legacy)** option.*

Level/Numbering

The **Level** drop-down list is available when you select the **Structured** option from the **BOM View** drop-down list. This drop-down list is used to specify whether only the first level components will be displayed or all level components will be displayed in the BOM. The **Numbering** drop-down list is available when you select the **Parts Only** option from the **BOM View** drop-down list. You can specify whether the numbering for the components will be numeric or alpha.

Min. Digits

This drop-down list is used to set the minimum digits for numbering the components in the BOM. The range varies from 1 to 6.

Delimiter

This drop-down list is used to set delimiter for numbering the structured item of the components in the BOM. This is available when you select the **All Level** option from the **Level** drop-down list. Also, available when the **Structured (legacy)** option is selected from **BOM View** drop-down list.

Case This drop-down list is used to set the case of the part names.

Table Wrapping Area

The options in the **Table Wrapping** area are used to specify the format of the parts list. These options are generally used for the assemblies that have a large number of components. The parts list of such an assembly gets very lengthy. You can split it into two or three sections to reduce its length. However, in such parts lists, the width increases as the columns are increased by two or three times. The options in this area are discussed next.

Direction to Wrap Table

The **Left** and **Right** radio buttons in this area are used to specify the side of the parts list to which the additional section will be added if the number of sections are more than 1.

Enable Automatic Wrap

This check box is used to set the option for enabling automatic wrapping. When you select this check box, the **Maximum Rows** and **Number of Sections** radio buttons are enabled. The **Maximum Rows** radio button is used to specify the maximum number of rows after which the parts list will be wrapped to the specified side. You can specify the number of rows in the edit box available on the right of this radio button. The **Number of Sections** radio button is used to specify the number of sections in which the parts list will be split.

After setting the options in the **Part List** dialog box, choose the **OK** button; the dialog box will close and you will return to the drawing sheet. Also, you will notice that the parts list is attached to the cursor. Place the parts list at the desired point. Figure 12-10 shows the drawing views of the Double Bearing assembly with the parts list.




Figure 12-10 Drawing views of an assembly with the parts list

EDITING THE PARTS LIST THE DEFAULT PARTS LIST, WHICH IS PLACED IN AN ASSEMBLY, HAS ONLY SELECTED COLUMNS. TO ADD MORE COLUMNS TO THE PARTS LIST OR DELETE SOME OF THE COLUMNS FROM IT, YOU NEED TO EDIT

IT. TO EDIT A PARTS LIST, RIGHT-CLICK ON IT; A SHORTCUT MENU WILL BE DISPLAYED. CHOOSE **EDIT PARTS LIST** FROM THE SHORTCUT MENU; THE **PARTS LIST** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 12-11. ALTERNATIVELY, DOUBLE-CLICK ON THE PARTS LIST TO INVOKE THE **PARTS LIST** DIALOG BOX.

In this dialog box, the default columns and values are displayed. You will notice that the values are displayed in black color. To modify the value of any field, click on it and enter the new value. The other options in this dialog box are discussed next.




Figure 12-11 The **Parts List** dialog box for editing the parts list

Column Chooser

The **Column Chooser** button is used to select the columns that are displayed in the parts list. By default, the parts list displays some preselected columns. To display more columns in the parts list, choose the **Column Chooser** button; the **Parts List Column Chooser** dialog box will be displayed, as shown in Figure 12-12. This dialog box has two main areas: **Available Properties** and **Selected Properties**. The **Selected Properties** area displays all columns that are selected and displayed in the parts list. The **Available Properties** area displays all columns that can be selected for adding to the parts list. Select the column that you want to display in the parts list from the **Available Properties** area and then choose the **Add** button. On doing so, the selected column will be displayed in the **Selected Properties** area. Similarly, if you want to remove any column from the **Selected Properties** area, select the column and then choose the **Remove** button.

You can also define a new property by choosing the **New Property** button from this dialog box. On choosing this button, the **Define New Property** dialog box will be displayed. Enter the name of the property to be defined in the display box of this dialog box and then choose **OK**; the property will be added to the **Selected Properties** area of the **Parts List Column Chooser** dialog box. Next, choose **OK** from this dialog box; a new column with the defined property will be added to the **Parts List** dialog box.

Group Settings

The **Group Settings** button is used to invoke the **Group Settings** dialog box. You can use this dialog box to group similar items in the parts list.




Figure 12-12 The Parts List Column Chooser dialog box

Filter Settings The **Filter Settings** button is chosen to invoke the **Filter Settings** dialog box. You can use this dialog box to define the list of parts to be filtered. The **Filter Settings** dialog box updates the part list table according to the filtering conditions.

Sort

The **Sort** button is chosen to sort the items in the parts list. If you choose this button, the **Sort Parts List** dialog box will be displayed. Using this dialog box, you can sort the items in the parts list.

Export

The **Export** button is chosen to export the parts list to an external file. When you choose this button, the **Export Parts List** dialog box will be displayed. You can use this dialog box to specify the file type of the new file and its location.

Table Layout

The **Table Layout** button is chosen to define the heading of the parts list and its location in the table. When you choose this button, the **Parts List Table Layout** dialog box will be displayed. The name of the parts list can be specified in the edit box given below the **Title** check box. If this check box is not selected, the title name is not displayed and the location can be specified using the options from the drop-down available under the **Heading** area. If you choose the **No Heading** option, the heading of the parts list will not be displayed. This dialog box is also used to define the line spacing of the parts list.

Renumber Items

The **Renumber Items** button is chosen to renumber the items in the parts list. If the parts list has some items that are improperly numbered, they will be numbered according to their original numbering.

Save Item Overrides to BOM

If you change the number of items in the **Item** column of the part list, then you need to choose this button to save the changes that you have made in the parts list to the assembly BOM.

Member Selection

This button will be available only when you edit the parts list of an iAssembly. On choosing this button, the **Member Selection** dialog box will be displayed that allows you to select the members to be included in the parts list.

Adding/Removing Custom Parts To add a custom part row, move the cursor over the gray color button on the extreme left of the part list shown in the **Parts List** dialog box; the cursor will be replaced by a small arrow pointing in the direction of the row. Next, right-click and choose the **Insert Custom Part** option from the shortcut menu; a new custom part row will be added.

To delete a custom part row, move the cursor over the gray color button on the extreme left of the custom row; the cursor will be replaced by a small arrow pointing in the direction of the row. Now, press the left mouse button. The custom row will be selected and highlighted in black color. Right-click on the selected row and choose **Remove Custom Part**; the custom part row will be removed.

Shortcut Menu Options

In addition to using buttons, the parts list can also be edited using the options available in the shortcut menu. To do so, right click on a column head; the shortcut menu will be displayed as shown in Figure 12-13. Most of the options in this shortcut menu are similar to those in the **Parts List** dialog box. The remaining options are discussed next.




Figure 12-13 Shortcut menu displayed by right-clicking on a column heading

Format Column

This option is used to modify the format of the columns in the parts list. When you choose this option, the **Format Column** dialog box will be displayed. You can use the **Column Format** tab of this dialog box to modify the justification and heading of the selected column. You can also modify the units formatting using this tab. You can use the **Substitution** tab of the **Format Column** dialog box to substitute the value of a selected field with that of the other selected field.

Column Width

This option is used to modify the width of the column. When you choose this option, the **Column Width** dialog box will be displayed. This dialog box will be used to modify the width of the columns in the parts list.

SETTING THE STANDARD FOR THE PARTS LIST
YOU CAN SET THE STANDARD FOR THE PARTS LIST USING THE **STYLE AND STANDARD EDITOR [LIBRARY - READ ONLY]** DIALOG BOX. THIS DIALOG BOX IS INVOKED WHEN YOU CHOOSE THE **STYLES EDITOR** TOOL FROM THE **STYLES AND STANDARDS** PANEL OF THE **MANAGE** TAB OF THE **RIBBON**. AFTER INVOKING THIS DIALOG BOX, EXPAND THE **PARTS LIST** OPTION AND THEN SELECT THE REQUIRED PARTS LIST STANDARD FROM IT; THE OPTIONS RELATED TO THE SELECTED PARTS LIST STANDARD WILL BE DISPLAYED IN THE RIGHT PANE, AS SHOWN IN FIGURE 12-14. USING THESE OPTIONS, YOU CAN SET THE PARAMETERS RELATED TO THE PARTS LIST. AFTER MAKING THE NECESSARY MODIFICATIONS IN THE PARTS LIST STANDARDS, CHOOSE THE **SAVE** BUTTON. YOU WILL NOTICE THAT THE CHANGES ARE REFLECTED IN THE PARTS LIST ON THE SHEET.




Figure 12-14 The *Style and Standard Editor [Library - Read Only]* dialog box with the parts list options

ADDING BALLOONS TO ASSEMBLY DRAWING VIEWS WHENEVER YOU ADD THE PARTS LIST TO THE ASSEMBLY DRAWING VIEWS, ALL COMPONENTS IN THE ASSEMBLY ARE LISTED IN THE PARTS LIST IN A TABULAR FORM. YOU WILL NOTICE THAT EACH COMPONENT IN THE PARTS LIST IS ASSIGNED A UNIQUE NUMBER. AS A RESULT, IF AN ASSEMBLY HAS TEN COMPONENTS, ALL OF THEM WILL BE LISTED IN THE PARTS LIST WITH A DIFFERENT SERIAL NUMBER ASSIGNED TO THEM. HOWEVER, IN THE DRAWING VIEWS, THERE IS NO REFERENCE


ABOUT THESE COMPONENTS. THEREFORE, IF YOU ARE NOT FAMILIAR WITH THE NAMES OF THE COMPONENTS, IT IS DIFFICULT TO RECOGNIZE THEM IN THE DRAWING VIEW. TO AVOID THIS CONFUSION, AUTODESK INVENTOR ALLOWS YOU TO ADD CALLOUTS, CALLED BALLOONS, TO THE COMPONENTS IN THE DRAWING VIEW. THESE CALLOUTS ARE BASED ON THE SERIAL NUMBER OF THE COMPONENTS IN THE PARTS LIST. IF THE COMPONENT IS ASSIGNED SERIAL NUMBER 1 IN THE PARTS LIST, THE CALLOUT WILL ALSO SHOW NUMBER 1. BALLOONS MAKE IT CONVENIENT TO RELATE THE COMPONENTS IN THE PARTS LIST TO THOSE IN THE DRAWING VIEW. YOU CAN ADD BALLOONS TO THE SELECTED COMPONENTS MANUALLY OR AUTOMATICALLY. THE METHODS OF ADDING BALLOONS ARE DISCUSSED NEXT.

Adding Balloons to Selected Components Ribbon:

Annotate > Table > Balloon drop-down > Balloon You can add balloons to the selected components in a drawing view by using the **Balloon** tool, see Figure 12-15. To do so, you need to invoke the **Balloon** tool. After invoking this tool, move the cursor over one of the edges of the component to which you want to add the balloon; the

component will be highlighted in red. Also, a plus sign (+) will be displayed on the right of the cursor. Select the edge and move the cursor away from the component; one end of the balloon will be attached to the component and the other end will be attached to the cursor. Specify a point for placing the balloon and right-click to display the shortcut menu. In the shortcut menu, choose **Continue** to place a balloon. You will notice that a callout is added to the selected component and the name of the callout is the same as that in the parts list. Remember that you can add as many balloons as you want by selecting the edges of components.

Remember that if you have not created the parts list of the component(s) before invoking this tool, the **BOM Properties** dialog box will be invoked, as shown in Figure 12-16. This dialog box is used to define the source file and the BOM settings to create item number for balloons. The options in this dialog box are similar to those of the **Parts List** dialog box explained earlier in this chapter.



*Figure 12-15 Tools in the **Balloon** drop-down*




Figure 12-16 The **BOM Properties** dialog box

Note You can edit the balloon's properties by double clicking on it.

Adding Automatic Balloons Ribbon: Annotate > Table > Balloon drop-down > Auto Balloon You can also automatically add balloons to all components in a selected drawing view in a single attempt. To do so, choose the **Auto Balloon** tool from the **Table** panel in the **Annotate** tab, refer to Figure 12-15; the **Auto Balloon** dialog box will be displayed, as shown in Figure 12-17. The options in this dialog box are discussed next.




Figure 12-17 The Auto Balloon dialog box

Selection Area

This area provides the options to select the view and the components to which the balloons will be added. When you invoke the **Auto Balloon** dialog box, the **Select View Set** button in this area will be chosen automatically and you will be prompted to select the view to add balloons. As soon as you select the view, the **Add / Remove Components** button will be chosen and you will be prompted to select the components for ballooning. You can use window or crossing selection methods to select multiple components. The **Ignore Multiple Instances** check box is selected by default because of which multiple instances of the same component are not ballooned.

Placement Area

The options in the **Placement** area are automatically enabled as soon as you select the components to be ballooned. Using the options in this area, you can specify whether the balloons should be placed along a horizontal or a vertical line, or around the view. The distance between the balloons can be set using the **Offset Spacing** edit box in this area. After selecting the option to place the balloon, choose the **Select Placement** button in this area; the preview of the balloons will be displayed and you will be prompted to select the balloon placement. If you are not satisfied with the orientations of the balloons after placing them, you can select any other option from the **Auto Balloon** dialog box. You can also choose the **Select Placement** button and place the balloons again.

BOM Settings Area

The options in this area are similar to those mentioned in the **Parts List** dialog box.

Style overrides Area

The options in this area are used to override the default balloon styles. To override the style, select the **Balloon Shape** check box and then select the required balloon shape. If the current drawing document has some sketch symbols, you can override them also by choosing the **User-Defined Symbol** button. When you choose this button, the drop-down list in this area becomes available and you can select the required sketch symbol.

To create a user-defined symbol expand the **Drawing Resources** folder. Right-click on the **Sketched Symbols** in the browser bar; a shortcut menu will be displayed. Choose **Define New Symbol** from it; the sketching environment will be invoked. Create a symbol using a sketch tool and then choose **Finish Sketch**; the **Sketched Symbols** dialog box will be displayed. Specify a name for the symbol in the **Name** edit box and click on the **Save** button. The name of the created symbols will be displayed in the browser bar.

After placing the balloons, choose **OK** from the **Auto Balloon** dialog box. Figure 12-18 shows a drawing sheet with the parts list and balloons added to the components in the drawing view.




Figure 12-18 Drawing sheet with the parts list and balloons

Tip. 1. You can modify the styles of balloons using the **Style and Standard Editor [Library - Read Only]** dialog box. Invoke this dialog box and then expand the **Balloon** option. Now, select the desired balloon style and modify its parameters from the **Balloon Style** area in the right pane of the dialog box. Save the style before you exit.

2. Balloons use the default styles for arrowheads and text. Therefore, to modify these styles, you need to modify the respective sub-styles from the **Sub-styles** area in the right pane of the **Style and Standard Editor [Library - Read Only]** dialog box when the balloon options are displayed. After setting the sub-styles, you can choose the **Back** button to switch back to previous pane.

ADDING TEXT TO A DRAWING SHEET
AUTODESK INVENTOR ALLOWS YOU TO ADD
USER-DEFINED TEXT TO A DRAWING SHEET.
DEPENDING UPON YOUR REQUIREMENT, YOU
CAN ADD MULTILINE TEXT WITH OR WITHOUT
A LEADER. THE METHODS OF ADDING BOTH
TYPES OF TEXT ARE DISCUSSED NEXT.

Adding Multiline Text without a Leader Ribbon:
Annotate > Text > Text You can add multiline text without a leader using the **Text** tool. On invoking this tool, you will be prompted to specify the location of the text or specify a rectangle by dragging the mouse to define the bounding box of the text. After you specify the location of the text or the bounding box of the text, the **Format Text** dialog box will be displayed, as shown in Figure 12-19. Enter text in the text box of this dialog box.

Text > Leader Text A text with a leader is generally added to the entities to which you want to point and add some information. You can add the text with a leader using the **Leader Text** tool. After invoking this tool, select the entity to which you want to add the leader text. As you move the cursor close to an entity, it will be highlighted in red. Also, the symbol of the coincident constraint will be attached to the cursor. This symbol indicates that the coincident constraint will be added between the selected entity and the arrowhead of the leader. After selecting the entity, move the cursor away and define the second vertex of the leader. You can define as many vertices as you want in the leader line. Once you have defined the leader line, right-click to display the shortcut menu and choose **Continue**; the **Format Text** dialog box will be displayed. This dialog box is similar to the one that is displayed when you invoke the **Text** tool. You can enter the text in this dialog box and then choose **OK**. The leader text will be added to the drawing sheet. Figure 12-20 shows a drawing sheet after adding text with and without a leader.




Figure 12-20 Drawing sheet after adding text with and without a leader

Note To add a center mark to a circle, choose the **Center Mark** tool from the **Symbols** panel of the **Annotate** tab in the **Ribbon** and then select the circle.

TUTORIALS

Tutorial 1

In this tutorial, you will generate the top view, front view, right-side view, and isometric view of the model created in Exercise 1 of Chapter 5. You will use the ANSI mm standard drawing sheet of A2 size. Dimension the drawing views, as shown in Figure 12-21. You will create a new dimension style with the name **Custom** for dimensioning the drawing view. This dimension style has the following specifications: **(Expected time: 30 min)**

Dimension Units: **mm** Linear Precision: **0**

Text Size: **5 mm** Terminator Length: **5 mm** Terminator Width: **2 mm**




Figure 12-21 The dimensioned drawing views to be generated for Tutorial 1

The following steps are required to complete this tutorial:

- Copy the model of Exercise 1 of Chapter 5 to the current folder and then start a new ANSI mm standard drawing file.
- Create a new dimension style with the name **Custom** and modify the parameters as given in the tutorial description.

- c. Generate the required drawing views.
- d. Retrieve the model dimensions in the drawing views. Drag dimensions so that they are displayed as desired.

Copying the Model to the Current Folder As mentioned in the previous chapter, you need to copy the model whose drawing views have to be generated to the current folder.

1. Create a folder with the name *c12* at the location *C:\Inventor_2016*.
2. Copy the file *Exercise1.ipt* from *C:\Inventor_2016\c05* to the *c12* folder and then rename it *Tutorial1.ipt*.

Starting a New Drawing File As mentioned in the tutorial description, you need to start a new ANSI mm standard drawing sheet for generating drawing views.

1. Choose the **New** tool to invoke the **Create New File** dialog box. Next, choose the **Metric** tab and double-click on the **ANSI (mm).idw** option; the default ANSI mm standard drawing sheet is displayed.
2. Right-click on **Sheet:1** in the **Browser Bar** and then choose **Edit Sheet** from the shortcut menu to invoke the **Edit Sheet** dialog box.
3. Select **A2** from the **Size** drop-down list and choose **OK** to close the **Edit Sheet** dialog box.

Creating the Dimension Style As mentioned in the tutorial description, you need to create a new dimension style with the defined settings. You will create the new dimension style, taking the ANSI mm dimension style as the base style.

1. Choose the **Styles Editor** tool from the **Styles and Standards** panel of the **Manage** tab in the **Ribbon**; the **Style and Standard Editor [Library - Read Only]** dialog box is displayed.

2. Select **Local Styles** from the **Filter Styles** drop-down list at the upper right corner of the dialog box, if not already been selected.
3. Click on the plus sign (+) located on the left of the **Dimension** in the left pane of the dialog box to display the available local dimension styles.
4. Select **Default - mm (ANSI)** from the list; the parameters related to this dimension style are displayed in various tabs at the right pane of this dialog box. Select **0** from the **Precision** drop-down list in the **Linear** area of the **Units** tab. The precision for a linear dimension is forced to 0. This means no digit will be displayed after decimal in dimensions. Then, choose the **New** button; a message box is displayed. Choose the **Yes** button from it. Then, the **New Local Style** dialog box is displayed. Enter **Custom** as the name of the new dimension style in the **New Local Style** dialog box. Next, choose **OK**; the dialog box is closed and a new dimension style is created with the name Custom.
5. Choose the **Text** tab to display the text options. Next, choose the **Vertical Dimension** button under the Linear in the **Orientation** area to display a flyout and then choose the **Inline - Horizontal** button from this flyout. This forces the text of the vertical dimension to be placed horizontally.
6. Similarly, choose the **Aligned Dimension** button to display a flyout and then choose the **Inline - Horizontal** button from this flyout; the text of the aligned dimensions is also placed horizontally.
7. Choose the **Save** button to save the changes made in the dimension style.
8. Now, choose the **Edit Text Style** button on the right of the **Primary Text Style** drop-down list to display the text parameters.
9. Enter **5** in the **Text Height** edit box in the **Character Formatting** area and press ENTER.
10. Choose the **Save** button and then the **Back** button to redisplay the dimension style parameters.

11. Choose the **Display** tab to set attributes for terminators of dimensions. In the **Terminator** area, enter **5** as the value of size in the **Size (X)** edit box and enter **2** as the value of height in the **Height (Y)** edit box. Choose **Save** to save the changes made in the dimension style and then choose **Done** to exit the dialog box.

Generating the Drawing Views In this tutorial, you need to generate four drawing views. The base view is the top view and the remaining views are the projected views. The front view is generated by using the top view as the parent view, and the right-side view and the isometric view are generated by using the front view as the parent view. Note that while generating drawing views, dimensions are not displayed. They are displayed only after generating drawing views.

1. Using the **Base** tool in the **Create** panel of the **Place Views** tab, generate the top view and then the front view of the *Tutorial1* part file that you have copied at the beginning of this tutorial. The scale of the views is 1.5. Place the top view close to the top left corner of the drawing sheet and the front view below the top view using ViewCube.
2. Taking the front view as the parent view, generate the right-side view and the isometric view. Modify the scale of the isometric view to **1**, see Figure 12-22.




Figure 12-22 Drawing sheet after generating the drawing views

- Retrieving the Model Dimensions
1. Move the cursor over the top view and right-click when the dotted rectangle is displayed; a shortcut menu is displayed.
 2. Choose **Retrieve Dimensions** from the Marking Menu; the **Retrieve Dimensions** dialog box is displayed.
 3. Select the **Select Parts** radio button in the **Select Source** area and then select the part in the top view; dimensions are displayed.
 4. Choose the **Select Dimensions** button from the **Retrieve Dimensions** dialog box and then drag the cursor to select all the dimensions to be retained. Next, choose the **Apply** button; the selected dimensions in the top view are retrieved and the **Select View** button is automatically chosen in the **Retrieve Dimensions** dialog box.

Figure 12-23 Drawing sheet after adding the dimensions

9. Save the file with the name *Tutorial1.idw* at the location *C:\Inventor_2016\c12* and then close the file.

Tutorial 2

In this tutorial, you will open the drawing views of the Double Bearing assembly generated in Exercise 1 of the *c11* folder. Note that in Exercise 1 of the *c11* folder, the drawing views were generated with positional representation. But, in this tutorial, you will create the parts list of the drawing views without positional representation. After opening the drawing views, you will add the parts list and balloons to components. Note that you will add balloons to the isometric view of the sectioned front view. The final parts list should appear as shown in Figure 12-24. **(Expected time: 45 min)**

Parts List			
ITEM	QTY	NAME	DESCRIPTION
1	1	Base	Bronze
2	1	Cap	Steel
3	2	Bushing	Steel
4	6	Bolt	.50-13UNC X 4.00

Figure 12-24 Parts list for Tutorial 2

The following steps are required to complete this tutorial:

- a. Copy the *Double Bearing* folder from the *C:\Inventor_2016\c12* folder to the current folder.
- b. Open the *Exercise1.idw* file in this folder.
- c. Place the default parts list by using the **Parts List** tool. Use the isometric view of the sectioned front view for placing the parts list.
- d. Modify the parts list such that it appears as the one shown in Figure 12-24.
- e. Add balloons to the components in the isometric view by using the **Balloon** tool.

Copying the Double Bearing Folder to the Current Folder 1. Copy the *Double Bearing* folder from *C:\Inventor_2016\c11* to the current folder.

2. Open the *Exercise1.idw* file from the location *C:\Inventor_2016\c12*.

The drawing file is opened with the top view, sectioned front view, and isometric view generated in Exercise 1 of Chapter 11.

Note To complete this tutorial, you must delete the positional representation of view-2 (isometric view) from the **Browser Bar**. To do so, select the positional representation from **Browser Bar** and right click on it. Then choose the **Delete** option from the shortcut menu displayed. Next, choose the **OK** button. You will notice that the position representation is deleted from the graphics window as well as **Browser Bar**.

Placing the Parts List As mentioned earlier, the parts list is placed using the **Parts List** tool. But, when you place the parts list, the data will be listed in it using the default parameters. For example, the fields under the **DESCRIPTION** column do not display any data. You need to modify the parts list after placing it so that it appears as the one shown in Figure 12-24.

1. Choose the **Parts List** tool from the **Table** panel of the **Annotate** tab; the **Parts List** dialog box is displayed.

As mentioned earlier, the parts list can be placed taking the reference of a drawing view. It is recommended that the drawing view that is used as a reference for placing the parts list should have all components. On doing so, all components are listed in the parts list.

2. Select the isometric view as the reference view for placing the parts list.

3. Accept the other default options in this dialog box and choose the **OK** button to exit it.

On exiting the dialog box, a rectangle attached to the cursor is displayed on the screen. This rectangle is the parts list that will be placed at the specified point.

- Specify the location of the parts list at the lower right corner of the sheet above the title block. The sheet with the default parts list is shown in Figure 12-25.




Figure 12-25 Drawing sheet with the default parts list

Modifying the Parts List When you place a parts list in the drawing views, it is displayed in the drawing sheet and in the **Browser Bar**. You need to modify the parts list by changing the heading **PART NUMBER** to **NAME**. Also, you need to enter data in the fields below the **DESCRIPTION** column and center-align the data in this column.

- Double-click on the parts list in the drawing sheet; the **Parts List** dialog box is displayed.
- Click on the first field below the **DESCRIPTION** column and type **Bronze**.

3. Similarly, click on the remaining fields in the **DESCRIPTION** column and enter description about the remaining components. For more information about the data to be entered, refer to Figure 12-24.

By default, the data in the **DESCRIPTION** column is left-aligned. You need to modify the alignment and make the text center-aligned.

4. Move the cursor over the heading **DESCRIPTION**. You will notice that the cursor is replaced with an arrow pointing downward.
5. Right-click and then choose **Format Column** from the shortcut menu; the **Format Column : DESCRIPTION** dialog box is displayed.
6. Choose the **Center** button on the right of **Value** in the **Justification** area to center-align the data in the fields below the **DESCRIPTION** heading. Choose **OK** to exit this dialog box.

You will notice that the data in the selected field is center-aligned.

7. Right-click on the **DESCRIPTION** heading again and then choose the **Column Width** option from the shortcut menu. Enter **60** in the **Column Width** edit box and choose **OK**. This increases the width of the fields below the **DESCRIPTION** heading.

By default, the heading of the column that displays the name of the components is **PART NUMBER**. You need to modify this heading to **NAME**.

8. Move the cursor over the heading **PART NUMBER** and right-click when the cursor is replaced with an arrow. Next, choose **Format Column** from the shortcut menu; the **Format Column : PART NUMBER** dialog box is displayed.
9. Enter **NAME** in the **Heading** edit box and choose **OK** to exit the **Format Column : PART NUMBER** dialog box.
10. Next, choose the **OK** button to exit the **Parts List** dialog box. The sheet after

editing the parts list is shown in Figure 12-26.




Figure 12-26 Drawing sheet after modifying the parts list

Adding Balloons to the Components As mentioned earlier, balloons are the callouts that are attached to the components in the drawing view so that they can be referred to in the parts list. These balloons are based on the item numbers in the parts list. You can add balloons using the **Balloon** tool or the **Auto Balloon** tool. In this tutorial, balloons are added using the **Balloon** tool.

Before you add balloons, you need to set the parameters related to them.

1. Invoke the **Style and Standard Editor [Library - Read Only]** dialog box from the **Style and Standard** panel of the **Manage** tab and then expand the **Balloon** option in the left pane.
2. Select the **Balloon (JIS)** option from the left pane; the parameters related to

this balloon standard are displayed in the right pane of the dialog box.

3. Choose the **Edit Leader Style** button on the right of the **Leader Style** drop-down list.
4. Select the **Filled** option from the **Arrowhead** drop-down list in the **Terminator** area.
5. Enter **6** in the **Size (X)** edit box and **2** in the **Height (Y)** edit box in the **Terminator** area. Save the changes and then exit the dialog box.
6. Choose the **Balloon** tool from **Annotate > Table > Balloon** drop-down; you are prompted to select a component. Move the cursor over one of the edges of the Bolt at the upper left corner of the assembly in the isometric view; the component is highlighted and a plus sign is displayed on the left of the cursor.
7. Select the bolt; the start point of the balloon is attached to the selected edge of the bolt and the other end of the balloon is attached to the cursor.

*Tip. If you have selected a wrong component for adding the balloon, you can deselect it from the current selection set before choosing **Continue** from the shortcut menu. To do so, right-click and then choose **Back** from the shortcut menu.*

8. Specify the location of the other end of the balloon above the view, refer to Figure 12-27.




Figure 12-27 Drawing sheet after adding balloons

9. Now, right-click and then choose **Continue** from the shortcut menu; a balloon is created and the number 4 is displayed inside the circle. Note that number 4 corresponds to the Bolt in the parts list.
10. Next, move the cursor over the circular edge of the Bushing, which is not sectioned in the isometric view. Select it when it is highlighted; one end of the balloon is attached to the edge.
11. Specify the location of the other end of the balloon on the left of the view, refer to Figure 12-27. Right-click to display the shortcut menu and then choose **Continue** to place the balloon.
12. Similarly, add balloons to the Base and the Cap, refer to Figure 12-27.
13. After placing balloons, right-click to display the shortcut menu. Choose **Cancel [ESC]** from it to exit this tool. The drawing sheet after adding the parts list and balloons is shown in Figure 12-27.

Tip. If you double-click on the parts list after adding balloons to components, you will notice that the symbols of the balloon is displayed in front of all components in the **Parts List** dialog box. These symbols suggest that the balloons corresponding to the components are added to the drawing sheet.

To change the arrowhead of a balloon, right-click on it and then choose **Edit Arrowhead**; the **Change Arrowhead** dialog box will be displayed with a drop-down list. Now, you can select the required arrowhead style from this drop-down list.

14. Save the file with the name *Tutorial2.idw* at the location *C:\Inventor_2016\c12\Double Bearing* and then close the file.

Note If the drawing file consists of more than one sheet, irrespective of which sheet was active while closing the file, the first sheet will be active when you open the drawing file next time.

Tutorial 3

In this tutorial, you will generate the drawing views of the Drill Press Vice assembly created in Exercise 1 of Chapter 9. The drawing views that need to be generated are shown in Figure 12-28. The parts list should appear as the one shown in Figure 12-29. You will use the ANSI mm standard sheet and the A3 size sheet for generating the drawing views. **(Expected time: 45 min)**

The following steps are required to complete this tutorial:

- a. Copy the *Drill Press Vice* folder from the *c09* folder to the *c12* folder. Start a new ANSI mm standard drawing file using the **Metric** tab of the **Create New File** dialog box.
- b. Modify the sheet to the A3 size sheet.
- c. Modify the drafting standards and generate the required drawing views.
- d. Add the parts list and modify it such that it resembles the one shown in Figure 12-29.
- e. Add balloons to components.




Figure 12-28 Drawing sheet for Tutorial 3

Parts List			
ITEM	QTY	NAME	MATERIAL
1	1	Base	Cast Iron
2	1	Safety Handle	Steel
3	2	Jaw Face	Steel
4	1	Movable Jaw	Steel
5	4	Cap Screw	Steel
6	1	Clamp Screw	Steel
7	1	Clamp Screw Handle	Steel
8	2	Handle Stop	Steel

Figure 12-29 Parts list to be added

Copying the Drill Press Vice Assembly 1. Copy the *Drill Press Vice*

folder from the location *C:\Inventor_2016\c09* to the *c12* folder.

Starting a New ANSI mm Standard File 1. Start a new metric file with ANSI mm standards.

The default ANSI mm standard drawing sheet is displayed. The size of the default sheet is D. You need to change this size to A3.

2. Right-click on **Sheet:1** in the **Browser Bar** and then choose **Edit Sheet** from the shortcut menu; the **Edit Sheet** dialog box is displayed.
3. Select **A3** from the **Size** drop-down list in the **Format** area. Choose **OK** to exit the dialog box; the sheet size changes to A3.

Generating the Drawing Views 1. Generate the top view of the Drill Press Vice assembly with a scale of 0.5. Break the view such that the length of the Safety Handle is reduced.

2. Generate the front and isometric views, as shown in Figure 12-30.




Figure 12-30 Drawing sheet after generating the drawing views

Placing the Parts List

1. Choose the **Parts List** tool from the **Table** panel of the **Annotate** tab; the **Parts List** dialog box is displayed.
2. Select the isometric view as the reference view for placing the parts list.
3. Accept the default options in this dialog box and choose **OK**; a rectangle, which is actually the parts list, gets attached to the cursor and you are prompted to specify the location of the parts list.
4. Place the parts list above the title block.

Modifying the Parts List

1. Double-click on the parts list to display the **Parts List** dialog box.

2. Right-click on the **DESCRIPTION** heading and then choose the **Format Column** option from the shortcut menu; the **Format Column : DESCRIPTION** dialog box is displayed. Enter **MATERIAL** as the heading of this column in the **Heading** edit box.
3. Choose the **Center** button on the right of **Value** in the **Justification** area to center-align the data in the **MATERIAL** column. Next, choose **OK** to exit this dialog box.
4. Similarly, right-click on the **PART NUMBER** column and modify its heading to **NAME** in the **Heading** edit box of the **Format Column : PART NUMBER** dialog box. Next, choose **OK** to exit the dialog box.
5. Enter data in the **MATERIAL** field, based on the parts list shown in Figure 12-29. Choose **OK** to exit the dialog box.

Adding Balloons to the Components The final step in this tutorial is to add balloons to the components in the isometric view. In this assembly, you will add balloons using the **Balloon** tool. Also, you need to drag balloons such that they are placed at proper locations in the drawing sheet. But before generating balloons, you need to modify

the balloon style.

1. Invoke the **Style and Standard Editor [Library - Read Only]** dialog box and then expand the **Balloon** option in the left pane.
2. Select the **Balloon (ANSI)** option; the parameters related to this balloon standard are displayed on the right pane of the dialog box.
3. Choose the **Edit Leader Style** button on the right of the **Leader Style** drop-down list to display the leader parameters.
4. Enter **4** in the **Size (X)** edit box and **1.5** in the **Height (Y)** edit box. Choose **Save** and then **Done** to exit this dialog box; the size of arrowheads in the balloons is increased.
5. Choose the **Balloon** tool from **Annotate > Table > Balloon** drop-down; you are prompted to select a component.
6. Move the cursor over one of the edges of the Base in the isometric view and click to add the balloon. Next, move the cursor away from the Base and place it below the component, refer to Figure 12-31. Right-click and then choose **Continue** from the shortcut menu.
7. Similarly, add balloons to the remaining components, refer to Figure 12-31.




Figure 12-31 Final drawing sheet for Tutorial 3

8. Drag balloons to a proper location in the drawing sheet. The final drawing sheet after adding the parts list and balloons is shown in Figure 12-31.
9. Save this file with the name *Tutorial3.idw* at the location *C:\Inventor_2016\c12\Drill Press Vice* and then close the file.

Self-Evaluation Test Answer the following questions and then compare them to those given at the end of this chapter:

1. You can add the parts list to the assembly drawing views using the _____ tool.
2. You can add a multiline text without a leader using the _____ tool.
3. When you open a new drawing file, only _____ sheet is available by default.

4. The _____ make it convenient to relate the components in the parts list to the components in the drawing views.
5. You can modify the size of a drawing sheet by using the _____ dialog box.
6. If you assemble some of the components in a separate assembly file and insert the subassembly in the current assembly file, the components of the subassembly are called _____ components.
7. The drafting standards of a drawing sheet can be modified using the **Style and Standard Editor [Library - Read Only]** dialog box. (T/F)
8. You can add parametric dimensions and reference dimensions to drawing views. (T/F)
9. You can modify an existing dimension style with a new dimension style. (T/F)
10. You cannot modify the default parts list. (T/F)

Review Questions Answer the following questions:

1. Which of the following tools is used to add text along with a leader?

(a) **Text** (b) **Parts List** (c) **Leader Text** (d) None of these
2. Which of the following tools is used to add center marks to circles in the drawing views?

(a) **Center Mark** (b) **Center Line** (c) **Center** (d) None of these
3. Which of the following options of the **Style and Standard Editor [Library - Read Only]** dialog box is used to create a new dimension style?

(a) **Dimension** (b) **Terminator** (c) **Common** (d) **Sheet**
4. Which of the following dialog boxes is used to create a new dimension style?

(a) **Dimension Style** (b) **Dimension Text** (c) **Drafting Standards** (d) **Style and Standard Editor [Library - Read Only]**
5. Which of the following dialog boxes is displayed when you double-click on the parts list to edit it?

(a) **Parts List** (b) **Edit Sheet** (c) **Edit Dimension** (d) None of these

6. You cannot control the line weight of lines in drawing views. (T/F)

7. Whenever you open an old drawing file that has more than one sheet, the sheet that was active last time is displayed as the active sheet. (T/F)

8. You can modify the size of the arrowheads of balloons using the **Style and Standards Editor [Library - Read Only]** dialog box. (T/F)

9. Autodesk Inventor allows you to add a user-defined text to a drawing sheet. (T/F)

10. You can edit text by double-clicking on it. (T/F)

Exercise

Exercise 1

Add the parts list and balloons to the drawing views of the Plummer Block assembly created in Tutorial 2 of Chapter 11, as shown in Figure 12-32. The parts list to be added is shown in Figure 12-33. **(Expected time: 45 min)**




Figure 12-32 Drawing sheet for Exercise 1

Figure 12-33 Parts list for Exercise 1

Parts List			
ITEM	QTY	NAME	MATERIAL
1	1	Casting	Cast Iron
2	1	Brass Bottom	Cast Iron
3	1	Brass Top	Gunmetal
4	1	Cap	Mild Steel
5	2	Bolt	Mild Steel
6	2	Nut	Mild Steel
7	2	Lock Nut	Mild Steel

Answers to Self-Evaluation Test **1. Parts List**, **2. Text**, **3. one**, **4. Balloons**, **5. Edit Sheet**, **6. second-level**, **7. T**, **8. T**, **9. T**, **10. F**

Chapter 13

Presentation Module

Learning Objectives

After completing this chapter, you will be able to:

- ***Create or restore an assembly view for creating presentations.***
- ***Tweak components and add trails to them.***
- ***Rotate views using the Precise View Rotation tool.***
- ***Animate a tweaked view.***

THE PRESENTATION MODULE

As mentioned earlier, Autodesk Inventor allows you to animate the assemblies created in the **Assembly** module. You can view some of the assemblies in motion by animating them. The animation of assemblies can be created in the **Presentation** module. You can use the **Presentation** module to create the exploded views of an assembly. An exploded view is the one in which the assembled components are moved to a defined distance from their original locations. To invoke the **Presentation** module, double-click on the **Standard (mm).ipn** file in the **Metric** template of the **Create New File** dialog box, see Figure 13-1.




Figure 13-1 Opening a new presentation file in the Metric template

Note

1. When you open a new presentation file, you will notice that only the **Create View** tool is available in the **Presentation** tab of the **Ribbon**. This is because first you need to create the presentation view of an assembly. Once the presentation view has been created, other tools will also become available in this module.
2. As mentioned earlier, all the modules of Autodesk Inventor are bidirectionally associative. Therefore, if you make any modification in an assembly or the components of an assembly, the changes will automatically reflect in the **Presentation** module.
3. You cannot modify an assembly or its components in the **Presentation** module.

The default screen appearance of the **Presentation** module is shown in Figure 13-2.




Figure 13-2 Default screen appearance of the **Presentation** module

CREATING THE PRESENTATION VIEW

Ribbon: Presentation > Create > Create View

The presentation view is used to animate




Figure 13-3 The Select Assembly dialog box

an assembly or create its exploded state. You can create presentation views by using the **Create View** tool. To do so, choose the **Create View** tool from the Create panel of the **Presentation** tab. On invoking this tool, the Select Assembly dialog box will be displayed, as shown in Figure 13-3. The options in this dialog box are discussed next.

Assembly Area

The options in the **Assembly** area are used to select the assembly for creating the presentation view. These options are discussed next.

File

The **File** drop-down list displays the assembly file selected for creating the presentation view. By default, this drop-down list displays **<select assembly document>** as no assembly file is selected. To select an assembly file, choose the **Open an existing file** button on the right of this drop-down list; the **Open** dialog box will be displayed, see Figure 13-4. You can use this dialog box to select the assembly file to be used for creating the presentation view. The selected assembly file and its location will be displayed in the **File** drop-down list.




Figure 13-4 The **Open** dialog box for selecting assembly file

*Tip. In the **Open** dialog box, the **Files of type** drop-down list displays only the **Assembly Files (.iam)** option because you can create the presentation views of the assembly files only.*

Options

The **Options** button will be activated only after selecting a file for creating a presentation. Choose this button; the **File Open Options** dialog box will be displayed. Using this dialog box, you can select the design view representation, positional representation, or level of detail representation to be used for generating the presentation view.

Explosion Method Area

As mentioned earlier, an exploded view is the one in which all the components of an assembly move to a specified distance from their original location in the assembly. The options in the **Explosion Method** area are used to select the method for exploding the selected assembly. These options are discussed next.

Auto Explode

Select the **Auto Explode** check box to automatically explode the assembly when the presentation view is to be created. After explosion, the components of the assembly will move in the direction of the constraint that is used to assemble them.

One Level

This button will be activated only when the **Auto Explode** check box is selected. It is used to automatically explode all components except the components of subassemblies down to one level in the hierarchy.

All Levels

This button will be activated only when the **Auto Explode** check box is selected. It is used to automatically explode all components of the assembly down to all levels in component hierarchy. It will explode subassemblies as well.

Distance

This edit box is used to specify the desired tweak distance for each component or part from a fixed component while creating an exploded view.

Default trails

Trails are defined as the parametric lines that display the path and direction of the assembled components. These lines can be used as a reference for determining the path and the direction in which the components are assembled. The **Default trails** drop-down list contains various options that are used to create trails for the components or parts of an assembly.

None

If you do not want to create a trail, select the **None** option.

All Components

This option is used to create trails for the components only.

All Parts

This option is used to create trails for the parts as well as subassemblies.

Single

This option is used to create a single trail for each tweak created on using the **Auto Explode** option.

Figure 13-5 shows the Drill Press Vice assembly exploded using the **Auto Explode** check box. The distance of explosion is 25 mm. This figure also shows the trails that define the path and direction of the assembled components.




Figure 13-5 Exploded assembly with trails

*Tip. If the explosion distance is large, the result of exploding the assemblies using the **Auto Explode** method may not be as desired. This is because with a large explosion distance, the components of an assembly will move to a large distance and start interfering with other components, refer to Figure 13-6. Therefore, if components need to be moved to a large distance, you should explode assemblies manually by dragging the green sphere of trails to a desired distance. To display the green sphere, move the cursor over a trail; a green sphere will be displayed at the start point of the trail. Now, you can drag the green sphere to the desired location.*

DEFINING UNITS IN PRESENTATION FILES

Autodesk Inventor allows you to define the units in the presentation (.ipn) file. By defining the units in the presentation file, you can control the distance and angle while specifying the tweak. To define the units in the presentation file, choose the **Document Settings** tool from the **Options** panel of the **Tools** tab; the **Document Settings** dialog box will be displayed. Choose the **Units** tab and specify the length and angle units.

TWEAKING COMPONENTS IN THE PRESENTATION VIEW

Ribbon: Presentation > Create > Tweak Components

As mentioned earlier, if the distance by which the components move in the automatically exploded view is large, the components may interfere with one another, refer to Figure 13-6. This figure shows an automatic exploded view, in which the components are moved to a distance of 42 mm. Notice the interference between the Movable Jaw and the Base, between the two Jaw Faces, and between the Clamp Screw and the Base. To avoid such interferences, it is recommended that if the components need to be exploded to a large distance, you should create the exploded view manually by tweaking the components. Tweaking is defined as the process of adjusting the position of the assembled components with respect to the other components of the assembly by transforming them in the specified direction. The components can be tweaked by using the **Tweak Component** tool. The tweaked components can also be animated thus creating the animation of the assemblies. On invoking the **Tweak Component** tool, a mini toolbar will be displayed along with a triad. Figure 13-7 shows the mini toolbar. The options in this mini toolbar are discussed next.




Figure 13-6 Exploded assembly displaying the interfering components

Move

The **Move** tool is used to create linear tweak of the selected parts or components. Whenever you select this tool, you will be prompted to select the origin point for the triad. Select the origin for the triad; the reference part will get selected for tweaking and the **Distance** edit box will be displayed in the graphics window. And, you will be prompted to select the part for tweaking. Select the part(s) for tweaking. Next, enter the tweak distance in the **Distance** edit box. The selected parts will get tweaked linearly along one of the selected direction arrow of the triad. When you select the **Local** option from the **Orientation** drop-down list to tweak the component, the direction arrow of the triad is placed relative to the coordinate system of the component and the component will be tweaked in the default selected direction of the triad. If you select the **World** option, the default orientation of the triad will be same as the axis system of Autodesk Inventor. Note that if you have to select a sub assembly for tweaking from an assembly then you need to select the **Component** option from the **Select** drop-down list in the mini toolbar. You can also delete the existing trail and add new trail by choosing the **Delete** and **Add** tools, respectively, from the mini toolbar.




Figure 13-7 The mini toolbar displayed on choosing the Tweak Component tool

Continuous Move

This tool works similar to the **Move** tool with the only difference that even after choosing the **Apply** button, the **Part** option remains activated and you can continue tweaking components. It is used to create sequence of linear tweaks.

Rotate

The **Rotate** tool is used to create a rotational tweak of selected parts or components about specified axis of angle manipulator. When this tool is chosen, the **Angle** edit box along with the angle manipulator is displayed in the graphics window. The angle of rotation can be entered in the **Angle** edit box. You can also rotate the component with the help of the angle manipulator and change the direction of rotational tweak by selecting its desired axis. Figure 13-8 shows the exploded view of the Drill Press Vice assembly with no interference among components.




Figure 13-8 Exploded view of the Drill Press Vice assembly with no interference among components

Tip. To modify the tweak values of components, click on the + sign located on the left of the name of the assembly in the **Browser Bar**; all the components in the assembly will be displayed. Click on the + sign located on the left of any component to display its tweak value. Select the tweak; an edit box will be displayed at the bottom of the **Browser Bar**. Modify the tweak value in this edit box.

ANIMATING AN ASSEMBLY

Ribbon: Presentation > Create > Animate

You can animate the tweaked or exploded assemblies by using the **Animate** tool. On invoking this tool, the **Animation** dialog box will be displayed, as shown in Figure 13-9. The options in this dialog box are discussed next.




Figure 13-9 The Animation dialog box

Parameters Area

The options in the **Parameters** area are used to set the interval of a tweak in the animation and the number of repetitions in it. These options are discussed next.

Interval

The **Interval** spinner is used to specify the interval between the tweaks in an animation. You can use the spinner to specify the value or enter the value directly.

Repetitions

The **Repetitions** edit box is used to enter the number of repetitions in an animation. You can specify the number of repetitions by setting the value of the **Repetitions** spinner directly or entering a value in this edit box.

Motion Area

The options in this area are used to set the motion of components or record the animation. These options will be activated only when you change the parameters in the **Parameters** area and then choose the **Apply** button. These options are discussed next.

Forward By Tweak

The **Forward By Tweak** button is chosen to force the tweaked components to move to the end value of the tweak distance. If you have tweaked the selected components to a linear distance of 25 mm in the Z direction, then on choosing this button, all the tweaked components will move forward by a complete tweak distance that is 25 mm in this case.

Forward By Interval

Whenever you create an animation, the total tweak distance or tweak angle is automatically divided into small intervals that are used as the animation sequence. The **Forward By Interval** button is chosen to force the tweaked components to move forward by one interval in the animation.

Reverse By Interval

The **Reverse By Interval** button is chosen to force the tweaked components to move backward by one interval in the animation.

Reverse By Tweak

The **Reverse By Tweak** button is chosen to force the tweaked components to move to the start value of the tweak distance. This button will work only if one cycle of the animation is completed or the components are moved to the end position by using the **Forward By Tweak** button.

Play Forward

The **Play Forward** button is chosen to play the animation of the assembly in the forward direction. The number of cycles in the animation will be based on the value in the **Repetitions** spinner of the **Parameter** area. If the number of repetitions is more than one, the components will be repositioned at the start point of the forward cycle after the first repetition is completed and the second repetition will again begin from the start point of animation.

Auto Reverse

If the **Auto Reverse** button is chosen, the animation of the assembly will be first played in the forward direction and then played automatically in the reverse direction. The number of forward and reverse cycles will depend upon the value in the **Repetitions** spinner. Note that in this case the forward and reverse movement of components is considered as one cycle.

*Tip. If the components have already moved to the end value of the tweak distance, then on choosing the **Auto Reverse** button, the components will animate in the reverse direction. In this case the number of repetitions will be one.*

Play Reverse

The **Play Reverse** button is used to play the animation of assembly in the backward direction. The number of cycles in the animation will be based on the value of **Repetitions** spinner in the **Parameters** area. If the number of repetitions is more than one, the components will be repositioned at the start point of the reverse cycle after the first repetition is completed and the second repetition will again begin from the end point of the animation.

Pause

The **Pause** button is used to temporarily stop the animation of the assembly.

Record

The **Record** button is used to store the animation of an assembly. You can record the animation in the *.wmv* or *.avi* format. On choosing this button, the **Save As** dialog box will be displayed, refer to Figure 13-10. This dialog box is used to specify the location and name of an animation file.




Figure 13-10 The Save As dialog box for saving animation

After specifying the location and name of the file, choose the **Save** button; the **WMV Export Properties** dialog box will be displayed, as shown in Figure 13-11. The options in this dialog box are used to set properties for saving the simulation of a file to the *.avi* or *.wmv* file format. The **Profile** drop-down list is used to specify the profile for the animation file. If you select the **Custom Profile** option from this drop-down list, the other options in this dialog box will be activated and the information about the selected profile can be seen in the **Profile Description** area. You can specify the bandwidth by using the options in the **Network Bandwidth** area of the **WMV Export Properties** dialog box. The options in the **Network Bandwidth** area are used to control the output and

quality of recording. The options in the **Image Size** area are used to specify the size of the recorded window. Set the required values in this dialog box and then choose the **OK** button.

Once the export properties are set, you can create the *.avi* file. Now, choose the **Play Forward**, **Play Reverse**, or **Auto Reverse** button to create the animation of the assembly. After the animation is recorded, choose this button again to exit the recording.

Note

If you select the .avi file format to save the animation of the presentation view for the first time, the **Video Compression** dialog box will be displayed instead of the **WMV Export Properties** dialog box. Accept the default values in this dialog box and choose **OK** to record the animation.




Figure 13-11 The **WMF Export Properties** dialog box

Minimize dialog during recording

The **Minimize dialog during recording** check box is selected to minimize the **Animation** dialog box while recording the animation. This is done because whatever appears on the graphics screen is also recorded in the *.avi* file while recording the animation. If the dialog box is not minimized, it will also be recorded and will appear in the recorded file.

Apply


Choose the **Apply** button to apply the changes made to the parameters in this dialog box.

Reset

Choose the **Reset** button to reset the parameters in the **Animation** dialog box to the default values.

More

This button is provided at the lower right corner of the **Animation** dialog box and is used to expand the **Animation** dialog box. The expanded dialog box displays the **Animation Sequence** area, refer to Figure 13-12. All tweaked components along with their tweak values are displayed in the list box in this area. Note that all the components that were selected together while tweaking are displayed as a single sequence. The buttons in this area are discussed next.



*Figure 13-12 The Animation Sequence area displayed on choosing the **More** button*

Move Up

The **Move Up** button is chosen to move the selected sequence up in the order in the list box. Remember that the sequence that is displayed on top in the list box will be played first in the animation.

Move Down

The **Move Down** button is chosen to move the selected sequence down in the order in the list box.

Group

The **Group** button is chosen to group various sequences in the animation. All the grouped sequences will show the same sequence number after grouping. To create a group, you need to press and hold the CTRL or SHIFT key, select the components to be grouped, and then choose the **Group** button.

*Tip. The **Group** button is chosen when you want to club different tweak sequences together. Grouping a rotational tweak and a linear tweak provides the effect of linear and rotational movements together.*

Ungroup

The **Ungroup** button is chosen to ungroup the grouped sequences in the animation.

Note

*After grouping or ungrouping sequences, choose the **Apply** button. If you do not choose it, the buttons to start the animation in the **Motion** area will not be available.*

ROTATING THE PRESENTATION VIEW PRECISELY

Ribbon: Presentation > Create > Precise View Rotation Autodesk Inventor allows you to rotate the presentation view precisely in the Presentation module. You can rotate a view by using the Precise View Rotation tool. On invoking this tool, the Incremental View Rotate dialog box will be displayed, see Figure 13-13. The options provided in this dialog box are discussed next.




Figure 13-13 The Incremental View Rotate dialog box

Increment

The **Increment** edit box is used to specify the angle through which the presentation view will be rotated.

Rotate Down

The **Rotate Down** button is chosen to rotate the presentation view in the downward direction. The presentation will be rotated through the value entered in the **Increment** edit box.

Rotate Up

The **Rotate Up** button is chosen to rotate the presentation view in the upward direction.

Rotate Left

The **Rotate Left** button is chosen to rotate the presentation view toward the left through the values specified in the **Increment** edit box.

Rotate Right

The **Rotate Right** button is chosen to rotate the presentation view toward the right through the values specified in the **Increment** edit box.

Roll Counter Clockwise

The **Roll Counter Clockwise** button is chosen to rotate the presentation view in the counterclockwise direction through the value specified in the **Increment** edit box.

Roll Clockwise

The **Roll Clockwise** button is chosen to rotate the presentation view in the clockwise direction through the value specified in the **Increment** edit box.

Reset

The **Reset** button is chosen to reset the current view to the default view.

TUTORIALS

Tutorial 1

In this tutorial, you will explode the Plummer Block assembly saved in the *c09* folder and then create the animation of disassembling (exploding) and assembling (unexploding) of the assembly. The exploded state of the Plummer Block assembly is shown in Figure 13-14. **(Expected time: 45 min)**




Figure 13-14 Exploded view of the Plummer Block Assembly

The following steps are required to complete this tutorial:

- a. Copy the *Plummer Block* folder from the *c09* folder to the *c13* folder.
- b. Open a new metric presentation file and create a new presentation view by using the **Create View** tool, refer to Figure 13-15.
- c. Manually explode the assembly in four sequences. The first sequence will tweak the two Bolts and the second sequence will tweak the Cap, Lock Nuts, and Nuts. The third sequence will tweak the Lock Nuts. The final sequence will tweak the Nuts, refer to Figure 13-18.
- d. Invoke the **Animate** tool and then combine all the four sequences.
- e. Finally, animate the sequences by using the **Auto Reverse** button from the **Animation** dialog box.

Copying the Folder

The presentation view is generated by using the Plummer Block assembly.

Therefore, you need to copy the *Plummer Block* folder from the *c09* folder to the *c13* folder.

1. Create a folder with the name *c13* at the location *C:\Inventor_2016*.
2. Copy the *Plummer Block* folder from the *c09* folder to the *c13* folder.

Starting a New Presentation File

1. Invoke the **Create New File** dialog box and then choose the **Metric** tab from it.
2. Double-click on the **Standard (mm).ipn** option; a new presentation file is started.

Creating the Presentation View

When you open a new presentation file, only the **Create View** tool is available in the **Create** panel of the **Presentation** tab in the **Ribbon**.

1. Choose the **Create View** tool from the **Create** panel of the **Presentation** tab; the **Select Assembly** dialog box is displayed.
2. In this dialog box, choose the **Open an existing file** button on the right of the **File** drop-down list in the **Assembly** area; the **Open** dialog box is displayed.
3. Open the folder *Plummer Block* from the location *C:\Inventor_2016\c13*.

You will notice that only the *Plummer Block.iam* file is available in this folder because you can create the presentation view of an assembly file only.

4. Double-click on the *Plummer Block.iam* file to select the Plummer Block assembly for creating the presentation view; the **Open** dialog box is closed and the **File** drop-down list in the **Assembly** area of the **Select Assembly** dialog box displays the name and path of the selected assembly.
5. Accept the default options from the **Select Assembly** dialog box and choose the **OK** button.

The presentation view is created and the current view is changed automatically to the isometric view. The file after creating the presentation view is shown in Figure 13-15.

Note

If the presentation view is not the same as shown in Figure 13-15 then you can change the orientation of view using the ViewCube.




Figure 13-15 Presentation file after creating the presentation view

Tweaking the Components of the Assembly

Now, you need to explode the assembly or add tweaks to the components of the assembly by using the **Tweak Components** tool.

1. Choose the **Tweak Components** tool from the **Create** panel of the **Presentation** tab; a mini toolbar is displayed along with triad in the graphics window.
2. Choose the **Continuous** tool from the mini toolbar; you are prompted to select the origin of the triad.
3. Press the SHIFT key and select the vertical edge of the Casting to define origin of the triad, refer to Figure 13-16.

The triad is displayed at the selected edge with the direction arrows representing the coordinate system of the casting.

Note

While selecting a origin point, hold the SHIFT key and select the component to exclude the component from the selection set.




Figure 13-16 *Selecting the direction for the tweak*

4. Choose the **World** option from the **Orientation** drop-down list; the direction arrows of triad oriented along the world coordinate system.
5. Now, choose the **Part** tool from the mini toolbar, if it is not chosen; you are prompted to select the parts to be tweaked.
6. Select both the Bolts one by one to tweak from the portion where they extend out of the Lock Nuts.

The top faces of the Bolts are displayed with a blue outline indicating that the parts are selected and can be tweaked. Also, one of the direction arrows of triad gets activated indicating the tweak direction.

Make sure that the activated arrow is pointing along the axis of the Bolt.

Otherwise, select the required direction arrow of triad.

7. Enter **-50** in the **Distance** edit box to tweak the parts downward. Next, choose the **Apply** button in the mini toolbar.

The two Bolts move downward, see Figure 13-17. This is the first sequence of the tweak.

As the **Part** tool is still active, you are prompted again to select the parts to be tweaked. Also, notice that the two Bolts are still displayed with a blue outline. This indicates that the parts are still selected, and if you enter a tweak value in the edit box, the parts will be tweaked by the specified distance. Therefore, first you need to remove these parts from the selected set.




Figure 13-17 Assembly after tweaking the two Bolts

8. Press and hold the SHIFT key and click on the Bolts one by one. You will notice that the blue outline is not displayed on the Bolts.
9. Select the Cap, two Nuts, and two Lock Nuts; all the selected parts are displayed in a blue outline.

10. Enter **50** in the **Distance** edit box and then choose the **Apply** button.

The selected parts move upward by a distance of 50 mm. This is the second tweak sequence.

11. Next, press and hold the SHIFT key and click on the Cap and both Nuts one by one to remove them from the current selection set. Now, only the two Lock Nuts are displayed with a blue outline.

12. Enter **50** in the **Tweak Distance** edit box and choose the **Apply** button.

This is the third tweak sequence. You will notice that blue trails are created as you tweak the parts.

13. Choose the **Zoom All** button from the **Navigation Bar** on the right of the graphics window to increase the drawing display area. The complete exploded assembly is displayed in the graphics window.

14. Press and hold the SHIFT key and click on the two Lock Nuts one by one to remove them from the selection set. Next, release the SHIFT key and select the two Nuts.

You will notice that the Nuts are displayed with a blue outline.

15. Enter **25** in the **Tweak Distance** edit box and then choose the **Apply** button from the mini toolbar. Both the Nuts move upward by a distance of 25 mm and are placed between the Cap and the two Lock Nuts. This is the fourth and final tweak sequence.

16. Choose the **Cancel** button to exit the mini toolbar.

You will notice that the triad, which was displayed in the assembly, is removed from the drawing window. The assembly after creating four tweak sequences is shown in Figure 13-18.




Figure 13-18 Exploded assembly

Animating the Assembly

The next step after tweaking the assembly is to animate it. The animation will carry out the simulation of exploding and unexploding the assembly. Note that when you tweak the components, the assembly is exploded and the components move to the tweaked position. Therefore, the first cycle in the animation is to unexplode the assembly by moving the components back to their original assembled position and the second cycle is to explode the assembly by moving the components to the tweaked position.

1. Choose the **Animate** tool from the **Create** panel of the **Presentation** tab to display the **Animation** dialog box.
2. Next, choose the **More** button provided at the lower right corner of the dialog box to expand it.

You will notice that there are four sequences in the **Animation Sequence** area. If you animate the assembly now, the assembly will animate in four steps. These four steps are actually the four sequences displayed in the **Animation Sequence** area. Note that the next step will start only after the previous step has been completed. In order to animate the assembly such that all the sequences animate together, you need to select all the components of the assembly and group them.

3. Press and hold the SHIFT key and select all the sequences displayed in the **Animation Sequence** area.

All the sequences are displayed with a blue background. Also, only the **Group** button is activated in the **Animation Sequence** area.

4. Choose the **Group** button from the **Animation Sequence** area to group all the sequences together.

Now, all tweaks are grouped together as 1 under the **Sequence** column.

5. Choose the **Apply** button from the **Animation** dialog box to apply changes to the assembly.

6. Move the **Animation** dialog box to the left of the drawing window by

dragging its title bar such that it does not overlap with the assembly.

7. Choose the **Auto Reverse** button from the **Motion** area.

All the tweaked components in the animation move together to their original assembled position and then move back to the tweaked position.

8. Choose the **Cancel** button from the **Animation** dialog box to exit it. Save the presentation file with the name *Tutorial1.ipn* at the location given below.

C:\Inventor_2016\c13\Plummer Block

Tutorial 2

In this tutorial, you will animate the Drill Press Vice assembly. The animation consists of a rotational tweak and a linear tweak. Save the animation in an *.avi* file with the name *Drill Press Vice*. **(Expected time: 1 hr)**

The following steps are required to complete this tutorial:

- a. Copy the *Drill Press Vice* folder from the *c12* folder to the *c13* folder.
- b. Start a new metric presentation file and create the presentation view of the Drill Press Vice assembly by using the **Create View** tool.
- c. Tweak components by using the **Tweak Components** tool.
- d. Invoke the **Animation** dialog box and group sequences.
- e. Create the *.avi* file and store the animation in it.

Copying the Drill Press Vice Assembly

1. Copy the *Drill Press Vice* folder from the *c12* folder to the *c13* folder.

Starting a New Presentation File

1. Choose the **New** tool from the **Standard** toolbar to invoke the **Create New File** dialog box.
2. In this dialog box, choose the **Metric** tab and double-click on the **Standard (mm).ipn** option to start a new metric presentation file.

Creating the Presentation View

1. Choose the **Create View** tool from the **Create** panel of the **Presentation** tab to invoke the **Select Assembly** dialog box.
2. Choose the **Open an existing file** button on the right of the **File** drop-down list in the **Assembly** area to invoke the **Open** dialog box.
3. Browse to *C:\Inventor_2016\c13\Drill Press Vice*; the *Drill Press Vice.iam* file is displayed.
4. Double-click on the *Drill Press Vice.iam* file.

The assembly is selected and displayed along with its path in the **File** drop-down list in the **Assembly** area.

5. Accept the remaining default options and choose the **OK** button.

The presentation view is created and the current view is changed to the isometric view, see Figure 13-19.




Figure 13-19 Presentation file after creating the presentation view of the Drill Press Vice assembly

Tweaking the Components of the Assembly

In this assembly, you need to apply the rotational tweak to the Clamp Screw, Clamp Screw Handle, and two Handle Stops. Next, you need to apply the linear tweak to the above-mentioned components and also to the Movable Jaw, the Jaw Face assembled with the Movable Jaw, and the two Cap Screws used to assemble the Jaw Face and the Movable Jaw.

1. Choose the **Tweak Components** tool from the **Create** panel of the **Presentation** tab; a mini toolbar is displayed along with a triad. In this mini toolbar, choose the **Continuous Move** tool; you are prompted to select a new origin for the triad.
2. Move the cursor close to the cylindrical face of the head of the Clamp Screw, see Figure 13-20.




Figure 13-20 Defining the tweak direction on the head of the Clamp Screw

You will notice that the head of the Clamp Screw is displayed with a red outline and a triad is displayed on the component. Also, the direction arrow of the triad is oriented along the Z axis of the world coordinate system and displayed in dark brown if the **World** option is selected from the **Orientation** drop-down list, refer to Figure 13-20.

Note

*While selecting an origin point, hold the **SHIFT** key and select the component to exclude the component from the selection set.*

3. Press the **SHIFT** key and select the cylindrical face of the head of the Clamp Screw to set the origin point of the triad.

Note that the resultant animation will not be as required if the direction arrow of the triad does not coincide with the central axis of the Clamp Screw.

4. Select the Clamp Screw, Clamp Screw Handle, and two Handle Stops; the selected components are displayed in a blue outline. Now, select the direction arrow of triad which coincides with the central axis of the Clamp Screw.

5. Choose the **Rotate** tool from the mini toolbar.

On doing so, the angle manipulator with the **Angle** edit box is displayed in the graphics window. The angle manipulator is displayed on the selected face with three triangular arrows that control the rotation of a component about the world coordinate system axes.

6. Enter **720** in the **Angle** edit box and select the triangular arrow which is normal to the X axis of the world coordinate system. Next, choose the **Apply** button from the mini toolbar.

The rotational tweak is applied to the selected components. This is the first sequence of the tweak. Note that the effect of rotational tweak is not visible on the screen at this time. Also, you will notice that the **Rotate** tool is still active. So, you are again prompted to set the origin point for the triad.

Next, you need to apply the linear tweak to the components.

7. Select the **Continuous Move** tool; you are prompted to select the origin for the triad. Select the right face of the Movable Jaw to set the origin point of the triad; you are prompted to select the part to be tweaked. Select the Clamp Screw, Clamp Screw Handle, two Handle Stops and two Cap Screws which are used to fasten the Jaw Face with the Movable Jaw. Next, select the

direction arrow of triad which is along the axis of the clamp screw.

All the selected components are displayed in a blue outline.

8. Enter **25** in the **Distance** edit box in the mini toolbar and then choose the **Apply** button.

The selected components move to a distance of 25 mm along the axis of the clamp screw. This is the second sequence of the tweak.

9. Choose the **Cancel** button to exit the mini toolbar. Now, choose the **Zoom All** button from the **Navigation Bar** to increase the drawing display area and fit the assembly into the current view. The assembly after tweaking is shown in Figure 13-21.




Figure 13-21 Assembly after tweaking the components

Animating the Assembly

1. Choose the **Animate** tool from the **Create** panel of the **Presentation** tab to invoke the **Animation** dialog box.
2. Choose the **More** button provided at the lower right corner of the dialog box to expand the dialog box.

You will notice that two sets of sequences are displayed in the **Animation Sequence** area. You need to group these sequences to rotate and move the components simultaneously.

3. Press and hold the SHIFT key and select all the sequences from the **Animation Sequence** area; all the sequences are displayed in a blue background.
4. Choose the **Group** button to group all the sequences into a single sequence.
5. Choose the **Apply** button to apply changes to all the tweaked components.

It is recommended that before you store the animation in the *.avi* file, you should play it once to make sure the animation is correct.

6. Move the dialog box to the left on the screen such that it does not overlap the assembly. Now, choose the **Auto Reverse** button from the **Animation** dialog box to play the animation in forward and reverse directions.

You will notice that all the tweaked components are moving in forward direction while the Clamp Screw, Clamp Screw Handle, and two Handle Stops are rotating about the central axis of the Clamp Screw in the clockwise direction. This is because you have applied the rotational tweak to the Clamp Screw, Clamp Screw Handle, and two Handle Stops. After the forward cycle is completed, all the components move in reverse direction and the components to which the rotational tweak has been applied rotate in counterclockwise direction. This shows the effect of working of the Drill Press Vice assembly.

Now, you can store the animation of the assembly in the *.avi* file format. Before you store the animation in a *.avi* file, it is recommended that you increase the

interval of the sequence so that the .avi file be smooth.

7. Choose the **Cancel** button from the **Animation** dialog box to close it.
8. Choose the **Sequence View** option from the **View** drop-down in the **Browser Bar**. You will notice that the **Task1** and **Drill Press Vice.iam** sub nodes are displayed below the **Explosion1** node in the **Browser Bar**. Alternatively, click on the + sign located on the left of the **Explosion1** node to display them.
9. Right-click on **Task1** and then choose **Edit** from the shortcut menu displayed; the **Edit Task & Sequences** dialog box is displayed, see Figure 13-22.




Figure 13-22 The **Edit Task & Sequences** dialog box

*Tip. There is only one sequence named **Sequence1** in the drop-down list in the **Sequences** area. This is because you grouped the two sequences into a single sequence. If you invoke the **Edit Task & Sequences** dialog box before grouping the sequences, all the sequences that you have created will be displayed in the drop-down list.*

10. Enter **75** in the **Interval** edit box and then choose the **Apply** button. Next, choose **OK** to close this dialog box.
11. Invoke the **Animation** dialog box again and then choose the **Record** button from it; the **Save As** dialog box is displayed.

Browse to the *Drill Press Vice* folder, if it is not the default location.

12. Select **AVI Files (*.avi)** from the **Save as type** drop-down list. Enter **Drill Press Vice** as the name of the animation in the **File name** edit box and then choose the **Save** button. The animation file is saved with the name *Drill Press Vice.avi* in the folder *Drill Press Vice* at the location *C:\Inventor_2016\c13*.
13. As you choose the **Save** button in the **Save As** dialog box, the **Video Compression** dialog box is displayed. Accept the default options in this dialog box and choose **OK** to close it.
14. Make sure the **Minimize dialog during recording** check box is selected in the **Motion** area of the **Animation** dialog box. Now, choose the **Auto Reverse** button.

The assembly starts animating and the dialog box is minimized. After the animation is completed and the *.avi* file is created, the dialog box is restored on the screen.

The animation file is created and now you can view it by using the Windows Media Player.

15. Save the presentation file with the name *Tutorial2.ipn* at the following location and then close the file.

C:\Inventor_2016\c13\Drill Press Vice

Answer the following questions and then compare them to those given at the

end of this chapter:

1. The **Open** dialog box that is displayed while creating a design view can be used to select only the _____ files.
2. The animation of assemblies can be stored in the _____ or _____ format.
3. There are two types of tweaks: _____ and _____.
4. By choosing the _____ button in the **Motion** area of the **Animation** dialog box, you can animate assemblies in forward as well as in reverse direction.
5. _____ are defined as the parametric lines that display the path and direction of the assembled components.
6. The _____ button in the **Animation** dialog box is chosen to group different tweak sequences into a single sequence.
7. Autodesk Inventor allows you to explode assemblies in a special environment called the **Presentation** module. (T/F)
8. Presentation templates are available in the **Metric** tab of the **Create New File** dialog box for creating different presentations. (T/F)
9. If the explosion distance in the automatic explosion is large, components start interfering with each other. (T/F)
10. When you open a new presentation file, only the **Create View** tool will be available. (T/F)

Answer the following questions:

1. Which of the following tools is used to precisely rotate the presentation view in the **Presentation** module?

- (a) **Rotate View** (b) **Precise View**
(c) **Precise View Rotation** (d) None of these

2. Which of the following tweaks is used to rotate the selected components about a specified rotational axis?

- (a) **Linear** (b) **Circular**
(c) **Rotational** (d) None of these

3. Which of the following dialog boxes is used to explode assemblies?

- (a) **Tweak Component** (b) **Explode Component** (c) **Tweak Assemblies** (d) None of these

4. Which of the following check boxes in the **Animation** dialog box need to be selected to display trails in the exploded view?

- (a) **Trail** (b) **Trail On**
(c) **Display Trail** (d) None of these

5. You can modify the individual tweak values of components. (T/F)

6. You can modify the interval value of an animation. (T/F)

7. You cannot ungroup the sequences that have been grouped together. (T/F)

8. After grouping an animation, you need to choose the **Apply** button. (T/F)

9. The **.avi** files can be viewed in the Windows Media Player. (T/F)

10. You cannot move the triad without moving the components but can rotate it without rotating the components. (T/F)

Exercise 1

Create the animation of exploding and unexploding the Butterfly Valve assembly. The exploded view of the Butterfly Valve assembly is shown in Figure 13-23. **(Expected time: 1 hr)**




Figure 13-23 Exploded view of the Butterfly Valve assembly

Answers to Self-Evaluation Test

1. assembly, **2.** *.wmv*, *.avi*, **3.** transational, rotational, **4.** **Auto Reverse**, **5.** Trails,
6. **Group**, **7.** T, **8.** F, **9.** T, **10.** T

Chapter 14

Working with Special Design Tools

Learning Objectives

After completing this chapter, you will be able to:

- *Understand the concept of adaptivity and create adaptive parts.*
- *Define parameters for creating parts.*
- *Create standard and custom iPart factories.*
- *Place iParts using the custom and standard iPart factories.*
- *Create 3D Sketches.*
- *Understand hybrid surface-solid modeling.*

ADAPTIVE PARTS

Adaptive parts automatically update their adaptive features or driven dimensions based on the dimensions and constraints of the relative parts with which they are assembled. Note that while creating the adaptive parts or adaptive features, the corresponding sketch should be partially constrained. The missing dimension and adaptive features will then be modified based on the sizes, location of other components, and constraints applied between the components. You can remove the adaptivity of the components at any time and add the missing dimensions so that the parts do not change their size. To convert a feature or sketch into an adaptive feature, right-click on it in the **Browser Bar** and choose **Adaptive** from the shortcut menu displayed. Similarly, to convert a part into an adaptive part in the **Assembly** module, right-click on the part in the **Browser Bar** and choose **Adaptive** from the shortcut menu displayed. Two semicircular arrows pointing in counterclockwise direction will be displayed on the left of the adaptive part,

feature, or sketch in the **Browser Bar**. Remember that components originally created in other solid modeling tools and imported to the Inventor file cannot be converted into an adaptive part.

DEFINING PARAMETERS

Ribbon: Manage > Parameters > Parameters

As mentioned earlier, every dimension in Autodesk Inventor is assigned a unique name termed as parameter. When you specify the value for the dimension, the dimension parameter is equated in an expression with the value that you specified. Autodesk Inventor allows you to use parameters or expressions instead of entering value while dimensioning a sketch. These parameters or expressions can also be entered in the edit boxes of a dialog box while creating a feature. You can create a new parameter by defining it in terms of the other parameter in an expression. The new parameters can be created before or after creating the sketch. You can use the **Parameters** tool to create new parameters. However, you can use this tool to control the relative position of the component in an assembly besides controlling the shape and size of the feature. When you invoke this tool from the **Parameters** panel, the **Parameters** dialog box will be displayed, refer to Figure 14-1. This dialog box has two types of parameters that are discussed next.

Model Parameters

Model parameters are those that are automatically created when you apply dimensions to the entities or when you create a feature. The model parameters are displayed in a tabular form, as shown in Figure 14-1. The options in this table are discussed next.

Parameter Name

The **Parameter Name** column displays the names of parameters. To modify the name of a parameter, click on its field in the **Parameter Name** column. The field will change to an edit box and you can enter the new name in it. Note that you cannot duplicate the name of parameters. This means you cannot have two parameters with the same name.




Figure 14-1 The **Parameters** dialog box

Unit/Type

The **Unit/Type** column displays the unit of measuring the parameters. Note that you cannot modify the unit of a parameter.

Equation

The equations are mathematical expressions in which the parameters are equated with the algebraic or the trigonometric functions. Autodesk Inventor allows you to define the parameters using the existing parameters and equations. For example, to define a parameter d2, you can use the equation such as $d2 = (d0/2 + d1/2)$, where d0 and d1 are the existing parameters. However, in the d2 field of the **Equation** column, you will not enter “d2=”. All you need to enter is $(d0/2 + d1/2)$ as the equation. Since it is entered in the d2 field of the **Equation** column, Autodesk Inventor will automatically equate it with the d2 parameter.

You can also add tolerance to the parameter using the **Equation** column. To add tolerance, click on the field corresponding to the required parameter in the **Equation** column; the field changes into an edit box with an arrow on its right. Next, click on this arrow or right-click on the **Equation** field (edit box); a shortcut menu will be displayed. Choose **Tolerance** from this shortcut menu; the **Tolerance** dialog box will be displayed, as shown in Figure 14-2. You can set

the tolerance parameters using the options in this dialog box.




Figure 14-2 The Tolerance dialog box

Nominal Value

This column shows the resulting value of the equation and expressions entered in the equations column.

Tol.

The **Tol.** column is used to select the nominal, median, upper, or the lower tolerance size for the dimension. You can select the required tolerance size from the drop-down list that is displayed when you click on the field under the **Tol.** column.

Model Value

Generally, it is not possible for a component to be manufactured using the nominal values. Therefore, you need to assign some tolerance to the dimension. The **Model Value** column shows the actual value after assigning the tolerance. The value in this column depends on the tolerance assigned to the dimension by using the **Tolerance** dialog box.

Key

Select this check box to designate the selected parameter as the key parameter. These parameters are easy to identify. You will learn more about keys later in this chapter.

Export Parameter

The **Export Parameter** column displays the check boxes for each parameter. If you select the check box of a parameter, that parameter will be added to the custom properties and can be displayed in the parts list.

Comment

The **Comment** column is used to enter some information about the selected parameter. To enter a value, click on this field. The field is changed into a text box and you can enter the desired comment in it.

User Parameters

User parameters are the parameters that are defined by the user for specifying the dimensions of the entities and the features. To create a user-defined parameter, choose the **Add Numeric** button in the **Parameters** dialog box; a new row will be displayed in the **User Parameters** table. You can specify the new settings of the user-defined parameters in the table. Note that you can modify the units of the user-defined parameter. To modify the units, click on the field below the **Unit** column; the **Unit Type** dialog box will be displayed, as shown in Figure 14-3. You can select the desired units from this dialog box. In addition to the **Add Numeric** option, there are two more options that can be used to create user parameters. These options are **Add Text** and **Add True/False**. These options can be invoked by clicking on the down arrow located on the right of the **Add Numeric** button and then choosing the required option from the flyout. These options work in coordination with the iLogic features of Autodesk Inventor. The iLogic features will not be discussed here as

they are out of the scope of this textbook.




Figure 14-3 The **Unit Type** dialog box

Note

*The options in the **User Parameters** table are similar to those discussed in the **Model Parameters** table.*

Update

Choose this button to update the feature or the model when the parameters are changed.

Immediate Update

This check box is selected by default. As a result, the feature or the model is updated immediately when the parameters are changed. If you clear this check box, you need to choose the **Update** button whenever the parameters are

changed.

Purge Unused

Choose this button to purge the unused parameters of the model. When you choose this button, a list of all the unused parameters is displayed in a separate window. You can purge them in one operation.

Link

In addition to the model parameters and the user-defined parameters, Autodesk Inventor also allows you to create link parameters. The link parameters are created in a separate Microsoft Excel spreadsheet. Note that the model parameters and the user-defined parameters can be used only in the current file, whereas the link parameters can be used in as many number of files as you require. This is because the link parameters are external parameters that can be imported to any file. To import a link parameter, choose the **Link** button; the **Open** dialog box is displayed, as shown in Figure 14-4. You can specify the name and the location of the Microsoft Excel spreadsheet by using the **Open** dialog box.




Figure 14-4 The Open dialog box for selecting the spreadsheet

When you select the spreadsheet, its location and name are displayed in the dialog box and a new table is displayed. This table shows the parameters imported from the selected spreadsheet.

The following table shows a sample of the spreadsheet that can be created in order to be used as link parameters.

LEN	60
LEN1	30
WID	20
HT	15

Filter

On choosing this button, a flyout will be displayed. The options in this flyout are used to limit the number of parameters displayed in the **Parameters** dialog box. You can choose the **All** option from the flyout if you want all the parameters to be displayed. If you choose the **Key** option, only the parameters that have been assigned the keys will be displayed in the **Parameters** dialog box. But if you choose the **Non-Key** option, only the parameters that have not been assigned any key will be displayed. If you choose the **Renamed** option, only the parameters that have been renamed will be displayed. If you choose the **Equation** option, the parameters that have been defined using equations or the parameters that are used to define equations are displayed in the **Parameters** dialog box.

WORKING WITH IPARTS

While working on assemblies, you may need to create parts having identical designs but with different sizes, materials, or other variables. Autodesk Inventor allows you to create these parts and then use them with one or more variables. These parts are called as iParts. There is a special technique for creating parts at the places where “**collaborative engineering**” has been used. This special technique is called iPart factories. The iPart factories can be shared by the members in the collaborative engineering environment to create iParts. The properties and dimensions of an iPart factories are saved in a table and you can

use these dimensions to create an iPart in an assembly modeling environment.

Types of iPart Factories

In Autodesk Inventor, you can create two types of iPart factories. These are the Standard iPart factories and the Custom iPart factories. Both these types of iPart factories are discussed next.

Standard iPart Factories

The Standard iPart factories create iParts whose dimensions cannot be changed. This type of iPart factory is used to create standard parts. You can store these parts in the location of standard parts so that other members can also use them.

Custom iPart Factories

The Custom iPart factories create iParts with different dimensions. You can specify the dimension of the iPart while inserting it in the assembly modeling environment.

Creating iPart Factories

Ribbon: Manage > Author > Create iPart

The iPart factories are created using the standard parts. However, it is recommended that the dimensions of the standard parts should be defined in terms of the model or user-defined parameters using the **Parameters** dialog box. To create the iPart factories, create a standard part using the parameters and then choose the **Create iPart** tool from the **Author** panel of the **Manage** tab in the **Ribbon**; the **iPart Author** dialog box will be displayed. The options in this dialog box are discussed next.

Parameters Tab

The options in the **Parameters** tab (Figure 14-5) are used to select the parameters and dimensions to be included in the iPart factory. When you invoke this tool, the **Parameters** tab becomes active. This tab of the **iPart Author** dialog box is divided into three areas. These areas are discussed next.

Part Parameters Pane

The **Part Parameters** pane is on the left side in the **Parameters** tab. This pane lists all the parameters and dimensions in the current part.

Selected Parameters Pane

The **Selected Parameters** pane is on the right of the **Parameters** tab. This pane lists all the parameters included in the iPart factory. When you invoke the **iPart Author** dialog box, all the user-defined parameters in the current file appear on this pane automatically. You can remove a parameter from this pane by selecting it and then choosing the **Remove** (<<) button on the left of this pane. Once the selected parameter is removed from the iPart factory, you cannot modify the value related to this parameter when you create an iPart using this iPart factory. Similarly, you can add a parameter by selecting it from the **Part Parameters** pane and then choosing the **Add** (>>) button.




Figure 14-5 The Parameters tab of the iPart Author dialog box

Assigning Keys: By assigning a key to a parameter, you can recognize the values assigned to the parameter. Later on, you can change the attribute values of the parameters that have been assigned the keys. To assign a key to a parameter, click on the corresponding key of the parameter in the **Key** column; a key of numeric value 1 will be assigned to the parameter and the key of that parameter will turn blue. The keys of the remaining parameters

will be gray. To modify the numeric value of the key, click on the value; a flyout will be displayed. Select the required key value from the flyout.

Making a Parameter Column Custom: Making a parameter column custom allows you to change its value while creating the iPart. To create a standard iPart factory, do not make any parameter column custom. However, to create a custom iPart factory, you need to make at least one parameter custom. To make a parameter column custom, first make sure no key is assigned to it. Next, right-click on it to display the shortcut menu. Choose **Custom Parameter Column** from the shortcut menu that is displayed; the selected parameter is made custom and the current iPart factory is made the custom iPart factory. Whenever you create an iPart using this factory, you can change the value of the custom parameter. The custom parameter column is displayed in blue in the **iPart Table** below the two list boxes in the **iPart Author** dialog box.

iPart Table

The **iPart Table** is available below the two list boxes. By default, this table has only one row with the default values of the parameters. The number of columns depend on the number of parameters in the **Selected Parameters** list box. You can add rows to this table by right-clicking on any cell of the table and choosing **Insert Row** from the shortcut menu. A new row is added to the table. Each row in the **iPart Table** represents a separate iPart in the iPart factory. You can edit the value of the iPart parameter by clicking on its field. The new iPart created using this iPart factory will use the value that you specify.

Note

*You can customize particular cell of the **iPart Table** by right-clicking on it and choosing **Custom Parameter Cell** from the shortcut menu after assigning key.*

Properties Tab

The options in the **Properties** tab (Figure 14-6) are used to select the summary of the component, project properties, and physical properties. You can select a property from the **File Properties** pane on the left and add it to the **Selected Properties** pane on the right.




Figure 14-6 The **Properties** tab of the **iPart Author** dialog box

Suppression Tab

The options in the **Suppression** tab (Figure 14-7) are used to specify whether the selected features will be computed or suppressed while creating a part using the iPart factory.

If you want that a feature should be suppressed when you create a part using the iPart factory, select it from the **Model Features** pane and add it to the **Selected Features** pane. Next, right-click on it and choose **Custom Parameter Column** from the shortcut menu displayed. The selected feature will be made custom and you can now specify whether the feature will be computed or suppressed while creating an assembly using the iPart factory. If you are selecting the **Suppress** option for a feature, it will not appear in the model.




Figure 14-7 The Suppression tab of the iPart Author dialog box

iFeatures Tab

The options in the **iFeature** tab (Figure 14-8) are used to specify the table-driven iFeatures to be included in the iPart table. You can specify a unique iFeature row for each iPart row of the included iFeature. By using the iPart table, you can control the suppression status of the iFeature. The iFeatures will be discussed in detail in Chapter 17.




Figure 14-8 The *iFeatures* tab of the *iPart Author* dialog box

iMates Tab

The **iMates** tab (Figure 14-9) is used to select the iMates applied to the part that will be included in the iPart factory. iMates are created on the parts to be assembled. Creating iMates allows you to assemble parts automatically in the assembly environment. iMates will be discussed in detail in Chapter 17. The iMates will be displayed in the **Model iMates** pane if you have created them on the part. To include iMates in the iPart factory, select them from the **Model iMates** pane and add to the **Selected iMates** pane. The selected iMates will be added to the iPart factory.




Figure 14-9 The iMates tab of the iPart Author dialog box

Work Features Tab

The options in the **Work Features** tab (Figure 14-10) are used to add work features to the iPart factory. The work features of a component include work planes, work axes, and work points. These work features are displayed on the left pane of the **iPart Author** dialog box only when they are created in the part. You can turn on or off the visibility of work features by selecting the required check boxes from the **Object Visibility** drop-down in the **Visibility** panel of the **View** tab.

Threads Tab

The options in the **Threads** tab (Figure 14-11) are used to add the parameters related to threads in the iPart factory. The threads are displayed on the left pane in the **iPart Author** dialog box only if you have created them in the part. You can select threads parameters from the **Thread definition tree** and add them to the **Selected Thread** pane.




Figure 14-10 The Work Features tab of the iPart Author dialog box




Figure 14-11 The Threads tab of the iPart Author dialog box

Other Tab

The options in the **Other** tab (Figure 14-12) are used to add other parameters to iPart factories. Note that these parameters cannot control the size of the part created using the iPart factory.




Figure 14-12 The **Other** tab of the **iPart Author** dialog box

To add the other parameter, click on **Click here to add value** and then enter the value of the other parameter in the text box that appears in the **Other Parameters** pane. You will notice that the parameter that you add in the **Other Parameters** pane is also added to the **iPart Table**. You can modify the value of the individual cells by selecting each field of the new parameter in the **iPart Table**.

After setting the options in various tabs of the **iPart Author** dialog box, choose **OK** to exit the dialog box and to save the file. The saved file will act as the iPart factory to place the parts in the assembly files.

Note

*When you create an iPart factory, the **Table** item is added to the **Browser Bar**. If you click on the + sign located on the left of the **Table** item in the **Browser Bar**, the tree view will expand and the parameters in the iPart factory will be displayed.*

Procedure to Create Standard iPart

The procedure to create standard iPart is discussed next.

1. Create a component in the Part environment using the parameters.

2. Invoke the **iPart Author** dialog box by choosing the **Create iPart** tool from the **Author** panel of the **Manage** tab. By default, the **Parameters** tab is chosen in this dialog box. You can include iMates, work features, threads, and other customized properties in the part by using the tabs displayed in the **iPart Author** dialog box.
3. Select the required parameter from the left pane of the **iPart Author** dialog box and then choose the **Add (>>)** button; the selected parameter will be added to the right pane of the dialog box. Repeat the same procedure in other tabs of the **iPart Author** dialog box to add the required parameters to the right pane. You can also remove parameters from the right pane by first selecting them and then choosing the **Remove (<<)** button from the dialog box. Using different tabs in the **iPart Author** dialog box, you can control the suppression and visibility of the created features.
4. Next, assign keys to the parameters that you want to identify later. You can change the values of the parameters that have been assigned the keys. To assign a key to a parameter, click on its corresponding key in the **Key** column.
5. After assigning keys, you need to add the number of rows that is equal to the number of iParts you want to create in the **iPart Table**. Add the required number of rows in the **iPart Table** and then change the parameter value in the required parameter. Note that you need to change the parameter values of the parameters that have been assigned the keys. The size of other parameters will vary according to the expressions used in defining the parameters.
6. After adding the required number of rows in the **iPart Table**, you need to verify the table for errors. If there are any errors in the table, they will be highlighted in yellow. Rectify the error, if any, found in the table.
7. Next, save the table by choosing **OK** from the **iPart Author** dialog box and then exit the part file.

Procedure to Create Custom iPart

The procedure to create the custom iPart is similar to the procedure to create standard iPart. To create custom iPart, perform Step 1 through Step 5 from the

section *Procedure of Creating Standard iPart*. After adding the required number of rows in the iPart Table, right-click in **Member** column of the **iPart Table**; a shortcut menu will be displayed. Choose the **Custom Parameter Column** option from it. Now, you need to verify the table for errors. If there are any errors in the table, they will be highlighted in yellow. Click on the **Verify** button to rectify the error, if any. Now, save the table by choosing the **OK** button from the **iPart Author** dialog box and then exit the part file.

Inserting an iPart into an Assembly

You can insert an iPart into an assembly file using the **Place** tool. The number of iParts that can be inserted into the graphics window depends upon the number of rows added to the **iPart Table**. Depending on whether you select a standard iPart factory or custom iPart factory, the dialog box for placing the part will differ. The procedure for placing both these types of iPart factories is discussed next.

Placing Standard iParts in an Assembly

To place a part using the standard iPart factory, choose the **Place** tool from the **Component** panel of the **Assemble** tab; the **Place Component** dialog box will be displayed. Select the required standard iPart and choose the **Open** button from the **Place Component** dialog box; the **Place Standard iPart** dialog box will be displayed. The options in the three tabs of this dialog box are discussed next.

Keys Tab

The **Keys** tab (Figure 14-13) consists of the **Predefined values** pane that displays the name and value of the parameters that were assigned the keys in the **Selected Parameters** pane of the **iPart Author** dialog box. Note that because it is a standard iPart, you cannot modify the value of any of the parameters in this dialog box. However, if more than one rows were created in the **iPart Table**, you can select the standard values from the list of available values. This list is displayed when you click on one of the values and select the **All Values** check box.




Figure 14-13 The Keys tab of the Place Standard iPart dialog box

Tree Tab

The **Tree** tab (Figure 14-14) displays the name and values of the parameters in the form of a tree view in the **iPart Author** dialog box. You can click on the + sign on the left of each parameter to expand the tree view.




Figure 14-14 The Tree tab of the Place Standard iPart dialog box

Table Tab

The **Table** tab (Figure 14-15) displays the iPart table created in the **iPart Author** dialog box. As mentioned earlier, each row in this table represents a part. Also, different fields in the rows can be set to different values in the **iPart Author** dialog box. As a result, you can select any row from this tab to insert the iPart. Depending on the value of the parameters defined for the selected row in the **iPart Author** dialog box, the part will be placed.

Placing Custom iParts in an Assembly

To place a part using the custom iPart factory, invoke the **Place** tool. Next, select

the custom iPart; the **Place Custom iPart** dialog box will be displayed. The options in the three tabs of this dialog box are discussed next.




Figure 14-15 The Table tab of the Place Standard iPart dialog box

Keys Tab

The **Keys** tab of the **Place Custom iPart** dialog box (Figure 14-16) has two panes. The pane on the left is the **Predefined values** pane and displays all the parameters that were not made custom in the **iPart Author** dialog box. Note that you cannot modify the values of the parameters available in this pane. The pane on the right is called the **Custom values** pane. It displays all the parameters that were made custom using the **iPart Author** dialog box. To modify the value of the parameter, click on the **Value** field of that parameter in the **Custom values** pane; the field will change to an edit box. Enter the new value in it. The part that will be placed using this iPart factory will have the specified value of the parameter.




Figure 14-16 The Keys tab of the Place Custom iPart dialog box

Tree Tab

The **Tree** tab (Figure 14-17) also has two panes. The left pane displays the name and values in the form of a tree view of the parameters that were assigned keys in the **iPart Author** dialog box. The right pane displays the parameters that were made custom using the **iPart Author** dialog box.




Figure 14-17 The **Tree** tab of the **Place Custom iPart** dialog box

Table Tab

The **Table** tab of the **Place Custom iPart** dialog box (Figure 14-18) is similar to that of the **Place Standard iPart** dialog box. It displays the iPart table that was created in the **iPart Author** dialog box. You can select the table to place the part based on the values in that table.




Figure 14-18 The **Table** tab of the **Place Custom iPart** dialog box

Changing the iParts in the Assembly File

If the iPart factory used to place the iPart in the assembly file has more than one row in the iPart table, you can replace the iPart with the other iPart defined in the rows. To change the iPart, right-click on **Table** under **iPart** in the **Browser Bar**; a shortcut menu will be displayed. Choose **Change Component** from the

shortcut menu; the **Place Standard iPart** dialog box or the **Place Custom iPart** dialog box will be displayed. Choose the **Table** tab and then select the row of the required iPart; the previous iPart will be replaced by the other iPart whose row you select.

CREATING 3D SKETCHES

Ribbon: 3D Model > Sketch drop-down > Start 3D Sketch **In earlier chapters, you have learned to create 2D sweeps by defining path in 2D space. In this chapter, you will learn to create a 3D sketch that can be used for creating sweep features in 3D environment, as shown in Figure 14-19.**

To create a 3D sketch, choose the **Start 3D Sketch** tool from the **Sketch** drop-down in the **Sketch** panel of the **3D Model** tab; the 3D sketching environment will be activated. Note that because a 3D sketch has to be created, you will not be prompted to select the sketching plane. As soon as you enter the 3D sketching environment, the **3D Sketch** tab will be activated. Some of the tools in this tab are the same as those discussed in 2D sketching. The functions of the remaining tools are discussed next.

Line

The **Line** tool is used to create a line in the 3D space. Note that similar to drawing a line in a 2D sketch, you can create a line by specifying the points on the graphics screen. The 3D line can also be created by using work points, vertices of an existing model, or center points of a cylindrical feature or hole. You can also turn on the option of creating bends at the corners of a 3D line. By default, this option is turned off. To turn this option on, invoke the **Line** tool in the 3D sketching environment and then right-click in the drawing window to display the Marking Menu. Choose the **Auto-Bend** option. Now, when you draw a 3D line, it will automatically be bent at the corners and the bend radius will be displayed, as the value of the first instance. At the remaining instances, the value will be displayed as a function of the first value. As a result, when you modify the first value, the remaining values will be modified automatically. If you want to modify any other value, double-click on it and modify it using the **Edit Dimension** edit box. However, in this case, the modified value will no more be the function of the first value. Figure 14-20 shows a 3D line created by using the vertices of an existing model and the center points of the holes.




Figure 14-19 Pipe created by sweeping a profile along a 3D path




Figure 14-20 3D line created using work points and vertices of a model

Spline

The **Spline** tool is used to create splines in the 3D sketching environment. This tool works similar to the **Spline** tool of 2D sketching environment. You can use work points, vertices of an existing feature, or center points of holes or cylindrical features for creating a 3D spline.

Bend

The **Bend** tool is used to create bends manually at the corners of the 3D line. When you invoke this tool, the **Bend** toolbar will be displayed, as shown in Figure 14-21. You can specify the radius of the bend in this toolbar and then select the two lines that comprise of the corner where the bend will be created. Note that if a cross is displayed on placing the cursor over the lines, it suggests

that the lines can not be selected for creating a bend.



Figure 14-21 The Bend toolbar

Include Geometry

The **Include Geometry** tool is used to include an existing 2D geometry in the 3D sketch. You can also select an edge of an existing model to be included in the 3D sketch. This is similar to projecting geometries or cutting edges. The only difference is that in this case, the selected entities are projected in a 3D sketching environment.

Intersection Curve

The **Intersection Curve** tool is used to create a 3D curve using the intersection of two surfaces, work planes, or existing components. When you invoke this tool, the **3D Intersection Curve** dialog box will be displayed, as shown in Figure 14-22.




Figure 14-22 The 3D Intersection Curve dialog box

When you invoke this dialog box, the **Select intersecting geometry** button is chosen by default. Select the first intersecting geometry; the **Select geometry to be intersected** button will be chosen automatically. Now, select the other intersecting surface and then choose **OK** button; a 3D curve will be created at

the intersection of the two selected geometries. Figure 14-23 shows two intersecting surfaces and Figure 14-24 shows the resultant 3D curve created using the intersecting surfaces.




Figure 14-23 Intersecting surfaces




Figure 14-24 3D curve created using the surfaces

Helical Curve

The **Helical Curve** tool allows you to create 3D helical curves that consist of a helical curve and a centerline. The dimensions of the curve are also displayed in the drawing area. To create a 3D helical curve, choose the **Helical Curve** tool from the **3D Sketch** tab; the **Helical Curve** dialog box will be displayed, as shown in Figure 14-25. Also, you will be prompted to select a start point for the helix axis. The **Inventor Precise Input** toolbar that is displayed along with the **Helical Curve** dialog box can be used to specify the start point and endpoint of the helix axis. The rest of the options that are used to create the helical curve are

similar to those discussed while creating coil feature in Chapter 8. Figure 14-26 shows a helical curve along with other components displayed in the drawing area.




Figure 14-25 The *Helical Curve* dialog box




Figure 14-26 Helical curve with its components

Note

The other options in this environment are similar to those discussed in the 2D Sketching environment and Part modeling environment.

TUTORIALS

Tutorial 1

In this tutorial, you will create new parameters and then use them for sketching and extruding the model shown in Figure 14-27. The dimensioned sketch is shown in Figure 14-28. The sketch should be extruded to a distance of EXT. The dimensions in the sketch should be displayed as equations, as shown in Figure 14-28. **(Expected time: 30 min)**

The numeric values of parameters are given below.

$$\text{LEN} = 60$$

$$\text{WID} = \text{LEN}/2$$

$$\text{RAD} = \text{LEN}/6$$

$$\text{EXT} = \text{LEN}/3$$




Figure 14-27 Model for Tutorial 1




Figure 14-28 Sketch for the model

The following steps are required to complete this tutorial:

- Start Autodesk Inventor and then start a new metric standard part file.
- Create the sketch and add required constraints to it, refer to Figure 14-29.

- c. Invoke the **Parameters** tool and create required parameters, refer to Figure 14-30.
- d. Invoke the **Document Settings** dialog box and select the option to display the dimensions as equations.
- e. Invoke the **Dimension** tool and dimension the sketch by entering parameters instead of entering values in the **Edit Dimension** edit box, refer to Figure 14-31.
- f. Exit the sketching environment and extrude the sketch. Enter the parameters instead of entering value in the extrusion distance edit box.

Starting a New Part File

1. Start Autodesk Inventor and invoke the **Create New File** dialog box.
2. Choose the **Metric** and start a new metric part file. Invoke the Modeling environment and define a new sketching plane on the XZ plane.

Drawing the Sketch

1. Draw the sketch for the model by using the sketching tools. Add the required constraints to it. The sketch after adding the constraints is shown in Figure 14-29.




Figure 14-29 Sketch after adding the constraints

Creating Parameters

As mentioned earlier, parameters are created by using the **Parameters** dialog box. You can invoke this dialog box by using the **Parameters** tool.

1. Choose the **Parameters** tool from the **Parameters** panel of the **Manage** tab to invoke the **Parameters** dialog box.

2. Choose the **Add Numeric** button from this dialog box to enter a new row in the **User Parameters** table. Enter the name of the parameter as **LEN** in the **Parameter Name** field and then press ENTER.

You will notice that a new row with the name LEN is created. The unit of the parameter is mm, and the equation and value is 1. Now, you need to modify the value of the parameter.

Note

*Note that the parameter names are case-sensitive. Therefore, if you enter a name in uppercase characters, you need to enter the parameters in the same case while specifying them in the **Edit Dimension** edit box or in a dialog box.*

3. Click on the **Equation** field of the LEN row; it changes into an edit box. Enter **60** in this edit box and then press ENTER.

You will notice that the values of the **Nominal Value** field and the **Model Value** field are automatically changed to 60.000000.

4. Again, choose the **Add Numeric** button to add another row to the **User Parameters** table.

5. Enter **WID** in the **Parameter Name** field.

6. Click on the **Equation** field of the WID row and enter **LEN/2** in this field. Next, press ENTER.

You will notice that the value in the **Model Value** field has automatically changed to 30.000000. This is because the value of the LEN parameter is 60 and $WID = LEN/2 = 60/2 = 30$. Also, notice that **ul** has automatically been added on the right of the equation. You do not need to enter this value while defining the equation as it is automatically added by Autodesk Inventor.

7. Similarly, create the remaining parameters. The **Parameters** dialog box after creating all the parameters is shown in Figure 14-30. Choose **Done** to exit the

Parameters dialog box.




Figure 14-30 The **Parameters** dialog box after adding the user-defined parameters

Note

As you have not dimensioned the sketch until now, no row will be displayed in the **Model Parameters** table. Once you add dimensions to the sketch, the parameters will automatically be added to the **Model Parameters** table.

Displaying Dimensions as Equations

As mentioned in the tutorial description, you need to display dimensions as equations. Therefore, you need to select this option from the **Document Settings** dialog box.

1. Choose the **Document Settings** tool from the **Options** panel of the **Tools** tab to invoke the **Document Settings** dialog box.
2. In this dialog box, choose the **Units** tab and select the **Display as expression** radio button from the **Modeling Dimension Display** area. Next, choose **Apply** and then choose **Close** to exit the dialog box.

Dimensioning the Sketch

Now, you need to dimension the sketch by using parameters. As mentioned earlier, parameters are case-sensitive. This means if you have specified the name of the parameter in capital letters, you need to enter the name in the **Edit Dimension** edit box in capital letters only, otherwise **Autodesk Inventor** dialog box states you that this expression cannot be evaluated.

1. Invoke the **Dimension** tool and then select the vertical lines one by one at the two ends of the sketch. Place the dimension below the sketch; the **Edit Dimension** edit box is displayed.
2. Enter **LEN** in the **Edit Dimension** edit box and press ENTER.

You will notice that the dimension is automatically modified and displayed as an equation on the graphics screen. This happens because you have selected the option of displaying dimensions as equations.

3. Select the left vertical line and then place the dimension on the left of the sketch; the **Edit Dimension** edit box is displayed. Enter **WID** in the **Edit Dimension** edit box and press ENTER.
4. Select the upper arc and then place the dimension on the left of the arc; the **Edit Dimension** edit box is displayed. Enter **RAD** in the **Edit Dimension** edit box and press ENTER.

This completes the dimensioning of the sketch. The sketch after adding all the dimensions is shown in Figure 14-3. In this figure, the grid lines and axes have not been displayed for better visibility of the sketch.

Note

If you do not dimension the sketch in the same sequence as mentioned above, the names of the model parameters with which the user parameters are equated will be different from those shown in Figure 14-28.

Extruding the Sketch

1. Exit the sketching environment and then change the current view to the isometric view.

2. Invoke the **Extrude** dialog box and then enter **EXT** in the edit box provided in the **Extents** area. Accept the remaining default options and then choose the **OK** button.

The sketch is extruded through a distance defined by the EXT parameter. You can also specify the parameters of the extruded feature using the mini toolbar that is displayed on invoking the **Extrude** tool.

3. Save the model with the name *Tutorial1.ipt* at the location given below and then close the file.

C:\Inventor_2016\c14




Figure 14-31 Sketch displaying the dimensions as equations

Tutorial 2

In this tutorial, you will create an assembly of the Outer Plate and the Inner Plate shown in Figure 14-32. The dimensions of the Outer Plate are shown in Figure 14-33. Create the Inner Plate as an adaptive part such that it automatically adjusts its size to fit inside the Outer Plate. Apply the **Mate** constraint with an offset of 10 mm to all the outer faces of the Inner Plate and the inner faces of the groove in the Outer Plate. After assembling the components, edit the inner cavity of the Outer Plate such that the Inner Plate again automatically adjusts its size.

(Expected time: 1 hr)

Note

As the Inner Plate has to be an adaptive part, its dimensions are not required.

The following steps are required to complete this tutorial:

- a. Start a new metric assembly file and then create the Outer Plate, refer to Figure 14-34.
- b. Invoke the **Create** tool and then select the top face of the Outer Plate as the sketching plane for the Inner Plate.
- c. Make the sketch of the Inner Plate adaptive and then set the parameters in the **Assembly** tab of the **Options** dialog box.
- d. Sketch the Inner Plate and then extrude it up to the bottom face of the Outer Plate.
- e. Save the model and then exit the Part environment.
- f. Add the **Mate** constraint between all inner faces of the groove in the Outer Plate and the outer faces of the Inner Plate. The size of the Inner Plate automatically changes in order to adjust inside the Outer Plate, refer to Figure 14-35.
- g. Modify the dimensions of the inner cavity of the Outer Plate. The size of the Inner Plate again changes automatically to retain the design intent, refer to Figure 14-38.




Figure 14-32 Assembly for Tutorial 2




Figure 14-33 Dimensions of the Outer Plate

Creating the Outer Plate

You can directly create the Outer Plate and the Inner Plate in the assembly file.

Before creating the Outer Plate, you need to change the measurement unit to mm.

1. Start a new metric standard assembly file. Next, choose the **Create** tool from the **Component** panel of the **Assemble** tab; the **Create In-Place Component** dialog box is displayed. Enter **Outer Plate** as the name of the component in the **New Component Name** edit box in this dialog box. Next, choose the **OK** button; the dialog box is closed and you are prompted to select a plane for the base feature. Select the XY plane as the base plane; part environment is invoked.
2. Select the XY plane as the sketching plane.

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*
2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

3. Choose the **Document Settings** button from the **Options** panel of the **Tools** tab; the **Document Settings** dialog box is displayed. Choose the **Units** tab and then select **millimeters** from the **Length** drop-down list in the **Units** area of this dialog box. Next, choose **Apply** and then close the dialog box.
4. Create the Outer Plate on the XY plane. After creating the Outer Plate, return to the assembly file. The assembly file after creating the Outer Plate is shown in Figure 14-34. For dimensions, refer to Figure 14-33.




Figure 14-34 Assembly after creating the Outer Plate

Creating the Inner Plate

You will sketch the Inner Plate by selecting the top face of the Outer Plate as the sketching plane. Note that the sketch plane should be constrained to the selected face.

1. Invoke the **Create** tool. Make sure that the **Constrain sketch plane to selected face or plane** check box is selected in the **Create In-Place Component** dialog box.
2. Enter **Inner Plate** as the name of the component in the **New Component Name** edit box in the **Create In-Place Component** dialog box. Choose **OK** from the dialog box and then select the top face of the Outer Plate.

3. Invoke the sketching environment by selecting the top face of the Outer Plate as the sketching plane.

Note that before selecting sketching plane, you need choose the **Home** button from the ViewCube.

4. Right-click on **Sketch1** in the **Browser Bar** and then choose **Adaptive** from the shortcut menu displayed; the Inner Plate becomes adaptive and its size gets adjusted automatically based on the surrounding
5. Choose the **Application Options** tool from the **Options** panel of the **Tools** tab to display the **Application Options** dialog box. Choose the **Assembly** tab from this dialog box to display the options in this tab.
6. Select all the check boxes in the **In-place features** area to make the model adaptive. As a result, on extruding the model up to the bottom face of the Inner Plate, the new part is modified automatically.
7. Choose **Apply** and then choose **Close** from the **Application Options** dialog box. Next, draw the sketch for the Inner Plate and then extrude it up to the bottom face of the Outer Plate. Save the part file and then exit the part modeling environment.

You do not need to add dimensions to the Inner Plate as it is an adaptive part. The assembly after creating the Inner Plate is shown in Figure 14-35.





Figure 14-35 Assembly after creating the Inner Plate


8. Now, apply the **Mate** constraint with an offset value of 10 mm between the

selected faces as shown in Figure 14-36; the Inner Plate shifts toward right.

9. Change the display type of both plates to **Wireframe** and then apply the **Mate** constraint with an offset of 10 mm between the selected faces, as shown in Figure 14-37; the Inner Plate gets shifted.



*Figure 14-36 Faces selected to apply the **Mate** constraint*




*Figure 14-37 Faces selected to apply the **Mate** constraint*


10. Now, change the display type of both the plates to **Shaded** and apply the **Mate** constraint with an offset value of 10 mm between the selected faces, as shown in Figure 14-38. Also, You will see that the size of the Inner Plate is reduced in order to fit inside the cavity of the Outer Plate. This is because of the adaptive property of the Inner Plate.
11. Similarly, apply the **Mate** constraint with an offset value of 10 mm between the selected faces, as shown in Figure 14-39.

Notice the size of the Inner Plate. It has further reduced in order to fit inside the cavity of the Outer Plate.

12. Close the **Place Constraint** dialog box. The assembly after applying the constraints is shown in Figure 14-40. Notice the change in the size of the Inner Plate.



*Figure 14-38 Faces selected to apply the **Mate** constraint*



*Figure 14-39 Faces selected to apply the **Mate** constraint*




Figure 14-40 Assembly after applying the constraints

Modifying Dimensions of the Cavity of the Outer Plate

You can edit the dimensions of the cavity of the Outer Plate in the assembly file.

Since the Inner Plate is an adaptive part, its dimensions will automatically be changed when the dimensions of the cavity are modified.

1. Double-click on **Outer Plate:1** in the **Browser Bar** to activate this component.
2. Modify the dimensions of the cavity, as shown in Figure 14-41.




Figure 14-41 Modified dimensions of the cavity

3. Choose **Return** from the **Quick Access Toolbar** to exit the sketching

environment. You may need to add the **Return** tool to the **Quick Access Toolbar** if it is not displayed by default.

4. Again, choose **Return** from the **Quick Access Toolbar** to exit the part modeling environment. Next, change the current view to the isometric view.

On doing so, you will notice that the dimensions of the Inner Plate are modified in order to retain the design intent of the assembly. The assembly after modifying the dimensions of the cavity is shown in Figure 14-42. Notice the change in the dimensions of the Inner Plate.




Figure 14-42 Modified assembly

5. Choose the **Save** button from the **Quick Access Toolbar**; the **Save As** dialog box is displayed. Browse to the *C:\Inventor_2016\c14* location and then enter **Tutorial2** as the file name in the **File name** edit box.
6. Choose the **Save** button from this dialog box; the **Save** message dialog box is displayed. Choose **Yes to All** from this dialog box to save the individual part files that you have created in the assembly environment. Next, choose **OK** to save the file.

Tutorial 3

In this tutorial, you will create a Pipe in 3D space, as shown in Figure 14-43. Assume the dimensions of the pipe. **(Expected time: 30 min)**

The following steps are required to complete this tutorial:

- a. Create a 2D sketch consisting of three lines on the XY plane and then exit the sketching environment, refer to Figure 14-44.
- b. Define a new work plane normal to the existing sketch and then create the second 2D sketch on this new work plane, refer to Figure 14-45. The start point of the first line in the second sketch should be the endpoint of the right vertical line in the first sketch.
- c. Invoke the 3D sketching environment and then select all lines to be included in the 3D sketch using the **Include Geometry** tool.
- d. Add bends at all the corners and then exit the 3D sketching environment, refer to Figure 14-46.
- e. Define a new work plane at the start point of the path and then sketch the profile of the pipe. Take the reference of the start point of the first line for drawing the sketch.
- f. Exit the sketching environment and sweep the sketch along the 3D path.




Figure 14-43 Pipe for Tutorial 3

Drawing the First 2D Sketch

1. Invoke the **Create New File** dialog box and then choose the **Metric** tab from it.
2. Start a new metric part file and then draw the first sketch on the XY plane, as shown in Figure 14-44.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button

from the ViewCube in order to maintain the right orientation of the model.

*2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

3. Exit the sketching environment by choosing the **Finish Sketch** button.

Drawing the Second 2D Sketch

You need to create the second 2D sketch on a work plane that is normal to the third line of the first 2D sketch. Therefore, first you need to define a new work plane normal to the third line of the sketch.

1. Define a new work plane normal to the right vertical line in the sketch and then select it as the sketching plane for drawing the next 2D sketch.
2. Draw the next sketch starting from the origin of the sketch plane. The origin of the sketch plane is the endpoint of the right vertical line of the first sketch, see Figure 14-45.

To ensure that the start point of the line is at the origin, you need to project the third line of the sketch. On doing so, the line will be projected as a point that will be placed at the origin. Now, apply the **Coincident** constraint between the endpoint of the line and the projected point.

3. Exit the sketching environment and turn off the display of the work plane. The first and second 2D sketches are shown in Figure 14-45.




Figure 14-44 First 2D sketch




Figure 14-45 First and second 2D sketches

Creating the 3D Sketch

1. Choose the **Start 3D Sketch** tool from **3D Model > Sketch > Sketch** drop-down to invoke the 3D Sketching environment.
2. Choose the **Include Geometry** tool from the **Draw** panel of the **3D Sketch** tab.
3. Select one by one all the lines in the first 2D sketch and the second 2D sketch.
4. Choose the **Bend** tool from the **Draw** panel of the **3D Sketch** tab to display the **Bend** toolbar. Enter **10** in this toolbar and then select all the lines that form the corners of the 3D sketch.

You will notice that a fillet kind of bend is created at all the corners of the 3D

sketch and the dimension is displayed on all the bends.

5. Exit the 3D sketching environment.
6. Now, turn off the visibility of the two 2D sketches using the **Browser Bar**. The 3D sketch after turning off the visibility of the 2D sketches is shown in Figure 14-46.

Note

If you are not able to fillet the vertex at the intersection of the first and second 2D sketches, it implies that the endpoint of the first 2D sketch is not coincident with that of the second 2D sketch. In other words, the start point of the first line of the second 2D sketch is not at the origin. Therefore, you need to edit the second 2D sketch and move it to the origin.

Creating the Profile for the Sweep Feature

To create the profile for the sweep feature, you need to define a new work plane at the start point of the first 2D sketch. Next, you need to select this work plane as the new sketching plane and draw the sketch of the profile.

1. Define a new work plane at the start point of the 3D path from where the first 2D sketch was started. Select this work plane as the new sketching plane.
2. Draw the 2D sketch of the profile of the sweep feature. The sketch of the profile consists of two concentric circles. The center of the circles should be at the start point of the first line of the 3D path. Specify 6 mm as the diameter of the outer circle and 4 mm as the diameter of the inner circle.
3. Exit the sketching environment.

Sweeping the Profile along the 3D Path

1. Invoke the **Sweep** dialog box and select the area between the two circles as the profile of the sweep feature; the area between the two circles turns blue and the **Path** button gets activated in the **Sweep** dialog box.
2. Select the 3D path as the path of the sweep feature; the complete 3D path

turns blue.

3. Choose **OK** to close the **Sweep** dialog box. The final pipe for Tutorial 3 is shown in Figure 14-47.
4. Now, turn off the visibility of work plane 2 by using the **Browser Bar**.




Figure 14-46 3D Sketch after turning off the visibility of the 2D sketches




Figure 14-47 Pipe for Tutorial 3

5. Save this model with the name *Tutorial3* at the location *C:\Inventor_2016\c14*.

Tutorial 4

In this tutorial, you will open the model saved in Tutorial 1 and add another parameter to it with the name **FILLET**, where $\text{FILLET} = \text{LEN}/10$. Using this parameter, you will fillet the model. Figure 14-48 shows the final filleted model. Next, you will change this model into a custom iPart factory. Make the **LEN** and

FILLET as custom variables, and then suppress the FILLET variable. Finally, place the two iParts in an assembly file using the custom iPart factory that you created. The details of the two iParts that you need to place in the assembly are given below. **(Expected time: 30 min)**

iPart 1

Value of LEN = 60

Suppress the fillet in the model

iPart 2

Value of LEN = 100




Figure 14-48 Model after filleting the edges using the FILLET parameter

The following steps are required to complete this tutorial:

- a. Open the *Tutorial1.ipt* file and save it with the name *Tutorial4.ipt*.
- b. Create a new user-defined parameter, FILLET in the part. The value of this parameter is LEN/10.
- c. Fillet the model using the FILLET parameter.
- d. Invoke the **iPart Author** dialog box and make the LEN parameter custom.
- e. Add one more row to the iPart table. Change the value of the LEN parameter to 100.
- f. Invoke the **Suppression** tab and suppress the FILLET variable.
- g. Make the FILLET variable custom.
- h. Save the file and then open a new assembly file.
- i. Place iParts in an assembly file using the custom iPart factory created earlier.

Opening the Tutorial 1 File

1. Open the *Tutorial1.ipt* file created earlier in this chapter.
2. Next, save it with the name *Tutorial4.ipt*.

Adding a User-defined Parameter

You need to add a User-defined Parameter to the current file. This parameter will be used to fillet the model.

1. Choose the **Parameters** tool from the **Parameters** panel of the **Manage** tab to invoke the **Parameters** dialog box.
2. Choose the **Add Numeric** button to enter a new row in the **User Parameters** table. Enter **FILLET** in the **Parameter Name** field and then press ENTER.

Notice that a new row of the user-defined parameter is added. At this stage, the value of this parameter is **1.00** mm in the **Equation** column. Now, you need to equate this parameter in terms of the LEN parameter.

3. Click on the **Equation** field in the FILLET row; the field changes to an edit box.
4. Enter **LEN/10** in the edit box and then press ENTER. You will notice that the value of this parameter automatically changes to 6.000000 in the **Nominal Value** and **Model Value** edit boxes.
5. Choose the **Done** button to exit the **Parameters** dialog box.

Adding a Fillet to the Model Using the FILLET Parameter

1. Choose the **Fillet** tool from the **Modify** panel of the **3D Model** tab to invoke the **Fillet** dialog box.
2. Select the four edges to be filleted from the




Figure 14-49 Rotated view of filleted model model.

3. Enter **FILLET** in the **Radius** field of the **Constant** tab in the **Fillet** dialog box.

Note that when you enter values in terms of parameters, you need to delete **mm** from the edit boxes.

4. Choose **OK**; the fillet is added to the model and the model looks similar to the one shown in Figure 14-49.

Creating the Custom iPart Factory

Next, you need to create the custom iPart factory. You will create it by customizing the LEN parameter and suppressing the fillet feature.

1. Choose the **Create iPart** tool from the **Author** panel of the **Manage** tab; the **iPart Author** dialog box is displayed with the **Parameters** tab chosen.

You will notice that all the user-defined parameters are displayed on the **Selected Parameters** pane. You will also notice that only one row is available in the iPart table. This row has default values for the variables.

2. Right-click on the LEN variable in the **iPart Table**; a shortcut menu is displayed. Choose **Custom Parameter Column** from the shortcut menu.

You will notice that the **LEN** column in the **iPart Table** turns blue and the key on the left of this parameter in the **Selected Parameters** pane is removed.

3. Click on the key corresponding to the WID parameter; a key with numeric value **1** is assigned to the WID parameter.
4. Choose the **Suppression** tab and then select **Fillet1** from the **Model Features** pane. Choose the **Add** button (>>) to add this feature to the **Selected Features** pane.

5. Next, right-click on **Fillet1** in the **iPart Table**, and then choose **Custom Parameter Column** from the shortcut menu; this feature is made custom. Now, you can suppress or compute it while inserting iParts using this iPart factory. Choose the **OK** button from the **iPart Author** dialog box to create the iPart factory. Now, you can save it and use it to place iParts.
6. Choose the **Save** button from the **Quick Access Toolbar** and then close this file.

Placing iParts Using the Custom iPart Factory

Generally, iParts are placed in the assembly files. Therefore, you need to start a new assembly file to place iParts in it.

1. Start a new assembly file and then invoke the **Place** tool from the **Component** panel of the **Assemble** tab; the **Place Component** dialog box is displayed.
2. Select the *Tutorial4.ipt* file from this dialog box to place the iPart and then choose the **Open** button; the **Place Custom iPart** dialog box is displayed.

The **Predefined values** pane shows only the WID parameter because only this parameter was assigned the key. On the other hand, the **Custom values** pane shows the LEN parameter and the **Fillet1** feature. As a result, you can modify the value of the LEN parameter and suppress or compute the **Fillet1** feature.

3. Click on the **Value** field of the **Fillet1** feature in the **Custom values** pane; the field is changed into a drop-down list.
4. Select **Suppress** from this drop-down list. Next, click anywhere on the screen to place the component.
5. Choose **OK** to close the dialog box.

Notice that an iPart is placed in the assembly file and the fillet in this part is suppressed.

Tip. If you want to unsuppress fillet in the iPart placed in the current assembly

file, click on the + sign located on the left of the part in the **Browser Bar**; the tree view expands, and **Table** and **Origin** appear in the **Browser Bar**. Next, right-click on the **Table**, and then choose **Change Component** from the shortcut menu; the **Place Custom iPart** dialog box will be displayed. Change **Suppress** to **Compute** in the **Value** field of **Fillet1**. Choose **OK** to exit the dialog box; the fillet will be computed and then shown in the model.

6. Next, you need to place another iPart with a different value in the assembly. Invoke the **Place** tool to display the **Place Component** dialog box.
7. Next, select the *Tutorial4.ipt* in this dialog box to place the iPart and choose **Open** button from it; the **Place Custom iPart** dialog box is displayed. Click on the **Value** field of the **LEN** parameter; the field changes into an edit box.
8. Enter **100** in this edit box and then click anywhere on the graphics screen. Next, right-click, and then choose **OK** from the shortcut menu displayed; the component is placed and the dialog box is closed.
9. Next, save the file.

You can now use these components to create an assembly.

Tutorial 5

In this tutorial, you will use the hybrid surface-solid modeling to create the model shown in Figure 14-50. Figure 14-51 shows another view of this model. The dimensions of this model are given in the tutorial steps. **(Expected time: 45 min)**




Figure 14-50 Model for Tutorial 5




Figure 14-51 Another view of the model for Tutorial 5

The following steps are required to complete this tutorial:

- a. Open a new part file and then create the sketch shown in Figure 14-52 on the default XY plane.
- b. Revolve this sketch through an angle of 180-degree so that the final output is a surface, refer to Figure 14-53.
- c. Create two extruded surfaces, refer to Figure 14-55.
- d. Split surfaces using the **Face Split** option, refer to Figure 14-56.
- e. Delete faces using the **Delete Face** tool, refer to Figure 14-58.
- f. Define a new work plane at an offset distance of 45 mm and then create the sketch shown in Figure 14-60.
- g. Split the base surface using the last sketch, and then delete the face, refer to Figure 14-61.
- h. Create a 3D sketch on the deleted face and then share the sketch that was used in splitting the base surface. Create a lofted surface using the shared sketch and the 3D sketch, as shown in Figure 14-63.
- i. Create a boundary patch to close the top face of the lofted surface, refer to Figure 14-64.
- j. Stitch all surfaces together and fillet all sharp edges, refer to Figure 14-65.
- k. Thicken the surface using the **Thicken/Offset** tool, refer to Figure 14-68.

Creating the Base Surface

You will create the base surface using the sketch drawn on the XY plane. Next, you will revolve this sketch by an angle of 180 degrees.

1. Open a new metric standard part file and then draw the sketch on the XY plane, as shown in Figure 14-52. Constrain the sketch fully by specifying dimensions and geometric constraints.

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*

*2. If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

Note that a sketch point is placed at the origin and is fixed using the **Fix** constraint. The sketch is dimensioned using this point to make it a fully constrained sketch. Note that a sketch is fully constrained only when all its entities are displayed in blue.

2. Exit the sketching environment and then invoke the **Revolve** tool from the **Create** panel of the **3D Model** tab; the **Revolve** dialog box will be displayed. In this dialog box, the **Surface** button is automatically chosen in the **Output** area.

Select the sketch from the drawing area if it is not selected already; you are prompted to select the axis.

3. Select the centerline as the axis of revolution; the preview of the resultant surface is displayed.
4. Select **Angle** from the drop-down list in the **Extents** area and set the value of the angle to 180 degrees. Next, choose **OK**; the base surface is created, as shown in Figure 14-53.




Figure 14-52 Fully constrained sketch for the base surface




Figure 14-53 Base surface

Creating Side Surfaces

You need to create two cuts on both sides of the base surface by splitting the base surface using the two surfaces at sides. Therefore, first you need to create side surfaces.

1. Define a new sketch plane on the XY plane and then create an ellipse, as shown in Figure 14-54. Note that the center point of the ellipse should be coincident with the edge of the base surface.

Next, you need to extrude the ellipse to create the surface.

2. Exit the sketching environment and then extrude the ellipse as a surface through a distance of 30 mm.
3. Choose the **Mirror** tool from the **Pattern** panel of the **3D Model** tab; the **Mirror** dialog box is displayed and you are prompted to select a feature to pattern.
4. Select the extruded elliptical surface and then select **XZ Plane** as the mirror plane. Next, choose **OK** from the **Mirror** dialog box; the feature is mirrored, as shown in Figure 14-55.




Figure 14-54 Ellipse created on the XY plane




Figure 14-55 Model after creating the mirror feature

Creating Cuts on Sides by Using Side Surfaces

To create cuts on the sides, first you will use the two side surfaces to split the base surface. Next, you will use the base surface to split the side surfaces. Finally, all the unwanted surfaces will be deleted using the **Trim** tool.

1. Invoke the **Trim** tool from the **Surface** panel of the **3D Model** tab and select one of the extruded elliptical surfaces as the cutting tool.
2. Select the portion common between the base surface and the extruded surface as the portion to be trimmed, as shown in Figure 14-56. Choose **OK** from the dialog box.
3. Trim the revolved base surface using the second extruded surface as the cutting tool.
4. Using the base surface as the cutting tool, trim the remaining portion of the extruded surface on the left of the base surface, as shown in Figure 14-57.
5. Trim the other extruded elliptical surface using the base surface as the trim tool. Note that you need to select the outer portion of the extruded surface to trim, as shown in Figure 14-58.

The model after trimming all the unwanted surfaces is shown in Figure 14-59.




Figure 14-56 Trimming the base surface




Figure 14-57 *Trimming one of the extruded surfaces*




Figure 14-58 *Trimming the other extruded surface*




Figure 14-59 *Model after trimming unwanted surfaces*

Creating the Lofted Surface

Next, you need to create the lofted surface. To create this surface, you need to create a work plane at an offset from the XY plane.




Figure 14-60 Sketch drawn on the offset plane

1. Create a new work plane at an offset distance of 45 mm above the XY plane.
2. Select this plane as the sketching plane and draw the sketch, as shown in Figure 14-60.
3. Exit the sketching environment and invoke the **Split** tool from the **Modify** panel of the **3D Model** tab.
4. Select the sketch as the split tool and select the base surface as the face to be split.
5. Choose **OK** button from **Split** dialog box; the base surface is split using the sketch.
6. Delete the split surface from the base surface using the **Delete Face** tool. The model after deleting the split surface is shown in Figure 14-61.

Next, you will create a 3D sketch using the edges of the surface that are removed from the base surface.

7. Invoke the 3D sketching environment and then choose the **Include Geometry** tool from the **Draw** panel of the **3D Sketch** tab.
8. Select the four edges that resulted from the split surface which was removed from the base surface, see Figure 14-62.



Figure 14-61 Model after deleting the split surface




Figure 14-62 3D Sketch created using edges

9. Exit the 3D sketching environment.
10. Turn on the visibility of the sketch that was used to split the base surface, refer to Figure 14-60.
11. Create a lofted surface between the two sketches.
12. Turn off the visibility of the sketches. The model after creating the lofted surface is shown in Figure 14-63.

Next, you need to cover the top face of the lofted surface using the **Patch** tool.

13. Choose the **Patch** tool from the **Surface** panel of the **3D Model** tab to invoke the **Boundary Patch** dialog box.
14. Select the top edges of the lofted surface and choose **OK** from the **Boundary Patch** dialog box; a boundary patch covering the top of the lofted surface is created, see Figure 14-64.




Figure 14-63 Model after creating the lofted surface




Figure 14-64 Model after covering the top face of the lofted surface

Stitching Surfaces and Hiding Original Surfaces

After creating all the surfaces, you need to stitch them together and hide the original surfaces. The surfaces will be stitched using the **Stitch Surface** tool.

1. Invoke the **Stitch Surface** tool from the **Modify** panel of the **Surface** tab. Select all the surfaces so that they get stitched together. Next, choose **Apply** and then **Done** from the **Stitch** dialog box. Figure 14-65 shows the model after stitching surfaces.

When you stitch the surfaces, a stitched surface is created above the original surfaces and the visibility of original surfaces is automatically turned off.

2. Fillet all the sharp edges of the stitched surface with a radius of 2 mm. The surface after creating fillets is shown in Figure 14-66.




Figure 14-65 Model after stitching surfaces




Figure 14-66 Model after filleting surfaces

Thickening the Surface

The final step in creating the hybrid surface-solid model is to thicken the complex surface created in the previous steps. By thickening, you can add material to the surface model so as to make it a solid model. The model can be thickened using the **Thicken/Offset** tool.

1. Invoke the **Thicken/Offset** tool from the **Modify** panel of the **3D Model** tab; **Thicken/Offset** dialog box is displayed. Select the **Quilt** radio button from it.
2. Set the value in the **Offset** edit box in **Distance** area to **1**, if it is not already set. Select the stitched surface.

As you have selected the **Quilt** radio button, you will notice that the entire stitched surface is selected in a single click.

3. Choose **OK** to exit the dialog box. Now, turn off the visibility of the stitched surface using the **Browser Bar**. The final model for Tutorial 5 is shown in Figure 14-67. Figure 14-68 shows the rotated view of the same model.




Figure 14-67 Final hybrid model




Figure 14-68 Rotated view of the hybrid model

Answer the following questions and then compare them to those given at the end of this chapter:

1. The options in the _____ tab of the **iPart Author** dialog box are used to add the thread parameters to the iPart factory.

2. _____ parameters are automatically created when you apply dimensions to entities or create a feature.
3. _____ are mathematical expressions in which parameters are equated with algebraic or trigonometric functions.
4. The dimensioning of _____ parts is changed automatically depending upon the dimensions and functions of other parts to which they are assembled.
5. In Autodesk Inventor, every dimension is assigned a unique name called _____.
6. The _____ tool is used to create bends manually at the corners of the 3D line.
7. Autodesk Inventor allows you to create custom and standard iParts. (T/F)
8. You cannot turn off the display of surfaces. (T/F)
9. In Autodesk Inventor, the hybrid surface-solid modeling is used to create complex surfaces. (T/F)
10. Autodesk Inventor does not allow you to display dimensions as equations. (T/F)

Answer the following questions:

1. Which of the following tabs in the **iPart Author** dialog box is used to select the parameters and dimensions to be included in the iPart factory?
(a) **Parameters** (b) **Threads**
(c) **Work Plane** (d) None of these
2. Which of the following is not a parameter?

- (a) Drawing (b) Model
- (c) User (d) Link

3. Which of the following tabs in the **Document Settings** dialog box is used to display dimensions as equations?

- (a) **Units** (b) **Sketch**
- (c) **Modeling** (d) None of these

4. Which of the following tabs in the **iPart Authors** dialog box is used to specify whether the selected features will be computed or suppressed while creating a part using the iPart factory?

- (a) **Parameters** (b) **Threads**
- (c) **Work Plane** (d) **Suppression**

5. Which of the following tools is used to merge a 2D sketch entity into a 3D sketch?

- (a) **Line** (b) **Bend**
- (c) **Include Geometry** (d) None of these

6. You can modify dimensions while inserting custom iParts to an assembly. (T/F)

7. You can specify sketch points using the **Inventor Precise Input** toolbar in the 3D sketching environment. (T/F)

8. Unlike the 2D sketching environment, you can save a file in the 3D sketching environment. (T/F)

9. The Link parameters are created in a separate Microsoft Excel spreadsheet. (T/F)

10. The User parameters are defined by the user for specifying the dimensions of entities and features. (T/F)

Exercise 1

Create the following sketch with the help of parameters. After dimensioning the sketch, display the dimensions as expressions, as shown in Figure 14-69. The numeric values of the parameters are given below. **(Expected time: 30 min)**

$$\text{LEN} = 60$$

$$\text{LEN1} = \text{LEN}/3$$

$$\text{LEN2} = \text{LEN}/2.5$$

$$\text{WID} = \text{LEN} * 0.75$$

$$\text{WID1} = \text{WID}/5$$

$$\text{WID2} = \text{WID1}$$

After displaying the dimensions as expressions, display them as names.




Figure 14-69 Sketch with dimensions as equations

Answers to Self-Evaluation Test

1. Threads, 2. Model, 3. Equations, 4. adaptive, 5. parameter, 6. Bend, 7. T, 8. F, 9. T, 10. F

Chapter 15

Working with Sheet Metal Components

Learning Objectives

After completing this chapter, you will be able to:

- ***Set parameters for creating sheet metal parts.***
- ***Create the base of a sheet metal component.***
- ***Fold a part of a sheet metal part.***
- ***Add a flange to a Sheet metal component.***
- ***Create a cut feature in a sheet metal part.***
- ***Add a corner seam to sheet metal parts.***
- ***Round the corners of a sheet metal part.***
- ***Chamfer the corners of a sheet metal part.***
- ***Punch 3D shapes into sheet metal components.***
- ***Add a hem to a sheet metal part.***
- ***Create the flat pattern of a sheet metal component.***

THE SHEET METAL MODULE

A component having a thickness greater than 0 and less than 12.7 mm is called a sheet metal component. A sheet metal component is created by bending, cutting, or deforming a sheet of metal that has uniform thickness, see Figure 15-1.

As it is not possible to machine such a model, therefore after creating a sheet metal component, you need to flatten it for its manufacturing. Figure 15-2 shows the flattened view of the sheet metal component that is shown in Figure 15-1.




Figure 15-1 A sheet metal component




Figure 15-2 The flattened view of the sheet metal component

Autodesk Inventor allows you to create sheet metal components in a module, called the **Sheet Metal** module. This environment provides all tools required for creating the sheet metal components. To invoke the **Sheet Metal** module, double-click on **Sheet Metal (mm).ipt** in the **Metric** tab of the **Create New File** dialog box, see Figure 15-3; the sheet metal environment will be invoked as shown in Figure 15-4

Note

1. Sheet metal files are saved in the *.ipt format.
2. You can convert a sheet metal part into a solid part. To do so, choose the **Convert to Standard Part** button from the **Convert** panel of the **3D Model** tab of the sheet metal environment; the sheet metal component is converted into solid

part and the modeling environment is invoked.

3. In sheet metal design, End of Part (EOP) marker is changed to End of Folded (EOF) marker. It includes various operations such as Move EOF to Top and Move EOF to End in the Browser Bar.




Figure 15-3 Starting a new sheet metal file from the Metric tab of the Create New File dialog box




Figure 15-4 Initial screen of the Sheet Metal module

After invoking the sheet metal environment, you need to create a 2D sketch of the base feature of the sheet metal component. To do so, click on the Start 2D Sketch tool in the Sketch panel of the Sheet Metal tab; you will be prompted to select a plane to create the sketch. When you select a plane, the sketching environment will be invoked. Next, create the sketch for the base feature and exit the sketching environment. Note that very few tools are available in this tab. More tools will be available after you create the base of the sheet metal part.

Before converting the sketch into the sheet metal base, it is recommended that you set the parameters related to the sheet metal components by using the Sheet Metal Defaults tool. This tool is discussed next.

SETTING SHEET METAL COMPONENT PARAMETERS

Ribbon: Sheet Metal > Setup > Sheet Metal Defaults

You can set the parameters related to a sheet metal component by using the **Sheet Metal Defaults** tool. On invoking this tool, the **Sheet Metal Defaults** dialog box will be displayed, as shown in Figure 15-5. The procedures to specify parameters, material style, and unfolding rule by using the options in this dialog box are discussed next.




Figure 15-5 The Sheet Metal Defaults dialog box

Setting the Sheet Metal Rule

The sheet metal rule is set by choosing the **Edit Sheet Metal Rule** button, which is available on the right of the **Sheet Metal Rule** drop-down list. On choosing this button, the **Style and Standard Editor [Library-Read Only]** dialog box will be displayed, as shown in Figure 15-6. Choose the **New** button; the **New Local Style** dialog box will be displayed. Enter the name to create a new rule in this dialog box and choose the **OK** button; the new name will be displayed in the left pane of the dialog box. Right-click on the name and choose **Active** from the shortcut menu, so that if you modify the settings, they are stored in this name. The options related to the selected name will be displayed in the right pane of the **Style and Standard Editor [Library - Read Only]** dialog box. This dialog box provides three tabs for setting the parameters of the sheet metal components. The options in these three tabs are discussed next.




Figure 15-6 The Sheet tab of the Style and Standard Editor [Library - Read Only] dialog box

Sheet Tab

The options in the **Sheet** tab are discussed next, refer to Figure 15-6.

Sheet Area

The options in the **Sheet** area are used to specify the material and thickness of the sheet and are discussed next.

Material: The **Material** drop-down list is used to specify the material of the sheet. You can select the desired predefined material in this drop-down list.

Thickness: The **Thickness** edit box is used to specify the thickness of the sheet. You can enter the thickness of the sheet in this edit box or select from the predefined thicknesses by choosing the arrow on the right of this edit box.

Note

*If the **Use Thickness from Rule** check box is selected in the **Sheet Metal Defaults** dialog box, the value entered in the **Thickness** edit box will be used as the default thickness. However, you can change the thickness by clearing the **Use Thickness from Rule** check box and entering a new value in the **Thickness** edit box. Alternatively, to change the thickness, enter a new value in the **Thickness** edit box in the **Sheet** area of the **Style and Standard Editor [Library - Read Only]** dialog box.*

Unfold Rule Area

The drop-down list in this area is used to select the predefined unfolding rule.

Miter/Rip/Seam Gap

This edit box is used to specify the gap to be used for miter/rip/seam. By default, the thickness value specified in the **Thickness** edit box is used as the value of the miter/rip/seam for the sheet metal component. Enter a new value in this edit box to change the gap value.

Flat Pattern Bend Angle Area

The options in this area determine how the reported bend angle will be measured when the folded model is displayed as a flat pattern. The options in this area are discussed next.

Report Bending Angle (A): This option is selected by default in the drop-down list below the **Flat Pattern Bend Angle** area. As a result, the bend angle will

be measured between the selected face and the outside face of the bend.

Report Open Angle (B): If you select this option, the bend angle will be measured between the selected face and the inside face of the bend.

You can preview these reported bend angles in the window given below the **Flat Pattern Bend Angle** area.

Flat Pattern Punch Representation Area

The options in this area determine how the sheet metal punch features will be displayed when the folded model is displayed as a flat pattern. The options in this area are discussed next.

Formed Punch Feature: This option, if selected, displays the sheet metal punch features as 3D features in the flat pattern of the component.

2D Sketch Representation: This option, if selected, displays the sheet metal punch features using a previously created 2D sketch in the flat pattern of the component.

2D Sketch Rep and Center Mark: This option, if selected, displays the sheet metal punch features using a previously defined 2D sketch along with a Center Mark in the flat pattern of the component.

Center Mark Only: This option, if selected, displays the sheet metal punch features using only the center mark of the sketch, when the flat pattern of the component is displayed.


After setting the parameters, choose the **Save** button.

Bend Tab

The options in the **Bend** tab are used to set the parameters related to the bending of a sheet, refer to Figure 15-7. These options are discussed next.

Bend Relief Area

The options in this area are used to control the bend relief width, bend relief depth, and so on. These options are discussed next.



*Figure 15-7 The **Bend** tab of the **Style and Standard Editor [Library - Read Only]** dialog box*

Relief Shape: Whenever you bend or fold a sheet metal component such that the bend does not extend throughout the length of the edge, a groove is added at the end of the bend so that the walls of the sheet metal part do not intersect when folded or unfolded. This groove is known as relief. The **Relief Shape** drop-down list is used to select the shape of the relief. By default, a straight relief is added, as shown in Figure 15-8. You can add a round relief by selecting the **Round** option from this drop-down list. Figure 15-9 shows a round relief. You can also add a tear relief by selecting the **Tear** option from this drop-down list. A tear relief is added when tight bends are required in the sheet metal component.




Figure 15-8 Straight relief added




Figure 15-9 Round relief added

Relief Width (A): This edit box is used to enter the value of the width of the relief. The default value of the relief width is equal to the thickness of the sheet. You can enter the value of the relief width in this edit box. Figure 15-10 shows a sheet metal component with a relief width of 1 mm and Figure 15-11 shows a sheet metal component with a relief width of 4 mm.




Figure 15-10 Sheet metal with relief width of 1 mm




Figure 15-11 Sheet metal with relief width of 4 mm

Relief Depth (B): This edit box is used to specify the value of relief depth.

Minimum Remnant: This edit box is used to set the value of the material between the relief created by bending or folding and the edge of the sheet metal component.

Bend Radius

This edit box is used to set the radius of the bend or the fold. The default value of the radius of the bend is equal to the thickness of a sheet. You can enter a numeric value in this edit box to set it as the bend radius. Figure 15-12 shows a sheet folded with a radius of 1 mm and Figure 15-13 shows a sheet folded with a radius of 5 mm.




Figure 15-12 Sheet folded with 1 mm bend radius




Figure 15-13 Sheet folded with 5 mm bend radius

Tip. *If you modify the bend radius after bending or folding a sheet metal component, the model will be automatically updated and will acquire the new bend radius when you choose the **Save** button and exit the **Style and Standard Editor** dialog box.*

Bend Transition

The **Bend Transition** drop-down list is used to specify the transition type in the unfolded view when no relief is specified. The default value of this drop-down list is **None**. You can select the **Intersection**, **Straight Line**, **Arc**, or **Trim to Bend** transition type from this drop-down list.

After setting the parameters, choose the **Save** button.

Corner Tab

The options in the **Corner** tab are used to set the parameters related to the relief at the corners where the three faces of a sheet metal component are folded, refer to Figure 15-14. These options are discussed next.




Figure 15-14 The Corner tab of the Style and Standard Editor [Library - Read Only] dialog box

2 Bend Intersection Area

The options in the **2 Bend Intersection** area allow you to specify the corner relief when two bends intersect. These options are discussed next.

Relief Shape: The **Relief Shape** drop-down list is used to specify the shape of the relief at the corner where the two faces are folded. The preview of the selected type of relief will be displayed in the preview window below the **Relief Size** edit box in the **2 Bend Intersection** area. Remember that the options in this drop-down list will work only when one of the two faces is created by using the **Corner Seam** tool, which is discussed later in this chapter. The options in this drop-down list are discussed next.

Note

*To get a better view of various corner relief shapes, the sheet metal component should be flattened using the **Flat Pattern** tool. This tool will be discussed later in the chapter.*

Trim to Bend: The **Trim to Bend** is the default option in the **Relief Shape** drop-down list. It appears as a polygonal cut bounded by bend lines. Figure 15-15 shows the flattened sheet metal part with no relief at the corner.

Round: The **Round** option is used to create a round corner relief, which is centered at the intersection of bend lines. Figure 15-16 shows a sheet metal part with a round relief.




Figure 15-15 Flattened sheet metal part with no corner relief




Figure 15-16 *Flattened sheet metal part with round corner relief*

Square: The **Square** option is used to create a square corner relief, which is centered at the intersection of bend lines. Figure 15-17 shows a sheet metal part with a square corner relief.

Tear: The **Tear** option is used to create a corner relief that appears torn at the corners. Figure 15-18 shows a flattened sheet metal part with a tear corner relief.

Linear Weld: This option is used to apply a linear weld type of relief at the corners. This type of weld appears as a V-shaped cutout. It lies at the intersection of the inner bend zone lines to the outer bend zone line's intersection with the flange, refer to Figure 15-19.

Arc Weld: This option is used to create a relief that is suitable for the components that need to be created by arc welding, refer to Figure 15-20.




Figure 15-17 *Flattened sheet metal part with square corner relief*




Figure 15-18 Flattened sheet metal part with tear corner relief




Figure 15-19 Flattened sheet metal part with linear weld




Figure 15-20 Flattened sheet metal part with arc weld

Relief Size: The **Relief Size** edit box is used to specify the size of the corner relief. You can enter the value as an equation in terms of the thickness of the sheet or as a numeric value. This edit box will be activated only when you select the **Round** or **Square** option in the **Relief Shape** drop-down list.

3 Bend Intersection Area

The options in the **3 Bend Intersection** area allow you to specify the corner relief when three bends intersect at a common point. These options are discussed next.

Relief Shape: The **Relief Shape** drop-down list is used to specify the shape of the relief at the corner where all faces are folded. The preview of the selected type of relief will be displayed in the preview window below the **Relief Radius** edit box in the **3 Bend Intersection** area. The options in this drop-down list are discussed next.

No Replacement: This option, if selected, retains the default corner relief that was selected before creating the component.

Intersection: This option is used to create relief by extending and intersecting all flange edges.

Full Round: This option, if selected, creates a corner relief by extending the flange edges to their intersection and then, creates a fillet tangent to the bend zone tangent lines.

Round with Radius: This option is selected by default. As a result, a corner relief will be created by extending the flange edges to their intersection and then a tangent fillet of specified radius will be created. The radius of the fillet created using the **Round with Radius** option is smaller compared to the fillet created by using the **Full Round** option.

Relief Radius: The **Relief Radius** edit box will be available only when the **Round with Radius** option is selected from the **Relief Shape** drop-down list. This edit box is used to specify the radius of the fillet.

After making the necessary modifications, choose the **Save** button to save the changes and then choose the **Done** button to close the **Style and Standard Editor [Library - Read only]** dialog box.

Once you have made necessary initial settings, you are ready to create the sheet

metal component.

Setting the Material

You can set material for a sheet metal component by using the **Material** drop-down list in the **Sheet** area of the **Sheet** tab in the **Style and Standard Editor [Library - Read Only]** dialog box. To do so, select the material from the **Material** drop-down list of **Sheet** area of this dialog box, refer to Figure 15-21. You can select the desired predefined material from this drop-down list.




Figure 15-21 Selecting material from the **Material** drop-down list

Setting the Unfolding Rule

You can apply the available unfolding rule to a sheet metal component using the **Unfold Rule** drop-down list in the **Sheet Metal Defaults** dialog box. To do so, select the required unfolding rule from this drop-down list. You can also edit an existing unfolding rule. To do so, choose the **Edit Unfold Rule** button on the right of this drop-down list; the **Style and Standard Editor [Library - Read Only]** dialog box will be displayed, as shown in Figure 15-22. You can edit the default parameters in this dialog box and then choose the **Save** button to save the settings. The options in the **Sheet Metal Unfold** area are used to specify

parameters to unfold the sheet metal component for manufacturing. These options are discussed next.





Figure 15-22 The partial view of the **Style and Standard Editor [Library - Read Only]** dialog box

Unfold Method

The **Unfold Method** drop-down list consists of three options for unfolding the sheet metal component. The first option is the **Linear** method. This method uses a simple unfolding technique for flattening the component. You can set the KFactor value manually using the **KFactor Value** edit box. Note that the KFactor value should be between 0 and 1. You can specify the spline factor value in the **Spline Factor Value** edit box. This value is significant in case of contour flanges, contour rolls, and lofted flanges. After setting the required parameters, choose **Save** and then the **Done** button.

The second option is the **Bend Table** method. On selecting this option, all parameters related to the unfolding rule will be displayed, as shown in Figure 15-23. You can set these parameters based on your requirement. After setting the required parameters, choose **Save** and then the **Done** button.

The third option is the **Custom Equation** method. When you select this option, you can use different types of equations for calculating the size of bend zone. These equations can be selected from the **Equation Type** drop-down list in the **Style and Standard Editor [Library - Read Only]** dialog box. You can select the **Bend Allowance**, **Bend Compensation**, **Bend Deduction**, or **KFactor** option from the **Equation Type** drop-down list as per your requirement. Figure 15-24 shows different options related to the **Custom Equation** option. After setting the required parameters, choose **Save** and then the **Done** button.



*Figure 15-23 The Style and Standard Editor [Library - Read Only] dialog box with the options related to the **Bend Table** method*




Figure 15-24 The Style and Standard Editor [Library - Read Only] dialog box with the options related to the Custom Equation option

CREATING SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Create > Face

The **Face** tool is used to create the base of a sheet metal component or to add additional faces to it. To create the base of a sheet metal component, first invoke the sketching environment and then create the sketch of the base feature. After creating the sketch, exit from the sketching environment and then invoke the **Face** tool. On invoking this tool, the **Face** dialog box will be displayed, as shown in Figure 15-25. This dialog box has three tabs. But, since you are creating the base, the options in these tabs are not required. If there is a single sketch in the graphics screen, it will be selected automatically for creating the sheet metal part. The thickness defined in the **Sheet** tab of the **Style and Standard Editor [Library - Read Only]** dialog box will be taken as the thickness of the sheet. Figure 15-26 shows a sketch and Figure 15-27 shows the sheet metal component created using the same sketch.




Figure 15-25 The *Shape* tab of the *Face* dialog box




Figure 15-26 Sketch for creating the sheet metal part




Figure 15-27 Sheet metal part created using the same sketch

An alternative method to invoke the **Face** tool is by using the mini toolbar. The mini toolbar is displayed on selecting a sketched entity after exiting the sketching environment. To create the base of the sheet metal component, choose the **Create Face** button from the mini toolbar; the preview of the base of sheet metal will be displayed in the graphics window. Also, the **Face** dialog box will

be displayed, refer to Figure 15-25. Specify the required parameters and then choose the **OK** button to create the base of the sheet metal.

After creating the base of the sheet metal component, if you create a sketch and invoke the **Face** tool again, the other options in the **Face** dialog box will be available. The other options in the **Face** dialog box are discussed next.

Shape Tab

The options in the **Shape** tab are used to define the shape and bend radius of the face, refer to Figure 15-25. These options are discussed next.

Shape Area

The options in the **Shape** area are used to specify the shape of the face. These options are discussed next.

Profile

The **Profile** button is chosen to select the sketch of the face. If there is only one unconsumed sketch on the screen, it will be automatically selected. However, if there are more than one unconsumed sketches or the sketch consists of multiple closed loops, you will have to select them manually by using this button.

Offset

The **Offset** button is chosen to reverse the direction of the face creation.

Solids

This **Solids** button is used to select a body in the multi-body environment so that the resultant feature becomes a portion of the selected body. This button will be active only when there are multiple bodies in the graphic window.

Bend Area

Whenever you create a face on an existing sheet metal component, a bend is created at the edge where the new face joins the existing component. Also, a bend relief is added to the new face. The options related to the bend and the bend relief are available in the **Bend** area. These options are discussed next.

Radius

The **Radius** edit box is used to specify the radius of the bend. By default, the bend radius value defined in the **Bend** tab of the **Style and Standard Editor [Library - Read Only]** dialog box is selected. You can also specify a new bend radius by entering a numeric value in this edit box.

Edges

The **Edges** button is chosen to select the edge that will be joined with the existing sheet metal component. If one of the edges of the sketch is coincident with an edge of the existing sheet metal part, the common edge will be automatically selected. However, if the edge of the sketch is not coincident with an edge of the sheet metal component, you will have to select the edge manually. You can also use this button to select additional faces that you want to add to the bend.

Figure 15-28 shows the sketch to be used for creating the face of a sheet metal component and Figure 15-29 shows the sheet metal component created after adding the face. Notice the bend and the bend relief created with the face.




Figure 15-28 Sketch for creating a new face of the sheet metal part




Figure 15-29 Sheet metal part after adding the new face

Figure 15-30 shows a sketch that has no edge coincident with the edge of the sheet metal part. Notice that in this figure, the edge of the sheet metal base is selected for creating the face. Figure 15-31 shows the sheet metal component created by using the given sketch.




Figure 15-30 Selecting the sketch and the edge for creating the face of the sheet metal part




Figure 15-31 Sheet metal part after creating the new face

Extend Bend Aligned to Side Faces

If you choose the **Extend Bend Aligned to Side Faces** button, the material will be added on the sides of the edges along the faces and not normal to the axis of the bend, as shown in Figure 15-32

Extend Bend Perpendicular to Side Faces

If you choose the **Extend Bend Perpendicular to Side Faces** button, the material will be added perpendicular to the side faces, as shown in Figure 15-



*Figure 15-32 Flange on the sheet metal part created when the **Extend Bend Aligned to Side Faces** button is chosen*



*Figure 15-33 Flange on the sheet metal part created when the **Extend Bend Perpendicular to Side Faces** button is chosen*

Unfold Options Tab

Choose the **Unfold Options** tab to specify the unfold style using the **Unfold Rule** drop-down list. If you have created a new unfold style as discussed earlier, then you can select it by using the **Unfold Rule** drop-down list, as shown in Figure 15-34.

Bend Tab

The options in the **Bend** tab are used to specify the parameters related to bend relief. By default, the options specified in the **Bend** tab of the **Style and Standard Editor [Library - Read Only]** dialog box are used. If you want to override the options specified in this dialog box, select an option other than the **Default (Straight)** option in the **Relief Shape** drop-down list. The options

available in the **Bend** tab are shown in Figure 15-35. These options are similar to those discussed in the **Style and Standard Editor [Library - Read Only]** dialog box, refer to Figure 15-7.




Figure 15-34 The Unfold Options tab of the Face dialog box




Figure 15-35 The Bend tab of the Face dialog box

FOLDING SHEET METAL COMPONENTS


Ribbon: Sheet Metal > Create > Fold

Autodesk Inventor allows you to fold sheet metal component by using the **Fold** tool. Remember that the sheet metal part will be folded with the help of a sketched line. Note that the line that you want to use should not extend beyond the face that you want to fold. On choosing the **Fold** tool from the **Create** panel of the **Sheet Metal** tab, the **Fold** dialog box will be displayed. The options in the

Fold dialog box are discussed next.

Shape Tab

The options in the **Shape** tab are used to specify the shape of the fold, refer to Figure 15-36. These options are discussed next.



*Figure 15-36 The **Shape** tab of the **Fold** dialog box*

Bend Line

The **Bend Line** button is chosen to select the bend line that will be used to fold the component. When you invoke the **Fold** dialog box, this button is chosen by default. Note that only the line that has both its endpoints at the edges of the sheet metal component can be selected to bend the component. As soon as you select the bend line, two green arrows are displayed on it. The straight arrow points in the direction of the portion of the sheet metal part that will be folded and the curved arrow points in the direction of bending.

Flip Controls Area

The buttons in this area allow you to reverse the direction of folding and the side of the sheet metal component to be folded. The **Flip Side** button is chosen to reverse the side of the sheet metal part that will be folded and the **Flip Direction** button is chosen to reverse the direction in which the sheet metal component will be folded.

Fold Location Area

The buttons in this area are chosen to specify the location of the bend with respect to the sketch line selected as the bend line. The three buttons in this area are discussed next.

Centerline of Bend

By default, the **Centerline of Bend** button is chosen in the **Fold Location** area. So, the bend line will be considered as the centerline of the bend and the bend will be created equally in both the directions of the bend line.

Start of Bend

If the **Start of Bend** button is chosen, the bend will be created such that the bend line is located at the start of the bend.

End of Bend

If the **End of Bend** button is chosen, the bend will be created such that the bend line is located at the end of the bend.

Fold Angle

The **Fold Angle** edit box is used to specify the angle of the fold for the sheet metal component. The default value in this edit box is 90.0. You can specify desired value in this edit box.

Bend Radius

The **Bend Radius** edit box is used to specify the radius of a bend. By default, the value specified in the **Bend** tab of the **Style and Standard Editor [Library - Read Only]** dialog box is taken as the bend radius. You can also enter any desired value in this edit box.

Figure 15-37 shows a line that will be used to fold the sheet metal part and Figure 15-38 shows the sheet metal part folded through an angle of 60 degrees.




Figure 15-37 Line for folding the sheet metal part




Figure 15-38 Sheet metal part folded through an angle of 60 degrees

Note

*The options in the **Unfold Options** and **Bend** tabs are the same as those discussed in the previous sections of this chapter.*

ADDING FLANGES TO SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Create > Flange

Autodesk Inventor allows you to directly add a folded face to the existing sheet metal component. This is done using the **Flange** tool. On invoking this tool, the **Flange** dialog box will be displayed. The options in the **Flange** dialog box are discussed next.

Shape Tab

The options in the **Shape** tab are used to set the parameters related to the shape of the flange, refer to Figure 15-39. These options are discussed next.

Edge Select Mode

The **Edge Select Mode** button is chosen by default and it allows you to select the edges on which the flanges will be attached.




Figure 15-39 The Shape tab of the Flange dialog box

Loop Select Mode

The **Loop Select Mode** button is used to select an edge loop and to create a flange on this loop. Figure 15-40 shows the edge loop selected on the top face of the base wall for creating flange and Figure 15-41 shows the flanges created on the selected loop.

Edges Area

The **Edges** area displays all the edges that have been selected to create a flange. Click in the **Edges** area to add new edges to attach the flange.




Figure 15-40 Edge loop selected on the top face of the base wall




Figure 15-41 Flanges created at an angle of 60 degrees on the selected loop

Height Extents Area

The **Height Extents** area allows you to specify the height of the flange wall. The drop-down list in this area has two options, **Distance** and **To**, which determine the height of the flange. If the **Distance** option is selected from the drop-down list, the height of the flange can be entered in the edit box below the drop-down list. If the **To** option is selected from the drop-down list, you will be prompted to select a point or vertex that terminates the flange.

Flip Direction

The **Flip Direction** button is chosen to reverse the direction of the flange. If you select an edge on the top face of the sheet metal component, by default, the flange will be created in the upward direction. But if you choose the **Flip Direction** button, the flange will be created in the downward direction. However, note that the selected edge will still be the starting edge of the flange.

Flange Angle

The **Flange Angle** edit box is used to specify the angle through which the flange

will be bent with respect to the sheet metal component. The default value in this edit box is 90.0 and therefore, the flange will be bent through an angle of 90-degree. The value of flange angle can vary from 0 to 180 degrees.

Tip. If a flange is created through an angle of 180 degrees, it will merge with the face of the sheet metal component and therefore will not be visible. However, if a flange is created through an angle of 170 degrees, it will create a face similar to a hem. The hems will be discussed later in this chapter.

Bend Radius

The **Bend Radius** edit box is used to enter the radius of the bend. By default, the value set in the **Sheet Metal Defaults** dialog box is taken as the bend value. However, you can specify a bend value of your choice by entering it in this edit box.

Height Datum Area

The options in this area allow you to specify the datum reference for measuring the height of the flange. These options are discussed next.

Bend from the intersection of the two outer faces

This button, if chosen, measures the height of the flange from the intersection of the outer faces.

Bend from the intersection of the two inner faces

This button, if chosen, measures the height of the flange from the intersection of the inner faces.

Parallel to the flange termination detail face

This button, if chosen, measures the height of the flange parallel to its face and tangent to the bend.

Aligned VS Orthogonal

This button, if chosen, measures the height of the flange aligned with the flange face or orthogonal to the base face.

Bend Position Area

The buttons in this area are used to specify the position of the bend relative to the face containing the selected edge. These options are discussed next.

Inside of base face extents

This button, if chosen, creates the bend in such a way that the inner face of the flange is aligned with the extended selected edge.

Bend from the adjacent face

This button, if chosen, creates the bend starting from the selected edge.

Outside of base face extents

This button, if chosen, aligns the outer face of the flange with the intersection of the outer face and the selected edge.

Bend Tangent To Side Face

The **Bend Tangent To Side Face** button is chosen to create a flange that is tangent to the side face of a sheet metal component.

Figure 15-42 shows the edge being selected for creating a flange and Figure 15-43 shows the sheet metal component after creating flange.




Figure 15-42 Selecting the edge for creating the flange




Figure 15-43 Sheet metal component after creating the flange at an angle of 60 degrees

More (>>) Button

The **More** button is available at the lower right corner of the **Flange** dialog box. When you choose this button, the **Flange** dialog box expands showing more options. These options are discussed next.

Width Extents Area

The options in the **Width Extents** area are used to set the parameters related to the width of a flange, refer to Figure 15-44. These options are provided in the **Type** drop-down list and are discussed next.




Figure 15-44 The Width Extents area of the Flange dialog box

Edge

The **Edge** option is selected by default in the **Type** drop-down list. This option ensures that the flange is created along the whole length of the edge selected from the sheet metal component.

Width

The **Width** option is used to create a flange of specified width on the selected edge and at a specified offset distance. If you select this option, the **Centered** and **Offset** radio buttons will be available. The **Centered** radio button will be selected by default and the **Width** edit box will be displayed. On specifying the width of the flange in the **Width** edit box, the flange will be created at the center of the specified width on the selected edge. If the **Offset** radio button is selected, you can create flange by specifying the offset distance from the faces of the selected edge. You can select a face for specifying the offset by choosing the **Offset1** button from the **Width Extents** area of the **Flange** dialog box. Figure 15-45 shows a flange created at an offset of **10 mm** from the selected start point and with a width of **25 mm**. Notice the bend relief that is automatically created on both the sides.

Offset

The **Offset** option is selected to define the width of a flange in terms of offset from two points on the selected edge. On invoking this option, the **Offset1** and **Offset2** edit boxes will be displayed in the **Width Extents** area. By default, the start point and endpoint of the flange will be selected. You can change the start point and endpoint of the flange by choosing the **Offset 1** and **Offset 2** buttons and then selecting the required points/vertices from the sheet metal part. You can define the offset from the start point and the endpoint in the **Offset1** and **Offset2** edit boxes, respectively. Based on the two offset values and the known length of the edge, the width of the flange is automatically calculated. Figure 15-46 shows a flange created with the **Offset1** value, 20 mm and the **Offset2** value 10 mm.




Figure 15-45 Flange created at an offset of 10 mm and width of 25 mm




Figure 15-46 Flange created with **Offset1** = 20 mm and **Offset2** = 10 mm

From To

This option, if selected, allows you to create a flange with the width defined by selecting an existing geometry.

Design Area

The **Old Method** check box allows you to edit the flanges that were created in releases prior to the Autodesk Inventor 2009 release by using the options used when the component was first created. This check box remains clear for all the components created in Autodesk Inventor 2009 and later releases. As a result, you have more control over the bend measurement and its positioning. If you want to edit the component with the features available in Autodesk Inventor 2009, clear this check box and continue editing it.

Note

*The options in the **Unfold Options**, **Bend**, and **Corner** tabs of the **Flange** dialog box are similar to those discussed in the previous sections of this chapter.*

*Tip. You can create two flanges using the **Flange** tool such that they form a corner. When you do so, the **Corner Seam** icon will be displayed at the corner. If you click on this icon, the **Corner Edit** dialog box will be displayed. You can specify the required corner seam and corner type using this dialog box.*

CREATING CUTS IN SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Modify > Cut

You can create any type of cut in a sheet metal component by drawing its sketch and then cutting it by using the **Cut** tool. Note that if you invoke this tool without creating a sketch, you will be informed that there is no unconsumed sketch. On invoking this tool, the **Cut** dialog box will be displayed, as shown in Figure 15-47. The options in this dialog box are discussed next.

Shape Area

The options in the **Shape** area are used to specify the shape of the cut. These options are discussed next.




Figure 15-47 The Cut dialog box

Profile

The **Profile** button is chosen to select the profile of the cut. This button is chosen by default in the **Cut** dialog box. If there is only one unconsumed sketch on the sheet metal part, it will be automatically selected for creating the cut. However, if there are more than one unconsumed sketches, you will be prompted to select the profile.

Solids


This option has already been discussed.

Cut Across Bend


The **Cut Across Bend** check box is selected to cut the material to a required

depth or throughout the thickness of the sheet across the bend of the sheet metal component. If you select this check box, the drop-down list in the **Extents** area will not be available. The edit box below the drop-down list allows you to specify the thickness for the cut feature.

Figure 15-48 shows the cut feature on sheet metal component when the **Cut Across Bend** check box is cleared and Figure 15-49 shows the sheet metal component when the **Cut Across Bend** check box is selected.



*Figure 15-48 Cut feature on the sheet metal component when the **Cut Across Bend** check box is cleared*



*Figure 15-49 Cut feature on the sheet metal component when the **Cut Across Bend** check box is selected*

Cut Normal

The **Cut Normal** check box is selected to cut the material normal to bend face to a required depth or throughout the thickness of the sheet metal component. If you select this check box, the drop-down list in the **Extents** area will be activated. It allows you to specify the termination of the material for the cut feature and it is normal to the profile or the sketch plane. In this case, the termination distance is equal to the default thickness of the sheet.

Figure 15-50 shows the cut feature on sheet metal component when the **Cut Normal** check box is cleared and Figure 15-51 shows the sheet metal component when the **Cut Normal** check box is selected.




Figure 15-50 Cut feature on the sheet metal when the **Cut normal** check box is cleared




Figure 15-51 Cut feature on the sheet metal when the **Cut normal** check box is selected

Extents Area

The options in the **Extents** area are used to specify the extents of the cut. The options in this drop-down list are similar to those discussed for the solid model components. Note that the options in this area will not be available when the **Cut Across Bend** check box is selected.


CREATING SEAMS AT THE CORNERS OF SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Modify > Corner Seam

Autodesk Inventor allows you to create corner seams in a sheet metal component with the help of the **Corner Seam** tool. On invoking this tool, the **Corner Seam** dialog box will be displayed. The options in this dialog box are discussed next.

Shape Tab

The options in the **Shape** tab are used to set the parameters related to the shape of a seam, refer to Figure 15-52. These options are discussed next.



*Figure 15-52 The **Shape** tab of the **Corner Seam** dialog box*

Shape Area

The options in the **Shape** area are used to create a corner seam or a corner rip by selecting edges using the **Edges** button. These options are discussed next.

Seam

The **Seam** radio button is selected when you want to create a seam between two existing coplanar or intersecting faces of a sheet metal component.

Rip

The **Rip** radio button is selected when you want to rip a corner of a solid component that has three faces meeting at a corner. This is generally used when you want to convert a shelled solid model into a sheet metal component and rip its corner in order to open it. Note that the thickness of the component must be equal to the thickness specified in the **Sheet Metal Defaults** dialog box. To rip a corner of such a component, select the vertical edge at the corner. Figure 15-53 shows a shelled solid model component before ripping the corners and Figure 15-54 shows a solid model component converted into a sheet metal component with the ripped corners. The **Flat Pattern** and **Bend** tools are discussed later in this chapter.




Figure 15-53 Model before ripping the corners




Figure 15-54 Model after ripping the corners

Edges

The **Edges** button is chosen to select the edges for creating the corner seam. In the **Corner Seam** dialog box, the **Edges** button is chosen by default and no option is available in the **Seam** area. The options in the **Seam** area will be available only after you have selected the edges for creating the corner seam.

*Tip. To convert a solid model into a sheet metal component, first you need to shell it. Remember that the wall thickness in the shell should be equal to or less than the thickness of the active sheet specified in the **Style and Standard Editor [Library - Read Only]** dialog box or the **Sheet Metal Defaults** dialog box. After shelling the component, choose the **Convert to Sheet Metal** button from the **Convert** panel of the **3D Model** tab. Next, rip its corners by using the **Corner Seam** tool.*

Seam Area

The options in this area are discussed next.

Maximum Gap Distance

Select this radio button to create a seam between two edges.

Face/Edge Distance

Select this radio button to create a seam between an edge and a face.

Symmetric Gap

This button will be available only when the **Maximum Gap Distance** radio button is selected. This is the first button in the **Seam** area and if chosen, creates a seam in such a way that the distance between the seamed material and the nearest intersecting corner is symmetric.

No Overlap

This button will be available only when the **Face/Edge Distance** radio button is selected. This button is chosen by default and ensures that there is no overlapping of the faces whose edges are selected for creating the corner seam. Figure 15-55 shows the two edges to be selected for creating the corner seam and Figure 15-56 shows the sheet metal component after creating the corner seam. Notice that there is no overlapping of the faces. Also, the bend relief in both the faces is automatically adjusted with reference to the corner seam.




Figure 15-55 Edges to be selected for creating a corner seam




Figure 15-56 Model after creating the corner seam

For example, to create a corner seam between the edges, select the **Maximum Gap Distance** radio button and then choose the **Symmetric Gap** button, refer to Figure 15-57. Next, specify the gap of 1mm in the **Gap** edit box; the gap between Edge 1 and Edge 2 in the resultant model will become 1mm.




Figure 15-57 Reference edges and faces for creating the corner seam

Similarly, to create a corner seam between the edges, select the **Face/Edge Distance** radio button and then choose the **No Overlap** button, refer to Figure 15-57. Next, specify the gap of 1mm in the **Gap** edit box; the gap between Edge 1 and Face 2 in the resultant model will become 1mm.

Overlap

The **Overlap** button is provided on the right of the **No Overlap/Symmetric Gap** button. If this button is chosen, the face defined by the first selected edge will overlap the face defined by the second selected edge, refer to Figure 15-

58. In this figure, the sequence of selection of edges is the same as that of selection of edges in Figure 15-55.

Reverse Overlap

If the **Reverse Overlap** button is chosen, the face defined by the second selected edge will overlap the face defined by the first selected edge, as shown in Figure 15-59. The sequence of selection of edges is the same as that of selection of edges in Figure 15-55.




Figure 15-58 Overlapping of faces



Figure 15-59 Reverse overlapping of faces

Percent Overlap

This edit box is available if you choose the **Overlap** or the **Reverse Overlap** button. This edit box is used to specify the percentage of the overlap using the decimal values 0 to 1.

Gap

The **Gap** edit box is used to specify the gap between two faces in the corner seam. You can enter any desired value in this edit box.

Miter Area

The **Seam** area is replaced by the **Miter** area, if the edges selected to define corner seam are coplanar and perpendicular to each other, as shown in Figure 15-60. The options in this area are similar to those discussed earlier in the **Seam** area.

You can create different models using different buttons in the **Miter** area, as shown in Figures 15-61 through 15-63.

Note

*The options in the **Bend** and **Corner** tabs are the same as those discussed in the previous sections of this chapter.*




Figure 15-60 Selecting the edges to create a miter corner




Figure 15-61 A 45-degree miter corner




Figure 15-62 Overlap miter corner




Figure 15-63 Reverse overlap miter corner

BENDING THE FACES OF A SHEET METAL COMPONENT

Ribbon: Sheet Metal > Create > Bend

Autodesk Inventor allows you to add a new bent face between two existing faces. This is done by using the **Bend** tool. On invoking this tool, the **Bend** dialog box will be displayed. The options in this dialog box are discussed next.

Shape Tab

The options in the **Shape** tab are used to set the parameters related to the shape of a bent face, refer to Figure 15-64. These options are discussed next.




Figure 15-64 The Shape tab of the Bend dialog box

Bend Area

The options in this area are discussed next.

Edges

The **Edges** button is chosen to select the edges on the two faces between which the bent face will be added. By default, this button is chosen in the **Bend** dialog box and you are prompted to select the edge. Remember that until you select the edges for creating the bent face, the options in the **Double Bend** area will not be available.

Bend Radius

The **Bend Radius** edit box is used to specify the radius of the bend. The default value of this edit box is the bend radius specified in the **Style and Standard Editor [Library - Read Only]** dialog box. However, you can override this value by entering a new value in the **Bend Radius** edit box.

Double Bend Area

The options in the **Double Bend** area are used to specify the shape of bend.

Fix Edges

The **Fix Edges** radio button is selected to create bends of equal dimensions at the selected edges. Note that when you select the edges for defining the bend, the edge selected first is taken as the fixed edge. While creating the bent face,

if the sizes of the two selected edges are different, the size of the fixed edge and the face defined by this edge remains constant by default. However, the size of the other edge and the face defined by it is either trimmed or extended in order to adjust the new face.

45 Degree

The **45 Degree** radio button is selected to create 45-degree bend between the selected edges. Figure 15-65 shows the 45-degree bend created between the selected edges.

Full Radius

The **Full Radius** radio button is selected to create a half circle bent face between two selected edges. Figure 15-66 shows the two edges to be selected for creating the bend and Figure 15-67 shows a full radius bend created between the selected faces. Notice that in Figure 15-67, the face defined by the second edge has been modified to adjust the new bent face.

90 Degree

The **90 Degree** radio button is selected to create a 90-degree bend between selected edges, as shown in Figure 15-68. In this figure, the sequence of selecting edges is the same as that of selecting edges in Figure 15-66.




Figure 15-65 The 45-degree bend between the selected edges




Figure 15-66 Edges to be selected to create bend

Flip Fixed Edge

The **Flip Fixed Edge** check box is chosen to change the fixed edge. As mentioned earlier, the edge selected first is taken as the fixed edge and the face defined by the other edge is modified to adjust the new bent face. However, if you choose this button, the edge selected second will be taken as the fixed edge and the face defined by the first edge will be modified to adjust the new bent face.




Figure 15-67 A full radius bent face




Figure 15-68 *The 90-degree bend*

Bend Extension Area

The options in this area are discussed next.

Extend Bend Aligned to Side Faces

If you choose the **Extend Bend Aligned to Side Faces** button, material will be added on the sides of the edges along the faces and not normal to the axis of the bend.

Extend Bend Perpendicular to Side Faces

This button is chosen by default in the **Bend** dialog box. As a result, the bend material is extended perpendicular to the bend axis.

Note

*The options in the **Unfold Options** and **Bend** tabs are the same as those discussed in the previous sections of this chapter.*

ROUNDING THE CORNERS OF SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Modify > Corner Round

The corners of a sheet metal component can be rounded by using the **Corner Round** tool. You can use this tool to round a single selected corner or all corners of a selected face. On invoking this tool, the **Corner Round** dialog box will be

displayed, as shown in Figure 15-69. The options in this dialog box are discussed next.

Corner

The **Corner** column lists the number of corners that are selected to be rounded. When you invoke the **Corner Round** dialog box, you are prompted to select a corner to be rounded. By default, this column displays **0 Selected** as no corner is selected for rounding. To round a corner, select the edge that defines the corner of the sheet metal plate. When you select a corner, this column displays **1 Selected**. Similarly, if you select more corners, the **Corner** column lists the number of corners that you have selected. You can preview the corner round on the graphics screen.




Figure 15-69 The Corner Round dialog box

Radius

The **Radius** column displays the radius of the corner round. To modify the radius, enter new radius in the edit box that is displayed when you click on the value in the **Radius** column.

Select Mode Area

The options in the **Select Mode** area are used to specify the mode for selecting object to be filleted. The options in this area are discussed next.

Corner

The **Corner** radio button is selected by default in the **Select Mode** area and it allows you to individually select the corners to be rounded.

Feature

The **Feature** radio button is used to select a feature whose all corners will be rounded. On selecting this radio button, you will be prompted to select the feature to be rounded. As soon as you select a feature, you will notice that all its corners are selected. Note that if a feature has some faces that are folded then the corner of those faces will also get selected. Figure 15-70 shows a feature being selected for rounding the corners. Notice that the dotted lines display the original feature before the face is folded. Figure 15-71 shows the sheet metal component after all corners of the selected feature are rounded. Because the two flanges were not a part of the actual base feature, their corners are not rounded.




Figure 15-70 Selecting the feature to be rounded





Figure 15-71 Feature after rounding all corners

CHAMFERING THE CORNERS OF SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Modify > Corner Chamfer

You can chamfer the corners of a sheet metal component by using the **Corner Chamfer** tool. On invoking this tool, the **Corner**

Chamfer dialog box will be displayed, as shown in Figure 15-72. The options in this dialog box are discussed next.



*Figure 15-72 The **Corner Chamfer** dialog box*

One Distance

The **One Distance** is the first button in the **Corner Chamfer** dialog box. This button is chosen by default and is used to create a chamfer with an equal distance in both the directions of the chamfer corner. This option is used to create a chamfer at a 45-degree angle. The chamfer distance can be specified in the **Distance** edit box that is available in the area that is on the extreme right of this dialog box.

Distance and Angle

The **Distance and Angle** button is provided below the **One Distance** button. This button is chosen to define the chamfer by using one distance and one angle value. When you choose this button, the **Edge** button will be displayed in the area that is in the middle of the **Corner Chamfer** dialog box and you are prompted to select a face to be chamfered. This is the face along which the distance value will be calculated. On selecting the face, you will be prompted to select the corner to be chamfered. Select the edge from the sheet metal component; the corner chamfer will be created. You can define the distance value in the **Distance** edit box and the angle value in the **Angle** edit box. These edit boxes will be displayed in the area located on the extreme right of the **Corner Chamfer** dialog box.

Two Distances

The **Two Distances** button below the **Distance and Angle** button is used to create a chamfer by defining the two distances of the chamfer. The two distances

can be entered in the **Distance1** and **Distance2** edit boxes. These edit boxes are displayed in the area located on the extreme right of the **Corner Chamfer** dialog box. Choose the **Flip Direction** button available below the **Corner** button to flip the distance values. Figure 15-73 shows a sheet metal component before chamfering the corners and Figure 15-74 shows the component after chamfering the corners.




Figure 15-73 Component before chamfering




Figure 15-74 Component after chamfering

PUNCHING 3D SHAPES INTO SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Modify > Punch Tool

You can punch a 3D shape into a sheet metal component using the **Punch Tool** tool. Note that a 3D shape can be punched only on a sketched point, endpoints of a line or an arc, or center points of arcs and circles. Therefore, you need to create any of these entities before invoking this tool. On invoking this tool, the **Punch Tool Directory** dialog box will be displayed, as shown in Figure 15-75. Using

this dialog box, you can select a predefined punch tool from the punch tool library.

Select a predefined punch tool and then choose the **Open** button from the **PunchTool Directory** dialog box; the **PunchTool** dialog box will be displayed. This dialog box has three tabs that allow you to set the parameters for the punch. You can also choose the **Cancel** button from the **PunchTool Directory** dialog box to exit it and accept the default punch tool. Select the **Across Bend** check box to create a punch across the bends of the sheetmetal component.





Figure 15-75 The PunchTool Directory dialog box

Preview Tab

The **Preview** tab is the first tab that is displayed when you invoke this dialog box, refer to Figure 15-76. The options in this tab allow you to select the shape to be punched on the sheet metal component. The options in this tab are discussed next.



*Figure 15-76 The **Preview** tab of the **PunchTool** dialog box*

Location


The **Location** display box is activated only when you choose the **Cancel** button from the **PunchTool Directory** dialog box. It displays the name and path of the selected 3D punch shape. To select a new punch shape library file, choose the **Select PunchTool Library Folder** button. When you choose this button, the **PunchTool Directory** dialog box is displayed. You can use this dialog box to select the library file that stores the punch shapes. The library file and its path will be displayed in the **Location** display box. If you have already selected the 3D punch shape in the **PunchTool Directory** dialog box, then the **Location** display box and the **Select PunchTool Library Folder** will not be available.

Punch Area

The list box in the **Punch** area displays the list of the punch shapes available in the selected library file. You can select the required punch shape from the list box. On doing so, its preview will be displayed in the preview window on left of this list box.

Geometry Tab

The options in the **Geometry** tab are used to specify the location and orientation of the punch shape, refer to Figure 15-77. As soon as you select the location of the punch shape, its preview will be displayed on the screen. You can change the orientation of the punch shape by entering its value in the **Angle** edit box.



*Figure 15-77 The **Geometry** tab of the **PunchTool** dialog box*

Size Tab

The **Size** tab of the **PunchTool** dialog box is used to modify the dimensions of the punch shape. The name and the value of the dimension are displayed under the **Name** column and the **Value** column, respectively, as shown in Figure 15-78. To modify a dimension value, click on its field; the field will turn into an edit box or a drop-down list. If it turns into an edit box, you can enter value in it. If the field turns into a drop-down list, you can select value from the drop-down list. After setting dimensions, choose the **Finish** button to exit the dialog box and punch the shape into the sheet metal component.

Figure 15-79 shows a sheet metal component after punching the keyway into the flange face.




Figure 15-78 The **Size** tab of the **PunchTool** dialog box




Figure 15-79 Sheet metal component after punching the keyway


CREATING HEMS

Ribbon: Sheet Metal > Create > Hem

Hem is a folded part created on a face of a sheet metal component. Hems are created to strengthen a sheet metal component or to remove its sharp edges. Hems make a sheet metal component easy to handle and assemble. You can create hems by using the **Hem** tool. Choose the **Hem** tool from the **Create** panel of the **Sheet Metal** tab; the **Hem** dialog box will be invoked. The options in this dialog box are discussed next.

Shape Tab

The options in the **Shape** tab are used to set the parameters related to the shape of a hem, refer to Figure 15-80. These options are discussed next.



*Figure 15-80 The **Shape** tab of the **Hem** dialog box*

Type

The **Type** drop-down list provides the types of hems that can be created. These options are discussed next.

Single

The **Single** is the default hem type and is used to create a single hem, as shown in Figure 15-81.

Teardrop

The **Teardrop** type is used to create a teardrop hem, as shown in Figure 15-82.




Figure 15-81 Single hem on flanges




Figure 15-82 Teardrop hem on flanges

Rolled

The **Rolled** type is used to create a rolled hem that does not have a face extending beyond a curve, as shown in Figure 15-83.

Double

The **Double** type is used to create a double hem by rotating the hem twice, as shown in Figure 15-84. This type of hem does not have any shared edge; therefore, it is very easy to handle.




Figure 15-83 Rolled hem on flanges




Figure 15-84 Double hem on flanges

Shape Area

The options in this area are discussed next.

Select Edge

When you invoke the **Hem** dialog box, this button is chosen by default and you are prompted to select the edge. Select the required edge; the hem will be created. Note that you can select only one edge at a time for creating hem. After selecting an edge, set parameters and choose the **Apply** button to create hem. Once the hem has been created on one edge, this button will be chosen automatically and you will be prompted to select another edge to create hem.

Flip Direction

The **Flip Direction** button is chosen to reverse the direction of a hem.

Gap/Radius

The **Gap** edit box is used to set the value of the gap of a hem for single hem type or double hem type. The default value in this edit box is $\text{Thickness} \times 0.50$. You can enter any desired value as the gap of the hem in this edit box. This edit box is replaced with the **Radius** edit box for the teardrop and rolled hems and is used to define the radius of the teardrop or rolled hem.

Length/Angle

The **Length** edit box is used to set the length of hem for a single hem type or double hem type. The default value in this edit box is $\text{Thickness} \times 4.0$. You can enter any desired value as the length of the hem in this edit box. This edit box

is replaced with the **Angle** edit box for the teardrop and rolled hems and is used to define the angle of teardrop or rolled hem. The angle value can vary from 181 degrees to 359 degrees.

Note

1. *The options in the **More** area are the same as those discussed in the **Flange** dialog box.*
2. *The options in the **Unfold Options** and **Bend** tabs are the same as those discussed in the **Sheet Metal Defaults** dialog box.*

CREATING CONTOUR FLANGES

Ribbon: Sheet Metal > Create > Contour Flange

Contour flanges are created by using an open sketch. To create a contour flange, first you need to create an open sketch. After creating the sketch, invoke the **Contour Flange** tool; the **Contour Flange** dialog box will be displayed. The options in this dialog box are discussed next.

Shape Tab

The options in the **Shape** tab are used to set the parameters related to the shape of a contour flange, refer to Figure 15-85. These options are discussed next.

Profile

The **Profile** button is chosen to select the profile that will be used to create the contour flange. When you invoke the **Contour Flange** dialog box, this button is chosen by default and you are prompted to select an open profile.

Solids

This option has already been discussed in detail earlier in this chapter .




Figure 15-85 The *Shape* tab of the *Contour Flange* dialog box

Join

This button is used to join the contour flange with the existing sheet metal component.

New Solid

This button is used to create contour flange as a new sheet metal component.

Edges Area

The options in this area are discussed next.

Edge Select Mode

The **Edge Select Mode** button is chosen by default and allows you to specify the edges on which the flanges will be attached.

Loop Select Mode

This button allows you to select an edge loop and creates a flange attached to all selected edges.

Edges

This list box displays the number of edges that have been selected to create a

flange.

Bend Area

The options in this area are discussed next.

Radius

The **Radius** edit box is used to set the value of the radius of the bend in the contour flange.

Extend Bend Aligned to Side Faces

If you choose the **Extend Bend Aligned to Side Faces** button, the material is added on the sides of the edges along the faces and not normal to the axis of the bend.

Extend Bend Perpendicular to Side Faces

This button is chosen by default in the **Contour Flange** dialog box. As a result, the bend material extends perpendicular to the bend axis.

Offset Direction Area

The three buttons in this area are used to specify the direction for adding material to create a counter flange.

More (>>)

The **More** button is the button with two arrows and is available at the lower right corner of the **Contour Flange** dialog box. When you choose this button, the **Contour Flange** dialog box expands and displays the **Width Extents** area. This area has the **Type** drop-down list for specifying the extents of the flange. All the options in this drop-down list, except for the **Distance** option, are the same as those discussed in the previous sections of this chapter. The **Distance** option is discussed below.

Distance

The **Distance** option is used to specify the distance of the contour flange. When you select this option, the **Distance** edit box appears in the **Width Extents** area. You can define the distance of the contour flange in this edit box. You can reverse the direction of the flange creation by choosing the buttons available below the **Distance** edit box.

Figure 15-86 shows the profile and the edge selected for creating contour flange and Figure 15-87 shows the resulting contour flange.




Figure 15-86 The profile and the edge selected




Figure 15-87 The resulting contour flange

Note

*The options in the **Unfold Options**, **Bend**, and **Corner** tabs are the same as those discussed in the previous sections of this chapter.*

CREATING THE FLAT PATTERNS OF SHEET METAL COMPONENTS

Ribbon: Sheet Metal > Flat Pattern > Create Flat Pattern

You can unfold the sheet metal components by using the **Create Flat Pattern**

tool. On invoking this tool, the sheet metal component will be unfolded and displayed in the graphics window. Note that the modifications made in the unfolded sheet metal component will not be reflected in the folded model. However, if you make any changes in the sheet metal component, they will be reflected in the flat pattern. When you create the flat pattern, it is added in the **Browser Bar** below all features of the sheet metal component. Figure 15-88 shows a sheet metal component and Figure 15-89 shows the flat pattern of the same component.




Figure 15-88 Sheet metal part




Figure 15-89 Flat pattern of the sheet metal part

Adding or Removing Material from the Flat Pattern

This feature allows you to add or remove material from the flat patterned sheet metal component. When you create the flat pattern of a component, notice that the **Sheet Metal** tab is replaced by the **Flat Pattern** tab, displaying the tools that can be used to add or remove material from the flat pattern sheet metal component. The tools that can be used for this purpose are **Extrude**, **Revolve**, **Hole**, and so on. After creating the flat pattern, choose the **Create 2D Sketch** tool from the

Sketch panel of the **Flat Pattern** tab and select the required face as the sketching plane. Remember that you cannot select the existing default datum planes from the **Browser Bar**. On selecting a face to create a feature, the **Autodesk Inventor Professional** message box will be displayed informing you about the exclusive application of the edits to the flat pattern without affecting the folded model. Choose the **OK** button from the **Autodesk Inventor Professional** message box; the sketcher environment will be activated. Create the sketch and exit the sketched environment. Now, invoke the flat pattern editing feature tools such as **Extrude**, **Revolve**, or other features from the **Flat Pattern** tab and complete creating the feature. Figure 15-90 shows a sheet metal component with flange walls and Figure 15-91 shows its flat pattern with an extruded cut feature and two hole features.




Figure 15-90 Sheet metal component with flange walls




Figure 15-91 Flat pattern with an extruded cut and two hole features

Tip. To activate a folded model after creating the flat pattern of a sheet metal component, double-click on the **Folded Model** node in the **Browser Bar**. Similarly, to invoke the flat pattern of a sheet metal, double-click on the **Flat Pattern** node in the **Browser Bar**. You can also use the **Ribbon** to switch between the folded model and flat pattern of a sheet metal component. To activate a folded model, choose the **Go To Folded Part** tool from the **Folded Part** panel of the **Flat Pattern** tab in the **Ribbon**. To switch to the flat pattern of the model, choose the **Go To Flat Pattern** tool from the **Flat Pattern** panel of the **Sheet Metal** tab.

TUTORIALS

Tutorial 1

In this tutorial, you will create the sheet metal component of the Holder Clip shown in Figure 15-92a. Its views and dimensions are shown in Figures 15-92b and 15-92d. The thickness of the sheet is 1 mm. The flat pattern of the component is shown in Figure 15-92c. After creating the sheet metal component, create its flat pattern. **(Expected time: 45 min)**




Figure 15-92a Sheet metal component of the Holder Clip




Figure 15-92b Top view of the Holder Clip




Figure 15-92c Flat pattern of the component




Figure 15-92d Front view of the Holder Clip

The following steps are required to complete this tutorial:

- Start a new metric sheet metal file and then draw the sketch of the top face of

the sheet metal component.

- b. Set parameters in the **Sheet Metal Defaults** dialog box and convert the sketch into the sheet metal face.
- c. Add the contour flange on the right and left faces of the top feature.
- d. Add the contour flange on the front face of the feature.
- e. Create a cut feature on the front face of the new flange and then add another face and chamfer it.
- f. Create the last flange and then create two holes. Finally, create the flat pattern.

Opening a New Metric Sheet Metal File

1. Start Autodesk Inventor 2016 and invoke the **Create New File** dialog box.
2. Choose the **Metric** tab and then double-click on the **Sheet Metal (mm).ipt** option to start a new metric sheet metal file.
3. Invoke the sketching environment by selecting the **XY** plane from the **Browser Bar**. Now, you can draw the sketch of the top face of the sheet metal component.

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*
 2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*
4. Draw the sketch of the top face of the Holder Clip, as shown in Figure 15-93.

Note

In Figure 15-93, grid lines are hidden for the sake of clarity of the sketch.

5. Exit the Sketching environment by choosing the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab.

Converting the Sketch into the Sheet Metal Face

Before converting the sketch into the sheet metal face, it is recommended that you set parameters in the **Style and Standard Editor [Library-Read Only]** dialog box. These parameters control the thickness of sheet, radius of bend, parameters of relief, and so on.

1. Choose the **Sheet Metal Defaults** tool from the **Setup** panel of the **Sheet Metal** tab to invoke the **Sheet Metal Defaults** dialog box. Choose the **Edit Sheet Metal Rule** button from the dialog box; the **Style and Standard Editor [Library-Read Only]** dialog box is invoked.

In the **Style and Standard Editor [Library-Read Only]** dialog box, the **Sheet** tab is chosen by default. You can set the parameters related to the thickness of the sheet using this tab. Since all other parameters are based on the thickness of the sheet, they automatically change when you change the thickness of the sheet.

2. Enter **1** in the **Thickness** edit box of the **Sheet** area.
3. Choose **Save** and then **Done** to save the changes and exit the **Style and Standard Editor [Library-Read Only]** dialog box. Next, choose the **Cancel** button from the **Sheet Metal Defaults** dialog box and exit the dialog box.
4. Choose the **Face** tool from the **Create** panel of the **Sheet Metal** tab; the **Face** dialog box is invoked.

As there is only one unconsumed sketch, it is automatically selected and highlighted.

5. Choose **OK** to create the face and exit the **Face** dialog box. Change the current view to the isometric view, if it is not set to isometric. The isometric view of the Holder Clip is shown in Figure 15-94.




Figure 15-93 Sketch of the top face of the Holder Clip




Figure 15-94 Isometric view of the Holder Clip

Creating the First Contour Flange

As mentioned earlier, a contour flange is created with the help of a sketched contour. Therefore, first you need to sketch the contour so that it can be used to create a flange.

1. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab and then select the face as the sketching plane, as shown in Figure 15-95.
2. Draw the sketch of the contour flange, as shown in Figure 15-96.
3. Exit the sketching environment. Choose the **Contour Flange** tool from the **Create** panel of the **Sheet Metal** tab; the **Contour Flange** dialog box is invoked. In this dialog box, the **Profile** button in the **Shape** tab is chosen by default. As a result, you are prompted to select the profile for creating the contour flange.

4. Select one of the two sketched lines as the profile for creating the flange. As the other line is a part of the same sketch, it is selected automatically and turns blue.

As soon as you select the profile, the **Edge Select Mode** button in the **Edges** area is chosen and you are prompted to select the edge on which the flange will be created.




Figure 15-95 Face to be selected as the sketching plane




Figure 15-96 Sketch of the contour flange

5. Select the edge on the right of the top face to create the flange, refer to Figure 15-96.
6. Accept the remaining default options and choose **OK** to create the flange. You will notice that a bend is automatically created between the base sheet and the flange. The dimensions and parameters of this bend are taken from the

parameters defined in the **Style and Standard Editor [Library - Read Only]** dialog box.

7. Similarly, create the second contour flange on the other side of the top face. You may need to flip the direction of the contour flange by using the **Flip Side** button, which is the middle button in the **Offset Direction** area of the **Shape** tab. On choosing this button, the front face of the flange becomes coplanar with the left face of the base sheet. The sheet metal model of the Holder Clip after creating the two contour flanges is shown in Figure 15-97.




Figure 15-97 Sheet metal component after creating the two contour flanges

Creating the Third Contour Flange

1. Define a new sketch plane on the planar face of the base feature and then create the sketch for the contour flange, as shown in Figure 15-98.




Figure 15-98 The sketch plane and the sketch for the contour flange




Figure 15-99 Sheet metal component after creating the contour flange

2. Exit the sketching environment. Next, choose the **Contour Flange** tool from the **Create** panel of the **Sheet Metal** tab; the **Contour Flange** dialog box is invoked. In this dialog box, the **Profile** button in the **Shape** tab is chosen by default. As a result, you are prompted to select the profile for creating the contour flange.
3. Select the sketch created in step 1 as the contour for creating the flange. As soon as you select the profile, the **Edge Select Mode** button in the **Edges** area is chosen and you are prompted to select the edge on which the flange will be created.
4. Select the horizontal edge on the top face to create the flange.
5. Choose the middle **Flip Side** button to reverse the direction along which the face of the flange needs to be created.
6. Accept the remaining default options and choose **OK** to create the flange. The sheet metal component after creating the third contour flange is shown in Figure 15-99.

Creating a Cut and a New Face on the Front Face of the Third Contour Flange

1. Define a new sketch plane on the front face of the third contour flange and create the sketch of the cut feature, as shown in Figure 15-100. After creating the sketch, exit the sketching environment.

2. Invoke the **Cut** tool and then create the cut feature by selecting the **All** option from the drop-down list in the **Extents** area of the **Cut** dialog box. The sheet metal component after creating the cut is shown in Figure 15-101.




Figure 15-100 Sketch of the cut feature




Figure 15-101 Model after creating the cut feature

3. Similarly, again define a sketch plane on the front face of the third contour flange and create a new rectangular face by using the **Face** tool, refer to Figure 15-92d for dimensions.
4. Next, add the corner chamfer by using the **Corner Chamfer** tool, as shown in Figure 15-102, refer to Figure 15-92d for dimensions.




Figure 15-102 Sheet metal component after creating the new face and the corner chamfer

Creating the Flange

1. Choose the **Flange** tool from the **Create** panel in the **Sheet Metal** tab; the **Flange** dialog box is displayed and you are prompted to select the edge for creating the flange.
2. Select the edge on the top face of the base feature, as shown in Figure 15-103.
3. Enter **19** in the **Distance** edit box; the size of the flange in the preview is modified.
4. Choose the **Flip Direction** button from the **Flange** dialog box to flip the direction of the flange.
5. Accept the remaining default options and choose the **OK** button to create the flange and exit the dialog box. The sheet metal component after creating the flange is shown in Figure 15-104.




Figure 15-103 Selecting the edge to create the flange




Figure 15-104 Model after creating the flange

Creating Rounds and Holes

1. Create all rounds by using the **Corner Round** tool, refer to Figures 15-92b and 15-92d for dimensions.
2. Create two holes by using the **Hole** tool from the **Modify** panel of the **Sheet Metal** tab, refer to Figures 15-92b and 15-92d for dimensions.

This completes the creation of the sheet metal component of the Holder Clip. The final sheet metal component of the Holder Clip is shown in Figure 15-105.

3. Save the sheet metal component with the name *Tutorial1.ipt* at the location *C:\Inventor_2016\c15*.

Creating the Flat Pattern

The flattened view of a sheet metal component plays a very important role in the process of planning and designing the punch tools and dies for creating a sheet metal component. Therefore, the flattened view is a very important part of any sheet metal component. As mentioned earlier, you can unfold a sheet metal component and display its flattened view in a separate graphics window by using the **Create Flat Pattern** tool.

1. Choose the **Create Flat Pattern** tool from the **Flat Pattern** panel of the **Sheet Metal** tab; the sheet metal component is unfolded and displayed as a

flat component, as shown in Figure 15-106.




Figure 15-105 Final model of the Holder Clip




Figure 15-106 Flat pattern of the sheet metal part

Note

You can also use the **Measure Distance** tool to measure distances in the flat pattern. To measure distances, right-click in the graphics window, and then choose **Measure > Measure Distance** from the Marking menu.

Tutorial 2

In this tutorial, you will create the sheet metal component shown in Figure 15-107a. Its dimensions are shown in Figures 15-107b through 15-107d. The flat pattern of the component is shown in Figure 15-108. The thickness of the sheet is 1 mm and the radius of corner bends is 3 mm. The dimensions of hems are not given. Select the default parameters as the dimensions for creating hems on the two faces.

(Expected time: 45 min)




Figure 15-107a Sheet metal component




Figure 15-107b Top view of the component




Figure 15-107c Left view of the component




Figure 15-107d Front view of the component




Figure 15-108 Flat pattern of the sheet metal component

The following steps are required to complete this tutorial:

- a. Start a new metric sheet metal file and create the sketch for the base of the sheet metal component on the XY plane.
- b. Exit the Sketching environment and convert the sketch into a face by using the **Face** tool.
- c. Create one hole and then pattern it to create the remaining three instances.
- d. Create flanges on the left and right faces of the sheet metal base.
- e. Create hems on both flanges and then create two keyways using the **PunchTool** dialog box.
- f. Create flange on the front face of the base.

Drawing the Sketch for the Base Feature

1. Choose the **New** tool from the **Quick Access Toolbar**; the **Create New File** dialog box is invoked.
2. Choose the **Metric** tab and start a new metric sheet metal file.

3. Draw the sketch for the base on the XY plane, as shown in Figure 15-109, and then exit the Sketching environment.

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*
2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

Converting the Sketch into a Sheet Metal Face

As mentioned earlier, first you need to set parameters in the **Sheet Metal Defaults** dialog box and then convert the sketch into a face.

1. Choose the **Sheet Metal Defaults** tool from the **Setup** panel of the **Sheet Metal** tab; the **Sheet Metal Defaults** dialog box is displayed. Choose the **Edit Sheet Metal Rule** button from this dialog box to invoke the **Style and Standard Editor [Library - Read Only]** dialog box.
2. Enter **1** in the **Thickness** edit box in the **Sheet** area. Choose **Save** and then choose **Done** to close the dialog box.
3. Choose the **Cancel** button from the **Sheet Metal Defaults** dialog box to close it.
4. Choose the **Face** tool from the **Create** panel of the **Sheet Metal** tab to invoke the **Face** dialog box.

As there is only one unconsumed sketch, it is automatically selected and the preview of the face of the sheet metal component is displayed in the drawing window.

5. Choose **OK** to create the face and exit the **Face** dialog box.

6. Invoke the **Hole** dialog box by choosing the **Hole** tool from the **Modify** panel of the **Sheet Metal** tab and create a hole at the lower left corner of the base using the **Linear** option, refer to Figure 15-107b for dimensions.
7. Create the rectangular pattern of the hole, refer to Figure 15-107b for dimensions. Change the current view to the isometric view. The base feature of the sheet metal component after creating the hole pattern is shown in Figure 15-110.



Figure 15-109 Sketch for the base feature




Figure 15-110 Base after creating the hole pattern

Creating the Two Flanges

1. Choose the **Flange** tool from the **Create** panel of the **Sheet Metal** tab; the **Flange** dialog box is invoked and you are prompted to select the edge for creating a flange.
2. Select the right edge of the bottom face on the base feature; the preview of the flange is displayed.

3. Choose the **Flip Direction** button if the direction of the flange is not upward and then enter **50** in the **Distance** edit box.
4. Next, choose the **Apply** button.
5. Next, select the left edge of the bottom face of the base. You will notice that the flange is created in the upward direction. This is because the parameters have already been set in the **Flange** dialog box.
6. Choose the **OK** button from the **Flange** dialog box to create the flange and exit the dialog box. Change the current view to the isometric view. The sheet metal component after creating flanges is shown in Figure 15-111.

Creating Hems

1. Choose the **Hem** tool from the **Create** panel of the **Sheet Metal** tab; the **Hem** dialog box is invoked and you are prompted to select an edge to create the hem.
2. Select the outer edge on the top face of the right flange. You will notice that the preview of the hem is displayed.
3. Accept the default parameters in the **Hem** dialog box and choose **Apply** to create the hem.
4. Now, select the outer edge of the left flange; the preview of the hem is displayed. Choose the **OK** button to create the hem and exit the dialog box. The sheet metal component after creating hems is shown in Figure 15-112.




Figure 15-111 Model after creating flanges




Figure 15-112 Model after creating hems

Creating Keyways

Next, you will create keyways by punching the predefined shape on both flanges. As mentioned earlier, the shapes are punched by using a sketched point. Therefore, first you need to sketch a point in the middle of one of the flanges.

Before creating keyways, it is recommended that you suppress hems. This is because after creating hems, the actual dimensions of the face are reduced and you cannot get the proper locations of keyways.

1. Using the **Browser Bar**, suppress the two hems. Now, define a new sketch plane on the outer face of the right flange.
2. Create a sketch point at the center of the face of the right flange. Note that the vertical dimension of the point from the top edge should be 25 mm and its horizontal dimension from the left edge of the flange should be 20 mm, refer to figure 15-107c.

3. Exit the Sketching environment and then choose the **Punch Tool** from the **Modify** panel of the **Sheet Metal** tab; the **PunchTool Directory** dialog box is displayed.
4. Select **keyway.ide** from this dialog box and choose **Open**; the **PunchTool** dialog box is displayed with the preview of the selected punch feature.
5. Choose the **Geometry** tab from the **PunchTool** dialog box. In this tab, choose the **Centers** button and specify the angle in the **Angle** edit box. The preview of the keyway is displayed on the sheet metal flange at the sketched point. In the preview, you will notice that the keyway is pointing toward the right of the circle. You need to rotate it to get the proper orientation.
6. Enter **90** in the **Angle** edit box of the **Geometry** tab. Next, choose the **Size** tab from the **PunchTool** dialog box, accept the other default dimension values, and then choose **Finish** to create the keyway.

If units of the keyway in the preview are different, then set the following parameters in the **Size** tab of the **PunchTool** dialog box:

bottom_fillet: 0 mm top_fillet: 0 mm keyway_depth: 5 mm keyway_width: 2 mm diameter: 12 mm.

Note

*The punched 3D shapes are displayed as iFeature in the **Browser Bar**.*

7. Similarly, define a new sketch plane on the outer face of the left flange and then project the last sketch point on this face. Using this projected point, create the keyway on the left flange. The model after creating both keyways is shown in Figure 15-113.

Creating the Next Flange

1. Choose the **Flange** tool from the **Create** panel of the **Sheet Metal** tab; the **Flange** dialog box is invoked and you are prompted to select the edge for creating the flange.
2. Select the upper edge on the front face of the base of the sheet metal

component; the preview of the flange is displayed on the graphics screen.

3. Enter **13** in the **Distance** edit box and then choose the **Flip Direction** button to reverse the direction of feature creation. Choose the **More (>>)** button at the lower right corner of the dialog box to expand it.
4. Select **Width** from the **Type** drop-down list in the **Width Extents** area and then select the **Centered** radio button; the **Width** edit box is displayed in the **Width Extents** area with the preview of the flange.
5. Enter **10** in the **Width** edit box and then choose **OK** to create the flange and exit the dialog box.
6. Create rounds on the two corners of the flange created previously by using the **Corner Round** tool. The radius of the corner round is 3 mm.

This completes the creation of the sheet metal component. Unsuppress the hem features by using the **Browser Bar**. The final sheet metal component is shown in Figure 15-114.




Figure 15-113 Sheet metal component after creating the keyways




Figure 15-114 Completed sheet metal component for Tutorial 2

Creating the Flat Pattern

1. Choose the **Create Flat Pattern** tool from the **Flat Pattern** panel of the **Sheet Metal** tab; the flat pattern of the sheet metal component is displayed, as shown in Figure 15-115.




Figure 15-115 Flat pattern of the component

2. Choose the **Save** tool from the **Quick Access Toolbar**; the **Save As** dialog box is displayed.
3. Specify the name of the file as *Tutorial2.ipt* and then choose the **Save** button; a message box is displayed, informing that the model cannot be saved in the flat pattern edit mode.
4. Choose the **OK** button from the message box; the model is saved with the name *Tutorial2.ipt* at the location given next and then close the file.

C:\Inventor_2016\c15

Answer the following questions and then compare them to those given at the end of this chapter:

1. You can unfold a sheet metal component by using the _____ tool.
2. By default, the value of the bend radius is equal to the _____ of a sheet.
3. In Autodesk Inventor, you can fold a sheet metal face only by using a

_____ line that acts as the _____ line.

4. Autodesk Inventor allows you to create corner seams in a sheet metal component with the help of the _____ tool.
5. If a flange is created through an angle of _____, it will not be visible as it merges with the face of sheet metal component.
6. To convert a solid model into a sheet metal component, first you need to _____ it.
7. The sheet metal files are saved as the *.ipt files. (T/F)
8. When you start a new sheet metal file, the Sketching environment is invoked. (T/F)
9. A contour flange is created only with the help of a sketched contour. (T/F)
10. A sketched point is automatically selected as the center of the punched 3D shape. (T/F)

1. Which of the following tools is used to create the base of a sheet metal component?

- (a) **Flange** (b) **Contour Flange**
(c) **Face** (d) **Hem**

2. Which of the following tools is used to round all corners of the base feature?

- (a) **Round** (b) **Corner Round**
(c) **Face** (d) **Hem**

3. If you modify a value in the **Style and Standard Editor [Library - Read Only]** dialog box after creating a sheet metal component, the changes will

- reflect in the sheet metal component when you exit the dialog box after saving the changes. (T/F)
4. You can measure the dimensions of a sheet metal component by using different measuring tools. (T/F)
 5. You can select material to apply to a sheet metal component from the **Material** drop-down list in the **Sheet Metal Defaults** dialog box. (T/F)
 6. The values of the bend and unfold parameters that are set in the **Style and Standard Editor [Library - Read Only]** dialog box cannot be overridden from the dialog boxes of any tool. (T/F)
 7. You can set a value in an edit box as an equation in terms of thickness of a sheet. (T/F)
 8. A punched 3D shape cannot be mirrored. (T/F)
 9. The **Contour Flange** tool is used to create a flange that follows a sketched shape in a sheet metal component. (T/F)
 10. You can create an Obround hem in Autodesk Inventor. (T/F)

Exercise 1

Create the sheet metal component shown in Figure 15-116a. The dimensions of the model are shown in Figures 15-116b and 15-116d. Assume the missing dimensions. The flat pattern of the component is shown in Figure 15-116c. **(Expected time: 30 min)**

Hint

*Create the flanges of same width on the top and left faces and then by using the **Corner Seam** tool, you can force them to close together. This way the corner relief will also be created.*




Figure 15-116a Sheet metal component for Exercise 1

Sheet thickness = 0.5 mm




Figure 15-116b Top view of the component




Figure 15-116c Flat pattern of the component




Figure 15-116d Front view of the component

Answers to Self-Evaluation Test

1. **Create Flat Pattern**, 2. thickness, 3. sketched, folding, 4. **Corner Seam**, 5. 180 degrees, 6. shell, 7. T, 8. F, 9. T, 10. T

Chapter 16

Introduction to Weldments

Learning Objectives

After completing this chapter, you will be able to:

- Understand weldment assemblies and Weldment environment.

- *Create a cosmetic weld.*
- *Create a fillet weld.*
- *Create a groove weld.*

UNDERSTANDING WELDMENT ASSEMBLIES

Weldment assemblies are those in which you can weld a component with another component by using welds. These assemblies are also called weldments. Autodesk Inventor provides you with a dedicated environment for creating weldments, called the Weldment environment. This environment is similar to the assembly environment and provides tools to assemble components as well as to weld components. In this environment, you can also make some initial preparations to weld components. The initial preparations include creating cut features by using the tools available in the assembly environment.

Similar to various types of drawing templates, you are also provided with various weldment templates in Inventor. To invoke the Weldment assembly environment, double-click on any of the weldment assembly templates in the **Create New File** dialog box, see Figure 16-1.




Figure 16-1 Various types of weldment templates in the *Create New File* dialog box

Figure 16-2 shows the Weldment assembly environment invoked using the **Weldment (ANSI - mm).iam** template.



Note You can convert an assembly created in the Assembly modeling environment into a weldment assembly by using the **Convert to Weldment** tool from the **Convert** panel of the **Environments** tab. However, remember that an assembly once converted into a weldment cannot be converted back into a simple assembly.




Figure 16-2 Weldment assembly environment

MAIN TYPES OF WELDS IN AUTODESK INVENTOR

Autodesk Inventor allows you to create three main types of welds: cosmetic, fillet, and groove. In addition to these, there are some other types of welds that can be used to create weldments. But, they are not discussed in this book. The three main types of welds are discussed next.

Cosmetic Welds

Cosmetic welds are artificial welds added to an edge. These types of welds are not actual welds and as a result, no weld bead is added to the model. To create a cosmetic weld, you just need to select the edge that requires welding.



Note Adding cosmetic welds does not result in the modification of the physical properties of an assembly. This is because adding cosmetic welds does not physically add any material to a model. It only adds a convention that gives an impression of welding.

Figure 16-3 shows a part of the Shock assembly in which a cylinder is assembled with a bracket. Note that as there is no physical bonding between these two components, they cannot be held together. Therefore, you need to weld these

two components together. Figure 16-4 shows the same assembly after creating a cosmetic weld. The cosmetic weld symbol is also shown in the assembly.




Figure 16-4 Assembly after creating the cosmetic weld




Figure 16-3 Assembly before welding

Fillet Welds

Fillet welds are actual welds and are represented by a solid feature in an assembly. When you add fillet welds, a solid feature representing the weld bead is added in the assembly. Also, the physical properties of the assembly are modified. To create a fillet weld, you need two surfaces. Figure 16-5 shows the Shock assembly after adding a fillet weld to the bracket and cylinder. Figure 16-6 shows a butt-joint with a fillet weld.

Groove Welds

Groove welds are used to weld the parts that are placed at a certain offset from each other or have some grooves between them. These are also known as actual welds and are represented by a solid feature in an assembly. Figure 16-7 shows a

partial three-quarter section view of the Shock assembly after adding a groove weld to the bracket and cylinder. Note that in this case, the cylinder is assembled at some offset from the bracket. As evident from this figure, the groove weld bead is filled in this offset space. Figure 16-8 shows a butt-joint with a groove weld. As is evident from this figure also, some offset is maintained between the two mating faces of the plates between which the groove weld bead is filled.




Figure 16-5 Assembly with a fillet weld
Figure 16-6 Butt-joint with a fillet weld






Figure 16-7 Assembly with a groove weld
Figure 16-8 Butt-joint with a groove weld



ADDING WELDS TO ASSEMBLIES

The process of creating weldment assemblies is completed in three steps: assembling the components, preparing components for welding, and creating welds. These three steps are discussed next.

Assembling the Components of Weldment Assemblies

As mentioned earlier, you can create the weldment assemblies in the weldment environment. Alternatively, you can assemble the components in the assembly modeling environment and then switch to the weldment environment to add welds to the components. Remember that once you switch from the assembly modeling environment to the weldment environment, you cannot switch back.

Preparing Assemblies for Weldments

Once you have assembled components of the weldment assemblies, you need to prepare them for welding by removing material from the components to accommodate the weld beads. You can create cut features, holes, fillets, and chamfers to remove the material. For example, to create a butt-joint, you need to chamfer the two edges of the plates between which the weld bead will be added. This step would not be required if the components were chamfered during their creation. Note that similar to the assembly features, these features are also limited to the assembly and are not made on the individual part files.

To prepare weldments, choose the **Preparation** tool from the **Process** panel of the **Weld** tab. Alternatively, double-click on the **Preparations** node in the **Browser Bar**; various material removal tools will get activated in the **Weld** tab of the **Ribbon**. Next, use the required preparation tool from the **Preparation and Machining** panel of the **Weld** tab and then choose the **Return** tool from the

Return panel to return to the weldment environment.



Note While preparing weldments, the *Extrude* and *Revolve* tools provide only the *Cut* option.

Adding Welds

The final step in creating weldments is adding welds. To do so, choose the **Welds** tool from the **Process** panel of the **Weld** tab. Alternatively, double-click on the **Welds** node in the **Browser Bar**; various weldment tools will be activated in the **Weld** panel of the **Weld** tab. You can also invoke the **Welds** tool from the Marking menu, which is displayed on right-clicking in the graphics window. You can add the fillet symbol while adding welds or later on by using the **Symbol** tool.

CREATING FILLET WELDS

Ribbon: Weld > Weld > Fillet



To create a fillet weld between components, choose the **Fillet** tool from the **Weld** panel of the **Weld** tab; the **Fillet Weld** dialog box will be displayed, as shown in Figure 16-9. The **Fillet Weld** tool can also be invoked from the Marking menu.




Figure 16-9 The Fillet Weld dialog box

Bead Area

To create a fillet weld, you need to select the two faces that are to be welded

together. This is the reason, the **1** button in the **Bead** area will automatically be chosen in the **Fillet Weld** dialog box. Also, you will be prompted to select a face to be welded. After selecting the first face to weld, choose the **2** button; you will again be prompted to select the second face to weld. Select the second face; the second face will be highlighted and the preview of the fillet weld will appear. Selecting the **Chain** check box ensures that all the faces tangent to the selected face are also selected.

You can specify the dimension of the weld in terms of leg length or in terms of throat measurement by selecting their respective radio buttons from this area. The value of the weld leg or the throat measurement can be entered in the edit boxes below the **1** and **2** buttons. There are two radio buttons present in this area; **Leg Length Measurement** and **Throat Measurement**. If you select the **Leg Length Measurement** radio button, then you need to specify the **Leg 1** and **Leg 2** parameters of the Fillet weld in their respective edit boxes. If you select the **Throat Measurement** radio button, then you need to specify the value of the throat in the **Throat Measurement** edit box. Further you can reverse the direction of the weld by clicking on the **Direction** button.

Contour Area

The options in this area are used to specify the contour of the resulting weld bead. By default, the **Flat** button is chosen. To use any other button, click on the down arrow on the right of the **Flat** button in this area; a flyout will be displayed. Choose the **Convex** or **Concave** button to specify the required contour of weld bead. Specify the offset value of the convex or concave surface in the **Offset** edit box in this area. Figure 16-10 shows a fillet weld with convex contour.

Intermittency Area

The options in this area are used to create an intermittent fillet weld. You can specify the length and pitch of the intermittent fillet in the **Length** and **Pitch** edit boxes, respectively. Figure 16-11 shows an intermittent fillet weld in a butt-joint. In this case, the length value is 10 mm and the pitch value is 20 mm.




Figure 16-10 *Fillet weld with convex contour*




Figure 16-11 *Intermittent fillet weld in a butt-joint*


Extents Area

The options in this area are used to specify the extents of a fillet weld. The **All** option is used to create the fillet weld throughout the selected faces. You can also specify the start and end offsets of the fillet weld. The **From-To** option is used to define the extent of the intermittent weld. You can create work planes to specify the “from” and “to” faces. The **Start-Length** option is used to create a weld that starts from a selected face and ends at a specified length.

Start Offset/End Offset

The **Start Offset** and **End Offset** edit boxes will **Figure 16-12** *Fillet weld offset from the start and end edges* be available only when you select the **All** option from the drop-down list in the **Extents** area. These edit boxes are used to specify the distance value of a weld from the start/end edge of the components on which

you want to create a fillet weld, as shown in Figure 16-12. If you select the **From-To** option from the drop-down list in the **Extents** area, the **From** and **To** buttons will be available. You can select faces or planes for the start and end of the fillet. If you select the **Start-Length** option from the drop-down list, the **Start Offset** and **Length** edit boxes will be available. You can specify the start offset and the length of the fillet weld in these edit boxes.



Create Welding Symbol

When you select this check box, the **Fillet Weld** dialog box expands and provides option to add weld symbols.

CREATING COSMETIC WELDS

Ribbon: Weld > Weld > Cosmetic To create cosmetic welds between components, choose the Cosmetic tool from the Weld panel of the Weld tab; the Cosmetic Weld dialog box will be displayed, as shown in Figure 16-13. You can also invoke this tool from the Marking menu.




Figure 16-13 The Cosmetic Weld dialog box

Bead Area

When you invoke the **Cosmetic Weld** dialog box, the **1** button is chosen and you are prompted to select an edge or loop for the weld. You can set the selection mode using the options in the **Select Mode** area on the right of the **1** button. The selected edge turns blue.

Extents

The options in this area are used to create a cosmetic weld up to a specified extent. By default, the **All** option is selected in this area. As a result, the weld is created across the whole length of the chosen edge. The extent of the weld can also be specified by selecting the **From-To** option from the drop-down list in this area. You can create work planes to specify the “from” and “to” faces.

Area

The edit box in this area is used to specify the cross-sectional area of the fillet weld. Note that even when you increase this value, there will be no change in the display of the fillet weld in the model. This is because this value is used only for calculating the physical properties of the model after welding.

Figure 16-14 shows two components welded together using the cosmetic weld.




Figure 16-14 Two components welded using the cosmetic weld

Note

All welds are listed in the **Beads** folder under the **Welds** node in the **Browser Bar**.

CREATING GROOVE WELDS

Ribbon: Weld > Weld > Groove **As mentioned earlier, groove welds are created between the components that are either assembled at some offset or have some grooves between them. To create groove weld, invoke the Welding environment and choose the Groove tool from the Weld panel of the Weld tab; the Groove Weld dialog box will be displayed, as shown in Figure 16-15. The options in this dialog box are discussed next.**




Figure 16-15 The Groove Weld dialog box

Bead Area

The options in this area are used to specify the faces to be groove welded. You can also specify the direction of the groove weld. These options are discussed next.

Face Set 1 Area

The options in this area are used to select the first face for applying the groove weld. When you invoke the **Groove Weld** dialog box, the **1** button in the **Face Set 1** area will be chosen and you will be prompted to select the face to be welded. The face selected as face set 1 turns blue. You can select the **Full Face Weld** check box to add the weld bead to the entire face.

Face Set 2 Area

The options in this area are used to select the second face for applying the groove weld. The face selected as face set 2 is highlighted. You can select the

Full Face Weld check box to add the weld bead to the entire face.

Fill Direction Area

If you are not creating a full face weld, you need to specify the direction of a groove weld. You can specify the direction by using a linear edge, cylindrical face, or planar face, or by using two vertices.

Figure 16-16 shows the quarter section view of a full face groove weld. Note that in this case, the cylinder is assembled at an offset from the bracket. Select the **Radial Fill** check box to project the groove weld for the cylindrical or hole feature, as no fill direction is required for welding these features.

Ignore Internal Loops

Select this check box to create a groove weld by ignoring the internal loop. Figure 16-17 shows the quarter section view of a groove weld created by ignoring the internal loop, which is the hole in the bracket.

Figure 16-16 Full face groove weld






Figure 16-17 Groove weld created by ignoring the internal loop

CREATING SYMBOLS

Ribbon: Weld > Weld > Symbol You can add welding symbols to a weld bead. To do so, choose the Symbol tool from the Weld panel of the Weld tab; the Welding Symbol dialog box will be displayed, refer to Figure 16-18. Now, select a weld bead from the model; a weld symbol will be displayed attached to the selected bead. Next, specify the weld properties in the respective edit boxes available in the Welding Symbol dialog box. After specifying the properties, choose the OK button; the weld symbol along with the specified properties will be displayed on the weld bead.

Figure 16-18 The Welding Symbol dialog box



GENERATING REPORT

Ribbon: Weld > Weld > Bead Report In Autodesk Inventor, you can generate bead report. This report will be in form of Excel spreadsheet and provides information about different properties like weld ID, type, length, mass, area, and volume. To generate a bead report, choose the Bead Report tool from the Weld panel of the Weld tab; the Weld Bead Report dialog box will be displayed. Now, choose the Next button from this dialog box; the Report Location dialog box will be displayed. In this dialog box, specify the file name and file location. Next, choose the Save button; bead report is generated in Excel format at the specified location.

TUTORIALS

Tutorial 1

In this tutorial, you will create the welded butt-joint shown in Figure 16-19. To create this weldment, you will use the **Weldment (ANSI - mm).iam** template and the top-down approach for assembling plates. Next, you will prepare plates for welding in the weldment environment by chamfering their edges. The plate to be used for creating the butt-joint is 30 mm long and 50 mm wide. The thickness of the plate is 5 mm and the chamfer is a 3 mm equidistant chamfer. **(Expected time: 30 min)**




Figure 16-19 Welded butt-joint for Tutorial 1

The following steps are required to complete this tutorial:

- a. Open a new **Weldment (ANSI - mm).iam** template and then create a plate using the top-down assembly approach.
- b. Exit the part modeling environment and insert another instance of the plate into the weldment environment.
- c. Prepare plates for welding by creating chamfers.
- d. Assemble two plates by using assembly constraints.
- e. Invoke the welding options and create the butt-joint using the fillet weld.

Opening a New Weldment File and Creating a Plate

As mentioned in the tutorial description, you need to use the **Weldment (ANSI - mm).iam** file for creating the butt-joint. Therefore, you need to select this file from the **Create New File** dialog box.

1. Start Autodesk Inventor and invoke the **Create New File** dialog box. Next, double-click on the **Weldment (ANSI - mm).iam** template from the **Metric** tab to invoke the Weldment environment.

2. Now, choose the **Create** tool from the **Assemble** tab; the **Create In Place Component** dialog box is displayed. Enter **Plate** in the **New Component Name** edit box and choose the **OK** button and then create a plate of dimensions 50 x 30 x 5 mm. Save the file and then choose the **Return** tool from the **Return** panel to return to the Assembly environment. The Weldment assembly after creating the plate is shown in Figure 16-20.




Figure 16-20 Weldment after creating the plate

3. Choose the **Save** tool from the **Quick Access Toolbar**; the **Save As** dialog box is displayed.
4. Specify **Tutorial 1** in the **File name** edit box of this dialog box and then choose the **Save** button; the **Save** message box is displayed.
5. Choose **Yes to All** and then **OK** from the **Save** message box to save both part and assembly files.

Placing another Instance of the Plate

Next, you need to place another instance of the Plate in the Weldment (assembly) environment. Note that you will not assemble the two plates at this stage. First, you need to prepare them for welding by chamfering their edges.

1. Choose the **Place** tool from the **Component** panel of the **Assemble** tab to

invoke the **Place Component** dialog box.

2. Double-click on *Plate.ipt* file; the file is selected and the **Place Component** dialog box is closed. Also, you are prompted to place the component.
3. Specify a point on the screen at a location where the second instance will not interfere with the previous instance. Right-click and then choose **OK** from the shortcut menu displayed.
4. Choose **Zoom All** from the **Navigation Bar** to modify the drawing display area.

Preparing the Two Plates for Welding

Next, you need to prepare the two plates for welding by chamfering them. To chamfer the edges, you need to activate the **Weld** tab.

1. Choose the **Preparation** tool from the **Weld** tab or double-click on **Preparations** in the **Browser Bar** to activate various preparation and machining tools in the **Ribbon**. You can also invoke this tool from the Marking menu.
2. Choose the **Chamfer** tool from the **Preparation and Machining** panel of the **Weld** tab to invoke the **Chamfer** dialog box.
3. Enter **3** in the **Distance** edit box and then select one of the edges (of 50 mm length) of one of the plates. Choose **OK** to create the chamfer and exit the dialog box.
4. Similarly, chamfer the edge on the top face of the other plate. You will notice that **Chamfer 1** and **Chamfer 2** are added under **Preparations** in the **Browser Bar**. This is because you have created both the chamfers in the two plates as two different features.
5. Choose the **Return** tool from the **Return** panel of the **Weld** tab to finish the preparation (chamfering) of the component for weldment. The weldment assembly after chamfering the edges of the two plates is shown in Figure 16-21.




Figure 16-21 Weldment after chamfering the two plates

Assembling the Two Plates

1. Apply multiple instances of the **Mate** constraint to the two instances of the plate and assemble them. The assembly of the two plates is shown in Figure 16-22.




Figure 16-22 Weldment after assembling the two plates

Creating the Fillet Weld

Next, you need to create the fillet weld. To weld components, you need to activate the welding tools.

1. Choose the **Welds** tool from the **Process** panel of the **Weld** tab or double-click on **Welds** in the **Browser Bar**; various welding tools are activated. You can also invoke this tool from the Marking menu.

Remember that when you double-click on **Preparations** in the **Browser Bar**, the welding tools in this panel do not get activated. But, when you double-click on **Welds** in the **Browser Bar**, these tools get activated.

2. Choose the **Fillet** tool from the **Weld** panel of the **Weld** tab; the **Fillet Weld** dialog box is displayed and you are prompted to select the face to weld. You can also invoke this tool from the Marking menu.
3. Select the chamfered face on one of the plates; the selected face turns blue.
4. Choose the **2** button from the **Bead** area of the **Fillet Weld** dialog box; you are prompted again to select the face to weld.
5. Rotate the model using the **Rotate** tool and select the chamfered face on the other plate.

The second selected face gets highlighted. Also, the preview of the weld is displayed on the plates. You will notice that the weld extends beyond the V groove created in the two plates. If you apply the weld at this stage, a warning box will appear, informing that the face selected for the leg of the bead is recomputed to be smaller than the specified leg size. Therefore, you need to reduce the leg size of the bead.

6. Enter **4** in the **Leg 1** edit box below the **1** button. Make sure that the **Leg Length Measurement** radio button is selected in the dialog box.

The welding shown in the preview will not extend beyond the V groove. As is evident from Figure 16-19, the fillet weld has a convex contour. Therefore, you need to select the **Convex** option from the **Fillet Weld** dialog box.

- Click on the down arrow on the right of the **Flat** button in the **Contour** area; a flyout is displayed. Next, choose the **Convex** button from the flyout. On doing so, the **Offset** edit box is enabled.
- Enter **1** in the **Offset** edit box.




Figure 16-23 Final weldment assembly after creating the fillet weld

With this, all welding options are defined and you can now apply the weld.

- Choose the **Apply** button and then the **Cancel** button to exit the dialog box. Next, choose the **Return** button to finish the creation of the fillet weld. The welded plates are shown in Figure 16-23.
- Save the assembly with the name *Butt-Joint* at the location *C:\Inventor_2016\c16\Tutorial1*.

Tutorial 2

In this tutorial, you will create the Shock Assembly in the Assembly modeling environment. Also, you will switch to the weldment environment and weld components, as shown in Figure 16-24a. The dimensions of the two components are shown in Figures 16-24b and 16-24c, 16-25a and 16-25b. **(Expected time: 45 min)**




Figure 16-24a *Welded Shock Assembly*




Figure 16-24b *Top view of the Bracket*




Figure 16-24c *Top view of the Cylinder*




Figure 16-25a Front view of the Bracket




Figure 16-25b Sectioned view of the Cylinder

The following steps are required to complete this tutorial:

- a. Create the Bracket and the Cylinder as separate part files.
- b. Start a new assembly file and then place the Bracket and the Cylinder in the assembly file.
- c. Assemble both components by using the assembly constraints.
- d. Switch to the weldment environment.
- e. Weld components using the fillet weld.

Creating Components

1. Create two components, Bracket and Cylinder, in separate part files and then save them at the location *C:\Inventor_2016\c16\Shock Assembly*.

Assembling the Components

As mentioned in the tutorial description, you need to assemble the components in the Assembly modeling environment and then switch to the weldment environment. Therefore, you need to start a new assembly file using the **Create New File** dialog box to assemble the components.

1. Start a new assembly file by using the **Create New File** dialog box. Now, place one instance each of the Bracket and the Cylinder in the current assembly file.
2. Assemble the Cylinder with the Bracket using the assembly constraints. The assembly file after assembling the components is shown in Figure 16-26.




Figure 16-26 Assembly file after assembling the Bracket and the Cylinder


Welding the Components

Components can be welded in the Weldment assembly environment. Therefore, you need to switch from the Assembly environment to the Weldment assembly environment.

1. Choose the **Convert to Weldment** tool from the **Convert** panel of the **Environments** tab; the **Autodesk Inventor Professional** warning box is displayed, informing that once an assembly has been converted into a weldment, you cannot convert it back to an assembly.
2. Choose **Yes** in the warning box; the **Convert to Weldment** dialog box is

displayed, as shown in Figure 16-27.

Figure 16-27 *The Convert to Weldment dialog box*



This dialog box is used to convert an assembly into a weldment of specified standard. You can also change the color of weldment by using this dialog box.

3. Select the **ANSI** radio button from the **Standard** area of this dialog box. Accept the remaining default options and choose **OK** to close this dialog box.

On doing so, the Weldment environment is invoked and the **Weld** tab is activated. Since no preparation is required for welding the components, you can directly weld the components.

4. Choose the **Welds** tool from the **Process** panel of the **Weld** tab to activate the welding tools. You can also invoke this tool from the Marking menu which is displayed on right-clicking in the graphics window.
5. Choose the **Fillet** tool from the **Weld** panel of the **Weld** tab; the **Fillet Weld** dialog box is invoked and you are prompted to select the face to be welded.
6. Select the outer face of the Cylinder as the first face to be welded; the selected face turns blue.
7. Choose the **2** button from the **Fillet Weld** dialog box; you are prompted again to select the face to be welded.
8. Select the upper face of the Bracket with which the Cylinder needs to be assembled; the preview of the weld appears on the assembly.

9. Enter **10** in the **Leg 1** edit box below the **1** button.

The fillet contour shown in Figure 16-24a is concave. Therefore, you need to specify the corresponding options from the **Contour** area.

10. Click on the down arrow on the right of the **Flat** button in the **Contour** area to display a flyout. Next, choose the **Concave** button from the flyout.

11. Enter **2** in the **Offset** edit box. Choose **Apply** and then **Cancel** to exit the dialog box. Next, choose the **Return** tool from the **Return** panel of the **Weld** tab to finish the welding.

The final weldment assembly is shown in Figure 16-28.

12. Save the assembly with the name *Tutorial 2* at the location *C:\Inventor_2016\c16\Shock Assembly*.




Figure 16-28 Final weldment assembly

Answer the following questions and then compare them to those given at the

end of this chapter: 1. Which of the following types of welds does not affect the physical properties of an assembly?

(a) **Cosmetic** (b) **Groove** (c) **Fillet** (c) None of these 2. Which of the following contours is not a type of weld bead?

(a) Flat (b) Convex
(c) Concave (d) Round

3. Which of the following welds is not considered as an actual weld?

(a) **Fillet** (b) **Cosmetic** (c) **Groove** (d) None of these 4. You can convert an assembly created in the Assembly modeling environment to a Weldment assembly by choosing the _____ tool from the **Convert** panel of the **Assemble** tab.

5. You can create a _____ weld between two parts with or without including internal loops.

6. Select the _____ check box to add weld symbols to a welded assembly.

7. The Weldment environment is used to weld the components of an assembly. (T/F) 8. You can convert a weldment file into an assembly file. (T/F) 9. Groove welds are added to the parts that are placed at certain offset from each other or have grooves between them. (T/F) 10. You can create the extruded and revolved join features while preparing welds. (T/F)

Answer the following questions:

1. Which of the following options is used to create a fillet that extends throughout the selected edges of components?

(a) **All** (b) **From-To** (c) **Start-Length** (d) None of these

2. Which of the following sub-nodes of the **Browser Bar** lists all welds of a weldment assembly?

(a) **Preparations** (b) **Welds** (c) **Machining** (d) **Representations 3**. You can add a fillet symbol by using the **Fillet** tool or by using the _____ tool.

4. To create a cosmetic weld, you just need to select the edge that requires welding. (T/F)

5. The process of creating weldment assemblies is completed in four steps. (T/F)

6. You can prepare the assembled components for welding by removing material from them to accommodate weld beads. (T/F) Exercise

Exercise 1

In this exercise, you will create the Base Plate and the Top Mounting as separate part files and then assemble them using the assembly constraints in the **Weldment** environment. The weldment assembly is shown in Figure 16-29. The dimensions of both components are shown in Figures 16-30 and 16-31. **(Expected time: 45 min)**




Figure 16-29 Weldment assembly for Exercise 1




Figure 16-30 Dimensions of the Base Plate




Figure 16-31 Dimensions of the Top Mounting

Answers to Self-Evaluation Test

1. **Cosmetic**, 2. Round, 3. **Cosmetic**, 4. **Convert to Weldment**, 5. groove, 6. **Create Welding Symbol**, 7. T, 8. F, 9. T, 10. F

Chapter 17

-

Miscellaneous Tools

Learning Objectives

After completing this chapter, you will be able to:

- Find the Center of Gravity of a model.

- *Extract an iFeature.*
- *Insert an iFeature.*
- *Create an iMate.*
- *Understand the use of iProperties.*
- *Create user-defined drawing sheets.*
- *Import AutoCAD blocks into Inventor.*

Introduction

In this chapter, you will learn about some of the tools that help in enhancing your working efficiency.

COPYING THE SKETCHES

Ribbon: Sketch > Modify > Copy **The Copy tool is available in the sketching environment and allows you to copy and paste the sketched entities from one location to the other. Note that if dimensions are also selected along**

with the entities to be copied, then the selected dimensions will also be copied along with the sketched entities. To copy the sketched entities, invoke the Copy tool from the Modify panel of the Sketch tab; the Copy dialog box will be displayed, as shown in Figure 17-1. The options in this dialog box are discussed next.




Figure 17-1 The Copy dialog box

Select

This button is used to select the entities to be copied. On invoking the **Copy** tool, this button is automatically chosen and you are prompted to select the geometry to copy. You can select individual entities using the mouse button or select more than one entity using the Window or Crossing options.

Base Point

This button is chosen to specify the point that will act as the base point for moving the copied entities. Once you have selected all the entities to be copied, choose this button to select the point from where the movement will start.

Clipboard [Ctrl-C]

This check box, if selected, temporarily saves the selected geometry or the clipboard so that after choosing the **Done** button, you can paste the selected geometry by pressing CTRL+V keys from the keyboard.

Precise Input

This check box, if selected, allows you to specify the coordinates for the base point and the destination point using the **Inventor Precise Input** toolbar.

Optimize for Single Selection

If this check box is selected, the **Base Point** button will be activated automatically after making a single selection or the window selection of geometry. But if you clear this check box, you can make multiple geometry selections before choosing the **Base Point** button.

After selecting the geometry and the base point, you will be prompted to specify the endpoint for copy. Specify the end point in the drawing window; the copied geometry will be pasted. You will notice the **Copy** tool is still active. If you need multiple copies, specify more endpoints, else right-click and choose **Cancel(ESC)**.

SCALING THE SKETCHES

Ribbon: Sketch > Modify > Scale **The Scale tool is available in the sketching environment and is used to resize the sketched entities with respect to the specified base point. On invoking this tool, the Scale dialog box will be displayed, as shown in Figure 17-2. Most of the options in this dialog box are similar to those discussed in the Move dialog box in Chapter 4.**




Figure 17-2 The Scale dialog box

Select the sketched entities to be scaled. After selecting the sketched entities, choose the **Base Point** button; you will be prompted to select the base point. Select a base point; the **Scale Factor** edit box will be highlighted. As you move the cursor in the drawing window, the entities will be resized with respect to the cursor position and the value in the **Scale Factor** edit box will change dynamically. You can also enter the required value manually in the **Scale Factor** edit box to resize the entities. Alternatively, you can specify the coordinates of

the base point by using the **Inventor Precise Input** toolbar. To do so, select the **Precise Input** check box in the **Scale** dialog box; the **Inventor Precise Input** toolbar will be displayed. Specify the coordinates to locate the base point.

FINDING THE CENTER OF GRAVITY

Ribbon: View > Visibility > Center of Gravity **This tool allows you to find the Center of Gravity (COG) of a model or an assembly. To invoke this tool, choose the Center of Gravity tool from the Visibility panel of the View tab; the Autodesk Inventor Professional message box will be displayed, as shown in Figure 17-3.**




Figure 17-3 The Autodesk Inventor Professional message box

Choose the **OK** button from the dialog box; the Center of Gravity triad will be displayed, as shown in the Figure 17-4. The red arrow indicates the X-axis, the green arrow indicates the Y-axis, the blue arrow indicates the Z-axis, and the yellow sphere indicates the location of the Center of Gravity of the selected component. This triad also includes three selectable work planes and a selectable work point at the origin of COG.

You can use the COG symbol as a virtual reference in the designing process. The triad can be used for measuring the distance. To measure distance, choose the **Distance** tool from the **Measure** panel of the **Inspect** tab. Next, select one of the planes of the triad, and then select a face of the model; the measurements will be displayed in the **Measure Distance** dialog box. For more information on measurement tools, refer to Chapter 3. If you modify the model, the triad becomes fade. For updating the Center of Gravity, you need to remove the existing COG triad. To do so, choose the **Center of Gravity** tool from the **View** tab again; the COG will disappear. Repeat the above procedure to display the updated COG.




Figure 17-4 Center of Gravity triad

EXTRACTING THE IFEATURE RIBBON: MANAGE > AUTHOR > EXTRACT IFEATURE FEATURES SUCH AS SLOT AND KEYWAYS ARE USED IN MOST OF THE DESIGNS WITH VARIATION IN DIMENSIONS. IN AUTODESK INVENTOR, YOU CAN CREATE THESE FEATURES AS SKETCHED FEATURES IN ONE DESIGN, AND THEN EXTRACT AND PLACE THEM IN OTHER DESIGNS. THESE EXTRACTED FEATURES ARE CALLED AS IFEATURE. THE IFEATURE IS CREATED BY USING THE **EXTRACT IFEATURE** TOOL. NOTE THAT IF A FEATURE CREATED USING THE JOIN OPERATION IS EXTRACTED AS AN IFEATURE AND PLACED ON THE OTHER MODEL, THE MATERIAL WILL BE ADDED TO THE MODEL. SIMILARLY, IF THE FEATURE CREATED USING

THE CUT OPERATION IS EXTRACTED AS AN IFEATURE AND PLACED ON THE OTHER MODEL, THE MATERIAL WILL BE REMOVED FROM THE MODEL.

Note

The features created using the 2D sketches are known as Sketched Features. Extrude, revolve, and sweep are some of the examples of the sketched features. The features that do not require a sketch are known as Placed Features. Fillet, chamfer, threads, and shells are some of the examples of the placed features.

After creating the required sketched features on the model, choose the **Extract iFeature** tool from the **Author** panel of the **Manage** tab; the **Extract iFeature** dialog box will be displayed, as shown in Figure 17-5. The options in this dialog box are discussed next.

Type Area

In this area, there are two radio buttons, **Standard iFeature** and **Sheet Metal Punch iFeature**. Select the **Standard iFeature** radio button, if you want to create the iFeature that has to be placed in the part environment. Select the **Sheet Metal Punch iFeature** radio button, if you want to create the iFeature that has to be placed in the part or sheet metal environment. Also, note that if you want to create an iFeature using the **Sheet Metal Punch iFeature** radio button, then the sketch of the original feature must have a center point.




Figure 17-5 The Extract iFeature dialog box

Selected Features Area

After invoking the **Extract iFeature** dialog box, you need to select the sketched feature to be extracted as iFeature. Select a sketched feature from the **Browser Bar**; the feature will be displayed in the **Selected Features** area along with all its dimensions. If you select the feature in this area, its dependent geometry as well as two buttons on the right of this area will get activated. Next, choose the button with arrows pointing toward right; the dimensions of the selected feature will be displayed in the **Size Parameters** area.

Size Parameters Area

This area displays the dimensions and parameters to be edited at the time of inserting an iFeature in another design. If you need to edit a particular parameter, then click in its corresponding column and edit it.

Position Geometry Area

This area displays the reference geometry that defines the position of the iFeature. It is recommended that you include all the depended geometries in this

area, so that they can be used to define the position of the iFeature while inserting it.

Manufacturing Area

The options in this area will be activated only when you select the **Sheet Metal Punch iFeature** radio button in the **Type** area. Using these options, you can specify the punch ID in the **Specify Punch ID** edit box. If you have selected multiple features to create the sheet metal punch iFeature, then you can specify the reference center point by choosing the **Select Sketch** button.

Depth Area

The **Custom** edit box in this area is used to specify the punching depth.

After defining all parameters, choose the **Save** button; the **Save As** dialog box will be displayed. This dialog box is used to save the iFeature created. The iFeature file will be saved in **.ide* file format.

INSERTING THE IFEATURE RIBBON: MANAGE > INSERT > INSERT IFEATURE THE INSERT IFEATURE TOOL IS USED TO INSERT THE IFEATURES INTO A MODEL. TO INSERT AN IFEATURE, CHOOSE THE INSERT IFEATURE TOOL FROM THE INSERT PANEL OF THE MANAGE TAB; THE OPEN DIALOG BOX ALONG WITH THE INSERT IFEATURE DIALOG BOX WILL BE DISPLAYED AS SHOWN IN FIGURE 17-6.

Now, you can select the iFeature either from the **Open** dialog box or close this dialog box and then select the iFeature by using the **Insert iFeature** dialog box.




Figure 17-6 The **Open** dialog box along with the **Insert iFeature** dialog box. In the **iFeature** dialog box, the flow chart on the left shows four indicators and their names. The active indicator turns green and the information of the respective indicator is displayed on the right pane of this dialog box. These indicators are discussed next.

Select

This indicator is chosen by default. On the right side of this indicator, the **Browse** button is available in a pane. Choose this button; the **Open** dialog box will be displayed. You can open the required *.ide file using this dialog box.

Position

When you open a *.ide file, the **Position** indicator will be activated and names of the reference geometry such as work plane, point, axis, and line will be displayed in the list box. You need to define the reference geometry in the model where you need to place it. To do so, click once on the name of the reference geometry in the dialog box and then specify its position in the drawing window.

Size

After defining the position of the reference geometry, choose the **Next** button; the **Size** indicator will be activated and the dimensions will be displayed along with their names on the right pane of the indicator. You can modify these dimensions according to your requirement.

Precise Pos.

After defining all the dimensions of the iFeature, choose the **Next** button; the **Precise Pos.** indicator will be activated and two radio buttons will be displayed in the **Upon Completion of Placement** area on the right side of the pane. These radio buttons are discussed next.

Activate Sketch Edit Immediately If you select this radio button and then choose the **Finish** button, the Sketching environment will be activated.

Do Not Activate Sketch Edit

If you select this radio button, the Sketching environment will not be activated.

After completing all the steps, choose the **Finish** button to place the iFeature.

CREATING IMATES RIBBON: MANAGE > AUTHOR
> CREATE IMATE SOME PARTS SUCH AS BOLTS,
RODS, WASHERS, NUTS, AND FLANGES ARE
USED IN MANY ASSEMBLIES IN THE SAME WAY.
SO, IF YOU SPECIFY THE MATE REFERENCES ON
SUCH PARTS BEFORE THEY ARE ASSEMBLED,
ASSEMBLING THESE PARTS WILL BE EASIER.
THESE MATE REFERENCES ARE CALLED AS
IMATES. AFTER DEFINING AN IMATE ON A PART,
IF YOU PLACE IT IN THE ASSEMBLY
ENVIRONMENT, IT WILL BE PLACED IN ITS
POSITION AUTOMATICALLY. TO CREATE AN

IMATE, FIRST CREATE THE PART OR SUBASSEMBLY AND THEN INVOKE THE **CREATE IMATE** TOOL FROM THE **AUTHOR** PANEL OF THE **MANAGE** TAB; THE **CREATE IMATE** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 17-7. THIS DIALOG BOX IS SIMILAR TO THE **PLACE CONSTRAINTS** DIALOG BOX DISCUSSED IN CHAPTERS 9 AND 10. HOWEVER, IN THIS DIALOG BOX, THE **TRANSLATION** TAB IS NOT AVAILABLE. SELECT THE TYPE OF MATE TO BE APPLIED TO THE PART FROM THE **TYPE** AREA AND THEN SELECT THE FACE TO WHICH THE MATE HAS TO BE APPLIED. NOTE THAT YOU CAN SELECT THE TYPE OF MATE FROM THE **TYPE** AREA AVAILABLE IN THE **ASSEMBLY** OR **MOTION** TAB. AT THE LOWER RIGHT CORNER OF THIS DIALOG BOX, THE **MORE** BUTTON IS PROVIDED. IF YOU CHOOSE THIS BUTTON, THE **CREATE IMATE** DIALOG BOX WILL EXPAND. FIGURE 17-8 SHOWS THE PARTIAL VIEW OF THE EXPANDED **CREATE IMATE** DIALOG BOX. THIS EXPANDED DIALOG BOX CAN BE USED TO INCREASE THE ACCURACY OF THE MATE. THE OPTIONS IN THE EXPANDED DIALOG BOX ARE DISCUSSED NEXT.




Figure 17-7 The Create iMate dialog box




Figure 17-8 Options in the expanded Create iMate dialog box

Name Area

You can specify the name of the current iMate in the edit box of this area. If you leave this area blank, a default name will be given to the iMate.

Limits Tab

In Autodesk Inventor, you can specify the maximum and minimum limits of the constraint to be applied to an iMate component. You can specify these limits in the **Maximum** and **Minimum** edit boxes in the **Limits** tab. These options of the **Limits** tab have already been discussed in detail in Chapter 9.

Matching Tab

In this tab, you can list the name of iMate with which the part will mate. When a part is placed in the assembly, the system will first try to mate the part with the iMate located in the **Match List** area. For adding, deleting, and moving the name in the list box, four buttons are provided at the right side of the list box. These buttons are discussed next.

Add name to list

If you choose this button, the **New Name** edit box will be displayed in the **Match List** list box. In the edit box, you can specify the name of the iMate to which this part has to be assembled. For adding another name, you need to choose this button again.

Delete selected name

This button is used to remove the selected name from the **Match List** list box.

Move selected name up in priority This button is used to move the selected name one step up in the **Match List** list box to change the priority of matching.

Move selected name down in priority This button is used to move the selected name one step down in the **Match List** list box to change the priority of matching.

After setting the parameters, choose the **OK** button to apply iMates. You will observe that a circular symbol is attached to a face of the part. Also, the **iMates** node is created in the **Browser Bar**.

APPLYING IMATES IN THE ASSEMBLY ENVIRONMENT FOR APPLYING IMATES IN AN ASSEMBLY, PLACE THE FIRST COMPONENT TO WHICH IMATES ARE ASSIGNED. NEXT, YOU NEED TO PLACE THE SECOND COMPONENT TO WHICH THE RESPECTIVE IMATES ARE

ASSIGNED. TO PLACE THE SECOND COMPONENT, CHOOSE THE **PLACE** TOOL FROM THE **COMPONENT** PANEL IN THE **ASSEMBLE** TAB; THE **PLACE COMPONENT** DIALOG BOX WILL BE DISPLAYED. THE BUTTONS IN THE **IMATES** AREA OF THIS DIALOG BOX CAN BE USED TO PLACE THE COMPONENT USING DIFFERENT METHODS, REFER TO FIGURE 17-9. THESE METHODS ARE DISCUSSED NEXT.



Figure 17-9 The iMates area in the Place Component dialog box

Interactively place with iMates This button is used to insert the component with matching iMates in an assembly. It also enables you to place the number of instances in an assembly.

Automatically generate iMates on place If this button is activated, then on inserting the iMate component, the component will automatically be assembled with the other respective iMate component of the assembly.

Choose the **Open** button after selecting the component and specifying the method; the part will be placed in its position automatically. If you have chosen the **Interactively place with iMates** button, then you will be prompted to

specify the next location. Else, the tool will be terminated.

VIEWING THE IPROPERTIES APPLICATION MENU: IPROPERTIES THE PROPERTIES OF THE COMPONENT CREATED IN THE ASSEMBLY ENVIRONMENT IN AUTODESK INVENTOR ARE KNOWN AS IPROPERTIES. IPROPERTIES CAN BE USED FOR CREATING REPORTS, UPDATING BOM, UPDATING TITLE BLOCK, AND TO DISPLAY ALL THE RELATED INFORMATION OF THE COMPONENT CREATED. THE OPTIONS OF IPROPERTIES ARE INTERNALLY LINKED WITH THE RELATED COMPONENT. THEREFORE, WHENEVER YOU UPDATE INFORMATION IN IPROPERTIES, IT WILL BE REFLECTED IN THE RELATED COMPONENT. YOU CAN INVOKE THIS TOOL BY CHOOSING THE **IPROPERTIES** OPTION FROM THE **APPLICATION MENU**.

ALTERNATIVELY, RIGHT-CLICK ON THE NAME OF THE COMPONENT IN THE **BROWSER BAR** OF THE CURRENT ASSEMBLY AND CHOOSE **IPROPERTIES** FROM THE SHORTCUT MENU DISPLAYED; THE **IPROPERTIES** DIALOG BOX OF THE CORRESPONDING COMPONENT WILL BE DISPLAYED, AS SHOWN IN FIGURE 17-10. THE TABS IN THIS DIALOG BOX ARE DISCUSSED NEXT.

General Tab

This tab displays the name, size, and type of the file. It also displays the date when the file was created, modified, and accessed.

Summary Tab

This tab is used for classifying and managing files. This tab displays eight edit boxes: **Title**, **Subject**, **Author**, **Manager**, **Company**, **Category**, **Keywords**, and **Comments**. You can enter the required information in these edit boxes. On choosing the **Apply** button, this information updates the Title blocks and BOM in the drawing file.




Figure 17-10 The iProperties dialog box

Note

*If the component is not saved at any location after it is created then the **iProperties** dialog box displayed will be different from the one shown in Figure 17-10.*

Project Tab

This tab is used to define the project iProperties of the component.

Status Tab

This tab is used to define the status of the component.

Custom Tab

This tab is used to add the custom iProperties of the component.

Save Tab

This tab is used for setting the saving options of the image of the component. In this tab, the **Save Preview Picture** check box is selected by default. Therefore, it saves the thumbnail image of the model that will be displayed in the **Open File** dialog box. You can turn off the image from the **Open File** dialog box by clearing this check box.

Occurrence Tab

This tab is used to specify the properties of the component. By using this tab, you can make any component grounded, adaptive and so on. You can select the **Degrees of Freedom** check box to display the degrees of freedom of a component. By selecting the **Suppress** check box, you can suppress any component. You can also set preferences for BOM Structure by using the **Current Offset from the Parent Assembly Origin** area and can place a component at an offset from the parent assembly.

*Tip. The **Occurrence** tab will be available only when you invoke the **iProperties** dialog box by right-clicking on the component of an assembly in the **Browser bar** and choose the **iProperties** option from the shortcut menu.*

Physical Tab

This tab is used to calculate and display the physical and inertial properties of the model. This helps you analyze how the differences in materials, tolerances, and dimensions can affect the model. To analyze the physical properties, select the required material from the **Material** drop-down list; the values of density, mass, area, and volume of the model are displayed for the selected material. Note that the **Material** drop-down list will be activated only in the part environment. The coordinates of the COG are displayed in the **General Properties** area. In the **Inertial Properties** area, the **Principal**, **Global** and **Center of Gravity** buttons are available. By choosing these buttons, you can view the inertial properties of the component for the applied materials.

CREATING USER-DEFINED DRAWING SHEETS
AUTODESK INVENTOR PROVIDES YOU AN
OPTION TO CREATE USER-DEFINED DRAWING
SHEETS BY DEFINING BORDER AND TITLE
BLOCK ACCORDING TO YOUR REQUIREMENT.
THE PROCEDURES TO CREATE THE USER-
DEFINED DRAWING SHEETS ARE DISCUSSED
NEXT.

Whenever you open a drawing (.*idw*) file, the **Drawing Resources** node will be displayed in the **Browser Bar**. Click on the plus (+) sign beside the **Drawing Resources** node to expand it. Three sub-nodes will be displayed under this node. These sub-nodes and their options are discussed next.

Sheet Formats

Click on the plus (+) sign of this sub-node; a list of drawing sheets will be displayed. If you right-click on any of these sheets; a shortcut menu will be displayed, as shown in Figure 17-11. Choose **New Sheet** from the shortcut menu; the **Select Component** dialog box will be displayed, as shown in Figure

17-12. In this dialog box, choose the button on right of the **Document Name** drop-down list and open a part or an assembly; the path of the selected component will be displayed in the **Document Name** drop-down list. Choose the **OK** button from the **Select Component** dialog box; the selected model will be drafted in the new sheet with a number of views. Note that the number of views and the size of the new sheet depend upon the name of the sheet selected in the **Browser Bar**.




Figure 17-11 Creating a new sheet using the shortcut menu




Figure 17-12 The Select Component dialog box

Borders

The **Borders** sub-node has a predefined border style, which will be applied to the sheet. You can also define and insert a new border and new zone border in the drawing sheet using this node. The procedures to define a new border, border zone, and inserting a new border zone are discussed next.

Defining a New Border

To define a new border, choose the **Define New Border** option from the shortcut menu that is displayed on right-clicking on the **Borders** sub-node, refer to Figure 17-13; the sketching environment will be activated. You can draw a

border in the sketching environment based on your requirement. After drawing the border, choose the **Return** tool from the **Quick Access Toolbar** or choose the **Finish Sketch** button from the **Exit** panel of the **Sketch** tab; the **Border** dialog box will be displayed, as shown in Figure 17-14. Enter a new name in the **Name** edit box and choose the **Save** button; the new name will be displayed in the **Browser Bar** below the **Borders** node.




Figure 17-13 Choosing the **Define New Border** from the shortcut menu





Figure 17-14 The **Border** dialog box

Defining a New Zone Border

To define a new zone border, choose the **Define New Zone Border** option from the shortcut menu that is displayed on right-clicking on the **Borders** sub-node; the **Default Drawing Border Parameters** dialog box will be displayed. In this dialog box, you can set the horizontal and vertical zones of the border from the respective areas. If you choose the >> button from the lower right corner of this dialog box, the **Default Drawing Border Parameters** dialog box will expand, as shown in Figure 17-15. In the expanded area, you can set the appearance of the border. After setting all parameters, choose the **OK** button; the new border with its dimensions will be displayed in the sketching environment, where you

can edit these dimensions. You can modify the border using the tools provided in the sketching environment. After modifying the border according to the requirements, choose the **Return** button from the **Quick Access Toolbar**; the **Borders** dialog box will be displayed again, refer to Figure 17-14. Enter a new name in the **Name** edit box and choose the **Save** button; the new name will be displayed in the **Browser Bar** below the **Borders** sub-node.



*Figure 17-15 The **Default Drawing Border Parameters** dialog box*

Inserting a New Border

For inserting a new border, you need to delete the existing border. To do so, right-click on the **Default Border** option available in the **Sheet:1** node of the **Browser Bar**; a shortcut menu will be displayed, as shown in Figure 17-16. Choose the **Delete** option from the shortcut menu; the existing border will be deleted from the drawing sheet as well as from the **Browser Bar**. After deleting the border, click on the **Borders** sub-node; all available borders will be displayed. Double-click on any of the borders; the selected border will be displayed in the active drawing sheet.




Figure 17-16 Deleting the existing border using the shortcut menu

Title Blocks

The **Title Blocks** sub-node has a predefined title block. You can define a new title block using the procedure given next.

Defining a New Title Block

Choose the **Define New Title Block** option from the shortcut menu of the **Title Blocks** sub-node, as shown in Figure 17-17; the sketching environment will be activated. You can draw a title block in the sketching environment based on your requirements. After drawing the title block, choose the **Finish Sketch** button from the **Exit** panel of the **Ribbon**; the **Title Block** dialog box will be displayed, as shown in Figure 17-18. Enter a new name in the **Name** edit box and choose the **Save** button; the name will be displayed in the **Browser Bar** below the **Title Blocks** sub-node. You can insert a new title block in a way similar to inserting a new border.




Figure 17-17 Defining a new title block using the shortcut menu




Figure 17-18 The Title Block dialog box

Creating a Customized Title Block You can create a customized title block based on your requirements that gets updated when its iProperties change. To do so, right-click on the name of the title block that is available in the **Browser Bar** below the **Title Blocks** sub-node; a shortcut menu will be displayed, as shown in Figure 17-19. Choose the **Edit** option from the shortcut menu; the sketching environment will be activated. Also, the title block along with the dimensions and names will be displayed in the drawing window, as shown in Figure 17-20. These names are internally linked with the iProperties of the active drawing file. Therefore, it is recommended that while editing the title block, keep the required names and delete the remaining portion of the title block.





Figure 17-19 The shortcut menu of the existing title block



*Figure 17-21 Choosing the **Text Box** option from the Marking Menu*




Figure 17-22 Editing a title block in the Sketching environment

After customizing the title block, choose the **Return** tool from the **Quick Access Toolbar**; the **Save Edits** message box will be displayed, as shown in Figure 17-23. If you choose the **Yes** button from this message box, then the changes made to the title block will be saved in the existing title block and will be displayed in the drawing window, as shown in Figure 17-24. If you choose the **Save As** button, the **Title Block** dialog box will be displayed. In the **Name** edit box of this dialog box, you can enter the name for the title block. On doing so, the name

will be displayed in the **Title Blocks** sub-node in the **Browser Bar**.




Figure 17-23 The Save Edits message box

CADCIM		
5/6/2011		

Figure 17-24 Customized title block created

Next, choose the **iProperties** option from the **Application Menu** to invoke the **iProperties** dialog box. Enter the required information in different tabs of the dialog box for the current drawing. Now, choose the **Apply** button and then the **Close** button from the **iProperties** dialog box; the information will be displayed in the title block, see Figure 17-25.

CADCIM Technologies		
CADCIM	XYZ	Template
5/6/2011	5/6/2011	Casting

Figure 17-25 The updated title block with the change in its iProperties

Inserting a New Title Block


Click on the plus (+) sign of the **Title Blocks** sub-node in the **Browser Bar**; the list of all available title blocks will be displayed in the **Browser Bar**. You can insert any of the title blocks from this list. Note that you need to delete the existing title block before inserting a new one. To delete the existing title block, click on the plus (+) sign of the sheet in the **Browser Bar**; a node list will be displayed. Next, right-click on the name of the title block available below the name of the sheet **Sheet:1** in the **Browser Bar**; a shortcut menu will be displayed, as shown in Figure 17-26. Choose the **Delete** option from the shortcut

menu; the existing title block will be deleted. To activate another title block, double-click on the name of the title block that is available in the **Title Blocks** sub-node in the **Browser Bar**; the selected title block will be displayed in the drawing window.


Tip. It is recommended that you save the file after creating the customized border and title block so that you can use it as a template file.

Creating Sketch Symbols

Sometimes in the drafting process, you need to use some special symbols frequently. For this, Autodesk Inventor provides a special sub-node, named **Sketched Symbols**. You can use this option to create a customized sketch symbol that can be used whenever you want. To do so, right-click on the **Sketched Symbols** sub-node in the **Browser Bar**; a shortcut menu will be displayed, as shown in Figure 17-27. If you choose **Define New Symbol** from the shortcut menu, the sketching environment will be activated. You can draw any symbol by using the sketching tools of the **Create** panel in the **Sketch** tab. After creating a symbol, if you choose the **Return** tool from the **Quick Access Toolbar**, the **Sketched Symbol** dialog box will be displayed. Enter a name for the symbol in the **Name** edit box and choose the **Save** button; the name will be displayed below the **Sketched Symbols** in the **Browser Bar**. If you double-click on that name in the **Browser Bar**, then the cursor will be changed to a plus (+) sign. Next, if you click anywhere in the drawing window, the sketch symbol that you created will be placed at that point. You can place a number of sketch symbols in the drawing window by clicking at various points.



*Figure 17-26 Choosing the **Delete** option from the shortcut menu*



*Figure 17-27 The shortcut menu of the **Sketched Symbols** sub-node*

*Tip. If you have generated the drawing views of a model or an assembly, you can display the COG mark on it. To do so, click on the (+) sign on the right of the **View** node; the model or assembly node will be displayed. Next, right-click on the corresponding model or assembly node to invoke a shortcut menu. Choose the **Center of Gravity** option from this shortcut menu; a plus (+) sign will be displayed on the related drawing view indicating the position of the COG of that model.*

IMPORTING AUTOCAD BLOCKS INTO INVENTOR RIBBON: ANNOTATE > SYMBOLS > IMPORT

AUTOCAD BLOCK IN AUTODESK INVENTOR, YOU CAN IMPORT THE BLOCKS CREATED IN AUTOCAD INTO THE DRAWING SHEETS OF INVENTOR. ALSO, YOU CAN MOVE, SCALE, AND ROTATE THEM IN INVENTOR. TO IMPORT AN AUTOCAD BLOCK INTO INVENTOR, FIRST CREATE IT IN AUTOCAD AND THEN SAVE IT. NEXT, START A NEW DRAWING (DWG) FILE IN INVENTOR AND CHOOSE THE **IMPORT AUTOCAD BLOCK** TOOL FROM **ANNOTATE > SYMBOLS** IN THE **RIBBON**; THE **IMPORT BLOCK** DIALOG BOX WILL BE DISPLAYED, AS SHOWN IN FIGURE 17-28.

Browse to the required AutoCAD file and then select it; all blocks created in the file will be displayed in the form of icons in the **Block Definitions** area of the **Import Block** dialog box, see Figure 17-28. Select the required block from the **Block Definitions** area and then specify the scale and rotation angle values in the **Scale** and **Rotate** edit boxes at the bottom of the dialog box. Next, choose the **Insert** button; the **Import Block** dialog box will disappear and you will be prompted to insert the AutoCAD block. Note that the **Insert** button will be available only when you select a block from the **Block Definitions** area. Click on the drawing sheet at the location where you want to place the block; the block will be placed at the specified location. You can place any number of AutoCAD blocks in the drawing sheet.

After inserting the required block, right-click and then choose **Done [ESC]** from the shortcut menu; the inserted blocks will be displayed in the **AutoCAD Blocks** node under the **Sheet** node in the **Browser Bar**, refer to Figure 17-29. Expand the **AutoCAD Blocks** node to display the inserted blocks. If you double-click on a block, the **AutoCAD Blocks** dialog box will be displayed, as shown in Figure 17-30. In this dialog box, you can specify the scale and rotation angle values in

their respective edit boxes. By default, the **Static** check box is selected in this dialog box. As a result, the AutoCAD block behaves as static entity and you cannot rotate or scale it manually. However, you can move it by using the base point grip that is displayed in green in the drawing sheet. If you clear this check box, the grips surrounding the block will be displayed. With the help of these grips, you can scale, move, and rotate a block manually. The yellow, green, and blue grips are used to scale, move, and rotate the block, respectively.




Figure 17-28 The *Import Block* dialog box

Figure 17-31 shows an AutoCAD block with grips displayed on it in the drawing sheet.

Note

1. You can also invoke the **AutoCAD Blocks** dialog box by using the **Drawing Resources** node in the **Browser Bar**. To do so, expand the **Drawing Resources** node; the sub-nodes of this node will be displayed, refer to Figure 17-29. Expand the **AutoCAD Blocks** node; all the inserted blocks will be displayed under this node. Next, right-click on the required block and choose the **AutoCAD Blocks** option from the shortcut menu; the **AutoCAD Blocks** dialog box will be displayed, refer to Figure 17-30.

2. The **Import AutoCAD Block** tool will be available only when you select the **.dwg** template from the **Create New File** dialog box to create a new drawing file.




Figure 17-29 AutoCAD blocks in the **Sheet** and **Drawing Resources** nodes in the **Browser Bar**




Figure 17-30 The **AutoCAD Blocks** dialog box




Figure 17-31 Grips displayed on an AutoCAD block

TUTORIALS

Tutorial 1

In this tutorial, you will create a shaft with a groove, as shown in Figure 17-32. Extract the groove as an iFeature and place it on a hexagonal bar, as shown in Figure 17-33.

(Expected time: 45 min)




Figure 17-32 A shaft with a groove




Figure 17-33 Hexagonal bar with a groove

The following steps are required to complete this tutorial:

- a. Create a circular shaft and chamfer the sharp edges.
- b. Draw the profile for the groove on the XZ-plane and apply the dimensions to the profile, refer to Figure 17-34.
- c. Revolve the profile about the Z-axis using the **Cut** option, refer to Figure 17-35.
- d. Extract the iFeature of the groove using the **Extract iFeature** tool.
- e. Create a hexagonal shaft and place the iFeature by using the **Insert iFeature** tool.
- f. Save the model.

Creating the Shaft

First, you need to create a shaft and then create an iFeature from it.

1. Start a new metric file and invoke the Sketching environment by selecting XY plane as the sketching plane. By default, a point is displayed at the origin (0,0).

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*
2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to*

*the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

2. On the XY plane, create a circle of 50 mm diameter such that its center coincides with the origin. Next, exit the Sketching environment.
3. Extrude the profile to 100 mm using the **Extrude** tool.
4. Apply the chamfer of 2 mm at the ends of the shaft.

Creating the Groove 1. Choose the **Start 2D Sketch** tool from the **Sketch** panel of the **3D Model** tab and select the **XZ** Plane as the Sketching plane; the Sketching environment is invoked.

2. Use the ViewCube to orient the model, see Figure 17-34.
3. Press the F7 key to slice the model.
4. Draw a rectangle and apply vertical dimensions (20 mm and 25 mm) to it with respect to the origin, refer to Figure 17-34. Apply the horizontal dimension (15 mm) to it with respect to the origin, see Figure 17-34. Also, dimension the length (8 mm) of the rectangle.
5. Choose the **Finish Sketch** tool from the **Exit** panel of the **Sketch** tab; the part modeling environment is displayed.
6. Invoke the **Revolve** tool. Next, choose the **Cut** option from the **Operation** area and create the groove feature with Z axis as the axis of the revolution, see Figure 17-35.




Figure 17-34 Dimensions applied to the profile for creating a groove



Figure 17-35 The shaft after creating the groove

7. Save the part with the name *shaft_iFeature.ipt* at the following location:
C:\Inventor_2016\c17\Tutorial1

Creating the iFeature

1. Choose the **Extract iFeature** tool from the **Author** panel of the **Manage** tab; the **Extract iFeature** dialog box is displayed.
2. Select the **Revolution1** node in the **Browser Bar**; the name of the feature and its related dimensions and references are displayed in the **Selected Features** area of the **Extract iFeature** dialog box.
3. Select **Center Point** from the **Browser Bar**; the **Center Point** is displayed along with **Extrusion1**, **Chamfer1**, and **Revolution1** in the **Selected Features** area. It is also displayed in the **Position Geometry** area with the name **Point1**.
4. Right-click on **Extrusion1** in the **Selected Features** area and then choose **Remove Feature** from the flyout displayed; all features except **Center Point** and **Revolution1** are removed from the **Selected Features** area.
5. Select the **Revolution1** node from the **Selected Features** area and choose the double arrow pointing toward the right; all related dimensions are displayed in the **Size Parameters** area and **Sketch Plane1** is displayed in the **Position Geometry** area.

6. Select **Z Axis** from the **Browser Bar**; the **Z Axis** is displayed in the **Selected Features** area. It is also displayed in the **Position Geometry** area with the name **Axis1**.

You will notice that in the **Size Parameters** area, default names are displayed in the **Prompt** column. You need to change these names. Changing the default names will make identifying and modifying a parameter easy when you insert iFeatures. Follow the steps given next to edit default names.

7. Click once in the field corresponding to the value 20 mm in the **Prompt** column; an edit box is displayed.
8. Enter **ID** in the edit box.
9. Similarly, change the default names for the remaining values in the **Prompt** column as given next in the table.

Value	Prompt to be modified as
15	REF
25	OD
8	GW

10. Change the field corresponding to **Sketch Plane1** to **Sketch Plane** in the **Prompt** column of the **Position Geometry** area.
11. Similarly, change the fields corresponding to **Point1** and **Axis1** to **Center Point** and **Z Axis**, respectively in the **Prompt** column of the **Position Geometry** area. After changing the prompts, the **Extract iFeature** dialog box appears, as shown in Figure 17-36.




Figure 17-36 The **Extract iFeature** dialog box

12. Choose the **Save** button from the **Extract iFeature** dialog box; the **Save As** dialog box is displayed.

13. Save the iFeature with the name *groove_iFeature.ide* at the following location:

C:\Inventor_2016\c17\Tutorial1

14. Save the part file and close it.

Creating the Hexagonal Shaft

1. Start a new part file.

2. Create a hexagon on the XY-plane, as shown in Figure 17-37.

Note

1. Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.

2. *If the orientation of the ViewCube is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the ViewCube; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*
3. Extrude the profile up to 150 mm.
 4. Choose the **Insert iFeature** tool from the **Insert** panel of the **Manage** tab; the **Insert iFeature** dialog box along with the **Open** dialog box is displayed. Close the **Open** dialog box by choosing **Cancel** button from **Open** dialog box.
 5. Choose the **Browse** button from the **Insert iFeature** dialog box; the **Open** dialog box is displayed again.
 6. Open the *groove_iFeature.ide* file from *C:\Inventor_2016\c17\Tutorial1*; the **Position** indicator is activated. Also, on the right of the pane, **Sketch Plane1** is highlighted in red. On the lower side of the dialog box, a prompt is displayed prompting you to select the sketching plane for placing iFeature.
 7. Select **XZ Plane** from the **Browser Bar**.
 8. Next, select **Point1** from the right pane of the dialog box; it turns red and you are prompted to select the Center Point. Select **Center Point** from the **Browser Bar**.
 9. Select **Axis1** from the right pane of the dialog box; it turns red and you are prompted to select the Z Axis. Select the **Z Axis** from the **Browser Bar**.




Figure 17-37 Sketch for creating the Hexagonal shaft

10. Choose the **Next** button in the **Insert iFeature** dialog box; the **Size** indicator is highlighted in the left pane of the dialog box. Similarly, in the right pane of the dialog box, the dimensions of the iFeature are displayed.
11. Click on 20 mm in the right pane, **ID** is displayed in the prompt box.
12. Enter **22 mm** in place of 20 mm.
13. Click on 15 mm; **REF** is displayed in the prompt box. Enter **18 mm** in place of 15 mm.
14. Click on 25 mm; **OD** is displayed in the prompt box. Enter **30 mm** in place of 25 mm.
15. Click on 8 mm; **GW** is displayed in the prompt box. Enter **10 mm** in place of 8 mm.
16. Choose the **Refresh** button from the dialog box; the preview of the iFeature is displayed on the model.




Figure 17-38 The iFeature applied to the model

17. Choose the **Next** button; the **Precise Pos.** indicator is activated on the left in the dialog box and the **Do Not Activate Sketch Edit** radio button is selected automatically.
18. Choose the **Finish** button; the iFeature is applied to the model, refer to Figure 17-38. You will notice that the **iFeature** node is created in the **Browser Bar**.
19. Save the model with the name `applied_iFeature` at the location `C:\Inventor_2016\c17\Tutorial1` and then close the file.

Tutorial 2

In this tutorial, you will create a circlip and a shaft using the dimensions given in Figures 17-39 and 17-40. Apply iMates to the circlip and the groove of the shaft. Then, assemble the parts using the **Insert** constraint, as shown in Figure 17-41. **(Expected time: 45 min)**




Figure 17-39 The Circlip for Tutorial 2




Figure 17-40 A shaft with a groove




Figure 17-41 Final assembly

The following steps are required to complete this tutorial:

- a. Create the shaft.
- b. Apply iMates to the groove of the shaft using the **Create iMates** tool.
- c. Create the circlip and apply fillets according to dimensions.
- d. Apply iMates to the circlip using the **Create iMates** tool.
- e. Place the shaft in the new assembly file.
- f. Place the circlip into the assembly using the **Automatically generate iMates on place** button from the **Place Component** dialog box.
- g. Save the Assembly.

Applying iMates to the Shaft

1. Create the shaft with groove, refer to Figure 17-40 for dimensions.




Figure 17-42 The Create iMate dialog box

2. Choose the **Create iMate** tool from the **Author** panel of the **Manage** tab; the **Create iMate** dialog box is displayed. Choose the **Insert** button from the **Type** area.

3. Choose the >> button available at the lower right corner of the dialog box; the dialog box expands.
4. Enter **insert_1** in the **Name** edit box and then choose the **Matching** tab; the **Match List** area is displayed, see Figure 17-42.
5. Choose the **Add name to list** button from the **Match List** area; an edit box is displayed in the list box.
6. Enter **insert_2** in the edit box displayed, refer to Figure 17-42.
7. Accept the default settings for the rest of the options and select the inner edge of the groove from the drawing area.
8. Choose the **Apply** button and then the **Cancel** button to close the dialog box.
9. Save the model with the name *shaft.ipt* and close the file.

Creating the Circlip

1. Start a new part file and invoke the Sketching environment by selecting XY plane as the sketching plane.
2. Draw the profile for creating a circlip and then apply dimensions to it, as shown in Figure 17-43.
3. After drawing the sketch, extrude the profile up to 8 mm.
4. Apply the fillets of 1 mm radius to the model. The model after creating the fillets is shown in Figure 17-44.




Figure 17-43 Dimensions for circlip



Figure 17-44 Final rotated model of circlip

Applying iMates to the Circlip

1. Choose the **Create iMate** tool from the **Author** panel of the **Manage** tab; the **Create iMate** dialog box is displayed. Now, choose the **Insert** button from the **Type** area.
2. Choose the >> button from the lower right corner of the dialog box; the dialog box expands.
3. Enter **insert_2** in the **Name** edit box. Note that this is the name you entered in the **Match List** area of the **Create iMate** dialog box while setting the iMate of the shaft, refer to Figure 17-42.
4. Choose the **Matching** tab from the **Create iMate** dialog box and then choose the **Add name to list** button from the **Match List** area; an edit box is displayed in the list box.

5. Enter **insert_1** in the edit box displayed. Note that this is the name you had specified as the name of iMate of the shaft.
6. Choose the inner edge of the circlip.
7. Accept the default settings for the rest of the options. Next, choose the **Apply** button and then the **Cancel** button to close the dialog box.
8. Save the model with the name *circlip.ipt* and then close the file.

Assembling the Circlip and the Shaft Using iMates 1. Start a new assembly file and choose the **Place** tool from the **Component** panel of the **Assemble** tab; the **Place Component** dialog box is displayed.

2. Place the component *shaft.ipt* in the Graphics window.
3. Again, invoke the **Place Component** dialog box by choosing the **Place** tool from the **Assemble** tab.
4. Choose the **Automatically generate iMates on place** button from the **iMates** area of the **Place Component** dialog box.
5. Open the part file *circlip*; the circlip is automatically assembled with the shaft, as shown in Figure 17-45.




Figure 17-45 Final model after applying the iMates

6. Save the assembly with the name *iMate_assembly.iam* at the location given below:

C:\Inventor_2016\c17\Tutorial2

Answer the following questions and then compare them to those given at the end of this chapter:

1. The **Scale** tool is used to resize the selected sketched entities with respect to the specified _____.
2. The triad of the Center of Gravity can be used for measuring _____.
3. You can specify the punching depth in the _____ area for creating a Sheet Metal Punch iFeature.
4. The file format of iFeature is _____.
5. You need to _____ the existing border before inserting a new type of border into a sheet.

6. When you open the required *.ide file, the _____ indicator is activated automatically for inserting the iFeature.
7. In Autodesk Inventor, you cannot find the Center of Gravity of an assembly in the drawing environment. (T/F)
8. The features created by using 2D sketches are known as placed features. (T/F)
9. iMates are used to place parts in their proper positions automatically. (T/F)
10. The **Translation** tab is available in the **Create iMate** dialog box. (T/F)

Answer the following questions:

1. Which of the following buttons from the **Place Component** dialog box is used to insert a component with matching iMates into an assembly?

(a) **Create iMate** (b) **Interactively place with iMates** (c) **Create iFeature** (d) **Automatically generate iMates on place**
2. Which of the following tabs is used to calculate and display the physical and inertial properties of a part or an assembly?

(a) **Physical** (b) **Summary** (c) **Project** (d) **Custom**
3. Which of the following environments is invoked when you choose the **Define New Title Block** option from the shortcut menu of the **Title Blocks** node?

(a) Drawing (b) Part (c) Sketching (d) Assembly
4. Which of the following dialog boxes will be displayed if you choose the **Define New Zone Border** option from the shortcut menu that is displayed on right-clicking on the **Border** node?

(a) **Border** (b) **Default Drawing Border Parameters** (c) **Title Block** (d) **Name**
5. When the **Size** indicator is activated, _____ will be displayed on the right pane of the **Insert iFeature** dialog box.
6. You cannot set the priority of the Mate reference in the **Create iMate** dialog box. (T/F)
7. There is only one button available in the **Selections** area of the **Create iMate** dialog box. (T/F)

8. A feature must include a center point for creating a Sheet Metal Punch iFeature. (T/F)
9. The **iProperties** dialog box can be used for creating reports, updating BOM, and updating title blocks. (T/F)
10. When you open an *.idw file, the **Drawing Resources** folder is displayed in the **Browser Bar**. (T/F)

Exercise 1

Create a Nut according to the dimensions shown in Figure 17-46. The threads of the Nut to be created are ANSI Metric M Profile with a size of 14 and M14X2 designation. Next, apply the iMate constraints on the Nut and bolt (For dimensions of the bolt, refer to Tutorial 2 of Chapter 8). Assemble both the nut and the bolt using the iMates. The final model is shown in Figure 17-47. **(Expected time: 45 min)**




Figure 17-46 Dimensions for creating the Nut




Figure 17-47 Final assembly after applying the iMates

Answers to Self-Evaluation Test **1.** base point, **2.** distance, **3. Depth**, **4.** *.ide, **5.** delete, **6. Position**, **7.** F, **8.** F, **9.** T, **10.** F

CHAPTER 18

Introduction to Stress Analysis

Learning Objectives

After completing this chapter, you will be able to:

- *Understand the basic concept and general working of FEA.*
- *Understand the types of analysis.*
- *Understand how FEA helps INVENTOR to solve problems.*
- *Understand the important terms and definitions in FEA.*
- *Set the analysis preferences and units.*
- *Understand the analysis procedure in Inventor Professional.*

Introduction To FEA

The Finite Element Analysis (FEA) is a computing technique that is used to obtain approximate solution to boundary value problems. It is the numerical procedure to find the solution of engineering problems like stress analysis, thermal analysis, fluid flow analysis, electrical analysis and so on. These problems are basically the mathematical models for physical situation. These mathematical models are differential equations with a set of boundary values and

initial conditions. The method used to derive these equations is called Finite Element Method (FEM).

The concept of FEA can be explained with a small example of measuring the perimeter of a circle. To measure the perimeter of a circle without using the conventional formula, divide the circle into equal segments, as shown in Figure 18-1. Next, join the start point and the endpoint of each of these segments with a straight line. Now, you can measure the length of straight line very easily, and thus, the perimeter of the circle by adding the length of these straight lines.




Figure 18-1 The circle divided into small equal segments

If the number of segments into which a circle divided is less, you will not get accurate results. For accuracy, divide the circle into more number of segments. However, with more segments, the time required to get the accuracy will be more. The same concept can be applied to FEA also, and therefore, there is always a compromise between accuracy and speed while using this method. This compromise between accuracy and speed makes it an approximate method.

The FEA was first developed to be used in the aerospace and nuclear industries, where the safety of structures is critical. Today, even the simplest of products rely on FEA for design evaluation.

The FEA simulates the loading conditions of a design and determines the design response in those conditions. It can be used in new product design as well as in existing product refinement. A model is divided into a finite number of regions/divisions called elements. These elements can be of predefined shapes, such as triangular, quadrilateral, hexahedron, tetrahedron, and so on. The predefined shape of an element helps define the equations that describe how the

element will respond to certain loads. The sum of the responses of all elements in a model gives the total response of the design.

TYPES OF ENGINEERING ANALYSIS

THE FOLLOWING TYPES OF ANALYSIS CAN BE PERFORMED BY USING THE FEA SOFTWARE:

1. Structural analysis
2. Thermal analysis
3. Fluid flow analysis
4. Electromagnetic field analysis
5. Coupled field analysis

Structural Analysis

In structural analysis, first the nodal degrees of freedom (displacement) are calculated and then the stress, strains, and reaction forces are calculated from nodal displacements. The classification of structural analysis is shown in Figure 18-2. The types of structural analysis are discussed next.




Figure 18-2 Types of structural analysis

Static Analysis

In static analysis, the load or field conditions do not vary with respect to time, and therefore, it is assumed that the load or field conditions are applied gradually, not suddenly. The system under this analysis can be linear or nonlinear. The inertia and damping effects are ignored in structural analysis. In structural analysis, the following matrices are solved:

$$[K] \times [X] = [F]$$

Where,

K = Stiffness Matrix

X = Displacement Matrix

F = Load Matrix

The above equation is called the force balance equation for the linear system. If the elements of matrix $[K]$ are the function of $[X]$, the system is known as the nonlinear system. Nonlinear systems include large deformation, plasticity, creep, and so on. The loadings that can be applied in a static analysis include:

1. Externally applied forces and pressures
2. Steady-state inertial forces (such as gravity or rotational velocity)
3. Imposed (non-zero) displacements
4. Temperatures (for thermal strain)
5. Fluences (for nuclear swelling)

Following can be the outputs of analysis performed by FEA software:

1. Displacements
2. Strains
3. Stresses
4. Reaction forces

Dynamic Analysis

In dynamic analysis, the load or field conditions do vary with time. In this analysis, the assumption is that the load or field conditions are applied suddenly. The system can be linear or nonlinear. The dynamic load includes oscillating loads, impacts, collisions, and random loads. The three main categories of the dynamic analysis are discussed next.

Modal Analysis

It is used to calculate the natural frequency and mode shape of a structure.

Harmonic Analysis

It is used to calculate the response of a structure to the loads that are varying with time harmonically.

Transient Dynamic Analysis

It is used to calculate the response of a structure to arbitrary time varying

loads.

Spectrum Analysis

This is an extension of the modal analysis and is used to calculate stress and strain due to the response of the spectrum (random vibrations). For example, you can use it to analyze how well a structure will perform and survive in an earthquake.

Buckling Analysis

This type of analysis is used to calculate the buckling load and the buckling mode shape. Slender structures (thin and long) when loaded in the axial direction, buckle under relatively small loads. For such structures, the buckling load becomes a critical design factor.

Explicit Dynamic Analysis

This type of structural analysis is used to get fast solutions for large deformation dynamics and complex contact problems, for example, explosions, aircraft crash worthiness, and so on.

Thermal Analysis

The thermal analysis is used to determine the temperature distribution and related thermal properties such as:

1. Thermal distribution
2. Amount of heat loss or gain
3. Thermal gradients
4. Thermal fluxes

All primary heat transfer modes such as conduction, convection, and radiation can be simulated. You can perform two types of thermal analysis by using the FEA software: Steady-State and Transient.

Steady State Thermal Analysis

In this analysis, the system is studied under steady thermal loads with respect to time.

Transient Thermal Analysis

In this analysis, the system is studied under varying thermal loads with respect to time.

Fluid Flow Analysis

This analysis is used to determine the flow distribution and temperature of a fluid. The outputs that are expected from the fluid flow analysis are velocities, pressure, temperature, and film coefficients.

Electromagnetic Field Analysis

This type of analysis is conducted to determine the magnetic fields in electromagnetic devices. The types of electromagnetic analyses are:

1. Static analysis
2. Harmonic analysis
3. Transient analysis

Coupled Field Analysis

This type of analysis considers the mutual interaction between multiple fields. It is impossible to solve fields separately because they are interdependent. Therefore, you need a program that can solve both the physical problems by combining them.

For example, if a component is bent in different shapes using one of the metal forming processes and then subjected to heating, the thermal characteristics of the component will depend on the new shape of the component. Therefore, first the shape of the component has to be determined through structural simulations. This is known as coupled field analysis.

GENERAL PROCEDURE TO CONDUCT FINITE ELEMENT ANALYSIS

The following steps are used to conduct the Finite Element Analysis:

1. Set the type of analysis to be used.
2. Create model.

3. Define the element type.
4. Divide the given problem into nodes and elements (mesh the model).
5. Apply material properties and boundary conditions.
6. Derive element matrices and equations.
7. Assemble element equations.
8. Solve the unknown quantities at nodes.
9. Interpret the results.

FEA through Software

The Finite Element Analysis process can be carried out in three main phases using software: preprocessor, solution, and postprocessor, refer to Figure 18-3.




Figure 18-3 The general process of FEA

Preprocessor

The preprocessor is a phase that processes the input data to produce the results, which are used as input in the subsequent phase (solution). The following are the input data that need to be given to the preprocessor:

1. Type of analysis
2. Geometric Model

3. Meshing
4. Material properties
5. Loadings and boundary conditions

The input data are preprocessed for the output data. These data files are used in the subsequent phase (solution), refer to Figure 18-3.

Solution

The solution phase is completely automatic. The FEA software generates element matrices, computes nodal values and derivatives, and stores the result data in files. These files are further used in the subsequent phase (postprocessor) to review and analyze the results through the graphic display and tabular listings, refer to Figure 18-3.

Postprocessor

The output from the solution phase (result data files) is in the numerical form and consists of nodal values of the field variable and its derivatives. For example, in structural analysis, the output of the postprocessor is nodal displacement and stress in elements. The postprocessor processes the result data and displays them in graphical form to check or analyze the result. The graphical output gives the detailed information about the required result data. The postprocessor phase is automatic and generates graphical output in the specified form, refer to Figure 18-3.

IMPORTANT TERMS AND DEFINITIONS

THERE ARE SOME IMPORTANT TERMS AND DEFINITIONS USED IN FEA SOFTWARE THAT ARE DISCUSSED NEXT.

Strength

When a material is subjected to an external load, the system undergoes a deformation. The material, in turn, offers resistance against this deformation. This resistance is offered by the material by virtue of its strength.

Load

The external force acting on a body is called load.

Stress

The force of resistance offered by a body per unit area against the deformation is called stress. The stress is induced in the body while the load is being applied on the body. The stress is calculated as load per unit area.

$$p = F/A$$

Where,

p = Stress in N/mm^2

F = Applied Force in Newton

A = Cross-Sectional Area in mm^2

The material can undergo various types of stresses which are discussed next.

Tensile Stress

If the resistance offered by a body is against the increase in the size, the body is said to be under tensile stress.

Compressive Stress

If the resistance offered by a body is against the decrease in the size, the body is said to be under compressive stress. Compressive stress is just the reverse of tensile stress.

Shear Stress

The shear stress exists when two materials tend to slide across each other in any typical plane of shear on the application of force parallel to that plane. In other words, shear stress is generated in the body when force is applied parallel to the cross-section of the body.

$$\text{Shear Stress} = \text{Shear resistance (R)} / \text{Shear area (A)}$$

Strain

When a body is subjected to a load (force), its length changes. The ratio of change in the length to the original length of the member is called strain. If the body returns to its original shape on removing the load, the strain is called elastic strain. If the body remains distorted after removing the load, the strain is called plastic strain. The strain can be of three types, tensile, compressive, and shear

strain.

Strain (e) = Change in Length (dl) / Original Length (l)

Elastic Limit

The maximum stress that can be applied to a material without producing the permanent deformation is known as the elastic limit of the material. If the stress is within the elastic limit, the material returns to its original shape and dimension on removing the external stress. The following laws are used to define the response of elastic limit.

Hooke's Law

This law states that the stress is directly proportional to the strain within the elastic limit.

Stress / Strain = Constant (within the elastic limit)

Young's Modulus or Modulus of Elasticity

In case of axial loading, the ratio of intensity of the tensile or compressive stress to the corresponding strain is constant. This ratio is called Young's modulus, and is denoted by E.

$$E = p/e$$

Shear Modulus or Modulus of Rigidity

In case of shear loading, the ratio of shear stress to the corresponding shear strain is constant. This ratio is called Shear modulus, and it is denoted by C, N, or G.

Ultimate Strength

The maximum stress that a material withstands when subjected to an applied load is called its ultimate strength.

Factor of Safety

The ratio of the ultimate strength to the estimated maximum stress in ordinary

use (design stress) is known as factor of safety. It is necessary that the design stress is within the elastic limit, and to achieve this condition, the ultimate stress should be divided by a 'factor of safety'.

Lateral Strain

If a cylindrical rod is subjected to an axial tensile load, the length (l) of the rod will increase (dl) and the diameter (ϕ) of the rod will decrease ($d\phi$). In short, the longitudinal stress will not only produce a strain in its own direction, but will also produce a lateral strain. The ratio dl/l is called the longitudinal strain or the linear strain, and the ratio $d\phi/\phi$ is called the lateral strain.

Poisson's Ratio

The ratio of the lateral strain to the longitudinal strain is constant within the elastic limit. This ratio is called the Poisson's ratio and is denoted by $1/m$. For most of the metals, the value of 'm' lies between 3 and 4.

$$\text{Poisson's ratio} = \frac{\text{Lateral Strain}}{\text{Longitudinal Strain}} = \frac{1}{m}$$

Bulk Modulus

If a body is subjected to equal stresses along the three mutually perpendicular directions, the ratio of the direct stresses to the corresponding volumetric strain is found to be constant for a given material, when the deformation is within a certain limit. This ratio is called the bulk Modulus and is denoted by K .

Stress Concentration

The value of stress changes abruptly in the regions where the cross-section or profile of a structural member changes abruptly. The phenomenon of this abrupt change in stress is known as stress concentration and the region of the structural member affected by stress concentration is known as the region of stress concentration. The region of stress concentration needs to be meshed densely to get accurate results.

Bending

When a force is applied perpendicular to the longitudinal axis of a body, the body starts deforming. This phenomenon is known as bending. In case of

bending, strains vary linearly from the centerline of a beam to the circumference. In case of pure bending, the value of strain is zero at the center line.

Bending Stress

When a non-axial force is applied on a structural member, some compressive and tensile stresses are developed in the member. These stresses are known as bending stresses.

Creep

At elevated temperature and constant load, many materials continue to deform, but at a slow rate. This behavior of materials is called creep. At a constant stress and temperature, the rate of creep is approximately constant for a long period of time. After a certain amount of deformation, the rate of creep increases, thereby causing fracture in the material. The rate of creep is highly dependent on both the stress and the temperature.

Degrees of Freedom (DOF)

The Degrees of freedom is defined as the freedom allowed to a given object to move and rotate in any direction in space.

There are six DOFs for any object in 3-dimensional (3D) space: 3 translational DOFs (one each in the X,Y and Z directions) and 3 rotational DOFs (one rotation about each of the X,Y, and Z axes).

STRESS ANALYSIS IN Autodesk Inventor 2016

To carry out Stress Analysis in Autodesk Inventor, you need to define the geometry on which you want to carry out the analysis. The Stress Analysis can be started by using the **Stress Analysis** tool available in the **Environments** tab in the **Ribbon**.

A geometry or a model can be included in the analysis in two ways: by creating a new geometry or by opening an already created model in Inventor Professional. To create a new model, choose the **New** button from the **Launch** panel of the **Get Started** tab; the **New File** dialog box will be displayed. Select the desired template and create the model.

To open an existing part file, choose the **Open** button from the **Launch** panel of the **Get Started** tab; the **Open** dialog box will be displayed. Browse to the desired folder to open the file.

Now, as the geometry for the analysis is ready, you can invoke the Stress Analysis environment. To do so, choose the **Stress Analysis** tool from the **Begin** panel in the **Environments** tab of the **Ribbon**; the **Stress Analysis** contextual tab will be displayed. By default, the **Create Simulation**, **Guide**, **Stress Analysis Settings**, and **Finish Stress Analysis** tools are highlighted in this tab, as shown in Figure 18-4. These tools are discussed next.



Figure 18-4 The Stress Analysis contextual tab

Creating Simulation

Ribbon: Stress Analysis > Manage > Create Simulation

To perform stress analysis, you need to create simulation first. To create simulation, choose the **Create Simulation** tool from the **Manage** panel of the **Stress Analysis** contextual tab; the **Create New Simulation** dialog box will be displayed, as shown in Figure 18-5. In this dialog box, you can specify a name for the simulation, the type of simulation to be carried out, design objectives, type of contacts to be used among components, and so on. The options in this dialog box are discussed next.

Name

The **Name** edit box is used to specify the name for the analysis to be carried out. The default value in this field is **Simulation:1**. To change the name of the simulation, click on the edit box and enter the desired name.

Design Objective

The **Design Objective** drop down list is available below the **Name** edit box. There are two options available in this drop-down list: **Single Point** and **Parametric Dimension**. The **Single Point** option is selected by default. As a result, only one set of geometry data is simulated. If **Parametric Dimension** is selected from the drop-down list, you can optimize the geometry by changing

the design parameters. The results, thus achieved, are based on various parameters used for analysis.




Figure 18-5 The Create New Simulation dialog box

Simulation Type Tab

This tab is used to specify the analysis type and contact type to be used among components.

The options in this tab are discussed next.

Static Analysis

This radio button is selected by default. As a result, the analysis evaluates the model in static condition or in no movement state. The check boxes in this area are activated on selecting the **Static Analysis** radio button and are discussed next.

Detect and Eliminate Rigid Body Modes: Select this check box if you want to detect and remove the solid body on which enough constraints are not defined. However, in this case, the load after the removal of solid body must remain balanced.

Separate Stresses Across Contact Surfaces: This check box is selected when different stresses are required across contact surfaces. This is mainly because of different materials selected for different components.

Motion Load Analysis: This check box is selected to export motion loads of parts.

Part: This drop-down list includes all the parts whose motion loads are exported.

Time Step: This drop-down list includes time steps available for all the parts selected to export motion loads.

Modal Analysis

This radio button is used to determine the natural frequencies of vibrations for the model under consideration. The check boxes activated on selecting this radio button are discussed next.

Number of Modes: On selecting this check box, the edit box next to it is activated where you can specify the number of resonant frequencies to be found in analysis.

Frequency Range: On selecting this check box, the edit boxes next to it are activated in which you can specify the range of frequency for the desired model analysis.

Compute Preloaded Modes: This check box is selected to compute preloaded stress on the model and then compute the resonant frequencies under pre-stressed conditions.

Enhance Accuracy: If selected, this check box helps in improving the accuracy of the calculated frequencies by a magnitude of 10.

Contacts Area

The edit boxes in this area are used to specify values for tolerances among contacts and specify stiffness for spring contacts. These edit boxes are discussed next.

Tolerance: This edit box is used to specify values for tolerance between contact surfaces or edges.

Type: The options in the **Type** drop-down list are used to specify the type of contacts to be applied on the part. Various contacts available in this drop-down list are: **Bonded, Separation, Sliding/No Separation, Separation/No Sliding, Shrink Fit/ Sliding, Shrink Fit/No Sliding, Spring.**

Normal Stiffness: This edit box is used to specify equivalent normal stiffness for the spring contacts.

Tangential Stiffness: This edit box is used to specify equivalent tangential stiffness for the spring contacts.

Reset

This button is used to reset all the parameters to their default value.

OK

This button is used to apply all the changes and close the dialog box.

Cancel

This button is used to cancel all the changes made and close the dialog box.

Model State Tab

This tab is used to specify the assembly representation for simulation. You can specify the design view representation and positional representation of assembly design using the options in this tab. You can also specify the level of details for reducing the simulation time and meshing time.




Figure 18-6 The Simulation Guide window

iPart

This option is used to associate the i assembly and ipart with the simulation.

After you specify the required parameters, most of the options in the **Stress Analysis** contextual tab will be activated. Also, various nodes will be attached to the **Browser Bar**. You will learn more about **Browse bar** latter in this chapter.

Using the Guide Tool

Ribbon: Stress Analysis > Guide > Guide

The **Guide** tool is available in the **Guide** panel of the **Stress Analysis** contextual tab. This tool is useful if you are a beginner to stress analysis in Autodesk Inventor or you have the basic knowledge about carrying out stress analysis and you want to learn more. On choosing this tool, the **Simulation Guide** window will be displayed on the right side of the graphics screen, as shown in Figure 18-6. In this window, you can select options based on your expertise on the subject

matter and perform steps as suggested.

Applying Stress Analysis Settings

Ribbon: Stress Analysis > Settings > Stress Analysis Settings

The **Stress Analysis Settings** tool is used for viewing and modifying the parameters of stress analysis. On choosing this button, the **Stress Analysis Settings** dialog box will be displayed as shown in Figure 18-7. This dialog box consists of three tabs: **General**, **Solver**, and **Meshing**. In this dialog box, you can set the default analysis type, objective of the analysis, contact details, and so on.





Figure 18-7 The Stress Analysis Settings dialog box

STRESS ANALYSIS BROWSER BAR

The **Stress Analysis Browser Bar** is the most important component of the Autodesk Inventor Stress analysis environment and is available below the **Ribbon** on the left of the drawing window. It displays all the operations performed during the analysis process in a sequence. All these operations are displayed in the form of a tree view. Figure 18-8 shows the partial view of the

default **Browser Bar**.



*Figure 18-8 Partial view of the default **Browser Bar***

ASSIGNING MATERIAL

In the analysis process, you need to assign material properties to the geometry created or imported. These properties are based on the analysis type and variation in material properties in 3D space. The material properties can be linear or nonlinear.

Assign Material

Ribbon: Stress Analysis > Material > Assign

To assign materials to a model, choose the **Assign** tool available in the **Material** panel of the **Stress Analysis** contextual tab; the **Assign Materials** dialog box will be displayed, as shown in Figure 18-9. Alternatively, right-click on the **Material** node in the **Stress Analysis Browser Bar**; a shortcut menu will be displayed, refer to Figure 18-10. Choose the **Assign Materials** option from the shortcut menu to invoke the **Assign Materials** dialog box.




Figure 18-9 The Assign Materials dialog box




Figure 18-10 The shortcut menu displayed on right-clicking on the Material node

The various options in the **Assign Materials** dialog box are discussed next.

Component Column

The **Component** column lists all the components to which a material is to be assigned for analysis.

Original Material Column

This column displays the original or the default material type that is already applied to the corresponding component in the **Component** column.

Override Material Column

When you click on the first row of the **Override Material Column**, a drop-

down list is displayed which contains the materials that can be overridden on the existing materials. To override a material, select the material from the **Override Material** drop-down list and choose the **OK** button. Figure 18-11 shows the **Override Material** drop-down list.




Figure 18-11 The Override Material drop-down list

Safety Factor Column

After selecting the required option from the **Override Material** drop-down list, you can specify whether to use yield strength or ultimate tensile strength to determine safety factor for the model. To do so, select the required option from the **Safety Factor** drop-down list, refer to Figure 18-12.




Figure 18-12 The Safety Factor drop-down list

Materials

This button is used to browse and assign materials to the parts. When this button

is chosen from the **Assign Materials** dialog box, the **Material Browser** dialog box is displayed. The default materials present in the Inventor material library are displayed in this dialog box. Browse to the desired material type and assign it to the parts. In this dialog box, you can modify existing materials, add new materials, assign colors to materials, and so on. After assigning the material type to the parts, close the dialog box; the **Assign Materials** dialog box will be displayed again. The changes that are made to the model are displayed under the material node of the **Stress Analysis Browser Bar**.

OK

After all the parameters are set in the **Assign Materials** dialog box, choose this button to apply changes and exit the dialog box.

Cancel

Choose this button to exit the **Assign Materials** dialog box without accepting any changes. After the material is applied to a component, a plus (+) sign is attached to the **Material** node in the **Stress Analysis Browser Bar** indicating that a material has been assigned to the model.

APPLYING CONSTRAINTS

The constraints are applied to restrict the degrees of freedom of a component or group of components. Autodesk Inventor assumes the model under analysis to be fully constrained. This means there should not be any rigid body movements or free fall. The **Constraints** node in the **Stress Analysis Browser Bar** shows the constraints applied to the system. In Autodesk Inventor Stress Analysis, you can apply three types of constraints: **Fixed**, **Pin**, and **Frictionless**. These constraints are discussed next.

Fixed

Ribbon: Stress Analysis > Constraints > Fixed

A fixed constraint restricts the movement of a part, which is fixed with a structure. To apply a fixed constraint, choose the **Fixed** tool from the **Constraints** panel in the **Stress Analysis** contextual tab. Alternatively, choose this tool from the Marking menu. To do so, select the **Constraints** node from the **Stress Analysis Browser Bar** and then right-click in the **Graphics** screen; the Marking menu will be displayed, as shown in Figure 18-13. You can also choose

this tool from the shortcut menu which is displayed when you right-click on the **Constraints** node in the **Stress Analysis Browser Bar**, as shown in Figure 18-14.





Figure 18-13 Marking menu displayed for constraints



*Figure 18-14 Choosing the **Fixed Constraint** tool from the shortcut menu*

On choosing this tool, the **Fixed Constraint** dialog box will be displayed, as shown in Figure 18-15. By default, only the **Location** and **Cancel** buttons are active in this dialog box. Select the faces, points, or edges to specify the location of the fixed constraint; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the constraint and exit the dialog box. Alternatively, you can choose the **Apply** button and continue applying more fixed constraints.




Figure 18-15 The Fixed Constraint dialog box

Pin

Ribbon: Stress Analysis > Constraints > Pin

A pin constraint is applied when two cylindrical surfaces are connected to an external support. To apply a pin constraint, choose the **Pin** tool from the **Constraints** panel of the **Stress Analysis** contextual tab. Alternatively, choose this tool from the Marking menu. You can also choose this tool from the shortcut menu which is displayed when you right-click on the **Constraints** node in the **Stress Analysis Browser Bar**, refer to Figure 18-14.

On choosing this tool, the **Pin Constraint** dialog box will be displayed, as shown in Figure 18-16. By default, only the **Location** and **Cancel** buttons are active in this dialog box. Select the faces, points, or edges to specify the location of the pin constraint; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the constraint and exit the dialog box. Alternatively, you can choose the **Apply** button and continue to apply more pin constraints.




Figure 18-16 The Pin Constraint dialog box

Frictionless

Ribbon: Stress Analysis > Constraints > Frictionless

A frictionless constraint is applied where models can freely slide over each other but cannot be separated at any point of time. To apply a frictionless constraint,

choose the **Frictionless** tool from the **Constraints** panel. Alternatively, right-click in the **Graphics** screen. Next, choose this tool from the Marking menu displayed, refer to Figure 18-14. You can also choose this tool from the shortcut menu displayed when you right-click on the **Constraints** node in the **Stress Analysis Browser Bar**, refer to Figure 18-14.




Figure 18-17 The Frictionless Constraint dialog box

On choosing this tool, the **Frictionless Constraint** dialog box will be displayed, as shown in Figure 18-17. By default, only the **Location** and **Cancel** buttons are active in this dialog box. Select the faces to specify the location of the frictionless constraint; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the constraint and exit the dialog box. Alternatively, you can choose the **Apply** button and continue to apply more frictionless constraints.

APPLYING LOADS

The **Loads** node in the **Stress Analysis Browser Bar** displays all the loads that are applied to the model considered for stress analysis. After the constraints are defined, it is very important that you apply the load for which you want to analyze the model. In Autodesk Inventor, only structural analysis is done and therefore only structural loads are available. The various structural loads that can be applied on the model are: Force, Pressure, Bearing load, Moment, Gravity, Remote Force, and Body load. These loads are discussed next.

Force

Ribbon: Stress Analysis > Loads > Force

To apply force load, you need to specify a point, an edge, or a face on which force needs to be applied. When applied on a point, the force load becomes point load, whereas when applied on an edge or a face, it becomes a uniformly distributed load. By applying this type of load, you can simulate the behavior of the model under that particular load. To do so, choose the **Force** tool from the **Loads** panel of the **Stress Analysis** contextual tab. Alternatively, you can

choose this tool from the Marking menu, refer to Figure 18-18. You can also choose this tool from the shortcut menu that is displayed when you right-click on the **Loads** node in the **Stress Analysis Browser Bar**, as shown in Figure 18-19.





Figure 18-18 Marking menu displayed for loads



*Figure 18-19 Choosing the **Force Load** tool from the shortcut menu*

On choosing this tool, the **Force** dialog box will be displayed, as shown in Figure 18-20. By default, the dialog box is in collapsed form. You can expand the dialog box to see more options in it. To do so, click on the **More (>>)** button available at the bottom right corner of the dialog box. Figure 18-21 shows the expanded **Force** dialog box. Select any vertex, edge, or face to specify the location where force load needs to be applied; the selected component turns blue in color indicating that it has been selected for applying the force load. Also, an

arrow is displayed indicating the direction of the load. Next, specify the magnitude of the load in the **Magnitude** edit box of the **Force** dialog box; the **OK** and **Apply** buttons become active. Choose the **OK** button to specify the load and exit the dialog box.




Figure 18-20 The Force dialog box




Figure 18-21 The expanded Force dialog box

Figure 18-22 shows a model with the force load applied on it. The arrow displays the direction in which the load is applied.




Figure 18-22 Force load applied on a block

Pressure

Ribbon: Stress Analysis > Loads > Pressure

Pressure is a force applied per unit area in a direction perpendicular to the surface of the model. To apply pressure load on a surface, choose the **Pressure** tool from the **Loads** panel in the **Stress Analysis** contextual tab. Alternatively, you can choose this tool from the Marking menu, refer to Figure 18-18. You can also choose this tool from the shortcut menu which is displayed when you right-click on the **Loads** node in the **Stress Analysis Browser Bar**, refer to Figure 18-19.

On choosing this tool, the **Pressure** dialog box will be displayed, as shown in Figure 18-23. By default, only the **Faces** and **Cancel** buttons are activated. Select the faces on which you want to apply the pressure load and then specify the magnitude of the load in the **Magnitude** edit box; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the load and close the **Pressure** dialog box. Figure 18-24 shows the pressure load applied onto the face of a component.




Figure 18-23 The Pressure dialog box




Figure 18-24 The pressure load applied to a component

Bearing Load

Ribbon: Stress Analysis > Loads > Bearing Load

Bearing Load is compressive in nature. It varies over the size and direction of the force that it supports. To apply the bearing load, choose the **Bearing Load** tool from the **Loads** panel in the **Stress Analysis** contextual tab. Alternatively,

you can choose this tool from the Marking menu, refer to Figure 18-18. You can also choose this tool from the shortcut menu which is displayed when you right-click on the **Loads** node of the **Stress Analysis Browser Bar**, refer to Figure 18-19.

Note

You can apply bearing loads only on cylindrical surfaces.

On choosing this tool, the **Bearing Load** dialog box will be displayed, as shown in Figure 18-25. By default, in this dialog box, only the **Faces** and **Cancel** buttons are active. Select the cylindrical surface on which you want to apply the bearing load and specify a magnitude for the load in the **Magnitude** edit box; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the bearing load and close the dialog box. Figure 18-26 shows the bearing load applied on a cylindrical surface.




Figure 18-25 The **Bearing Load** dialog box




Figure 18-26 Bearing load applied on the cylindrical surface of model

Moment

Ribbon: Stress Analysis > Loads > Moment

The moment load tends to overturn or bend the axis of rotation of a model in an angular direction. To apply moment load, you can choose the **Moment** tool from the **Loads** panel of the **Stress Analysis** contextual tab. Alternatively, choose this tool from the Marking menu, refer to Figure 18-18. You can also choose this tool from the shortcut menu which is displayed when you right-click on the **Loads** node in the **Stress Analysis Browser Bar**, refer to Figure 18-19.

On choosing this tool, the **Moment** dialog box will be displayed, as shown in Figure 18-27. By default, in this dialog box only the **Location** and **Cancel** buttons are activated. Select the face on which you want to apply the moment load and then specify the magnitude of the load in the **Magnitude** edit box; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the load and close the **Moment** dialog box. Figure 18-28 shows the momentum load applied on the face of a rectangular block.




Figure 18-27 The Moment dialog box




Figure 18-28 Momentum load applied on the block

Gravity

Ribbon: Stress Analysis > Loads > Gravity

The Gravity tool is used to apply gravity force to a component. To apply this load, choose the **Gravity** tool from the **Loads** panel of the **Stress Analysis** contextual tab. Alternatively, you can choose this tool from the Marking menu. You can also choose this tool from the shortcut menu which is displayed when you right-click on the **Loads** node in the **Stress Analysis Browser Bar**.

On choosing this tool, the **Gravity** dialog box will be displayed, as shown in Figure 18-29. By default, in this dialog box, only the **Faces** and **Cancel** buttons are active. Select any face of the component and specify the gravity value in the

Magnitude edit box; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the load and close the **Gravity** dialog box.




Figure 18-29 The Gravity dialog box

Remote Force

Ribbon: Stress Analysis > Loads > Remote Force

The **Remote Force** tool is used to apply the forces to the component at any location. It gives the flexibility to apply forces at any point by specifying the geometric coordinates of the point. To apply the remote forces, choose the **Remote Forces** tool from the drop-down in the **Loads** panel in the **Stress Analysis** contextual tab. Alternatively, choose this tool from the Marking menu. You can also choose this tool from the shortcut menu which is displayed when you right-click on the **Loads** node in the **Stress Analysis Browser Bar**.

On choosing this tool, the **Remote Force** dialog box will be displayed, as shown in Figure 18-30. Select the location on which you want to apply the force and then enter the geometric coordinates of the point to apply the load. If necessary, choose the **Direction** button from the dialog box to flip the direction of the force. Next, specify the magnitude value of the force in the **Magnitude** edit box; the **OK** and **Apply** buttons become active. Choose the **OK** button to apply the load and close the **Remote Force** dialog box. Figure 18-31 shows the load applied on the face of a component at a specified location.




Figure 18-30 The Remote Force dialog box




Figure 18-31 Force applied at a specified location


Body

Ribbon: Stress Analysis > Loads > Body

The **Body** tool is used to apply the velocity and acceleration in the linear and angular direction to the component. To apply the body load, choose the **Body** tool from the drop-down in the **Loads** panel of the **Stress Analysis** contextual tab. Alternatively, choose this tool from the Marking menu. You can also choose this button from the shortcut menu, which is displayed when you right-click on the loads node in the Stress Analysis browser bar.

On choosing this tool, the **Body Loads** dialog box will be displayed, as shown in Figure 18-32. In this dialog box, there are two tabs: Linear and Angular. The **Linear** tab is used to apply acceleration in the linear direction and the **Angular** tab is used to apply both acceleration and velocity in the angular direction. Select the required tab from the dialog box and choose the corresponding check box to enable the options to apply the loads. Figure 18-33 shows the angular

acceleration applied to a component.



*Figure 18-32 The **Body Loads** dialog box*




Figure 18-33 Angular acceleration applied at the specified location

MESHING THE COMPONENT

A mesh is the discretization of a component into a number of small elements of defined size. Finite Element Analysis divides the geometry into various small number of elements. As a result, a number of nodes are created which are used to connect the elements. A collection of these elements is called as mesh. The tools used for creating the mesh are discussed next.

Mesh View

Ribbon: Stress Analysis > Mesh > Mesh View

The **Mesh View** tool is used to create the default mesh in the component by using the default settings. These default settings are provided by the system based on the geometry to be meshed. To generate the default mesh, choose the **Mesh View** tool from the **Mesh** panel in the **Stress Analysis** contextual tab. Alternatively, you can choose this tool from the Marking menu, as shown in Figure 18-34. You can also choose this tool from the shortcut menu, which is displayed when you right-click on the **Mesh** node in the **Stress Analysis**

Browser Bar, as shown in Figure 18-35.

On choosing this tool, the **Mesh** progress box will be displayed, as shown in Figure 18-36 and mesh is generated on the component with default settings, refer to Figure 18-37.

Mesh Settings

Ribbon: Stress Analysis > Mesh > Mesh Settings

The **Mesh Setting** tool is used to set or edit the element length of the mesh. To do so, choose the **Mesh Settings** tool from the **Mesh** panel of the **Stress Analysis** contextual tab. Alternatively, choose this tool from the Marking menu, refer to Figure 18-34. You can also choose this tool from the shortcut menu which is displayed when you right-click on the **Mesh** node in the **Stress Analysis Browser Bar**, refer to Figure 18-35.



Figure 18-34 Marking menu displayed for mesh




Figure 18-35 Choosing the **Mesh View** tool from the shortcut menu




Figure 18-36 The **Mesh** progress box




Figure 18-37 Mesh generated with default settings

On choosing this tool, the **Mesh Settings** dialog box will be displayed, as shown in the Figure 18-38. In this dialog box, you can set the average element size and minimum element size using the corresponding edit boxes.




Figure 18-38 The Mesh Settings dialog box

Local Mesh Control

Ribbon: Stress Analysis > Mesh > Local Mesh Control

The **Local Mesh Control** tool is used to refine mesh of the specified element size to the faces or edges of the component. To create the local refined mesh for any part, choose the **Local Mesh Control** tool from the **Mesh** panel of the **Stress Analysis** contextual tab. Alternatively, you can choose this tool from the Marking menu, refer to Figure 18-34. You can also choose this button from the shortcut menu which is displayed when you right-click on the **Mesh** node in the **Stress Analysis Browser Bar**, refer to Figure 18-35.

On choosing this tool, the **Local Mesh Control** dialog box will be displayed, as shown in Figure 18-39. Select the faces or edges of the model that are to be meshed. Next, enter the element size value in the **Element Size** edit box and then choose the **OK** button. A new Local Mesh controls sub node will be added under the **Mesh** node in the Simulation tree. Figure 18-40 shows the mesh created for the component by applying the local mesh to the hole edges with different element sizes.




Figure 18-39 The Local Mesh Control dialog box




Figure 18-40 Mesh generated after applying the local mesh control for holes

Note

Once the mesh setting are edited and the local mesh controls are applied to the component, the mesh cannot be updated automatically. In such case a thunder symbol will be displayed beside the **Mesh** node in the Simulation tree indicating that the mesh has to be updated. To update the mesh, select the **Mesh** node and right-click to invoke a shortcut menu. Next, choose the **Update Mesh** option from the shortcut menu, refer to Figure 18-41.




Figure 18-41 The **Mesh Settings** dialog box

Convergence Settings

Ribbon: Stress Analysis > Mesh > Convergence Settings

As discussed earlier, the FEA simulation is done by generating and solving the differential equations of the component. To obtain the best results, these equations are to be converged. This is done by setting the iterative equations for FEA results and refining the mesh. The **Convergence Settings** tool is used to set the meshing refinements, iterative criteria, and converging results. To do so, choose the **Convergence Settings** tool from the **Mesh** panel of the **Stress**

Analysis contextual tab; the **Convergence Settings** dialog box will be displayed, as shown in Figure 18-42. Enter the refinement value in the **Maximum Number of h Refinements** edit box to refine the mesh. The **Stop Criteria (%)** edit box is used to specify the percentage of convergence between the default mesh and the refined mesh. The **h Refinement Threshold (0 to 1)** edit box is used to control the meshing refinement. If the value entered in the edit box is **0** then all the elements in the mesh will be included for refinement and if the value entered is **1** then all the elements in the mesh will be excluded from refinement. In the **Results to Converge** area select the type of result case to converge the simulation. Select the type of geometric selection in the **Geometry Selections** area to set the convergence criteria for simulation.




Figure 18-42 The Convergence Settings dialog box

SOLUTION PHASE OF ANALYSIS

Ribbon: Stress Analysis > Solve > Simulate

After meshing the model and applying boundary conditions to it, you need to solve the analysis problem for the applied boundary condition. In the solution phase, the time taken by the computer to perform calculations and solve the problem mainly depend upon the modal size and type of solution. To do so, choose the **Simulate** tool from the **Solve** panel of the **Stress Analysis** contextual tab; the **Simulate** dialog box will be displayed, as shown in Figure 18-43. Choose the **Run** button from this dialog box; the solver will run the solution process. After completing the process, the Von-Mises stress result based on the specified settings will be displayed, as shown in Figure 18-44.




Figure 18-43 The Simulate dialog box




Figure 18-44 The Von Mises stress result of the component

POSTPROCESSING THE SOLUTIONS

After completing the solution process, the results generated for the model will be based on the geometric conditions and the preprocessor settings. In the postprocessing step, you will view the results data and then display them in a graphical form for analyzing. In Autodesk Inventor, there are a number of tools used for viewing results in the **Result**, **Display**, and **Report** panels of the **Stress Analysis** contextual tab. The methods of generating report and animating the results are discussed next.

Generating Report

Ribbon: Stress Analysis > Report > Report

The **Report** tool is used to generate the complete report of the preprocessor, solver, and postprocessor data of the problem after completing the solution. To generate the complete report, choose the **Report** tool from the **Report** panel of the **Stress analysis** contextual tab; the **Report** dialog box will be displayed, as shown in Figure 18-45.

By default, the **Complete** radio button is selected in this dialog box. Therefore, the complete report for the default settings will be generated. You can also

customize the settings to generate customized report by selecting the **Custom** radio button.

This dialog box has four tabs: **General**, **Properties**, **Simulations**, and **Format**. By default, the **General** tab is chosen. The options in this tab are used to specify the title, author name, logo for analysis, summary of the analysis, and the location to save the report. The options in the **Properties** tab and the **Simulation** tab are used to specify the settings for the content that is to be included while generating the results report. The options in the **Format** tab are used to specify the type of format in which the report has to be generated.

After specifying the required options in the **Report** dialog box, choose the **OK** button; the **Stress Analysis Report** status window will be displayed, as shown in Figure 18-46 and the reporting process is started. After completing the process, stress analysis report will be displayed on the internet browser.




Figure 18-45 The Report dialog box




Figure 18-46 The Stress Analysis Report status window

Animating the Results

Ribbon: Stress Analysis > Result > Animate



The **Animate** tool is used to generate and save the animation view of the results generated in the postprocessing phase. On choosing the **Animate** tool from the **Result** panel of the **Stress Analysis** contextual tab, the **Animate Results** dialog box will be displayed, as shown in Figure 18-47. The options in this dialog box are used to play, stop, save, and set the speed of animation.




Figure 18-47 The Animate Results dialog box

TUTORIALS
TUTORIAL 1

In this tutorial, you will analyze the effect of loads on an I-section beam of steel material, as shown in Figure 18-48. The dimensions and the boundary conditions of the I-Section are shown in Figure 18-49. It is fixed at one end and loaded on the other. Under the given load and constraints, generate the analysis report for stresses, strains, and deflections. **(Expected time: 45 min)**




Figure 18-48 The I-Section beam




Figure 18-49 The dimensions and boundary conditions of the model

The following steps are required to complete the tutorial:

- Start a new **Standard (mm).ipt** template and then create an I-section beam.
- Start the Stress Analysis simulation.
- Apply the Material.
- Apply the constraints and loads.
- Create the mesh.

- f. Generate the analysis report.
- g. Save the simulation.

Starting a New Metric Part File and Creating an I-Section

1. Start Autodesk Inventor 2016 and invoke the **Create New File** dialog box.
2. Choose the **Metric** tab and then double-click on the **Standard(mm).ipt** option to start a new metric part file.
3. Create an I-Section beam on YZ sketching plane and extrude it to 300. For dimensioning, refer to Figure 18-49 .

Note

1. *Before selecting the sketching plane, you need to choose the **Home** button from the ViewCube in order to maintain the right orientation of the model.*
 2. *If the orientation of the **ViewCube** is not the same as the orientation of the selected plane (Top/Front) then click on the down arrow available next to the **ViewCube**; a flyout is displayed. Next, choose **Set Current View as > Top/Front** from the flyout.*

4. Save the model.

Starting a New Simulation

After creating the model, the next step is to start the simulation procedure.

1. Choose the **Stress Analysis** tool from the **Begin** panel of the **Environment** tab; a new environment with the **Stress Analysis** contextual tab is invoked.
2. Choose the **Create Simulation** tool from the **Manage** panel of the **Stress Analysis** contextual tab; the **Create New Simulation** dialog box is displayed.
3. Enter **Static Analysis** in the **Name** edit box and choose the **OK** button from the **Create New Simulation** dialog box; the **Static Analysis** Simulation tree is displayed and the tools and options in the **Stress Analysis** contextual tab are activated.

Applying the Material

Now, you need to apply the Alloy steel material to the beam.

1. Choose the **Assign** tool from the **Material** panel of the **Stress Analysis** contextual tab; the **Assign Material** dialog box is displayed.
2. Choose the **Material** button from the **Assign Material** dialog box; the **Material Browser** dialog box is displayed.
3. Browse to the **Steel, Alloy** material in the **Inventor Material Library** of the **Material Browser** dialog box and select it. Next, right-click on it; a shortcut menu is displayed.
4. Choose the **Assign to Selection** option from the shortcut menu; the material is applied to the beam.
5. Next, close the **Material Browser** dialog box and then choose the **OK** button from the **Assign Material** dialog box to close it.

Applying Constraints

After applying material to the model, you need to apply constraint to one end of the model.

1. Choose the **Fixed** tool from the **Constraints** panel of the **Stress Analysis** tab; the **Fixed Constraint** dialog box is displayed.
2. Rotate the model such that you can see the left face of the beam. Next, select the left face of the model and choose the **OK** button from the **Fixed Constraint** dialog box; the fixed constraint is applied.

Applying the Load

After applying the material and constraints to the model, you need to apply load at the top right edge of the model.

1. Choose the **Force** tool from the **Loads** panel of the **Stress Analysis** contextual tab; the **Force** dialog box is displayed.

2. Expand the dialog box by clicking on the **More >>** button; the dialog box is expanded.
3. Next, choose the top right edge of the model; the force arrow is displayed.
4. Select the **Use Vector Components** check box from the dialog box; the geometric vector edit boxes are activated.
5. Enter **-1000** in the **Fz** edit box; the force arrow is modified according to the specified direction.
6. Choose the **OK** button from the **Force** dialog box to apply the load and to close it. Figure 18-50 shows the model after applying the load.




Figure 18-50 Model after applying the load

Creating and Refining the Mesh

After applying the constraints and loads to the model, you need to generate mesh for the model.

1. Choose the **Mesh View** tool from the **Mesh** panel of the **Stress Analysis** tab; the **Meshing** progress box is displayed. Once the meshing process is done, the meshed model is displayed in the drawing area, as shown in Figure 18-51.

Notice that after generating the default mesh of the model, the quality of the mesh is not fine. To obtain more accurate results in the static analysis of the model, you need to generate a good quality mesh. The next step is to discretize the model in such a manner that a smooth and good quality mesh is obtained.

2. Next, choose the **Mesh Settings** tool from the **Mesh** panel of the **Stress Analysis** tab; the **Mesh Settings** dialog box is displayed.
3. Enter **0.02** in the **Average Element Size** edit box and **0.1** in the **Minimum Element Size** edit box. Next, choose the **OK** button from the **Mesh Settings** dialog box.
4. By default, the mesh settings will not be applied on the model. To apply the settings, select the **Mesh** node in the Design tree and right-click; a shortcut menu is displayed. Choose the **Update Mesh** option from the shortcut menu; the **Mesh** progress box is displayed. Once the meshing process is done, the new meshed model is displayed in the drawing area, as shown in Figure 18-52.




Figure 18-51 The meshed model with default mesh settings




Figure 18-52 The meshed model with refined mesh settings

Solving the Static Analysis

After applying all the required settings like constraints, loads, and mesh, you

need to solve the analysis for the model.

1. Choose the **Simulate** tool from the **Solve** panel of the **Stress Analysis** contextual tab; the **Simulate** dialog box is displayed.
2. Choose the **Run** button from the **Simulate** dialog box; the solving procedure starts and the Von Mises stress contour is displayed in the drawing area, as shown in Figure 18-53.




Figure 18-53 The resultant model with von Mises contour

Calculating the Maximum and Minimum Stress Values

After solving the analysis, the next step is to find the maximum and minimum stress values for the simulated model.

1. Choose the **Maximum Value** tool from the **Display** panel of the **Stress Analysis** contextual tab; a probe point with maximum value of the von Mises stress callout is displayed in the drawing area, refer to Figure 18-54.
2. Similarly, choose the **Minimum Value** tool from the **Display** panel of the **Stress Analysis** tab; a probe point with the minimum value of the von Mises stress callout is displayed in the drawing area, refer to Figure 18-55.




Figure 18-54 The von Mises contour with the maximum stress value callout




Figure 18-55 The von Mises contour with the maximum and minimum stress value callouts

Generating the Analysis Report

Now, you need to generate the complete report of the simulation for the model.

1. Choose the **Report** tool from the **Report** panel of the **Stress Analysis** contextual tab; the **Report** dialog box is displayed.
2. By default, the **General** tab is chosen in this dialog box. Enter **Stress analysis for I-Section beam** in the **Report Title** and **File Name** edit boxes and accept the remaining settings.
3. Choose the **OK** button from the **Report** dialog box; the **Stress Analysis Report** status window is displayed. After the reporting process is done, the report is generated in *.html* format and is displayed in your default internet browser.

After completing the simulation procedure and generating the analysis report, now you need to save the model.

4. Choose the **Save** button from the **Quick Access** toolbar; the **Save As** dialog box is displayed.
 5. Specify the name of the file as **Tutorial1.ipt** and browse to the location **C:\Inventor_2016\c18**. Next, choose the **Save** button to save this model.
-

TUTORIAL 2

In this tutorial, you will carry out the model analysis of the leaf spring. The geometric constraints applied to the leaf spring are shown in Figure 18-56. The dimensions of the leaf spring are shown in Figure 18-57. The leaf spring is fixed at its both ends and loaded at its center. Under these conditions, you will determine the first 6 natural frequencies and their mode shape. (**Expected time 45 min**)




Figure 18-56 The constraints applied to the Leaf Spring




Figure 18-57 The dimensions and boundary conditions of Model

The following steps are required to complete the tutorial.

- a. Start a new Standard **(mm).ipt** template and then create the leaf spring.
- b. Start a new Stress Analysis simulation.
- c. Apply material to the leaf spring
- d. Apply the constraints and loads.
- e. Create the mesh.
- f. Generate the analysis report.
- g. Save the simulation file.

Starting a New Metric Part File and Creating an I-Section

1. Start Autodesk Inventor 2016 and invoke the **Create New File** dialog box.
2. Next, choose the **Metric** tab and double-click on the **Standard(mm).ipt** option to start a new metric part file environment.
3. Create the leaf spring, as shown in Figure 18-58, and save the model.




Figure 18-58 The preview of the leaf spring

Starting a New Simulation

After creating the model, the next step is to start the simulation procedure.

1. Choose the **Stress Analysis** tool from the **Begin** panel of the **Environment** contextual tab; a new environment with the **Stress Analysis** contextual tab is invoked.
2. Choose the **Create Simulation** tool from the **Manage** panel of the **Stress Analysis** contextual tab; the **Create New Simulation** dialog box is displayed.

3. In the **Simulation Type** tab of the **Create New Simulation** dialog box, select the **Modal Analysis** radio button; the options related to model analysis are activated.
4. Make sure that the **Number of Modes** check box is selected and enter **6** in the **Number of Modes** edit box.
5. Next, enter **Modal Analysis of the leaf spring** in the **Name** edit box and choose the **OK** button from the **Create New Simulation** dialog box; the **Static Analysis** design tree is displayed and the tools and options in the **Stress Analysis** contextual tab are activated.

Applying the Material

Now, you need to apply the steel mild material to the leaf spring.

1. Choose the **Assign** tool from the **Material** panel of the **Stress Analysis** contextual tab; the **Assign Materials** dialog box is displayed.
2. Choose the **Materials** button from the **Assign Materials** dialog box; the **Material Browser** dialog box is displayed.
3. Browse to the **Steel, Mild** material in the **Inventor Material Library** of the **Material Browser** dialog box and select it. Next, right-click on it; a shortcut menu is displayed.
4. Choose the **Assign to Selection** option from the shortcut menu; the material is applied to the leaf spring.
5. Next, close the **Material Browser** dialog box and then choose the **OK** button from the **Assign Materials** dialog box to close it.

Applying the Constraints

After applying the material to the model, you need to constraint both ends of the model.

1. Choose the **Fixed** tool from the **Constraints** panel of the **Stress Analysis** contextual tab; the **Fixed Constraint** dialog box is displayed.

2. Select the two inner surfaces of the eye of the leaf spring, as shown in Figure 18-59.




Figure 18-59 The faces selected for applying fixed constraint

3. Next, choose the **OK** button from the **Fixed Constraint** dialog box; the fixed constraint is applied on the selected faces.

Creating and Refining the Mesh

After applying geometric constraints to the model, now you need to generate the mesh for the model.

1. Choose the **Mesh View** tool from the **Mesh** panel of the **Stress Analysis** contextual tab; the **Mesh** progress box will be displayed. Once the meshing process is done, the meshed model is displayed in the drawing area, as shown in Figure 18-60.

To obtain more accurate results, the mesh has to be refined.

2. Next, choose the **Mesh Settings** tool from the **Mesh** panel of the **Stress Analysis** contextual tab; the **Mesh Settings** dialog box is displayed.
3. Enter **0.01** in the **Average Element Size** edit box and **0.01** in the **Minimum Element Size** edit box. Next, choose the **OK** button from the **Mesh Settings** dialog box.
4. To apply the settings, select the **Mesh** node in the Design tree and right-click; a shortcut menu is displayed. Choose the **Update Mesh** option from the

shortcut menu; the **Mesh** progress box is displayed. Once the meshing process is done, the new meshed model is displayed in the drawing area, as shown in Figure 18-61.




Figure 18-60 The meshed model with default mesh settings




Figure 18-61 The meshed model with refined mesh settings

Solving the Modal Analysis

After applying all the necessary settings like constraints and mesh, you need to solve the analysis for the model.

1. Choose the **Simulate** tool from the **Solve** panel of the **Stress Analysis** contextual tab; the **Simulate** dialog box is displayed.
2. Choose the **Run** button from the **Simulate** dialog box; the solving procedure starts and the mode shape of the first natural frequency contour is displayed in the drawing area, as shown in Figure 18-62.




Figure 18-62 The mode shape of the first natural frequency

Generating the Analysis Report

Now, you need to generate the complete report of the simulation for the model analysis.

1. Choose the **Report** tool from the **Report** panel of the **Stress Analysis** contextual tab; the **Report** dialog box is displayed.
2. By default, the **General** tab is chosen in this dialog box. Enter **Leaf Spring Model Analysis** in the **Report Title** and **File Name** edit boxes and accept the remaining settings.
3. Choose the **OK** button from the **Report** dialog box; the **Stress Analysis Report** status window is displayed. After the reporting process is completed, the report is generated in *.html* format and is displayed in your default internet browser.

After completing the simulation procedure and generating the analysis report, now you need to save the model.

4. Choose the **Save** button from the **Quick Access Toolbar**; the **Save As** dialog box is displayed.
 5. Specify the name of the file as **Tutorial2.ipt** and browse to the location *C:\Inventor_2016\c18*. Next, choose the **Save** button; the model is saved.
-

TUTORIAL 3

In this tutorial, you will carry out static and modal analysis of the Wheel Support assembly, as shown in Figure 18-63. The exploded view of the assembly is shown in Figure 18-64. The dimensions and boundary conditions of the assembly parts are shown in Figures 18-65 through 18-68.

In this tutorial, you will prepare all the parts in the part environment and assemble them in the assembly environment of Autodesk Inventor. Consider that Cast Iron is the material for all the parts. Next, you will perform static analysis and then modal analysis for the first 6 natural frequencies. The Base part of the assembly will be fixed in all directions, the wheel will be loaded with angular velocity of 25 deg/sec, and the gravitational force will be applied to the wheel in downward direction. **(Expected time: 45 min)**




Figure 18-63 The assembly model for Tutorial 3




Figure 18-64 The exploded view of the assembly




Figure 18-65 The dimensions for the Base




Figure 18-66 The dimensions for the Support




Figure 18-67 The dimensions for the Wheel part




Figure 18-68 The dimensions for the Shoulder screw

The following steps are required to complete the tutorial.

- Create all components of the assembly as separate part files and save them at the location `C:\Inventor_2016\c18\Tutorial3`.
- Start a new metric assembly file and place all the components and assemble them.
- Assign material to the components.
- Start a new Stress Analysis simulation.
- Apply constraints and loads.
- Create mesh.
- Generate the analysis report.
- Save the simulation.

Creating the Components

Before creating the assembly, you need to create its components as separate part files and then you need to save them at a common location for the ease of assembling.

1. Create all the components of the wheel support assembly as separate part files. Next, save the files with their respective names, refer to Figures 18-65 through 18-68. The files should be saved at location *C:\Inventor\c18\Tutorial3*.

Assembling the Components

Now, you will assemble all the components in the assembly environment by using the **Constraint** tool.

1. Start the new metric assemble file and choose the **Place** tool from the **Component** panel of the **Assemble** tab; the **Place Component** dialog box is displayed.
2. Browse to the *Tutorial3* folder and select the base component. Next, choose the **Open** button; the base component is attached to the cursor and moves along with it.
3. Click on the drawing area; the base component is placed in the assembly environment.
4. Again, choose the **Place** tool from the **Component** panel of the **Assemble** tab; the **Place Component** dialog box is displayed.
5. Browse to the *Tutorial3* folder and select the support component. Next, choose the **Open** button; the support component is attached to the cursor and moves along it.
6. Click in the drawing area; the support component is placed in the assembly environment.
7. Apply the constraint to the component by using the **Constraint** tool.
8. Similarly, assemble the remaining components and apply the necessary constraints.

Applying the Material to the Components

After assembling the components, you need to apply material to all the

components.

1. Select the base component from the **Browser bar**; the base component is highlighted in the drawing area. Next, choose the **Material** tool from the **Material and Appearance** panel of the **Tools** tab; the **Material Browser** dialog box is displayed.
2. Select the **Iron Cast** option from the **Inventor Material Library** tab and right-click on it; a shortcut menu is displayed.
3. Next, choose the **Assign to Selection** option from the shortcut menu; the selected material is applied on the base component and the appearance of the base component is changed to the selected material.
4. Similarly, apply the cast iron material to all the components in the assembly. After applying the materials to the components, close the **Material Browser** dialog box.

Starting Static Analysis

After assembling the components and applying material to the components, you need to start a new simulation.

1. Choose the **Stress Analysis** tool from the **Begin** panel of the **Environments** contextual tab; the **Stress Analysis** tab is activated.
2. Choose the **Create Simulation** tool from the **Manage** panel of the **Stress Analysis** contextual tab; the **Create New Simulation** dialog box is displayed.
3. Specify **Static analysis for assembly** in the **Name** edit box and accept the other default settings in the **Create New Simulation** dialog box.
4. Next, choose the **OK** button from the dialog box; the new analysis starts and the options in the **Stress Analysis** contextual tab are activated.

Applying the Constraints and Loads to the Assembly

After starting the new analysis system, you need to apply the boundary constraints and load to the assembly.

1. Choose the **Fixed** tool from the **Constraints** panel of the **Stress Analysis** tab; the **Fixed Constraint** dialog box is displayed.
2. Next, choose the top face of the base feature, as shown in Figure 18-69 and then, choose the **OK** button from the **Fixed Constraint** dialog box; the fixed constraint is applied and the dialog box is closed.

To apply the angular velocity of 25 deg/sec on the surface of the wheel, you need to make the wheel clearly visible in the drawing area.

3. Select the support2 component in the Browser bar and right-click on it; a shortcut menu is displayed.
4. Choose the **Visibility** option from the shortcut menu; the visibility of the selected component is turned off.
5. Next, choose the **Body** tool from the **Loads** panel of the **Stress Analysis** contextual tab; the **Body Loads** dialog box is displayed.
6. Choose the **Angular** tab in the **Body Loads** dialog box; the options used to apply the angular velocity and accelerations are displayed.
7. Select the **Enable Angular Velocity and Acceleration** check box; the options in the **Angular** tab of the **Body Loads** dialog box are activated.
8. Choose the **Select** button in the **Velocity** area of the **Body Loads** dialog box and choose the circular face of the wheel component, as shown in Figure 18-70.



Figure 18-69 Face selected for applying the fixed constraint.




Figure 18-70 Circular face selected for applying the angular velocity.

9. Enter **25** in the **Magnitude** edit box and then choose **OK** button; the angular velocity is applied on the body.

Applying the Gravitational Load to the Assembly

After applying the loads and constraints to the assembly, you need to apply the gravitational force to the assembly in the downward direction.

1. Choose the **Gravity** button from the **Loads** panel of the **Stress Analysis** contextual tab; the **Gravity** dialog box is activated.
2. Expand the dialog box and select the **Use Vector Component** check box; the **g[x]**, **g[y]**, and **g[z]** edit boxes are activated.
3. Enter **-9180** in the **g[z]** edit box and choose the **OK** button; the gravity is applied to the assembly.
4. Next, select the Support2 component from the Design tree and right-click; a

shortcut menu is displayed.

5. Choose the **Visibility** option from the shortcut menu; the support2 is displayed in the drawing area.

Setting Contact between Components

Now you need to set contacts between the components in the assembly.

1. Choose the **Automatic Contacts** button from the **Contacts** panel of the **Stress Analysis** tab; the **Detecting Automatic Contacts** dialog box is displayed and the process of detecting the contacts is started.

By default, the bonded contacts are generated among the components in the assembly. Some of these components have the sliding and rotating motion between the components. Therefore, you have to edit the contact type that are generated automatically.

2. Expand the **Bonded** sub-node under the **Contacts** node in the Design tree; the automatically generated contacts are displayed, as shown in Figure 18-71.
3. Select the **Bonded:3 (Support:1, Shoulder screw:1)** node and right-click; a shortcut menu is displayed.
4. Choose the **Edit Contact** option from the shortcut menu; the **Edit Automatic Contact** dialog box is displayed.
5. Select the **Sliding / No Separation** option from the **Contact Type** drop-down list and choose the **OK** button; the sliding / no separation contact type is applied to the selected contact.
6. Similarly, change the contact type of all the contacts generated by default, except the contacts related to the base component.




Figure 18-71 The **Bonded** node under the **Contacts** node

Figure 18-72 shows the modified Design tree (after changing the contact type to some of the contacts generated automatically).



Figure 18-72 The **Contacts** node displayed after editing the contact type

Creating and Refining the Mesh

After creating and editing the contacts between the components in the assembly, you need to create the mesh for the components in the assembly.

1. Choose the **Mesh View** tool from the **Mesh** panel in the **Stress Analysis** contextual tab; the **Mesh** dialog box is displayed and the meshing process of the components is started.

After the meshing process is done, the meshed components are displayed in the drawing area, as shown in Figure 18-73. To obtain more accurate results for the analysis, you need to refine the mesh by changing the mesh settings.




Figure 18-73 The meshed view of the components

2. Choose the **Mesh Settings** tool from the **Mesh** panel of the **Stress Analysis** contextual tab; the **Mesh Settings** dialog box is displayed.
3. Enter **0.05** in the **Average Element Size** edit box and **0.1** in the **Minimum Element Size** edit box. Next, choose the **OK** button from the **Mesh Settings** dialog box.
4. To apply the mesh modifications to the components, choose the **Update Mesh** option from the shortcut menu displayed on right-clicking on the **Mesh** node in the Design tree; the mesh component is updated, as shown in Figure 18-74.




Figure 18-74 The update meshed view of the components

Solving the Static Analysis

After generating the refined mesh for the components of the assembly, you need to solve the analysis.

1. Choose the **Simulate** tool from the **Solve** panel of the **Stress Analysis** tab; the **Simulate** dialog box is displayed.
2. Choose the **Run** button in the **Simulate** dialog box; the solving procedure starts and the Von Mises stress contour is displayed in the drawing area, as shown in Figure 18-75.

Due to the effect of the angular velocity and constraints applied on the components of the assembly, maximum stresses are applied on the shoulder screw. To view these stresses in the drawing area, you need to disable the visibility of the support2 component in the assembly.

3. Select the Support2 component from the Design tree and right-click on it; a shortcut menu is displayed.





Figure 18-75 The resultant model with Von Mises contour

4. Choose the **Visibility** option from the shortcut menu; the visibility of the selected component is turned off.
5. Similarly, turn off the visibility of the wheel component; the stress generated on the shoulder screw component is displayed, as shown in Figure 18-76.



6. Next, turn on the visibility of the components that are hidden.

Generating the Analysis Report

Now, you need to generate the complete report of the simulation for the static analysis.

1. Choose the **Report** tool from the **Report** panel of the **Stress Analysis** contextual tab; the **Report** dialog box is displayed.
2. By default, the **General** tab is chosen in this dialog box. Enter **Stress Analysis Report of the Wheel Support** in the **Report Title** and **File Name** edit boxes and accept the other default settings.
3. Choose the **OK** button from the **Report** dialog box; the **Stress Analysis Report** dialog box along with the part window is displayed. After the reporting process is completed, the report is generated in *.html* format and is displayed in your default internet browser.

After completing the simulation procedure and generating the analysis report, save the model.

Starting a Modal Analysis

After completing the static analysis and generating the analysis report, you need to start the model analysis for the assembly.

1. Choose the **Create Simulation** tool from the **Manage** panel of the **Stress Analysis** contextual tab; the **Create New Simulation** dialog box is displayed.
2. In the **Simulation Type** tab of the **Create New Simulation** dialog box, select the **Modal Analysis** radio button; the options related to the model analysis are activated.
3. Enter **6** in the **Number of Modes** edit box and choose the **OK** button; the **Simulation: 2** node is displayed in the Design tree.
4. Next, apply the fixed support to the base component by using the **Fixed** tool.
5. Now, generate the contacts for the components of the assembly by using the **Automatic Contacts** tool.

In model analysis, the contacts among the components of the assembly are considered as the bonded contacts.

6. Next, generate the mesh for the components of the assembly by using the **Mesh View** tool.

Solving the Modal Analysis

After generating the refined mesh for the components of the assembly, you need to solve the analysis for the first 6 natural frequencies and their mode shapes.

1. Choose the **Simulate** tool from the **Solve** panel of the **Stress Analysis** contextual tab; the **Simulate** dialog box is displayed.
2. Choose the **Run** button in the **Simulate** dialog box; the solving procedure starts and the first natural frequency model shape contour is displayed in the drawing area, as shown in Figure 18-77.




Figure 18-77 The mode shape of the first natural frequency

Generating the Analysis Report

Now, you need to generate the complete report of the simulation for the modal analysis.

1. Choose the **Report** tool from the **Report** panel of the **Stress Analysis** contextual tab; the **Report** dialog box is displayed.
2. By default, the **General** tab is chosen in this dialog box. Enter **Model Analysis Report of the Wheel Support** in the **Report Title** and **File Name** edit boxes and accept other default settings.
3. Choose the **OK** button from the **Report** dialog box; the **Stress Analysis Report** status window is displayed. After the reporting process is done, the report is generated in *.html* format and is displayed in your default internet browser.

After completing the simulation process and generating the analysis report, save the model.

4. Choose the **Save** button from the **Quick Access Toolbar**; the **Save As** dialog box is displayed.
5. Specify the name of the file as **Tutorial3.ipt** and browse to the location *C*

:\\Inventor_2016\\c18. Next, choose the **Save** button; the model is saved.

Answer the following the questions and then compare them to those given at the end of the chapter:

1. In FEA the geometric model has to be discretized into small parts known as _____.
2. In Autodesk Inventor, you can start the FEA simulation by choosing the _____ tool.
3. The _____ tool is used to apply the linear and angular velocities to the model.
4. The contacts among the components in the assembly can be generated by using the _____ tool.
5. By default, _____ type of contact is generated by using the **Automatic Contacts** tool.
6. After solving the simulation problems, the maximum stress value can be calculated by using the _____ tool.
7. The _____ tool is used to generate the solution of the simulation.
8. In modal analysis, the frequency range can be set in the _____ edit box.
9. The _____ tool is used to create the local refined mesh for the model.
10. The properties of the material are displayed in the _____ dialog box.

Answer the following questions:

1. The _____ tool is used to generate the mesh for a model.

2. FEA stands for _____.
3. The _____ tool is used to apply material to the model.
4. After solving the simulation, the minimum stress value can be located by using _____ tool.
5. The tools in the _____ panel of the **Stress Analysis** contextual tab are used for generating and refining the mesh.
6. An automatically generated mesh can be refined by using the _____ tool.
7. In a static analysis, the deformation can only be achieved along the X-axis. (T/F)
8. You can apply the fixed constraint to a model by using the **Fixed** tool. (T/F)
9. In modal analysis, you can find the stresses induced in the model. (T/F)
10. In Autodesk Inventor, after generating the contacts, you cannot change the type of contact among the components. (T/F)
11. To start a modal analysis in Autodesk Inventor, you first need to run the Static Structural analysis. (T/F)

EXERCISE 1

In this exercise, you will perform the static analysis of the model shown in Figure 18-78. The dimensions, boundary conditions, and load applied on the model are shown in Figure 18-79. The model is made up of alloy steel material. **(Expected time: 45 min)**




Figure 18-78 The model for Exercise 1




Figure 18-79 The dimensions, boundary condition, and loads applied on the model

EXERCISE 2

In this exercise, you will perform the modal analysis for the first 5 natural frequencies and their mode shapes of the model shown in Figure 18-80. The dimensions and boundary conditions applied to the model are shown in Figure 18-81. The model is made up of Steel Alloy material. **(Expected time: 45 min)**




Figure 18-80 The Boundary conditions for the model




Figure 18-81 The dimensions for the model

Answers to Self-Evaluation Test

1. elements, 2. Stress Analysis, 3. Body, 4. Automatic or Manual Contacts, 5. Bonded, 6. Maximum Value, 7. Simulate, 8. Frequency Range, 9. Local Mesh Control, 10. Material Editor

CHAPTER 19

Introduction to PLASTIC MOLD DESIGN

Learning Objectives

After completing this chapter, you will be able to:

- *Understand the components required in a mold system.*
- *Create core and cavity of a model.*
- *Specify locations for gates.*
- *Create various types of gates as per the requirement.*
- *Create mold base for the component.*
- *Create runner and cooling systems in the mold base.*
- *Analyze the mold fill.*

Introduction To Plastic Mold Design

Mold Design is the process of shaping pliable raw material into a desired shape by using a rigid frame called pattern. This pattern is then used to create a mold. A mold is a hollow block that is used to fill some material to get a component of desired shape and size. In Autodesk Inventor, you can design a mold by using the tools available in the Mold environment.

INVOKING THE MOLD ENVIRONMENT

To invoke the Mold environment, start Autodesk Inventor and then choose the **New** tool from the **Launch** panel in the **Get Started** tab of the **Ribbon**; the **Create New File** dialog box will be displayed. In this dialog box, select the **Mold Design(mm).iam** option from the **Assembly - Assemble 2D and 3D components** node, and then choose the **Create** button; the Assembly interface will be displayed along with the **Create Mold Design** dialog box, as shown in Figure 19-1.




Figure 19-1 Assembly interface with the Create Mold Design dialog box

In this dialog box, specify the name of the file in the **Mold Design File Name** edit box. You can specify the location of the mold design file in the **Mold Design File Location** edit box. After specifying the desired options, choose the **OK** button from the dialog box to create a mold design file; the Mold Design interface will be displayed, as shown in Figure 19-2. The tools in the **Ribbon** are arranged according to their application in creating Mold Design.

METHODS OF DESIGNING CORE AND CAVITY

In any mold, there are two parts that form the shape of the component to be created: core and cavity. You can design core and cavity by using two methods. In the first method, you will import a model and then create core/cavity from it. However, in the second method, you will create core and cavity from two individual components respectively in the Mold environment. These two methods are discussed next.




Figure 19-2 Mold Design interface of Autodesk Inventor

Importing Plastic Part in Mold Environment

To import a model in the Mold environment, choose the **Plastic Part** tool from the **Plastic Part** drop-down of the **Mold Layout** panel in the **Ribbon**; the **Plastic Part** dialog box will be displayed, as shown in Figure 19-3. In this dialog box, browse and select the inventor part file of the model to be imported into the Mold environment.




Figure 19-3 The Plastic Part dialog box

Now, choose the **Open** button from the dialog box; the preview of the model will be displayed in the drawing area. Also, the cursor will change in a plastic part place icon. You can now align the part with references such as **Part_Centroid**, **Part_CSYS**, or **Work Reference**. To align the part, right-click in the drawing area; a shortcut menu will be displayed, as shown in Figure 19-4. By default, the **Align with Part_Centroid** option is chosen in the shortcut menu. So, the plastic part to be placed is automatically aligned to the **Part_Centroid**. To align the plastic part to the part coordinate system, choose the **Align with Part_CSYS** option from the shortcut menu. To align the part with the work reference, choose the **Align with Work Reference** option from the shortcut menu; the plastic part will be aligned with the work reference available in the part to be inserted.




Figure 19-4 The shortcut menu displayed on right-clicking

Adding Core and Cavity by using Individual Models

In this method, you will add core and cavity to models. To do so, choose the **Place Core and Cavity** tool from the **Plastic Part** drop-down; the **Place Core and Cavity** dialog box will be displayed, refer to Figure 19-5. Click on the Place component button adjacent to the **Core File** edit box; the **Place Component** dialog box will be displayed, as shown in Figure 19-6. In this dialog box, browse and select the file to be added as core. Similarly, place the cavity model by using the desired file.




Figure 19-5 The Place Core and Cavity dialog box

Tip. Core is the part of mold which has pin and impressions to give desired shape to the solidifying material. Cavity is that part of mold in which the molten material is filled.




Figure 19-6 The Place Component dialog box

ADJUSTING ORIENTATION AND POSITION OF A PART

After placing the part, you can orient or position it by using the tools available in the **Adjust Orientation** drop-down. There are two tools available in this drop-down: **Adjust Orientation** and **Adjust Position**. The procedure to adjust orientation of the part is discussed next.

Adjusting Orientation of the Part

To adjust the orientation of the part, choose the **Adjust Orientation** tool from the **Adjust Orientation** drop-down in the **Mold Layout** panel of the **Mold Layout** tab in the **Ribbon**; the part will be selected and the opening direction will be displayed on the part, refer to Figure 19-7. Also, the **Adjust Orientation** dialog box will be displayed, as shown in Figure 19-8.




Figure 19-7 Preview of the object with opening direction displayed




Figure 19-8 The Adjust Orientation dialog box

Using the options in this dialog box, you can change the orientation of the part. The options in this dialog box are discussed next.

Plastic Part

This button is used to select the plastic part. If the part is already selected, then this button will not be active.

Method Area

There are two buttons available in this area: **Rotate around Axis** and **Align with Axis**. Choose the **Rotate around Axis** button if you want to rotate the plastic part around an axis. If you want to move the plastic part along an axis then choose the **Align with Axis** button from this area.

X/Y/Z

There are three buttons that are used to change the axis around which the part is

to be rotated or along which the part is to be moved. These buttons act as toggle buttons. You can select any of the three buttons at a time.

Align Area

There are two buttons available in this area: **Select edge or surface** and **Flip moldable part**. The **Select edge or surface** button is used to select an edge or a face to align the opening direction of the part. The **Flip moldable part** button is used to reverse the direction of part.

Reset

This button is used to reset the part to its original orientation.


After adjusting the orientation of the part, choose the **OK** button from the dialog box.

Note

*The **Adjust Orientation** tool cannot be used for orienting individually added core and cavity. In such cases, an error message will be displayed stating that there is no moldable part.*

Adjusting Position of the Part

To adjust the position of the part, choose the **Adjust Position** tool from the **Adjust Orientation** drop-down; the **Adjust Position** dialog box will be displayed, as shown in Figure 19-9. The options in this dialog box are discussed next.



*Figure 19-9 The **Adjust Position** dialog box*

Align XY Plane with Reference

This button is used to adjust the position of the part along X-axis and Y-axis. This button is chosen by default. As a result, the **X Offset** and **Y Offset** edit boxes will be displayed in the dialog box. Specify the distance value along the X axis and Y axis in the respective edit boxes and then choose the **OK** button from the dialog box; the part will move to the specified location.

Align Center with X/Y Direction

This button is used to adjust the position of the part along X or Y direction through its center. On choosing this button, the **X** and **Y** buttons will become available. Choose the **X** button if you want to align center of the part along the **X** axis; the **X Offset** edit box will be displayed. Specify the value of distance in the edit box and then choose the **OK** button; the part will move by the specified distance along the X direction. If you want to align center of the part along the Y axis then choose the **Y** button from the dialog box. On doing so, the **Y Offset** edit box will be displayed. Specify the value of distance in the edit box and then choose the **OK** button; the part will be moved by the specified distance.

Free Transform

This button is used to move the part along all the three axes. On choosing this button, the **X Offset**, **Y Offset** and **Z Offset** edit boxes will be displayed, refer to Figure 19-10. You can specify the value of offset along the X, Y, and Z axes in the edit boxes.




Figure 19-10 The Adjust Position dialog box with the Free Transform button chosen

SELECTING MATERIAL

To design a mold, you need to first select material for the part. To select the material, choose the **Select Material** tool from the **Mold Layout** panel of the

Mold Layout tab in the **Ribbon**; the **Select Material** dialog box will be displayed, as shown in Figure 19-11. Options in this dialog box are discussed next.




Figure 19-11 The Select Material dialog box

Commonly used materials

This radio button is used when you want to select material from the list of commonly used materials. On selecting this radio button, the options available in the list below will get highlighted. Select the desired material from the list. You can remove materials from the commonly used materials list by choosing the **Remove** button. Choose the **OK** button from the dialog box; the selected material will be applied to the part.

Specific material

This radio button is used when you want to select material from the list of materials available in Autodesk Inventor. On selecting this radio button, the options below it become active. There are two drop-down lists available below this radio button: **Manufacturer** and **Trade name**. In the **Manufacturer** drop-down list, select the name of the manufacturer of material. In the **Trade name** drop-down list, select the name of the material which you want to apply on the part. You can also search the material to be applied on the part. To do so, choose the **Search** button from the dialog box; the **Search Criteria** dialog box will be

displayed, as shown in Figure 19-12.




Figure 19-12 The *Search Criteria* dialog box

From the **Search Fields** area of this dialog box, select the category in which you want to search the material. In the **Filter** area of this dialog box, specify the keywords that you want to search for the material. You can find the exact match for the specified keywords by selecting the **Exact string match** check box from the dialog box. After specifying the search criteria, choose the **Search** button; the **Select Thermoplastics material** dialog box will be displayed, refer to Figure 19-13. Select the material from the list, and then choose the **Select** button from the dialog box; the selected material will be displayed in the drop-down lists of the **Select Material** dialog box. Now, choose the **OK** button from the dialog box to apply the material.





Figure 19-13 The *Select Thermoplastics material* dialog box

Details

This button is used to view details of the material selected in the dialog box. To view the details, choose the **Details** button from the **Selected material** area of the dialog box; the **Thermoplastic material** dialog box will be displayed with the details of selected material, refer to Figure 19-14.



The screenshot shows a dialog box titled "Thermoplastics material" with a tabbed interface. The "Description" tab is active, displaying the following information:

Mechanical Properties		Shrinkage Properties		Filler Properties		Environmental Impact		Quality Indicators	
Description		Recommended Processing		Rheological Properties		Thermal Properties		pVT Properties	
Family name	POLYAMIDES (NYLONS, PPA...)								
Trade name	Alcom 6PA 900/8 GF 10 MR 20								
Manufacturer	Abis Plastics GmbH								
Link									
Family abbreviation	PA6								
Material structure	Crystalline								
Data source	Moldflow Plastics Labs : pVT-Measured : mech-Supplemental								
Date last modified	14-MAR-07								
Date tested	19-SEP-03								
Data status	Non-Confidential								
Material ID	20311								
Grade code	MAT2020								
Supplier code	ALBIS								
Fibers/fillers	10% Glass Fiber Filled, 20% Mineral Filled								

At the bottom of the dialog box, there is a "Name" field containing "Alcom 6PA 900/8 GF 10 MR 20" and "Abis Plastics GmbH". There are "OK" and "Help" buttons at the bottom right.

Figure 19-14 The **Thermoplastics material** dialog box

Report

This button is used to generate a report on the properties of the selected material. To generate a report, choose the **Report** button from the **Selected material** area of the dialog box; the **Material Data Method Report** dialog box will be displayed, as shown in Figure 19-15.




Figure 19-15 The Material Data Method Report dialog box

CREATING CORE AND CAVITY FOR THE PART

You can create core and cavity for the part by using the **Core/Cavity** tool. To do so, choose the **Core/Cavity** tool from the **Mold Layout** panel in the **Mold Layout** tab of the **Ribbon**; the **Core/Cavity** contextual tab will get added to the **Ribbon**, refer to Figure 19-16. The tools in this tab are discussed next.



Figure 19-16 The Core/Cavity contextual tab

Adjusting Orientation

You can adjust the orientation of the part by using the **Adjust Orientation** tool from the **Core/Cavity** contextual tab. Details of this tool have already been discussed in this chapter.

Specifying Gate Location

You can specify the location of the gate by using the Gate Location tool. To do so, choose the **Gate Location** tool from the **Plastic Part** panel in the **Core/Cavity** tab of the **Ribbon**; the **Gate Location** dialog box will be

displayed, as shown in Figure 19-17. There are two tabs available in this dialog box: **Set** and **Suggest**. These tabs are discussed next.




Figure 19-17 The Gate Location dialog box with the Set tab chosen

Set Tab

The options in this tab are used to manually set the location of the gate. The options in this tab are discussed next.

Name

This edit box is used to specify a name for the gate location.

Plastic Part

This button will be active only if there are multiple parts in the file. To select a plastic part, choose the **Plastic Part** button; you will be prompted to select a part. Select the part; the selected part will be used to set the location of gate.

Location

This button is used to specify the location of the gate. To specify the location of the gate, choose this button; a point mark will be attached to the cursor and you will be prompted to select a gate location. Click on the part to specify the location of the gate; the coordinates of the specified location will be displayed in the right of the dialog box.

[X, Y, Z]

This check box is used to show the value of coordinates in terms of X, Y, and Z values. By default, the coordinates of the gate location point are displayed in terms of U and V values.

After specifying the gate location point, choose the **Apply** button; the gate location point will be placed. Choose the **Done** button from the dialog box to exit.

Suggest Tab

The options in this tab are used to find out the best possible locations of the gates in the mold, refer to Figure 19-18. The options in this tab are discussed next.




Figure 19-18 The Gate Location dialog box with the Suggest tab chosen

Number of Gate Locations [1:10]

This edit box is used to specify the number of gates that need to be added in the mold. You can specify up to 10 gates in a mold. Autodesk Inventor suggests the locations of the gates on the basis of the value specified in this edit box.

Start

This button is used to start the analysis for suggesting the location of gates. Before starting the analysis, make sure that the material is applied on the part. Now, choose this button to start the analysis; the **Analysis running** message box will be displayed, as shown in Figure 19-19.






Figure 19-19 The Analysis running message box

You can configure the display of this dialog box by choosing the **Prompts** button. On choosing this button, the dialog box expands, as shown in Figure 19-20.



*Figure 19-20 The expanded **Analysis running** message box*

There are four radio buttons available in the expanded dialog box. Select the desired radio button and then choose the **OK** button to exit the dialog box; the **Gate Location** dialog box will be displayed, as shown in Figure 19-21. After the analysis is complete, the **Summary** dialog box will be displayed, as shown in Figure 19-22.



*Figure 19-21 The **Gate Location** dialog box*




Figure 19-22 The *Summary* dialog box

There are two tabs in this dialog box: **General** and **Gate Location**. On choosing the **General** tab, the general summary of the gate location is displayed in the dialog box. If you choose the **Gate Location** tab, the position of gates is displayed in the dialog box. Choose the **OK** button to accept the location or the **Cancel** button to start the analysis again. On choosing the **OK** button, the location of the gate will be displayed with a yellow mark on the part, refer to Figure 19-23.




Figure 19-23 The *Gate Location* mark on the part

Stop

This button is used to stop the progress of analysis. On choosing this button, the **Stop Analysis** message box will be displayed, as shown in Figure 19-24. If

you choose the **Yes** button, the **Gate Location** dialog box will be displayed in its default mode. Choose the **Start** button to start the analysis again.




Figure 19-24 The Stop analysis message box

Note

Sometimes, the analysis suggests you a location which is not feasible for a mold maker to use. In such cases, you need to specify the gate location manually.

Settings for the Process

After defining the gate location, you need to specify the settings such as mold temperature, melt temperature, pressure, and clamp open time by using the **Part Process Settings** tool. To do so, choose the **Part Process Settings** tool from the **Plastic Part** panel in the **Core/Cavity** contextual tab of the **Ribbon**; the **Part process settings** dialog box will be displayed, as shown in Figure 19-25. There are two tabs in this dialog box: **Set** and **Suggest**. These tabs and their options are discussed next.




Figure 19-25 The Part process settings dialog box

Set Tab

The options in this tab are used to set the parameters required for the molding process. This dialog box is divided into four areas; **Material properties**, **Maximum injection limit pressure**, **Machine injection time**, and **Machine clamp open time**. The options in these areas are discussed next.

Material properties

There are two spinners available in this area: **Mold temperature** and **Melt temperature**. Set the value in both the spinners as per the requirement. To set the default value in the spinner, choose the **Default** button adjacent to that spinner.

Maximum injection limit pressure

In this area, the **Maximum machine injection pressure [10.00 : 500.00]MPa** spinner is used to set the value of maximum pressure at which the injection of molten plastic will be done. You can specify the injection pressure from 10 MPa to 500 MPa. By default, the **Automatic velocity/pressure switch-over** check box is selected in this area. As a result, you do not need to specify the value of velocity/pressure switch-over. If you want to specify the value of velocity/pressure switch-over, then clear the check box; the **Velocity/pressure switch-over by volume %** edit box will get activated. Now, you can specify the percentage value of the velocity/pressure switch-over in this edit box.

Machine injection time

By default, the **Automatic injection time** check box is selected in this area. So, the injection time is calculated automatically. However, you can specify the machine injection time manually. To do so, clear the **Automatic injection time** check box; the **Time [Sec]** edit box in this area will become active. Specify the value of injection time in terms of seconds in the edit box.

Machine clamp open time

The **Time [Sec]** edit box in this area is used to specify the time (in seconds) required to open the machine clamp.

Suggest Tab

Using the options in this tab, you can find the optimum settings for the current process. To do so, select the required surface finish from the **Required surface finish** area of the tab and then choose the **Start** button from the dialog box; the **Analysis running** dialog box will be displayed. Choose the **OK** button from the dialog box. After the analysis is complete, the **Summary** dialog box will be displayed, refer to Figure 19-26. The optimum values of various parameters are displayed in the dialog box. Choose the **OK** button from the dialog box to accept the changes.




Figure 19-26 The Summary dialog box

Analyzing Part for Filling

After specifying the gate location and setting the process parameters, you need to check whether the filling is appropriate in the mold or not. To do so, choose the **Part Fill Analysis** tool from the **Plastic Part** panel in the **Core/Cavity**

contextual tab of the **Ribbon**; the **Part Fill Analysis** dialog box will be displayed, as shown in Figure 19-27. Choose the **Start** button from the dialog box to start analyzing the part for filling. Choose the **OK** button from the **Analysis Running** dialog box displayed; the analysis will start. After the analysis is complete, the **Summary** dialog box with fill analysis report will be displayed, refer to Figure 19-28. At the top of the report, you can find the result and advice to improve the filling process. You can see the general summary of the part by choosing the **General** tab in the dialog box.




Figure 19-27 The Part Fill Analysis dialog box




Figure 19-28 The Summary dialog box with Fill analysis report

Specifying Shrinkage Allowance

During the molding process, when the material starts cooling in the mold, it starts shrinking as well. You need to specify this shrinkage allowance in the mold before you start filling the mold with material. To specify the shrinkage allowance, choose the **Part Shrinkage** tool from the **Plastic Part** panel in the **Core/Cavity** contextual tab of the **Ribbon**; the **Part Shrinkage** dialog box will be displayed, refer to Figure 19-29. There are two tabs in this dialog box: **Set** and **Suggest**. These tabs are discussed next.




Figure 19-29 The Part Shrinkage dialog box

Set Tab

The options in this tab are used to specify the coordinate system and percentage of shrinkage in the material during the molding process. The options in this dialog box are discussed next.

Coordinate System

The options in this drop-down list are used to specify the coordinate system corresponding to which the shrinkage will be defined. By default, there are three options in this drop-down list, **Mold_CSYS**, **Part_CSYS**, and **Specify UCS**. Using the **Specify UCS** option, you can specify a new coordinate system.

Shrink Percentage

The options in this area are used to specify the percentage of shrinkage in the material during the molding process. By default, the **Isotropic** check box is selected. So, the shrinkage value specified in the **X** edit box will also be applied in the **Y** and **Z** edit boxes. If you clear this check box, then you can specify the different values of shrinkage in the **X**, **Y**, and **Z** edit boxes.

Material

This edit box is used to specify the name of the material that is applied to the part.

Range

This edit box is used to specify the range of shrinkage % for the part.

Suggest Tab

Using the options in this tab, you can find the optimum shrinkage values for the current process. The options in this tab are discussed next.

Packing Profile

The options in this area are used to specify the values in the packing profile table. You need to specify filling time and pressure in the table. After specifying these values, choose the **Plot** button to see the packing profile plot. On doing so, the **Packing Profile Plot** dialog box will be displayed, refer to Figure 19-30.




Figure 19-30 The **Packing Profile Plot** dialog box

Start

This button is used to start the analysis. To do so, choose this button; the **Analysis running** dialog box will be displayed. Choose the **OK** button from the dialog box the analysis will begin. After the analysis is complete, the **Summary** dialog box will be displayed. You can find out the estimated shrinkage allowance from the dialog box, refer to Figure 19-31.




Figure 19-31 The Summary dialog box

Defining Workpiece

After specifying the parameters related to the workpiece, now you need to specify the workpiece in which the mold will be created. To define the workpiece, choose the **Define Workpiece Setting** tool from the **Parting Design** panel of the **Core/Cavity** contextual tab in the **Ribbon**; the **Define Workpiece Setting** dialog box will be displayed, as shown in Figure 19-32. The options in this dialog box are discussed next.




Figure 19-32 The Define Workpiece Setting dialog box

Workpiece Type

Using the options in this drop-down list, you can specify the shape of the

workpiece. There are two options in this drop-down list: **Rectangular** and **Cylinder**. The **Rectangular** option is used to create a cuboid workpiece. The **Cylinder** option is used to create a cylindrical workpiece.


Reference

Using the options in this drop-down list, you can specify the boundaries of the workpiece. There are two options in this drop-down list: **By Boundary Box** and **By References**. The **By Boundary Box** option is used to specify the boundary of the workpiece by specifying values. If you want to specify boundary of the workpiece by selecting references, then choose the **By References** option from the drop-down list. On doing so, the **Multiple references** check box will be activated. On selecting this check box, you can select references for the boundary. If you clear this check box, then the boundary is defined by only one reference.

Chamfer or Fillet

These options are available in the expanded **Define Workpiece Setting** dialog box, refer to Figure 19-33. To display the expanded **Define Workpiece Setting** dialog box, select the **Rectangular** option from the **Workpiece Type** drop-down list and then choose the >> button from the **Define Workpiece Setting** dialog box. There are two buttons available in the expanded dialog box: **Chamfer** and **Fillet**. If you choose the **Chamfer** button, the corners of the workpiece will get chamfered. Select the check box corresponding to the corner to be chamfered; the edit box adjacent to the selected check box will become active. Specify the value of chamfer in the edit box; the corner will be chamfered by the specified value. Similarly, you can apply fillet by choosing the **Fillet** button.

After specifying the desired options, choose the **OK** button from the dialog box; the workpiece will be created.



*Figure 19-33 The expanded **Define Workpiece Setting** dialog box*

Creating Patching Surface

After defining the workpiece, you need to create the patching surface for the mold to restrict the flow of material in the desired areas. To create the patching surface, choose the **Create Patching Surface** tool from the **Parting Design** panel of the **Core/Cavity** contextual tab in the **Ribbon**; the **Create Patching Surface** dialog box will be displayed, as shown in Figure 19-34. You can use the **Auto Detect** button to create the patches automatically. To do so, choose the **Auto Detect** button available at the top of the dialog box; the possible patches will be created automatically and will be displayed in the list. You can specify the patches manually also. To do so, select the **Click to add** option displayed in the list; you will be prompted to select edges to create a patch surface. Select the edges of the surface where you want to create the patch surface. The selected edges will be displayed in the **Loop** area of the dialog box. You can add more than one patching surfaces. To do so, select the **Click to add** option again. Choose the **OK** button after specifying the desired patching surfaces; the created patching surfaces will be displayed in brown color.




Figure 19-34 The Create Patching Surface dialog box

Creating Planar Patches

You can also create patches manually using the **Create Planar Patch** tool. To do so, choose the **Create Planar Patch** tool from the **Parting Design** panel in the **Core/Cavity** tab of the **Ribbon**; the **Create Planar Patch** dialog box will be displayed, as shown in Figure 19-35. Also, you will be prompted to select one or more connected edges. Select the edges and then choose the **Apply** button to create the patch. Select more edges if you want to create more patches and then choose the **OK** button to exit the dialog box.




Figure 19-35 The Create Planar Patch dialog box

Note

You can create a patching surface before defining the workpiece.

Creating Runoff Surface

The runoff surface is used for parting the core and the cavity. The runoff surface can be created only after defining the workpiece. To create a runoff surface, choose the **Create Runoff Surface** tool from the **Parting Design** panel in the **Core/Cavity** tab of the **Ribbon**; the **Create Runoff Surface** dialog box will be

displayed, as shown in Figure 19-36. Now, you can either manually specify the runoff surface or the location of the runoff surface can be suggested by Inventor. To manually specify the location of the runoff surface, select an edge on the model; the plane will be created as runoff surface.

To automatically specify the location of the runoff surface, choose the **Auto Detect** tool from the top of the dialog box; the preview of the runoff surface will be displayed in the modeling area. Choose the **OK** button from the dialog box to accept the results; the runoff surface will be created and displayed in the modeling area.




Figure 19-36 The Create Runoff Surface dialog box

Generating Core and Cavity

After creating the workpiece and specifying the runoff surface, you can generate core and cavity for the part. To do so, choose the **Generate Core and Cavity** tool from the **Parting Design** panel in the **Ribbon**; the **Generate Core and Cavity** dialog box will be displayed, as shown in Figure 19-37. In the **Opacity Setting** area of the dialog box, you can change the color of the cavity and the core by using the buttons available next to their name in the area. You can change the opacity of color of the core and cavity by using the sliders available next to their respective color buttons. These sliders will be activated only after choosing the **Preview/Diagnose** button. The method to display the preview of the core and cavity is discussed next.




Figure 19-37 The Generate Core and Cavity dialog box

Previewing/Diagnosing the Core and Cavity

You can preview/diagnose the core and cavity by using the **Preview/Diagnose** button available at the top of the dialog box in the **Preview** tab. Choose this button to preview the core and cavity; the core and cavity will be displayed in the specified colors, refer to Figure 19-38. Also, the sliders available in the dialog box will be activated. Using the **Body Separation** slider, you can preview the core and cavity in a separated position, refer to Figure 19-39. Choose the **OK** button from the dialog box to accept the core and cavity or you can see the result by choosing the **Parting Diagnostics** tab from the dialog box. Figure 19-40 shows diagnostics of a core and cavity.




Figure 19-38 Preview of the core and cavity




Figure 19-39 Preview of separated core and cavity




Figure 19-40 Parting diagnostics of the core and cavity

Choose the **OK** button from the **Generate Core and Cavity** dialog box to generate the core and cavity of the part, refer to Figure 19-41.




Figure 19-41 The core and cavity of the part

After generating the core and the cavity, choose the **Finish Core/Cavity** tool from the **Exit** panel in the **Core/Cavity** contextual tab of the **Ribbon**; the core and cavity will be displayed.

Now, you need to create a runner in the mold to facilitate the flow of plastic in the mold.

CREATING PATTERN OF THE MOLD

In a molding machine, multiple molds are created at a time. So, you need to create pattern of the mold in Inventor to facilitate this type of process. To create pattern of the mold, choose the **Pattern** tool from the **Mold Layout** panel in the **Mold Layout** tab of the **Ribbon**; the **Pattern** dialog box will be displayed. These are three tabs in this dialog box: **Rectangular**, **Circular**, and **Variable**. These tabs are used to create rectangular, circular and variable patterns, respectively. The methods to create these patterns are discussed next.

Creating a Rectangular Pattern

To create a rectangular pattern, choose the **Rectangular** tab in the dialog box; the **Pattern** dialog box will be displayed, as shown in Figure 19-42. By default, the **Base Pattern** button is chosen in the **Pattern Type** area of the dialog box. Now, you need to specify the number in the instances of the mold in the edit boxes available in the **X Direction** and **Y Direction** areas. You can also specify

the distance between the two instances along the X and Y axes by using the edit boxes available in the **X Direction** and **Y Direction** areas. You can also change the orientation of the mold along the X axis or Y axis by using the **X Balance** and **Y Balance** buttons available in the **Pattern Type** area of the dialog box.




Figure 19-42 The Pattern dialog box

Creating a Circular Pattern

To create a circular pattern, choose the **Circular** tab from the dialog box; the **Pattern** dialog box will be modified, as shown in Figure 19-43. Specify the number of instances in the edit box available in the **Circular** area displaying the value as 1. Similarly, you can specify the value of angular distance, angular offset, and distance between the instances in the respective edit boxes in **Circular** area of the dialog box. As you specify the values in the edit boxes, the preview of the specified parameters is displayed in the modeling area.




Figure 19-43 The Pattern dialog box with the Circular tab chosen

Creating a Variable Pattern

To create a variable pattern, choose the **Variable** tab from the dialog box; the dialog box will be modified, as shown in Figure 19-44. Right-click in the list displayed in dialog box; a shortcut menu will be displayed, refer to Figure 19-45. To add an instance, choose the **Add** option from the shortcut menu; a new instance of the mold will be added. To specify the parameters of the instances created, click in the corresponding fields of the instances.




Figure 19-44 The **Pattern** dialog box with the **Variable** tab chosen




Figure 19-45 The shortcut menu displayed

After specifying the desired options, choose the **OK** button from the dialog box; the pattern will be created.

CREATING RUNNER OF THE MOLD

In a molding machine, material is filled in the molds with the help of a passage. This passage is called runner. The runner provides equal amount of material in each of the molds in the molding machine. To add a runner, you need to create a sketch for the runner first. The method to create runner sketch is discussed next.

Creating Runner Sketch

To create a runner sketch, there are two tools available in Autodesk Inventor: **Auto Runner Sketch** and **Manual Sketch**. These tools are available in the **Auto Runner Sketch** drop-down. Using the **Auto Runner Sketch** tool, you can create a runner sketch automatically. To do so, choose the **Auto Runner Sketch** tool; the **Auto Runner Sketch** dialog box will be displayed, refer to Figure 19-46. Choose the desired options from the **Balance** and **Pattern** drop-down lists and then select a reference on the mold to create a sketch for the runner. On doing so, the reference name and the length of the runner sketch is displayed on the right in the dialog box, refer to Figure 19-46. Also, the arrows are displayed on the runner sketch to translate or rotate it, refer to Figure 19-47. Move and rotate the runner sketch as per the requirement. Next, choose the **OK** button from the dialog box and then choose the **Finish Sketch** button from the **Exit** panel in the **Sketch** contextual tab of the **Ribbon**; the **3D Model** tab will be activated to facilitate modeling of the runner. Choose the **Return** tool from the **Return** panel in the **3D Model** tab of the **Ribbon**; the runner sketch will be created, refer to Figure 19-48.




Figure 19-46 The **Auto Runner Sketch** dialog box




Figure 19-47 A mold pattern with runner and its arrowheads




Figure 19-48 Runner sketch created on the mold pattern

To create a runner sketch manually, choose the **Manual Sketch** tool from the **Auto Runner Sketch** drop-down in the **Ribbon**; the **Manual Sketch** dialog box will be displayed, as shown in Figure 19-49. Select the **Runner Sketch** radio

button from the dialog box if not selected, and then select a reference for drawing the runner sketch. Now, choose the **OK** button from the dialog box; the **Sketch** contextual tab will be displayed in the **Ribbon** and you will be prompted to draw a sketch for the runner. Draw a sketch for the runner and then choose the **Finish Sketch** button from the **Exit** panel in the **Sketch** contextual tab of the **Ribbon**; the **3D Model** tab will be activated to facilitate modeling of the runner. Create the required shape of the runner and then choose the **Return** tool from the **Return** panel in the **3D Model** tab of the **Ribbon**; the runner sketch will be created.




Figure 19-49 The Manual Sketch dialog box

After drawing a sketch for the runner, you can create a runner for the current mold. The method to create a runner is discussed next.

Creating Runner

To create a runner, choose the **Runner** tool from the **Runner** drop-down in the **Runners and Channels** panel of the **Ribbon**; the **Create Runner** dialog box will be displayed, as shown in Figure 19-50 and you will be prompted to select a sketched curve for the runner. Select the sketched curve and then specify the desired parameters in the dialog box; a preview of the runner will be displayed in the modeling area. Choose the **OK** button from the dialog box to create the runner. Figure 19-51 shows a runner created in the pattern.




Figure 19-50 The *Create Runner* dialog box




Figure 19-51 The runner created in the mold pattern

After creating the runner, you need to add gates to the molds. The method of creating gates is discussed next.

CREATING GATES FOR THE MOLDS



Gates can be created only after specifying the gate locations. To do so, choose the **Gate** tool from the **Runners and Channels** panel in the **Ribbon**; the **Create Gate** dialog box will be displayed, as shown in Figure 19-52 and you will be prompted to select gate locations. Select the gate locations and then

choose the **OK** button from the dialog box; the gates will be added at the selected locations. The options in this dialog box are discussed next.




Figure 19-52 The Create Gate dialog box

Type

The options in this drop-down list are used to specify the type of gate to be added at the selected gate locations. The options available in this drop-down list are discussed next.

Edge

This option is used to create an edge type gate. This gate type is used to create multi-cavity molds and medium or thick sections. The edge gate is located on the parting line and the part fills from the side, top or bottom.

Fan

This option is used to create fan type gate. This gate type is used to create thick-sectioned moldings and enables slow injection without freeze-off, which is preferred for low stress moldings or where warpage and dimensional stability are factors to be considered.

Pin

This option is used to create pin type gate. This gate type is used with a 3-plate tool because the gate and the part are to be ejected in the opposite direction. The

pin type gate is weak and may break while ejecting. This is the most suitable gate to use with thin sections.

Pin Point

This option is used to create pin point type gate. This gate type is used for cylindrical parts. It is easily detachable and saves material.

Submarine

This option is used to create submarine type gate. The submarine gate is used in two-plate mold construction. In this type of gate, tapered tunnel is machined from the end of the runner to the cavity below the parting line.

Flat-Bottom Submarine

This option is used to create a flat bottom submarine type gate. This gate is also used in two plate mold construction.

Tunnel

This option is used to create tunnel type gate. This type of gate is just a variation in the submarine type of gates. In this gate type, the curves at the end are in the form of a half circle.

Sprue

This option is used to create sprue type gate. The sprue type gate is used where single cavity mold is used and symmetry is required in the mold.

Placement

The options in this drop-down list are used to specify the placement of the gate in the mold. There are two options available in this drop-down list: **One Point** and **Two Points**. Select the **One Point** option from the list; you will be prompted to specify the gate location only. Select the **Two Points** option if you also want to specify the end point of the gate.

Copy to all pockets

This check box is used to create the specified gate at all the locations available on the pattern.

ADDING COLD WELLS

During the molding process, the material at the tip of sprue may solidify after one time material injection. This solid material can obstruct the flow of material. To avoid this situation, a cold well is needed in the runner line. To add a cold well, choose the **Cold Well** tool from the **Runners and Channels** panel in the **Mold Layout** tab of the **Ribbon**; the **Cold Well** dialog box will be displayed, as shown in Figure 19-53. You can create two types of cold wells, **Taper** and **Annular**. The options to specify the type are available in the **Type** drop-down list in the dialog box. You can specify the related dimensions in the **Profile** area of the dialog box. After specifying the desired parameters, choose the **Point** button from the **Position** area of the dialog box; you will be prompted to specify the position of the cold well. Select a point on the runner sketch to create the cold well. Choose the **OK** button from the dialog box to exit.




Figure 19-53 The Cold Well dialog box

Now, you need to create a mold base to support core and cavity, and to facilitate the molding process in the machine.

ADDING MOLD BASE TO THE ASSEMBLY

After creating core and cavity design, you need to add a mold base to the assembly. To add a mold base, choose the **Mold Base** tool from the **Mold Base** drop-down in the **Mold Assembly** panel of the **Mold Assembly** tab in the **Ribbon**; the **Mold Base** dialog box will be displayed, as shown in Figure 19-54.




Figure 19-54 The *Mold Base* dialog box

The options in this dialog box are discussed next.

Standard Area

The options in this area are used to specify the type and size of the mold base. These options are discussed next.

Vendor and Type

The options in this drop-down list are used to specify the type and maker of the mold base.

Size

The options in this drop-down list are used to specify the size of the mold base.

Customize

Select this check box to customize the mold base. On doing so, the expanded

Mold Base dialog box with the **Component** area will be displayed, as shown in Figure 19-55. The options available in the **Component** area are used to customize individual components of the mold base.




Figure 19-55 The expanded Mold Base dialog box

Placement Area

The options in this area are used to specify the position of the mold base. These options are discussed next.

Placement Reference

This button is used to specify the position of the mold base. To specify the position of the mold base, choose this button; you will be prompted to specify the position of the mold base. Select a point in the drawing area; the mold base will be placed.

Core Pocket Depth

This check box is used to specify the depth of the core pocket. On selecting this check box, the edit box below it will be activated. Using this edit box, you can specify the depth of the pocket.

Rotate Mold Base

The options in this drop-down list are used to specify the rotation angle of the mold base.

Layout Information Area

The options in this area are used to display the information regarding the layout of the mold base.

After specifying the desired options, choose the **OK** button from the dialog box to create the mold base. Figure 19-56 shows a mold base with core and cavity added.




Figure 19-56 The mold base with core and cavity added

ADDING SPRUE BUSHING

Sprue bushing is added to the mold base to fill molten plastic in the mold. To add a sprue bushing, choose the **Sprue Bushing** tool from the **Mold Assembly** panel in the **Mold Assembly** tab of the **Ribbon**; the **Sprue Bushing** dialog box will be displayed, as shown in Figure 19-57. Select the desired options from the dialog box and then choose the **Point** button to specify the position of the sprue bushing. Click at the middle of the runner line in the mold; the sprue bushing will be created. You can specify the desired parameters for the sprue bushing by using the options available in the table at the bottom right of the dialog box. Now, choose the **OK** button from the dialog box; the sprue bushing will be created at the specified position.




Figure 19-57 The Sprue Bushing dialog box

ADDING COOLING CHANNEL

Due to the repetitive use of molds, the system gets heated and can disturb the quality of the object to be molded. To avoid this situation, a cooling channel is required in the mold. To create a cooling channel, choose the **Cooling Channel** tool from the **Runners and Channels** panel in the **Mold Layout** tab of the **Ribbon**; the **Cooling Channel** dialog box will be displayed, refer to Figure 19-58. Also, you will be prompted to select a face on which the cooling channel will be created. Select a face; you will be prompted to specify references for constraining the cooling channel, refer to Figure 19-59. Select the two references and then specify the desired parameters using the options available in the **Drill Point** and **Extents** areas of the dialog box.




Figure 19-58 The Cooling Channel dialog box




Figure 19-59 The face selected for cooling channel

GENERATING DRAWING VIEWS

After creating the complete mold system, you need to create the drawing views of the system so that they can be used for manufacturing. Before generating the drawing views, make sure that you have saved the file. You can generate the drawing views by using the **2-D Drawing** tool from the **2-D Drawing** panel in the **Mold Assembly** tab of the **Ribbon**. To generate the drawing views, choose the tool from the **Ribbon**; the **2-D Drawing** dialog box will be displayed, as shown in Figure 19-60. Select the check boxes adjacent to the parts of the molding system for which you want to generate the drawing views. Choose the

OK button from the dialog box; the drawing files will be generated as per the selection in the dialog box and will be displayed in Inventor as tabs at the bottom.




Figure 19-60 The 2-D Drawing dialog box

TUTORIAL

Tutorial 1

In this tutorial, you will create molding system for the model shown in Figure 19-61. Also, you will analyze the filling of material in the mold. **(Expected time: 45 min)**



Figure 19-61 Model for mold design

The following steps are required to complete this tutorial:

- a. Download the input file.
- b. Start a new mold design file and import the plastic part.
- c. Apply material to the part and specify gate locations, refer to Figures 19-66 and 19-67.
- d. Specify process settings and create workpiece, refer to Figures 19-71 and 19-73.
- e. Generate core and cavity, refer to Figure 19-79 and create runner, refer to Figure 19-81.
- f. Add gates at the gate locations, refer to 19-85 and add the mold base, refer to Figure 19-86.
- g. Add sprue with locating ring to the mold base, refer to Figures 19-88 and 19-90.
- h. Create cooling channel, refer to Figure 19-93 and cold well, refer to Figure 19-94.

Downloading the File

You need to download the input file of this chapter from www.cadcim.com.

1. Download the zipped file from www.cadcim.com. The complete path for downloading the file is:
Textbooks > CAD/CAM > Inventor > Autodesk Inventor 2016 for Designers > Input files
2. Extract the downloaded input file as Tutorial1_mold. Next, copy the file and paste at the following location *C:\Inventor_2016\c19*.

Starting a New Mold Design File

1. Invoke the **Create New File** dialog box and then choose the **Metric** tab from it.
2. Double-click on the **Mold Design (mm).iam** option; the **Create Mold Design** dialog box will be displayed, as shown in Figure 19-62.




Figure 19-62 The *Create Mold Design* dialog box

3. Specify the name as *Tutorial1* in the **Mold Design File Name** edit box and the location as *C:\Inventor_2016\c19* in the **Mold Design File Location** edit box. Next, choose the **OK** button from the dialog box; the user interface of the mold design will be displayed.

Importing a Plastic Part in the Drawing

Now, you need to add a plastic part for which the mold will be designed.

1. Choose the **Plastic Part** tool from the **Plastic Part** drop-down in the **Mold Layout** panel of the **Mold Layout** tab in the **Ribbon**; the **Plastic Part** dialog box is displayed, as shown in Figure 19-63.




Figure 19-63 The *Plastic Part* dialog box

2. Browse to the file location *C:\Inventor_2016\c19* and select the file with the

name *Tutorial1_mold*.

3. Choose the **Open** button from the dialog box; the preview of the part is displayed in the modeling area.
4. Click anywhere in the drawing area to place the part.

Applying Material to the Part

Now, you will specify a material for the part to be molded.

1. Choose the **Select Material** tool from the **Mold Layout** panel of the **Mold Layout** tab of the **Ribbon**; the **Select Material** dialog box is displayed, refer to Figure 19-64.




Figure 19-64 The Select Material dialog box

2. Select the **SABIC Innovative Plastics US, LLC** option from the **Manufacturer** drop-down list and the **Cycloc G360** option from the **Trade name** drop-down list in the dialog box.
3. Choose the **OK** button from the dialog box; the selected material is applied on the part.

Specifying Gate Location on the Part

Now, you will specify a gate location on the part to fill material in the cavity.

1. Choose the **Core/Cavity** tool from the **Mold Layout** panel in the **Mold Layout** tab of the **Ribbon**; the **Core/Cavity** contextual tab is displayed.
2. Choose the **Gate Location** tool from the **Plastic Part** panel in the contextual tab; the **Gate Location** dialog box is displayed, as shown in Figure 19-65.




Figure 19-65 The Gate Location dialog box

3. Select a point on the part, as shown in Figure 19-66 and then choose the **Apply** button from the dialog box.




Figure 19-66 Point specified for gate location

4. Similarly, specify two more points on the part, as shown in Figure 19-67 and then choose the **Done** button from the dialog box.




Figure 19-67 Total points specified for gate location

Specifying Settings for the Part Process

Now, you will specify settings such as mold temperature and melt temperature for the part.

1. Choose the **Part Process Settings** tool from the **Plastic Part** panel in the **Core/Cavity** tab of the **Ribbon**; the **Part process settings** dialog box is displayed, refer to Figure 19-68.




Figure 19-68 The Part process settings dialog box

2. Choose the **Suggest** tab from the dialog box; the **Required surface finish** area is displayed, as shown in Figure 19-69.




Figure 19-69 The Part process settings dialog box with the Suggest tab

3. Select the **Low Gloss** radio button from the **Required surface finish** area of the dialog box and then choose the **Start** button from the dialog box; the analysis begins. Choose the **OK** button from the **Analysis Running** dialog box.
4. After the analysis is complete, the **Summary** dialog box is displayed, refer to Figure 19-70. Choose the **OK** button from the dialog box; the suggested process settings are applied.




Figure 19-70 The Summary dialog box

Defining a Workpiece

Now, you will define a workpiece for the part. This workpiece is used to create core and cavity.

1. Choose the **Define Workpiece Setting** tool from the **Parting Design** panel in the **Core/Cavity** tab of the **Ribbon**; the **Define Workpiece Setting** dialog box is displayed, as shown in Figure 19-71.




Figure 19-71 The Define Workpiece Setting dialog box

2. Select the **Rectangular** option from the **Workpiece Type** drop-down list in the dialog box; preview of the workpiece is displayed in the modeling area, refer to Figure 19-72.




Figure 19-72 Preview of the workpiece displayed

3. Choose the **OK** button from the dialog box; the workpiece is created, refer to Figure 19-73.




Figure 19-73 The workpiece created

Creating Patching Surfaces

Now you will create the patching surface. Patching surfaces are used to restrict the flow of melt in the desired locations.

1. Choose the **Create Patching Surface** tool from the **Parting Design** panel in the **Core/Cavity** contextual tab of the **Ribbon**; the **Create Patching Surface** dialog box is displayed, as shown in Figure 19-74.




Figure 19-74 The Create Patching Surface dialog box

2. Choose the **Auto Detect** button available at the top of the dialog box; a preview of the patching surfaces is displayed in the modeling area, refer to Figure 19-75.




Figure 19-75 Preview of the patching surfaces

3. Choose the **OK** button from the dialog box; the patching surfaces are created.

Creating Runoff Surfaces

Now, you need to create a runoff surface. Runoff surface is used to specify the plane at which the core and the cavity meet.

1. Choose the **Create Runoff Surface** tool from the **Parting Design** panel in the **Core/Cavity** contextual tab of the **Ribbon**; the **Create Runoff Surface** dialog box is displayed, as shown in Figure 19-76.




Figure 19-76 The Create Runoff Surface dialog box

2. Select the outer loop of the top face of the model; a preview of the runoff surface is displayed, refer to Figure 19-77.




Figure 19-77 Preview of the runoff surface

3. Choose the **OK** button from the dialog box; the runoff surface is created.

Generating Core and Cavity

1. Choose the **Generate Core and Cavity** tool from the **Parting Design** panel in the **Core/Cavity** tab of the **Ribbon**; the **Generate Core and Cavity** dialog box is displayed, as shown in Figure 19-78.




Figure 19-78 The Generate Core and Cavity dialog box

2. Choose the **OK** button from the dialog box; the core and cavity are generated, as shown in Figure 19-79.




Figure 19-79 The core and cavity generated

Now, choose the **Finish Core/Cavity** tool from the **Core/Cavity** contextual tab to finish the process of generating core and cavity.

Creating Plane for the Runner Sketch

Now, you need to create a plane offset from the runoff surface.

1. Choose the **Offset from Plane** tool from the **Plane** drop-down in the **Work Features** panel in the **3D Model** tab of the **Ribbon**; you are prompted to select a plane or face.
2. Select the runoff surface. Next, specify the value of offset as **30** in the edit box displayed in the modeling area; the plane is created.

Creating Sketch for the Runner

Now, you need to create a sketch for the runner system.

1. Choose the **Manual Sketch** tool from the **Auto Runner Sketch** drop-down in the **Runners and Channels** panel in the **Mold Layout** tab of the **Ribbon**; the **Manual Sketch** dialog box is displayed, as shown in Figure 19-80.




Figure 19-80 The Manual Sketch dialog box

2. Select the plane created earlier and choose the **OK** button from the dialog box; the **Sketch** contextual tab is displayed in the **Ribbon** and you are prompted to draw a sketch for the runner.
3. Create the runner sketch, as shown in Figure 19-81, using the Top view orientation.

Note

While creating sketch for the runner, make sure that you connect the end points of the sketch with the gate location points.




Figure 19-81 Sketch for the runner

4. Choose the **Finish Sketch** button from the **Exit** panel in the **Sketch** contextual tab of the **Ribbon**; the **3D Model** tab becomes active in the **Ribbon**.

5. Choose the **Return** tool from the **Return** panel in the **3D Model** tab of the **Ribbon**; the runner sketch is created.

Creating Runner Using the Sketch

Now, you need to create a runner using the sketch.

1. Choose the **Runner** tool from the **Runner** drop-down in the **Runners and Channels** panel in the **Mold Layout** tab of the **Ribbon**; the **Create Runner** dialog box is displayed, as shown in Figure 19-82.




Figure 19-82 The Create Runner dialog box

2. Select the runner sketch and then specify the value of diameter of the runner as **10** in the edit box available in the **Parameters** area; the preview of the runner is displayed in the modeling area.
3. Choose the **OK** button from the dialog box; the runner is created according to the sketch.

Adding Gates to the Gate Locations

Now, you need to add gates at the locations specified earlier for gates.

1. Choose the **Gate** tool from the **Runners and Channels** panel of the **Mold**

Layout tab in the **Ribbon**; the **Create Gate** dialog box is displayed, as shown in Figure 19-83.




Figure 19-83 The Create Gate dialog box

2. Select the **Sprue** option from the **Type** drop-down list in the dialog box and then select a gate location in the modeling area; the preview of the gate is displayed at the location.
3. Choose the **Apply** button from the dialog box; the gate is created.
4. Similarly, create the remaining gates and then choose the **Done** button from the dialog box.

Adding Mold Base to the Core and Cavity

Now, you need to add mold base to the core and cavity.

1. Choose the **Mold Base** tool from the **Mold Assembly** panel in the **Mold Assembly** tab of the **Ribbon**; the **Mold Base** dialog box is displayed, as shown in Figure 19-84.




Figure 19-84 The **Mold Base** dialog box

2. Retain the default settings and choose the **Placement Reference** button from the **Placement** area of the dialog box; you are prompted to specify a location for the mold base.
3. Click at the location as, shown in Figure 19-85, and then choose the **OK** button from the dialog box; the mold base is created, refer to Figure 19-86.




Figure 19-85 The point to be selected on the workpiece




Figure 19-86 The mold base created

Creating Sprue in the Mold Base

Now, you need to add a sprue to fill molten material in the runners.

1. Choose the **Sprue Bushing** tool from the **Mold Assembly** panel in the **Mold Assembly** tab of the **Ribbon**; the **Sprue Bushing** dialog box is displayed, as shown in Figure 19-87.




Figure 19-87 The Sprue Bushing dialog box

2. Click on the down arrow in the **Type** area; a window is displayed.
3. Select **DME** from the **Vendor** drop-down list. Next, select **AGN** from the list box below the **Vendor** drop-down list.
4. Select the point in the modeling area where the three runners meet, refer to Figure 19-88; the preview of the sprue bushing is displayed.




Figure 19-88 The point to be selected

5. Select the value **76** from the drop-down list displayed for the **L** parameter in the dialog box; the preview of the sprue bushing is displayed.

6. Choose the **OK** button from the dialog box; the sprue is created at the selected location.

Creating Locating Ring for the Sprue

Now, you need to create a locating ring to stop the movement of the sprue.

1. Choose the **Locating Ring** tool from the **Mold Assembly** panel in the **Mold Assembly** tab of the **Ribbon**; the **Locating Ring** dialog box is displayed, as shown in Figure 19-89.




Figure 19-89 The Locating Ring dialog box

2. Click on the down arrow in the **Type** area; a window is displayed.
3. Select **RABOURDIN** from the **Vendor** drop-down list available in the window. Next, select **646-Type B** from the list box below the **Vendor** drop-down list.
4. Choose the **OK** button from the dialog box; the locating ring is created, refer to Figure 19-90.



Figure 19-90 The locating ring created

Creating Cooling Channel in the Mold

Due to the flow of molten material in the mold, it gets hot. The mold needs to be cooled so that its strength is retained. In this section, you will add a cooling channel to the mold.

1. Choose the **Cooling Channel** tool from the **Runners and Channels** panel in the **Mold Layout** tab of the **Ribbon**; the **Cooling Channel** dialog box is displayed, refer to Figure 19-91 and you are prompted to select a face for specifying the position of the cooling channel.




Figure 19-91 The Cooling Channel dialog box

2. Select the face shown in Figure 19-92; the preview of the cooling channel is displayed.




Figure 19-92 The face to be selected

3. Select the **Through All** option from the **Extents** drop-down list in the dialog box and then choose the arrow button available for Linear Edge 1 in the dialog box; you are prompted to select an edge.
4. Select the right vertical edge of the plane highlighted in Figure 19-92; the distance value is displayed with dimension line on the model and you are prompted to select a horizontal reference.
5. Select the top horizontal edge of the plane highlighted in Figure 19-92; the distance value is displayed.
6. Click on these dimensions and specify the value **30** for vertical distance and **100** for horizontal distance; a preview of the cooling channel is displayed, as shown in Figure 19-93.




Figure 19-93 Preview of the cooling channel

7. Choose the **OK** button from the dialog box; the cooling channel is created.

Adding Cold Wells in the Mold

Now, you will add cold wells to the mold. The cold well is used to trap the solidified plastic left in the runner.

1. Choose the **Cold Well** tool from the **Runners and Channels** panel in the **Mold Layout** tab of the **Ribbon**; the **Cold Well** dialog box is displayed and you are prompted to select a point.
2. Select the midpoint of any of the runner and choose the **Apply** button; the cold well is created.
3. Similarly, create more cold wells on each runner, refer to Figure 19-94.




Figure 19-94 The cold well created

Now, the molding system is ready for the mold fill analysis.

Specifying Settings for the Mold Process

Now, you will specify settings such as mold temperature and melt temperature for the mold.

1. Choose the **Mold Process Settings** tool from the **Mold Simulation** panel in the **Mold Layout** tab of the **Ribbon**; the **Mold process settings** dialog box is displayed, refer to Figure 19-95.




Figure 19-95 The Mold process settings dialog box

2. Choose the **Suggest** tab from the dialog box; the **Required surface finish** area is displayed.
3. Select the **Low Gloss** radio button from the **Required surface finish** area of the dialog box and then choose the **Start** button from the dialog box; the analysis begins. Choose the **OK** button from the **Analysis Running** dialog box.
4. After the analysis is complete, the **Summary** dialog box is displayed, refer to Figure 19-96. Choose the **OK** button from the dialog box; the suggested process settings are applied.




Figure 19-96 The Summary dialog box

Analyzing the Mold Fill

Using the analysis, you can find out the estimate time and method to fill the molten material in the mold.

1. Choose the **Mold Fill Analysis** tool from the **Mold Simulation** panel in the **Mold Layout** tab of the **Ribbon**; the **Mold Fill Analysis** dialog box is displayed, as shown Figure 19-97.




Figure 19-97 The Mold Fill Analysis dialog box

2. Choose the **Start** button from the dialog box and choose the **OK** button from the **Analysis Running** dialog box displayed; the analysis begins.
3. After the analysis is complete, the summary is displayed in the summary dialog box, as shown in Figure 19-98. Choose the **Cancel** button to exit. You can view the analysis report any time from the **Results** node in the **Mold Design** Browse Bar.




Figure 19-98 The Summary dialog box

Self-Evaluation Test

Answer the following questions and then compare them to those given at the end of this chapter:

1. To start designing core and cavity, choose the _____ tool from the **Mold Layout** panel.
2. The _____ tool is used to manually create a sketch for the runner.
3. The _____ tool is used to manually create planar patches.
4. You can create a runoff surface without defining the workpiece. (T/F)
5. You can create patching surfaces without defining the workpiece. (T/F)
6. Gate locations are specified only to place gates in the mold. (T/F)

Review Questions

Answer the following questions:

1. The surface finish of mold is specified in _____ dialog box.

2. The _____ tool is used to add sprue bushing in the mold base.
3. The model imported as plastic part in mold design can be reoriented anytime during designing. (T/F)
4. The **Cooling Channel** tool is available in the **Mold Assembly** tab. (T/F)
5. The **Manual Sketch** tool can be used to create sketch for the cooling channel. (T/F) Exercise

Exercise 1

Create the mold system for the component shown in Figure 19-97. The part file for this component has been created in Tutorial 3 of Chapter 6. **(Expected time: 1hr)**




Figure 19-99 The component for the mold system creation

Answers to Self-Evaluation Test

1. Core/Cavity, 2. Manual Sketch, 3. Create Planar Patch, 4. F, 5. T, 6. T

